

October 3, 2012

Elmo E. Collins, Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
1600 East Lamar Blvd.
Arlington, Texas 76011-4511

Subject: **Docket No. 50-361**
Confirmatory Action Letter - Actions to Address Steam Generator Tube Degradation
San Onofre Nuclear Generating Station, Unit 2

- References:
1. Letter from Mr. Peter T. Dietrich (SCE) to Mr. Elmo E. Collins (USNRC), dated March 23, 2012, Steam Generator Return-to-Service Action Plan, San Onofre Nuclear Generating Station
 2. Letter from Mr. Elmo E. Collins (USNRC) to Mr. Peter T. Dietrich (SCE), dated March 27, 2012, Confirmatory Action Letter 4-12-001, San Onofre Nuclear Generating Station, Units 2 and 3, Commitments to Address Steam Generator Tube Degradation

Dear Mr. Collins:

On March 23, 2012, Southern California Edison (SCE) submitted a letter (Reference 1) to the NRC describing actions it planned to take with respect to issues identified in the steam generator (SG) tubes of San Onofre Nuclear Generating Station (SONGS) Units 2 and 3. On March 27, 2012, the NRC responded by issuing a Confirmatory Action Letter (CAL) (Reference 2), describing the actions that the NRC and SCE agreed would be completed to address those issues and ensure safe operations. The purpose of this letter is to report the completion of the Unit 2 CAL actions, which are to be completed prior to entry of Unit 2 into Mode 2 (as defined in the SONGS technical specifications).

Completion of the Unit 2 CAL actions is summarized below. Detailed information demonstrating fulfillment of Actions 1 and 2 of the CAL is provided in SCE's Unit 2 Return to Service Report which is included as Enclosure 2 of this letter. Enclosure 1 provides a list of new commitments identified in this letter.

CAL ACTION 1:

“Southern California Edison Company (SCE) will determine the causes of the tube-to-tube interactions that resulted in steam generator tube wear in Unit 3, and will implement actions to prevent loss of integrity due to these causes in the Unit 2 steam generator tubes. SCE will establish a protocol of inspections and/or operational limits for Unit 2, including plans for a mid-cycle shutdown for further inspections.”

COMPLETION OF CAL ACTION 1:

SCE has determined the causes of tube-to-tube interactions that resulted in SG tube wear in Unit 3, as summarized below. In addition, SCE implemented actions to prevent loss of tube integrity due to these causes in the Unit 2 SGs and established a protocol of inspections and operational limits, including plans for a mid-cycle shutdown. These are summarized under CAL Action 2.

Causes of Tube-to-Tube Interactions in Unit 3

As noted in Reference 1, the SG tube wear that caused a Unit 3 SG tube to leak was the result of tube-to-tube interaction. This type of wear was confirmed to exist in a number of other tubes in the same region in both Unit 3 SGs. Subsequent inspections of the Unit 2 SGs found this type of wear also existed in a single pair of tubes (one contact location) in one of the two Unit 2 SGs (SG 2E-089).

To determine the cause of the tube-to-tube wear (TTW), SCE performed extensive inspections and analyses, and commissioned the assistance of experts in the fields of thermal-hydraulics and in SG design, manufacturing, operation, and maintenance. Based on the results of these inspections and analyses, SCE determined the cause of the TTW in the two Unit 3 SGs was fluid elastic instability (FEI), resulting from the combination of localized high steam velocity, high steam void fraction, and insufficient contact forces between the tubes and the anti-vibration bars (AVBs). The FEI caused vibration of SG tubes in the in-plane direction that resulted in TTW in a localized area of the SGs. Details of SCE's investigation and cause evaluation are provided in Section 6 of Enclosure 2.

Corrective and Compensatory Actions, Inspections, and Operational Limits

To prevent loss of integrity due to FEI and TTW in Unit 2, SCE implemented corrective and compensatory actions and established a protocol of inspections and operational limits, including plans for a mid-cycle shutdown. These are described in CAL Action 2 below.

CAL ACTION 2:

“Prior to entry of Unit 2 into Mode 2, SCE will submit to the NRC in writing the results of your assessment of Unit 2 steam generators, the protocol of inspections and/or operational limits, including schedule dates for a mid-cycle shutdown for further inspections, and the basis for SCE's conclusion that there is reasonable assurance, as required by NRC regulations, that the unit will operate safely.”

COMPLETION OF CAL ACTION 2:

Assessment of Unit 2 Steam Generators

SCE evaluated the causes of TTW in the Unit 3 SGs and the applicability of those causes to Unit 2 and inspected the Unit 2 SGs for evidence of similar wear. SCE determined the TTW effects were much less pronounced in Unit 2 where two adjacent tubes were identified with TTW indications. The wear depth was less than 15% through-wall wear, which is below the threshold of 35% through-wall at which tube plugging is required. These two tubes are located in the same region of the SG as those with TTW in Unit 3. Given that the thermal hydraulic conditions are essentially the same in both units, the significantly lower level of TTW in Unit 2 has been attributed to manufacturing differences that resulted in greater contact between the tubes and AVBs in Unit 2, providing greater tube support. Details of SCE's investigation and cause evaluation are provided in Section 6 of Enclosure 2.

Actions to Prevent Loss of Integrity due to TTW in Unit 2 SG Tubes Including Protocol of Inspections and Operational Limits

SCE has taken actions to prevent loss of Unit 2 SG tube integrity due to TTW including establishing a protocol of inspections and operational limits to provide assurance that Unit 2 will operate safely. These actions are summarized below, with details provided in Section 8 of Enclosure 2. The operational assessments performed to confirm the adequacy of these operational limits are described in Section 10 of Enclosure 2.

1. SCE will administratively limit Unit 2 to 70% reactor power prior to a mid-cycle shutdown (Commitment 1). Limiting Unit 2 power to 70% eliminates the thermal hydraulic conditions that cause FEI from the SONGS Unit 2 SGs by reducing the steam velocity and void fraction. Further, at 70% power, the SONGS Unit 2 SGs will operate within an envelope of steam velocity and void fraction that has proven successful in the operation of other SGs of similar design. Thus, limiting power to 70% ensures that loss of tube integrity due to FEI will not occur.
2. SCE plugged the two tubes with TTW in Unit 2. As a preventive measure, additional tubes were plugged in the Unit 2 SGs. Tubes were selected for preventive plugging using correlations between wear characteristics in Unit 3 tubes and actual wear patterns found in Unit 2 tubes. Removing these tubes from service will prevent any further wear of these tubes from challenging tube integrity.
3. SCE will shut down Unit 2 for a mid-cycle SG inspection outage within 150 cumulative days of operation at or above 15% power (Commitment 2). This shortened inspection interval will ensure that any potential tube wear will not challenge the structural integrity of the in-service tubes. The protocol for mid-cycle inspections is provided in Section 8.3 of Enclosure 2.

To ensure that these actions are effective in preventing a loss of tube integrity due to FEI, SCE retained the experience and expertise of AREVA NP, Westinghouse Electric Company LLC, and Intertek/APTECH. These companies routinely perform operational assessments (OAs) of SGs for the U.S. nuclear industry. AREVA and Westinghouse also have extensive steam generator design experience. SCE retained these companies to develop independent OAs using different methodologies to evaluate whether, under the operational limits imposed by SCE, SG tube

integrity will be maintained until the next SG inspection. Each of these independent OAs demonstrates that operating at 70% power will prevent loss of tube integrity beyond the 150 cumulative day inspection interval.

The actions to operate at reduced power and shut down for a mid-cycle inspection within 150 cumulative days of operation are interim compensatory actions. SCE will reevaluate these actions during the mid-cycle inspection based on the data obtained during the inspections. In addition, SCE has established a project team to develop and implement a long term plan for repairing the SGs.

Defense-in-depth measures were developed to provide increased safety margin in the unlikely event of tube-to-tube degradation in the Unit 2 SGs during operation at 70% power. These actions, identified in Section 9 of Enclosure 2, will facilitate early detection of a SG tube leak and ensure immediate and appropriate plant operator and management response.


Basis for Conclusion of Reasonable Assurance

SCE has evaluated the causes of TTW in the Unit 3 SGs and, as described in response to CAL Action 2 above, has completed corrective and compensatory actions in Unit 2 to prevent loss of tube integrity due to these causes. Tubes within regions of the Unit 2 SGs that might be susceptible to FEI have been plugged. In addition, as described in response to CAL Action 2 above, SCE has established operational limits that eliminate the thermal-hydraulic conditions associated with FEI from the SONGS Unit 2 SGs. Specifically, operation of Unit 2 will be administratively limited to 70% power. Within 150 cumulative days of operation at or above 15% power, Unit 2 will be shut down for inspection to confirm the condition of the SG tubes. The analyses and OAs performed by SCE and independent industry experts demonstrate that under these conditions, tube integrity will be maintained. On this basis, SCE concludes that Unit 2 will operate safely.

We understand that the NRC will conduct inspections at SONGS to confirm the bases for the above information.

Please call me or Mr. Richard St. Onge at (949) 368-6240 should you require any further information.

Sincerely,



Enclosures: 1. List of Commitments
2. Unit 2 Return to Service Report

cc: NRC Document Control Desk
R. Hall, NRC Project Manager, San Onofre Units 2 and 3
G. G. Warnick, NRC Senior Resident Inspector, San Onofre Units 2 and 3
R. E. Lantz, Branch Chief, Division of Reactor Projects, Region IV

ENCLOSURE 1

List of Commitments

**Enclosure 1
List of Commitments**

This table identifies actions discussed in this letter that Southern California Edison commits to perform. Any other actions discussed in this submittal are described for the NRC's information and are not commitments.


	Description of Commitment	Scheduled Completion Date
1	Prior to a mid-cycle shutdown of Unit 2, SCE will administratively limit operation of Unit 2 to 70% power (refer to cover letter, Completion of CAL Action 2).	mid-cycle shutdown of Unit 2
2	SCE will shut down Unit 2 for a mid-cycle steam generator (SG) inspection outage. During this outage, inspections of Unit 2 SG tubes will be performed to confirm the effectiveness of the corrective and compensatory actions taken to address tube-to-tube wear in the Unit 2 SGs. (refer to cover letter, Completion of CAL Action 2).	within 150 cumulative days of operation at or above 15% power
3	SCE will install a temporary N-16 radiation detection system (refer to Enclosure 2, Section 9.2). The temporary N-16 detectors will be located on the Unit 2 main steam lines and be capable of detecting an increase in steam line activity.	prior to Unit 2 entry into Mode 2
4	SCE Plant Operators will receive training on use of the new detection tools for early tube leak identification and on lessons learned from response to the January 31, 2012, Unit 3 shutdown due to a steam generator (SG) tube leak (refer to Enclosure 2, Section 9.4.2).	prior to Unit 2 entry into Mode 2
5	SCE will upgrade the Unit 2 Vibration and Loose Part Monitor System (refer to Enclosure 2, Section 11.1). The new system will provide additional monitoring capabilities for steam generator secondary side noise.	prior to Unit 2 entry into Mode 2
6	SCE will install analytic and diagnostic software (GE Smart Signal) utilizing existing instrumentation (refer to Enclosure 2, Section 11.2).	prior to Unit 2 entry into Mode 2

ENCLOSURE 2

San Onofre Nuclear Generating Station

Unit 2 Return to Service Report

[Proprietary Information Redacted]




SOUTHERN CALIFORNIA
EDISON[®]

An *EDISON INTERNATIONAL*[®] Company

Enclosure 2

SOUTHERN CALIFORNIA EDISON
An *EDISON INTERNATIONAL* Company

**SAN ONOFRE NUCLEAR GENERATING STATION
UNIT 2 RETURN TO SERVICE REPORT
October 3, 2012**



SOUTHERN CALIFORNIA
EDISON[®]

An EDISON INTERNATIONAL[®] Company

SONGS Unit 2 Return to Service Report

Record of Revision

Revision No.	Pages/Sections/ Paragraphs Changed	Brief Description / Change Authorization
0	Entire Document	Initial Issue

Table of Contents

	Page
RECORD OF REVISION.....	2
LIST OF TABLES	6
LIST OF FIGURES	7
ABBREVIATIONS AND ACRONYMS	8
1.0 EXECUTIVE SUMMARY.....	10
1.1 Occurrence and Detection of the Unit 3 Tube Leak	10
1.2 Inspections of the Steam Generator Tubes and Cause Evaluations of Tube Wear	11
1.3 Compensatory, Corrective, and Defense-in-Depth Actions	11
1.4 Operational Assessments.....	11
1.5 Conclusion.....	12
2.0 INTRODUCTION	13
3.0 BACKGROUND	14
3.1 Steam Generator Tube Safety Functions.....	14
3.2 SG Regulatory/Program Requirements	15
3.3 The SONGS Steam Generator Program.....	16
4.0 UNIT 2 AND 3 REPLACEMENT STEAM GENERATORS.....	17
5.0 UNIT 3 EVENT – LOSS OF TUBE INTEGRITY	18
5.1 Summary of Event.....	18
5.2 Safety Consequences of Event.....	19
5.2.1 Deterministic Risk Analyses	19
5.2.2 Probabilistic Risk Assessment (PRA)	20
6.0 UNIT 3 EVENT INVESTIGATION AND CAUSE EVALUATION.....	21
6.1 Summary of Inspections Performed.....	21
6.2 Summary of Inspection Results	22
6.3 Cause Analyses of Tube-to-Tube Wear in Unit 3.....	30
6.3.1 Mechanistic Cause	30
6.3.2 Potential Applicability of Unit 3 TTW Causes to Unit 2.....	30
6.4 Industry Expert Involvement.....	31
6.5 Cause Analysis Summary.....	31

Table of Contents
(continued)

	Page
7.0 UNIT 2 CYCLE 17 INSPECTIONS AND REPAIRS	32
7.1 Unit 2 Cycle 17 Routine Inspections and Repairs	32
7.2 Unit 2 Cycle 17 Inspection in Response to TTW in Unit 3	33
7.3 Differences between Units 2 and 3	36
8.0 UNIT 2 CORRECTIVE AND COMPENSATORY ACTIONS TO ENSURE TUBE INTEGRITY...37	
8.1 Limit Operation of Unit 2 to 70% Power	37
8.2 Preventive Tube Plugging for TTW	45
8.2.1 Screening Criteria for Selecting Tubes for Plugging	45
8.2.2 Plant Operations with Tubes Plugged in Unit 2	48
8.3 Inspection Interval and Protocol of Mid-cycle Inspections	48
8.3.1 Inspection of Inservice Tubes (Unplugged)	48
8.3.2 Inspection of Plugged Tubes	48
9.0 UNIT 2 DEFENSE-IN-DEPTH ACTIONS	50
9.1 Injection of Argon into the Reactor Coolant System (RCS)	50
9.2 Installation of Nitrogen (N-16) Radiation Detection System on the Main Steam Lines ...	50
9.3 Reduction of Administrative Limit for RCS Activity Level	50
9.4 Enhanced Operator Response to Early Indication of SG Tube Leakage	50
9.4.1 Operations Procedure Changes	50
9.4.2 Operator Training	50
10.0 UNIT 2 OPERATIONAL ASSESSMENT	51
11.0 ADDITIONAL ACTIONS	52
11.1 Vibration Monitoring Instrumentation	52
11.2 GE Smart Signal™	52
12.0 CONCLUSIONS	53
13.0 REFERENCES	54

Table of Contents
(continued)

Page

ATTACHMENTS

- 1 SONGS Unit 2 Relevant Technical Specifications
- 2 AREVA Document 51-9182368-003, SONGS 2C17 Steam Generator Condition Monitoring Report*
- 3 AREVA Document 51-9180143-001, SONGS Unit 3 February 2012 Leaker Outage – Steam Generator Condition Monitoring Report*
- 4 MHI Document L5-04GA564, Tube Wear of Unit-3 RSG - Technical Evaluation Report*
- 5 MHI Document L5-04GA571, Screening Criteria for Susceptibility to In-Plane Tube Motion*
- 6 SONGS U2C17 Steam Generator Operational Assessment*

* [Proprietary Information Redacted]

List of Tables

	Page
TABLE 5-1: SONGS UNIT 3 SG 3E-088 IN-SITU PRESSURE TESTS WITH TUBE LEAKAGE	19
TABLE 6-1: STEAM GENERATOR WEAR DEPTH SUMMARY	29
TABLE 7-1: TTW COMPARISON BETWEEN UNIT 2 AND UNIT 3 SGS.....	36
TABLE 8-1: INDEPENDENT ATHOS COMPARISON RESULTS – STEAM QUALITY	38
TABLE 8-2: COMPARISON OF MAXIMUM VOID FRACTION	40
TABLE 8-3: COMPARISON OF MAXIMUM INTERSTITIAL VELOCITY (FT/S).....	42
TABLE 8-4: UNIT 2 STEAM GENERATOR TUBE PLUGGING SUMMARY	45

List of Figures

	Page
FIGURE 3-1: REPLACEMENT STEAM GENERATOR SECTION VIEW	14
FIGURE 6-1: STEAM GENERATOR SECTION VIEW SKETCH	23
FIGURE 6-2: UNIT 2 DISTRIBUTION OF WEAR AT AVB SUPPORTS	24
FIGURE 6-3: UNIT 3 DISTRIBUTION OF WEAR AT AVB SUPPORTS	24
FIGURE 6-4: UNIT 2 DISTRIBUTION OF WEAR AT TSP SUPPORTS.....	25
FIGURE 6-5: UNIT 3 DISTRIBUTION OF WEAR AT TSP SUPPORTS.....	25
FIGURE 6-6: PROBABILITY OF DETECTION FOR TUBE WEAR.....	26
FIGURE 6-7: 3E-088 ROTATING COIL INSPECTION REGION.....	27
FIGURE 6-8: 3E-089 ROTATING COIL INSPECTION REGION.....	28
FIGURE 7-1: 2E-088 ROTATING COIL INSPECTION REGION.....	34
FIGURE 7-2: 2E-089 ROTATING COIL INSPECTION REGION.....	35
FIGURE 8-1: STEAM QUALITY CONTOUR PLOTS FOR 100% POWER AND 70% POWER.....	39
FIGURE 8-2: MAXIMUM VOID FRACTION VERSUS POWER LEVEL AND.....	41
FIGURE 8-3: INTERSTITIAL VELOCITY CONTOUR PLOTS FOR 100% POWER AND 70% POWER.....	43
FIGURE 8-4: GAP VELOCITY AT 100% POWER AND 70% POWER FOR 2E-088 R141C89.....	44
FIGURE 8-5: GAP VELOCITY AT 100% POWER AND 70% POWER FOR 2E-089 R141C89.....	44
FIGURE 8-6: 2E-088 PLUGGING AND STABILIZING MAP	46
FIGURE 8-7: 2E-089 PLUGGING AND STABILIZING MAP	47

ABBREVIATIONS AND ACRONYMS

2E-088	Unit 2 Steam Generator E-088
2E-089	Unit 2 Steam Generator E-089
3E-088	Unit 3 Steam Generator E-088
3E-089	Unit 3 Steam Generator E-089
AILPC	Accident Induced Leakage Performance Criterion
Ar	Argon
ATHOS	Analysis of Thermal-Hydraulics of Steam Generators
AVB	Anti-Vibration Bar
CDP	Core Damage Probability
CM	Condition Monitoring
DA	Degradation Assessment
DID	Defense in Depth
ECT	Eddy Current Testing
EFPD	Effective Full Power Days
EPRI	Electric Power Research Institute
ETSS	Examination Technique Specification Sheet
FEI	Fluid Elastic Instability
FIV	Flow Induced Vibration
FO	Foreign Object
FOSAR	Foreign Object Search and Retrieval
gpd	Gallons Per Day
INPO	Institute of Nuclear Power Operations
LERP	Large Early Release Probability
MHI	Mitsubishi Heavy Industries, Ltd.
MSLB	Main Steam Line Break
MWt	Megawatt Thermal
N-16	Nitrogen – 16
NEI	Nuclear Energy Institute
NODP	Normal Operating Differential Pressure
OA	Operational Assessment
OSG	Original Steam Generator
post-trip SLB	Steam Line Break Post-Trip Return-To-Power Event
PRA	Probabilistic Risk Assessment
RB	Retainer Bar
RCPB	Reactor Coolant Pressure Boundary
RCE	Root Cause Evaluation
RCS	Reactor Coolant System
Ref.	Reference
RSG	Replacement Steam Generator
SCE	Southern California Edison
SG	Steam Generator
SGTR	Steam Generator Tube Rupture
SIPC	Structural Integrity Performance Criterion
SLB	Steam Line Break
SGP	Steam Generator Program
SONGS	San Onofre Nuclear Generating Station
SR	Stability Ratio
T/H	Thermal-Hydraulics
TEDE	Total Effective Dose Equivalent
TS	Technical Specification
TSP	Tube Support Plate



SOUTHERN CALIFORNIA
EDISON[®]

An EDISON INTERNATIONAL[®] Company

SONGS Unit 2 Return to Service Report

TTW	Tube-to-Tube Wear
TW	Through Wall
TWD	Through Wall Depth
U2C17	Unit 2 Cycle 17
UFSAR	Updated Final Safety Analysis Report
UT	Ultrasonic Testing
WEC	Westinghouse Electric Company

1.0 EXECUTIVE SUMMARY

On January 31, 2012, a leak was detected in a steam generator (SG) in Unit 3 of the San Onofre Nuclear Generating Station (SONGS). Southern California Edison (SCE) operators promptly shut down the unit in accordance with plant operating procedures. The leak resulted in a small radioactive release to the environment that was well below the allowable federal limits. Subsequently, on March 27, 2012, the Nuclear Regulatory Commission (NRC) issued a Confirmatory Action Letter (CAL) (Ref. 1) to SCE describing actions that the NRC and SCE agreed must be completed prior to returning Units 2 and 3 to service.

To address the tube leak and its causes, SCE assembled a technical team including experts in the fields of thermal hydraulics (T/H) and in SG design, manufacture, operation, and maintenance. The team performed extensive investigations into the causes of the tube leak and developed compensatory and corrective actions that SCE has implemented to prevent recurrence of the tube-to-tube wear (TTW) that caused the leak. SCE also implemented defense-in-depth (DID) measures to provide additional safety margin. SCE has planned SG inspections following a shortened operating interval to confirm the effectiveness of its compensatory and corrective actions.

As required by the SONGS technical specifications (TSs), the SONGS Steam Generator Program (SGP), and industry guidelines, an Operational Assessment (OA) must be performed to ensure that SG tubing will meet established performance criteria for structural and leakage integrity during the operating period prior to the next planned inspection. Because of the unusual and unexpected nature of the SG TTW, SCE commissioned three independent OAs by experienced vendors. These vendors applied different methodologies to ensure a comprehensive and diverse evaluation. An additional OA was performed to evaluate SG tube wear other than TTW. Each of these OAs independently concluded that the compensatory and corrective actions implemented by SCE are sufficient to address tube wear issues so that the Unit 2 SGs will operate safely.

The purpose of this report is to provide detailed information demonstrating completion of CAL actions required prior to entry of Unit 2 into Mode 2. The report also describes in detail the basis for the conclusion that Unit 2 will continue to operate safely after restart.

This report describes:

- Results of inspections of the SG tubes
- Causes of the tube wear in the Unit 2 and Unit 3 SGs
- Compensatory and corrective actions that SCE has taken to address tube wear in Unit 2
- OAs that have been performed to demonstrate that those compensatory and corrective actions ensure that TTW will be prevented until the next SG inspections
- Additional controls and DID actions that SCE is implementing to ensure health and safety of the public in the unlikely event of a loss of SG tube integrity

1.1 Occurrence and Detection of the Unit 3 Tube Leak

New SGs were placed into service at SONGS Units 2 and 3 in 2010 and 2011, respectively. The replacement steam generators (RSGs) were installed to resolve corrosion and other degradation issues present in the original steam generators (OSGs). The RSGs were designed and manufactured by Mitsubishi Heavy Industries (MHI). On January 9, 2012, after 22 months of operation, Unit 2 was shut down for a routine refueling and SG inspection outage. This was the first inspection of the Unit 2 SG tubes performed following SG replacement. The condition monitoring (CM) assessment performed to evaluate the results of this inspection confirmed that the SG performance criteria were satisfied during the operating interval.

On January 31, 2012, while the Unit 2 outage was in progress, SONGS Unit 3 was operating at 100 percent power when a condenser air ejector radiation monitor alarm indicated a primary-to-secondary leak. Unit 3 was

promptly shut down in accordance with plant operating procedures and placed in a stable cold shutdown condition. The TS limit for operational leakage (150 gallons per day (gpd)) was not exceeded during the event. A small, monitored radioactive release to the environment occurred, resulting in an estimated 0.0000452 mrem dose to the public. This estimated dose was well below the allowable federal limit specified in 10 CFR 20 of 100 mrem per year to a member of the public.

1.2 Inspections of the Steam Generator Tubes and Cause Evaluations of Tube Wear

Subsequent to the reactor cooldown, extensive inspection, testing, and analysis of SG tubes was performed in both Unit 3 SGs. This was the first inspection of the Unit 3 SG tubes performed following SG replacement after approximately 11 months of operation. The leak was identified in SG 3E-088 and was caused by TTW in the U-bend portion of the tube in Row 106 Column 78. Additional inspections revealed significant TTW in many tubes in Unit 3.

In accordance with SGP requirements for unexpected degradation, SCE initiated a cause evaluation of the TTW phenomenon. The Root Cause Evaluation (RCE) Team used significant input from the SG Recovery Team which included the services of MHI and industry experts in the fields of T/H and in SG design, manufacturing, operation, and repair. The mechanistic cause of the TTW in Unit 3 was identified as fluid elastic instability (FEI), caused by a combination of localized high steam velocity (tube vibration excitation forces), high steam void fraction (loss of ability to dampen vibration), and insufficient tube to anti-vibration bar (AVB) contact to overcome the excitation forces. The FEI resulted in a vibration mode of the SG tubes in which the tubes moved in the in-plane direction parallel to the AVBs in the U-bend region. This resulted in TTW in a localized region of the Unit 3 SGs.

Although no TTW had been detected during the routine inspections of all tubes in Unit 2, the unit was not returned to service pending an evaluation of the susceptibility of the Unit 2 SGs to the TTW found in Unit 3. In March 2012, as part of this evaluation, additional inspections using a more sensitive inspection method were performed on the Unit 2 tubes. Shallow TTW was identified between two adjacent tubes in SG 2E-089.

1.3 Compensatory, Corrective, and Defense-in-Depth Actions

SCE has implemented compensatory and corrective actions that will prevent loss of integrity due to TTW in Unit 2, including:

1. Limiting Unit 2 to 70% power prior to a mid-cycle SG inspection outage
2. Preventively plugging tubes in both SGs
3. Shutting down Unit 2 for a mid-cycle SG inspection outage within 150 cumulative days of operation at or above 15% power

SCE has also implemented conservative DID measures to provide an increased safety margin in the unlikely event of tube-to-tube degradation in the Unit 2 SGs during operation at 70% reactor power. Additionally, SCE has provided enhanced plant monitoring capability to assist in evaluating the condition of the SGs.

1.4 Operational Assessments

As required by the CAL (Ref. 1), SCE has prepared an assessment of the Unit 2 SGs that addresses the causes of TTW wear found in the Unit 3 SGs, prior to entry of Unit 2 into MODE 2.

Due to the significant levels of TTW found in Unit 3 SGs, SCE assessed the likelihood of additional TTW in Unit 2 from several different perspectives, utilizing the experience and expertise of AREVA NP, Westinghouse Electric Company, LLC (WEC), and Intertek/APTECH. Each of these companies routinely prepare OAs to assess the safety of operation of SGs at U.S. nuclear power plants. These companies developed independent OAs to

evaluate the TTW found at SONGS and the compensatory and corrective actions being implemented to address TTW in the Unit 2 SGs. These OAs apply different methodologies to ensure a comprehensive and diverse evaluation. Each of these OAs concluded that the compensatory and corrective actions implemented by SCE are sufficient to address tube wear issues so that the Unit 2 SGs will operate safely. The results of these analyses fulfill the TS requirement to demonstrate that SG tube integrity will be maintained over the reduced operating cycle until the next SG inspection.

1.5 Conclusion

On the basis of the compensatory and corrective actions, DID actions, and the results of the OAs, SCE concludes that Unit 2 will operate safely at 70% power for 150 cumulative days of operation with substantial safety margin and without loss of tube integrity. Reducing power to 70% eliminates the thermal hydraulic conditions that cause FEI and associated TTW from the SONGS Unit 2 SGs. After this period of operation, Unit 2 will be shut down for inspection of the steam generator tubes to confirm the effectiveness of the compensatory and corrective actions that have been taken. SCE will continue to closely monitor steam generator tube integrity and take corrective actions as appropriate to ensure the health and safety of the public is maintained.

2.0 INTRODUCTION

On March 27, 2012, the NRC issued a CAL (Ref. 1) to SCE describing actions that the NRC and SCE agreed would be completed prior to returning Units 2 and 3 to service. The purpose of this report is to provide detailed information to demonstrate fulfillment of Actions 1 and 2 of the CAL, which are required to be completed prior to entry of Unit 2 into Mode 2. The actions as stated in the CAL are as follows:

CAL ACTION 1: "Southern California Edison Company (SCE) will determine the causes of the tube-to-tube interactions that resulted in steam generator tube wear in Unit 3, and will implement actions to prevent loss of integrity due to these causes in the Unit 2 steam generator tubes. SCE will establish a protocol of inspections and/or operational limits for Unit 2, including plans for a mid-cycle shutdown for further inspections."

CAL ACTION 2: "Prior to entry of Unit 2 into Mode 2, SCE will submit to the NRC in writing the results of your assessment of Unit 2 steam generators, the protocol of inspections and/or operational limits, including schedule dates for a mid-cycle shutdown for further inspections, and the basis for SCE's conclusion that there is reasonable assurance, as required by NRC regulations, that the unit will operate safely."

This report describes the actions SCE has taken to return Unit 2 to service while ensuring that the unit will operate safely. Because the SGs in Units 2 and 3 have the same design, the causes of the tube leak in Unit 3 and the potential susceptibility of Unit 2 SGs to the same mechanism are also addressed. This report will demonstrate that actions have been completed to prevent loss of integrity in the Unit 2 SG tubes due to these causes.


3.0 BACKGROUND

3.1 Steam Generator Tube Safety Functions

The Reactor Coolant System (RCS) circulates primary system water in a closed cycle, removing heat from the reactor core and internals and transferring it to the secondary side main steam system. The SGs provide the interface between the RCS and the main steam system. Reactor coolant is separated from the secondary system fluid by the SG tubes and tube sheet, making the RCS a closed system and forming a barrier to the release of radioactive materials from the core. The secondary side systems also circulate water in a closed cycle transferring the waste heat from the condenser to the circulating water system. However, the secondary side is not a totally closed system and presents several potential release paths to the environment in the event of a primary-to-secondary leak.

The SG tubes have a number of important safety functions. As noted above, the SG tubes are an integral part of the Reactor Coolant Pressure Boundary (RCPB) and, as such, are relied on to maintain primary system pressure and inventory. The SG tubes isolate the radioactive fission products in the primary coolant from the secondary system. In addition, as part of the RCPB, the SG tubes act as the heat transfer surface that transfers heat from the primary system to the secondary system. Figure 3-1 provides a section view of a SONGS SG.

Figure 3-1: Replacement Steam Generator Section View



3.2 SG Regulatory/Program Requirements

The nuclear industry and the NRC have instituted rigorous requirements and guidelines to ensure that SG tube integrity is maintained such that the tubes are capable of performing their intended safety functions. Title 10 of the Code of Federal Regulations (10 CFR) establishes the fundamental regulatory requirements with respect to integrity of the SG tubes. The SONGS TSs include several requirements relating to the SGs including the requirement that SG tube integrity is maintained and all SG tubes reaching the tube repair criteria are plugged in accordance with the SGP (TS 3.4.17), that a SGP is established and implemented to ensure that SG tube integrity is maintained (TS 5.5.2.11), that a report of the inspection and CM results be provided to the NRC following each SG inspection outage (TS 5.7.2.c), and that the primary-to-secondary leakage through any one SG is limited to 150 gpd (TS 3.4.13). These TSs are provided in their entirety in Attachment 1.

TS 5.5.2.11, Steam Generator Program, requires the establishment and implementation of a SGP to ensure that SG tube integrity is maintained. The SGP ensures the tubes are repaired, or removed from service by plugging the tube ends, before the structural or leakage integrity of the tubes is impaired. TS 3.4.13 includes a limit on operational primary-to-secondary leakage, beyond which the plant must be promptly shutdown. Should a flaw exceeding the tube repair limit not be detected during the periodic tube inspections, the leakage limit provides added assurance of timely plant shutdown before tube structural and leakage integrity are impaired.

TS 5.5.2.11 requires the SGP to include five provisions, which are summarized below

- a. CM assessments shall be conducted during each SG inspection outage to evaluate the “as found” condition of the tubing with respect to the performance criteria for structural integrity and accident induced leakage. The purpose of the CM assessment is to ensure that the SG performance criteria have been met for the previous operating period.
- b. SG tube integrity shall be maintained by meeting the specified performance criteria for tube structural integrity, accident induced leakage, and operational leakage.
- c. Tubes found by in-service inspection to contain flaws with a depth equal to or exceeding 35% of the nominal tube wall thickness shall be plugged.
- d. Periodic SG tube inspections shall be performed as specified in the TS. The inspection scope, inspection methods, and inspection intervals shall be such as to ensure that SG tube integrity is maintained until the next SG inspection.
- e. Provisions shall be made for monitoring operational primary-to-secondary leakage.

TS 3.4.13, RCS Operational Leakage, limits primary-to-secondary leakage through any one SG to 150 gpd. The limit of 150 gpd per SG is based on the operational leakage performance criterion in the Nuclear Energy Institute (NEI) 97-06, Steam Generator Program Guidelines (Ref. 2). The limit is based on operating experience with SG tube degradation mechanisms that result in tube leakage.

3.3 The SONGS Steam Generator Program

The purpose of the SGP is to ensure tube integrity and compliance with SG regulatory requirements. The program contains a balance of prevention, inspection, evaluation and repair, and leakage monitoring measures. The SONGS SGP (Ref. 10), which implements the requirements specified in TS 5.5.2.11, is based on the NEI 97-06, Steam Generator Program Guidelines (Ref. 2) and its referenced Electric Power Research Institute (EPRI) guidelines. Use of the SGP ensures that SGs are inspected and repaired consistent with accepted industry practices.

The SGP requires assessments of SG integrity. This assessment applies to SG components which are part of the primary pressure boundary (e.g., tubing, tube plugs, sleeves and other repairs). It also applies to foreign objects (FOs) and secondary side structural supports (e.g., tube support plates (TSPs)) that may, if severely degraded, compromise pressure-retaining components of the SG. Three types of assessments are performed to provide assurance that the SG tubes will continue to satisfy the appropriate performance criteria: (1) Degradation Assessment (DA); (2) CM Assessment; and (3) OA.

The DA is the planning process that identifies and documents information about plant-specific SG degradation. The overall purpose of the DA is to prepare for an upcoming SG inspection through the identification of the appropriate examinations and techniques, and ensuring that the requisite information for integrity assessment is obtained. The DA performed for Unit 2 Cycle 17 (U2C17) SG Inspection Outage is discussed in Section 7.1 of this report.

The CM is backward looking, in that its purpose is to confirm that adequate SG tube integrity has been maintained during the previous inspection interval. The CM involves an evaluation of the as-found condition of the tubing relative to the integrity performance criteria specified in the TS. The tubes are inspected according to the EPRI Pressurized Water Reactor SG Examination Guidelines (Ref. 3). Structural and leakage integrity assessments are performed and results compared to their respective performance criteria. If satisfactory results are not achieved, a RCE is performed and appropriate corrective action taken. The results of this analysis are factored into future DAs, inspection plans, and OAs of the plant. The CM results for U2C17 are presented in Section 7 of this report.

The OA differs from the CM assessment in that it is forward looking rather than backward looking. Its purpose is to demonstrate that the tube integrity performance criteria will be met throughout the next inspection interval. During the CM assessments, inspection results are evaluated with respect to the appropriate performance criteria. If this evaluation is successful, an OA is performed to show that integrity will be maintained throughout the next interval between inspections. If any performance criterion is not met during performance of CM, a RCE is required to be performed and the results are to be factored into the OA strategy. The results of the OA determine the allowable operating time for the upcoming inspection interval. The OA addressing all degradation mechanisms found during U2C17 is discussed in Section 10 of this report.

4.0 UNIT 2 AND 3 REPLACEMENT STEAM GENERATORS

New SGs were placed into service at SONGS Units 2 and 3 in 2010 and 2011, respectively. The RSGs were intended to resolve corrosion and other degradation issues present in the OSGs. The RSGs were designed and manufactured by MHI.

The steam generator is a recirculating, vertical U-tube type heat exchanger converting feedwater into saturated steam. The steam generator vessel pressure boundary is comprised of the channel head, lower shell, middle shell, transition cone, upper shell and upper head. The steam generator internals include the divider plate, tubesheet, tube bundle, feedwater distribution system, moisture separators, steam dryers and integral steam flow limiter installed in the steam nozzle. The channel head is equipped with one reactor coolant inlet nozzle and two outlet nozzles. The upper vessel is equipped with the feedwater nozzle, steam nozzle and blowdown nozzle. In the channel head, there are two 18 inch access manways. In the upper shell, there are two 16 inch access manways. The steam generator is equipped with six handholes and 12 inspection ports providing access for inspection and maintenance. In addition, the steam generators are equipped with several instrumentation and minor nozzles for layup and chemical recirculation intended for chemical cleaning.

5.0 UNIT 3 EVENT – LOSS OF TUBE INTEGRITY

5.1 Summary of Event

On January 31, 2012, while the Unit 2 refueling and SG inspection outage was in progress, SONGS Unit 3 was in Mode 1 operating at 100 percent power, when a condenser air ejector radiation monitor alarm indicated a primary-to-secondary leak. A rapid power reduction was commenced when the primary-to-secondary leak rate was determined to be greater than 75 gpd with an increasing rate of leakage exceeding 30 gpd per hour. The reactor was manually tripped from 35 percent power, and placed in a stable cold shutdown condition in Mode 5. The TS 3.4.13 limit for RCS operational leakage (150 gpd) was not exceeded. A small, monitored radioactive release to the environment occurred, resulting in an estimated 0.0000452 mrem dose to the public, which was well below the allowable federal limit specified in 10 CFR 20 of 100 mrem per year to a member of the public.

Subsequent to the reactor cooldown, extensive inspection, testing, and analysis of SG tube integrity commenced in both Unit 3 SGs. This was the first inspection of the Unit 3 SG tubes performed following SG replacement after approximately eleven months of operation. The work scope included the following activities: bobbin probe and rotating probe examinations using eddy current testing (ECT), secondary and primary side visual examinations, and in-situ pressure testing. The location of the leak in SG 3E-088, which resulted in the Unit 3 shutdown, was determined to be in the U-bend portion of the tube in Row 106 Column 78. ECT was subsequently performed on 100% of the tubes in both Unit 3 SGs. During these inspections, unexpected wear was discovered in both SGs including wear at AVBs, TSPs, RBs, and significant TTW in the U-bend area of the tubes. The TTW in Unit 3 was found to be much more extensive than in Unit 2, where only two tubes in one SG were determined to be affected.

The EPRI guidelines (Ref. 4) allow assessment of the structural and accident induced leakage integrity to be performed either analytically or through in-situ pressure testing. In accordance with EPRI guidelines and the SGP, in-situ pressure testing was performed on a total of 129 tubes in Unit 3, (73 in SG 3E-088 and 56 in SG 3E-089) in March 2012. The pressure tests were performed to determine if the tubes met the performance criteria in the TS (Attachment 1). The testing resulted in detected leaks in eight tubes in SG 3E-088 at the pressures indicated in Table 5-1. The failure location for all eight tubes was in the U-bend portion of the tube bundle in the tube freespan area. The locations of the tubes that were pressure tested and the tubes that failed the pressure tests are shown in Figure 6-7 and Figure 6-8. The first tube listed in the table (location 106-78) was the tube with the through-wall leak which resulted in the Unit 3 shutdown on January 31, 2012. No leaks were detected in the remaining 121 tubes tested in Unit 3. For the eight tubes indicating leakage, three tubes failed both the accident induced leakage performance criterion (AILPC) and the structural integrity performance criterion (SIPC); and 5 tubes passed the AILPC but failed the SIPC. All tubes met the operational leakage performance criterion of TS Limiting Condition for Operation 3.4.13. Details of the Unit 3 inspections and in-situ testing results are documented in the Unit 3 CM Report included as Attachment 3.

Additional testing performed to identify the extent and cause of the abnormal wear is presented in Section 6. Required reports in response to the reactor shut down and in-situ test failures were made to the NRC in accordance with 10 CFR 50.72 and 50.73 (Refs. 5-8).

Table 5-1: SONGS Unit 3 SG 3E-088 In-Situ Pressure Tests with Tube Leakage

Test Date, Time	Tube Location (row-column)	Maximum Test Pressure Achieved (see Note 1)	Performance Criteria Not Met (see Note 2)
03/14/12, 1120PDT	106-78	2874 psig	Accident Induced Leakage
03/14/12, 1249PDT	102-78	3268 psig	Accident Induced Leakage
03/14/12, 1425PDT	104-78	3180 psig	Accident Induced Leakage
03/15/12, 1109PDT	100-80	4732 psig	Structural Integrity
03/15/12, 1437PDT	107-77	5160 psig	Structural Integrity
03/15/12, 1604PDT	101-81	4889 psig	Structural Integrity
03/15/12, 1734PDT	98-80	4886 psig	Structural Integrity
03/16/12, 1216PDT	99-81	5026 psig	Structural Integrity

Note 1

Test Pressures:
(Calculated)

Normal Operating Differential Pressure (NODP) Test Pressure = 1850 psig
Accident Induced Leakage DP (Main Steam Line Break) Test Pressure = 3200 psig
Structural Integrity Limit (3 x NODP) Test Pressure = 5250 psig

Note 2

Performance Criteria:

Structural Integrity – No burst at 3 x NODP test pressure
Accident Induced Leakage - leak rate < 0.5 gpm at MSLB test pressure
Operational Leakage - TS Limiting Condition for Operation 3.4.13

5.2 Safety Consequences of Event

As discussed above, the Unit 3 shutdown on January 31, 2012, due to a SG tube leak, resulted in a small, monitored radioactive release to the environment, well below allowable limits. The potential safety significance of the degraded condition of the Unit 3 SG tubes is discussed below.

5.2.1 Deterministic Risk Analyses

The SONGS Updated Final Safety Analysis Report (UFSAR) Section 15.10.1.3.1.2 presents the current licensing basis steam line break (SLB) post-trip return-to-power event (post-trip SLB). Based on the actual plant RCS chemistry data, the accident-induced iodine spiking factor of 500, and the estimated SG tube rupture leakage rate, the calculated dose would have been at least 32 percent lower than the dose consequences reported in the UFSAR for the post-trip SLB event with a concurrent iodine spike. The postulated post-trip SLB with tube rupture and concurrent iodine spike Exclusion Area Boundary, Low Population Zone, and Control Room doses would be less than 0.068 Rem Total Effective Dose Equivalent (TEDE), which is well below the post-trip SLB Control Room limit of 5 Rem TEDE, and the Exclusion Area Boundary and Low Population Zone limit of 2.5 Rem TEDE.

The potential for a seismically-induced tube rupture was also evaluated. The analysis determined the equivalent flaw characteristics of the most limiting degraded tube in Unit 3 SG 3E-088 from its in-situ pressure test result. This tube, Row 106 Column 78 (the leaking tube), sustained an in-situ test pressure of 2,874 psi before exceeding leakage limits. This in-situ test pressure, which is slightly more than twice the operating differential pressure on the tube, corresponds to the limiting stress for crack penetration or plastic collapse with large deformation. The combined stresses due to operating differential pressure and seismic forces corresponding to SONGS Design Basis Earthquake (DBE) are lower than this limiting stress and are also less than the allowable stress for the faulted condition (i.e., including DBE) according to the American Society of Mechanical Engineers Code. Therefore, the degraded tube would not have burst under this worst case loading.

5.2.2 Probabilistic Risk Assessment

A Probabilistic Risk Assessment (PRA) was performed to analyze the risk impact of the degraded SG tubes on SONGS Unit 3 SG 3E-088 with respect to two cases: (1) any increased likelihood of an independent SG tube rupture (SGTR) at normal operating differential pressure (NODP), or (2) due to a SGTR induced by an excess steam demand event, also referred to as a main steam line break (MSLB). The SONGS PRA model was used to calculate the increases in Core Damage Probability (CDP) and Large Early Release Probability (LERP) associated with each case. In both cases, all postulated core damage sequences are assumed to result in a large early release since the containment will be bypassed due to the SGTR; therefore, the calculated CDP and LERP are equal. The total Incremental LERP (ILERP) due to the degraded SG tubes (i.e., the sum of the two analyzed cases) was determined to be less than 2×10^{-7} . This small increase in risk is attributed to two factors. First, the exposure time for the postulated increased independent SGTR initiating event frequency case was very short (0.1 Effective Full Power Month (EFPM)). Second, a MSLB alone does not generate sufficient differential pressure to cause tube rupture in Case 2. The differential pressure across the SG tubes necessary to cause a rupture will not occur if operators prevent RCS re-pressurization in accordance with Emergency Operating Instructions.

6.0 UNIT 3 EVENT INVESTIGATION AND CAUSE EVALUATION

6.1 Summary of Inspections Performed

Following the identification of SG tube leakage in the Unit 3 SG 3E-088, extensive inspections were performed to determine the location and cause of the leak. The location of the leak was identified by filling the SG secondary side with nitrogen and pressurizing to 80 psig. The test identified the tube located at Row 106, Column 78 (R106 C78) as the source of the leakage. Using eddy current bobbin and rotating probes, the tube at R106 C78 and those immediately adjacent to it were inspected and the leakage location was confirmed. The leak location was in the U-bend portion of the tube in the “freSPAN” area between AVB support locations (refer to Figure 6-1).

To determine the extent of the wear that had resulted in a leak, an eddy current bobbin probe examination of the full-length of all tubes in both Unit 3 SGs was performed. The locations of tubes with TTW are shown on Figures 6-7 and 6-8. Based on the results of the bobbin probe examinations, TTW indications were then examined using a more sensitive +Point™ rotating probe. Figure 6-6 illustrates a comparison of the sensitivity of the two types of examinations. The more sensitive rotating probe examinations were also performed on a region of tubes adjacent to the tubes with detected TTW. This region is also shown on Figures 6-7 and 6-8. TTW indications were identified in 161 tubes in 3E-088 and 165 tubes in 3E-089. All of the TTW flaws were located in the U-bend portion of the tubes between TSPs 7H and 7C (shown on Figure 6-1).

The more sensitive eddy current rotating probe provided an estimated depth and overall length of TTW flaws on each tube examined. The examination technique (EPRI Examination Technique Specification Sheet, ETSS 27902.2) was site validated by building a test specimen with flaws similar to the TTW flaws observed in Unit 3. Comparison of estimated wear depths with actual wear depths of the specimen supported the conclusion that ETSS 27902.2 conservatively estimated the depths across the entire range of depths tested (from 5% through-wall to 81% through-wall).

The tubes with flaws identified by ECT were analyzed to determine if they were capable of meeting the SONGS TS tube integrity performance criteria (Attachment 1). Tubes that did not meet the performance criteria based on analysis were tested via in-situ pressure testing. As described in detail in Section 5 and in the CM report (Attachment 3), a total of 129 tubes in the Unit 3 SGs were selected for in-situ pressure testing. Three tubes failed both the AILPC and the SIPC, and 5 tubes passed the AILPC but failed the SIPC as defined in TS 5.5.2.11. These eight tubes are listed in Table 5-1. Figure 6-7 and Figure 6-8 show the locations of the tubes that were in-situ tested and the eight tubes that did not meet the performance criteria.

Secondary side remote visual inspections were performed to supplement the eddy current results and provide additional information in support of the cause evaluation. The inspections included the 7th TSP and inner bundle passes at AVBs B04 and B09 (shown on Figure 6-1). The 7th TSP inspection revealed no unexpected or unusual conditions. The inner bundle passes included several inspections between columns 73 and 87 and showed instances of wear indications that extended outside the AVB intersection. This was confirmed by eddy current data. Additional passes were made between columns 50 and 60. These inspections did not show any AVB wear outside the AVB intersections.

6.2 Summary of Inspection Results

This section provides a summary of the different types of tube wear found in the SONGS Unit 2 and 3 SGs. Wear is characterized as a loss of metal on the surface of one or both metallic objects that are in contact during movement.

The following types of wear were identified in the SONGS Units 2 and 3 SG tubes:

- AVB wear - wear of the tubing at the tube-to-AVB intersections
- TSP wear - wear of the tubing at the tube-to-TSP intersections
- TTW - wear in the tube free-span sections between the AVBs located in the U-bend region.
- RB wear - wear of the tubing at a location adjacent to a RB (RBs are not designed as tube supports for normal operation)
- FO wear - wear of the tubing at a location adjacent to a FO.

Most of the tube wear identified in the SGs is adjacent to a tube support. Figure 6-1 is a side view of an SG, showing the relationship of the tubes to the two types of tube supports: TSPs in the straight portions and AVBs in the U-bend portions of the tubes. All tubes are adjacent to many of these two types of tube supports. The RB supports are not shown because a very small number of tubes are adjacent to them.

TTW indications occurred in the free span sections of the tubes. The “free span” is that section of the tube between support structures (AVBs and TSPs shown in Figure 6-1). TTW occurred almost exclusively in Unit 3 and is located on both the hot and cold leg side of the U-tube. In many cases, the region of the tube with TTW has two separate indications on the extrados and intrados of the tube. The wear indications on neighboring tubes have similar depth and position (ranging from 1.0 to 41 inches long and 4% to 100% throughwall) along the U-bend, confirming the tube-to-tube contact.

Table 6-1 provides the Wear Depth Summary for each of the four SGs based on eddy current examination results. Detailed results of the examinations performed are provided in the Units 2 and 3 CM reports included as Attachments 2 and 3. Figures 6-2 through 6-5 provide distributions of wear at AVB and TSP supports for all four SGs.

Figure 6-1: Steam Generator Section View Sketch




Figure 6-2: Unit 2 Distribution of Wear at AVB Supports




Figure 6-3: Unit 3 Distribution of Wear at AVB Supports




Figure 6-4: Unit 2 Distribution of Wear at TSP Supports




Figure 6-5: Unit 3 Distribution of Wear at TSP Supports




Figure 6-6: Probability of Detection for Tube Wear




Figure 6-7: 3E-088 Rotating Coil Inspection Region





Figure 6-8: 3E-089 Rotating Coil Inspection Region



SONGS Unit 2 Return to Service Report

Table 6-1: Steam Generator Wear Depth Summary

SG 2E-088							
TW Depth	AVB Wear Indications	TSP Indications	TTW Indications	Retainer Bar Indications	Foreign Object Indications	Total Indications	Tubes with Indications
TW ≥ 50%	0	0	0	1	0	1	1
35 - 49%	2	0	0	1	0	3	3
20 - 34%	86	0	0	0	2	88	74
10 - 19%	705	108	0	0	0	813	406
TW < 10%	964	117	0	0	0	1081	600
Total	1757	225	0	2	2	1986	734*
SG 2E-089							
TW Depth	AVB Wear Indications	TSP Indications	TTW Indications	Retainer Bar Indications	Foreign Object Indications	Total Indications	Tubes with Indications
TW ≥ 50%	0	0	0	1	0	1	1
35 - 49%	0	0	0	1	0	1	1
20 - 34%	78	1	0	3	0	82	67
10 - 19%	1014	85	2	0	0	1101	496
TW < 10%	1499	53	0	0	0	1552	768
Total	2591	139	2	5	0	2737	861*
SG 3E-088							
TW Depth	AVB Wear Indications	TSP Indications	TTW Indications	Retainer Bar Indications	Foreign Object Indications	Total Indications	Tubes with Indications
TW ≥ 50%	0	117**	48	0	0	165	74
35 - 49%	3	217	116	2	0	338	119
20 - 34%	156	506	134	1	0	797	197
10 - 19%	1380	542	98	0	0	2020	554
TW < 10%	1818	55	11	0	0	1884	817
Total	3357	1437	407	3	0	5204	919*
SG 3E-089							
TW Depth	AVB Wear Indications	TSP Indications	TTW Indications	Retainer Bar Indications	Foreign Object Indications	Total Indications	Tubes with Indications
TW ≥ 50%	0	91**	26	0	0	117	60
35 - 49%	0	252	102	1	0	355	128
20 - 34%	45	487	215	0	0	747	175
10 - 19%	940	590	72	0	0	1602	450
TW < 10%	2164	94	1	0	0	2259	838
Total	3149	1514	416	1	0	5080	887*

* This value is the number of tubes with a wear indication of any depth at any location. Since many tubes have indications in more than one depth category, the total number of tubes with wear indications is not the additive sum of the counts for the individual depth categories.

** All TSP indications ≥50% TW were in tubes with TTW indications.

6.3 Cause Analyses of Tube-to-Tube Wear in Unit 3

6.3.1 Mechanistic Cause

SCE established a RCE team to investigate the condition, extent of condition, and cause of the event in Unit 3 and to determine corrective actions. The RCE was conducted, documented, and reviewed in accordance with the SONGS Corrective Action Program (CAP). The RCE Team used systematic approaches to identify the mechanistic cause of the TTW, including failure modes analysis (Kepner-Tregoe). The RCE team had access to and used significant input from the SG Recovery Team, which included the services of MHI and industry experts in the fields of T/H and in SG design, manufacturing, operation, and repair.

The failure modes analysis identified a list of 21 possible causes. The list was narrowed down, using facts, analysis, and expert input, to a list of eight potential causes that warranted further technical evaluation. The potential causes included manufacturing/fabrication, shipping, primary side flow induced vibration, divider plate weld failure and repair, additional rotations following divider plate repair, TSP distortion, tube bundle distortion during operation (flowering), and T/H conditions/modeling.

The eight potential causes underwent rigorous analysis using both empirical and theoretical data, and support-refute methodology. This approach identified likely causes and eliminated non-causes. Each of the potential causes was evaluated by engineering analysis of the supporting and refuting data. The mechanistic cause of the TTW in Unit 3 was identified as FEI, involving the combination of localized high steam velocity (tube vibration excitation forces), high steam void fraction (loss of ability to dampen vibration), and insufficient tube to AVB contact to overcome the excitation forces. A more detailed discussion of the cause of FEI in the Unit 3 SGs is provided in MHI's Technical Evaluation Report, which is included as Attachment 4.

6.3.2 Potential Applicability of Unit 3 TTW Causes to Unit 2

At the time of the Unit 3 SG tube leak, Unit 2 was in the first refueling outage after SG replacement and undergoing ECT inspections per the SGP. Following the discovery of TTW in Unit 3, additional Unit 2 inspections identified two tubes with TTW indications in SG 2E-089. The location of TTW in the Unit 2 SG was in the same region of the bundle as in the Unit 3 SGs indicating causal factors might be similar to those resulting in TTW in the Unit 3 SGs. Because of the similarities in design between the Unit 2 and 3 RSGs, it was concluded that FEI in the in-plane direction was also the cause of the TTW in Unit 2.

After the RCE for TTW was prepared, WEC performed analysis of Unit 2 ECT data and concluded TTW was caused by the close proximity of these two tubes during initial operation of the RSGs. With close proximity, normal vibration of the tubes produced the wear at the point of contact. With proximity as the cause, during operation the tubes wear until they are no longer in contact, a condition known as 'wear arrest'. This wear mechanism is addressed in Section 10 and Attachment 6.

As described in Section 8, the compensatory and corrective actions implemented to prevent loss of tube integrity caused by TTW in Unit 2 are sufficient to conservatively address both identified causes.

6.4 Industry Expert Involvement

Upon discovery of TTW in Unit 3, SCE commissioned the services of industry experts to assist in assessing the cause of this phenomenon. SCE selected experts based upon their previous experience in design, evaluation, tube vibration, testing and causal determinations related to SGs. Members included experts in T/H and SGPs from MPR Associates, AREVA, Babcock & Wilcox Canada, Palo Verde Nuclear Generating Station, EPRI, Institute of Nuclear Power Operations (INPO), and MHI, as well as experienced consultants including former NRC executives and a research scientist. A series of panel meetings were conducted during which testing and analysis results were presented. The panel members assessed whether the current work by SCE and its partners was sufficient in understanding the TTW phenomenon and whether the corrective actions developed were sufficient to ensure tube integrity in the future.

6.5 Cause Analysis Summary

SCE has determined the mechanistic cause of the TTW in Unit 3 was FEI, resulting from the combination of localized high steam velocity, high steam void fraction, and insufficient contact forces between the tubes and the AVBs. The FEI resulted in a vibration mode of the SG tubes in which the tubes moved in the in-plane direction, parallel to the AVBs, in the U-bend region. This resulted in TTW in a localized area of the SGs. As discussed in the following sections, SCE has identified actions to prevent loss of integrity due to FEI in the Unit 2 SG tubes. The extent of condition inspections performed in Unit 2 and differences identified between Units 2 and 3 are discussed in Section 7. The compensatory and corrective actions to prevent loss of integrity due to these causes in the Unit 2 SG tubes are discussed in Section 8.

7.0 UNIT 2 CYCLE 17 INSPECTIONS AND REPAIRS

On January 9, 2012, Unit 2 was shut down for a routine refueling and steam generator inspection outage after approximately 22 months of operation. As discussed in Section 3.3, the SGP requires a CM assessment to confirm that SG tube integrity has been maintained during the previous inspection interval. SCE conducted a number of inspections on each of the two Unit 2 SGs (2E-088 and 2E-089) in accordance with the SGP. Based on the inspection results, the Unit 2 CM assessment (included as Attachment 2) concluded that the TS SG performance criteria were satisfied by the Unit 2 SGs during the operating period prior to the current U2C17 outage. The TS performance criteria for tube integrity for all indications were satisfied through a combination of ECT examination, analytical evaluation, and in-situ pressure testing. The operational leakage criterion was satisfied because the Unit 2 SGs experienced no measurable primary-to-secondary leakage during the operating period preceding the Cycle 17 outage.

The Unit 2 outage was in progress on January 31, 2012, when Unit 3 was shut down in response to a tube leak. Although the SG performance criteria had been met by the Unit 2 SGs, the unit was not returned to service pending an evaluation of the tube leak in Unit 3. Subsequent to the discovery of TTW conditions in the U-bend region of the Unit 3 SGs, additional inspections were performed on the Unit 2 tubes and shallow TTW was identified in two adjacent tubes in SG 2E-089.

Section 7.1 provides a summary of results from the routine inspections performed in Unit 2 and Section 7.2 provides a summary of results from the additional Unit 2 inspections performed in response to the discovery of TTW in Unit 3. Details of all the inspections are provided in the Unit 2 CM report (Attachment 2). Section 7.3 summarizes the differences observed between Units 2 and 3.

7.1 Unit 2 Cycle 17 Routine Inspections and Repairs

The SGP requires that a DA be performed prior to a SG inspection outage to develop an inspection plan based on the type and location of flaws to which the tubes may be susceptible. This assessment was performed prior to the inspection and was updated when unexpected degradation mechanisms were found during the inspection. These unexpected degradation mechanisms included (1) RB wear and (2) the TTW observed in Unit 3.

Initially, eddy current bobbin probe examinations of the full length of each tube was performed on 100% of the tubes in both Unit 2 SGs. Selected areas were then inspected using a more sensitive rotating +Point™ examination. During the ECT examinations, wear was detected at AVBs, TSPs and RB locations. Six tubes with high wear indications (equal to or exceeding 35% of the tube wall thickness) were found. Four of those indications occurred in the vicinity of the RBs and two were associated with AVB locations as shown in Table 6-1. One in-situ pressure test was performed on a tube with RB wear, with satisfactory results. No other indications required in-situ pressure testing. Numerous smaller depth wear indications were also reported at other AVB and TSP locations. The ECT results are summarized in Table 6-1.

In accordance with TS 5.5.2.11.c, tubes that are found to have indications of degradation equal to or exceeding 35% through wall (TW) are removed from service by the installation of a plug in both ends of the tube. Once plugs are installed in both ends of a tube, they prevent primary system water from entering the tube. Plugs may also be used to preventively remove tubes from service. Use of preventive plugging is discussed in Section 8.2.

An RCE was completed for the unexpected RB wear. The RCE concluded that the RB size (diameter and length) was inadequate to prevent the RB from vibrating and contacting adjacent tubes during normal plant operation. The vibration source was a turbulent two phase flow (water and steam) across the RBs. As a corrective action, the 94 tubes adjacent to the RBs in each Unit 2 SG were plugged, including two tubes with RB wear in SG 2E-088 and four tubes with RB wear in SG 2E-089.

SONGS Unit 2 Return to Service Report

Four additional tubes were plugged due to wear at AVB locations. Two of these were plugged as required for wear depths equal to or exceeding 35% TW; the other two with through wall depths (TWDs) of approximately 32% were plugged as a preventive measure. A significant number of tubes were preventively plugged and removed from service using screening criteria based on TTW indications in Unit 3. Table 6-1 provides the total numbers of tubes and indications due to all types of wear in the Unit 2 SGs. The tubes and criteria used to select tubes to be removed from service by preventive plugging due to their susceptibility to TTW are discussed in Section 8.2 and Attachment 5.

During the eddy current inspection of SG 2E-088, FO indications and FO wear indications were reported in two adjacent tubes at the 4th TSP. A secondary side foreign object search and retrieval (FOSAR) effort was performed and the object was located and removed. A follow-up analysis identified the object as weld metal debris. The two adjacent tubes were left in service because the indications were below the TS plugging limit and the cause of the degradation had been removed.

Remote visual inspections were performed to confirm the integrity of the RBs. The results of these visual inspections are summarized below:

- No cracking or degradation of RBs or RB-to-retaining bar welds was observed
- No cracking or degradation of AVB end caps or end cap-to-RB welds was observed
- No FOs or loose parts were found in the RB locations

Post sludge lancing FOSAR examination at the top-of-tubesheet (periphery and the no-tube lane) found no evidence of degradation and no FOs.

7.2 Unit 2 Cycle 17 Inspection in Response to TTW in Unit 3

Subsequent to the discovery of TTW conditions in the U-bend region of Unit 3 SGs, an additional review of the U-bend region bobbin probe data was performed for the Unit 2 SGs. The tubes selected for review encompassed the suspected TTW zone as observed in Unit 3 and tubes surrounding that zone. Over 1,000 tubes in each Unit 2 SG were reviewed. The review included a two-party manual analysis (primary/secondary) of the complete U-bend with emphasis on the detection of low level freespan indications, which may not have been reported during the original analysis of the U2C17 bobbin coil data. No new indications were identified during this review.

Additional examinations of the U-bends were performed using rotating probe (+Point™) technology. The scope of this examination is identified on the tubesheet maps provided in Figure 7-1 and Figure 7-2. During this examination, two adjacent tubes with TTW indications were detected. The indications were approximately 6 inches long, located between AVBs B09 and B10 in tubes R111 C81 and R113 C81 in SG 2E-089. Figure 7-2 shows the location of the two tubes with TTW in 2E-089. The maps in Figure 6-7 and Figure 6-8 show the inspection region overlaying the locations of the TTW found in the Unit 3 SGs.

SCE notified the NRC of the discovery of the two tubes with TTW in a letter dated April 20, 2012. (Ref. 9)

Remote visual inspections of the secondary side upper tube bundle were conducted in the Unit 2 SGs. These inspections were similar to those performed in Unit 3 SGs to assist in the development of the mechanistic root cause of TTW and tube wear at RB locations. No indications of TTW or other conditions associated with the FEI in Unit 3 (i.e., AVB wear extending outside the supports) were observed.

Rotating Pancake Coil ECT and Ultrasonic Testing (UT) were performed to measure the tube-to-AVB gap sizes in the Unit 2 SGs. Tube-to-AVB gap data was used to validate the contact force distribution model used in the TTW OA, (Attachment 6, Appendix B).

Figure 7-1: 2E-088 Rotating Coil Inspection Region





Figure 7-2: 2E-089 Rotating Coil Inspection Region



7.3 Differences between Units 2 and 3

As discussed in Section 6, inspections of the Unit 3 SG's found significant levels of TTW while Unit 2 SGs were limited to two shallow indications at one area of contact between two tubes.

A comparison of TTW and of factors associated with TTW between Unit 2 and Unit 3 SGs is provided below:

Table 7-1: TTW Comparison between Unit 2 and Unit 3 SGs

Description	Unit 2	Unit 3
TTW Indications	2	823
TTW Tubes	2	326
Max Depth (ECT %TW)	14%	99%
Max Length (inches)	~6	~41
TTW In-Situ Pressure Tests	0	129
TTW In-Situ Pressure Tests (Unsatisfactory)	0	8
Operating Period (EFPD)	627	338

In addition to the above parameters, differences in manufacturing dimensional tolerance dispersion (distribution of dimensional values for manufacturing parameters that remain within acceptable tolerances) exist between the Units 2 and 3 SGs. Manufacturing process improvements implemented during the fabrication of the Unit 3 SGs resulted in lower manufacturing dispersion than in the Unit 2 SGs. MHI concluded that the reduced manufacturing dispersion in the Unit 3 SGs resulted in smaller average tube-to-AVB contact force than in the Unit 2 SGs. Due to the smaller average tube-to-AVB contact force, Unit-3 was more susceptible to in-plane vibration.

8.0 UNIT 2 CORRECTIVE AND COMPENSATORY ACTIONS TO ENSURE TUBE INTEGRITY

SCE has implemented the following corrective and compensatory actions to prevent the loss of SG tube integrity due to TTW in Unit 2:

1. Limiting Unit 2 to 70% power prior to a mid-cycle SG inspection outage (CAL Response Commitment 1)
2. Preventively plugging tubes in both SGs (complete)
3. Shutting down Unit 2 for a mid-cycle SG inspection outage within 150 cumulative days of operation at or above 15% power (CAL Response Commitment 2)

The actions to operate at reduced power and perform a mid-cycle inspection within 150 cumulative days of operation are interim compensatory actions. SCE will reevaluate these actions during the mid-cycle inspection using data obtained during the inspections. In addition, SCE has established a project team to develop and implement a long term plan for repairing the SGs. SCE will keep the NRC informed of any findings or developments in the future.

SCE has performed an OA to assess the adequacy of the compensatory actions taken in Unit 2. The OA results demonstrate that operating at 70% power level will prevent loss of tube integrity due to TTW. In particular, reducing power to 70% eliminates the T/H conditions that cause FEI and associated TTW from the SONGS Unit 2 SGs. The OA and supporting analyses are summarized in Section 10 and provided in Attachment 6.

8.1 Limit Operation of Unit 2 to 70% Power

SCE will administratively limit Unit 2 to 70% reactor power prior to a mid-cycle SG inspection outage. The cause of the TTW in the Unit 3 SGs was in-plane tube vibration due to FEI, resulting in tube-to-tube contact and wear. An indication of whether a tube is susceptible to FEI is a calculated term defined as the stability ratio (SR). The SR calculation takes into account T/H conditions (including fluid flow and damping) and tube support conditions and provides a measure of the margin to a critical velocity value at which the tubes may experience the onset of instability due to FEI. The OA and its supporting analyses provided in Section 10 and Attachment 6 demonstrate that operating at 70% power will result in acceptable SRs in Unit 2.

Three independent comparisons were performed of the T/H parameters of SONGS RSGs operating at 100% and 70% power. SONGS RSG's were compared with five operating plants with recirculating SGs of similar design that have not observed TTW. The SONGS RSG's were also compared with the SONGS OSGs. The comparisons were conducted as follows:

- (1) SCE Engineering conducted a study of average T/H parameters
- (2) WEC performed an Analysis of Thermal-Hydraulics of Steam Generators (ATHOS) study of SONGS RSGs to OSGs
- (3) An industry expert in SG design performed an independent ATHOS comparison of T/H parameters that can influence FEI

Based on these comparisons, Plant A was selected for detailed analysis due to similarity of design characteristics and thermal power rating. Both SONGS and Plant A SGs use a U-bend design with the same tube diameter and pitch. Plant A operates at 1355 megawatts thermal per SG (MWt/SG) bounding the SONGS RSGs at 70% power (1210 MWt/SG). Plant A RSGs and SONGS RSGs utilize out-of-plane AVBs in the U-bend. Plant A RSGs have operated for two fuel cycles without indications of TTW.

SONGS Unit 2 Return to Service Report

Results of the comparisons of three T/H parameters (steam quality, void fraction, and fluid velocity) are presented in the following subsections. These results demonstrate that operating SONGS SGs at 70% power improves the T/H parameters to values lower than those in Plant A at 100% power.

Steam Quality

Steam quality, defined as mass fraction of vapor in a two-phase mixture, is an important factor used in determining SRs. Steam quality is directly related to void fraction for a specified saturation state. This description is important when considering effects on damping. Damping is the result of energy dissipation and delays the onset of FEI. Damping is greater for a tube surrounded by liquid compared to a tube surrounded by gas. Since quality describes the mass fraction of vapor in a two-phase mixture, it provides insight into the fluid condition surrounding the tube. A higher steam quality correlates with dryer conditions and provides less damping. Conversely, lower steam quality correlates with wetter conditions resulting in more damping, which decreases the potential for FEI.

Steam quality also directly affects the fluid density outside the tube, affecting the level of hydrodynamic pressure that provides the motive force for tube vibration. When the energy imparted to the tube from hydrodynamic pressure (density times velocity squared or ρv^2) is greater than the energy dissipated through damping, FEI will occur. When steam quality decreases, the density of the two-phase mixture increases, decreasing velocity. Since the hydrodynamic pressure is a function of velocity squared, the velocity term decreases faster than the density increases. Small decreases in steam quality significantly decrease hydrodynamic pressure and the potential for FEI.

Steam quality in the SONGS RSGs was calculated for 100% and 70% power using the industry expert's independent ATHOS model and compared to Plant A at 100% power. The results of the calculations are summarized in Table 8-1 and graphically presented in Figure 8-1.

Limiting SONGS power to 70% reduces steam quality and hydrodynamic pressure to values less than Plant A. Plant A has not experienced TTW.


Table 8-1: Independent ATHOS Comparison Results – Steam Quality

	SONGS 100%	SONGS 70%	Plant A 100%
Thermal Power (MWt)	1715	1199	1368
Primary Inlet Temp (°F)	597.8	589.1	596.0
Maximum Mixture Density (kg/m3)	782	772	782
Minimum Mixture Density (kg/m3)	34	97	43
Maximum Dynamic Pressure (N/m2)	4140	2430	4220
Maximum Steam Quality	0.876	0.312	0.734


Note: The thermal power levels were calculated in the independent ATHOS comparison.

Figure 8-1: Steam Quality Contour Plots for 100% Power and 70% Power

100% Power (Maximum Steam Quality = 0.876 from Independent ATHOS T/H Comparison)



70% Power (Maximum Steam Quality = 0.312)



Void Fraction

Void fraction, defined as volume fraction of vapor in a two-phase mixture, is a factor used in determining SRs. A higher void fraction represents a lower percentage of liquid in the steam. Liquid in the steam dampens the movement of tubes. Higher void fractions result in less damping. Decreasing the void fraction in the upper bundle region during power operation increases damping and reduces the potential for FEI.

The void fraction in the SONGS RSGs was calculated at 100% and 70% power using ATHOS models from MHI, an independent industry expert, and WEC. The results are summarized in Table 8-2.

A significant effect of limiting power to 70% is the elimination of void fractions greater than Plant A. Plant A has not experienced TTW.


Table 8-2: Comparison of Maximum Void Fraction

	SONGS 100%	SONGS 70%	Plant A 100%	SONGS OSGs 100%
Thermal Power (MWt)	1729	1210	1355	1709
Bend Type	U-Bend	U-Bend	U-Bend	Square Bend
MHI ATHOS T/H Results	0.996	0.927	-	-
Independent ATHOS T/H Comparison	0.994	0.911	0.985	-
WEC ATHOS T/H Comparison	0.9955	0.9258	-	0.9612

Note: Not all sources had access rights to the ATHOS models of some of the comparison plants, resulting in blank cells in this table.

Void fractions at the locations of tubes with TTW in the RSGs are shown in Figure 8-2. The figure demonstrates that the occurrence of TTW was limited to tubes operating with maximum void fractions of greater than 0.993.

Figure 8-2: Maximum Void Fraction versus Power Level and Ratio of Tube Wear versus Maximum Void Fraction



Wear indication on tubes which are located in the region where max void fraction exceeds 0.993

By limiting power to 70% as presented in Table 8-2, void fractions are reduced to levels well below those associated with the TTW experienced at 100% power in the SONGS RSGs.

Fluid Velocity

The fluid velocity in a steam generator’s secondary side is a factor in SR calculations. Hydrodynamic pressure is the fluid velocity squared multiplied by the fluid density (ρv^2) and is described in the “Steam Quality” section above.

The results of the velocity calculations are summarized in Table 8-3 and a graphical presentation of the results throughout a SG is shown in Figure 8-3. Interstitial velocity is a representative average velocity of flow through a porous media, which accounts for the structures and flow obstructions in the flow path.

Table 8-3: Comparison of Maximum Interstitial Velocity (ft/s)

	SONGS 100%	SONGS 70%	Plant A 100%	SONGS OSGs 100%
Thermal Power (MWt)	1729	1210	1355	1709
Bend Type	U-Bend	U-Bend	U-Bend	Square Bend
MHI ATHOS T/H Results	23.60	13.38	-	-
Independent ATHOS T/H Comparison	22.08	11.91	17.91	-
WEC ATHOS T/H Comparison	28.30	13.28	-	22.90


Note: Not all sources had access rights to the ATHOS models of some of the comparison plants, resulting in blank cells in this table.

An additional analysis of velocity at different locations along a tube at 100% and 70% power was performed by WEC. This analysis used gap velocity, which relates to interstitial velocity through the geometric arrangement of the tube bundle and the angle of incidence between the fluid flow and tube (interstitial velocity multiplied by a surface porosity based on the tube bundle geometry). Tube R141 C89 has the longest bend radius in the bundle and relatively high gap velocities. A significant reduction in gap velocity for this tube occurs in the U-bend (mainly the hot leg side) when power is limited to 70%. The results for 2E-088 are shown in Figure 8-4, and results for 2E-089 are shown in Figure 8-5. The slight differences in the plots for the two SGs are caused by differences in numbers and locations of plugged tubes.

Limiting power to 70% significantly reduces fluid velocity. The reduction in fluid velocity significantly reduces the potential for FEI.

Figure 8-3: Interstitial Velocity Contour Plots for 100% Power and 70% Power

100% Power (Maximum Interstitial Velocity = 6.73 m/s = 22.08 ft/s
from Independent ATHOS T/H Comparison)



70% Power (Maximum Interstitial Velocity = 3.63 m/s = 11.91 ft/s)






Figure 8-4: Gap Velocity at 100% power and 70% power for 2E-088 R141C89



* Note: Two lines are shown for 70% power because separate ATHOS simulations were run for each half of the tube bundle due to the asymmetrical plugging in the SG

Figure 8-5: Gap Velocity at 100% power and 70% power for 2E-089 R141C89



* Note: Two lines are shown for 70% power because separate ATHOS simulations were run for each half of the tube bundle due to the asymmetrical plugging in the SG.

MHI's ATHOS model was used to calculate the T/H input parameters for the SR calculations. ATHOS is an EPRI computer program used by SG design companies in North America. SCE commissioned two independent T/H analyses to verify the MHI ATHOS analysis. These independent verifications were performed by WEC using ATHOS and AREVA using their T/H computer code CAFCA4. MPR Associates compared the three T/H analyses (MHI ATHOS, WEC ATHOS, and AREVA CAFCA4) and concluded the models predicted similar void fraction, quality, and velocity results.

8.2 Preventive Tube Plugging for TTW

Tubes were identified for preventive plugging using correlations between wear characteristics in Unit 3 tubes and wear patterns at AVBs and TSPs in Unit 2. The screening criteria used to select these tubes is discussed in Section 8.2.1. Removing these tubes from service prevents future wear from challenging SG performance criteria for structural and leakage integrity. These tubes were plugged in addition to the 4 tubes plugged for AVB wear and the 182 tubes plugged as a preventive measure against potential RB wear (described in Section 7.1). A summary of all tubes selected for plugging in Unit 2 is provided in Table 8-4. The impact on operations of the plugged tubes is discussed in Section 8.2.2.

8.2.1 Screening Criteria for Selecting Tubes for Plugging

After identification of the TTW in Unit 3, additional examinations of the susceptible region in Unit 2 identified shallow TTW on two adjacent tubes. Although the 14% TW depth of these indications was below the TS plugging threshold of 35%, the tubes were stabilized and plugged to reduce the risk of tube failure due to continued wear. Using screening criteria developed by MHI from TTW indications in Unit 3, SCE selected 101 tubes in 2E-088 and 203 tubes in 2E-089 for preventive plugging. Nine screening criteria were identified using the quantity and location of AVB and TSP wear indications, length of AVB wear indications, average void fraction over the length of the tube, location of the tube within the tube bundle, and coupling between adjacent susceptible tubes. These criteria are provided in Attachment 5.

Table 8-4 provides a summary of all the tubes selected for plugging in Unit 2. The locations of the Unit 2 tubes selected for plugging and stabilization using the preventive plugging criteria are shown in Figure 8-6 and Figure 8-7. Additional screening criteria was provided by industry expert review (wear at 6 Consecutive AVBs) and WEC (TSP wear).

Table 8-4: Unit 2 Steam Generator Tube Plugging Summary

Steam Generator	TWD \geq 35% at AVB	TWD 30-35% at AVB	Wear at RB	TTW	Preventive Retainer Bar	TTW Preventive			Total Tubes Selected
						MHI Screening Criteria	Wear at 6 Consecutive AVBs	WEC Screening Additions	
2E-088	2	2	2	0	92	101	6	2	207
2E-089	0	0	4	2	90	203	6	3	308

Figure 8-6: 2E-088 Plugging and Stabilizing Map





Figure 8-7: 2E-089 Plugging and Stabilizing Map



8.2.2 Plant Operations with Tubes Plugged in Unit 2

Results from MHI's ATHOS calculations were used to analyze the effect of the plugged region on tubes remaining in service. The T/H parameters evaluated were:

- Maximum void fraction, velocity, and hydrodynamic pressure along the U-bend
- Average void fraction, velocity, and hydrodynamic pressure along the hot leg portion of the U-bend
- Average void fraction, velocity, and hydrodynamic pressure along the U-bend

The effect of 4% tube plugging on the remaining in-service tubes was evaluated and determined to be insignificant.

With power limited to 70%, there is no adverse impact on surrounding tubes of the preventive plugging in the Unit 2 SGs.

8.3 Inspection Interval and Protocol of Mid-cycle Inspections

As demonstrated in Section 8.1, limiting operations to 70% power significantly reduces the potential for FEI and improves tube stability margins. To provide additional safety margin, the Unit 2 inspection interval has been limited to 150 days of operation at or above 15% power. The protocol for the inspections to be performed during the mid-cycle outage is described below. (CAL Response Commitment 2)

8.3.1 Inspection of Inservice Tubes (Unplugged)

The following inspections will be performed during the mid-cycle SG inspection outage:

- Eddy Current Bobbin Coil Examinations of the full length of all in-service tubes
- Rotating Coil Examinations of the following areas:
 - a. U-bend region – inspection scope will repeat the pattern used during the refueling outage. (~1300 tubes/SG)
 - b. TSP and AVB wear bobbin coil indications $\geq 20\%$
- Visual inspection of small diameter RBs and welds

8.3.2 Inspection of Plugged Tubes

Plugged tubes will be inspected to determine if the compensatory and corrective actions (plugging and operating at reduced power) have been effective. The following inspections and evaluations are planned:

- Visual examination will be performed on all installed tube plugs
- 12 tubes in each SG will be unplugged and the stabilizer(s) removed to assess the effectiveness of the TTW compensatory and corrective actions. Following these inspections, all tubes will be re-plugged and stabilizers installed. The tubes will be selected as follows:
 - The 2 tubes with previous TTW indications
 - 5 tubes adjacent to tubes with TTW wear
 - 5 tubes selected from representative locations that were preventively plugged as part of the compensatory and corrective actions for TTW



Unit 2 Return to Service Report

- Any new TTW and TSP ECT indications will be assessed to determine if they are the result of FEI during the prior operating period or are cases of previously undetected wear (less than the probability of detection for the ECT probes used during the prior inspection).
- Confirmed new TTW or increases in TTW indication size beyond ECT uncertainty will require a review of the corrective actions implemented during the current inspection.

9.0 UNIT 2 DEFENSE-IN-DEPTH ACTIONS

As described in Section 8, Section 10, and Attachment 6, the compensatory and corrective actions taken by SCE eliminate the T/H conditions that cause FEI and associated TTW from the SONGS SGs. Nonetheless, SCE has developed DID measures to provide an increased safety margin even if tube-to-tube degradation in the Unit 2 SGs were to occur. The following actions have been taken to improve the capability for early detection of a SG tube leak and ensure immediate plant operator response.

9.1 Injection of Argon into the Reactor Coolant System (RCS)

Plant design has been modified to allow periodic injection of Argon (Ar-40) into the RCS. Ar-40 is activated over a short period of time to become Ar-41. The increased RCS activity makes it easier to detect primary-to-secondary tube leaks.

9.2 Installation of Nitrogen (N-16) Radiation Detection System on the Main Steam Lines

Plant design will be modified prior to Unit 2 startup (entry into Mode 2) by installing a temporary N-16 radiation detection system (CAL Response Commitment 3). This system is in addition to existing radiation monitoring systems and includes temporary N-16 detectors located on the main steam lines. This system provides earlier detection of a tube leak and initiation of operator actions.

9.3 Reduction of Administrative Limit for RCS Activity Level

The plant procedure for chemical control of primary plant and related systems has been modified to require action if the specific activity of the reactor coolant Dose Equivalent (DE) Iodine (I-131) exceeds the normal range of 0.5 $\mu\text{Ci/gm}$, which is one-half of the TS Limit of 1.0 $\mu\text{Ci/gm}$. In the event that the normal range is exceeded, Operations is required to initiate the Operational Decision Making process to evaluate continued plant operation.

9.4 Enhanced Operator Response to Early Indication of SG Tube Leakage

9.4.1 Operations Procedure Changes

The plant operating procedure for responding to a reactor coolant leak has been modified to require plant Operators to commence a reactor shutdown upon a valid indication of a primary-to-secondary SG tube leak at a level less than allowed by the plant's TSs. This procedure change requires earlier initiation of operator actions in response to a potential SG tube leak.

9.4.2 Operator Training

Plant Operators will receive training on use of the new detection tools for early tube leak identification (e.g., plant design changes described above), and lessons learned in responding to the January 31, 2012, Unit 3 shutdown due to a SG tube leak (CAL Response Commitment 4). This training will enhance operator decision making and performance in responding to an indication of a SG tube leak and will be completed prior to plant startup.

10.0 UNIT 2 OPERATIONAL ASSESSMENT

As defined in NEI 97-06 (Ref. 2), the OA is a “Forward looking evaluation of the SG tube conditions that is used to ensure that the structural integrity and accident leakage performance will not be exceeded during the next inspection interval.” The OA projects the condition of SG tubes to the time of the next scheduled inspection outage and determines their acceptability relative to the TS tube integrity performance criteria (Attachment 1).

As required by the CAL (Ref. 1), SCE has prepared an assessment of the Unit 2 SGs that addresses the causes of TTW wear found in the Unit 3 SGs, prior to entry of Unit 2 into MODE 2. The OA provided in Attachment 6 provides that assessment.

Due to the significant levels of TTW found in Unit 3 SGs, SCE has assessed the likelihood of additional TTW in Unit 2 from several different perspectives involving the experience and expertise of AREVA, WEC, and Intertek/APTECH. These companies developed independent OAs to address the TTW found at SONGS. These OAs apply different methodologies to ensure a comprehensive and diverse evaluation. The results of these analyses fulfill the TS requirement to demonstrate that SG tube integrity will be maintained until the next SG inspection. The OAs demonstrate that limiting operation to 70% power will prevent loss of tube integrity due to TTW. In particular, reducing power to 70% eliminates the T/H conditions that cause FEI and associated TTW from the SONGS Unit 2 SGs. The reduced 150 cumulative day inspection interval provides additional safety margin beyond the longer allowable inspection intervals identified in the OAs.

11.0 ADDITIONAL ACTIONS

As previously discussed, the OAs performed by AREVA, WEC, and Intertek/APTECH confirm that the compensatory and corrective actions implemented by SCE will result in continued safe operation of Unit 2 and that SG tube integrity will be maintained. SCE also implemented conservative DID measures to minimize the impact on public and environmental health and safety even if tube integrity were compromised. Additionally, SCE is establishing enhanced plant monitoring capability as described below.

11.1 Vibration Monitoring Instrumentation

The Vibration and Loose Parts Monitoring System (VLPMS) is designed in accordance with NRC Regulatory Guide 1.133, "Loose-Part Detection Program for the Primary System of Light-Water-Cooled Reactors" to detect loose metallic parts in the primary system. VLPMS includes accelerometers mounted externally to the SGs. The VLPMS sensors detect acoustic signals generated by loose parts and flow. The signals from these sensors are compared with preset alarm setpoints. Validated alarms are annunciated on a panel in the control room.

To improve sensitivity of the VLPMS, the system is being upgraded to WEC's Digital Metal Impact Monitoring System (DMIMS-DX) during U2C17 refueling outage (CAL Response Commitment 5). The following improvements will be implemented by the upgrade:

- Relocation of existing VLPMS accelerometers (2 per SG) from the support skirt to locations above and below the tubesheet. These will remain as VLPMS sensors to meet Regulatory Guide 1.133.
- Increased sensitivity accelerometers (2 per SG) will be installed at locations above and below the tubesheet.
- Increased sensitivity accelerometers (2 per SG) will be installed on an 8 inch hand hole high on the side of the SGs to monitor for secondary side noises at the upper tube bundle.

The upgraded system will provide SCE with additional monitoring capabilities for secondary side acoustic signals.

11.2 GE Smart Signal™

SCE will utilize GE Smart Signal™, which is an analytic tool that aids in diagnosis of equipment conditions (CAL Response Commitment 6). The tool will be used to analyze historical plant process data from the Unit 2 SGs following the inspection interval.

12.0 CONCLUSIONS

As noted in Reference 1, the SG tube wear that caused a Unit 3 SG tube to leak on January 31, 2012, was the result of tube-to-tube interaction. This type of wear was confirmed to exist in a number of other tubes in the same region in both Unit 3 SGs. Subsequent inspections of the Unit 2 SGs identified this type of wear also existed in two adjacent tubes in Unit 2 SG E-089.

To determine the cause of the TTW, SCE performed extensive inspections and analyses. SCE commissioned experts in the fields of T/H and in SG design, manufacturing, operation, and repair to assist with these efforts. Using the results of these inspections and analyses, SCE determined the cause of the TTW in the two Unit 3 SGs was FEI, caused by a combination of localized high steam velocity, high steam void fraction, and insufficient contact forces between the tubes and the AVBs. FEI caused in-plane tube vibration that resulted in TTW in a localized region of the SGs. The TTW in Unit 2 SG E-089 may have been caused by FEI, or alternatively, close proximity of the two tubes may have led to TTW from normal vibration.

SCE determined the TTW effects were much less severe in Unit 2 where two tubes were identified with TTW indications of less than 15% TW wear. These two tubes are located in the same region of the SGs as those with TTW in Unit 3. Given that the T/H conditions are essentially the same in both units, the less severe TTW in Unit 2 is attributed to manufacturing differences. Those differences increased tube-to-AVB contact forces in Unit 2, providing greater tube support.

To prevent loss of SG tube integrity due to TTW in Unit 2, SCE has implemented interim compensatory and corrective actions and established a protocol of inspections and operating limits. These include:

1. Limiting Unit 2 to 70% power prior to a mid-cycle SG inspection outage (CAL Response Commitment 1)
2. Preventively plugging tubes in both SGs (complete)
3. Shutting down Unit 2 for a mid-cycle SG inspection outage within 150 cumulative days of operation at or above 15% power (CAL Response Commitment 2)

On the basis of the compensatory and corrective actions discussed in Section 8, the DID actions presented in Section 9, and the results of the OAs presented in Section 10 and Attachment 6, SCE concludes that Unit 2 will operate safely at 70% power for 150 cumulative days of operation. Reducing power to 70% eliminates the T/H conditions that cause FEI and associated TTW from the SONGS Unit 2 SGs. SCE will continue to closely monitor SG tube integrity, perform SG inspections during the mid-cycle outage, and take compensatory and corrective actions to ensure the health and safety of the public.

13.0 REFERENCES

- 1 Confirmatory Action Letter (CAL) – Letter from Elmo E. Collins (NRC) to Peter T. Dietrich (SCE), dated March 27, 2012, Confirmatory Action Letter 4-12-001, San Onofre Nuclear Generating Station, Units 2 and 3, Commitments to Address Steam Generator Tube Degradation
- 2 Nuclear Energy Institute NEI 97-06, Steam Generator Program Guidelines, Revision 3, January 2011
- 3 Electric Power Research Institute (EPRI), Pressurized Water Reactor Steam Generator Examination Guidelines
- 4 EPRI 1019038, 1019038 Steam Generator Management Program: Steam Generator Integrity Assessment Guidelines, Revision 3, November 2009
- 5 Event Notification Number 47628 - Telephone notification, Manual Trip Due to a Primary to Secondary Leak, made to the NRC Emergency Notification System (ENS) as required by 10 CFR 50.72(b)(2)(iv)(B)
- 6 Event Notification Number 47744 (including 2 followups) - Telephone notifications, Unit 3 Steam Generator Tubes Failed In-Situ Pressure Testing, made to the NRC ENS as required by 10 CFR 50.72(b)(3)(ii)(A)
- 7 Unit 3 LER 2012-001, dated March 29, 2012, Manual Reactor Trip Due to the SG Tube Leak as required by 10 CFR 50.73(a)(2)(iv)(A), actuation of the Reactor Protection System
- 8 Unit 3 LER 2012-002, dated May 10, 2012, SG Tube Degradation Indicated by Failed In-situ Pressure Testing as required by 10 CFR 50.73(a)(2)(ii)(A), a condition which resulted in a principal safety barrier being seriously degraded (i.e., serious SG tube degradation)
- 9 Letter from Peter T. Dietrich (SCE) to Elmo Collins (USNRC), dated April 20, 2012, Update of Unit 2 SG Tube Inspection Results
- 10 SONGS Steam Generator Program (SO23-SG-1)

ATTACHMENT 1

SONGS Unit 2 Relevant Technical Specifications

3.4 REACTOR COOLANT SYSTEM (RCS)

3.4.17 Steam Generator (SG) Tube Integrity

LCO 3.4.17 SG tube integrity shall be maintained.

AND

All SG tubes satisfying the tube repair criteria shall be plugged in accordance with the Steam Generator Program.

APPLICABILITY: MODES 1, 2, 3, and 4.

ACTIONS

-----NOTE-----

Separate Condition entry is allowed for each SG tube.

CONDITION	REQUIRED ACTION	COMPLETION TIME
A. One or more SG tubes satisfying the tube repair criteria and not plugged in accordance with the Steam Generator Program.	A.1 Verify tube integrity of the affected tube(s) is maintained until the next refueling outage or SG tube inspection.	7 days
	<u>AND</u> A.2 Plug the affected tube(s) in accordance with the Steam Generator Program.	Prior to entering MODE 4 following the next refueling outage or SG tube inspection
B. Required Action and associated Completion Time of Condition A not met. <u>OR</u> SG tube integrity not maintained.	B.1 Be in MODE 3.	6 hours
	<u>AND</u> B.2 Be in MODE 5.	36 hours

SURVEILLANCE REQUIREMENTS

SURVEILLANCE	FREQUENCY
SR 3.4.17.1 Verify SG tube integrity in accordance with the Steam Generator Program.	In accordance with the Steam Generator Program
SR 3.4.17.2 Verify that each inspected SG tube that satisfies the tube repair criteria is plugged in accordance with the Steam Generator Program.	Prior to entering MODE 4 following a SG tube inspection



5.5 Procedures, Programs, and Manuals (continued)

5.5.2.8 Primary Coolant Sources Outside Containment Program (continued)

system (post-accident sampling return piping only until such time as a modification eliminates the post-accident piping as a potential leakage path). The program shall include the following:

- a. Preventive maintenance and periodic visual inspection requirements; and
- b. Integrated leak test requirements for each system at refueling cycle intervals or less.

5.5.2.9 Pre-Stressed Concrete Containment Tendon Surveillance Program

This program provides controls for monitoring any tendon degradation in pre-stressed concrete containment, including effectiveness of its corrosion protection medium, to ensure containment structural integrity. Program itself is relocated to the LCS.

5.5.2.10 Inservice Inspection and Testing Program

This program provides controls for inservice inspection of ASME Code Class 1, 2, and 3 components and Code Class CC and MC components including applicable supports. The program provides controls for inservice testing of ASME Code Class 1, 2, and 3 components. The program itself is located in the LCS.

5.5.2.11 Steam Generator (SG) Program

A Steam Generator Program shall be established and implemented to ensure that SG tube integrity is maintained. In addition, the Steam Generator Program shall include the following provisions:

- a. Provisions for condition monitoring assessments. Condition monitoring assessment means an evaluation of the "as found" condition of the tubing with respect to the performance criteria for structural integrity and accident induced leakage. The "as found" condition refers to the condition of the tubing during an SG inspection outage, as determined from the inservice inspection results or by other means, prior to the plugging of tubes. Condition monitoring assessments shall be conducted during each outage during which the SG tubes are inspected or plugged, to confirm that the performance criteria are being met.

(continued)

5.5 Procedures, Programs, and Manuals (continued)

5.5.2.11 Steam Generator (SG) Program (continued)

- b. Performance criteria for SG tube integrity. SG tube integrity shall be maintained by meeting the performance criteria for tube structural integrity, accident induced leakage, and operational LEAKAGE.
1. Structural integrity performance criterion: All in-service steam generator tubes shall retain structural integrity over the full range of normal operating conditions (including startup, operation in the power range, hot standby, and cool down and all anticipated transients included in the design specification) and design basis accidents. This includes retaining a safety factor of 3.0 against burst under normal steady state full power operation primary-to-secondary pressure differential and a safety factor of 1.4 against burst applied to the design basis accident primary-to-secondary pressure differentials. Apart from the above requirements, additional loading conditions associated with the design basis accidents, or combination of accidents in accordance with the design and licensing basis, shall also be evaluated to determine if the associated loads contribute significantly to burst or collapse. In the assessment of tube integrity, those loads that do significantly affect burst or collapse shall be determined and assessed in combination with the loads due to pressure with a safety factor of 1.2 on the combined primary loads and 1.0 on axial secondary loads.
 2. Accident induced leakage performance criterion: The primary to secondary accident induced leakage rate for any design basis accident, other than a SG tube rupture, shall not exceed the leakage rate assumed in the accident analysis in terms of total leakage rate for all SGs and leakage rate for an individual SG. Leakage is not to exceed 0.5 gpm per SG and 1 gpm through both SGs.
 3. The operational LEAKAGE performance criterion is specified in LCO 3.4.13, "RCS Operational LEAKAGE."

(continued)

5.5 Procedures, Programs, and Manuals (continued)

5.5.2.11 Steam Generator (SG) Program (continued)

c. Provisions for SG tube repair criteria.

1. Tubes found by inservice inspection to contain flaws with a depth equal to or exceeding 35% of the nominal tube wall thickness shall be plugged.

- d. Provisions for SG tube inspections. Periodic SG tube inspections shall be performed. The number and portions of the tubes inspected and methods of inspection shall be performed with the objective of detecting flaws of any type (e.g., volumetric flaws, axial and circumferential cracks) that may be present along the length of the tube, from the tube-to-tubesheet weld at the tube inlet to the tube-to-tubesheet weld at the tube outlet, and that may satisfy the applicable tube repair criteria. The tube-to-tubesheet weld is not part of the tube.

In addition to meeting the requirements of d.1, d.2, and d.3 below, the inspection scope, inspection methods, and inspection intervals shall be such as to ensure that SG tube integrity is maintained until the next SG inspection. An assessment of degradation shall be performed to determine the type and location of flaws to which the tubes may be susceptible and, based on this assessment, to determine which inspection methods need to be employed and at what locations.

1. Inspect 100% of the tubes in each SG during the first refueling outage following SG replacement.
2. Inspect 100% of the tubes at sequential periods of 144, 108, 72, and thereafter, 60 effective full power months. The first sequential period shall be considered to begin after the first inservice inspection of the SGs. In addition, inspect 50% of the tubes by the refueling outage nearest the midpoint of the period and the remaining 50% by the refueling outage nearest the end of the period. No SG shall operate for more than 72 effective full power months or three refueling outages (whichever is less) without being inspected.
3. If crack indications are found in any SG tube, then the next inspection for each SG for the degradation mechanism that caused the crack indication shall not exceed 24 effective full power months or one refueling outage (whichever is less). If definitive information, such as from examination of a pulled tube, diagnostic non-destructive testing, or engineering evaluation indicates that a crack-like indication is not associated with a crack(s), then the indication need not be treated as a crack.

- e. Provisions for monitoring operational primary to secondary LEAKAGE.

5.7 Reporting Requirements (continued)5.7.2 Special Reports

Special Reports may be required covering inspection, test, and maintenance activities. These special reports are determined on an individual basis for each unit and their preparation and submittal are designated in the Technical Specifications.

Special Reports shall be submitted to the U. S. Nuclear Regulatory Commission, Attention: Document Control Desk, Washington, D. C. 20555, with a copy to the Regional Administrator of the Regional Office of the NRC, in accordance with 10 CFR 50.4 within the time period specified for each report.

The following Special Reports shall be submitted:

- a. When a pre-planned alternate method of monitoring post-accident instrumentation functions is required by Condition B or Condition G of LCO 3.3.11, a report shall be submitted within 30 days from the time the action is required. The report shall outline the action taken, the cause of the inoperability, and the plans and schedule for restoring the instrumentation channels of the function to OPERABLE status.
- b. Any abnormal degradation of the containment structure detected during the tests required by the Pre-Stressed Concrete Containment Tendon Surveillance Program shall be reported to the NRC within 30 days. The report shall include a description of the tendon condition, the condition of the concrete (especially at tendon anchorages), the inspection procedures, the tolerances on cracking, and the corrective action taken.
- c. A report shall be submitted within 180 days after the initial entry into MODE 4 following completion of an inspection performed in accordance with the Specification 5.5.2.11, Steam Generator (SG) Program. The report shall include:

(continued)

5.7 Reporting Requirements (continued)

5.7.2 Special Reports (continued)

1. The scope of inspections performed on each SG,
 2. Active degradation mechanisms found,
 3. Nondestructive examination techniques utilized for each degradation mechanism,
 4. Location, orientation (if linear), and measured sizes (if available) of service induced indications,
 5. Number of tubes plugged during the inspection outage for each active degradation mechanism,
 6. Total number and percentage of tubes plugged to date,
 7. The results of condition monitoring, including the results of tube pulls and in-situ testing.
-

3.4 REACTOR COOLANT SYSTEM (RCS)

3.4.13 RCS Operational LEAKAGE

LCO 3.4.13 RCS operational LEAKAGE shall be limited to:

- a. No pressure boundary LEAKAGE;
- b. 1 gpm unidentified LEAKAGE;
- c. 10 gpm identified LEAKAGE; and
- d. 150 gallons per day primary to secondary LEAKAGE through any one Steam Generator (SG).

APPLICABILITY: MODES 1, 2, 3, and 4.

ACTIONS

CONDITION	REQUIRED ACTION	COMPLETION TIME
A. RCS Operational LEAKAGE not within limits for reasons other than pressure boundary LEAKAGE or primary to secondary LEAKAGE.	A.1 Reduce LEAKAGE to within limits.	4 hours
B. Required Action and associated Completion Time of Condition A not met. <u>OR</u> Pressure boundary LEAKAGE exists. <u>OR</u> Primary to secondary LEAKAGE not within limit.	B.1 Be in MODE 3.	6 hours
	<u>AND</u> B.2 Be in MODE 5.	36 hours

SURVEILLANCE REQUIREMENTS

SURVEILLANCE	FREQUENCY
<p>SR 3.4.13.1</p> <p>-----NOTES-----</p> <ol style="list-style-type: none"> 1. Not required to be performed in MODE 3 or 4 until 12 hours of steady state operation. 2. Not applicable to primary to secondary LEAKAGE. <p>-----</p> <p>Perform RCS water inventory balance.</p>	<p>-----NOTE-----</p> <p>Only required to be performed during steady state operation. If a transient evolution is occurring 72 hours from the last water inventory balance, then a water inventory balance shall be performed within 120 hours of the last water inventory balance</p> <p>-----</p> <p>72 hours</p>
<p>-----NOTE-----</p> <p>Not required to be performed until 12 hours after establishment of steady state operation.</p> <p>-----</p> <p>SR 3.4.13.2 Verify primary to secondary LEAKAGE is ≤ 150 gallons per day through any one SG.</p>	<p>72 hours</p>

ATTACHMENT 2

AREVA Document 51-9182368-003, SONGS 2C17 Steam Generator Condition Monitoring Report

[Proprietary Information Redacted]



AREVA NP Inc.

Engineering Information Record

Document No.: 51 - 9182368 - 003 (NP)

SONGS 2C17 Steam Generator Condition Monitoring Report

Supplier Status Stamp

VPL No:	1814-AU651-M0156	Rev No:	1	QC:	N/A
<input type="checkbox"/>	DESIGN DOCUMENT	ORDER NO.	800918458		
<input checked="" type="checkbox"/>	REFERENCE DOCUMENT-INFORMATION ONLY		<input type="checkbox"/> VIRP IOM MANUAL		
MFG MAY PROCEED: <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A					
<small>STATUS - A status is required for design documents and is optional for reference documents. Drawings are reviewed and approved for arrangements and conformance to specification only. Approval does not relieve the submitter from the responsibility of adequacy and suitability of design, materials, and/or equipment represented.</small>					
<input type="checkbox"/> 1. APPROVED					
<input type="checkbox"/> 2. APPROVED EXCEPT AS NOTED - Make changes and resubmit.					
<input type="checkbox"/> 3. NOT APPROVED - Correct and resubmit for review. NOT for field use.					
APPROVAL: (PRINT / SIGN / DATE)					
RE:	E. GRIBBLE		10/2/12		
FLS:					
Other:					

SCE DE(123) 5 REV. 3 07/11

REFERENCE: SO123-XXIV-37.8.26



SONGS 2C17 Steam Generator Condition Monitoring Report

Safety Related? YES NO

Does this document contain assumptions requiring verification? YES NO

Does this document contain Customer Required Format? YES NO

Signature Block

Name and Title/Discipline	Signature	P/LP, R/LR, A/A-CRF, A/A-CRI	Date	Pages/Sections Prepared/Reviewed/ Approved or Comments

Note: P/LP designates Preparer (P), Lead Preparer (LP)
 R/LR designates Reviewer (R), Lead Reviewer (LR)
 A/A-CRF designates Approver (A), Approver of Customer Requested Format (A-CRF)
 A/A-CRI designates Approver (A), Approver - Confirming Reviewer Independence (A-CRI)



SONGS 2C17 Steam Generator Condition Monitoring Report

Record of Revision

Revision No.	Pages/Sections/ Paragraphs Changed	Brief Description / Change Authorization
000	All	Original Release
001	Table 5-4	Edited title
	Table 5-7	Revised line 2 entry to max depth of 54%, line 6 entry to 29%
	Table 5-8	Revised second entry to max depth of 30%
	Sect. 6.2.4	Added missing callout to figure 6-6
002	All	Added Sections 2.0, 4.1, 4.2, 4.3, 6.3 and 6.4. Incorporated a significant number of editorial corrections and modifications throughout the document.
003	Section 4.3 Section 6.1 Section 6.2 Table 6-4 Table 6-5 Appendix A and B	Corrected Pre-Service examination statement from "Hot Leg (HL) and Cold Leg (CL) Top of Tubesheet (TTS)" to "Hot Leg (HL) and Cold Leg (CL) Tubesheet (TS)" to reflect that examination covered entire TS instead of just the Top of Tubesheet. Corrected Table number 5-2 to Table 6-2 in Section 6.1 Revised discussion of plugging Corrected Table 6-4 Total Indication Count Values Removed TTW wear and TTW Preventative counts from Table 6-5 Removed Appendix A and B Plugging lists

SONGS 2C17 Steam Generator Condition Monitoring Report

Table of Contents

	Page
SIGNATURE BLOCK.....	2
RECORD OF REVISION	3
LIST OF TABLES	6
LIST OF FIGURES	7
1.0 PURPOSE.....	8
2.0 ABBREVIATIONS AND ACRONYMS.....	9
3.0 SCOPE.....	12
4.0 BACKGROUND	12
4.1 Previous Operating Experience (OE) Related to Tube-to-Tube Wear	16
4.2 Previous Operating Experience Related to Tube-to-AVB Wear.....	17
4.3 Pre-Service Examination Results.....	18
5.0 PERFORMANCE CRITERIA	19
6.0 INSPECTION SUMMARY	20
6.1 Eddy Current Inspections Performed	21
6.2 Degradation Identified	23
6.3 Tube-to-Tube Wear Detection.....	24
6.4 Tube-to-Tube Wear Sizing	25
6.5 Secondary Side Visual Examination Results	26
7.0 CONDITION MONITORING ASSESSMENT	47
7.1 Input Parameters.....	47
7.2 Evaluation of Structural Integrity	49
7.2.1 AVB wear and TSP wear	49
7.2.2 Retainer Bar Wear	49
7.2.3 Foreign Object Wear.....	50
7.2.4 Tube-to-Tube Wear.....	51
7.3 Evaluation of Accident-induced Leakage Integrity	52
7.3.1 AVB wear and TSP wear	52
7.3.2 Retainer Bar Wear	52
7.3.3 Foreign Object Wear.....	52
7.3.4 Tube-to-Tube Wear.....	52
7.4 Evaluation of Operational Leakage Integrity	53
8.0 CONDITION MONITORING CONCLUSION.....	60



SONGS 2C17 Steam Generator Condition Monitoring Report

Table of Contents
(continued)

	Page
9.0 REFERENCES.....	61



SONGS 2C17 Steam Generator Condition Monitoring Report

List of Tables

	Page
TABLE 2-1: ABBREVIATIONS AND ACRONYMS	9
TABLE 4-1: SUMMARY OF PRE-SERVICE INSPECTION RESULTS	18
TABLE 6-1: STEAM GENERATOR TUBE INSPECTION SCOPE SUMMARY (FIRST PHASE).....	27
TABLE 6-2: APRIL 2012 RTS INSPECTION SG TUBE INSPECTION SUMMARY.....	28
TABLE 6-3: JULY 2012 RTS INSPECTION SG TUBE INSPECTION SUMMARY	28
TABLE 6-4: WEAR INDICATION SUMMARY	29
TABLE 6-5: PLUGGING SUMMARY	30
TABLE 6-6: REPORTED AVB WEAR DEPTHS (%TW).....	30
TABLE 6-7: REPORTED TSP WEAR DEPTHS (%TW).....	30
TABLE 6-8: RETAINER BAR WEAR	31
TABLE 6-9: FOREIGN OBJECT WEAR	31
TABLE 6-10: TUBE-TO-TUBE WEAR	31
TABLE 7-1: SONGS-2 STEAM GENERATOR INPUT VALUES	48
TABLE 7-2: EDDY CURRENT ETSS INPUT VALUES (REFERENCE 5).....	48

SONGS 2C17 Steam Generator Condition Monitoring Report

List of Figures

	Page
FIGURE 4-1: SONGS STEAM GENERATOR SUPPORT STRUCTURE LAYOUT	13
FIGURE 4-2: VIEW FROM ABOVE BUNDLE SHOWING RETAINER BAR LOCATIONS	14
FIGURE 4-3: SKETCH SHOWING RETAINER/RETAINING BAR CONFIGURATION.....	15
FIGURE 6-1: SG 2E-088 AVB WEAR	32
FIGURE 6-2: SG 2E-089 AVB WEAR	33
FIGURE 6-3: SG 2E-088 TSP WEAR – HOT LEG.....	34
FIGURE 6-4: SG 2E-088 TSP WEAR – COLD LEG	35
FIGURE 6-5: SG 2E-089 TSP WEAR – HOT LEG.....	36
FIGURE 6-6: SG 2E-089 TSP WEAR – COLD LEG	37
FIGURE 6-7: SG 2E-088 RETAINER BAR WEAR.....	38
FIGURE 6-8: SG 2E-089 RETAINER BAR WEAR.....	39
FIGURE 6-9: SG 2E-088 FOREIGN OBJECT WEAR.....	40
FIGURE 6-10: TUBE-TO-TUBE WEAR (DETECTED IN SG 2E-089 ONLY).....	41
FIGURE 6-11: SG 2E-088 AVB WEAR DEPTH DISTRIBUTION.....	42
FIGURE 6-12: SG 2E-089 AVB WEAR DEPTH DISTRIBUTION.....	43
FIGURE 6-13: SG 2E-088 TSP WEAR DEPTH DISTRIBUTION.....	44
FIGURE 6-14: SG 2E-089 TSP WEAR DEPTH DISTRIBUTION.....	45
FIGURE 6-15: FOREIGN OBJECT RETRIEVED FROM SG 2E-088.....	46
FIGURE 7-1: CM LIMIT FOR AVB WEAR, ETSS 96004.1	54
FIGURE 7-2: CM LIMIT FOR TSP WEAR, ETSS 96004.1.....	55
FIGURE 7-3: CM LIMIT FOR RB WEAR, ETSS 27903.1.....	56
FIGURE 7-4: CM LIMIT FOR FO WEAR, ETSS 27901.1.....	57
FIGURE 7-5: FOREIGN OBJECT POP-THROUGH AT 2560 PSI, UNIFORM 360° THINNING, ETSS 27901.1	58
FIGURE 7-6: CM LIMIT FOR TUBE-TO-TUBE WEAR, ETSS 27902.2	59



SONGS 2C17 Steam Generator Condition Monitoring Report

1.0 PURPOSE

In accordance with the EPRI Steam Generator Integrity Assessment Guidelines [2], a Condition Monitoring (CM) assessment must be performed at the conclusion of each steam generator eddy current examination. This process is described as “backward-looking,” since its purpose is to confirm that adequate Steam Generator (SG) integrity was maintained during the most recent operating period. It involves an evaluation of the as-found conditions of the steam generator relative to established performance criteria for structural and leakage integrity. The performance criteria are defined in plant Technical Specifications [17] [18]. The performance criteria are based on NEI (Nuclear Energy Institute) 97-06 [1] (see Section 5.0 below).

This report concludes that the SONGS (San Onofre Nuclear Generating Station) steam generator performance criteria were satisfied by Unit 2 during the operating period prior to 2C17.

SONGS 2C17 Steam Generator Condition Monitoring Report

2.0 ABBREVIATIONS AND ACRONYMS

The following table provides a listing of abbreviations and acronyms used throughout this report.

Table 2-1: Abbreviations and Acronyms

Abbreviation or Acronym	Definition
01C to 07C	Tube Support Plate Designations for Cold Leg (7 Locations)
01H to 07H	Tube Support Plate Designations for Hot Leg (7 Locations)
2E-088	Unit 2 Steam Generator 88
2E-089	Unit 2 Steam Generator 89
3E-088	Unit 3 Steam Generator 88
3E-089	Unit 3 Steam Generator 89
3 NOPD	3 Times Normal Operating Pressure Differential
3ΔP	3 Times Normal Operating Pressure Differential
ADI	Absolute Drift Indication
AILPC	Accident Induced Leakage Performance Criterion
ANO	Arkansas Nuclear One
ASME	American Society of Mechanical Engineers
AVB	Anti-Vibration Bar
B01 to B12	AVB Designations (12 Locations)
BLG	Bulge
C	Column
CE	Combustion Engineering
CL or C/L	Cold Leg
CM	Condition Monitoring
DA	Degradation Assessment
DBE	Design Basis Earthquake
DNG	Ding
DNT	Dent
ECT	Eddy Current Testing
EFPD	Effective Full Power Days
EOC	End of Operating Cycle
EPRI	Electric Power Research Institute
ETSS	Examination Technique Specification Sheet
FOSAR	Foreign Object Search and Retrieval
GMD	Geometric Distortion
GPD	Gallons per Day
GPM	Gallons per Minute

SONGS 2C17 Steam Generator Condition Monitoring Report

Table 2-1: Abbreviations and Acronyms

Abbreviation or Acronym	Definition
HL or H/L	Hot Leg
INPO	Institute of Nuclear Power Operators
kHz	Kilohertz
KSI	Thousand Pounds per Square Inch
LER	Licensee Event Report
MBM	Manufacturing Burnish Mark
MHI	Mitsubishi Heavy Industries
MSLB	Main Steam Line Break
NDE	Non Destructive Examination
NEI	Nuclear Energy Institute
NN	Nuclear Notification
NOPD	Normal Operating Pressure Differential
NQI	Non-Quantifiable Indication
NRC	Nuclear Regulatory Commission
NSAL	Nuclear Safety Advisory Letter
OA	Operational Assessment
OE	Operating Experience
OTSG	Once Through Steam Generator
PDA	Percent Degraded Area
PLP	Possible Loose Part
POD	Probability of Detection
PRX	Proximity Indication
PSI	Pounds per Square Inch
PSIG	Pounds per Square Inch Gage
PST	Pacific Standard Time
PVN	Permeability Variation
PWR	Pressurized Water Reactor
QA	Quality Assurance
R	Row
RB	Retainer Bar
RCS	Reactor Coolant System
REPL	Replacement
ROLLED	Rolled Plug Designation
ROLLSTAB	Rolled Plug with a Stabilizer
RPC	Rotating Probe Coil
RSG	Recirculating Steam Generator
SCE	Southern California Edison

SONGS 2C17 Steam Generator Condition Monitoring Report

Table 2-1: Abbreviations and Acronyms

Abbreviation or Acronym	Definition
SG	Steam Generator
SIPC	Structural Integrity Performance Criteria
SL2	St. Lucie Unit 2
SLB	Steam Line Break
SONGS	San Onofre Nuclear Generating Station
SSA	Secondary Side Anomaly
SSI	Secondary Side Inspection
SVI	Single Volumetric Indication
TMI	Three Mile Island
TSP	Tube Support Plate
TTW	Tube to Tube Wear
TW	Through Wall
U3F16B	Unit 3 Outage Designation
UB	U-bend


SONGS 2C17 Steam Generator Condition Monitoring Report

3.0 SCOPE

This evaluation pertains to the SONGS Unit 2 replacement steam generators, which are reactor coolant system components. The CM assessment documented in this report is required to be completed prior to plant entry into Mode 4 during start up after a SG inspection. The Unit 2 SGs passed CM, thus an OA (Operational Assessment) shall be completed for the next inspection interval within 90 days after Mode 4.

This document was originally a portion of AREVA document 51-9177491-001, "SONGS 2C17 Steam Generator Condition Monitoring and Preliminary Operational Assessment" [14]. The decision was made to separate the Condition Monitoring and Operational Assessment portions of the document.


4.0 BACKGROUND



MHI Proprietary


SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 4-1: SONGS Steam Generator Support Structure Layout



SONGS 2C17 Steam Generator Condition Monitoring Report


Figure 4-2: View From Above Bundle Showing Retainer Bar Locations



MHI Proprietary

SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 4-3: Sketch Showing Retainer/Retaining Bar Configuration



SONGS 2C17 Steam Generator Condition Monitoring Report

4.1 Previous Operating Experience (OE) Related to Tube-to-Tube Wear

Prior to the Songs Unit 3 shutdown in January of 2012, the recent operating experience related to tube-to-tube wear was limited to once-through steam generators. In December 2011, INPO (Institute of Nuclear Power Operators) OE 34946 [19] was released. This Operating Experience Report discusses experience at Three Mile Island Unit 1 (TMI-1). In July 2012, the NRC (Nuclear Regulatory Commission) released Information Notice 2012-07 [20]. This Information Notice contains information on the experience at TMI-1 as well as Oconee and ANO-1 (Arkansas Nuclear One – Unit 1). This section summarizes the experiences at these plants with once-through steam generators.

TMI-1 completed replacement of its original Once Through Steam Generators (OTSGs) in 2010. The design of the OTSG differs from the recirculating steam generator design in that the tubes are straight. The tubes are supported by 15 tube support plates. The first inspection of the TMI-1 replacement steam generators took place in the fall of 2011. During this examination, indications were detected on the absolute channel with no discernible response on the differential channel. The indications were designated as Absolute Drift Indications (ADIs). A comprehensive review of all of the ADIs identified tubes with long shallow wear signals between the eighth and ninth tube support plates. The indications were in adjacent tube combinations of either 2 or 3 tubes (the tube pattern is a triangular pitch). A more detailed investigation led to the conclusion that these wear indications were the result of tube-to-tube contact wear. The lengths ranged from 2 to 8 inches and from 1 to 21 percent through-wall.

As a result of the TMI-1 findings, and because TMI and ANO both have AREVA replacement steam generators, the licensee for Arkansas Nuclear One, Unit 1 (ANO-1) was notified. Upon a review of previously recorded eddy current examination data, it was determined that ANO-1 also had similar indications of tube-to-tube wear. The depth and length of the ANO-1 indications were similar to those recorded at TMI-1.

In the spring of 2012, the licensee for Oconee, Unit 3 also detected wear attributed to tube-to-tube contact in their replacement steam generators. Since the design of the Oconee OTSGs, which were built by BWI, is not the same as the TMI or ANO generators, the location of the tube-to-tube wear was different, but the characteristics were similar. The lengths ranged from 1 to 9 inches and the depths ranged up to 20 percent through-wall.

The severity of the replacement OTSG tube-to-tube wear was evaluated and was not found to compromise tube integrity.

The combined experience from the above discussion demonstrated several significant points:

- New or unexpected forms of degradation may be difficult to identify. Robust inspection planning is an important part of identifying new degradation as well as properly characterizing known degradation.
- A comprehensive review of examination data from different perspectives is valuable. By considering the change in indications over time, responses to different channels or techniques, or the spatial distribution of the indications, important information may be found.

SONGS 2C17 Steam Generator Condition Monitoring Report

- The reporting criteria is critical to proper identification of new or existing damage mechanisms.
- Comprehensive examination of new or replacement steam generators is necessary to ensure that performance is as expected.

4.2 Previous Operating Experience Related to Tube-to-AVB Wear

INPO OE 35359 [21] discusses the results of the first two inspections at St. Lucie Unit 2. The recirculating steam generators at St. Lucie Unit 2 were replaced during 2007. During the Cycle 18 Refueling Outage (SL2-18, April 2009), eddy current testing of the replacement steam generators reported over 5800 AVB wear indications in more than 2000 tubes. Fourteen tubes were plugged as a result of the wear indications. None of the indications challenged the Condition Monitoring limits.

Based on the high number of wear indications reported during the SL2-18 inspection, and to further establish growth rates, the St. Lucie Unit 2 SGs were examined again during the next refueling outage at SL2-19 in January 2011. Approximately 3000 new AVB wear indications were reported during the SL2-19 examination. As a result of the SL2-19 inspection, an additional twenty-one (21) tubes were plugged, only one of which exceeded the Plant Technical Specification limit of > 40 %TW (throughwall).

The OE reinforces the importance of inspecting replacement SGs with the bobbin coil at the end of the first cycle of operation, post-replacement. The diagnostic examinations performed with the +Point™ rotating coil concluded that the AVB wear indications could be flat or tapered, single or double sided. These wear characteristics are important to consider when selecting the proper depth-sizing technique(s).

SONGS 2C17 Steam Generator Condition Monitoring Report

4.3 Pre-Service Examination Results

During May and June of 2009, an on-site pre-service examination was performed in the Songs Unit 2 replacement SGs. The examination consisted of 100 % bobbin coil inspection of all tubes (9727 tubes), 100 % inspection of the Hot Leg (HL) and Cold Leg (CL) Tubesheet (TS) region with the +Point™ probe (9727 tubes), and a 100 % inspection of the row 1-15 U-bend regions with the +Point™ probe (1314 tubes).

No significant degradation was detected during this examination. There were a number of geometric type indications reported in each SG (dings, geometric distortions, proximity, bulge). The following table provides a count of the number of tubes and total number of indications for each Unit 2 SG.

Table 4-1: Summary of Pre-Service Inspection Results

Indication Code	SG 2E-088		SG 2E-089	
	Tube Count	Indication Count	Tube Count	Indication Count
BLG (Bulge)	0	0	1	1
DNG (Ding)	1089	2180	1033	2084
GMD (Geometric Distortion)	15	19	21	31
MBM (Manufacturing Burnish Mark)	0	0	2	2
NQI (Non-Quantifiable Indication)	0	0	1	1
PLP (Potential Loose Part)	1	1	0	0
PRX (Proximity)	66	66	42	42
PVN (Permeability Variation)	0	0	1	1

SONGS 2C17 Steam Generator Condition Monitoring Report

5.0 PERFORMANCE CRITERIA

The SONGS-2 performance criteria, based on NEI 97-06 [1] are shown below. The structural integrity and accident-induced leakage criteria were taken from Section 5.5.2.11 [17] from the SONGS-2 Technical Specifications. The operational leakage criterion was taken from Section 3.4.13 [18] of the SONGS Technical Specifications.

- Structural Integrity Performance Criterion: "All inservice steam generator tubes shall retain structural integrity over the full range of normal operating conditions (including startup, operation in the power range, hot standby, and cooldown and all anticipated transients included in the design specification) and design basis accidents. This includes retaining a safety factor of 3.0 against burst under normal steady state full power operation primary-to-secondary pressure differential and a safety factor of 1.4 against burst applied to the design basis accident primary-to-secondary pressure differentials. Apart from the above requirements, additional loading conditions associated with the design basis accidents, or combination of accidents in accordance with the design and licensing basis, shall also be evaluated to determine if the associated loads contribute significantly to burst or collapse. In the assessment of tube integrity, those loads that do significantly affect burst or collapse shall be determined and assessed in combination with the loads due to pressure with a safety factor of 1.2 on the combined primary loads and 1.0 on axial secondary loads.
- Accident-induced Leakage Performance Criterion: "The primary to secondary accident-induced leakage rate for any design basis accident, other than a SG tube rupture, shall not exceed the leakage rate assumed in the accident analysis in terms of total leakage rate for all SGs and leakage rate for an individual SG. Leakage is not to exceed 0.5 gpm per SG and 1 gpm through both SGs."
- Operational Leakage Performance Criterion: "RCS operational leakage shall be limited to 150 gallons per day primary to secondary leakage through any one steam generator."

SONGS 2C17 Steam Generator Condition Monitoring Report

6.0 INSPECTION SUMMARY

The SONGS Unit 2, 2C17 inspection scope occurred in three distinct phases. The first phase followed the planned shutdown for the 2C17 refueling outage and first SG ISI.

The next two inspection phases, performed in April and July 2012, were a direct result of a SG tube leak in Unit 3. The tube leak resulted from tube-to-tube wear (TTW) that was caused by fluid-elastic instability. These subsequent inspections are referred to as 2C17 RTS (Return-to-Service) inspections. The second-phase inspection (April 2012) was a full-length U-bend inspection of tubes deemed most susceptible to tube-to-tube wear based on the degradation identified in Unit 3. The third-phase inspection (July 2012) consisted of eddy current testing to measure the gaps between the AVBs and the tubes. Based on the gap measurements, an additional 104 tubes were examined in the U-bend region with the +Point™ coil.

Inspections included the following inspection activities for each of the two replacement steam generators (SG 2E-088 and SG 2E-089) using site validated ECT techniques [7]:

- Bobbin Coil Examinations
 - All in-service tubes, full length tube-end to tube-end
- Rotating Coil Examinations
 - Tubesheet periphery and divider lane tubes (from 3" above to 1" below the top of the tubesheet), both legs, approximately 3 tubes in from the periphery and 2 tubes in from the divider lane
 - Full-length U-bend Exam of Tubes Adjacent to Retainer Bars
 - Specific locations based on results of bobbin inspections (e.g., I-codes, selected wear indications, etc.)
 - Full-length U-bend +Point™ examination of tubes with potential for tube-to-tube wear (2C17 RTS inspection)
 - Full-length U-bend pancake coil examination of selected tubes for measurement of gaps between the AVBs and the tubes (2C17 RTS inspection)
- Secondary Side Visual Examinations
 - Foreign object search and retrieval (FOSAR) as required based on ECT
 - Post sludge lancing FOSAR examination at the top-of-tubesheet (periphery and the divider lane)
 - Visual inspections of the upper tube bundle at the 7th TSP and AVB / retainer bar regions

The subsections below discuss each aspect of the inspection and describe findings that are relevant to Condition Monitoring and operational assessment.

SONGS 2C17 Steam Generator Condition Monitoring Report

6.1 Eddy Current Inspections Performed

A summary of the total number of bobbin probe and rotating probe examinations performed during 2C17 is provided in Table 6-1 and Table 6-2. The Unit 2 examination was in progress when a tube leak developed in Unit 3 SG 2E-088. As a result of finding tube-to-tube wear in Unit 3, additional analysis and examinations were performed in Unit 2.

The original inspection scope included examination of the tubing in SG's 2E-088 and 2E-089 as follows:

- 100% bobbin coil probe (610 mil diameter) examination of the complete tube length in both Steam Generators.
- 100% of all previous (Pre-service exam) and newly reported bobbin coil "I" codes, Possible Loose Part (PLP), Manufacturing Burnish Mark (MBM), Non-Quantifiable Indication (NQI), Bulge (BLG) and Permeability Variation (PVN) locations with at rotating +Point™ / pancake coil probe.
- 100% of all reported bobbin coil Ding (DNG) and Dent (DNT) locations measuring ≥ 2.0 volts with a rotating +Point™ / pancake coil probe.
- A sample of AVB %TW wear indications as defined by SCE and/or tube integrity engineering.

Due to detection of a foreign object and the detection of wear at a retainer bar, scope expansions were performed in SG's 2E-088 and 2E-089 as follows:

- H/L and C/L Tubesheet Periphery exam (TSH/TSC +3/-1 inches with a rotating +Point™ / pancake coil probe.
- H/L and C/L Retainer Bar exam (07H-B06 & 07C-B07) with a single coil rotating +Point™ probe. This exam included all tubes adjacent to retainer bar locations.

SONGS 2C17 Steam Generator Condition Monitoring Report

Due to the detection of tube-to-tube wear (TTW) in Unit 3, additional inspections were performed in Unit 2 after the initial pre-planned scope was completed. These additional inspections were performed in two separate phases in April and July 2012. These inspections are referred to as RTS (Return-to-Service) inspections. These inspections included the following inspections in both steam generators.

- April 2012 RTS inspection: Full-length U-bend +Point™ inspections of tubes believed to be susceptible to TTW based on the affected tube population in Unit 3.
- July 2012 RTS inspection: Full-length U-bend pancake coil inspection of selected tubes for measurements of tube-to-AVB gaps.
- July 2012 RTS inspection: Full-length U-bend +Point™ inspections of 104 tubes in the 2E-089 SG based on the gap measurements.

The full-length U-bend +Point™ inspections performed in April 2012 included 1371 tubes in SG 2E-088 and 1375 tubes in SG 2E-089. Since these inspections were performed for detection of tube-to-tube wear (TTW), the tubes were selected based on the location of the affected tubes in Unit 3. The defined inspection scope bounded the affected tubes in Unit 3 by a minimum of four tubes on all sides. In July 2012, an additional 104 tubes were inspected in the 2E-089 SG over the full length of the U-bend with +Point™. The tubes for these additional inspections were selected based on the tube-to-AVB gap measurements.

A summary of the initial examination and subsequent expansions is provided in 51-9181604-000 [23].

SONGS 2C17 Steam Generator Condition Monitoring Report

6.2 Degradation Identified

The following tube degradation mechanisms were identified during the initial 2C17 inspections and the subsequent 2C17 RTS steam generator eddy current inspections:

- Anti-Vibration Bar (AVB) wear
- Tube Support Plate (TSP) wear
- Retainer Bar (RB) wear
- Foreign Object (FO) wear
- Tube-to-tube wear (TTW)

Table 6-4 summarizes the number of degradation indications and the number of affected tubes for each of the five wear categories. A complete accounting of the number of tubes plugged and stabilized for damage other than TTW during the 2C17 outage is provided in Table 6-5. The plugging information provided in this table is current for non-TTW. Due to the ongoing SG recovery efforts, the plugging strategy and, hence, the plugging and stabilization information for tubes with TTW wear and for tubes plugged as preventative measures for TTW may change prior to startup.

Table 6-6 through Table 6-9 summarize reported AVB wear, TSP wear, RB wear, FO and tube-to-tube wear depths, respectively. Table 6-8, Table 6-9, and Table 6-10 provide detailed information on all of the RB wear, FO wear, and tube-to-tube wear flaws identified. Within Table 6-8, Table 6-9, and Table 6-10, the structurally equivalent length and depth, as well as the overall length and maximum depth of the wear are provided. These structurally equivalent dimensions correspond to a rectangular flaw which would burst at the same pressure as the measured flaw. The structurally equivalent dimensions were determined using the methods described in Section 5.1.5 of Reference 4.

Figure 6-1 through Figure 6-10 provide tubesheet maps illustrating the locations of degradation reported in each steam generator. The AVB wear is most prevalent in the central region of the tubesheet matrix, in longer tube rows (Figure 6-1, Figure 6-2). Two other regions within each SG are also affected to a lesser degree. These regions are located near the periphery in slightly lower rows. TSP wear has affected fewer tubes than has AVB wear. TSP wear was identified at nearly every support elevation, with a greater tendency to occur on the hot leg than on the cold leg (Figure 6-3, Figure 6-4, Figure 6-5, Figure 6-6). RB wear was identified in only six tubes (Figure 6-7, Figure 6-8). Foreign object wear was identified in two tubes in SG 2E-088 (Figure 6-9). Tube-to-tube wear was detected in two tubes in SG 2E-089.

Figure 6-11 and Figure 6-12 provide histograms of the reported depths of AVB wear which demonstrate that the vast majority of AVB wear was less than 25 %TW. Four AVB wear flaws were sized >30%TW and the affected tubes were stabilized and plugged. Figure 6-13 and Figure 6-14 provide histograms of TSP wear depths and illustrate that the growth rate of TSP wear during the first operating cycle was less aggressive than that the growth rate of AVB wear. The maximum reported TSP wear flaw was 20%TW.

SONGS 2C17 Steam Generator Condition Monitoring Report

The retainer bar wear indications were not expected as they have not been reported in other MHI steam generators with the retainer bar design. As a result of the finding of retainer bar wear, the Degradation Assessment was revised during the outage to include this new mechanism.

After the completion of the initial scope of 2C17 inspections, additional inspections were performed as a result of the detection of tube-to-tube wear in Unit 3. Tube-to-tube wear was detected in two adjacent tubes in SG 2E-089. Both flaws measured 14% TWD with +Point™. The Degradation Assessment was also revised to include tube-to-tube wear.

6.3 Tube-to-Tube Wear Detection

Subsequent to finding tube-to-tube wear conditions in the U-bends of the Unit 3 tubing, SCE requested an additional review of the U-bend area bobbin coil data in Unit 2. The tubes selected for review encompassed the suspected tube-to-tube wear zone as defined in Unit 3 and included over 1000 tubes in each steam generator. This review included a two-party manual analysis (primary/secondary) of the complete U-bend (07H to 07C) with emphasis on the detection of low level freespan indications which may not have been reported during the original analysis of the U2C17 bobbin coil data. The analysts were instructed to report any indication detected on the differential channels and all indications measuring ≥ 0.40 volts on channel 6 absolute which would be a primary channel for detection of tube-to-tube wear. All indications identified during the analysis process were reviewed and dispositioned by the primary and secondary resolution analysis team with concurrence from the IQDA (Independent Qualified Data Analyst). None of the indications reviewed by the resolution team were deemed reportable and therefore, no new NQI indications were entered into the database based on this review.

The Unit 2 Return-to-Service inspection performed in April 2012 was comprised of a U-bend +Point™ examination which included 1371 tubes in SG 2E-088 and 1375 tubes in SG 2E089. The number for SG 2E-088 is less than SG 2E-089 because plugging of 4 tubes for AVB wear had already been performed in SG 2E-088 when these inspections were performed. Since these inspections were performed for detection of tube-to-tube wear (TTW), the tubes were selected based on the location of the affected tubes in Unit 3. The defined inspection scope bounded the combined population of affected tubes in both Unit 3 SGs by a minimum of four tubes on all sides. During this inspection, two tubes with indications indicative of tube-to-tube wear (TTW) were reported in SG 2E-089. The indications were approximately 6" long, located between AVBs B09 and B10, on one side of the tube (intrados for one tube and extrados for the other) and measured a maximum depth of 14%TW. The lower voltage amplitude curve defined in EPRI ETSS 27902.2 was used for sizing the indications. The SONGS Unit 2 & 3 site validation for sizing TTW can be found in AREVA document 51-9177744-000 "Site Validation of EPRI Sizing ETSS for Tube-Tube Wear in SONGS Steam Generators" [15].

SONGS 2C17 Steam Generator Condition Monitoring Report

The bobbin coil data for these two tubes was reviewed by the Lead Level III to determine if there were reportable bobbin coil indications associated with the TTW indications. The review revealed a very small amplitude absolute signal in the same vicinity as the TTW indications in both tubes. The Channel 6 amplitude for these two indications was 0.19 volts and 0.26 volts. Based on the amplitude, signal characteristics, and voltage criteria used for the initial bobbin coil review, it was determined that the bobbin indications were not reportable and are in a depth/size range where reliable detectability is a challenge.

A review of the detection performance of the bobbin coil versus the +Point™ coil was performed using the EPRI data for ETSS 27902.2 and the actual Unit 3 tube-to-tube wear data. The review is documented in AREVA Document 51-9179946-001 [16]. The EPRI technique was not specifically developed for tube-to-tube wear, but was the closest technique available. The review showed that the +Point™ probe had a slightly improved Probability of Detection (POD) over the bobbin coil and that the detection level for both techniques was above the minimum level of 0.80 POD at a 90 % LCL. The results of the Unit 3 specific tube-to-tube detection comparison produced similar results.

While the initial bobbin coil examination and subsequent review of bobbin data produced an acceptable detection performance for the depth of the two Unit 2 indications confirmed as tube-to-tube wear, it is likely that the Unit 2 flaw signal amplitudes were below the analysis detection threshold. The supplemental +Point™ examination was performed to provide the best possible detection performance.

During the July 2012 RTS inspection, an additional 104 tubes were inspected with +Point™ over the full length of the U-bend. These tubes were selected based on the tube-to-AVB gap measurements with emphasis placed on tubes having AVB intersections with gaps (as measured by eddy current) on both sides of the tube. No indications of TTW were reported in any of these tubes.

6.4 Tube-to-Tube Wear Sizing

Upon detection of tube-to-tube wear in the Unit 3 SG's, a determination was made that the most appropriate technique for sizing the wear was EPRI ETSS 27902.2 or 27902.5. However, with some initial review, it was apparent that the techniques produced very conservative depth estimates. The depth estimates reported for the deepest flaws were near 100% throughwall, however the tubes had maintained structural integrity at normal operating differential pressure. Using the actual operational conditions the throughwall depth values should have been at around 80 %TW in order to withstand pop-through. Based on the best understanding of the tube-to-tube wear degradation morphology, a standard was designed with two long, gradually-tapered machined wear flaws. Although the sample had only two separate flaws, the length of the flaws made it possible to measure multiple discrete depth sizing grading units. On the basis of these multiple points, a polynomial function was developed to adjust the depth estimates. The revised technique was documented in Reference 15.

The actual flaw sizing was performed using the 27902.2 technique. Screening for selection of in situ pressure test candidates was based on the 27902.2 sizing data without the polynomial correction in Reference 15. This produced a conservative population for in situ pressure testing.

SONGS 2C17 Steam Generator Condition Monitoring Report

6.5 Secondary Side Visual Examination Results

Secondary side visual inspections were performed in accordance with the plan outlined in Reference 8.

During the eddy current inspection of SG 2E-088, foreign object indications and foreign object wear indications were reported in two adjacent tubes at the 4th TSP (see Table 6-9 and Figure 6-9). Consequently, a secondary side foreign object search and retrieval effort was initiated, and the team successfully located and removed the object from the steam generator. Photographs of the object taken during retrieval are provided in Figure 6-15. Note that the FO wear indication identified in tube SG 2E-088 R137 C77 is visible in the upper photo in Figure 6-15. A follow-up analysis performed by SCE identified the object as weld metal debris [13]. These two adjacent tubes are being left in service because the indications are below the Technical Specification plugging limit and the cause of the degradation has been removed.

Due to the eddy current wear indications at the retainer bars, secondary side visual inspections of the retainer bars were performed in both steam generators. These inspections were performed on the retainer bars at B01, B02, B03, B10, B11, and B12. These retainer bars were selected for visual inspection since they are smaller in diameter and all retainer bar wear occurred at one of these locations. The visual inspections were focused on verifying the integrity of the retainer bar and the associated welds. All retainer bars and welds inspected were determined to be in the as-designed configuration. No cracking or degradation of the welds or retainer bars was observed.

The other secondary side examination activities (i.e., post-lancing visual exam at the top-of-tubesheet, visual exams performed in the upper bundle region) identified no foreign objects and no evidence of internal structure degradation. No conditions which could generate foreign objects or threaten tube integrity were identified during these examinations. In response to the detection of tube-to-tube wear in Unit 3, additional secondary side inspections were performed in Unit 2, similar to those done in Unit 3. The Unit 2 inspections in response to the Unit 3 condition included the following:

- Inspection of all small-diameter retainer bars (12).
- Inspection of retaining bars in the regions correlated to AVB/TSP damage in Unit 3 (Hot and Cold leg of bars B04 and B09 from columns 56 to 119).
- Inspection of AVB end caps on the retainer bar in the same area as identified above.
- Inspection through the transition cone handhole from column 73 to 87 through all rows to periphery of the following:
 - 7th Tube Support Plate
 - AVB B04 Hot Leg side column 73 to 87
 - AVB B04 in Columns 50-60
 - AVB B09 in Column 80 to 78



SONGS 2C17 Steam Generator Condition Monitoring Report

These inspections did not detect tube-to-tube wear or any other conditions that may be precursor signals to tube-to-tube wear, such as AVB wear indications extending outside of the intersection between the tube and the AVB.

Table 6-1: Steam Generator Tube Inspection Scope Summary (first phase)

SCOPE DESCRIPTION			SIG 2E-088			SIG 2E-089		
<i>Leg</i>	<i>Exam Description</i>	<i>Extents</i>	<i>Analyzed</i>	<i>Scope</i>	<i>% Completed</i>	<i>Analyzed</i>	<i>Scope</i>	<i>% Completed</i>
Hot / Cold	100 % Bobbin F/L	TEH-TEC	9,727	9,727	100.00%	9,727	9,727	100.00%
Hot	HL Special Interest	Various	33	33	100.00%	15	15	100.00%
Cold	CL Special Interest	Various	45	45	100.00%	16	16	100.00%
Hot / Cold	UB Special Interest	Various	125	125	100.00%	131	131	100.00%
Expansion								
Hot	HL Tubesheet Periphery	TSH+3/-1	1,030	1,030	100.00%	1,030	1,030	100.00%
Cold	CL Tubesheet Periphery	TSC+3/-1	1,030	1,030	100.00%	1,030	1,030	100.00%
Hot	HL Retainer Bar Tube RPC	07H-B06	96	96	100.00%	96	96	100.00%
Cold	CL Retainer Bar Tube RPC	07C-B07	96	96	100.00%	96	96	100.00%
Total Plan			12,182	12,182	100.00%	12,141	12,141	100.00%



SONGS 2C17 Steam Generator Condition Monitoring Report

Table 6-2: April 2012 RTS Inspection SG Tube Inspection Summary

SCOPE DESCRIPTION			S/G 2E-088			S/G 2E-089		
<i>Leg</i>	<i>Exam Description</i>	<i>Extents</i>	<i>Analyzed</i>	<i>Scope</i>	<i>% Completed</i>	<i>Analyzed</i>	<i>Scope</i>	<i>% Completed</i>
Hot	H/L U-Bend RPC	07H-B07	1,371	1,371	100.00%	1,375	1,375	100.00%
Cold	C/L U-Bend RPC	07C-B07	1,371	1,371	100.00%	1,375	1,375	100.00%
Hot/Cold	U-Bend 2-Coil Special Interest	Various	3	3	100.00%	6	6	100.00%
Hot	H/L U-Bend MagBias RPC	07H-B07	1	1	100.00%	N/A	N/A	N/A
Cold	C/L U-Bend MagBias RPC	07C-B07	1	1	100.00%	N/A	N/A	N/A
	Total Plan		2,745	2,745	100.00%	2,756	2,756	100.00%

Table 6-3: July 2012 RTS Inspection SG Tube Inspection Summary

SCOPE DESCRIPTION			S/G 2E-088			S/G 2E-089		
<i>Leg</i>	<i>Exam Description</i>	<i>Extents</i>	<i>Analyzed</i>	<i>Scope</i>	<i>% Completed</i>	<i>Analyzed</i>	<i>Scope</i>	<i>% Completed</i>
Hot	H/L U-Bend RPC	07H-B07	N/A	N/A	N/A	104	104	100.00%
Cold	C/L U-Bend RPC	07C-B07	N/A	N/A	N/A	104	104	100.00%
	Total Plan		N/A	N/A	N/A	208	208	100.00%

SONGS 2C17 Steam Generator Condition Monitoring Report

Table 6-4: Wear Indication Summary

Steam Generator SG2E88 (Through- Wall Wear)	Anti-Vibration Bar	Tube Support Plat	Tube-to-Tube Wear	Retainer Bar	Foreign Object	Total Indications	Tubes with Indications (out of 9727 total per SG)
≥ 50%	0	0	0	1	0	1	1
35 - 49%	2	0	0	1	0	3	3
20 - 34%	86	0	0	0	2	88	74
10 - 19%	705	108	0	0	0	813	406
< 10%	964	117	0	0	0	1081	600
TOTAL	1757	225	0	2	2	1986	734*

* This value is the number of tubes with wear indications of any depth and at any location. Since many tubes have indications in more than one depth and location, the total number of tubes is less than the total number of indications.

Steam Generator SG2E89 (Through- Wall Wear)	Anti-Vibration Bar	Tube Support Plat	Tube-to-Tube Wear	Retainer Bar	Foreign Object	Total Indications	Tubes with Indications (out of 9727 total per SG)
≥ 50%	0	0	0	1	0	1	1
35 - 49%	0	0	0	1	0	1	1
20 - 34%	78	1	0	3	0	82	67
10 - 19%	1014	85	2	0	0	1101	496
< 10%	1499	53	0	0	0	1552	768
TOTAL	2591	139	2	5	0	2737	861*

* This value is the number of tubes with wear indications of any depth and at any location. Since many tubes have indications in more than one depth and location, the total number of tubes is less than the total number of indications.

SONGS 2C17 Steam Generator Condition Monitoring Report

Table 6-5: Plugging Summary

Reason for Plugging	Steam Generator		Total*
	2E-088	2E-089	
Retainer Bar Wear	2	4	6
AVB Wear >=35%	2		2
AVB Wear <35% for OA Margin	2		2
Preventative - Retainer Bar **	92	90	182
Total	98	94	192

* The plugging status shown in this table is current for non-TTW degradation. Due to the ongoing SG recovery efforts, the plugging strategy related to tubes with TTW and for preventative plugging for TTW may change prior to startup.

** Although 96 tubes were included in the retainer bar inspection scope (see Table 6-1), only 94 tubes were removed from service due to their proximity to the retainer bars. Two tubes were removed from the list of potentially affected tubes after closer review of the design drawings and consultation with MHI.

Table 6-6: Reported AVB Wear Depths (%TW)

SG	Average	Upper 95 th	Maximum
2E-088	10.1	19.2	35
2E-089	9.8	18.0	29
Both SGs	9.9	19.0	35

Table 6-7: Reported TSP Wear Depths (%TW)

SG	Average	Upper 95 th	Maximum
2E-088	9.7	14.0	17
2E-089	10.7	16.0	20
Both SGs	10.1	15.0	20

SONGS 2C17 Steam Generator Condition Monitoring Report

Table 6-8: Retainer Bar Wear

SG	Row	Col	Location	Sizing ETSS	Circ Extent (in)	Axial Extent (in)	Structural Depth (%TW)	Structural Length (in)
2E-088	124	48	B03+0.57"	27903.1	0.35	0.31	43.4	0.27
2E-088	125	49	B03+0.46"	27903.1	0.30	0.28	52.4	0.22
2E-089	118	44	B11-0.50"	27903.1	0.16	0.26	26.5	0.21
2E-089	119	133	B02+0.54"	27903.1	0.46	0.43	83.8	0.29
2E-089	120	132	B10-0.50"	27903.1	0.16	0.23	25.3	0.18
2E-089	120	132	B11-0.42"	27903.1	0.21	0.35	27.0	0.30
2E-089	127	127	B03+0.50"	27903.1	0.31	0.45	34.7	0.30

Table 6-9: Foreign Object Wear



SG	Row	Col	Location	Sizing ETSS	Circ Extent (in)	Axial Extent (in)	Structural Depth (%TW)	Structural Length (in)
2E-088	136	76	04H+0.56"	27901.1	0.31	0.25	25.7	0.21
2E-088	137	77	04H+0.76"	27901.1	0.31	0.20	30.2	0.15

Table 6-10: Tube-to-Tube Wear

SG	Row	Col	Location	Length (in.)	Structural Depth (%TW)	Structural Length (in)
2E-089	111	81	B09 +1.63 to +7.95	6.32	14.0	2.28
2E-089	113	81	B09 +2.03 to +8.22	6.19	13.7	1.67



SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 6-1: SG 2E-088 AVB Wear



SONGS 2C17 Steam Generator Condition Monitoring Report


Figure 6-2: SG 2E-089 AVB Wear



SONGS 2C17 Steam Generator Condition Monitoring Report



Figure 6-3: SG 2E-088 TSP Wear – Hot Leg

<p>SCE-SONGS Unit 2 - REPL Hot Leg TSP Wear</p>		<p>GROUP</p> <p>>=35% TWD 0</p> <p>20-34% TWD 0</p> <p><20% TWD 141</p>
<p>S/G 88 Repl HOT PRIMARY FACE</p>		<p>AREVA - FORM msp module Version 11.4</p> <p>TOTAL TUBES: 9727</p> <p>SELECTED TUBES: 141</p> <p>OUT OF SERVICE (#): NA</p>
		<p>SCALE: 0.086571 X</p> <p>Fri Aug 10 15:42:56 2012</p>



SONGS 2C17 Steam Generator Condition Monitoring Report


Figure 6-4: SG 2E-088 TSP Wear – Cold Leg



SONGS 2C17 Steam Generator Condition Monitoring Report


Figure 6-5: SG 2E-089 TSP Wear – Hot Leg

<p>SCE-SONGS Unit 2 - REPL Hot Leg TSP Wear</p>		<p>GROUP</p> <p>>=35% TWD 0</p> <p>20-34% TWD 0</p> <p><20% TWD 86</p>	<p>TUBES</p> <p>0</p> <p>0</p> <p>86</p>
<p>AREVA - TSPMS Hot Leg Model Version 11.0</p>		<p>TOTAL TUBES: 9727</p> <p>SELECTED TUBES: 86</p> <p>OUT OF SERVICE (#): NA</p>	
<p>SG 89 Repl</p> <p>HOT</p> <p>PRIMARY FACE</p>	<p>SCALE: 0.086571 X</p> <p>Fri Aug 10 15:51:07 2012</p>		



SONGS 2C17 Steam Generator Condition Monitoring Report


Figure 6-6: SG 2E-089 TSP Wear – Cold Leg



SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 6-7: SG 2E-088 Retainer Bar Wear


<p>SCE-SONGS Unit 2 - REPL Retainer Bar Wear Indications</p>		<p>GROUP B 803</p>	<p>TUBES 2</p>
<p><small>AREVA - 2008 max model version 11.0</small></p>		<p>TOTAL TUBES: 9727 SELECTED TUBES: 2 OUT OF SERVICE (#): NA</p>	
<p>S/G 88 Repl HOT Leg Indications PRIMARY FACE</p>		<p>SCALE: 0.066571 X Fri Aug 10 11:25:33 2012</p>	



SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 6-8: SG 2E-089 Retainer Bar Wear


<p>SCE-SONGS Unit 2 - REPL Retainer Bar Wear Indications</p>		<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">GROUP</th> <th style="text-align: left;">TUBES</th> </tr> </thead> <tbody> <tr> <td>B02</td> <td>1</td> </tr> <tr> <td>B03</td> <td>1</td> </tr> <tr> <td>B10</td> <td>1</td> </tr> <tr> <td>B11</td> <td>2</td> </tr> </tbody> </table>	GROUP	TUBES	B02	1	B03	1	B10	1	B11	2
GROUP	TUBES											
B02	1											
B03	1											
B10	1											
B11	2											
<p>AREVA - FOMIS map module Version 11.2</p>	<p>TOTAL TUBES: 9727 SELECTED TUBES: 4 OUT OF SERVICE (#): NA</p>											
<p>SG 89 Repl HOT and COLD Leg Indications PRIMARY FACE</p>	<p>SCALE: 0.066571 X Fri Aug 10 16:00:40 2012</p>											



SONGS 2C17 Steam Generator Condition Monitoring Report


Figure 6-9: SG 2E-088 Foreign Object Wear

<p>SCE-SONGS Unit 2 - REPL Foreign Object Wear (@04H)</p>		<p>GROUP F Foreign Object Wear</p>	<p>TUBES 2</p>
<p>SIG 88 Repl HOT PRIMARY FACE</p>		<p>AREVA - TOWS max module version 1.2</p> <p>TOTAL TUBES: 9727 SELECTED TUBES: 2 OUT OF SERVICE (#): NA</p>	
		<p>SCALE: 0.066571 X Fri Aug 10 11:34:38 2012</p>	




SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 6-10: Tube-to-Tube Wear (Detected in SG 2E-089 Only)




SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 6-11: SG 2E-088 AVB Wear Depth Distribution




SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 6-12: SG 2E-089 AVB Wear Depth Distribution




SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 6-13: SG 2E-088 TSP Wear Depth Distribution




SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 6-14: SG 2E-089 TSP Wear Depth Distribution



SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 6-15: Foreign Object Retrieved from SG 2E-088



SONGS 2C17 Steam Generator Condition Monitoring Report

7.0 CONDITION MONITORING ASSESSMENT

In order to satisfy Condition Monitoring requirements, all degradation mechanisms detected during the 2C17 outage must meet the structural and leakage performance criteria described in Section 5.0. Satisfaction of the CM criteria can be demonstrated either analytically or through in situ pressure testing. Structural and accident-induced leakage integrity are evaluated analytically based on the degradation mechanism's characteristics, including circumferential extent, axial length, and through-wall depth. Operational leakage integrity is monitored via leakage detection systems and procedures during plant operation.

Consistent with the structural integrity criteria described in Section 5.0, the limiting pressure loading occurs at a value of three times the normal operating differential pressure. For SONGS-2 this value is 4290 psi [6]. In addition to pressure loads, the CM must also consider the impact of non-pressure accident loads if they could have a significant effect on the burst pressure of the degraded tubes. A review of the screening guidance of Section 3.7.2 of Reference 2 provides the basis for concluding that non-pressure accident loads are not limiting for the identified tube wear in SONGS-2 SG tubes. Reference 2 indicates that the burst pressure of flat bar wear in U-bend flanks of re-circulating SG tubes (i.e., AVB wear), wear less than 270° in circumferential extent at supports below the top TSP, and degradation with circumferential involvement less than 25 PDA (Percent Degraded Area) anywhere in the tube bundle; will not be significantly affected by non-pressure loads. The accident-induced leakage performance criteria must also be assessed, and in addition to the SLB pressure (2560 psi [6]), must also consider non-pressure loads where appropriate. This is discussed in more detail within this section.

In order for a degraded tube to be returned to service, the degradation must be measured using a qualified ECT sizing technique, and the degradation must be evaluated as acceptable for continued operation. The sizing techniques qualified for use at SONGS-2 are identified in the Degradation Assessment [6] and are detailed in the ECT technique site validation documents [7] and [15]. If a degradation mechanism cannot be sized with appropriate sizing confidence, it is plugged on detection. All degradation identified during the current outage was measured with a qualified ECT technique.

This was the first inservice inspection of the SONGS Unit 2 SG tubes; performed after one cycle of operation following SG replacement. The potential for mechanical wear to develop at various locations within the SGs was recognized prior to the examination, but the identification of significant wear at retainer bars was not specifically anticipated. Although the examination program as planned was well capable of detecting this mechanism, the Degradation Assessment [6] was revised during the outage to include this new mechanism. The identification of tube-to-tube wear was not anticipated and not detected in the initial inspection scope. After the identification of tube-to-tube wear in Unit 3, additional inspections were performed, wherein two tubes in SG 2E-089 with tube-to-tube wear were identified.

7.1 Input Parameters

Table 7-1 and Table 7-2 identify the input parameters used to perform the Condition Monitoring assessment. In particular, these inputs were used within the AREVA Mathcad tool which implements the SG Flaw Handbook equations [10], in order to generate the limit curves discussed in Section 7.2. The flaw model for axial thinning with limited circumferential extent was used for the analyses (Section 5.3.3 of Reference 4). The 4290 psi $3\Delta P$ value is based on a conservative assessment of Unit 2 secondary side steam pressure as measured during cycle 16.

SONGS 2C17 Steam Generator Condition Monitoring Report

Table 7-1: SONGS-2 Steam Generator Input Values

<i>Parameter</i>	<i>Value</i>
Desired probability of meeting burst pressure limit	0.95
Tubing wall thickness	0.043 inch, [7]
Tubing outer diameter	0.750 inch, [7]
Mean of the sum of yield and ultimate strengths at temperature	116000 psi, [11]
Standard deviation of the sum of yield and ultimate strengths	2360 psi, [11]
3 X Normal Operating Pressure Differential (3 NOPD)	4290 psid, [6]
EFPD from SG Replacement through 2C17	627.11, [10]

Table 7-2: Eddy Current ETSS Input Values (Reference 5)

<i>Parameter</i>	<i>ETSS 96004.1</i>	<i>ETSS 27903.1</i>	<i>ETSS 27902.2</i>	<i>ETSS 96910.1</i>	<i>ETSS 27901.1</i>
Probe Type	Bobbin Coil	+Point™	+Point™	+Point™	+Point™
NDE depth sizing regression parameters	Slope = 0.98 Intercept = 2.89 %TW	Slope = 0.97 Intercept = 2.80 %TW	Slope = 1.02 Intercept = 0.94 %TW	Slope = 1.01 Intercept = 4.30 %TW	Slope = 1.05 Intercept = -1.97 %TW
NDE depth sizing technique uncertainty (standard deviation)	4.19 %TW	2.11 %TW	2.87 %TW	6.68 %TW	2.30 %TW
NDE depth sizing analysis uncertainty (standard deviation)	2.10 %TW	1.06 %TW	1.44 %TW	3.34 %TW	1.15 %TW
Total NDE (Sizing and Technique) (standard deviation)*	4.69 %TW	2.36 %TW	3.22 %TW	7.48 %TW	2.60 %TW

* Total uncertainty is the technique and analysis uncertainties combined via the square root of the sum of the squares.

SONGS 2C17 Steam Generator Condition Monitoring Report

7.2 Evaluation of Structural Integrity

7.2.1 AVB wear and TSP wear

AVB wear and TSP wear were evaluated with the flaw model described in Reference 4 as “axial part-throughwall degradation < 135° in circumferential extent.” The maximum circumferential extent of a single 100%TW wear scar formed by a long flat bar positioned tangentially to the tube surface (e.g., an AVB) is 55.4°. For double-sided AVB wear the total circumferential extent for this limiting case would be well below the 135° limit established by this model; hence, this flaw model is appropriate for AVB wear. For double-sided AVB wear and double- or triple-sided TSP wear this model also remains bounding because the AVB and TSP geometries provide sufficient circumferential separation between the wear scars to permit each indication to be treated separately. The separation between centerline contact points for AVB wear and TSP wear is 180° and 120°, respectively, and results in negligible circumferential interaction between separate wear locations in the same axial plane of the tube.

The topic of external loads must be addressed. The maximum reported AVB wear depth (35 %TW), adjusted upward to conservatively account for sizing uncertainty (ETSS 96004.1), is 45%TW. If it assumed that this flaw is double-sided; and it is further conservatively assumed that the total circumferential extent is 111° (see above), the resulting Percent Degraded Area (PDA) would be 14. Similarly, the maximum reported TSP wear depth (20%TW) adjusted to account for NDE uncertainty is 30%TW. If it assumed that this wear depth occurs at all three TSP land contacts, each with the limiting circumferential extent of 55.4°, the resulting PDA would be 14. Because the circumferential involvement of these flaws is less than 25 PDA, external loads need not be considered in the evaluation of burst integrity.

The bobbin probe was used to measure the depth of AVB wear and TSP wear through the application of ETSS 96004.1. CM limit curves for AVB wear and TSP wear based upon ETSS 96004.1 and the parameters provided in Table 7-1 and Table 7-2, are provided in Figure 7-1 and Figure 7-2, respectively. These figures also include the throughwall depth of each indication reported, plotted at the assumed axial flaw length. The assumed flaw length for AVB wear indications was derived from the flaw profiles (using line-by-line sizing). Twenty-two AVB wear indications were profiled with emphasis placed on the deeper indications for profiling. Of the AVB wear scars profiled (using line by line sizing) the maximum structural length was determined to be slightly less than 0.6 inches. A bounding length of 0.7 inches was chosen for the AVB wear as shown on Figure 7-1. This is slightly longer than the 0.59 inch width of the AVBs.

The TSP wear flaws are plotted at a length of 1.4 inches, slightly longer than the thickness of the TSPs (1.38 inches). Since all AVB wear and TSP wear flaws lie below their respective CM limit curves, it is concluded that the structural integrity performance criterion was satisfied with respect to these degradation mechanisms during the operating period preceding the 2C17 outage.

7.2.2 Retainer Bar Wear

Retainer bar wear was also evaluated with the “axial part-throughwall degradation < 135° in circumferential extent” degradation model as described in Reference 4. The maximum measured circumferential extent of RB wear was 0.46 inches (Table 6-8) which corresponds with an angular extent at the mid tube wall of 75°; well within the 135° requirement for this flaw model. Because of the rather short axial extent of the RB wear indications, it is prudent to also consider the potential for rupture in the circumferential direction. For the indication with the largest circumferential extent (0.46

SONGS 2C17 Steam Generator Condition Monitoring Report

inch, SG 2E-089 R119 C133 B02), and a limiting assumption that the wear is 100%TW over the entire circumferential extent, the PDA is found to be 21 PDA (i.e., $(0.46)/(\pi(\text{mid-wall diameter}))$). This limiting flaw was evaluated with the degradation model for circumferential cracking under pressure loading as described in Reference 2. Based on this model the lower bound burst pressure in the circumferential direction was determined to be 6470 psi; much less limiting than the results from the axial part-throughwall model (discussed below). This provides the basis for concluding that the axial part-throughwall degradation model is appropriate for the evaluation of RB wear.

External loads which are assumed to exist concurrently with the SLB accident do not significantly affect burst pressure in tubes with flaws located in the U-bend region on the tube flanks ($\pm 45^\circ$) [2]. +Point™ probe examinations were performed with another eddy current probe placed in an adjacent tube in order to estimate the position of the limiting flaw (SG 2E-089 R119 C133 B02) relative to the tube flank. This testing showed that the flaw lies approximately 40 to 50 degrees from the flank position; consequently, the RB wear may not lie entirely within the flank region. However, it is also known that external loads do not significantly affect burst pressure in tubes with flaws whose circumferential involvement is less than 25 PDA [2]. The upper bound circumferential involvement of the limiting RB wear flaw is only 21 PDA. It is therefore concluded that the limiting Condition Monitoring structural criteria is 3x normal operating pressure differential, rather than 1.2x the combined loading of SLB pressure and external loads. In short, it is appropriate to consider pressure loading-only for the structural integrity evaluation of RB wear flaws.

The axial depth profile of each RB wear flaw was measured using ETSS 27903.1, and this data was used to determine the structurally significant dimensions of the flaws using the methods described in Section 5.1.5 of Reference 4. The results are provided in Table 6-8 and are plotted on the CM curve provided in Figure 7-3. Since the RB wear in tube SG 2E-089 R119 C133 B02 lies above the CM curve in Figure 7-3, it could not be demonstrated on the basis of NDE measurements and analytical evaluation that this tube met the structural integrity performance criteria. Consequently, this tube was subjected to in situ pressure testing. All other RB wear indications lie below the CM curve and, hence, are shown to meet the structural integrity performance criteria analytically.

In situ accident leakage and structural proof testing was performed on tube SG 2E-089 R119 C133 B02 in accordance with the guidance provided in Reference 3. The normal operating, accident level, and proof test hold pressures were adjusted to account for temperature effects on material strength, and other factors related to the test process. All testing was accomplished using full tube pressurization. The tube was held pressurized at the required hold times without any difficulties. No leakage or rupture occurred at any time during the test, thereby successfully demonstrating that the tube met the SONGS accident leakage performance criteria and structural integrity performance criteria during the operating period preceding the 2C17 outage. This result also demonstrates the generous level of conservatism inherent in the flaw sizing and analytical methods used to evaluate SONGS SG tube volumetric degradation. The in situ test results are documented in Reference 12.

7.2.3 Foreign Object Wear

Foreign object wear was evaluated with the "axial part-throughwall degradation $< 135^\circ$ in circumferential extent" flaw model as described in Reference 4. The measured circumferential extent of both reported FO wear flaws was 0.31 inches or 50° , which is well within the 135° constraint of this model. Although these flaws are short axially, the circumferential involvement is only 14 PDA. Thus these tubes would not preferentially burst in the circumferential mode prior to axial burst, and the use of the axial part-throughwall flaw model remains appropriate (see Section 7.2.2). In addition, because these flaws are located well below the top TSP (i.e., they are at the 4th TSP), and because the

SONGS 2C17 Steam Generator Condition Monitoring Report

circumferential involvement is less than 25 PDA, external loads need not be considered in the evaluation of burst integrity.

The +Point™ probe was used to measure the axial depth profile of the flaws through the application of ETSS 27901.1. This data was used to determine the structurally significant dimensions of the flaws (Table 6-9) by applying the methods described in Section 5.1.5 of Reference 4. The applicable CM limit curve, based upon ETSS 27901.1 and the parameters provided in Table 7-1 and Table 7-2, is shown in Figure 7-4 along with the structurally equivalent dimensions of each FO wear flaw. Since both flaws lie well below the CM limit curve, it is concluded that the structural integrity performance criteria was satisfied with respect to foreign object wear during the operating period preceding the 2C17 outage.

7.2.4 Tube-to-Tube Wear

Tube-to-tube wear (TTW) was evaluated with the flaw model described in Reference 4 as “axial part-throughwall degradation < 135° in circumferential extent.” The circumferential extent of a TTW flaw is limited by the geometry of the interacting tubes such that it can be modeled as a single 100%TW wear scar formed by a flat bar positioned tangentially to the tube surface. In this configuration the maximum circumferential extent of the degradation will be 55.4°. For double-sided TTW this model is bounding because the wear geometry provides sufficient circumferential separation between the wear scars to permit each indication to be treated separately. The separation between centerline contact points for double-sided TTW is 180°, and results in negligible circumferential interaction between separate wear locations in the same axial plane of the tube. With respect to external loads, each wear flaw at the same axial location may be treated individually. An individual TTW flaw with a depth of 100%TW and a circumferential extent of 55.4° would be less than 16 PDA. Because the circumferential involvement of this limiting flaw is less than 25 PDA, external loads need not be considered in the evaluation of burst integrity for TTW.

The +Point™ probe was used to estimate the depth and the overall length of TTW through the application of ETSS 27902.2. The flaws had estimated maximum depths of 15% and 14%TW. The maximum indicated length of TTW was 6.32 inches. These lengths and depths are well below the CM limit curve for TTW using ETSS 27902.2 (see Figure 6-6). Despite the fact that both of these flaws clearly meet the structural integrity criterion based on the maximum measured lengths and depths, both flaws were line-by-line sized to obtain structural depths and lengths as well as to obtain information on the shapes of the flaws. Figure 6-6 depicts the structurally-equivalent dimensions of both flaws relative to the CM limit curve.

Based on the shallow depths of the TTW flaws detected, in situ pressure testing of these flaws was not required nor was it performed.

SONGS 2C17 Steam Generator Condition Monitoring Report

7.3 Evaluation of Accident-induced Leakage Integrity

7.3.1 AVB wear and TSP wear

Volumetric degradation that is predominantly axial in orientation and is greater than 0.25 inch long will leak and burst at essentially the same pressure [2]. The SONGS-2 AVB wear and TSP wear flaws meet this description. The evaluation in Section 7.2.1 demonstrated that the AVB wear and TSP wear identified during the 2C17 outage satisfied the burst integrity criteria at a pressure of 4290 psi. Consequently, the leakage integrity of AVB wear and TSP wear at the much lower SLB pressure differential of 2560 psi is also demonstrated by that evaluation. All of the tubes with AVB wear and TSP wear flaws satisfied the SONGS accident-induced leakage performance criteria during the operating period prior to the 2C17 outage.

7.3.2 Retainer Bar Wear

The accident-induced leakage integrity of tubes with RB wear is bounded by tube SG 2E-089 R119 C133 which had the largest measured RB wear flaw identified during the 2C17 outage. The leakage integrity of this tube was confirmed by in situ pressure testing, during which the tube did not leak or rupture at any pressure level. Based upon the in situ test results it is concluded that all of the tubes with RB wear flaws satisfied the SONGS accident-induced leakage performance criteria during the operating period prior to the 2C17 outage. The in situ test is discussed in more detail in Section 7.2.2 and in Reference 12.

7.3.3 Foreign Object Wear

Since the axial length of the FO wear flaws is less than 0.25 inch it is theoretically possible that pop-through and leakage could occur prior to tube rupture. Per Reference 2, a conservative evaluation of this potential may be performed through the use of the Reference 4 flaw model for uniform depth, 360° volumetric degradation. The limit curve of Figure 7-5 identifies the throughwall limit for uniform 360° thinning at 2560 psi. As with a CM limit, this curve includes the effects of relational, material strength, and NDE sizing uncertainties. The relational uncertainty is the uncertainty between the actual burst pressure and the calculated burst pressure based on known structural lengths and depths. The reported maximum depth and overall axial length for the two FO wear flaws are also shown in Figure 7-5. Because both flaws lie well below the curve it is concluded that the foreign object wear identified did not violate the accident-induced leakage performance criteria during the operating period prior to the 2C17 outage.

7.3.4 Tube-to-Tube Wear

Volumetric degradation that is predominantly axial in orientation and is greater than 0.25 inch long will leak and burst at essentially the same pressure [2]. The tube-to-tube wear flaws meet this description. The evaluation in Section 7.2.4 demonstrated that the tube-to-tube wear identified during the 2C17 outage satisfied the burst integrity criteria at a differential pressure of 4290 psi. Consequently, the leakage integrity of tube-to-tube wear at the much lower SLB pressure differential of 2560 psi is also demonstrated by that evaluation. All of the tubes with tube-to-tube wear flaws satisfied the SONGS accident-induced leakage performance criteria during the operating period prior to the 2C17 outage.




SONGS 2C17 Steam Generator Condition Monitoring Report

7.4 Evaluation of Operational Leakage Integrity

Throughout the operating period preceding the 2C17 outage, SONGS Unit 2 experienced no measurable primary to secondary leakage. Therefore, the operational leakage performance criterion was satisfied during this period.


SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 7-1: CM Limit for AVB Wear, ETSS 96004.1




SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 7-2: CM Limit for TSP Wear, ETSS 96004.1




SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 7-3: CM Limit for RB Wear, ETSS 27903.1




SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 7-4: CM Limit for FO Wear, ETSS 27901.1




SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 7-5: Foreign Object Pop-Through at 2560 psi, Uniform 360° Thinning, ETSS 27901.1



SONGS 2C17 Steam Generator Condition Monitoring Report

Figure 7-6: CM Limit for Tube-to-Tube Wear, ETSS 27902.2





SONGS 2C17 Steam Generator Condition Monitoring Report

8.0 CONDITION MONITORING CONCLUSION

This Condition Monitoring assessment has evaluated all SG tube degradation detected during the 2C17 outage against the three SONGS technical specification performance criteria. Through a combination of eddy current inspection, analytical evaluation, in situ pressure testing, and operational leakage monitoring it has been determined that the three performance criteria: 1) structural integrity, 2) accident-induced leakage integrity, and 3) operational leakage integrity; were satisfied during the operating period prior to the 2C17 outage.

SONGS 2C17 Steam Generator Condition Monitoring Report

9.0 REFERENCES

1. NEI 97-06, "SG Program Guidelines," Rev. 3, January 2011.
2. EPRI Report 1019038, "SG Integrity Assessment Guidelines: Revision 3", November 2009.
3. EPRI Report 1014983, "Steam Generator In situ Pressure Test Guidelines, Revision 3", August 2007.
4. EPRI Report 1019037 "Steam Generator Degradation Specific Management Flaw Handbook, Revision 1", December 2009.
5. EPRI, SG Management Project, "sgmp.epri.com."
6. AREVA Document 51-9176667-001, "SONGS 2C17 & 3C17 Steam Generator Degradation Assessment"
7. AREVA Document 51-9104383-002, "SONGS Units 2 & 3 Replacement Steam Generators Eddy Current Technique Validation"
8. AREVA Document 03-9170186-003, "Secondary Side Visual Inspection Plan and Procedure for SONGS 2C17" (SONGS Procedure Number SO23-XXVII-25.36)
9. AREVA Document 32-5033045-002, "Mathcad Implementation of SG Flaw Handbook Equations for Integrity Assessment"
10. *Matheny, Southern California Edison, "Numerical Values for the SG DA, SONGS Unit 2, Southern California Edison," January 18, 2012
11. *SONGS Unit 2 Replacement Steam Generator Receipt Inspection QA Document Review Package, (statistics evaluated in Excel file "CMTR Final with Stats.xlsx")
12. AREVA Document 51-9177395-000, "In-Situ Pressure Test Summary for SONGS Unit 2 (Feb 2012)"
13. *SONGS Nuclear Notification 201854749, Created February 13, 2012
14. AREVA Document 51-9177491-001, "SONGS 2C17 Steam Generator Condition Monitoring and Preliminary Operational Assessment"
15. AREVA Document 51-9177744-000, "Site Validation of EPRI Sizing ETSS for Tube-Tube Wear in SONGS Steam Generators"
16. AREVA Document 51-9179946-001, "Comparison of Bobbin and +Point POD for Tube-Tube Wear in SONGS Steam Generators"
17. SONGS Technical Specifications Section 5.5.2.11, "Steam Generator (SG) Program", Amendment 204
18. SONGS Technical Specifications Section 3.4.13, "RCS Operational Leakage", Amendment 204
19. INPO Operating Experience Report OE 34946, "Tube-to-Tube Contact Wear Identified in TMI-1 Steam Generators (TMI-1)"
20. NRC Information Notice 2012-07, "Tube-to-Tube Contact Resulting in Wear in Once-Through Steam Generators"
21. INPO Operating Experience Report OE 35359, "Large Number of Anti-Vibration Bar Wear Indications Reported in the Unit 2 Replacement Steam Generators (St. Lucie)



SONGS 2C17 Steam Generator Condition Monitoring Report

- 22. MHI Document L5-04GA111, "San Onofre Generating Station, Units 2 & 3 Replacement Steam Generators Vendor Manual", Rev 6 (SONGS Document SO23-617-1-M1273, Rev 6)
- 23. AREVA Document 51-9181604-000, "SONGS Unit 2 Cycle 17 and U2 Return to Service Eddy Current Inspection Technical Summary"

* These references are not available from the AREVA records center; however, they are available from the SCE document control system. Therefore, these are acceptable references for use on this contract per AREVA NP Procedure 0402-01, Attachment 8 as authorized by the PM signature on page 2.