

1 UNITED STATES OF AMERICA

2 NUCLEAR REGULATORY COMMISSION

3 + + + + +

4 ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

5 SUBCOMMITTEE ON PLANT LICENSE RENEWAL

6 + + + + +

7 WEDNESDAY, APRIL 1, 2009

8 + + + + +

9 ROCKVILLE, MD

10 The Subcommittee convened in Room T2B3 in
11 the Headquarters of the Nuclear Regulatory Commission,
12 Two White Flint North, 11545 Rockville Pike,
13 Rockville, Maryland, at 1:30 p.m., Dr John Stetkar,
14 Chair, presiding.

15 SUBCOMMITTEE MEMBERS PRESENT:

16 JOHN W. STETKAR, Chair

17 JOHN D. SIEBER

18 SAM ARMIJO

19 WILLIAM J. SHACK

20 MARIO V. BONACA

21 SAID ABDEL-KHALIK

22 CHARLES H. BROWN, JR.

23 HAROLD B. RAY

24 MICHAEL T. RYAN

25

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24

CONSULTANT TO THE SUBCOMMITTEE PRESENT:

JOHN J. BARTON

NRC STAFF PRESENT:

BRIAN HOLIAN

JAY ROBINSON

EVELYN GETTYS

SAM LEE

GLENN MEYER

ROBERT SUN

XUHAN XI

MATT YODER

DUC NGUYEN

ALSO PRESENT:

MICHAEL GALLAGHER

STEVE QUEEN

FRED POLASKI

MARK MILLER

GENE NAVARTIL

DEBORA SPAMER

STU GETZ

MARJORIE AAMODT

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1	T-A-B-L-E O-F C-O-N-T-E-N-T-S	
2	Opening remarks	4
3	Staff introduction	6
4	Exelon Presentation	7
5	Introductions	
6	Operating History	11
7	GALL Consistency, Commitments, Confirmatory ..	
8	item 13	
9	Recent LR Industry Issues	29
10	Reactor Building Liner	30
11	Medium Voltage Cables	40
12	Fuel Storage Racks Containing Boral	59
13	NRC Staff Presentation SER Overview	87
14	Scoping and Screening Results	88
15	Onsite Inspection Results	94
16	NRC Audits	109
17	Public comment	
18	Marjorie Aamodt,	133
19	Committee on Health Aspects and	
20	Management of Nuclear Power	

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

P-R-O-C-E-E-D-I-N-G-S

1:29 p.m.

CHAIR STETKAR: The meeting will now come to order.

This is a meeting of the Plant License Renewal Subcommittee. I'm John Stetkar, Chairman of the Three Mile Island Plant License Renewal Subcommittee.

ACRS members in attendance are Jack Sieber, Sam Armijo, Bill Shack, Mario Bonaca, Said Abdel-Khalik, who made me too nervous, Mike Ryan. Who else is here? Charlie Brown and Harold Ray.

Christopher Brown of the ACRS staff is the Designated Federal Official for this meeting.

The purpose of this meeting is to review the license renewal application for the Three Mile Island Nuclear Station, the draft Safety Evaluation Report and associated documents. We will hear presentations from representatives of the Office of Nuclear Reactor Regulation and the applicant, Exelon Generation Corporation.

The Subcommittee will gather information, analyze relevant issues and facts and formulate proposed positions and actions as appropriate for deliberation by the full Committee.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 The rules for participation in today's
2 meeting were announced as part of the notice of this
3 meeting previously published in the *Federal Register*
4 on March 16, 2009.

5 We have received a request from one member
6 of the public who wishes to make an oral statement
7 over the phone. Ms. Marjorie Aamodt of the Committee
8 on Health Aspects and Management of Nuclear Power
9 requested ten minutes to make a statement regarding
10 today's meeting. We've opened a bridge line of Ms.
11 Aamodt.

12 Are you there?

13 MS. AAMODT: Yes, I'm here.

14 CHAIR STETKAR: Okay. Excellent.

15 MS. AAMODT: And I want to thank you,
16 Chairman.

17 CHAIR STETKAR: Thank you.

18 What we'll do is we'll put the bridge line
19 on mute so that you can listen in to the full
20 proceedings of the meeting and then open the bridge
21 line at the end of the meeting so that you can
22 participate and make your statement.

23 MS. AAMODT: Well, I will be able to
24 listen, though, all day, right?

25 CHAIR STETKAR: Oh, yes. Definitely.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Absolutely. You'll be able to listen to everything
2 that's said.

3 And with that, if you can -- thank you.

4 A transcript of the meeting is being kept
5 and will be made available as stated in the *Federal*
6 *Register* notice. Therefore, we request that
7 participants in this meeting use the microphones
8 located throughout the meeting room when addressing
9 the Subcommittee.

10 Participants should first identify
11 themselves and speak with sufficient clarity and
12 volume so that they can be readily heard.

13 We'll now proceed with the meeting and I
14 call upon Brian Holian, of the Office of Nuclear
15 Reactor Regulation to introduce the presents. Brian?

16 MR. HOLIAN: Thank you. Good afternoon.
17 My name is Brian Holian. I'm the Director of the
18 Division of License Renewal.

19 As the agenda states, I'll just make brief
20 staff introductions and turn it over to the licensee,
21 and then the staff presentation will follow.

22 To my left is Mr. David Pelton, the Branch
23 Chief that includes the Three Mile Island application
24 and review.

25 To his left is Mr. Jay Robinson, the

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Senior Project Manager responsible for the TMI review.

2 And to his left is Mr. Glenn Meyer, the
3 Senior Reactor Inspector from Region I.

4 In general, you know following up on this
5 morning's issue, Three Mile Island is similar to the
6 Susquehanna as relatively clean from the number of
7 open items or confirmatory items that the Subcommittee
8 received. We do have one item that the staff will
9 discuss during our presentation, which was similar to
10 this morning, on dissolved oxygen. One confirmatory
11 item where the staff in its peer reviews wants to
12 confirm some of the information from TMI on that
13 review. So you'll be hearing about that.

14 With that, I'll turn it over to Mr. Mike
15 Gallagher, Vice President for License Renewal Projects
16 for Exelon.

17 MR. GALLAGHER: Thanks, Brian.

18 Okay. Good afternoon. My name is Mike
19 Gallagher and I'm the Vice President of License
20 Renewal Projects at Exelon.

21 You can go to slide 2.

22 Before we get into today's presentation, I
23 would like to introduce the presenters.

24 Steve Queen was the TMI Engineering
25 Director during our license renewal application

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 preparation and is currently the Operations Director
2 at TMI. Steve has over 25 years experience at Three
3 Mile Island.

4 On our slide here we have Al Fulvio. Al,
5 unfortunately, became ill yesterday and cannot present
6 today. So presenting for Al will be Fred Polaski.
7 And Fred is our Corporate License Renewal Manager.
8 Fred has over 35 years of nuclear power plant
9 experience including over 10 years in license renewal.

10 Fred is an industry leader in the license renewal
11 field.

12 Next we have Pat Bennett. Pat is our
13 Mechanical Engineering Design Manager at TMI and has
14 over 25 years experience at TMI.

15 And to my left is Chris Wilson, our
16 Project Licensing Lead. Chris also has over 25 years
17 experience in nuclear power plants.

18 In addition to our technical support
19 personnel we have here today, we have Bill Noll. Bill
20 is our site Vice President at Three Mile Island.

21 And we have Amir Shahkarami. Amir is our
22 Senior VP of technical support and engineering at
23 Exelon.

24 Slide 3 shows our agenda for the
25 presentation. First, we will present to you the

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 highlights of the license renewal application.

2 Then we will present to you the one
3 confirmatory item that was in the draft SER.

4 And then we'll present to you some topics
5 of interest in aging management at TMI.

6 We believe we've developed a robust, high
7 quality license renewal application. We also
8 developed an overall effective aging management
9 program to ensure continued safe operation at TMI.

10 We appreciate this opportunity to make
11 this presentation and look forward to answering any
12 questions you may have.

13 If we go to slide 5, I'll now give a brief
14 overview of the TMI site. And I'll do this in the
15 next slide, slide 6 looking at the site aerial view.

16 So Three Mile Island is an island that's
17 in the Susquehanna River. It's in Londonderry
18 Township and it's about ten miles southeast of
19 Harrisburg, Pennsylvania.

20 In this photo the river flows north to
21 south, which is left to right in this photo.

22 On the island, this is the Unit 1 cooling
23 towers, the Unit 1 turbine building and the Unit 1
24 containment.

25 Unit 1 is a Babcock and Wilcox pressurized

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 water reactor.

2 Also located on the island is Unit 2. And
3 here are the Unit 2 cooling towers, turbine building
4 and containment.

5 And Unit 2 is owned by First Energy. Unit
6 2 has been shutdown since the March 28, 1979 accident
7 and is currently in safe storage mode called Post
8 Defueling Monitored Storage.

9 Unit 1 and Unit 2 are contained in a
10 common security protected area and is controlled by
11 Exelon. Exelon has access and use to all equipment
12 and facilities needed for the safe operation of Unit
13 1.

14 For license renewal there were two
15 structures that are owned by First Energy that are in
16 scope. They are the Unit 2 fuel handling building,
17 this structure right here, since it is a common
18 building with the Unit 1 fuel handling building. And
19 the Unit 2 diesel building, which is this structure
20 right here, since it contains the Unit 1 station
21 blackout diesel. These structures are all included in
22 the Unit 1 aging management programs.

23 On this photo you can also see the
24 switchyard, which is located on the island, and the
25 intake structure/pumphouse.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 If there's no questions, I'd like to then
2 turn it over to Steve Queen who will go over the plant
3 operating history.

4 MR. QUEEN: Good afternoon. My name is
5 Steve Queen and I'm the Operations Director at Three
6 Mile Island.

7 I'm going to give just a brief discussion
8 of the operating history of the plant.

9 The unit started commercial operation in
10 1974 and we operated on one year cycles at that time
11 until the TMI-2 accident in '79. At that point the
12 unit was shutdown for five to six years to do the
13 NUREG-0737 modifications.

14 On the restart, we went up in '88 by 1.3
15 percent power to 2568 and then went to two year
16 operating cycles.

17 In 1999 the unit was sold to Pico and
18 British Energy into a unity called AmerGen. And then
19 we replaced the turbine rotors, the main transformers,
20 our auxiliary transformers and a new reactor head.

21 We presented our license renewal
22 application in 2008. And then we transferred our
23 license in a name change only from AmerGen to Exelon.

24 The steam generators are scheduled for
25 fall of 2009. We'll replace those.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 And our operating history since 2001 has
2 been two consecutive breaker to breaker runs. And we
3 just recently started up in 2007 out of our outage and
4 we've been continuously running since then until our
5 2009 outage, when again we'll replace our steam
6 generators.

7 Unit capability factor has been about 95
8 percent during that time frame. And our current
9 license expires in 2014.

10 With that, if there's no questions on the
11 operating history.

12 MR. GALLAGHER: Okay. We'll turn it over
13 to Fred Polaski.

14 MR. POLASKI: Good afternoon. I'm Fred
15 Polaski with Exelon.

16 I would like to talk about and discuss the
17 consistency of the TMI license renewal application as
18 it compares to NUREG-1801, the NRC's GALL report and
19 also briefly discuss how TMI will implement the
20 commitments we've made as part of license renewal and
21 then address the one confirmatory item that we have in
22 the draft SER.

23 TMI and as part of the license renewal
24 application identified 38 aging management programs.
25 Twenty-four of these were consistent with the GALL

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 report and 14 are consistent with exceptions. The
2 exceptions that we took in the TMI license renewal
3 application were the same exceptions that have been
4 taken on other license renewal applications and have
5 been accepted by the NRC.

6 When we prepared our application and
7 prepared our aging management programs and then
8 compared them to the descriptions of the programs in
9 the GALL report, any differences we identified we
10 considered to be exceptions to the GALL report and
11 presented them as such in the application.

12 Now just some examples of that. There are
13 two exceptions where we credit EPRI reports. Since
14 the GALL document was published in 2005 EPRI has
15 updated those documents to later revisions. TMI
16 implements the later revision, so we considered those
17 as part of our exceptions because of the difference in
18 the revision of the document.

19 Five of the exceptions are due to aging
20 management programs that we expanded to include
21 materials, environments and aging effects, more than
22 what are those listed in the GALL report.

23 And as a final example there are two
24 exceptions because the GALL report references NRC
25 guidance documents which have been updated by the NRC.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 But the latest revision to the GALL hasn't yet been
2 updated to reflect those revisions. So we used the
3 latest revision at the plant.

4 So by way of example, the point is here
5 these revisions are minor in nature, they're not major
6 technical issues, a lot of them dealing with revisions
7 of existing documents.

8 On to slide 10. Oh, no, on the same one.

9 On commitments, all of our license renewal
10 commitments are managed through Exelon's fleet wide
11 commitment tracking program. This program implements
12 the guidance provided in NEI 99-04, which is the
13 Nuclear Energy Institute's guideline for managing NRC
14 commitment changes.

15 We have made 43 commitments for the TMI
16 license renewal application. Thirty-eight of these
17 are the aging management programs that we described in
18 the application that we'll be crediting for managing
19 aging during the period of extended operation. And
20 then there was five additional commitments that we
21 made.

22 One is that we have committed to implement
23 the pressurized water reactor vessel internals program
24 once it has been approved. It is currently under
25 development in the industry. TMI will submit our

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 inspection plans to the NRC once they're completed for
2 their review and approval and we'll do that at least
3 24 months prior to entering the period of extended
4 operation.

5 Second, TMI is committed to installing
6 these new steam generators prior to entering the
7 period of extended operation. Our commitment is to
8 have them installed before 2014. As Steve mentioned,
9 the plan is to do that in 2009.

10 We also will be submitting new reactor
11 vessel pressure-temperature limit curves prior to
12 entering the period of extended operation. The
13 commitment also includes a commitment to submit those
14 prior to reaching 29 effective full power years. The
15 current pressure-temperature curves for TMI are only
16 good for 29 EFPY. But TMI will reach 29 EFPY at about
17 the end of the current license term. With real good
18 operation it will be before, if there would be some
19 problems it may be after. So the commitment covers it
20 either way.

21 The fourth one is we've also committed to
22 perform weld repairs throughout the building liner to
23 correct some corrosion problems there. We've
24 committed to do that prior to entering the period of
25 extended operation.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 And the last commitment is that we will
2 continue to perform surveillance of the Boral test
3 coupons for the spent fuel storage racks.

4 MR. BARTON: What are the extended
5 corrosion of the liner?

6 MR. POLASKI: We've got an item we're
7 going to discuss that in detail later, if you wouldn't
8 mind holding off.

9 MR. BARTON: No problem.

10 MR. POLASKI: Okay.

11 CHAIR STETKAR: Fred, I had one question
12 and I don't think you're going to -- on one specific
13 exception that I kind of stumbled over and I wanted to
14 understand it a little bit.

15 On fuel oil testing --

16 MR. POLASKI: Yes.

17 CHAIR STETKAR: -- you took an exception
18 to testing the fuel oil in the 50,000 gallon fuel oil
19 storage tank. And not having had the ability to
20 figure out what fuel oil storage tank that 50,000
21 gallon storage tank: The first question is what does
22 the 50,000 gallon tank supply because there seemed to
23 be several fuel oil storage tanks?

24 MR. QUEEN: I'm Steve Queen, Operations
25 Director.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 The 50,000 gallon tank supplies actually a
2 second tank, which is a 30,000 gallon tank. And that
3 is the main supply tank to our emergency diesel
4 generators.

5 CHAIR STETKAR: Okay.

6 MR. QUEEN: That 50,000 tank has the
7 capability of supplying other things other than the
8 emergency diesel generator storage tank, but that's
9 its purpose.

10 CHAIR STETKAR: I'm just trying to sort it
11 out in my head.

12 You said that the place that you sample is
13 somewhere near the bottom of the tank. You said the
14 draw off line, I think the words are "toward the
15 bottom of the tank." And I believe that the
16 discussion says something to the effect while you
17 recirc the tank and you mix it up and then you sample
18 it, which is conservative. And I'm not sure how
19 that's conservative because you're sort of diluting
20 the contaminants in the main volume of the tank. So I
21 wasn't quite sure how that was conservative.

22 But I came across another commitment or
23 part of another program that says "activities to
24 periodically drain water and sediment from tank
25 bottoms for the 50,000 gallon fuel oil storage tank,

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the 30,000 gallon diesel fuel oil storage tank and the
2 diesel fire pump 350 gallon tank," that's one of the
3 enhancements to one of your programs. So I was
4 curious if you can drain water from the bottom of the
5 tank, why can't you sample from the bottom of the
6 tank, or am I misinterpreting something here?

7 MR. POLASKI: We'd like to ask Mark Miller
8 from Exelon to address that question.

9 MR. MILLER: Mark Miller from Exelon.

10 Yes. For the 50,000 gallon storage tank
11 we do sample because its sampled weekly because it is
12 the supply to the emergency diesel tanks, its sampled
13 as part of the recirculation loop. And in that way
14 because it's drawing off the normal pump suction for
15 that tank, it's lower towards the bottom of the tank,
16 we feel it does provide a representative sample of the
17 oil. The other option that the program requires is a
18 multilevel sample, which is lowering a sample
19 container down through the top of the tank, popping
20 the cork and pulling it up at a certain rate to get a
21 multilevel representative sample. Because this is
22 sampled weekly, that's not a practical thing to do
23 from a safety standpoint and climbing ladders and
24 things like that. So we took the exception to use
25 this recirculation mode and grab a sample off that

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 line and use that as our equivalent sample to a
2 multilevel sample.

3 CHAIR STETKAR: But does that mean -- I
4 was trying to understand that in combination with
5 what's called -- in the SER it's called enhancement 7.

6 It's probably not numbered that way in your program.

7 MR. MILLER: You're referring to the
8 draining, periodically draining water and sediment?
9 Yes, that's another --

10 CHAIR STETKAR: Yes. It says "from the
11 bottom of the tank."

12 MR. MILLER: Right. That's another
13 requirement for the fuel oil program.

14 CHAIR STETKAR: It's a requirement?

15 MR. MILLER: Right.

16 CHAIR STETKAR: But can you physically do
17 that from this tank?

18 MR. MILLER: Yes. Yes, there's drains.
19 Those will be done from the drains.

20 CHAIR STETKAR: Why can't you sample from
21 that drain then to see whether there's -- for the
22 status of the oil in the bottom of the --

23 MR. MILLER: Well, I believe they are when
24 they -- in some of the tanks at least, they do provide
25 a sampling. And they do a visual for the presence of

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 water under draining water and sediment if there is
2 any water and sediment.

3 MR. GALLAGHER: I think the question is--

4 CHAIR STETKAR: The question is if you can
5 drain things from the bottom of the tank, why did you
6 have to take the exception that you couldn't sample
7 the oil at the bottom of the tank?

8 MR. MILLER: Well, it would be an
9 exception to take a sample from the bottom since the
10 requirement is a multilevel sample. A bottom sample
11 wouldn't be considered multilevel.

12 CHAIR STETKAR: Oh, I understand. The
13 exception is multilevel and not --

14 MR. MILLER: Right. Right. Not -- yes.

15 CHAIR STETKAR: Understand. Thank you.
16 Thank you.

17 MEMBER BONACA: I have a question, too,
18 regarding tanks. There's problem on one time
19 inspections as inspections of the water chemistry,
20 fuel oil chemistry, lube oil chemistry, air, gas
21 whether the environment and here the concern -- one of
22 the concern is loss of material. And, you know, one
23 time exception typically has to do with a situation
24 where you do not expect to have a phenomenon so you do
25 once to verify the case. But reading the operating

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 experience for these tanks you had a number of
2 examples of loss of material. Could you expand on
3 that? I mean why would you have just one time
4 inspection rather than a program?

5 MR. QUEEN: The loss of material on tanks.

6 MEMBER BONACA: Fuel oil.

7 MR. QUEEN: Yes. And, Mark, why don't
8 you --

9 MEMBER BONACA: Fuel oil, lube oil; it's
10 only one time inspections you have under B.2.1.1.8.

11 MR. GALLAGHER: Right. So the question is
12 why is the one time inspection sufficient?

13 MEMBER BONACA: Given that you had other
14 history of some leaks here or there, why would you
15 consider one time inspection rather than having a
16 program to periodically inspect for loss of material?

17 MR. MILLER: Well, the reason there's a
18 one time inspection program is -- it's basically to
19 validate your chemistry programs and its specifically
20 targeted for stagnant or low flow areas where there's
21 no replenishment so you could maybe not have an
22 effective chemistry program in those spots. So that's
23 what the one time inspection program does, it looks at
24 -- in the case of fuel oil it'll look at fuel oil
25 piping and it'll find drain lines and vent lines and

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 things where chemistry will not be effective, or may
2 potentially not be effective in managing the aging
3 effects.

4 MEMBER BONACA: But you don't expect to
5 find a problem?

6 MR. MILLER: Right. Right. You know,
7 whereas the issues with the tanks are contaminates and
8 things like that tend to settle in the fuel oil tanks
9 and the fuel oil program is intended to prevent the
10 accumulation of those kind of things and to verify by
11 doing tank sampling and inspections that it's not
12 occurring within the tanks itself. And then that's
13 applied to the piping with verification to the one
14 time inspection program.

15 MEMBER BONACA: Okay. So it really is not
16 to the tanks itself, but the piping and the areas
17 where you do not have significant flow --

18 MR. MILLER: Right.

19 MEMBER BONACA: -- to have -- which is
20 consistent with your chemistry program? Okay.

21 Thank you.

22 CHAIR STETKAR: As long as we have you
23 here, what tank is FOT-1?

24 MR. MILLER: Geez.

25 MR. QUEEN: This is our main fuel oil tank

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 for --

2 MR. MILLER: Is that the 50,000 gallon?

3 MR. QUEEN: 50,000 gallon tank.

4 CHAIR STETKAR: That is the 50,000 gallon
5 tank? That's the one --

6 MR. QUEEN: Because FOT-2 -- FOT-1 is the
7 main tank where we deliver fuel oil.

8 MR. MILLER: That's the 30,000 gallon
9 tank?

10 MR. QUEEN: No. The 30,000 gallon tank--

11 MR. MILLER: Is FOT-8, I think.

12 MR. QUEEN: The 50,000 gallon tank and,
13 David, FOT-1 is which -- 200,000 gallon. It's the
14 main delivery tank. It's the main delivery tank for
15 fuel oil.

16 MR. MILLER: And that's not in scope and
17 it's not managed within the program, the 200,000
18 gallon tank. The 50,000 gallon tank is.

19 CHAIR STETKAR: Sorry.

20 MR. MILLER: No, that's okay. There's a
21 whole string of tanks that all connect --

22 CHAIR STETKAR: No. I mean, that was the
23 only one that was referred to by number. Everything
24 else is by gallons.

25 MR. MILLER: Right.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 CHAIR STETKAR: And I couldn't find
2 anything in the FSAR that kind of correlated
3 everything.

4 So continue. Thank you.

5 MR. GALLAGHER: Okay. Fred, I think you
6 still have it.

7 MR. POLASKI: Yes, I still have it. Slide
8 10.

9 We had one confirmatory item from the NRC
10 in the draft SER. The NRC requested information to
11 confirm that the dissolved oxygen level in the reactor
12 coolant during operation was less than 0.05 parts per
13 million. The reason for this is the dissolved oxygen
14 levels at input for the environmentally assisted
15 fatigue calculation. Now we have provided this
16 information to the NRC confirming that the dissolved
17 oxygen level during power operation is less than 0.050
18 ppm. And we understand that the staff is ready to
19 close this item, but they'll discuss that later today
20 during their presentation.

21 MEMBER SHACK: Now have you got a decimal
22 point in the wrong place here: 0.50 or 0.00?

23 MR. POLASKI: What was used in the
24 calculation for why it was less than .05, in reality
25 the dissolved oxygen is less than .005 or even less

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 than .0 -- it's not detectable because of the design
2 of the system with hydrogen in the system. So --

3 MEMBER SHACK: In your fatigue analyses
4 you relied very heavily on the number of design cycles
5 and you've used those as the basis and then
6 extrapolate those out. And typically that's very
7 conservative. But have you actually done a history
8 review to make sure that that's a conservative way to
9 do it?

10 MR. POLASKI: Yes, we've reviewed the
11 history. In the analysis we did, we did it initially
12 using the design numbers of cycles and actually did it
13 times one and a half to count 40 to 60 years. And for
14 some locations multiplying by one and a half and doing
15 the fatigue analysis you came out less than one. If
16 it didn't but we could show we were less than one at
17 the design numbers of cycles and we looked at the
18 history, we don't expect to come anywhere close to the
19 design numbers of cycles. And there was two locations
20 in considering environmental effects where we couldn't
21 stay less than one with the design number, so we used
22 a history.

23 The history was projected from when the
24 plant restarted after the six year shutdown going
25 forward and then conservatively assumed more cycles

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 than that to show that we would be less than one for
2 the environmentally assisted fatigue. We only needed
3 to do that on two locations only for environmental
4 effects.

5 MR. GALLAGHER: And, Dr. Shack, was your
6 question more about the severity of the individual
7 cycles? Because we also verified that.

8 MEMBER SHACK: Yes, that was --

9 MR. POLASKI: Right.

10 MR. GALLAGHER: We verified that the--

11 MEMBER SHACK: They truly were bounded?

12 MR. GALLAGHER: Yes, and it's something
13 that's routinely monitored, you know, in the fatigue
14 program. So that we not only did the numbers, but the
15 severity.

16 MR. POLASKI: And we used all of the
17 design cycles. We did not do any stress-based
18 analysis.

19 CHAIR STETKAR: I had a question. Bill,
20 are you --

21 MEMBER SHACK: Yes.

22 CHAIR STETKAR: Okay. The analyses that
23 were done to project the number of cycles for those
24 locations they're characterized as administrative
25 limits right now. So they're somewhere between the

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 current 40 year design limit or/and the number of
2 cycles that you would project given one and a half
3 times 40. Is that correct? I mean, that's --

4 MR. POLASKI: No. Where we put the
5 administrative limits on where those locations that on
6 the original design number of cycles when we did the
7 environmental assisted fatigue calculation would have
8 been greater than one. We have imposed an
9 administrative limit in our -- accounting program that
10 is a number lower than the design number of cycles.

11 So, for example, and I don't know if this
12 exact. For a particular cycle if the original design
13 number was 200 and we'd found out that at 200 cycles
14 we would have exceeded one in the CUF, but at 100
15 cycles we would have been less than one and we only
16 projected based on our operating history we have 60
17 cycles at the end of plant life, we would put an
18 administrative limit on less than a 100. Now don't go
19 looking those numbers up in the --

20 CHAIR STETKAR: The numbers, no.

21 MR. POLASKI: I just used them for an
22 example.

23 CHAIR STETKAR: I just wanted to know your
24 general thought process because I was trying to work
25 through --

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. POLASKI: Yes.

2 CHAIR STETKAR: Okay.

3 MR. POLASKI: And the reason this works
4 for TMI is that operating history has been so good,
5 you know. Steve mentioned they go breaker to break
6 one so you get one transient every cycle, it works out
7 fairly well.

8 Any other questions on the confirmatory
9 item? Okay.

10 Going on to slide 11.

11 I'd like to discuss two industry issues
12 and how we handled those in the TMI license renewal
13 application.

14 Slide 12.

15 The first of these deals with the
16 calculation of environmentally-assisted fatigue. In
17 preparing the TMI license renewal application we
18 completed all of the TLAA calculations for
19 environmentally-assisted fatigue to show we were less
20 than one. And we just talked about that.

21 The other thing is the important point
22 from an industry viewpoint is we used no simplified
23 analysis methods in the calculations. We used a full
24 set of stress-based information from the current
25 licensing basis and did the complete calculations.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 The second issue deals with the scoping
2 for station blackout recovery path. In our
3 application we included the high voltage circuit
4 breaks in the TMI switchyard within the scope of the
5 station blackout equipment in the application. And
6 this meets the NRC expectations in the interim staff
7 guidance on station blackout scoping.

8 Slide 13. This is a single line diagram
9 of the TMI switchyard. The green depicts all of the
10 equipment that's in scope of license renewal and
11 includes the high voltage circuit breakers. The
12 circuit breakers are the boxes. For example, in the
13 lower left hand corner GB1-02 is one of those circuit
14 breakers. So all of the ones in green are included in
15 scope for the recovery path.

16 Any questions on that?

17 All right. Well, I'd like to now
18 introduce Pat Bennett who is going to discuss the
19 topic of corrosion on the reactor building liner.

20 MR. BENNETT: Good afternoon. My name is
21 Pat Bennett and I'm the Mechanical Engineering Manager
22 at TMI.

23 My topic is the reactor building liner and
24 a corrosion issue that we first identified in the
25 1990s with our ASME Section 11 IWE program.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 We monitored this condition through the
2 IWE program and took corrective actions when we
3 discovered corrosion by cleaning and recoating the
4 effected liner areas. This presentation will describe
5 how we're addressing the corrosion issue.

6 Next slide, please.

7 The issue is past borated water leakage
8 and a degraded moisture barrier that resulted in
9 corrosion behind and just above the moisture barrier.

10 And we have fixed this.

11 The diagram to the left shows the bottom
12 floor of the reactor building where it nears the wall
13 liner. The area of interest is Detail A, which you
14 can see to the right. You can see the carbon steel
15 liner with the moisture barrier taking up the gap to
16 the concrete floor slab. The combination of areas of
17 degraded moisture barrier with episodes of borated
18 water leakage were the cause of liner coating
19 degradation and the resulting corrosion.

20 Next slide is a plan view of areas where
21 we found the corrosion. This is a plan view of the
22 lower level of the reactor building. We removed the
23 moisture barrier during last outage in 2007 360
24 degrees around the reactor building and inspected
25 above, at and below the moisture barrier. We found no

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 corrosion below the moisture barrier. The worst
2 corrosion was behind the moisture barrier where we
3 removed it.

4 Anywhere there was corrosion we measured
5 liner wall thickness and these are the areas that you
6 see on the diagram.

7 We evaluated the data to show that even
8 the thinnest area was it within design requirements?
9 And on the next slide I'll talk about specific actions
10 we took to prevent recurrence and what we're doing
11 about the corroded area.

12 Next slide, please.

13 MEMBER SIEBER: What was the moisture
14 barrier made out of?

15 MR. BENNETT: The old moisture barrier was
16 an RTDC liner

17 MEMBER SIEBER: Poured in?

18 MR. BENNETT: Laid in or poured in, yes.

19 MEMBER SIEBER: Below that's cork?

20 MR. BENNETT: The cork was a construction
21 aid when we had the liner laid and we poured the
22 concrete floor, that was there, yes.

23 MEMBER SIEBER: Water can go through that
24 pretty easily?

25 MR. BENNETT: Yes. It would run down if it

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 were poured.

2 MEMBER SIEBER: Do you think it's unusual
3 for the water to get through the moisture barrier
4 which is supposed to be impervious to water and not go
5 through the cork?

6 MR. BENNETT: No. What we found when we
7 did the inspection when we pulled it out was that the
8 moisture barrier hadn't fully separated, but had
9 provided a gap where it had come apart from the wall.
10 And the worst areas of corrosion was where we had
11 moisture laying in that gap. And so again --

12 MEMBER SIEBER: So the barrier wasn't
13 really broken all the way down?

14 MR. BENNETT: That's correct. And when we
15 pulled it all out, we removed it all, we inspected
16 down below that moisture barrier four to eight inches
17 down in the moisture barrier gap.

18 MEMBER SIEBER: Okay.

19 MR. BENNETT: And there was no corrosion
20 in that area.

21 MEMBER SIEBER: Okay. And so you recoated
22 the liner at that point?

23 MR. BENNETT: We recoated the liner.

24 MEMBER SIEBER: After you measured?

25 MR. BENNETT: That's correct. Recoated

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the liner and we also put in a brand new moisture
2 barrier with an improved moisture barrier.

3 MEMBER SIEBER: Okay. That's also a
4 poured?

5 MR. BENNETT: It's applied in. I don't
6 know if you could say it's poured.

7 MEMBER SIEBER: Like a troweling?

8 MR. BENNETT: Yes, it's troweled in, I
9 understand.

10 MEMBER SIEBER: Okay.

11 MR. BENNETT: Next slide. Thank you.

12 So in summary we identified corrosion in
13 the 1990s and later on and monitored and inspected the
14 liner in accordance with our IWE program.

15 The cause of the reactor building liner
16 corrosion was borated water leakage and a degraded
17 moisture barrier. And we fixed this.

18 Specifically the mitigation steps that we
19 took are:

20 We corrected leakage and established the
21 boric acid corrosion control program;

22 We inspected the entire moisture barrier
23 liner perimeter in 2007;

24 We measured the wall thickness of the
25 corroded liner areas in 2007 and ensured that the

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 existing liner meets design requirements;

2 We removed the old moisture barrier;
3 cleaned, recoated the liner and installed the new
4 improved moisture barrier in 2007, and;

5 We will inspect 100 percent of the
6 moisture barrier every refueling outage starting in
7 2009.

8 Our liner repair plan is to weld repair
9 any thinned area to establish all areas back to normal
10 thickness prior to the period of extended operations.

11 And that is scheduled in the fall of 2009 along with
12 our plant integrated leak rate test.

13 MEMBER SIEBER: And how many feet of
14 container or liner wall would that lineal feet would
15 that be?

16 MR. BENNETT: Yes. What we found was we
17 found 36 areas of corrosion when we went around the
18 wall. The area was approximately 13 percent of the
19 total perimeter --

20 MEMBER SIEBER: Which is?

21 MR. GALLAGHER: I think it's about 53
22 feet.

23 MR. BENNETT: About 53 feet of total area.

24 MEMBER SIEBER: Okay.

25 MR. GALLAGHER: And it's spread out,

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 spotted over areas.

2 MR. BENNETT: And again -- right.

3 MR. GALLAGHER: Not continuous.

4 MR. BENNETT: Right.

5 MEMBER SIEBER: Okay. So you have that
6 all marked?

7 MR. BENNETT: It's all marked.

8 MEMBER SIEBER: So go in and dig out and
9 do the weld repair?

10 MR. BENNETT: That's correct. And it's
11 scheduled for this upcoming outage.

12 MEMBER SIEBER: Okay. How are you going
13 to do the repair? Well, it's pretty close to the
14 surface of the concrete, I take it, within a half an
15 inch? That's so you can get welding rods and proper
16 equipment in there.

17 MR. BENNETT: That's correct. Well in
18 accordance with code.

19 MR. BARTON: Do steam generators fit
20 through the existing opening or do you have to do
21 anything with the opening?

22 MR. BENNETT: We're going to be cutting a
23 hole in the reactor building during the outage to get
24 the steam generators through.

25 MR. BARTON: So that'll be more welding on

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the liner?

2 MR. BENNETT: That's correct.

3 MR. BARTON: Okay.

4 MR. BENNETT: Yes, more opportunities.

5 MR. GALLAGHER: And that's why we want to
6 do that this outage because of the steam generator job
7 and we're going to do the ingrade and egrade test,
8 which is the post-installation test. And we'll take
9 care of all this at the same time.

10 MEMBER SIEBER: When you do the weld
11 repair of the liner, what kinds of action process will
12 you do to assure that the weld has been satisfactorily
13 laid in and that you've restored the thickness you
14 want, I guess integrity? You're going to do -- you'll
15 have to do a containment leak test, pressurized
16 containment leak test after cutting a hole in the
17 liner anyway?

18 MR. BENNETT: That's correct. And this
19 lines with IRLT very well. We've got to schedule
20 IRLT. We've got to do that for the steam generator
21 job, and that lines up with that.

22 MR. GALLAGHER: To answer Mr. Sieber's
23 question about --

24 MEMBER SIEBER: About how do you know--

25 MR. GALLAGHER: Do you want Gene to answer

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 that question?

2 MR. BENNETT: Yes. Gene Navratil is our
3 ISI engineer.

4 MR. NAVRATIL: Gene Navratil, Exelon.

5 Our plans are to perform the welding with
6 shielded metal arc welding. And after that we will
7 perform a magnetic particle examination and UT
8 examination to verify that we have the --

9 MEMBER SIEBER: So you have to prepare the
10 surface where the welding has been done?

11 MR. NAVRATIL: That's correct. We will
12 have to get rid of the rough edges.

13 MEMBER SIEBER: Well, yes, beads and
14 whatever.

15 MR. NAVRATIL: Correct. So, yes. The
16 process will be to remove the moisture barrier, any
17 paint, clean up the surface for welding, perform NDE,
18 do welding and then perform more NDE and verify
19 restored thickness.

20 MEMBER SIEBER: Now the NDE that you do
21 before the welding, what type will that be? You're
22 not going to have a prepared surface, so UT probably
23 is not applicable there. What are going to do for
24 that one?

25 MR. NAVRATIL: If I understand the

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 question correctly, after we do the cleaning of the
2 surface --

3 MEMBER SIEBER: And before the welding?

4 MR. NAVRATIL: Before the welding we would
5 perform a magnetic particle examination to assure
6 we've got no flaws.

7 MEMBER SIEBER: So you're looking for
8 cracks?

9 MR. NAVRATIL: That's correct.

10 MEMBER SIEBER: Thank you.

11 MEMBER ABDEL-KHALIK: How is the liner
12 attached to the concrete?

13 MR. BENNETT: Yes. There's metal
14 embedments that come out from the concrete and the
15 liner is attached to the concrete through that.

16 MEMBER SIEBER: Right.

17 MR. QUEEN: The liner was built first and
18 then the concrete was poured behind the liner.

19 MR. BENNETT: Was poured, right.

20 MR. QUEEN: And as it was, the embedments
21 were surrounded by the concrete and then encased in
22 the concrete.

23 MEMBER SIEBER: They used a movable form
24 to support containment?

25 MR. QUEEN: Yes, right. You build an

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 annular space essentially between the liner and the
2 concrete, poured the concrete in lifts between there.

3 MEMBER SIEBER: Built mostly with rebar?

4 MR. QUEEN: That's correct.

5 MEMBER SIEBER: Okay.

6 MEMBER ABDEL-KHALIK: Is that annular gap
7 between the liner and the concrete accessible for
8 inspection?

9 MR. QUEEN: No, there is no gap. There
10 was an annular gap built and then it was filled with
11 concrete. That's how the frame was --

12 MR. BENNETT: Well, if you go back to the
13 slide, Chris. That's pretty much it showed -- I guess
14 what you see you'll see the concrete. I'll point to
15 it here. That's pretty much --

16 MEMBER SIEBER: You got to take the bore
17 to inspect it.

18 MR. BENNETT: Right. That's correct.

19 MEMBER ABDEL-KHALIK: But there was no
20 buckling in that liner anywhere that would form a gap
21 between the liner and the concrete.

22 MR. BENNETT: That is correct.

23 MEMBER SIEBER: It is not subatmospheric?

24 MR. BENNETT: That's correct.

25 MEMBER SIEBER: Every time you do an LRT

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 you push the liner back out --

2 MR. BENNETT: That's correct.

3 MEMBER SIEBER: -- and there's no force to
4 pull it in.

5 MR. BENNETT: Any other questions?

6 Thank you.

7 MR. QUEEN: And next I'm going to talk
8 about our issue on medium voltage cables and our
9 underground vaults that contain those cables.

10 We have PMI of 8 total cable vaults that
11 are in scope. The cables in those vaults supply power
12 to our screen house, normally are energized to provide
13 power to our river water pumps as well as our circ
14 water pumphouse. So there were two sets of cables
15 through the 8 vaults.

16 Although we've had no failures of our
17 medium voltage cables we do inspect those cable vaults
18 periodically and have found some of them full of water
19 and have had to drain them.

20 The next couple of slides I'm going to
21 describe what the vaults look like, how they're
22 constructed, how we believe the water got in there and
23 what our plans are to prevent water from getting in
24 there in the future and to keep the cables dry going
25 forward.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Go to the next slide, Chris.

2 MEMBER SIEBER: Let me back up to the
3 liner just a moment.

4 MR. QUEEN: Sure.

5 MEMBER SIEBER: You had boric acid on the
6 containment floor and other areas where boric acid,
7 I'm sure -- I mean, it had to start from someplace.
8 What other elements of the structure -- have been
9 effected by boric acid leakage that on its way from
10 wherever it leaked from down to the containment floor
11 into the liner? Have you done an inspection to try to
12 figure out where the problems were and what's been
13 affected by it?

14 MR. BENNETT: Yes. This is Pat Bennett
15 responding.

16 Yes, we have. The boric acid control
17 program is in place to do just that. So anytime we
18 see borated water in the building, even a drop now, we
19 identify where it came from. We look for the path
20 where it came from. And then we address it in the
21 Corrective Action Program.

22 MEMBER SIEBER: Yes. My question is though
23 from the boron that you found that caused the
24 corrosion of the liner where did it come from?

25 MR. BENNETT: Oh. Okay. Yes. To answer

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 your question it came majorly from one episode of
2 valve leakage that has been repaired and also from a
3 seal plate leakage in the fuel transfer area that has
4 also been repaired and welded. And so it does--
5 there's no opportunity for leakage.

6 MEMBER SIEBER: What valve was it that
7 leaked, do you know?

8 MR. BENNETT: It was a chem-add valve, I
9 believe. It is a --

10 MEMBER SIEBER: Small bore?

11 MR. BENNETT: It was a small valve.

12 MEMBER SIEBER: Okay.

13 MR. QUEEN: Sampling. Chem sampling valve
14 that got cycled opened and closed each day to take
15 chem samples.

16 MR. BENNETT: Right.

17 MR. QUEEN: Small valve, one inch.

18 MEMBER SIEBER: Standard packing?

19 MR. QUEEN: Standard packing, yes.

20 MEMBER SIEBER: Did the packing leak?

21 MR. QUEEN: It was a packing leak and the
22 valve actually is located a floor above the location
23 where the worst corrosion damage was. And it did run
24 down along the floor, down the wall to the location.
25 And the whole area was inspected and cleaned.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER SIEBER: Now if the plant is
2 operating and you develop a leak like that one again,
3 how will you know that it's leaking or will it leak
4 until the end of the cycle and somebody goes in and
5 there's all this boric acid all over the place?

6 MR. BENNETT: Well, certain leaks --
7 well, you know well we understand if we have leakage
8 with leak rate --

9 MEMBER SIEBER: They can be pretty small.

10 MR. BENNETT: Right. Exactly.

11 MEMBER SIEBER: And once it's pretty
12 small, it's hard to calculate.

13 MR. BENNETT: We have periodic inspections
14 inside the reactor building and we've identified that.

15 MR. QUEEN: Right. We go in the reactor
16 building monthly. And these areas are all accessible.

17 MEMBER SIEBER: In containment?

18 MR. QUEEN: In containment. These areas
19 are accessible. You can see the liner.

20 MEMBER SIEBER: Are they on the outside of
21 the shield wall?

22 MR. QUEEN: It is.

23 MEMBER SIEBER: Okay.

24 MR. QUEEN: And also our leak rate
25 calculations would see the size of leak we had and

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 would flag us to go do additional inspections.

2 MEMBER SIEBER: Yes.

3 MR. BENNETT: One additional thing that
4 we've done with the installation of the new moisture
5 barrier is the old moisture barrier is laid flat on
6 the floor.

7 MEMBER SIEBER: Flat?

8 MR. BENNETT: The new one is tapered.
9 Starts up on the wall and curves down onto the floor.
10 So it's --

11 MEMBER SIEBER: The floor is concrete with
12 protective coating on top?

13 MR. BENNETT: That is correct.

14 MEMBER SIEBER: Right.

15 MR. BENNETT: That's correct.

16 MEMBER SIEBER: Okay. And what kinds of
17 supports are on that -- that floor is flat, right?

18 MR. BENNETT: That's correct. It does tend
19 to go towards drains, floor drains.

20 MEMBER SIEBER: Right.

21 MR. BENNETT: Slip to floor drains.

22 MEMBER SIEBER: So if you have leak, what
23 kind of supports would the leak contact and do you
24 have a program to look at those supports?

25 MR. BENNETT: We have a program do

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 inspections. So those inspections, those visual
2 inspections would include anything in the path;
3 supports, cable trays, anything.

4 MEMBER SIEBER: And how often do you do
5 that? Every refueling?

6 MR. BENNETT: The inspections, what did we
7 say, was --

8 MR. QUEEN: Inspections are performed each
9 refueling outage for the entire containment building.

10 Our boric acid corrosion control program requires
11 that anytime you find a leak of any size that you
12 inspect all the targets of the leak and you seek out
13 and find those targets and inspect them and determine
14 where the impact is.

15 So during our monthly inspections and
16 walk-throughs of the reactor building if we were to
17 find a leak, and these leaks would all be observable
18 because they're outside the D ring or the shielded
19 area, we would then -- it would kick the boric acid
20 corrosion program into gear and we would then be
21 required to look for targets and then clean the areas
22 to ensure corrosion is stopped.

23 MEMBER SIEBER: Thank you

24 MR. QUEEN: Okay. This is Steve Queen,
25 Operators Director.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 We had started discussing the medium
2 voltage cable issue. I completed the first slide
3 where we talked about the number of cable vaults we
4 have. We have eight vaults. And we had found that,
5 although we have had no cable failures, we have found
6 cases where we've had vaults full of water. And in
7 the next two slides I'm going to describe how the
8 vaults look and what we're doing to prevent water in
9 the future.

10 CHAIR STETKAR: Before we flip to the next
11 slide, Steve, the first bullet on this one says that
12 it's repeated occurrence of rainwater accumulation.
13 You're confident that it's rainwater, it's not bound
14 water, not leakage from other sources?

15 MR. QUEEN: Well we're reasonably
16 confident that it's rainwater. If there's a component
17 of groundwater to it, we have not seen that. But our
18 inspections going forward should identify that. I'll
19 describe to you why that is on the next slide, if you
20 can flip to the next slide.

21 CHAIR STETKAR: But you feel it's episodic
22 driven rather than --

23 MR. QUEEN: Yes. This picture here shows
24 a cross section of our vaults, of the typical cable
25 vault. And I'll describe how the water gets in there

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 and I think that'll answer your question.

2 These vaults are -- the top of the vault
3 is flush with the ground and the vaults are eight to
4 15 feet deep depending on the type of vault and the
5 size of the vault.

6 With respect to groundwater, the water
7 table is 5 to 15 feet below the bottom of the vault.
8 So the bottom of the vault would be where you see the
9 French drain area at the bottom in this picture; 5 to
10 15 feet below that is the groundwater level. So there
11 would typically be no groundwater to intrude in that
12 area. But what's happened over the years is in the
13 manhole area at the top we've had -- the grading has
14 changed over the years. People really weren't -- we
15 weren't thinking about well where does this water go,
16 what's the impact of that when the grading is changed
17 as well as the gasketing material in the manhole had
18 not been maintained. So that resulted in water coming
19 in through the manhole.

20 That in combination with on the bottom of
21 the vault area you'll notice a two inch pipe system
22 which actually drains to a French drain. Those drains
23 we found when we found these vaults full of water, we
24 started an inspection program, put together a
25 troubleshooting program. Went to inspect the vaults

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 and found that these French drains were full of silt
2 and debris. Had not been inspected, there was no
3 inspection program for the drains.

4 So as a result of that we have created an
5 inspection program and a repair plan to go fix the
6 drains so that the vaults will drain. And then
7 secondly, to fix the manhole covers and the grading so
8 that the water doesn't intrude into the vault.

9 MEMBER RYAN: Steve, one little question
10 that will clarify for me. Where is the bottom of the
11 vault relative to the water elevation of the river?

12 MR. QUEEN: The river typically is around
13 377, or 277 elevation. The bottom of the vault would
14 be around 295, on average.

15 MEMBER RYAN: Oh, so you have a pretty
16 good gradient from the bottom of the vault --

17 MR. QUEEN: Yes.

18 MEMBER RYAN: -- to the river?

19 MR. QUEEN: That's correct. The bottom of
20 the vault is up here and the river is down here.

21 MEMBER RYAN: Okay.

22 MR. GALLAGHER: The river water level is
23 277, as Steve said.

24 MR. QUEEN: 277.

25 MR. GALLAGHER: And then the water table

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 level is typically 281.

2 MEMBER RYAN: Okay.

3 MR. GALLAGHER: And then like he said, 5
4 to 15 feet above that are the bottom of the vaults.

5 MEMBER RYAN: And I guess those are
6 probably mean water level and mean table?

7 MR. QUEEN: Right. The island is -- under
8 worst case flood conditions that we've had in many,
9 many years the water level has gotten up to 299/300
10 elevation. That's really, really high. That's very
11 atypical.

12 MEMBER RYAN: I mean, that would be an
13 attention getting event --

14 MR. QUEEN: That would be.

15 MEMBER RYAN: -- for lots of reasons other
16 than the manholes. But that's pretty convincing
17 evidence that you really are dealing with the rain
18 coming down rather than anything else coming in or up?

19 MR. QUEEN: Right. And the water table's
20 well understood at TMI. We have -- because of the
21 focus on tritium now in the industry we have a
22 tremendous number of sampling wells drilled. And we
23 understand the water table. We also understand the
24 flow of groundwater at the island very well.

25 So probably the biggest indicator that

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 it's not significant groundwater intrusion is the fact
2 that simply the water table is well below the bottom
3 of the vault.

4 MEMBER RYAN: One thing I might add for
5 the rest of the Committee, the Subcommittee's benefit
6 is I did visit TMI was with the ACNW. And we did have
7 a presentation from the geohydrologic consultant you
8 had doing the groundwater monitoring for tritium. And
9 I'd concur, you've got a very good team there and a
10 good geohydrologic model of your site.

11 MR. BENNETT: Is 299 Agnes?

12 MR. QUEEN: I don't know what Agnes went
13 to.

14 MR. GALLAGHER: Steve wasn't born then, so
15 --

16 MR. BENNETT: Well, I'm really showing my
17 age, right. Agnes was like the 100 year flood.

18 MR. QUEEN: I think Agnes actually came
19 onto the island.

20 MR. BENNETT: Yes, but the dyke wasn't
21 complete at that time, I think.

22 MR. QUEEN: And the ground level on the
23 island is 305.

24 MR. GALLAGHER: Yes. Agnes was before
25 plant operations, like '72/'73.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS
1323 RHODE ISLAND AVE., N.W.
WASHINGTON, D.C. 20005-3701

1 MR. BENNETT: Yes.

2 MR. QUEEN: So, any other questions on
3 vault construction?

4 Okay. So two issues: The grading and the
5 manholes making them leak-tight. And then the second
6 issue is to make sure that the drainage system
7 functions. And that's the plan going forward.

8 On the next slide this shows in bullet
9 form essentially what I just talked through.

10 We will, our plan now starts this spring
11 and completes in the summer. And that will be to
12 install new lid gaskets, revise and improve the
13 grading around the manways, and then most importantly
14 get down in the vaults, clean out the French drain
15 systems, test the French drain systems to ensure they
16 work, we'll actually pour water into them to ensure
17 they drain. And then our inspection frequency after
18 that will be six month inspection frequency. We will
19 increase or vary that frequency depending on what we
20 find. If we find water in the vaults after we start
21 these inspections and have completed the repairs, our
22 troubleshooting plan would have us then do additional
23 troubleshooting to determine the cause and repair the
24 cause.

25 Our goal and our commitment is no

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 submerged cables.

2 MEMBER SIEBER: Okay. Now I'm sure you
3 received Generic Letter 2007-01. The title of it is
4 "Inaccessible or Underground Power Cable Failures That
5 Disabled Accident Mitigation Systems or Cause Plant
6 Transients." It's dated February 7th.

7 MR. QUEEN: Right.

8 MEMBER SIEBER: Okay. This is a generic
9 issue with most plants.

10 MR. QUEEN: Right.

11 MEMBER SIEBER: And so it's not really a
12 license renewal issue, it's an immediate issue. And I
13 presume that you have responded to the Generic Letter?

14 MR. QUEEN: Yes, we have. We have --

15 MEMBER SIEBER: Give me an outline of your
16 response.

17 MR. QUEEN: Would you like to do that,
18 Deb?

19 MS. SPAMER: Deb Spamer, Exelon Nuclear.

20 The Exelon response to the Generic Letter
21 identified a cable monitoring program that has a two
22 phased approach. The first approach is to screen for
23 failures. And then based on the types of failures you
24 found, if you found any, to incorporate a testing
25 program of the cables.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 At TMI since there's been no failures,
2 we're still in the screening phase of that
3 implementation program. But we are doing megger
4 testing of the cables.

5 MEMBER SIEBER: So right now you don't
6 have a commitment to do cable testing?

7 MS. SPAMER: That's correct.

8 MR. GALLAGHER: Part of license renewal,
9 Mr. Sieber, we're adding that to do commit to do cable
10 testing --

11 MS. SPAMER: That's correct.

12 MR. GALLAGHER: -- and every ten years.

13 MEMBER SIEBER: Could the staff address
14 that when they return?

15 CHAIR STETKAR: Just out of curiosity, do
16 you have a regular inspection frequency for these
17 manholes and vaults now? And I'm assuming you do, and
18 what is it?

19 MR. QUEEN: Yes, we do. We inspect them
20 every six months.

21 CHAIR STETKAR: Six months? Okay.

22 MR. QUEEN: And when we do, as I said, we
23 found them full of water at times and that's what
24 kicked off our troubleshooting to go find the issues
25 we did and resolve them.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS
1323 RHODE ISLAND AVE., N.W.
WASHINGTON, D.C. 20005-3701

1 CHAIR STETKAR: But it's regular
2 frequency, it isn't --

3 MR. QUEEN: It's a regular frequency
4 inspection. And when we look, we'll pump the vaults
5 down. And when we pumped them down, the water level
6 came back; not immediately but over time it would come
7 back. When you'd inspect the next time, the water was
8 back. It didn't fill itself back up, but it came back
9 over time.

10 CHAIR STETKAR: I mean, you don't have a
11 program that says after, you know, two inches of
12 rainfall you immediately go out and look at it.

13 MR. QUEEN: No, we do not. We do not.

14 MEMBER BONACA: Did you find that six
15 months is adequate?

16 MR. QUEEN: No, not with the drain system
17 fouled and the manways leaking it is not adequate. So
18 that's why this spring we started the program to fix
19 the drainage system as well as repair the manway so
20 that the water does not get into the vault.

21 If we do inspect these vaults and find
22 water in the future after we've taken these mitigating
23 steps, then we will be taking additional mitigating
24 steps to prevent the cables from being submerged. So
25 it's not just here's what we're going to do and here's

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the inspections we're doing. It's we will stop this
2 from happening.

3 MEMBER BROWN: Your viewgraph states that
4 you will adjust the frequency based on inspection
5 results. And that's a little bit -- is it will it
6 just get more frequent or would you move it from six
7 months to a year or something like that? You just
8 answered counter to that, you said no it's six months,
9 fixed frequency come hell or high water.

10 MR. QUEEN: Yes, we will adjust the
11 frequency based on what we find. If we find that the
12 vaults are continuing to fill with water, we'll
13 increase the frequency as well as change our
14 mitigation strategies. If we find the vaults remain
15 dry after we've mitigated them, then we would lengthen
16 the frequency.

17 MEMBER BROWN: Okay. So you'll go both
18 ways?

19 MR. QUEEN: Right, we'll go both ways.

20 MEMBER BROWN: I think that's a little bit
21 counter to it's always six months. If you've got a
22 baseline of six months, then you'll adjust based on
23 results.

24 MR. QUEEN: That's correct.

25 MEMBER BROWN: Either higher or lower

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 frequency. Okay.

2 MR. QUEEN: That's correct.

3 MEMBER BROWN: And you're already in that
4 program? You're not waiting the way I read part of
5 the -- I think it was the inspection reports? It
6 implied that it would be executed or implemented prior
7 to entering the period for extended operation. But in
8 fact, you're doing this now, is that correct?

9 MR. QUEEN: Yes. We already have been
10 doing an inspection program and we're starting now in
11 the spring with the mitigation program.

12 MEMBER BROWN: Okay.

13 MR. QUEEN: So the inspection program
14 continues, it just becomes a commitment now and then
15 the remediation becomes a commitment with respect to
16 keeping the cables substantially dry.

17 MEMBER BROWN: Okay. I see.

18 MR. BARTON: In their Appendix A in
19 commitments for license renewal, I noticed that a lot
20 of the programs are ongoing now and the dates that
21 they've provided for starting them are before license
22 renewal date. And that's different than a lot of
23 plants that say they're going to implement them on the
24 date of license renewal. This plant's already
25 implemented a lot of those programs.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 CHAIR STETKAR: Yes. Well we've heard
2 that in some of the other meetings it would be prior
3 to going into a period of extended operation. But for
4 the next five years it'll be where they are, so that's
5 why I asked the question.

6 MR. QUEEN: Yes.

7 And the final bullet on here was the
8 testing bullet we referred to, which is we will
9 perform cable testing in accordance with the industry
10 state-of-the-art methods, and then we'll follow those
11 methods. And as they change over the years, we will
12 revise our cable testing program to stay up with the
13 industry.

14 CHAIR STETKAR: And I think I heard now
15 that the type of testing that you do on the cables is
16 just megger testing, is that correct?

17 MR. QUEEN: Megger testing, that's
18 correct.

19 Any other questions on medium voltage
20 cables?

21 MR. GALLAGHER: Okay. With that, we'll
22 get into the next topic with Fred Polaski.

23 MR. POLASKI: Thanks, Mike. Fred Polaski.
24 We will talk about a topic of Boral and spent fuel
25 storage racks.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 What I'd like to do is describe the
2 phenomena that's of concern and interest right now.
3 Discuss the TMI experience and then provide our
4 analysis of the issue.

5 Slide 23.

6 The issue involves the formation of
7 blisters on the Boral neutron absorber material and
8 the potential for the blister to affect the
9 assumptions used in the criticality analysis for the
10 fuel storage racks.

11 The TMI fuel pool -- this is slide 24 --
12 there two types of high density fuel storage racks.
13 The Region 1 racks have a water gap between the cells.
14 And this water gap thermalizes neutrons and increases
15 the effectiveness of the Boral absorber panels.
16 Region 1 racks are used for new fuel prior to the fuel
17 being inserted into the core and for temporary storage
18 of once burned fuel when it's removed during outage,
19 and for that fuel that has not yet met the burnup
20 requirements to place it in the Region 2 racks.

21 The Region 2 racks do not have a water gap
22 and they're not affected by this issue. But they're
23 only used for discharged fuel that meets particular
24 specific burnup requirements. Typically if its been
25 in the reactor for two or three cycles.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 There's about 1500 fuel storage locations
2 at TMI. About 13 percent of those are Region 1 type
3 racks. And currently, because we're between outages,
4 those racks are empty.

5 Slide 25 shows a closer picture of the
6 Region 1 racks. The way they are built, there are two
7 plates of Boral absorber material between each fuel
8 cell. The other way to describe it is there's a plate
9 of the Boral on all four sides of each cell. And the
10 plates are separated by a water gap that's sometimes
11 called a flux trap.

12 Each plate of the Boral material consists
13 of a core of aluminum and boron carbide powder with a
14 cell of aluminum cladding on each side.

15 These plates only .081 inches thick. So
16 they're very thin plates on each side.

17 On 26, these Boral plates are placed in a
18 pocket of stainless steel that forms the cell box wall
19 and then there's a sheathing area on the outside of it
20 for physical protection. And the sheathing area is
21 water filled because its vented by design.

22 I'll just point out, this drawing is not
23 to scale. This is just a picture to show you what the
24 issue is. And it's not really based on any specific
25 data from particular blisters, but just to demonstrate

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the issue.

2 The blisters are created if the aluminum
3 corrodes, and corroding the aluminum results in
4 aluminum oxide and hydrogen gas which would be trapped
5 inside the cladding.

6 If the blister is such that it doesn't
7 deform the stainless steel pocket or the sheathing,
8 then the water gap between the two cells is unchanged
9 and there's no affect on the neutron thermalization.

10 The water chemistry program for the fuel
11 pool at TMI maintains boron concentration of the fuel
12 pool above 2500 ppm. And at this concentration there
13 will not be any corrosion or general corrosion of the
14 aluminum. Any corrosion that would occur would be
15 localized and it would occur in locations of surface
16 imperfections where there were any contaminates from
17 the manufacturing process. So it would be very
18 localized and not general corrosion.

19 MR. BARTON: Well, these racks -- I'm
20 sorry.

21 MEMBER SIEBER: Let me ask a question
22 about that. You have boron carbide encapsulated
23 between plates.

24 MR. POLASKI: Yes, sir.

25 MEMBER SIEBER: And the creation of the

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 blister is the plate is leaking somehow and you're
2 getting water behind that. Does the boron carbide ever
3 settle down inside the plate so that you end up with a
4 gap where there is no --

5 MR. POLASKI: The way they are formed is
6 that they are formed as one entity. So it's one
7 compressed sandwich, if you will.

8 MEMBER SIEBER: Right.

9 MR. POLASKI: In a big sheet and then
10 they're cut. So around the edges the boron carbide is
11 exposed to water. And that's how the water can work
12 its way through the carbide to get in between the two
13 aluminum plates.

14 MEMBER SIEBER: You're not aware of any
15 phenomenon where the boron carbide would be moved or
16 displaced, or anything like that?

17 MR. POLASKI: No. No.

18 MEMBER SIEBER: Okay.

19 MR. BARTON: Are the racks you're showing
20 here the same as in the Unit 2 fuel pool, or is this
21 just Unit 1 racks?

22 MR. POLASKI: This is just Unit 1 racks.

23 MR. BARTON: But what are the racks --
24 you're going to use Unit 2 fuel racks sometime, right,
25 for storage or whatever? No? Never going to use it?

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. QUEEN: No. We've reracked our pool
2 in Unit 1 so that --

3 MR. BARTON: Okay. So you don't have to
4 use the racks in Unit 2? There aren't any racks in
5 Unit 2 anymore, are there?

6 MR. QUEEN: No, Unit 2 --

7 MR. BARTON: No, that's right. Forget it.
8 Forget it.

9 MR. POLASKI: Any other questions on that?
10 Okay.

11 MR. BARTON: Forgot about that.

12 MR. POLASKI: All right. On slide 27 this
13 depicts what could occur if the blisters are large
14 enough and deforms a stainless steel pocket. The
15 water gap dimension would then be reduced and this
16 would affect the thermalization of neutrons.

17 Like I said before, the blister is caused
18 by water intrusion into the boral plate. And what we
19 expect is that the blister would remain full of water
20 because the water is what causes the corrosion. So if
21 the blister is full of water, then there's really no
22 reduction in the amount of water there to attenuate
23 the neutrons. So the concern would only be if the
24 blister would be full of gas.

25 So when we do any analysis looking at this

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 we assume that the blister is dry, no water in it, for
2 conservative assumptions in looking at the impact of
3 this.

4 If we go on to slide 28, the experience at
5 TMI. TMI installed high density Boral fuel racks in
6 1992. The surveillance coupons were installed at that
7 time, and they are representative of Boral in the
8 racks.

9 During the first five cycles the coupons
10 were removed during every outage so that they were
11 located and surrounded by newly offloaded fuel. And
12 this was done to provide accelerated exposure to
13 neutrons.

14 The analysis of the Boral coupons were
15 performed in 1995, '97, '99, 2001 and 2008. No
16 blistering was found during '95, '99 and '01. The
17 largest blister that was found was in 2008. There was
18 one blister found that was one inch in diameter and
19 measured .058 inches of thickness or height. And it
20 was determined to be water filled when it was
21 inspected.

22 The other thing is that when they did
23 these examinations when they removed the coupon from
24 the coupon rack, the Boral coupons are enclosed in a
25 stainless steel sheath similar to what's on the racks.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 And those stainless steel sheaths were examined as
2 part of the work and no issues were found with those.

3 So there's no detected expansion of the stainless
4 steel sheathing.

5 The coupons were tested and they showed no
6 loss of boron in the Boral, no reduction in neutron
7 absorption capacity in any of the coupons. And they
8 did that using neutron attenuation tests.

9 And the results of this is consistent with
10 findings that EPRI has found in the study they've done
11 of this issue at several locations where there have
12 been blistering in these Boral racks.

13 MEMBER BROWN: Why is the stainless steel
14 prototypical of the actual aluminum cladded?

15 MR. POLASKI: Well, the stainless steel is
16 typical of the configuration in the rack where the
17 Boral coupon, which consists of the Boral and the two
18 aluminum plates is in between the stainless steel
19 sheathing and the --

20 MEMBER BROWN: All right. All right.

21 MR. POLASKI: So the coupon is the
22 configuration -- the only difference between really
23 the coupon is it's only like 7½ inches long where the
24 Boral in the racks is 136 inches long. But they're
25 made out of the same material, same process, just the

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 coupons are just smaller.

2 MEMBER BROWN: Got it.

3 MR. POLASKI: Okay. On slide 29, just to
4 summarize where we are for TMI.

5 We have observed blisters. There have
6 only been a very small number. You know, the largest
7 one was one inch in diameter.

8 The effect of this blistering is bounded
9 by uncertainties in the analysis. They're performed
10 K_{eff} considering -- or the existing margins that are
11 required for that.

12 MEMBER ABDEL-KHALIK: How are those
13 criticality calculations performed?

14 MR. POLASKI: I'm going to ask Mr. Stu
15 Getz to answer that question.

16 MR. GETZ: Stu Getz, Exelon.

17 The criticality evaluation, we did an
18 evaluation based on the original evaluation that was
19 done for the licensing report for when these racks
20 were first installed. And what we determined from
21 that is we used a manufacturing tolerance based on the
22 cell. And that created an effect, simulated the fact
23 that we would have a full sized blister, full width
24 and full length over the entire size of the Boral
25 panels on each Boral panel in the rack. And it

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 simulates it being non-water filled because it
2 displaces the water in the flux trap.

3 And that effect when added as a penalty to
4 the neutron multiplication factor that was obtained
5 for the rack design gave us an increase because of the
6 reduction in flux trap.

7 MEMBER ABDEL-KHALIK: So this didn't
8 involve when you're doing a criticality calculation?

9 MR. GETZ: No, it did not.

10 MEMBER ABDEL-KHALIK: You just went back
11 to--

12 MR. GETZ: It did not. This was an
13 evaluation based on this grossly bounding full sized
14 blister, 100 percent of every Boral panel. And we
15 ended up with a K_{eff} effect that was well within the
16 existing margin.

17 MR. POLASKI: And the last thing is that
18 at TMI our Boral coupon surveillance program is going
19 to continue throughout the period of extended
20 operation.

21 And slide 30 to discuss aging management
22 program with respect to the fuel storage racks and the
23 Boral.

24 The first point, TMI water chemistry
25 program manages loss of material due to general

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 corrosion of the aluminum cladding of the Boral.

2 And second, we will continue our Boral
3 coupon surveillance program to continue throughout the
4 period of extended operations. And we will perform
5 evaluations to demonstrate that any effect on neutron
6 multiplication factor is due to a postulated reduction
7 water gap is within our design requirements. So we're
8 going to continue the program we've been doing up
9 until now. And any issues we find will be evaluated
10 versus the design of the racks.

11 Any questions on the Boral and fuel racks?

12 CHAIR STETKAR: Yes. The discussion you've
13 been having it relates strictly to the Region 1 rack
14 configuration where indeed you do have the--

15 MEMBER SIEBER: The flux trap.

16 MR. POLASKI: Yes. The flux trap.

17 CHAIR STETKAR: What additional concerns
18 are there? I'm assuming -- is the design of the Boral
19 sheaths and the plates different in Region 2 or is
20 exactly the same? And if it's the same, what other
21 concerns are there in the Region 2 where --

22 MR. POLASKI: I'm going to let Stu--

23 CHAIR STETKAR: -- make it more mechanical
24 interference, for example?

25 MR. POLASKI: Yes.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. GETZ: The design of the rack and the
2 sheathing is slightly different in Region 2.

3 In Region 1, as you can see, if there were
4 a blister that were to deform the sheathing, it
5 wouldn't have a mechanical interference effect on the
6 fuel that would be inserted into the box.

7 In Region 2, that's a deformation of the
8 sheathing could have an affect on the amount of
9 clearance that's available. But at the TMI Region 2
10 racks the sheathing is a thicker of material than the
11 sheathing used on the Region 1 racks and it's more
12 resistant to any kind of deformation that might
13 results from a blister.

14 The interior dimension of the box is 9 by
15 9 and the fuel assemblies are 8½ by 8½. So there's
16 currently about a quarter of an inch clearance all
17 around the -- it's an inserted bundle.

18 MEMBER ABDEL-KHALIK: How thick is the
19 water gap in --

20 MR. GETZ: 1.697 inches is the analyzed
21 water gap dimension.

22 CHAIR STETKAR: Can you be more precise
23 than that?

24 MR. GETZ: Approximately.

25 MEMBER ABDEL-KHALIK: If the gap was a lot

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 thinner than that, then I'm not sure the case assuming
2 of no water would be the most conservative. If the
3 thickness of this flux trap is a lot thinner than what
4 you indicate --

5 MR. GETZ: You mean if it were to be
6 reduced or, I'm not following. I'm sorry.

7 MEMBER ABDEL-KHALIK: I mean if the design
8 were such that this gap is a lot thinner than that--

9 MR. GETZ: Oh, I see.

10 MEMBER ABDEL-KHALIK: -- then there are
11 two competing effects. But in this case its thick
12 enough--

13 MR. GETZ: Yes.

14 MEMBER ABDEL-KHALIK: -- that it is
15 primarily a thermalization issue?

16 MR. GETZ: That's correct.

17 MR. POLASKI: The other aspect of this,
18 too, that I think sort of puts it in perspective is
19 that all of this is done assuming no borated water.
20 Stu, am I correct? That's correct?

21 MR. GETZ: In these analyses.

22 MR. POLASKI: And with the borated -- the
23 level of boron that we maintain in the fuel pool that
24 the K_{eff} is reduced to .75, or some number like that,
25 significantly less than .5. So we gain a whole lot of

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 margin.

2 You know, you don't credit the boron in
3 the water for the analysis, but it is there and really
4 almost makes this a mute point. But irrespective of
5 that, we will continue the coupon surveillance program
6 and then keep examining them, make sure they're
7 working right.

8 Any other questions on that? Then that
9 completes the --

10 MEMBER BROWN: I had a question.

11 CHAIR STETKAR: Are you done?

12 MR. GALLAGHER: Yes, Mr. Chairman, that
13 concludes our prepared presentation, but we're open to
14 any questions.

15 CHAIR STETKAR: And we'll probably have
16 some.

17 Charlie?

18 MEMBER BROWN: I will go ahead and go
19 ahead and go first.

20 Now under the fire protection area you all
21 had an exception to the fire protection. I guess the
22 GALL report says you're supposed to inspect those
23 every six months and you all do a Halon in 18 and CO₂
24 in 24. So after some roundabouts and after reading
25 six pages of discussion on the subject, see -- so I

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 want you to tell me whether I understand it and really
2 did, is that the exception was accepted, if you
3 convolute the language, although it appears that you
4 now do inspections from what I could read in this
5 thing, you're now doing the exception -- you're doing
6 on the Halon system every six months, every three to
7 six months. And you're now checking the storage tank
8 level pressure for the carbon dioxide weekly.

9 So why -- since you're inspecting the
10 Halon system every six months, why is that an
11 exception still? I guess I didn't understand if you're
12 really complying with the GALL periodicity.

13 MR. POLASKI: What we've committed to in
14 the application was inspections every 18 months
15 because the physical conditions of the equipment
16 indicates that there's no reason to have to commit to
17 every six months.

18 MEMBER BROWN: Okay. Well then if you go
19 back and look at your last three tests, 2006 -- 18
20 months apart, 12/06, 6/05 and 2/04 you had three
21 failures found or three problems found, whatever those
22 were. One was a damaged grill I think or something
23 like that. And then there was a fan motor failure and
24 a fouled limit switch, which would have indicated the
25 wrong position. It would not have indicated a valve, I

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 guess a fire water valve open. When it was really
2 open, it would have still indicated closed.

3 So I guess my question is when you find
4 multiple problems over that -- and that was just a
5 three year period, that sounds like something's not
6 working right or you're finding things every time you
7 go look, which would imply to me that you need to look
8 more frequently.

9 MR. QUEEN: Our approach --

10 MR. GALLAGHER: Let's let Stu answer that
11 question. Stu?

12 MR. GETZ: Stu Getz of Exelon.

13 On those specific examples you're citing
14 those were non-age related examples. One of them, I
15 believe, was a mispositioned switch. One of them was
16 a damaged grill.

17 MEMBER BROWN: Yes, the misadjusted
18 switch. Yes.

19 MR. GETZ: Right. And I think your point
20 on the other one is if we're doing examinations of the
21 Halon supply every six months and that kind of thing,
22 why are we taking exception. That exception was taken
23 due to the GALL requirement of a full functional test
24 every six months, which we do at 18 month intervals, I
25 think, on the GALL.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER BROWN: Then I guess I didn't
2 understand that particular point.

3 I understand these are not age related.

4 MR. GETZ: Okay.

5 MEMBER BROWN: But they're still problems
6 that potentially compromise the operation of at least
7 part of the fire protection system.

8 MR. GALLAGHER: Right. And those --

9 MEMBER BROWN: And you only do a
10 functional test every 18 months, so they would be
11 there and you wouldn't see them.

12 MR. GALLAGHER: Yes. There's other
13 inspections that are going to be done; operator
14 rounds, things like that where you identify
15 deficiencies and capture them in the Corrective Action
16 system. So, you know, that's how many things get
17 identified in the plant and are constantly looked at.

18 What we were talking about specifically,
19 like Stu was talking about with the exception, why was
20 it an exception and why based on our own operating
21 experience that the 18 month interval was sufficient
22 versus the six month interval. And that's not to say,
23 Mr. Brown, that you never find any problems in our
24 other inspection programs, and that's why we continue
25 to do those and capture them in the Corrective Action

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 system.

2 MEMBER BROWN: Well, it was implied that
3 you found these during the functional tests in each of
4 these things; that's when it was found during the 18
5 interval functional tests. Not by other inspections,
6 by people walking around and seeing a fan that's not
7 supposed to operate and not operating or a valve
8 that's not supposed to have been moved, not moved
9 because it hasn't been moved and not indicating
10 anything. So that's a little different than -- so
11 that's why I asked the question because they weren't
12 due to anything else. They were literally due to
13 functional test performed, those were found as
14 problems during the functional tests.

15 And from my background if I found problems
16 during functional tests every time I did the test,
17 then I kind of figured that I had to do it more
18 frequently to make sure that I didn't have that
19 failure already occur during the interval and then not
20 know it.

21 MR. QUEEN: Our preventive maintenance
22 program actually drives that. If we find enough
23 repeat failures, we then will do evaluations on them
24 and then change surveillance frequencies based on that
25 to prevent reoccurrence so that the existing program

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 for preventive maintenance and testing drives that
2 type of reinspection --

3 MEMBER BROWN: Well, does it actually
4 operate the value? Or, I mean, you say
5 "surveillance." I mean, surveillance to me means
6 eyeballs looking at something, not necessarily turning
7 a switch or initiating some action and having
8 something start.

9 MR. QUEEN: Yes. The surveillance would
10 identify the issues as well as operator rounds;
11 multiple ways of identifying. And then the Corrective
12 Action program identifies them and you bin them and
13 say here's the failures I had, here's the number of
14 components. This component had X number failures.
15 And then our cause evaluations would look at that and
16 say do we need to change the component, do we need to
17 increase the frequency of inspection or change the
18 maintenance practice.

19 MEMBER BROWN: So you're going to fog that
20 one right by me. I guess I would probably defer to a
21 couple of people on this Committee that are far more
22 experienced in the commercial world than I am. I come
23 out of a different -- the Naval nuclear world and
24 that's a totally different perspective. I would still
25 probably disagree with what you're telling me right

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 now because of just the time at which they were found
2 and the fact that these were actual tests where they
3 found as opposed to some other PM and I'm not familiar
4 -- I don't know how those PMs or other things do,
5 whether they actually these components or not.

6 MR. QUEEN: Yes. I guess --

7 MEMBER BROWN: So if nobody else is
8 protesting, I'll probably take it to the point where
9 I'll just wait and discuss it later with them. Okay.

10
11 Thank you.

12 That was it, John.

13 MR. BARTON: This miscellaneous yard
14 structures and concrete foundations you've got listed
15 in here, condensate storage tank and a BWST. And I
16 looked for the aging management program for these
17 tanks and the table for the BWST aging management
18 program says but the program is external surface
19 monitoring program. My question is how does that
20 check the bottom of the tank or is there another
21 program that does inspection at least one time or
22 something of the tank bottom to assure there's no
23 deterioration of tank bottom?

24 MR. GALLAGHER: Yes. Tank inspections.
25 Mark, is that you?

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. MILLER: Above ground, outdoor?

2 MR. GALLAGHER: The BWST.

3 MR. BARTON: Well, the BWST is outdoors, I
4 believe.

5 MR. MILLER: Yes. I am not familiar with
6 the --

7 CHAIR STETKAR: If you're going to say
8 something, you have to come up to the mic.

9 MR. MILLER: I'm not familiar BWST.

10 CHAIR STETKAR: You still have to -- this
11 is all on the public record and you have to officially
12 tell us that.

13 MR. MILLER: I have to say I don't know?

14 Mark Miller, Exelon.

15 I don't know the answer to your question,
16 off the top of my head.

17 MR. QUEEN: This is a question concerning
18 the interior of the tank?

19 MR. BARTON: Yes. Just tank failures
20 happen in this industry usually on the bottom of the
21 tank. All right. Your tanks are both directly on
22 concrete. And they've got a moisture barrier around
23 the lip of the tank, I believe, right? How do you
24 know that there's no deterioration of the tank bottom
25 when the aging management program says what I'm going

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 to do is external surface monitoring? Well, that
2 doesn't look at the bottom of the tank. So where is
3 your program for, you know, at least a one time
4 inspection of the bottom of the tank to assure there's
5 no deterioration of the bottom of the tank over the
6 period of operating life or over your operating
7 period?

8 MR. QUEEN: Yes. I can talk to both to
9 both of the tanks, our external tanks.

10 MR. BARTON: The borated water storage
11 tank is the same way.

12 MR. QUEEN: Condensate storage tanks, we
13 do have an external and an internal inspection program
14 for condensate storage tanks. They are inspected.
15 And that program looks at and examines the coatings in
16 those tanks. You know we coat the tanks in an
17 interval that's needed based on the inspections.

18 The borated water storage tank we had a
19 one time internal inspection of that that went in with
20 a robot, went down to the bottom, looked at the bottom
21 of the tank as well as the side walls of the tank
22 internally. It's a stainless steel tank. And we do
23 external inspections of it, but it was a one time
24 internal inspection.

25 MR. BARTON: And you've done that?

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. QUEEN: We've done that. That's
2 completed.

3 MR. BARTON: Okay. And you didn't find
4 anything wrong?

5 MR. QUEEN: We did not find anything
6 wrong.

7 MR. BARTON: Okay. Buried piping and tank
8 inspection program. They performed several
9 inspections of buried piping and you've already done
10 that. At the time the application for the renewal was
11 submitted the buried diesel generator fuel oil tank
12 internal inspection program was not performed. Have
13 you performed that and what were your results?

14 MR. QUEEN: The diesel tank, no. That's
15 this outage. This upcoming outage. The underground--

16 MR. BARTON: You're going to do it this
17 outage?

18 MR. QUEEN: That will be drained and
19 inspected internally.

20 MR. BARTON: Okay. Thank you.

21 CHAIR STETKAR: There's some discussion
22 about, I guess you have a common large -- I think it's
23 called an area intake tunnel, but an air intake plenum
24 that supplies air to the control building, the aux
25 building and somewhere else in the plant. And

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 apparently there's been a history of water intrusion
2 in there, that on an inspection report noted corrosion
3 of -- if I can read my notes here -- conduits, cable
4 boxes, conduit supports, degradation of fire
5 protection piping.

6 What all is routed through that tunnel? I
7 mean, obviously there are cables and pipes routed
8 through that tunnel. What is in there and what are
9 you doing to -- we talked about manways and trying to
10 keep water out of cable manways. What sort of program
11 do you have in place to address this issue, because it
12 wasn't clear?

13 MR. BENNETT: This is Pat Bennett.

14 So we do have inspections of the air
15 intake tunnel, periodic inspections of the air intake
16 tunnel. And when we do notice that there are -- if
17 there's a crack in the wall, if there's water coming
18 through the crack, we have repaired that. So when we
19 see a problem with water intrusion into the tunnel, it
20 does get repaired. We have done that, we have done
21 that in the past. And the past couple of years we
22 have done work where we have seen water coming in and
23 have sealed the cracks in the air intake tunnel.

24 MR. BARTON: Was that a routine inspection
25 or a periodic inspection or --

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. BENNETT: That's a routine inspection.
2 Actually, we have inspections going down through
3 there for fire service inspections. So there's a
4 number of inspections that go through the air intake
5 tunnel and they have the ability to identify issues.

6 CHAIR STETKAR: By the way, you've
7 mentioned -- what I read specifically mentioned fire
8 water piping. Are there any in scope cables that are
9 routed through that tunnel?

10 MR. QUEEN: I think Ed knows that for
11 sure. I think the answer is yes, but --

12 MS. SPAMER: Deb Spamer.

13 Yes, there have to be in scope cables in
14 there.

15 MR. QUEEN: There have to be?

16 MS. SPAMER: Yes, there have to be. Well,
17 the cables go out to the intake --

18 MR. GALLAGHER: The answer is there are.

19 CHAIR STETKAR: There are? Okay.

20 MS. SPAMER: Yes.

21 CHAIR STETKAR: Thanks.

22 MEMBER ABDEL-KHALIK: Back to the
23 criticality calculations. What was the geometry for
24 that limiting case? How was that geometry modified,
25 that perturbed geometry that takes into account

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 variations and dimensions? What does that geometry
2 look like?

3 MR. GETZ: Stu Getz, Exelon.

4 I think if I understand your question,
5 you're asking the basis of our evaluation --

6 MEMBER ABDEL-KHALIK: No, I understand the
7 baseline geometry.

8 MR. GETZ: I understand.

9 MEMBER ABDEL-KHALIK: What is the limiting
10 geometry?

11 MR. GETZ: We have not done an analysis
12 of, if I understand your question, how big a
13 deformation --

14 MEMBER ABDEL-KHALIK: No, no, no. I
15 understand exactly what you did.

16 MR. GETZ: All right.

17 MEMBER ABDEL-KHALIK: But what is the
18 geometry for that limiting calculation? Is it exactly
19 the same? You just changed the thickness of the
20 water, is that it?

21 MR. GETZ: We reduced the -- effectively
22 we reduced the flux trap/water gap by assuming the
23 full size blister on every Boral panel.

24 MEMBER ABDEL-KHALIK: So you have a gas
25 layer on both sides and that effectively changed the

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 thickness?

2 MR. GETZ: That's correct. If a blister
3 were to form on the panel that was gas filled, it
4 would effectively reduce the dimension of the water
5 gap. And our bounding example assumed a blister that
6 covers the entire surface.

7 MEMBER ABDEL-KHALIK: Yes, I understand.

8 MR. GETZ: Yes. And in so doing it
9 decreases the dimension of the water gap.

10 MEMBER ABDEL-KHALIK: All right. Thank
11 you.

12 MEMBER SHACK: One additional question.
13 As I understand it you only have the Alloy 600 nickel
14 alloy welds on the cold leg not on the hot leg, is
15 that right?

16 MR. POLASKI: I'm going to ask Gene
17 Navratil to answer that question.

18 MR. NAVRATIL: TMI is a B&W plant so we
19 have nickel alloy locations in multiple areas.

20 If the question is do we have Alloy 600
21 welds that fall under the MRP program, that's only on
22 the cold leg. The hot leg the Alloy 600 location has
23 a pressurizer surge line connection coming at the hot
24 leg because it's a carbon steel hot leg that has been
25 overlaid in 2003. So that's the only large bore hot

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 leg temperature connection we have on the piping. And
2 so that's been mitigated.

3 We are going to replace essentially the
4 top half of the hot leg, which has small instrument
5 connections for flow meters, vent lines, thermal
6 welds. That whole upper half will eliminate the rest
7 of the unmitigated Alloy 600 at hot leg temperature.

8 And we will be --

9 MEMBER SHACK: But the attachment of the
10 hot leg to the vessel has no nickel?

11 MR. NAVRATIL: No, that's correct. At the
12 reactor vessel there are no connections. The Alloy
13 600 welds, the 82/182 welds are adjacent to the pump
14 suction and discharge. Roughly two to three feet on
15 each side of the pump. That is a transition. There
16 is a forged stainless steel pipe that is welded to the
17 pump. And that is stainless steel to stainless steel
18 weld. And then about two to three feet away is a
19 carbon steel to stainless steel weld that's connected
20 with 82/182 material. So that's where those eight
21 welds are located. Basically one weld on the suction
22 and one weld on the discharge of each pump.

23 MEMBER SHACK: And the temperatures of
24 those?

25 MR. NAVRATIL: Cold leg temperature --

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 help me?

2 MR. QUEEN: 555, five hundred and fifty-
3 five degrees. Hot leg 600 degrees.

4 CHAIR STETKAR: Again, could you identify
5 yourself, just so we have your name?

6 MR. NAVRATIL: Oh, excuse me. Gene
7 Navratil, Exelon.

8 CHAIR STETKAR: Great. Thank you.

9 Any other members have any other
10 questions? If not, thank you very much. It was a
11 very good presentation.

12 And we will take a break until 3:15.

13 (Whereupon, at 3:00 p.m. a recess until
14 3:15 p.m.)

15 CHAIR STETKAR: Before we hear from the
16 staff, I've been reminded that as I ran down the list
17 of our participants here I overlooked John Barton, who
18 is our consultant. And I didn't mean to do that,
19 John. I'm sorry I slighted you. You certainly
20 participate and we appreciate your input. But John
21 Barton is here and he's our consultant.

22 And with that, I will turn it over to Jay
23 Robinson, I guess, who will lead the staff's
24 presentation.

25 MR. ROBINSON: Thank you, Mr. Chairman.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Brian, did you want to make any comments
2 first?

3 MR. HOLIAN: Yes. This is Brian Holian,
4 Director of License Renewal.

5 Just prior to, and for people who weren't
6 here this morning, assisting Jay up there is Evelyn
7 Gettys, the Project Manager for Susquehanna and we
8 have Dr. Sam Li here as the side table, the Deputy in
9 the Division of License Renewal.

10 I have just two other quick comments.

11 One, I just wanted to comment, Exelon
12 commented on their years of experience and that during
13 their presentation, which I think was very good. The
14 Subcommittee also probably knows that we gain in the
15 license renewal reviews when you have a fleet approach
16 to license renewal. And, you know, they're well into
17 their number of plants that they've reviewed and have
18 learned from kind of the operating experience from our
19 reviews. And I think that was evident in their
20 presentation and even in our review as Jay will cover
21 with the types of issues we found and how they
22 responded.

23 There was one question of them earlier on.
24 We'll have one of our staff members in particular
25 talk about the Boral issue again on potential failure

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 mechanisms or not. We'll pick that up during the
2 review.

3 That's all. Jay?

4 MR. ROBINSON: Thank you, Brian.

5 Good afternoon, Mr. Chairman, Subcommittee
6 members. My name is Jay Robinson. I'm the Safety
7 Project Manager for Three Mile Island license renewal.

8 Today I will be discussing the safety evaluation
9 report with open items.

10 Very briefly, this is the overview. I'll
11 go into Section 2: The scoping and screen review.
12 Following that Glenn Meyer will present information on
13 the license renewal inspections. And then we'll
14 discuss Section 3: Aging Management Program and
15 review results. And Section 4: Time-Limited aging
16 analyses.

17 Slide 3 is an overview which was
18 information previously discussed by the applicant. I
19 don't see any reason to repeat that here, so we'll
20 move on to slide 4.

21 The Safety Evaluation Report was issued in
22 March of 2009. There are no open items. There is one
23 confirmatory item which concerns dissolved oxygen.

24 In total there were 123 requests for
25 additional information issued and there are a total of

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 43 commitments.

2 Slide 5 just provides details on the
3 audits that were conducted. You can see we did a
4 scoping and screening methodology audit, followed by
5 our aging management program audit and followed by our
6 regional license renewal inspections.

7 Begin on Section 2, first looking at
8 Section 2.1 the scoping and screening methodology.
9 And based on its review of the application and the
10 additional information submitted as a result of our
11 requests for additional information, the staff
12 determined that the applicant's methodology is
13 consistent with the requirements of the applicable
14 regulations.

15 In addition to that in Section 2.2 for the
16 plant-level scoping results based on the staff's
17 review of the application and the RAIs, the staff
18 concluded that the applicant identified the systems
19 and structures that are within the scope of license
20 renewal per the applicable regulations.

21 MR. BARTON: That was after the 120 RAIs
22 on scoping and screening?

23 MR. ROBINSON: That is correct. There
24 weren't a 120 on scoping and screening.

25 MR. BARTON: I'm exaggerating. I thought

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 they could have done a better job of marking up
2 boundary drawings and stuff. I noticed there was an
3 awful lot of RAIs on the scoping drawing.

4 MR. ROBINSON: On Section 2?

5 MR. BARTON: Yes. Right.

6 MR. ROBINSON: Yes.

7 Moving on to Section 2:3 the scoping and
8 screening results for the mechanical systems. In that
9 section the staff identified nine systems that
10 required the applicant to revise the application and
11 add additional components into scope.

12 Examples of the component types omitted
13 included:

14 The fuel tank for the standby diesel
15 engine for the emergency diesel generator air start
16 system air compressor. That's the reason why we
17 didn't say "fuel tank" because it was involved. I
18 wanted to make sure everyone understood the correct
19 one;

20 Lube oil lines, and the intake bar racks.

21 And these items were subsequently added to scope and
22 subject to an aging management review.

23 And for Section 2.3 based on its review of
24 the application and the additional information
25 submitted as the result of the staff's RAIs, the staff

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 concluded that the applicant identified the mechanical
2 system components within the scope of license renewal
3 per the regulations and also subject to an aging
4 management review.

5 For Section 2.4 the scoping and screening
6 results for structures. The staff identified one
7 component that required the applicant to revise their
8 application and add the component into scope. This
9 was a structural steel platform associated with the
10 dyke and flood control system. This was located on
11 the inboard side of the dyke and it supported the
12 sluice gate and the associated operate.

13 And also with Section 2.4 based on a
14 review of the application and the additional
15 information submitted by the applicant, the staff
16 concluded that there were no omissions of structures
17 or structural components from the scope of license
18 renewal per the regulations. And also no omissions
19 from aging management review per the appropriate
20 regulations.

21 Section 2.5 which is the scoping and
22 screening results for the electrical systems and
23 commodity groups. The station blackout recovery path,
24 which was discussed in this section, includes the
25 complete circuits within the scope of license renewal.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 This includes the complete circuits between the
2 onsite circuits and up to and including the substation
3 which includes the switchyard circuits and associated
4 controls within the scope of license renewal.

5 I think in the applicant's presentation
6 they showed you a drawing of the switchyard which
7 depicts that.

8 In Section 2.5, again based on its review
9 of the application and the requests for additional
10 information, the staff concluded that there were no
11 omissions of electrical systems and commodity groups
12 from the scope of license renewal per the appropriate
13 regulations and no omissions from aging management
14 review.

15 The overall conclusion for Section 2.6
16 conclusion for scoping and screening. Based on its
17 reviews of the application, the onsite audit results
18 and additional information submitted as a result of
19 the RAIs, the staff concluded that the applicant's
20 scoping and screening methodology meets the
21 requirements of 10 CFR 54.4 and 54.21(a)(1). And also
22 that the applicant adequately identified those
23 systems, structures and components within the scope of
24 license renewal in accordance with 10 CFR 54.4(a) and
25 those structures and components subject to an AMR in

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 accordance with 10 CFR 54.21(a)(1).

2 And that concludes Section 2. Were there
3 any questions on Section 2?

4 CHAIR STETKAR: I would just like to
5 mention, I was pretty impressed with the thoroughness
6 that the staff did on this one on the scoping and
7 screening. You did a good job, I think, in terms of
8 searching --

9 MR. BARTON: As evidenced by the number of
10 RAIs.

11 CHAIR STETKAR: Well, and the types of
12 questions that were asked.

13 MR. BARTON: Yes, good questions.

14 CHAIR STETKAR: It's one of the better
15 jobs that I think we've seen. So I think you deserve
16 credit for that.

17 MR. ROBINSON: Well, thank you. Thank you
18 very much. I wasn't the Project Manager at the time.
19 Billy Rogers over there, Billy did that.

20 With that, I'll turn it over to Glenn
21 Meyer who will discuss the inspection results.

22 MR. MEYER: Good afternoon, Chairman
23 Stetkar, ACRS members.

24 I was on the regional inspection team, I
25 was not the team leader. Michael Modes was the team

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 leader, but we had a conflict this week between ACRS
2 presentations today and the inspection at Nine Mile
3 during the outage of their commitment fulfillment. So
4 we chose to split that up.

5 I will say in the scoping area, since it's
6 been brought up, it's interesting to compare
7 Susquehanna this morning and TMI this afternoon.
8 Susquehanna this morning was done quite a while ago
9 because of the delay. And what we've kind of evolved
10 to is I joined the scoping audit and look at things
11 from a regional standpoint, and also the reviewer in
12 addition to Billy and his continuing effort, the
13 reviewer is no longer contracted and so he's had an
14 in-house chance to get experienced and see the kinds
15 of issue that come up. So I think those factors have
16 tended to help the scoping.

17 And so I'll proceed.

18 Our inspection had two main objectives of
19 looking at the scoping of non-safety system structures
20 and components. We also sampled 19 of the aging
21 management programs to evaluate their thoroughness.

22 Regarding scoping, we concluded that
23 scoping of non-safety systems, structures and
24 components was generally accurate and they had used an
25 acceptable approach. We did review structural and

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 spatial interactions as a part of that.

2 In the aging management programs we did
3 pursue looking at the program procedures, the records,
4 we did walkdowns of systems in the plant, we evaluated
5 the operating experience that had gone into the
6 proposed activities for the aging management programs.

7
8 The concerns regarding aging management
9 programs were minimal. There were a few issues that
10 were raised. None of them rose to the level of
11 needing any changes to the application and they
12 addressed the concerns onsite within the program's
13 procedures.

14 We did have one item of interest. The
15 team leader choose to pursue the operating experience
16 approach that Exelon used in the TMI application where
17 they did rely on some period. Typically they'll look
18 at a five year period. And they did use the EPRI
19 mechanical tools for three years of that five year
20 period. So spent some time to look at how its
21 organized and capturing the information applicable to
22 TMI. And sampled some of the information both at TMI
23 and in the tools to make sure that it was thorough.
24 Our inspection concluded that the approach was a sound
25 one and had captured the right information.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 CHAIR STETKAR: Can I ask you a little bit
2 about that? I personally am a big fan in terms of
3 looking back at plant-specific operating experience.
4 I think you learn an awful lot from that. And when I
5 say "you," generically you, the applicant and the
6 staff.

7 This is the first, I believe, license
8 renewal certainly that I've been involved in, and I've
9 been on the Committee only for a year and a half now,
10 where there seems to be reliance on that EPRI tools
11 document as a surrogate for a detailed enumeration of
12 actual plant-specific operating experience.

13 As you mentioned, the applicant I believe
14 searched their plant-specific records, if I'm not
15 incorrect, from the period of January 1, 2005 through
16 November 30, 2006. So about two years. And the
17 remaining three years of the five year period that
18 they examined they referred back to the EPRI report.

19 I'm not familiar with that EPRI report.
20 So if someone could educate me quickly. Does that
21 EPRI report contain detailed information such that
22 it's an enumeration of events that have occurred at
23 each plant identified by plant or is it simply a
24 summary of industry experience?

25 MR. MEYER: I'm not certain I'm the right

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 person to talk to the EPRI tools --

2 CHAIR STETKAR: Okay. Okay.

3 MR. MEYER: -- since this was our first
4 experience at looking at them in detail.

5 CHAIR STETKAR: I'll turn to then someone
6 from Exelon who may have some --

7 MR. POLASKI: Yes. Fred Polaski with
8 Exelon.

9 Before I answer that question about
10 mechanical tools, let me clarify a little bit on how
11 we do the operating experience review at TMI. And
12 there's really two parts to that.

13 One is you do a review of plant operating
14 experience to determine if there's any aging effects
15 that are unique to your plant that hadn't previously
16 been identified. That was the review that we used the
17 mechanical tools to do.

18 The other part of the review we do is an
19 operating experience review of the programs and how
20 well the programs have worked. When we review the
21 programs we looked back at the entire plant history.
22 All right. We didn't limit that to five years. I
23 mean, so there's information we looked at, you know,
24 talking to plant program monitors going back beyond
25 the five years and identified any issues with

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 programs.

2 So just to be clear about the two
3 different parts and how we did that.

4 Now the part on the aging effects, what
5 the mechanical tools is its a document that was
6 initially generated over 12 years ago, 15 years ago by
7 the B&W Owners Group License Renewal Committee to
8 support the B&W plants. And this for Oconee and the
9 other B&W plants when they were early in the license
10 renewal process. And the reason for it was to
11 identify combinations for non-Class 1 equipment,
12 materials, environments and aging effects that needed
13 to be managed long term.

14 Subsequent to the B&W Owners Group having
15 developed it, the BWR owners Group, the Boiling Water
16 Reactor Owners Group, the Westinghouse Owners Group
17 bought into that, had it updated and expanded to
18 include BWR environments, Westinghouse operating
19 experience. And once we had developed that
20 altogether, we turned it over to EPRI to maintain it.

21 It gets periodically updated every so many years.

22 The update to that does a review of the
23 industry operating experience by looking at
24 significant events, NRC generic correspondence,
25 information from INPO, NEI information on issues that

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 have gone on and updating that document with broad-
2 based industry operating experience with respect to
3 materials, environments, aging effects and what they
4 are, what needs to be addressed is with managed aging
5 going forward.

6 So our position at TMI was that because
7 that had been updated through, I guess December of
8 2005 you mentioned or January 2005 that would have
9 included any aging effects that would have been
10 identified -- new aging effects identified at TMI.

11 You know, I've been working this for a
12 while and a lot of discussions the way the GALL is
13 developed and the way the rule is we look at aging
14 effects. So anytime if we found a new aging effect
15 for material environment combination, I'm sure that's
16 going to make a lot of news, it's going to be very
17 evident and will raise itself to a high level very
18 quickly because there'll be some new phenomena going
19 on that nobody had known about before.

20 So we believe that the search we did using
21 the mechanical tools and then our own detailed search
22 after the last update on the mechanical tools is more
23 than adequate to identify any aging effects that would
24 have been unique to TMI that hadn't been previously
25 identified.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. MEYER: Another thing that the tools
2 do is compare their guidance to the GALL and whether
3 its consistent so that it focuses--

4 CHAIR STETKAR: I understand that as a
5 generic industry type of comparison and clearinghouse.

6 I guess I'm still not -- again, I'm personally a big
7 proponent of looking at individual events, things that
8 occurred at your plant and understanding how they
9 relate to your plant rather than it being diluted
10 through an industry reporting and summarizing type of
11 process.

12 What types of -- I mean because I'm not
13 familiar with this process and I don't want to take
14 too much time but I do want to understand it because
15 of my emphasis on operating experience. How do you
16 report things and what things do you report? What
17 type of screening process do you use when you suddenly
18 decide that you're going to send something to EPRI to
19 be included within this tools document?

20 MR. POLASKI: In the operating experience
21 process at TMI, any of the Exelon plants and I suspect
22 I could say this for any plant in the industry, we all
23 have our own internal operating experience where we
24 review events at the plant. We also review external
25 experience that raises itself to the level it's of

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 industry interest, and we review that.

2 From an internal viewpoint if we would
3 have an event at a plant where it was -- the review of
4 that indicated that we had some failure of a piece of
5 equipment due to some new phenomena, that's going to
6 raise itself to a very high level. It will be of very
7 strong interest. It very well may have to be reported
8 on a Part 21 and have generic implications.

9 And so I think what we're dealing with
10 here is, for example, in boiling water reactors
11 because I'm a lot more familiar with them than I am
12 with pressurized water reactors, but we know that in
13 boiling water reactors recirc piping and stainless
14 steel is subject to intergranular stress corrosion
15 cracking. That's a very common phenomena, we
16 understand that. Carbon steel is not.

17 If we find that some plant would discover
18 that carbon steel was subject and has undergone IGSCC,
19 I'm sure that that kind of information, because this
20 is a new thing for carbon steel that nobody had
21 previously identified, would very quickly raise itself
22 to a very high level. And I truly expect that the NRC
23 generic correspondence is going to come out very
24 quickly on something like that. And that's the level
25 we're talking about when we're looking at aging

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 effects that we need to deal with for license renewal.

2 And in the review, you know, more than 50
3 percent of the plants nobody has found any new aging
4 effects yet.

5 CHAIR STETKAR: Well, except we have seen
6 experience where plants have looked back at their own
7 operating experience and identified something unique
8 to their plant. It could be water -- you know, we
9 talk about water intrusion, we talk about corrosion of
10 specific piping under specific soil conditions and
11 things like that. They don't rise to the surface of
12 the large industry generic issues that you're talking
13 about --

14 MR. POLASKI: Yes. Yes.

15 CHAIR STETKAR: -- and yet that it could
16 be something for that particular site that may dictate
17 -- and we've seen examples of this in our Committee
18 already; that may dictate the need for a unique
19 program for that site. It's a site-driven program.
20 And the only way that it's identified is to look
21 carefully at the site operating experience and say,
22 "Ah, we indeed have identified a problem here and we
23 need to address that with either a slightly different
24 program or an enhancement to an existing program to
25 address our condition."

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Those are my concerns. I am interested,
2 but I'm not concerned certainly with the large things
3 that certainly come up to the industry's attention.

4 MR. POLASKI: I agree with your concern in
5 that area, but that's the kinds of issues that the
6 plant internal operating experience ongoing review
7 process that occurs on a routine basis would identify
8 at a plant.

9 I mean, it's things I've seen is where you
10 get some unique situation where you've got -- the
11 plant ends up with an environment/material combination
12 that isn't typical.

13 CHAIR STETKAR: Yes.

14 MR. POLASKI: So if you get into some
15 condition like that, that will get you into the
16 programs that you maybe otherwise wouldn't have gotten
17 into because of some unique combination of material
18 environments it's not typical.

19 I think Mike wants to something, too.

20 MR. GALLAGHER: Right. This is Mike
21 Gallagher of Exelon.

22 And Mr. Stetkar, I think that's exactly
23 what Fred started out at the beginning, is we actually
24 did do a detailed operating review for programs for
25 just the point you're pointing out. Is there anything

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 unique at TMI that we need to address, and let's
2 factor it into the program. And in fact we have a
3 plant-specific program, there's one plant-specific
4 program.

5 What we were trying to do as far as in
6 this AMR review is really, you know, we have to
7 address all the aging effects that are in the GALL and
8 then we have identify are there any other ones out
9 there. So we used this industry tool and then we did
10 our own search. So we think we have all that basis
11 covered.

12 CHAIR STETKAR: What I'm trying to do is
13 to gain some confidence about the last part of that
14 statement "all the bases covered."

15 MR. GALLAGHER: Yes.

16 CHAIR STETKAR: Because the examples of
17 the operating experience that are documented in the
18 LRA and the SER, unless there's specific examples that
19 were provided in response to a request for additional
20 information, all of those plant-specific examples date
21 from January 1, 2001 to November of 2006 which has led
22 me to somewhat uneasiness about that completeness of
23 the surge back through five to ten years, at least, of
24 operating experience to understand that that had
25 someone been accounted for the process.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. GALLAGHER: Okay.

2 MEMBER BONACA: I had a question on this,
3 if I could. In the programs you have an attribute
4 which is operating experience.

5 MR. POLASKI: Yes.

6 MEMBER BONACA: That attribute is very
7 plant-specific, right?

8 MR. POLASKI: Yes. The OE -- well, there's
9 two parts to the operating experience for programs.
10 One is industry operating experience and the other is
11 plant-specific. So we do review industry operating
12 experience with programs and plant-specific operating
13 experience with the programs.

14 MR. HOLIAN: This is Brian Holian, Division
15 License Renewal. I'd just like to comment on
16 additional comment on operating experience.

17 I hope part of it might just be in the
18 write up at TMI. I mean, I presume that that's the
19 case. Just a month ago we had Indian Point in here
20 for a review. And ever since the Inspector General
21 finding they particularly looked at operating
22 experience and the usefulness of that and criticized
23 us for maybe not going into as much depth on
24 independent looks to their condition reporting
25 database. So we have been concentrating on that.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 We've added additional internal guidance
2 for our reviewers to go back. And on Indian Point in
3 particular they picked up some of those containment
4 concrete items that this Subcommittee looked at, which
5 was specific to their plant and we looked at for is
6 this a potential? Is this a new aging effect as
7 Exelon stated?

8 I think the Boral issue that we're talking
9 about is a potential new aging effect that's out
10 there. And, you know, it has besides just the
11 blister, maybe a possibility for gaps in the substance
12 itself. It hasn't maybe exhibited itself yet, but
13 other substances have that are used in spent fuel
14 pool.

15 So our staff is to look at that, not to
16 look necessarily just at the last five years or
17 whatever. And so I would propose that that's more of
18 a documentation issue. We've been trying to
19 concentrate on that and we'll try to make sure that's
20 flushed out in the SERs.

21 CHAIR STETKAR: Yes. Thanks.

22 MR. MEYER: It may be a statement of the
23 obvious, but the review of program effectiveness for
24 reviews of operating experience is not applied to the
25 new program on the theory that --

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 CHAIR STETKAR: Well, and that's indeed
2 one of the reasons -- not the program effectiveness,
3 but indeed some of the scope of the new -- especially
4 the new programs or the identification of a need of a
5 plant-specific new program in many cases can arise
6 from that review of the operating experience.

7 The effectiveness of the existing
8 programs, as the applicant mentioned, in many cases in
9 fact is tracked through the existing program process.

10 So, thanks.

11 MR. MEYER: Okay. I think we're up to
12 inspection conclusions. The inspection concluded that
13 the scoping of non-safety systems, structures and
14 components and the aging management programs are
15 acceptable. We concluded that the inspection results
16 support a conclusion of reasonable assurance that
17 aging effects will be managed and intended functions
18 will be maintained during the period of extended
19 operations.

20 Also, I'd like to touch briefly on current
21 performance at Three Mile Island. It's currently in
22 the licensee response column of the action matrix, the
23 lowest level of regulatory oversight. And that
24 position or categorization is based on all the
25 inspection findings being green and all the

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 performance indicators currently being green.

2 And I think we have a slide. So that
3 shows the performance indicators.

4 And that ends my presentation.

5 MR. ROBINSON: Okay. Thanks, Glenn.

6 Now it's Jay Robinson from the Division of
7 License Renewal.

8 With that we'll move on to Section 3, the
9 aging management review results. Slide 16 just goes
10 through the applicable sections of the SER.

11 We'll move to slide 17 to discuss the
12 aging management programs. There were 38 aging
13 management programs, seven were new, 31 were existing,
14 21 were consistent with the GALL report, nine of those
15 had enhancements. There was plant-specific program.
16 Eleven had exceptions. And then six had both
17 enhancements and exceptions.

18 MEMBER SIEBER: Could you characterize the
19 exceptions? You know, is it because the licensee
20 chose a later version of things or for what reasons?

21 MR. ROBINSON: For the most part, yes, as
22 the applicant stated earlier. Different revisions of
23 EPRI reports. I think one that comes to mind might be
24 the water chemistry guidelines the subsequent revision
25 came out whereas the GALL cites another revision, for

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the most part.

2 MEMBER SIEBER: None that we could
3 consider downgrades, right?

4 MR. ROBINSON: Pardon me?

5 MEMBER SIEBER: No exception was taken
6 that we would consider as a downgrade?

7 MR. ROBINSON: Not that I'm aware of.

8 MEMBER SIEBER: Less frequent
9 surveillance, less corrective action?

10 MR. ROBINSON: No.

11 MEMBER SIEBER: Everything is enhanced?

12 MR. ROBINSON: Yes, that's to my
13 understanding.

14 MR. MEYER: The fuel tank sampling that I
15 mentioned earlier.

16 MEMBER SIEBER: That's buried? Right.

17 MR. MEYER: So they made the point that it
18 made little sense to dig it up to look at it. And so I
19 think they substituted a UT or there was -- they met
20 the requirement in another way.

21 CHAIR STETKAR: The Halon and CO₂ --

22 MEMBER SIEBER: Okay.

23 MR. MEYER: Longer, you know, longer
24 inspection intervals, but that's pretty standard that
25 everybody takes.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER SIEBER: Okay.

2 MR. ROBINSON: Okay. We'll move on to
3 slide 18, which is the groundwater sampling results.
4 Groundwater sampling for pH, chloride and sulfate
5 concentrations will be performed every five years
6 during the period of extended operation. They did
7 conduct previous samples in 2007 and 2005. And those
8 samples indicated that the groundwater is considered
9 nonaggressive for steel embedded in concrete.

10 I'll touch a little bit on an issue that
11 the staff discovered concerning the reactor head
12 closure studs. During the audit the staff identified
13 the use of the Dow Corning G-N lubricate for reactor
14 head closure studs. This is composed of moly
15 disulfide which may promote stress corrosion cracking.
16 The staff issued an RAI on this and the applicant
17 agreed to enhance the program by selecting an
18 alternate stable lubricant that is compatible with the
19 material and the environment prior to the period of
20 extended operation. That is in commitment number 3.
21 They revised commitment 3.

22 MEMBER ABDEL-KHALIK: Has this lubricant
23 been used from day one?

24 MR. ROBINSON: I'm going to ask the
25 technical staff to answer that. He's coming.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. SUN: Robert Sun, Division of License
2 Renewal.

3 As far as I know, I believe that lubricant
4 has been used from day one. What happened was TMI had
5 initially stated that their program was consistent
6 with the GALL for this program element of preventive
7 actions. And while we were at the MP audit, you know,
8 we looked at a material spec sheet for the lubricant
9 and that turned out to include the 14 percent moly
10 disulfide, which led to the RAI. And we did look
11 closely at the operating experience. They didn't have
12 any evidence of cracking from their inspections which
13 they do every outage. And it didn't commit to the
14 enhancement.

15 MEMBER ABDEL-KHALIK: I think that was my
16 next questions. These studs have been examined for
17 cracks, I guess, and they're examined every outage?

18 MR. MEYER: Every outage.

19 MEMBER ABDEL-KHALIK: Thank you.

20 MR. ROBINSON: Thanks, Robert.

21 And based on the applicant's response for
22 the staff's request for additional information, the
23 staff found that acceptable and that resolved their
24 concern.

25 MEMBER SHACK: I thought moly disulfide

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 was gone a long time ago.

2 MR. ROBINSON: I guess not.

3 MR. BARTON: I thought people gave up on
4 that a long time ago.

5 MEMBER BONACA: Maybe they had a bit
6 supply of it.

7 MEMBER SHACK: That's right. A lifetime
8 supply.

9 MEMBER SIEBER: Don't sell your stock.

10 MR. ROBINSON: Move on? Okay. To the
11 next slide, which covers the reactor building liner,
12 which the applicant discussed in detail during their
13 presentation.

14 We looked at the operating experience and
15 that indicated corrosion at several locations due to
16 moisture intrusion through the moisture barrier. The
17 staff issued an RAI and the applicant committed to
18 restore the liner to its nominal plate thickness by
19 weld repair for the previously identified corroded
20 areas where the thickness of the base metal is reduced
21 by more than 10 percent of the nominal plate
22 thickness. And they were committed to do that prior
23 to the period of extended operation.

24 And also the applicant performed an
25 engineering evaluation and determined that the

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 intended function of the liner is currently being
2 maintained.

3 The staff found the applicant's proposed
4 corrective actions acceptable regarding the liner.

5 Now the next slide discusses the
6 inaccessible medium voltage cables not subject to 10
7 CFR 50.49 environmental qualification requirements.
8 The operating experience showed that inaccessible
9 medium voltage cables and several manholes experienced
10 water submergence for more than a few days.

11 During the staff's AMP audit the staff
12 found cables submerged underwater in two manholes. We
13 issued an RAI requesting the applicant provide a
14 certification of the cables ability to be submerged or
15 an action plan to preclude cable degradation. And the
16 applicant is going to adjust their frequency of
17 inspections based on the inspection results in order
18 to keep the cables from significant moisture.

19 And water in the manholes is a generic
20 current plant issue that's being addressed during the
21 current period of operation through the reactor
22 oversight process.

23 With regards to the aging management
24 programs, based on the staff's audit and review and
25 the additional information that the applicant

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 submitted as a result of the RAIs, the staff concluded
2 that the effects of aging will be managed so that
3 intended functions will maintained during the period
4 of extended operations per 10 CFR 54.21(a)(3).

5 The next slide discusses reduction of
6 neutron-absorbing capacity and loss of material due to
7 general corrosion. The applicant indicated that the
8 water chemistry program manages the loss of material
9 due to general corrosion. And that the Boral
10 surveillance program manages the reduction of neutron-
11 absorbing capacity.

12 The staff did issue an RAI on this and the
13 applicant did respond. In this particular case we're
14 able to put that information in the SER that we issued
15 in March. They do have a commitment to continue the
16 Boral test coupon surveillance through the period of
17 extended operation.

18 The staff did conclude that the programs
19 adequately managed loss of material from general
20 corrosion from Boral and also managed the reduction of
21 neutron-absorption capacity aging effect for the
22 period of extended operation.

23 And with that, I'd like to introduce Matt
24 Yoder who will talk more specifically to Boral.

25 MEMBER ABDEL-KHALIK: Before we get to

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 that, can we go back to slide 20.

2 MR. ROBINSON: Yes. Slide 20?

3 MEMBER ABDEL-KHALIK: I guess the
4 indication is that all the corrosion is above the
5 surface of the concrete. Is there any indication of
6 corrosion below that level in inaccessible areas?

7 MR. ROBINSON: Not that I'm aware of, but
8 I'll have the technical staff who reviewed that area
9 answer your question.

10 MR. XI: Xuhan Xi, structural engineer of
11 NRR.

12 During the audit we reviewed operating
13 experience. The corrosion we found is at 281 level,
14 most is, and the other is at 279 a six inch at that
15 depth. Yes. So basically it's behind the moisture
16 barrier.

17 MEMBER ABDEL-KHALIK: Who would you know
18 that there's no corrosion in the cork region?

19 MEMBER SIEBER: Take it out.

20 MR. ROBINSON: My understanding is that the
21 applicant inspected, I think, four to eight inches
22 below --

23 MEMBER SIEBER: Right. That's right.

24 MR. ROBINSON: -- the seal and which
25 involved the cork area.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER ABDEL-KHALIK: So that's the extent
2 of the applicant's knowledge as far as the state of
3 the liner; it goes four to six inches below the
4 surface of the concrete?

5 MEMBER SIEBER: The corrosion --

6 MEMBER ABDEL-KHALIK: Is that correct?

7 MR. BENNETT: This is Pat Bennett from
8 Exelon.

9 Sir, the corrosion, as I stated earlier,
10 was found behind the moisture barrier and above the
11 moisture barrier. And we did a full visual inspection
12 when we removed the moisture barrier and found no
13 corrosion below the moisture barrier.

14 MEMBER SIEBER: But the moisture barrier
15 is one inch, right?

16 MR. BENNETT: That's correct.

17 MEMBER SIEBER: So it's from one inch
18 below the surface to maybe a half an inch above, is
19 that right?

20 MR. BENNETT: That's correct, yes.

21 MEMBER SIEBER: But not in the cork area,
22 and you dug that out?

23 MR. BENNETT: As I said, we inspected four
24 to eight inches below the moisture barrier elevation
25 and there was no corrosion.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER ABDEL-KHALIK: Okay. Thank you.

2 MR. GALLAGHER: Sorry, one thing while
3 there was a slight pause in the action.

4 This is Mike Gallagher, Exelon.

5 We did have one little correction on the
6 reactor vessel stud inspection that you had asked a
7 little bit ago. So, Steve, could you do that?

8 MR. QUEEN: Yes. Steve Queen, Exelon.

9 Just for completeness we inspect the studs
10 each outage as a maintenance visual. We don't do NDE
11 on them each outage. And the maintenance visual looks
12 for boric acid, corrosion, any moisture and we don't
13 find that.

14 We also do NDE. We'll do UT on the studs.
15 Divide them into three groupings over ten years. So
16 about every outage to every other outage they get a
17 UT, a third of them. So I didn't want to imply that
18 we did NDE on them every outage. And we have not
19 found any cracking and we haven't found any evidence
20 during the visuals of any damage to the studs. But
21 the visuals are maintenance visuals, they're not NDE
22 VT1s, VT2s. They're not VT1s.

23 MR. GALLAGHER: And Mike Gallagher.

24 And it's primarily due to in addition to
25 this material you have to have moisture. So there's -

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 - we have been successful at TMI in keeping the
2 moisture out of that area.

3 MR. YODER: Okay. Matt Yoder from NRR.

4 I want to provide some of the staff
5 perspectives on Boral as well as other neutrons or
6 materials. And I'll keep this quick, but I think this
7 is going to be beneficial for the ACRS because it's a
8 topic you're going to hear over and over again.

9 We had a presentation by the applicant
10 today about blistering of Boral and how that could
11 impact the flux trap region in the Region 1 of the
12 spent fuel pool. And while the staff thinks that was
13 an excellent presentation and is fully aligned with
14 that, there is another potential degradation mechanism
15 that the licensee's program also covers that wasn't
16 discussed today, and it's also a concern for the
17 staff. And that would be the settlement out or the
18 dissolution of that material within the panels. So --

19 MEMBER SIEBER: That was my question.

20 MR. YODER: That was why I wanted to
21 address it.

22 WE have not seen this in Boral in date. We
23 have seen this with boroflex, of carbureon and with
24 some of the other materials.

25 So the staff position is regardless of the

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 material whether it's Boral where we don't have
2 history to date or it's one of the other materials
3 where we do have some operating experience on, we want
4 licensees to have surveillance programs in place such
5 that if we do hit some time where Boral starts to
6 degrade, we'll catch it early on and we'll be well
7 aware of what's going on.

8 So there's an interim staff guidance being
9 prepared on all neutron-absorbing materials. And I
10 just basically wanted to throw it out to clarify what
11 heard earlier, I guess.

12 MEMBER SIEBER: Let me follow up with a
13 question just to clarify my memory. It seems to me
14 Boral, that has boron, elemental boron in it. If it
15 captures a neutron, you get helium and something else,
16 which I forget what it is. Is it the helium gas that
17 causes the blister?

18 MR. YODER: My understanding is that the
19 blisters in Boral are caused by water intrusion and
20 then the corrosion of the aluminum material itself.

21 MEMBER SIEBER: Okay. As opposed to
22 helium?

23 MR. YODER: Correct.

24 MEMBER SIEBER: Okay.

25 MR. ROBINSON: Thank you.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER ABDEL-KHALIK: How far above a fuel
2 bundle does the Boral plate extend?

3 MR. GALLAGHER: Stu, can you answer that
4 question.

5 MR. GETZ: Stu Getz, Exelon.

6 The Boral panels in the racks are 136
7 inches long.

8 MEMBER ABDEL-KHALIK: But they're the
9 shorter than the bundle?

10 MR. GETZ: They are shorter than the
11 bundles by --

12 MEMBER ABDEL-KHALIK: Six inches?

13 MR. GETZ: -- approximately six inches.
14 That's correct.

15 MEMBER ABDEL-KHALIK: Okay.

16 MR. ROBINSON: Okay. We'll move on to the
17 conclusion for Section 3: Aging management review
18 results.

19 Based on its review of the application and
20 the additional information submitted by the applicant,
21 the staff concluded that aging effects will be managed
22 so that the intended functions will be maintained
23 consistent with the current licensing basis for the
24 period of extended operation.

25 And that concludes Section 3. We'll move

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 on to Section 4: Time-Limited aging analysis.

2 The first slide just shows the various
3 sections of Section 4. We're not going to go into
4 each one. We'll just go into some of the more notable
5 areas.

6 The first one is Section 4.2: Neutron
7 embrittlement of the reactor vessel and internals.
8 I'm going to discuss the Charpy upper shelf energy for
9 beltline plates and forgings. Also for beltline welds
10 and also pressurized thermal shock limits.

11 In this next slide here you can limiting
12 belt -- let's see here. The limiting material is the
13 lower shell plate C3251-1, which has a 52 EFPY Charpy
14 USE of 64, which is greater than the acceptance
15 criteria of 50.

16 Of the limiting beltline weld, which is
17 the limiting matter, is the upper shelf to lower shelf
18 circumferential weld WF-25 which has a 52 EFPY USE at
19 $\frac{1}{4}T$ of less than 50 and required equivalent margin
20 analysis.

21 And the results of the EMA were
22 acceptable.

23 Move on to the pressurized thermal shock
24 limits.

25 The referenced temperature pressurized

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 thermal shock units for the limiting beltline material
2 and the limiting beltline weld are below the
3 established screening criteria of 270 degrees and 300
4 degrees respectively found in the regulations.

5 Move on to Section 4.3: Metal fatigue of
6 piping and components.

7 A 60-year fatigue analysis were performed
8 for the applicable high fatigue locations of NUREG/CF-
9 6260. The initial analysis indicated that four
10 locations had a CUF greater 1.0. And they were:

11 The reactor vessel lower head instrument
12 nozzle penetration weld;

13 Reactor vessel outlet nozzle;

14 The pressurizer surge line elbow, and;

15 The makeup/high pressure injection nozzle.

16 Further evaluation was performed by the
17 applicant and the final results indicated that the
18 locations have an EAF-adjusted CUF of less than 1.0

19 And TMI will manage fatigue of Class 1
20 components using the metal fatigue of reactor coolant
21 pressure boundary aging management program.

22 Move on to Section 4.3.2, which includes
23 confirmatory item 4.3.2-1. This is similar to the
24 item we discussed this morning for Susquehanna.

25 The Fen values were calculated based on

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 assumed dissolved oxygen concentration data 0.05 ppm.

2 And the staff questioned whether that number was
3 bounding. The applicant indicated that it was
4 bounding and their historical DO levels were less than
5 .005. And they also indicated that they had
6 administrative controls in place to maintain data
7 before this level.

8 The applicant initially submitted data
9 from 1985 to current and then the confirmatory item
10 was mainly because we were looking for data from '74
11 to '79. And they did provide that information. They
12 pulled up all the old logs and confirmed what they
13 maintained during that time period. And the staff
14 agreed that that was acceptable and we're in the
15 process of closing out that confirmatory item.

16 Move on to section 4.9, which is the
17 conclusion for the TLAAs.

18 Based on the staff's review the
19 application and the additional information submitted
20 from the RAIs, the staff concluded that the applicant
21 provided an adequate list of TLAAs and that they will
22 remain valid for the period of extended operation.
23 That they have been projected to the end of the period
24 of extended operation. And that the aging effects
25 will be managed for the period of extended operation.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 CHAIR STETKAR: Jay, question. One of the
2 items in your list was environmental qualifications of
3 electrical equipment. And I noticed that, again,
4 going back to the theme of operating experience that
5 there had been at least one or two situations where
6 the temperature in an area that contains the main
7 feedwater reg valve and the feedwater bypass reg valve
8 was out of spec. The ventilation system apparently
9 had problems and temperature got to about 154 degree,
10 if I read correctly, which is higher than it's
11 supposed to be in the area but apparently less than
12 the qualification temperature.

13 I was curious whether there had been more
14 events because these events that were cited were
15 within that January 1st through November 2006 period
16 that I mentioned. I was curious whether there had
17 been other events in that area as part one.

18 The other part is that the applicant
19 apparently did an evaluation that said well these are
20 normally de-energized valves and the temperature
21 didn't exceed the qualification limits, and therefore
22 everything's okay. And I was curious about the claim
23 that these are normally de-energized valves since the
24 main feed reg valves are usually not normally de-
25 energized.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 So I guess we have a little bit of time
2 here and I'd like to understand a little bit more
3 about that particular location and whether:

4 1: Has there been any other history of
5 heating up that location because of ventilation
6 problems? Because it's normally a pretty warm
7 location, the main feedlines go through there.

8 And whether or not the fact that the
9 applicant -- I'm not personally familiar with
10 environmental qualification process. So whether the
11 fact that the applicant said that these are normally
12 de-energized components has any impact on the
13 determination of the effects of that temperature?

14 You may not be able to answer that
15 question. I'm kind of curious whether the --

16 MR. ROBINSON: The technical staff is
17 going to assist me on that one.

18 MR. NGUYEN: This is Duc Nguyen. I am the
19 auditor.

20 When we talk about environment
21 qualification, we do the pre-age shock cable. What we
22 mean we pre-age, that mean we cut the cable at the
23 shorter of period of time with the high temperature to
24 qualify that cable for the 40 year.

25 And this particular cable, I believe, is

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 they are qualified for very high temperature. 200
2 something degrees Fahrenheit.

3 The normal environment for that is 150, I
4 believe. And looking at the operating experience we
5 found that the environment is higher than the typical
6 environment. But this still below the environmental
7 qualification.

8 So that mean that this cable still
9 qualifies for the 40 year and it does not effect the
10 qualified life. When the end of the 40 year life,
11 then you have to replace the cable or requalify the
12 cable. So we determined that.

13 And this is only a short period of time
14 because the ventilation equipment, they're not working
15 for the period of time, a shutdown hour. So the
16 question then we say why doesn't it effect. And the
17 answer is they are qualified for 250 degrees and if we
18 are go below -- above 150 degrees for a few hours or a
19 few days, it doesn't effect the qualification.
20 Therefore, the staff concludes that it doesn't effect
21 the qualify of the cable.

22 CHAIR STETKAR: Okay. I'll ask the
23 applicant. Has there been a history of problems with
24 ventilation in this area? I recognize the fact the
25 temperature may be -- I think the statement was made

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the nominal temperature, according to your EQ file
2 ambient temperature for the area is 110 degrees
3 Fahrenheit and that the -- apparently the cables are
4 qualified for 198 degrees for a 40 year life, and
5 we're talking about getting 20 more years out of them.

6 MR. GALLAGHER: Yes. Mr. Stetkar, I'll
7 have Steve Queen that question.

8 This is Mike Gallagher, Exelon.

9 Steve?

10 MR. QUEEN: Yes. Steve Queen, Exelon.

11 The area is warm, 110 degrees typically.
12 We occasionally, not frequently, will have a
13 ventilation problem that we'll have to repair but it's
14 not typical that we'll temperatures above 150 degrees
15 in that area, as was the case stated here.

16 So the answer is no significant number of
17 failures of the ventilation system in the area. We
18 have not exceeded the EQ value when we have had
19 ventilation issues.

20 The energization issue is really around
21 solenoids, I believe. So there's solenoids attached to
22 the main reg valves, and that's -- you're correct.
23 The reg valves aren't energized, they're air operated
24 valves

25 CHAIR STETKAR: Well, but they're normally

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 controlling so --

2 MR. QUEEN: That's correct.

3 CHAIR STETKAR: They energized and de-
4 energized.

5 MR. QUEEN: Right.

6 CHAIR STETKAR: They're not normally de-
7 energized.

8 MR. QUEEN: That's correct.

9 CHAIR STETKAR: They're energized for a
10 reasonable fraction of time when they have to move.

11 All right. Thank you. I was looking more
12 in terms of the history of the operating experience,
13 again because this particular event was highlighted
14 because it happened during that January 1, 2000 to
15 November 2006 and I was curious if you went back
16 another five or ten years whether there was a history
17 of losses of ventilation.

18 MR. QUEEN: No, we haven't had any
19 significant loss of ventilation in those areas.

20 CHAIR STETKAR: Thank you.

21 MR. ROBINSON: Thank you.

22 I think we're on the lost slide here which
23 states the staff's conclusion regarding the
24 application for TMI-1 will be provided in the final
25 Safety Evaluation Report which is scheduled to be

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 issued in July of 2009.

2 And that concludes my presentation.

3 CHAIR STETKAR: Any other questions from--

4 MR. BARTON: Glenn, were you on this team,
5 or you weren't the team leader but you were on the
6 team?

7 MR. MEYER: On the team, not the team
8 leader.

9 MR. BARTON: Okay. In your inspection
10 report you noted as a result of general walk-through -
11 - I'm coming back at you -- inspection of the site
12 there were signs of degradation in various structures
13 visited. Inspection was focused on structural issues,
14 identified some weaknesses in the structural of aging
15 management program.

16 Well, you know, the applicant subsequently
17 changed their program, amended its program to take
18 care of those issues.

19 Now, did you guys look at anything else on
20 the structures and do you have any comment on what the
21 rest of the site looked like?

22 MR. MEYER: Structures. He does a walk-
23 through of various structures, looking at conditions,
24 making sure that things they've identified previously
25 are evaluated, tracked and trended.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 I think that TMI had some issues that were
2 in their system. It might not have been, say, as new
3 as Susquehanna that we talked about this morning. But
4 I don't think it was outside the bounds of acceptable
5 by any means.

6 CHAIR STETKAR: Okay.

7 MR. MEYER: And as to the rest of the
8 plant I really couldn't make any comments. There was
9 nothing noteworthy that we would say.

10 CHAIR STETKAR: All right. Okay.

11 MEMBER ABDEL-KHALIK: Have you taken any
12 systems and looked at it in detail like you did with
13 Susquehanna?

14 MR. MEYER: In this inspection we chose
15 not to do a system review. The operating experience
16 was, in a sense, a substitute for that. It's another
17 way of looking at the objectives. It varies.

18 CHAIR STETKAR: Anybody else?

19 Thank you very much.

20 And we find ourselves about 20 minutes
21 ahead of our schedule. What I'd like to do now is
22 open up the bridge line so that Ms. Aamodt has an
23 opportunity to make her statement that she's
24 requested.

25 So if we can -- are you there?

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MS. AAMODT: I'm here.

2 CHAIR STETKAR: Excellent. You are open
3 and we can hear you.

4 MS. AAMODT: Oh, good.

5 CHAIR STETKAR: And you have the floor.

6 MS. AAMODT: If there's some time if you
7 can't hear me. I feel like I'm so far away from you
8 that you can't hear me. But I know things work better
9 with telephones than shouting.

10 CHAIR STETKAR: So you have the floor.

11 MS. AAMODT: Well, I thank you very much,
12 Chairman Stetkar, for providing me this opportunity to
13 express our concerns.

14 I am an experimental psychologist. My
15 husband is an engineer and physicist. And we worked
16 as research scientists as members of the Technical
17 Staff of the Bell Telephone Laboratories in Murray
18 Hill, New Jersey before moving to Pennsylvania in
19 1963. We lived in Chester County, 45 minutes
20 southeast of TMI on a 300 acre site which we developed
21 into a working farm using organic horticulture.

22 We never left the consulting business and
23 other things we were doing, but we did that on the
24 side. We had lots of energy at that time.

25 In September of 1979 at the invitation of

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the NRC, our family became a party in the NRC hearing
2 to decide whether or not TMI Unit 1 should be
3 relicensed following the accident.

4 And after participating for nearly five
5 years, we first heard that residents who had symptoms
6 attributed to psychological stress lived in certain
7 neighborhoods. Now that belied a psychological origin
8 and thus, I went out and conducted a door-to-door
9 survey of three of those neighborhoods and uncovered a
10 rate of death from cancer which was ten times the
11 expected the rate for those townships.

12 The TMI Public Health Fund expressed
13 interest in my study, came to my home, verified the
14 data with their Pennsylvania Department of Health, the
15 population numbers and wrote to me to say this was
16 indeed an excess of cancer deaths with a clear
17 relationship to the TMI accident. Drs. Cobb, Cochran,
18 Morgan, Abrahamson and Woodwell were most intimately
19 involved with our work and they prevailed in getting
20 the Health Fund to underwrite a follow up by
21 researchers with Columbia University.

22 They found a post-accident rate of cancer
23 incidence for the ten mile area in excess of what as
24 expected. Particularly outstanding was the incidence
25 of lung cancer, but the cause was not attributed to

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the accident because the researchers were informed
2 that no member of the public received a radiation dose
3 in excess of 1000 mrems. This study was under review
4 and approval of the nuclear insurers.

5 Now in 1997, Dr. Steve Wing determined
6 that the rise in cancer incidence that was shown by
7 the Columbia Study among 60 civil divisions in the ten
8 mile area correlated almost perfectly with the
9 relative distribution of radiation, which was made by
10 Dr. Beyea who developed that distribution with the
11 utility's consultant.

12 The relationship between increased cancer
13 rates across increasing levels of dose was most
14 consistent for lung cancer.

15 Dr. Wing's work was published in
16 *Environmental Health Perspectives* IN 1997.

17 Now the lynch pin is that in 1994 and '94,
18 we obtained blood samples from residents who
19 complained of symptoms which were erythema, difficulty
20 breathing,, nausea, tingling over skin, metallic taste
21 and smell at the time of the accident and then a loss
22 of hair and graying of their hair. And one women
23 experienced a complete loss of her kidney.

24 There were 29 others who had lung
25 collapses and other kinds of problems that were so

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 outstanding.

2 There were 28 people that we tested
3 ranging in age from 16 to about 60 years and the
4 samples were analyzed by scientists at the Russian
5 Academy of Sciences. They found universal severe
6 immune system suppression, increased levels of stable
7 and unstable chromosome aberration and a frequency of
8 translocations obtained with the FISH method from
9 which they estimated average absorbed dose for the
10 examined person of approximately 100 rems. This work
11 was published by the Scientific Council of
12 Radiobiology of the Russian Academy of Sciences in
13 March 1996.

14 Now earlier, within a few years after the
15 accident, the NRC commissioned a study to investigate
16 alleged psychological systems experienced by
17 residents. And they found that all subject had
18 significant lymphocyte depression. Repeated testing
19 of these subjects five years later showed that immune
20 system depression persisted and the researcher
21 proposed that the cause was radiation exposure which
22 the students had in common since a control group
23 living in Delaware and highly stressed by
24 identification of a toxic waste dump in their
25 neighborhood did not exhibit lymphocyte depression.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 The threshold dose to cause
2 immunosuppression is 50 rems.

3 This was an NRC study which was funded by
4 the NRC and it was principally accomplished by Dr.
5 Andrew Baum of the Uniformed Services University.

6 The number of residents who were severely
7 exposed to ionized radiation is, of course, not
8 limited to the approximately 450 residents of the
9 three neighborhoods west of TMI which I surveyed or
10 the several dozen subjects studied by the Russian
11 Academy of Sciences or the two dozen subjects
12 considered by Dr. Baum. Many other people complained
13 of symptoms through various entities from the time of
14 the accident. Records of the identities of these
15 people are held by a Census-taker for the CDC
16 Pennsylvania Department of Health Survey of the five
17 mile area residents, a state representative who later
18 became Mayor of Harrisburg, several area doctors, and
19 most notably scientists who, upon finishing their
20 graduate courses at Columbia University, spent several
21 years immediately following the accident gathering
22 this information. These young scientists provided
23 their findings to the Three Mile Island Alert
24 organization and to the NRC, and then published in
25 journals of Kyoto University where one of the

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 researches is on the faculty.

2 The surviving members of this cohort of
3 exposed persons could be identified and tested for the
4 presence of translocations by the FISH method. I
5 would suggest using the services of the Russian
6 Academy of Sciences who have this vast experience in
7 conducting and interpreting these kinds of tests.

8 Now the most recent and alarming
9 information is that people who were living within 5
10 miles of TMI have been dying over the 20 years
11 following the accident at a significantly higher rate
12 than the population of the three adjacent counties.
13 This is indicating the effects of continued immune
14 system suppression on this population of approximately
15 30,000 people.

16 This is a study done at the University of
17 Pittsburgh by Dr. Evelyn Talbot funded by the Health
18 Fund. There were significant elevations in male
19 deaths from cancer of the respiratory system, of the
20 bronchus trachea and lung from a nonmalignant
21 respiratory disease. And also elevations in all
22 malignant neoplasm breast cancers in men and leukemia
23 and from all external causes.

24 For females there were significant
25 elevations in deaths from non-malignant respiratory

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 disease, cancer of the nervous system, breast cancer,
2 leukemia and lymphatic and hematopoietic tissue, other
3 lymphopoietic cancer and cancer from all external
4 causes.

5 Ten children under 18 years of age died
6 due to cancers, which included cancers of the
7 bronchus/lung, acute leukemia, Hodgkin's disease,
8 lymphoma, ovary and brain.

9 This cohort was identified by CDC and PDoH
10 for the specific purpose of determining the
11 environmental status of the people living close to the
12 reactor.

13 Our view is re-licensing of the TMI
14 reactor will expose already compromised people to an
15 unnecessary exposure to radioactivity which we believe
16 in contrary to the mandate of the NRC to protect human
17 health and safety. The NRC has admitted the release
18 of radioactivity to the environment in excess of
19 established limits as will result from the replacement
20 of the steam generators.

21 Many of these families have lived i the
22 TMI area for generations and are not able to move
23 away. I spoke with one such family on this recent
24 past 30th anniversary of the accident. They are
25 presently coping with the recovery of a daughter from

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the removal of a tumor the size of an orange that are
2 "the mother died of a heart attack after unexplained
3 suffering for many years of undiagnosed and leg
4 problems." The father still develops rashes when he
5 spends time outside. These are people who have
6 symptoms of exposure during the TMI accident. And I
7 interviewed them in 1984.

8 Now because the steam generators tubes
9 have been leaking these many years, people have been
10 receiving more exposures. I do not see where this
11 impact on a community has been evaluated. These
12 releases are of particulates of as many as 240
13 different kinds of radionuclides according to Dr.
14 Kocker. The risk is similar to the NRC's analysis of
15 exposure to radon. I am now quoting from your draft
16 statement on pages 8-27 and 28: "The particulates are
17 inhaled" and this your analysis of radon, I believe I
18 said that. "The particulates are inhaled and remain
19 lodged in the lungs, causing continued exposure."
20 This relevant exposure of TMI residents from
21 inhalation -- this is my own words now -- of
22 radioactive particulars has never been acknowledge or
23 considered. This is a chronic dose that is still
24 occurring in these people.

25 Your report admits that recent monitoring

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 of leafy vegetation, soils and sediment, surface water
2 and fish show concentration of radiological
3 contaminants. The REMP program found strontium 90 in
4 more than one half of the small number of milk samples
5 tested in nearly all food products. The pre-
6 operational period which you use as the baseline
7 included the accident and cleanup period. So I find
8 that an improper comparison. And assumptions of
9 residual fallout due to weapons testing at this time
10 is not a credible explanation.

11 I think that what you are saying is that
12 TMI area residents have experienced continual internal
13 exposure to radioactive particulates from fallout due
14 to weapons testing and from nuclear power generation.

15 We believe that the law and conscience
16 require, your conscience, requires additional
17 assessment of the health status of the population.
18 Before any decision is made to replace the steam
19 generators and re-license Unit 1, we are requesting
20 that the study of 5 mile residents be updated to the
21 present time. It stopped with 1999. And the data be
22 made available to independent researchers for a
23 consensus and a follow-up with FISH tests for
24 translocations in the blood of families suffering
25 medical problems. In the meantime, Unit 1 should be

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 shutdown. It would be the right thing for you to do.

2 As an alternative to re-licensing Unit 1,
3 the NRC acknowledges that "Conventional Hydroelectric
4 Power" could play a role but the NRC staff did not
5 evaluate hydropower as an alternative to license
6 renewal. I would strongly suggest that the NRC do
7 that.

8 Thank you very much.

9 CHAIR STETKAR: Ms. Aamodt, thank you very
10 much for your comments. And we will certainly
11 consider them during our Subcommittee deliberations
12 and during full Committee.

13 And, again, thank you very much for your
14 input.

15 We will now close the bridge line so you
16 can continue to listen in until the meeting is
17 adjourned, but we won't be able to hear you anymore.

18 So thank you again.

19 MS. AAMODT: Thank you. Bye-bye.

20 CHAIR STETKAR: Bye.

21 Let's see. Staff is finished.

22 What I'd like to do before we close the
23 meeting is just to make sure that there are no further
24 questions, either for the staff or for the applicant,
25 among any of our members. Anybody have anything?

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Nothing?

2 With that, we'll close the meeting.

3 (Whereupon, at 4:27 p.m. the meeting was
4 adjourned.)

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

Official Transcript of Proceedings
NUCLEAR REGULATORY COMMISSION

Title: Advisory Committee on Reactor
Safeguards Plant License Renewal
Subcommittee

Docket Number: (n/a)

Location: Rockville, Maryland

Date: Wednesday, April 1, 2009

Work Order No.: NRC-2756

Pages 1-140

NEAL R. GROSS AND CO., INC.
Court Reporters and Transcribers
1323 Rhode Island Avenue, N.W.
Washington, D.C. 20005



**Three Mile Island
Generating Station - Unit 1
License Renewal Application**

**ACRS Subcommittee
Presentation
April 1, 2009.**

**Advisory Committee on Reactor Safeguards (ACRS)
License Renewal Subcommittee
Three Mile Island Nuclear Station, Unit - 1 (TMI-1)
Safety Evaluation Report (SER) with Open Items**

April 1, 2009

Jay E. Robinson, Project Manager
Office of Nuclear Reactor Regulation

Introduction

- Overview
- Section 2: Scoping and Screening Review
- License Renewal Inspections
- Section 3: Aging Management Program and Review Results
- Section 4: Time-Limited Aging Analyses (TLAAs)

Overview

- LRA Submitted by letter dated January 8, 2008
- Babcock & Wilcox (B & W) Pressurized Water Reactor (PWR), carbon steel-lined concrete (DRYAMB) containment
- 2568 MWth, 852 MWe
- Operating License DPR-050 expires April 19, 2014
- Located 10 miles southeast of Harrisburg, PA
- Unit 2 Shutdown in safe storage mode of Post Defueling Monitored Storage (PDMS)

Overview

- Safety Evaluation Report issued March, 2009
- 0 Open Items
- 1 Confirmatory Item
- 123 RAIs issued
- 43 Commitments

Overview

- Scoping and Screening Methodology Audit
 - May 19, 2008 – May 22, 2008
- Aging Management Program (AMP) Audit
 - July 14, 2008 – July 16, 2008
 - July 28, 2008 – August 1, 2008
- Regional License Renewal Inspection
 - November 17, 2008 – November 21, 2008
 - December 08, 2008 – December 12, 2008

Section 2: Structures and Components Subject to Aging Management Review

- Section 2.1 - Scoping and Screening Methodology
 - Based on its review of the LRA and additional information submitted as a result of Requests for Additional Information (RAIs), the staff determined that the applicant's methodology is consistent with the requirements of 10 CFR 54.4 and 54.21(a)(1)
- Section 2.2 - Plant-Level Scoping Results
 - Based on its review of the LRA and additional information submitted as the result of an RAI, the staff concluded the applicant identified the systems and structures within the scope of license renewal per 10 CFR 54.4(a)

Section 2: Structures and Components Subject to Aging Management Review

- Section 2.3 – Scoping and Screening Results: Mechanical Systems
 - The staff identified nine systems that required the applicant to revise their application to add additional components into scope
 - Examples of component types omitted included: Fuel tank for the standby diesel engine for the emergency diesel generator air start system air compressor, lube oil lines, and intake bar racks, which were subsequently added to scope and subject to an AMR
 - Based on its review of the LRA and additional information submitted as the result of RAIs, the staff concluded that the applicant identified the mechanical system components within the scope of license renewal per 10 CFR 54.4(a) and subject to an aging management review per 10 CFR 54.21(a)(1)

- Section 2.4 – Scoping and Screening Results:
Structures
 - The staff identified one component that required the applicant to revise their application to add the component into scope
 - Based on its review of the LRA and additional information submitted as the result of RAIs, the staff concluded that there were no omissions of structures or structural components from scope of license renewal per 10 CFR 54.4(a), and no omissions from AMR per 10 CFR 54.21(a)(1)

- Section 2.5 – Scoping and Screening Results: Electrical Systems/Commodity Groups
 - Station blackout recovery path includes the complete circuits within the scope of license renewal
 - Based on its review of the LRA and additional information submitted as the result of an RAI, the staff concluded that there were no omissions of electrical systems/commodity groups from scope of license renewal per 10 CFR 54.4(a), and no omissions from AMR per 10 CFR 54.21(a)(1)


- Section 2.6 – Conclusion for Scoping and Screening
 - Based on its review of the LRA, the onsite audit results, and additional information submitted as the result of RAIs, the staff concluded that:
 - The applicant’s scoping and screening methodology meets the requirements of 10 CFR 54.4 and 54.21(a)(1), and
 - That the applicant adequately identified those SSCs within the scope of license renewal in accordance with 10 CFR 54.4(a), and those SCs subject to an AMR in accordance with 10 CFR 54.21(a)(1)

- Inspection Objectives
 - Scoping of Non-Safety SSCs
 - 19 Aging Management Programs (AMPs)
- Scoping
 - Scoping of non-safety SSCs – generally accurate and acceptable
 - Structural and spatial interactions reviewed


- Aging Management Programs
 - Reviewed AMP program procedures and records
 - Walked down systems in plant
 - Evaluated operating experience
 - Concerns – Minimal; addressed onsite

- Item of Interest
 - Operating Experience Approach
- Inspection Conclusions
 - Scoping of non-safety SSCs and aging management programs are acceptable
 - Inspection results support a conclusion of reasonable assurance that aging effects will be managed and intended functions will be maintained.

- Current Performance
 - Licensee Response Column of Action Matrix
 - All Findings – Green
 - All Performance Indicators (PIs) - Green



Performance Indicators



- Section 3.0 – Aging Management Programs
- Section 3.1 – Reactor Coolant System
- Section 3.2 – Engineered Safety Features
- Section 3.3 – Auxiliary Systems
- Section 3.4 – Steam and Power Conversion System
- Section 3.5 – Containments, Structures and Component Supports
- Section 3.6 – Electrical Commodity Group

- Section 3.0.3 – Aging Management Programs (AMPs)
 - 38 – AMPs
 - 7 New Programs
 - 31 Existing Programs
 - 21 consistent with GALL Report
 - 9 with enhancements
 - 1 plant specific
 - 11 with exceptions
 - 6 with both enhancements and exceptions

Groundwater Sampling

- Groundwater sampling for pH, chloride, and sulfate concentrations will be performed every 5 years during the period of extended operation.
- TMI-1 Groundwater is non-aggressive

	Acceptance Criteria	2007	2005 (Three Samples taken)
pH	>5.5	7.4	7.8/7.8/7.7
Chlorides	<500 ppm	58 ppm	57.3/42.4/65.5 ppm
Sulfates	<1500 ppm	27 ppm	44.2/53.3/48.0 ppm

Reactor Head Closure Studs

- During AMP audit, staff identified use of Dow Corning G-N lubricant for reactor head closure studs
 - Composed of 14% Molybdenum Disulfide
 - Molybdenum Disulfide may promote stress corrosion cracking
- Staff issued RAI and applicant agreed to enhance program by selecting an alternate stable lubricant that is compatible with the fastener material and the environment prior to the period of extended operation
- Staff found applicant's response to the RAI acceptable and their concern resolved

Reactor Building Liner

- Staff identified that operating experience indicated corrosion at several locations due to moisture intrusion through the moisture barrier
- Staff issued RAI and applicant committed to restore the liner to its nominal plate thickness by weld repair for previously identified corroded areas where thickness of the base metal is reduced by more than 10% of the nominal plate thickness, prior to the period of extended operation
- Applicant performed engineering evaluation and determined the intended function of the liner is currently being maintained
- Based on its review, the staff found the applicant's proposed corrective actions acceptable

Inaccessible Medium Voltage Cables Not Subject to 10 CFR 50.49 Environmental Qualification Requirements

- TMI-1 operating experience shows that inaccessible medium-voltage cables in several manholes experienced water submergence for more than a few days
- During AMP audit staff found cables submerged under water in two manholes
- Staff issued RAI for submergence certification for cables or action plan to preclude cable degradation
- Applicant will adjust frequency of inspections based on inspection results in order to keep cables from significant moisture
- Water in manholes is a generic, current operating plant issue that is being addressed during the current period of operation through the reactor oversight process in accordance with the requirements of 10 CFR Part 50

- Section 3.0.3 – Aging Management Programs (AMPs)
 - Based on it's audit and review and additional information submitted as the result of RAIs, the staff concluded that the effects of aging will be managed so that intended function(s) will be maintained during the period of extended operation, per 10 CFR 54.21(a)(3)

Reduction of Neutron-Absorbing Capacity and Loss of Material due to General Corrosion

- Water Chemistry Program
 - Loss of Material due to General Corrosion
- Boral Surveillance Program
 - Reduction of Neutron-Absorbing Capacity
- Staff issued RAI and applicant responded
- Commitment to continue Boral test coupon surveillance through period of extended operation
- Staff concluded that Water Chemistry Program will adequately manage loss of material from general corrosion of Boral, and the Boral Surveillance Program will adequately manage the reduction of neutron absorption capacity aging effect for the period of extended operation

- Section 3.7 – Conclusion
 - Based on its review of the LRA and additional information submitted as the result of RAIs, the staff concluded that aging effects will be managed so that the intended functions will be maintained consistent with the CLB for the period of extended operation, per 10 CFR 54.21(a)(3)

- 4.1 Introduction
- 4.2 Neutron Embrittlement of the Reactor Vessel and Internals
- 4.3 Metal Fatigue of Piping and Components
- 4.4 Leak-Before-Break Analysis of Primary System Piping
- 4.5 Fuel Transfer Tube Bellows Design Cycles
- 4.6 Crane Load Cycle Limits
- 4.7 Loss of Prestress in Concrete Containment Tendons
- 4.8 Environmental Qualification of Electrical Equipment

- Section 4.2 - Neutron Embrittlement of the Reactor Vessel and Internals
 - Charpy Upper-Shelf Energy for Beltline Plates and Forgings
 - Charpy Upper-Shelf Energy for Beltline Welds (Equivalent Margins Analysis)
 - Pressurized Thermal Shock Limits (RT_{PTS}) for Reactor Vessel Materials Due to Neutron Embrittlement

Section 4.2 – Charpy Upper-Shelf Energy for Beltline Plates, Forgings, and Welds

Limiting Beltline Material for Plates & Forgings — Lower Shell Plate (C3251-1) Unit 1

% CU	52 EFPY Fluence 1/4T Location, n/cm ²	Initial Charpy USE at 1/4T, (ft-lbs)	52 EFPY Charpy USE at 1/4T, (ft-lbs)	Acceptance Criterion per 10 CFR 50, App. G (ft-lb)
0.11	1.153 X 10 ¹⁹	81	64	>50

Limiting Beltline Weld— US to LS Circ Weld * (WF-25) Unit 1

% CU	52 EFPY Fluence 1/4T Location, n/cm ²	Initial Charpy USE at 1/4T, (ft-lbs)	52 EFPY Charpy USE at 1/4T, (ft-lbs)	Acceptance Criterion per 10 CFR 50, App. G (ft-lb)
0.34	1.119 X 10 ¹⁹	70	41.4	EMA

* The value for US to LS Circ Weld (WF-25) is the bounding value for beltline welds

Section 4.2: Pressurized Thermal Shock Limits (RT_{PTS}) for Reactor Vessel Materials Due to Neutron Embrittlement

Limiting Beltline Material for Plates & Forgings — Lower Shell Plate (C3307-1) Unit 1

% CU %Ni	52 EFPY Fluence (n/cm ²)	Initial RT_{NDT} °F	RT_{PTS} °F	Acceptance Criterion per 10 CFR 50.61, °F
0.12 0.55	1.971E+19	+1	161.8	<270°F

Limiting Beltline Weld—NB to US Circ Weld (WF-70) Unit 1


% CU %Ni	52 EFPY Fluence (n/cm ²)	Initial RT_{NDT} °F	RT_{PTS} °F	Acceptance Criterion per 10 CFR 50.61, °F
0.32 0.58	1.836E+19	-31.1	263.8	<300°F

- Section 4.3 – Metal Fatigue of Piping and Components
 - 60-year fatigue analyses were performed for the applicable high-fatigue locations of NUREG/CR-6260
 - Initial analysis indicated that 4 locations had a CUF >1.0:
 - Reactor Vessel Lower Head – Instrument Nozzle Penetration Weld
 - Reactor Vessel Outlet Nozzle
 - Pressurizer Surge Line (elbow)
 - Makeup/High Pressure Injection Nozzle
 - Further evaluation performed and final results indicated that the locations have an EAF-adjusted CUF value < 1.0
 - TMI-1 will manage fatigue of Class 1 components using the Metal Fatigue of Reactor Coolant Pressure Boundary Aging Management Program

- Section 4.3.2 – Evaluation of Reactor Water Environmental Effects on Fatigue Life of Piping and Components, GSI-190
 - Confirmatory Item 4.3.2-1
 - Fen values calculated based on assumed DO (dissolved oxygen) concentration data lower than 0.05 ppm
 - Staff questioned whether 0.05 ppm DO was bounding
 - Applicant indicated that 0.05 ppm was bounding since TMI-1 historically maintained its DO levels at less than 0.005 ppm, and administrative controls are in place to maintain it at or below this level
 - Applicant submitted additional information which staff found acceptable and is in process of closing out item and revising SER

- Section 4.9 – Conclusion
 - Based on its review of the LRA and additional information submitted as the result of RAIs, the staff concluded that the applicant provided an adequate list of TLAAs, per 10 CFR 54.3 and that the:
 - TLAAs will remain valid for the period of extended operation, per 10 CFR 54.21(c)(1)(i)
 - TLAAs have been projected to the end of the period of extended operation, per 10 CFR 54.21(c)(1)(ii)
 - Aging effects will be managed for the period of extended operation, per 10 CFR 54.21(c)(1)(iii)

- The staff's conclusion regarding the LRA for TMI-1 will be provided in the Final SER scheduled to be issued in July, 2009



U.S.NRC

United States Nuclear Regulatory Commission

Protecting People and the Environment

Introductions

- Mike Gallagher VP, Exelon License Renewal
- Steve Queen TMI-1 Operations Director
- Al Fulvio Manager, License Renewal
- Pat Bennett TMI-1 Engineering Manager
- Chris Wilson Licensing Lead

Agenda

- Introductions Mike Gallagher
- Site Description Al Fulvio
- Operating History Steve Queen
- GALL Consistency, Commitments, and Confirmatory Item Al Fulvio
- Topics of interest
 - Recent LR Industry Issues Al Fulvio
 - Reactor Building Liner Pat Bennett
 - Medium Voltage Cables Steve Queen
 - Fuel Storage Racks Containing Boral Al Fulvio
- Questions and Close Mike Gallagher

Site Description and Operating History

Site Description

- TMI-1 is a Babcock and Wilcox (B&W) Pressurized Water Reactor located on Three Mile Island, which is situated in the Susquehanna River
- Also located on Three Mile Island is TMI-2, which is owned by First Energy Corporation
 - TMI-2 has been shut down since the 3/28/79 accident and is now in a safe storage mode called Post Defueling Monitored Storage (PDMS)

Site Description



Operating History

- Commercial Ops 09/74
- TMI-2 Accident 03/79
- TMI-1 stays shutdown 03/79
- TMI-1 Restart 10/85
- 1.3 percent power uprate to 2568 MWt 07/88
- Sale of TMI-1 from GPU to AmerGen 12/99
- Turbine Rotor replacements 11/01
- Main and Aux Transformers replacement 11/01
- New Reactor Head 11/03
- LRA Submitted 01/08
- Transfer license from AmerGen to Exelon 01/09
- Scheduled installation of new S/Gs (1R18) Fall 2009
- Two consecutive breaker to breaker runs 2001-2005
- Unit Capability Factor (2007 & 2008 average) 95.28%
- Current License Expires 04/19/14

GALL Consistency Commitments Confirmatory Item

GALL Consistency and Commitments

- Total Aging Management Programs – 38
 - Consistent with GALL – 24
 - Exceptions to GALL – 14
- License Renewal Commitments managed through the fleet wide Exelon Commitment tracking program which implements the guidance provided by the Nuclear Energy Institute (NEI) NEI 99-04, Revision 0, "Guidelines for Managing NRC Commitment Changes,"
- Total of 43 License Renewal Commitments
 - 38 Aging Management Programs
 - PWR Vessel Internals
 - Install new Steam Generators prior to PEO
 - Submit new Pressure-Temperature limit curves to the NRC prior to exceeding 29 EFPY and prior to PEO
 - Weld repair the Reactor Building liner prior to the PEO
 - Boral Test Coupon Surveillance for the fuel storage racks will continue through the PEO

Confirmatory Item

CI 4.3.2-1 concerns the bounding assumption of less than 0.050 ppm for reactor coolant dissolved oxygen used in fatigue calculations

- TMI-1 controls reactor coolant to less than 0.005 ppm through implementation of EPRI guidelines
- Exelon is submitting the information to the staff to close this issue

Topic of Interest

Recent LR Industry Issues

Recent LR Industry Issues


Fatigue

- Environmentally-Assisted Fatigue has been satisfactorily evaluated
- No simplified analysis methods were used

Station Blackout

- TMI-1 LRA boundary for SBO recovery path includes the switchyard circuit breakers

TMI-1 Switchyard




Topic of Interest


Reactor Building Liner Corrosion

Issue

Past leakage and a degraded moisture barrier resulted in corrosion behind and just above the moisture barrier.



Areas of Corrosion at Moisture Barrier to Liner interface



Reactor Building Liner Corrosion

- Identified
 - Corrosion identified in 1990s and monitored and inspected per IWE Program
- Cause
 - Borated water leakage and degraded moisture barrier
- Mitigation
 - Corrected leaks and established Boric Acid Corrosion Control program
 - Inspected entire perimeter in Fall 2007
 - Measured thickness of corroded areas. Liner meets design requirements.
 - Removed old moisture barrier in 2007, cleaned, re-coated, and installed new improved moisture barrier
 - Inspect 100% of the moisture barrier every Refueling outage starting 2009
- Repair Plan
 - Weld repair prior to PEO (scheduled Fall 2009 with the Integrated Leak Rate Test)

Topic of Interest


Medium Voltage Cables

Medium Voltage Cables

ISSUE

- Periodic TMI-1 cable vault inspection results identified some cable vaults with repeat occurrences of rainwater accumulation and cable submergence
- 37 total TMI-1 cable vaults
- 8 cable vaults in scope for License Renewal Inaccessible Medium Voltage Cable aging management program
- There have been no failures of Medium Voltage Cables at TMI-1

Medium Voltage Cables



Typical Cable Vault

- Typical depth 8 to 15 feet
- Bottom of Cable Vault located 5 to 15 feet above water table
- Compartmentalized
- French drain
- Cables at varying elevations reflecting terrain & cable routes

Medium Voltage Cables

ACTIONS

- Implement semi-annual inspection
- Implement cable vault improvement initiative, including:
 - Prevent rainwater intrusion
 - Install lid gaskets
 - Improve grading/surrounding environment to prevent run-off into vaults
 - Restore/maintain French drains & drains between vaults
- Adjust frequency of inspection based on inspection results following remediation
- Perform Cable Tests prior to PEO and every 10 years per GALL

CONCLUSION

- This new Program will keep the medium voltage cables dry or infrequently submerged to effectively manage aging.

Topic of Interest

Fuel Storage Racks Containing
Boral


Fuel Storage Racks Containing Boral

Issue


The formation of blisters on Boral neutron absorber material has the potential to affect dimensional assumptions used in the criticality analysis of Region 1 type high-density spent fuel storage racks

Fuel Storage Racks Containing Boral

TMI-1 uses two types of high density storage racks:




Region 1 high-density storage racks have a water gap (flux trap) between storage cells




Region 2 high-density storage racks do not have a water gap (flux trap) between storage cells

Fuel Storage Racks Containing Boral




In PWR Region 1 storage racks, two plates of an absorber material (Boral) are located between each cell, separated by a water gap (flux trap)



Each plate of Boral absorber material is comprised of an aluminum and boron carbide powder core with aluminum cladding on each side


Fuel Storage Racks Containing Boral



The Boral absorber is contained within a pocket formed on each side of the rack cell by the stainless steel cell box wall and a stainless steel sheath

If a blister forms on the Boral but does not deform the sheathing, the analyzed flux trap water gap dimension is not affected

Fuel Storage Racks Containing Boral



If a blister forms on the Boral absorber sufficient to locally deform the sheathing, the flux trap water gap dimension can be reduced at that location

The pocket containing the Boral panel is water filled. Although water intrusion into the Boral core is the cause of corrosion that can form a blister, it is conservative to assume the blister is not water filled

Fuel Storage Racks Containing Boral

Background & Coupon Surveillance Results

- High-density fuel pool storage racks containing Boral panels were first installed at TMI-1 in 1992
- Boral coupon surveillance evaluations were performed in 1995, 1997, 1999, 2001, and 2008
- No blistering was found in coupons evaluated in 1995, 1999, or 2001
- 1997 coupon evaluation: seven small blisters found -
 - Diameter ~ 0.3”, depths between 0.01” and 0.02”
- 2008 coupon evaluation: one blister found -
 - Diameter ~ 1.0”, depth 0.058” and was water-filled
- Neutron attenuation tests show no loss of boron in the Boral and no reduction in neutron absorption capacity in any coupon, even at the location of the blister

Fuel Storage Racks Containing Boral

Issue Summary

- Blisters have been observed on TMI-1 Boral surveillance coupons
- The potential effect of blistering is bounded by the uncertainties in the analysis and is well within existing margins to the regulatory requirement for k_{eff}
- The TMI-1 Boral coupon surveillance program will continue throughout the period of extended operation

Fuel Storage Racks Containing Boral

Aging Management

- LRA credits the Water Chemistry program with aging management for loss of material due to general corrosion of the aluminum cladding of the Boral absorber
- Boral coupon surveillance program will continue throughout the period of extended operation
 - Evaluations will determine that any effect on neutron multiplication from a postulated reduction in the flux trap water gap is within the design requirement

Questions?



**Advisory Committee on Reactor Safeguards (ACRS)
License Renewal Subcommittee
Three Mile Island Nuclear Station, Unit - 1 (TMI-1)
Safety Evaluation Report (SER) with Open Items**

April 1, 2009

Jay E. Robinson, Project Manager
Office of Nuclear Reactor Regulation

Introduction

- Overview
- Section 2: Scoping and Screening Review
- License Renewal Inspections
- Section 3: Aging Management Program and Review Results
- Section 4: Time-Limited Aging Analyses (TLAAs)

Overview

- LRA Submitted by letter dated January 8, 2008
- Babcock & Wilcox (B & W) Pressurized Water Reactor (PWR), carbon steel-lined concrete (DRYAMB) containment
- 2568 MWth, 852 MWe
- Operating License DPR-050 expires April 19, 2014
- Located 10 miles southeast of Harrisburg, PA
- Unit 2 Shutdown in safe storage mode of Post Defueling Monitored Storage (PDMS)

Overview

- Safety Evaluation Report issued March, 2009
- 0 Open Items
- 1 Confirmatory Item
- 123 RAIs issued
- 43 Commitments

Overview

- Scoping and Screening Methodology Audit
 - May 19, 2008 – May 22, 2008
- Aging Management Program (AMP) Audit
 - July 14, 2008 – July 16, 2008
 - July 28, 2008 – August 1, 2008
- Regional License Renewal Inspection
 - November 17, 2008 – November 21, 2008
 - December 08, 2008 – December 12, 2008

Section 2: Structures and Components Subject to Aging Management Review

- **Section 2.1 - Scoping and Screening Methodology**
 - Based on its review of the LRA and additional information submitted as a result of Requests for Additional Information (RAIs), the staff determined that the applicant's methodology is consistent with the requirements of 10 CFR 54.4 and 54.21(a)(1)
- **Section 2.2 - Plant-Level Scoping Results**
 - Based on its review of the LRA and additional information submitted as the result of an RAI, the staff concluded the applicant identified the systems and structures within the scope of license renewal per 10 CFR 54.4(a)

Section 2: Structures and Components Subject to Aging Management Review

- **Section 2.3 – Scoping and Screening Results: Mechanical Systems**
 - The staff identified nine systems that required the applicant to revise their application to add additional components into scope
 - Examples of component types omitted included: Fuel tank for the standby diesel engine for the emergency diesel generator air start system air compressor, lube oil lines, and intake bar racks, which were subsequently added to scope and subject to an AMR
 - Based on its review of the LRA and additional information submitted as the result of RAIs, the staff concluded that the applicant identified the mechanical system components within the scope of license renewal per 10 CFR 54.4(a) and subject to an aging management review per 10 CFR 54.21(a)(1)

Section 2: Structures and Components Subject to Aging Management Review

- **Section 2.4 – Scoping and Screening Results: Structures**
 - The staff identified one component that required the applicant to revise their application to add the component into scope
 - Based on its review of the LRA and additional information submitted as the result of RAIs, the staff concluded that there were no omissions of structures or structural components from scope of license renewal per 10 CFR 54.4(a), and no omissions from AMR per 10 CFR 54.21(a)(1)

Section 2: Structures and Components Subject to Aging Management Review

- **Section 2.5 – Scoping and Screening Results: Electrical Systems/Commodity Groups**
 - Station blackout recovery path includes the complete circuits within the scope of license renewal
 - Based on its review of the LRA and additional information submitted as the result of an RAI, the staff concluded that there were no omissions of electrical systems/commodity groups from scope of license renewal per 10 CFR 54.4(a), and no omissions from AMR per 10 CFR 54.21(a)(1)

Section 2: Structures and Components Subject to Aging Management Review

- **Section 2.6 – Conclusion for Scoping and Screening**
 - Based on its review of the LRA, the onsite audit results, and additional information submitted as the result of RAIs, the staff concluded that:
 - The applicant’s scoping and screening methodology meets the requirements of 10 CFR 54.4 and 54.21(a)(1), and
 - That the applicant adequately identified those SSCs within the scope of license renewal in accordance with 10 CFR 54.4(a), and those SCs subject to an AMR in accordance with 10 CFR 54.21(a)(1)


- **Inspection Objectives**
 - Scoping of Non-Safety SSCs
 - 19 Aging Management Programs (AMPs)
- **Scoping**
 - Scoping of non-safety SSCs – generally accurate and acceptable
 - Structural and spatial interactions reviewed

- Aging Management Programs
 - Reviewed AMP program procedures and records
 - Walked down systems in plant
 - Evaluated operating experience
 - Concerns – Minimal; addressed onsite

- Item of Interest
 - Operating Experience Approach
- Inspection Conclusions
 - Scoping of non-safety SSCs and aging management programs are acceptable
 - Inspection results support a conclusion of reasonable assurance that aging effects will be managed and intended functions will be maintained.

- Current Performance
 - Licensee Response Column of Action Matrix
 - All Findings – Green
 - All Performance Indicators (PIs) - Green

License Renewal Inspections



Section 3: Aging Management Review Results

- Section 3.0 – Aging Management Programs
- Section 3.1 – Reactor Coolant System
- Section 3.2 – Engineered Safety Features
- Section 3.3 – Auxiliary Systems
- Section 3.4 – Steam and Power Conversion System
- Section 3.5 – Containments, Structures and Component Supports
- Section 3.6 – Electrical Commodity Group

- Section 3.0.3 – Aging Management Programs (AMPs)
 - 38 – AMPs
 - 7 New Programs
 - 31 Existing Programs
 - 21 consistent with GALL Report
 - 9 with enhancements
 - 1 plant specific
 - 11 with exceptions
 - 6 with both enhancements and exceptions

Groundwater Sampling

- Groundwater sampling for pH, chloride, and sulfate concentrations will be performed every 5 years during the period of extended operation.
- TMI-1 Groundwater is non-aggressive

	Acceptance Criteria	2007	2005 (Three Samples taken)
pH	>5.5	7.4	7.8/7.8/7.7
Chlorides	<500 ppm	58 ppm	57.3/42.4/65.5 ppm
Sulfates	<1500 ppm	27 ppm	44.2/53.3/48.0 ppm

Reactor Head Closure Studs

- During AMP audit, staff identified use of Dow Corning G-N lubricant for reactor head closure studs
 - Composed of 14% Molybdenum Disulfide
 - Molybdenum Disulfide may promote stress corrosion cracking
- Staff issued RAI and applicant agreed to enhance program by selecting an alternate stable lubricant that is compatible with the fastener material and the environment prior to the period of extended operation
- Staff found applicant's response to the RAI acceptable and their concern resolved

Reactor Building Liner

- Staff identified that operating experience indicated corrosion at several locations due to moisture intrusion through the moisture barrier
- Staff issued RAI and applicant committed to restore the liner to its nominal plate thickness by weld repair for previously identified corroded areas where thickness of the base metal is reduced by more than 10% of the nominal plate thickness, prior to the period of extended operation
- Applicant performed engineering evaluation and determined the intended function of the liner is currently being maintained
- Based on its review, the staff found the applicant's proposed corrective actions acceptable

Inaccessible Medium Voltage Cables Not Subject to 10 CFR 50.49 Environmental Qualification Requirements

- TMI-1 operating experience shows that inaccessible medium-voltage cables in several manholes experienced water submergence for more than a few days
- During AMP audit staff found cables submerged under water in two manholes
- Staff issued RAI for submergence certification for cables or action plan to preclude cable degradation
- Applicant will adjust frequency of inspections based on inspection results in order to keep cables from significant moisture
- Water in manholes is a generic, current operating plant issue that is being addressed during the current period of operation through the reactor oversight process in accordance with the requirements of 10 CFR Part 50

Section 3: Aging Management Review Results

- Section 3.0.3 – Aging Management Programs (AMPs)
 - Based on it's audit and review and additional information submitted as the result of RAIs, the staff concluded that the effects of aging will be managed so that intended function(s) will be maintained during the period of extended operation, per 10 CFR 54.21(a)(3)

Reduction of Neutron-Absorbing Capacity and Loss of Material due to General Corrosion

- Water Chemistry Program
 - Loss of Material due to General Corrosion
- Boral Surveillance Program
 - Reduction of Neutron-Absorbing Capacity
- Staff issued RAI and applicant responded
- Commitment to continue Boral test coupon surveillance through period of extended operation
- Staff concluded that Water Chemistry Program will adequately manage loss of material from general corrosion of Boral, and the Boral Surveillance Program will adequately manage the reduction of neutron absorption capacity aging effect for the period of extended operation

- **Section 3.7 – Conclusion**
 - Based on its review of the LRA and additional information submitted as the result of RAIs, the staff concluded that aging effects will be managed so that the intended functions will be maintained consistent with the CLB for the period of extended operation, per 10 CFR 54.21(a)(3)

Section 4: Time-Limited Aging Analysis

- 4.1 Introduction
- 4.2 Neutron Embrittlement of the Reactor Vessel and Internals
- 4.3 Metal Fatigue of Piping and Components
- 4.4 Leak-Before-Break Analysis of Primary System Piping
- 4.5 Fuel Transfer Tube Bellows Design Cycles
- 4.6 Crane Load Cycle Limits
- 4.7 Loss of Prestress in Concrete Containment Tendons
- 4.8 Environmental Qualification of Electrical Equipment

- Section 4.2 - Neutron Embrittlement of the Reactor Vessel and Internals
 - Charpy Upper-Shelf Energy for Beltline Plates and Forgings
 - Charpy Upper-Shelf Energy for Beltline Welds (Equivalent Margins Analysis)
 - Pressurized Thermal Shock Limits (RT_{PTS}) for Reactor Vessel Materials Due to Neutron Embrittlement

Section 4: Time-Limited Aging Analysis

Section 4.2 – Charpy Upper-Shelf Energy for Beltline Plates, Forgings, and Welds

Limiting Beltline Material for Plates & Forgings — Lower Shell Plate (C3251-1) Unit 1

% CU	52 EFPY Fluence 1/4T Location, n/cm²	Initial Charpy USE at 1/4T, (ft-lbs)	52 EFPY Charpy USE at 1/4T, (ft-lbs)	Acceptance Criterion per 10 CFR 50, App. G (ft-lb)
0. 11	1.153 X 10¹⁹	81	64	>50

Limiting Beltline Weld— US to LS Circ Weld * (WF-25) Unit 1

% CU	52 EFPY Fluence 1/4T Location, n/cm²	Initial Charpy USE at 1/4T, (ft-lbs)	52 EFPY Charpy USE at 1/4T, (ft-lbs)	Acceptance Criterion per 10 CFR 50, App. G (ft-lb)
0. 34	1.119 X 10¹⁹	70	41.4	EMA

* The value for US to LS Circ Weld (WF-25) is the bounding value for beltline welds

Section 4: Time-Limited Aging Analysis

Section 4.2: Pressurized Thermal Shock Limits (RT_{PTS}) for Reactor Vessel Materials Due to Neutron Embrittlement

Limiting Beltline Material for Plates & Forgings — Lower Shell Plate (C3307-1) Unit 1

% CU %Ni	52 EFPY Fluence (n/cm ²)	Initial RT_{NDT} °F	RT_{PTS} °F	Acceptance Criterion per 10 CFR 50.61, °F
0.12 0.55	1.971E+19	+1	161.8	<270°F

Limiting Beltline Weld—NB to US Circ Weld (WF-70) Unit 1

% CU %Ni	52 EFPY Fluence (n/cm ²)	Initial RT_{NDT} °F	RT_{PTS} °F	Acceptance Criterion per 10 CFR 50.61, °F
0.32 0.58	1.836E+19	-31.1	263.8	<300°F

- Section 4.3 – Metal Fatigue of Piping and Components
 - 60-year fatigue analyses were performed for the applicable high-fatigue locations of NUREG/CR-6260
 - Initial analysis indicated that 4 locations had a CUF >1.0:
 - Reactor Vessel Lower Head – Instrument Nozzle Penetration Weld
 - Reactor Vessel Outlet Nozzle
 - Pressurizer Surge Line (elbow)
 - Makeup/High Pressure Injection Nozzle
 - Further evaluation performed and final results indicated that the locations have an EAF-adjusted CUF value < 1.0
 - TMI-1 will manage fatigue of Class 1 components using the Metal Fatigue of Reactor Coolant Pressure Boundary Aging Management Program

Section 4: Time-Limited Aging Analysis


- Section 4.3.2 – Evaluation of Reactor Water Environmental Effects on Fatigue Life of Piping and Components, GSI-190
 - Confirmatory Item 4.3.2-1
 - Fen values calculated based on assumed DO (dissolved oxygen) concentration data lower than 0.05 ppm
 - Staff questioned whether 0.05 ppm DO was bounding
 - Applicant indicated that 0.05 ppm was bounding since TMI-1 historically maintained its DO levels at less than 0.005 ppm, and administrative controls are in place to maintain it at or below this level
 - Applicant submitted additional information which staff found acceptable and is in process of closing out item and revising SER

Section 4: Time-Limited Aging Analysis

- Section 4.9 – Conclusion
 - Based on its review of the LRA and additional information submitted as the result of RAIs, the staff concluded that the applicant provided an adequate list of TLAAs, per 10 CFR 54.3 and that the:
 - TLAAs will remain valid for the period of extended operation, per 10 CFR 54.21(c)(1)(i)
 - TLAAs have been projected to the end of the period of extended operation, per 10 CFR 54.21(c)(1)(ii)
 - Aging effects will be managed for the period of extended operation, per 10 CFR 54.21(c)(1)(iii)

Conclusion

- The staff's conclusion regarding the LRA for TMI-1 will be provided in the Final SER scheduled to be issued in July, 2009



U.S.NRC

United States Nuclear Regulatory Commission

Protecting People and the Environment

1 UNITED STATES OF AMERICA

2 NUCLEAR REGULATORY COMMISSION

3 + + + + +

4 ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

5 SUBCOMMITTEE ON PLANT LICENSE RENEWAL

6 + + + + +

7 WEDNESDAY, APRIL 1, 2009

8 + + + + +

9 ROCKVILLE, MD

10 The Subcommittee convened in Room T2B3 in
11 the Headquarters of the Nuclear Regulatory Commission,
12 Two White Flint North, 11545 Rockville Pike,
13 Rockville, Maryland, at 1:30 p.m., Dr John Stetkar,
14 Chair, presiding.

15 SUBCOMMITTEE MEMBERS PRESENT:

16 JOHN W. STETKAR, Chair

17 JOHN D. SIEBER

18 SAM ARMIJO

19 WILLIAM J. SHACK

20 MARIO V. BONACA

21 SAID ABDEL-KHALIK

22 CHARLES H. BROWN, JR.

23 HAROLD B. RAY

24 MICHAEL T. RYAN

25

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701