

**Official Transcript of Proceedings**  
**NUCLEAR REGULATORY COMMISSION**

Title:                   Advisory Committee on Reactor Safeguards  
                              Hope Creek License Renewal Subcommittee

Docket Number:       (n/a)

Location:               Rockville, Maryland

Date:                    Wednesday, November 3, 2010

Work Order No.:       NRC-542

Pages 1-120

**NEAL R. GROSS AND CO., INC.**  
**Court Reporters and Transcribers**  
**1323 Rhode Island Avenue, N.W.**  
**Washington, D.C. 20005**  
**(202) 234-4433**

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22

DISCLAIMER

UNITED STATES NUCLEAR REGULATORY COMMISSION'S  
ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

The contents of this transcript of the proceeding of the United States Nuclear Regulatory Commission Advisory Committee on Reactor Safeguards, as reported herein, is a record of the discussions recorded at the meeting.

This transcript has not been reviewed, corrected, and edited, and it may contain inaccuracies.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 UNITED STATES OF AMERICA

2 NUCLEAR REGULATORY COMMISSION

3 + + + + +

4 ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

5 (ACRS)

6 + + + + +

7 HOPE CREEK LICENSE RENEWAL SUBCOMMITTEE

8 + + + + +

9 WEDNESDAY

10 NOVEMBER 3, 2010

11 + + + + +

12 ROCKVILLE, MARYLAND

13 + + + + +

14 The Subcommittee met, at the Nuclear  
15 Regulatory Commission, Two White Flint North, Room  
16 T2B1, 11545 Rockville Pike, Rockville, Maryland, at  
17 1:30 p.m., William J. Shack, Chairman, presiding.

18 SUBCOMMITTEE MEMBERS:

19 WILLIAM J. SHACK, Chairman

20 J. SAM ARMIJO, Member

21 JOY REMPE, Member

22 JOHN D. SIEBER, Member

23 JOHN W. STETKAR, Member

24

25

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25

CONSULTANT:

JOHN J. BARTON

DESIGNATED FEDERAL OFFICIAL:

MICHAEL BENSON

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

Call to Order and Opening Remarks William Shack Chairman		4
Staff Introduction Brian Holian, NRR		5
PSEG Nuclear, LLC - Hope Creek Generating Station		8
Paul Davison, PSEG	8, 17, 18, 62, 80, 90	
Greg Sosson, PSEG	9, 48, 52, 56, 58, 62 66, 68, 74, 76, 84	
Randy Schmidt, PSEG		15, 18, 90
Andy Huk, PSEG		22, 29
James Stavely, PSEG	18, 31, 33, 55, 58, 66 77, 79, 86	
James Melchionna, PSEG		33, 38, 46
Bill Kopchick, PSEG		26, 40
Tom Quintenz, PSEG		32
Ed Keating, PSEG		37
George Seibold, PSEG	46, 47, 52, 55, 56, 65 67, 74, 78, 81	
Tom Roberts, PSEG		73
Paul Cervenka, PSEG		84, 85
Peter Tamburro, PSEG		92
NRC Staff		94
Brian Holian, NRR		94, 106, 111
Bennett Brady, NRR	99, 106, 114, 118	
Michael Modes, Region I		104
Cliff Douth		110
Ray Mathew		113
Allen Hiser		117, 119

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

P-R-O-C-E-E-D-I-N-G-S

1:29 p.m

CHAIRMAN SHACK: (Presiding) The meeting will now come to order.

This is a meeting of the Plant License Renewal Subcommittee. I am William Shack, Chairman of the Subcommittee meeting.

ACRS members in attendance are Jack Sieber, John Stetkar, Sam Armijo, and Joy Rempe. I got it right.

(Laughter.)

And our consultant, John Barton.

Michael Benson of the ACRS staff is the Designated Federal Official for this meeting.

The purpose of the Subcommittee meeting is to review the license renewal application and associated SER with open items for Hope Creek. We will hear presentations from the NRC staff and PSEG Nuclear, LLC.

We have received no written comments or requests for time to make oral statements from members of the public regarding today's meeting. The entire meeting will be open to public attendance.

The Subcommittee will gather information, analyze relevant issues and facts, and formulate the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 positions and actions as appropriate for deliberation  
2 by the full Committee.

3 The rules for participation in today's  
4 meeting have been announced as part of this meeting  
5 previously published in The Federal Register.

6 A transcript of the meeting is being kept  
7 and will be made available as stated in The Federal  
8 Register notice. Therefore, we request that  
9 participants in this meeting use the microphones  
10 located throughout the meeting room when addressing  
11 the Subcommittee. The participants should first  
12 identify themselves and speak with sufficient clarity  
13 and volume so they may be readily heard.

14 We will now proceed with the meeting. I  
15 call upon Brian Holian of the NRR's Division of  
16 License Renewal to begin.

17 Brian?

18 MR. HOLIAN: Good afternoon, Chairman and  
19 Committee.

20 We are pleased to be here today for the  
21 Hope Creek Subcommittee on License Renewal  
22 Application.

23 I am the Division Director of License  
24 Renewal. The agenda for today is I will just do brief  
25 opening comments and then turn it over to the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 applicant for their presentation, and following a  
2 break, the NRC staff will give their perspective on  
3 the open and confirmatory items and the staff review.

4 To my left is Ms. Bennett Brady. She is  
5 the Senior Project Manager on Hope Creek, and she will  
6 be doing the bulk of the presentation later.

7 To her left is Bo Pfam. He is in charge  
8 of the Branch that has both Salem and Hope Creek in-  
9 house, among other applications.

10 Behind them, and he will be speaking  
11 later, is Mike Modes. He has been to the Committee  
12 several times. He is a Senior Reactor Inspector from  
13 Region I, who will be giving inspection perspectives  
14 later on, and his Branch Chief is also in the  
15 audience, Mr. Rich Conte, from the Division of Reactor  
16 Safety, the Branch Chief.

17 Salem/Hope Creek application came in as a  
18 common application. We did do a common environmental  
19 review. We don't talk about that too much at the  
20 ACRS, but that environmental DSEIS is out. We have a  
21 public meeting in the area this month out at  
22 Salem/Hope Creek for those issues.

23 We are here this month to talk about Hope  
24 Creek, and the Subcommittee will be getting the Salem  
25 SER from the staff maybe this week. Yes, this Friday

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 I believe we will be sending that out. That has got a  
2 few other open items and some interesting issues there  
3 also.

4 On Hope Creek, we will be talking, and the  
5 applicant will be talking, first about buried piping.

6 That has been a common issue that we have been  
7 bringing all plants up to an improved aging management  
8 program, as we have identified that in GALL Rev 2. So  
9 that is a similar item that the Committee has seen  
10 before.

11 Also, medium-voltage cables, a similar  
12 issue that we will bring in the in-house applicants up  
13 to the kind of new standards for aging management.  
14 And they have got a confirmatory item on metal  
15 fatigue. So, you will hear that.

16 You will also see some slides from the  
17 applicant that they appropriately have brought in with  
18 some recent operating experience out of the refueling  
19 outage that is ongoing now. We had a protracted  
20 review with some refueling water leakage that the  
21 Committee is seeing on several plants. And where is  
22 that water going? What is it doing inside the plant?  
23 They've got some new news, even from the recent  
24 refueling outage, on that issue.

25 So, we look forward to a good presentation

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 today. And with that, I will turn it over to Mr. Paul  
2 Davison, Vice President of Ops Support at the site.

3 MR. DAVISON: Thank you very much, Mr.  
4 Holian.

5 And Good afternoon. My name is Paul  
6 Davison. I'm the Vice President of Operations Support  
7 for PSEG Nuclear. I'm also the executive sponsor for  
8 license renewal at the site.

9 Before we begin today's presentation, I  
10 would like to introduce the three other presenters I  
11 have with me at the table. To my right is Jim  
12 Stavely. He's the PSEG Nuclear License Renewal  
13 Manager for Hope Creek. Jim has 25 years of  
14 experience in the industry and 15 specifically with  
15 PSEG.

16 To Jim's right is Mr. Greg Sosson, PSEG  
17 Nuclear Engineering Services Director. Greg has 23  
18 years of experience, six with PSEG.

19 And to Greg's right, we have Jim  
20 Melchionna, our Corporate Buried Pipe Program Manager.

21 Jim has 28 years of nuclear experience, the last 18  
22 with PSEG.

23 In addition, behind you, I would like to  
24 have three other introductions. I would like to  
25 introduce Mr. Tom Joyce, the President and Chief

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Nuclear Officer for PSEG Nuclear; Bob Braun, the  
2 Senior Vice President of Nuclear Operations, and John  
3 Perry, the Site Vice President for Hope Creek.

4 Thank you.

5 Slide 2 shows today's presentation agenda.

6 We will begin with a description, as Mr. Holian  
7 mentioned, of the site and an overview of the Hope  
8 Creek operating history, followed by an overview of  
9 the license renewal application.

10 We will then continue with discussions on  
11 our two SER confirmatory items, one open item, and one  
12 topic of interest regarding aging management of Hope  
13 Creek's containment structure.

14 We have developed a comprehensive, high-  
15 quality license renewal application and a robust aging  
16 management program that will ensure the continued safe  
17 operation of Hope Creek Generating Station, and we  
18 certainly appreciate the opportunity to make this  
19 presentation and look forward to answering any  
20 questions you may have.

21 I will now turn it over to Greg Sosson to  
22 begin the presentation.

23 Greg?

24 MR. SOSSON: Thank you, Paul.

25 Good afternoon. My name is Greg Sosson,

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 and I am the Engineering Services Director for PSEG  
2 Nuclear.

3 Mr. Chairman and Subcommittee members, as  
4 shown on this slide, Hope Creek and the two Salem  
5 units share a common site on the New Jersey side of  
6 the Delaware River in southern New Jersey. They share  
7 a common protected area.

8 Hope Creek is a General Electric BWR owned  
9 and operated by PSEG Nuclear. Its reactor building is  
10 in the middle of this slide. A second Hope Creek unit  
11 was planned, but was not completed. You can see the  
12 planned location for the reactor building to the right  
13 of the Hope Creek build.

14 The Hope Creek service water intake  
15 structure is on the top of the slide. The Hope Creek  
16 cooling tower is to the right, and the Hope Creek  
17 switchyard is in the middle of the slide.

18 Next slide, please.

19 This slide shows some of the significant  
20 highlights in the Hope Creek operating history. Hope  
21 Creek was initially licensed to 3293 megawatts  
22 thermal. Following a successful startup test program,  
23 commercial operation began on December 20th, 1986.

24 In 1993, hydrogen water chemistry was  
25 implemented to enhance our protection of the reactor

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 coolant system materials.

2 Measurement uncertainty recapture was  
3 completed in 2001, adding 1.4 percent thermal power,  
4 to 3339 megawatts thermal. This change involved the  
5 installation of ultrasonic flow measurement technology  
6 for the feedwater flow system.

7 In 2004, the generator step-up  
8 transformers and the low-pressure turbine rotors were  
9 replaced as part of the preparations for an extended  
10 power uprate.

11 As part of long-term asset management, the  
12 bravo recirculation pump rotating assembly was  
13 replaced in 2006. Also in 2006, we completed our  
14 initial noble metals treatment as part of our  
15 continuing efforts to protect the reactor vessel and  
16 its internals.

17 The high-pressure turbine rotor was  
18 replaced in 2007. It is the last major modification  
19 necessary to support the extended power uprate.

20 Also in 2007, we replaced the alpha  
21 recirculation pump rotating assembly as part of long-  
22 term asset management.

23 An extended power uprate of 15 percent, to  
24 3840 megawatts thermal, was completed in 2008.

25 Hope Creek is on 18-month operating

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 cycles. Our current unit capacity factor is 92.3  
2 percent.

3 Our license renewal application was  
4 submitted on August 18th, 2009, and our current  
5 license expires April 11th, 2026.

6 I will now turn it over to Jim Stavely,  
7 who will present to you the highlights of our license  
8 renewal application.

9 MEMBER SIEBER: Before you do that, Hope  
10 Creek is a relatively late model, a late-licensed  
11 plant, 1986. So you have Mark I containment?

12 MR. SOSSON: That's correct.

13 MEMBER SIEBER: And it's also relatively  
14 high-powered compared to other plants with Mark I  
15 containments. Does that pose any particular aging  
16 management problems for that plant that differ from  
17 older and smaller output plants?

18 MR. SOSSON: Related to the size of the  
19 vessel with respect to the Mark I containment, not  
20 particularly. There are other reactors that are in  
21 similar vintage like that, but with respect to aging  
22 management, it doesn't present any challenges. And I  
23 will be talking about the Mark I containment later in  
24 this presentation.

25 MEMBER SIEBER: Are you also going to

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 address aging management of the steam separator inside  
2 the reactor vessel?

3 MR. SOSSON: As part of extended power  
4 uprate, we did do extensive inspections of the dryer  
5 and separator. Since the extended power uprate, we  
6 have done follow-up inspections and have seen no  
7 degradation related to the EPU or aging of the steam  
8 dryer.

9 MEMBER SIEBER: Right. As we go through  
10 the presentation, I would like to hear a few of the  
11 details about what you have found so far, what  
12 degradation you have had, what repairs you have had to  
13 make, and what your plans are for the future.

14 MR. SOSSON: With respect to the reactor  
15 internals, I will ask Randy Schmidt to provide --

16 MEMBER SIEBER: Yes, when it comes up in  
17 the agenda.

18 MR. SOSSON: Yes, it doesn't really come  
19 up. So, we can address it right now.

20 MEMBER SIEBER: Okay.

21 MR. SOSSON: Now is probably the best time  
22 to talk about it.

23 MEMBER ARMIJO: While you are doing that,  
24 I notice you probably have the largest fraction of  
25 your operating time has been with hydrogen water

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 chemistry, which addresses the protection of piping  
2 and internals. So, if you could incorporate whether  
3 that has really afforded you some benefit or not --

4 MEMBER SIEBER: Yes, noble metals was  
5 introduced pretty late.

6 MEMBER ARMIJO: But hydrogen was like six  
7 or seven years after the start of the plant.

8 MR. SOSSON: Yes, specifically, with  
9 hydrogen water chemistry, we did introduce that fairly  
10 early on, in accordance with the VIP recommendations.

11 MEMBER ARMIJO: Okay.

12 MR. SOSSON: So, we have been taking  
13 advantage of that for some time now. Noble metals  
14 first went in in 2006.

15 MR. BARTON: But your application on  
16 hydrogen water chemistry only talks about protection  
17 of recirc piping. Are you injecting at the rate where  
18 you were also protecting some lower reactor internals  
19 early on, before you put on noble metals?

20 MR. SOSSON: Yes.

21 MR. BARTON: Because your application  
22 doesn't address that. It just says you are protecting  
23 the piping.

24 MR. SOSSON: Okay, I'm going to ask Randy  
25 Schmidt to address this question.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 MR. SCHMIDT: Good afternoon. Randy  
2 Schmidt, PSEG Nuclear.

3 When we injected hydrogen initially, the  
4 purpose was to protect the recirc piping only. We do  
5 get some benefit to the internals, but we were not  
6 fully mitigated in the internals. Therefore, we  
7 injected noble metals at a later time to get the full  
8 protection of the reactor internals.

9 MEMBER ARMIJO: From the standpoint of  
10 license renewal, the question I have is, how effective  
11 has that been? Have you experienced IGSCC in your  
12 recirc piping? Have you experienced IASCC on your  
13 core internals? That sort of stuff, you know, is it  
14 really effective?

15 MR. SCHMIDT: We have not experienced any  
16 IGSCC of reactor coolant system piping. We have seen  
17 IGSCC and similar metal welds attached to the reactor  
18 vessel. We have experienced some, very little, minor  
19 IGSCC in our internals.

20 CHAIRMAN SHACK: And you have a core  
21 shroud that is in very good shape, I mean as these  
22 things go, when you measure your cracks in inches.

23 MR. SCHMIDT: Right. Our core shroud has  
24 six indications. Five are less than 2 inches; one is  
25 4.3 inches.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1                   MEMBER ARMIJO:    And you haven't had to  
2                   install any clamps or any of those --

3                   MR. SCHMIDT:       No, no repairs were  
4                   necessary.

5                   MEMBER ARMIJO:    Okay.

6                   CHAIRMAN SHACK:    I was curious, I mean you  
7                   do have the corrosion-resistant cladding. You have  
8                   solution heat-treated. You have done MSIP. You have  
9                   hydrogen. And yet, it says, "The Hope Creek ISI  
10                  Program identifies 386 augmented components that are  
11                  inspected in accordance with GL-8801." So, even after  
12                  all that, you still have 386 components left? What  
13                  are those? Mostly the attachment welds?

14                  MR. SCHMIDT:    We will have to get back to  
15                  you on that.

16                  CHAIRMAN SHACK:    Yes, okay.

17                  MR. SCHMIDT:    Did you want to talk about  
18                  the steam dryer as well right now?

19                  MEMBER SIEBER:    Yes, that would be good.

20                  MR. SCHMIDT:    Okay, on the steam dryer, we  
21                  have not had to make any repairs. Right now, we have  
22                  11 indications. Nine are due to IGSCC. One is a  
23                  freighter crack on a bracket weld from initial  
24                  welding, and one was caused by a mishandling event  
25                  early in our operation. So, that is our full extent,

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 11.

2 So, we do not have any indications due to  
3 fatigue issues.

4 MEMBER SIEBER: Maybe as a test of my  
5 memory, when you did the power uprate, you did agree  
6 to some kind of vibration monitoring. How did that  
7 work out?

8 MR. DAVISON: Well, I can address that.  
9 In our EPU application, our start-up test program  
10 addressed several issues. Randy just talked about the  
11 continued results or clean results of not finding  
12 indication on our dryer and the subsequent refuel  
13 outages since we operated the unit.

14 As part of the test program, we did flow-  
15 induced vibration monitoring as well as the acoustic  
16 sensing, if you recall our discussion --

17 MEMBER SIEBER: Right.

18 MR. DAVISON: -- around the steam line  
19 flows.

20 MEMBER SIEBER: Yes, that was just a few  
21 years ago.

22 MR. DAVISON: Correct, roughly three years  
23 ago.

24 We did not see any anomalies and had no  
25 specific hold points or violations of our criteria as

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 we went through our start-up program. We did make  
2 some minor adjustments, but based on our start-up test  
3 program, we did not see anything that was anomalous  
4 that would indicate any kind of pulsations back to the  
5 dryer or the vessel itself.

6 CHAIRMAN SHACK: But you have been finding  
7 occasional stress corrosion cracks, and you just had  
8 one in 2009 in the steam dryer.

9 MR. SCHMIDT: Randy Schmidt, PSEG Nuclear.  
10 Yes, that is correct. We did find an  
11 IGSCC flaw in 2009.

12 CHAIRMAN SHACK: But, I mean, you have had  
13 a history of a crack showing up every once in a while,  
14 IGSCC. I mean the good news is there is no fatigue  
15 cracks.

16 MR. SCHMIDT: Right. My own opinion is  
17 that, as the inspectors do a better job inspecting,  
18 they find these cracks and they have probably been  
19 there all along.

20 MR. DAVISON: Now we will turn it over to  
21 Jim Stavely, who will discuss the highlights of our  
22 license renewal application.

23 MR. STAVELY: Thank you.

24 Good afternoon. My name is Jim Stavely.  
25 I'm Hope Creek License Renewal Manager.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 My portion of the presentation covers the  
2 highlights of our application, including aging  
3 management programs, commitments, confirmatory items,  
4 and open items.

5 Next slide, please.

6 Preparing the application, we used  
7 industry and NRC guidance with the goal of making the  
8 application as consistent as possible with GALL, and  
9 we believe that we were successful.

10 There are 47 aging management programs, 33  
11 existing programs and 14 new programs, that were  
12 developed for the application. Sixteen of the  
13 existing programs required no changes to align with  
14 GALL. Seventeen of the existing programs required  
15 enhancements to align with GALL. Seven of these 33  
16 programs had exceptions. Only one of the 14 new  
17 programs had an exception.

18 The PSEG Nuclear program managers are  
19 fully cognizant of the content and the importance of  
20 these programs with relation to license renewal.

21 Next slide, please.

22 There are 53 license renewal commitments.  
23 These commitments are managed under an existing  
24 process consistent with NEI 99-04, Revision 0.

25 Commitments are tracked in the SAP

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 database system. SAP is the data foundation for many  
2 of our site processes, including the corrective action  
3 program.

4 Implementing documents, including  
5 procedures and work orders, are being annotated with  
6 references to ensure that commitments are maintained.

7 PSEG Nuclear is in the process of implementing many  
8 of the enhancements as well as the new programs.

9 Station and corporate positions are being  
10 created to support commitment implementation. In  
11 addition to this primary function, these positions  
12 will ensure that PSEG Nuclear maintains current with  
13 the industry OE with respect to aging management.

14 Next slide, please.

15 There are two confirmatory items. The  
16 first confirmatory item involves inaccessible power  
17 cables. Recent industry operating experience  
18 influenced some changes to this program. Low-voltage  
19 cables were added to the program.

20 We changed the maximum cable testing  
21 frequency from ten years to six years. The maximum  
22 frequency for inspection of cable vaults and manholes  
23 for water was changed from two years to one year.

24 We have submitted this information, which  
25 we believe will satisfy the staff's concerns. Our

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1       submittal is currently under staff review.

2                   MEMBER SIEBER:     Do your manholes have  
3       level detectors and automatic pumpout?

4                   MR. STAVELY:     No, there are no level  
5       detectors in the manholes, and there is no automatic  
6       de-watering system.

7                   MEMBER SIEBER:     So, somebody has to look  
8       in there to --

9                   MR. STAVELY:     Yes.     Right now, on the  
10      service water vaults, we are performing manual de-  
11      watering.

12                   MEMBER SIEBER:     Okay.

13                   MR. BARTON:     What is your frequency of  
14      looking at those vaults?

15                   MR. STAVELY:     What I would like to do is  
16      introduce our system manager for the vaults, and he  
17      can give you some additional information.     So, Mr.  
18      Andy Huk.

19                   MEMBER SIEBER:     But your commitment, I  
20      think you said, was only you are only required to  
21      inspect once a year?

22                   MR. STAVELY:     True, but we adjust.     That  
23      is the maximum frequency.     Our intent is to maintain  
24      these cables dry.     Right now, we are working through a  
25      systematic action plan to get to that state.     Andy can

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 give you some more information, but the maximum  
2 frequency is once a year.

3 MEMBER SIEBER: Okay, and none of your  
4 cables are qualified for underwater services, right?

5 MR. STAVELY: They are not qualified to  
6 that extent. They are high-quality cables, which Andy  
7 can explain, but not qualified --

8 MEMBER SIEBER: Yes, I've heard that  
9 expression before.

10 MR. STAVELY: Yes. So, we will not use  
11 that.

12 MR. HUK: Andy Huk, PSEG Nuclear.

13 Just to provide additional detail, we are  
14 doing weekly monitoring of our cable vaults. We are  
15 finding water on a weekly basis. That has been the  
16 study phase of our project, where we will now move  
17 forward, do additional sealing as required, and  
18 possibly putting in an automatic draining system,  
19 depending on the results of our sealing. So, the end  
20 result will be dry cable, but we are still working  
21 through that process.

22 MEMBER SIEBER: Well, you are doing it  
23 temporarily on a weekly basis, but I am sure you would  
24 prefer to have more time. Do you have any thoughts  
25 about extending the interval between inspections based

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 on, for example, groundwater levels, rainfall, or  
2 anything like that?

3 MR. HUK: We would extend, only extend  
4 that inspection frequency if we continually found no  
5 water or dry cables each time.

6 MEMBER SIEBER: That is coming from  
7 someplace.

8 MR. HUK: So, to answer your question,  
9 part of this weekly pumping we can correlate water  
10 levels within the vaults with rainwater and  
11 groundwater. So, that has all been part of the study.  
12 So, we will use that information --

13 MEMBER SIEBER: So you are looking at  
14 that?

15 MR. HUK: Yes.

16 MEMBER SIEBER: Okay.

17 MR. HUK: Absolutely.

18 MEMBER SIEBER: Okay. Thank you.

19 MEMBER STETKAR: Andy or Jim, I hate to  
20 bring this up, but I almost feel compelled on this one  
21 because, quite honestly, it sounds like you have had  
22 much more problems with water in cable ducts than most  
23 of the applications that certainly we have looked at  
24 in the last two or three years anyway.

25 And I am curious why you are not more

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 aggressive at doing something to solve the problem,  
2 rather than just simply monitoring it and pumping the  
3 water out when it is in there. Why aren't you  
4 aggressively trying to keep the water out or  
5 automatically pumping it dry?

6 And let me give you a little bit of my  
7 unease. Part of the staff's reports, I noticed that  
8 in June of 2009 you found submerged cables in two  
9 manholes for the C service water train, and you  
10 initiated a corrective action report to go examine the  
11 other vaults because, you know, they are in a similar  
12 location, you kind of expected to find water there.

13 And indeed, when you finally got around to  
14 looking in the A vaults in September, three or four  
15 months later, you found submerged cables there. And  
16 then, when you finally got around to looking at the B  
17 and D vaults in November, two more months later, you  
18 sort of found water there, too.

19 I would have understood this sort of -- I  
20 don't know what sort of approach -- if this had been  
21 1980, but this was 2009. This has been an issue now  
22 since the Generic Letter of 2007-01. The industry is  
23 aware of it. The staff is aware of it.

24 And I see, "Well, we are going to put it  
25 in our corrective action program; we are going to

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 think about adjusting our frequency of inspections  
2 based on how frequently we find water in there and  
3 have to pump them down again."

4 Why don't you fix the problem? Why don't  
5 you keep the water from coming in there or pump it  
6 out? Keep the cables dry?

7 MR. STAVELY: I think Andy Huk can provide  
8 a little bit more information in terms of the timing  
9 since we found the first vault with water in the  
10 vault, as to what happened with the other ones and  
11 what our plan is.

12 So, Andy, can you provide some more --

13 MR. HUK: Yes, just some additional  
14 information. The service water vaults are not easily  
15 accessible. So, they have 60-ton concrete blocks as  
16 lids.

17 So, our first step was to do a  
18 modification of the manholes to support frequent  
19 inspections. When we did that, we did not expect that  
20 weekly pumping would not be sufficient. We  
21 anticipated a lot less water ingress into the  
22 manholes.

23 Based on our results as far as having the  
24 weekly inspections not be adequate, we went back to  
25 the design process to say, hey, look, we need to do,

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 like you said; let's prevent the water from coming in.

2 So, that is what we are doing.

3 The next step will be boroscope  
4 inspections and additional sealing, because, ideally,  
5 stopping the water from coming in to begin with is the  
6 ideal solution, which just takes an additional level  
7 of effort.

8 Just to add in terms of timeline, we only  
9 can enter the vaults during service water pump  
10 outages.

11 MR. DAVISON: Andy, if I could ask --

12 MR. HUK: Sure.

13 MR. DAVISON: -- Mr. Bill Kopchick -- he  
14 is an SRO at the station -- to talk about the  
15 complications of getting access to those vaults?

16 MR. KOPCHICK: Good afternoon. Bill  
17 Kopchick, Senior Reactor Operator from 1998 to 2000 at  
18 the Hope Regenerating Station, PSEG Nuclear.

19 Yes, sir, understand very clearly the need  
20 to get into the vaults, and we are focused on that.  
21 As Andy said, it is an evolution to get in. The vault  
22 lids had not been lifted, and it did require some  
23 design changes to make sure they could be lifted  
24 safely.

25 The weight of the vault lids is extensive,

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 and it also requires entry into a 30-day LCO, which we  
2 go through our work management process to make happen  
3 and coordinate.

4 So, really, from the Station's  
5 perspective, the ease to get in there, to really  
6 understand what the intrusion of water is, we  
7 ultimately did a design change, as Andy mentioned, to  
8 get a hole or an access port on top of these heavy  
9 vault lids.

10 Once we in Engineering are able to say  
11 exactly what the source of the water is, using a  
12 least-invasive process to stop the ingress of water,  
13 we may proceed on to actually putting in a de-watering  
14 system, which in and of itself also may have some  
15 concerns from an environmental perspective, which we  
16 have to take into consideration.

17 MEMBER STETKAR: Can I ask you a couple,  
18 while you're up there? From what you said, it sounds  
19 like you're not entirely sure what the source of the  
20 water is. Do you know, is it infiltration from storms  
21 or is it groundwater? Do you know?

22 MR. KOPCHICK: I would say it's  
23 infiltration from storms. The sampling wouldn't  
24 indicate that what we have is like a salt intrusion  
25 from the river or any brackish. So, it is --

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1                   MEMBER STETKAR:    So you are not finding  
2                   that or are you?

3                   MR.    KOPCHICK:        We are not finding  
4                   saltwater intrusion from the Delaware River.

5                   So, Andy has actually correlated the sump  
6                   levels that we have found or the vault levels that we  
7                   have found compared to rainfall over the previous  
8                   weeks, which makes us confident that we understand the  
9                   design to be either a repair to conduit, i.e., plug  
10                  those that aren't used, or (b) there are transition  
11                  pieces that go into the vault which we could repair,  
12                  and those would be the least impactful or intrusive  
13                  efforts, which are simply stop it.    And the last  
14                  effort that we would go forth is to create a pumping  
15                  system and ensure that water is disposed of  
16                  appropriately.

17                  MEMBER STETKAR:    And probably, you know,  
18                  from what I read -- I just want to make sure I  
19                  understand a bit of the problem also -- it sounded  
20                  like at least the cable ducts and the vaults and the  
21                  manholes on the service water side of the plant were  
22                  originally designed to drain to the manholes.    They  
23                  were the low points, at least what I understood from  
24                  what I have read.    And the original design may have  
25                  called for sump pumps, but they were never installed.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1           Is that the design on that side; does  
2 everything slope to low points that are accessible for  
3 either inspection, if you are just going to follow  
4 through on inspection, or for the installation of sump  
5 pumps, if you are going to do an automatic de-  
6 watering?

7           MR. HUK: That is correct.

8           MEMBER STETKAR: Okay.

9           MR. HUK: Yes.

10          MEMBER STETKAR: On the other side of the  
11 plant, there are a number of cable ducts that contain  
12 in-scope cables for station blackout mitigation. I am  
13 assuming they are from the switchyard, or wherever.

14          And from what I was reading there, it  
15 almost sounded like the accessible points for either,  
16 again, inspection or de-watering, may not necessarily  
17 be the low points in those runs. Is that the case or  
18 did I read something wrong? It sounded like there  
19 seemed to be some uncertainty about saying there could  
20 be water trapped between inspection points.

21          MR. HUK: That is correct. So, there are  
22 sections of cable that go in duct banks below the  
23 elevation of the manholes for certain sections.

24          MEMBER STETKAR: Okay. Now I will ask the  
25 question that I have finally led you into, of course.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 How does your inspection program assure that those  
2 cables in those low points that you can't inspect are  
3 dry?

4 MR. HUK: Well, we assure the future  
5 operation of those cables through electrical testing.

6 That is why we have the complementary inspect for  
7 water and minimize it to the extent practical.

8 Then, the second part of our program is to  
9 monitor it through electrical testing to ensure that  
10 the cables are suitable for operation.

11 MEMBER STETKAR: And what is your  
12 commitments on testing frequencies for the cables?

13 MR. HUK: We are testing with a maximum  
14 frequency of every six years. Currently, we are  
15 testing every time we take the transformer out of  
16 service, every 36 months, and we will adjust the  
17 frequency as required to ensure that the cables are  
18 acceptable for use. But the six years is the  
19 backdrop, the most infrequent we would do.

20 MEMBER STETKAR: And what kind of test are  
21 you doing?

22 MR. HUK: We are completing tan delta  
23 testing at this time.

24 MEMBER STETKAR: Okay.

25 MR. STAVELY: Thank you.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701



1                   MEMBER STETKAR: This is an ongoing -- I  
2 mean, well, I will ask the staff, when you come up,  
3 about how this dovetails between current licensing  
4 basis and ongoing stuff for license renewal.

5                   MR. STAVELY: Thank you.

6                   The second confirmatory item is associated  
7 with the selection of locations for environmentally-  
8 assisted fatigue calculations. The staff had some  
9 questions concerning the selection and its consistency  
10 with NUREG-6260, application of NUREG-5999, and our  
11 fatigue curves for selection of the power plant  
12 components.

13                   We are confirming that the limiting  
14 locations selected for NUREG-6260 are bounding when  
15 compared to other plant-specific locations. We  
16 believe our submittal will satisfy the staff's  
17 concerns. The submittal will be submitted no later  
18 than November 15th.

19                   CHAIRMAN SHACK: How do you approach that?

20                   I mean one of the pieces, when you did the fatigue  
21 analysis first, the guys just used enough conservatism  
22 to get themselves down below one. If I actually rank  
23 those cumulative usage factors, I mean I don't have  
24 any real notion that I have ranked them actually in  
25 order of severity, just the degree of conservatism the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1       guy happened to use when he did the analysis.

2                   MR. STAVELY:     I would like to ask Tom  
3       Quintenz to respond to that question.

4                   MR. QUINTENZ:   Tom Quintenz.  I'm with the  
5       license renewal team.

6                   The process that we used is we went back  
7       to every stress report to determine what the maximum  
8       values were relative to the calculated CUFs and  
9       determined the points that would be bounding relative  
10      to --

11                  CHAIRMAN SHACK:   Yes, but that may only  
12      show you one guy did more conservatism in his  
13      calculation than the other guy did.  I mean all he was  
14      trying to do was to get down below one.  You know, he  
15      wasn't really trying to do a realistic calculation.

16                  MR. QUINTENZ:     Well, once we use the  
17      maximum values, then we go and we would, in one case  
18      in particular, perform an NB-3200 analysis to look at  
19      that particular location in order to assess the  
20      environmental effects.

21                  CHAIRMAN SHACK:   Yes, but you have picked  
22      that location as the worst.

23                  MR. QUINTENZ:     Right.

24                  CHAIRMAN SHACK:   And you know that on the  
25      old stress report, but what is your real degree of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 confidence that that is, in fact, the worst location  
2 or just the least conservative calculation?

3 MR. QUINTENZ: Well, you're right, it is  
4 all based on the design basis calcs. That is what we  
5 used to determine what the limiting locations were.

6 CHAIRMAN SHACK: Okay. If that's what you  
7 used, that's what you used.

8 MR. STAVELY: Thank you, Tom.

9 The open item involves buried piping.  
10 Since the writing of the draft SER, we have developed  
11 an approach that should close this open item. We have  
12 submitted our resolution. We believe it will satisfy  
13 the staff's concerns. Our submittal is currently  
14 under staff review.

15 I will now turn the presentation over to  
16 Jim Melchionna, who will discuss our buried piping  
17 program and the associated open item.

18 MR. MELCHIONNA: Thanks, Jim.

19 My name is Jim Melchionna. I am a  
20 Corporate Buried Piping Program Engineer at PSEG  
21 Nuclear.

22 Next slide, please.

23 The existing Buried Pipe Program  
24 encompasses all the buried piping systems at Hope  
25 Creek, three of which are in-scope for license

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 renewal. This includes the condensate storage and  
2 transfer system, the fire protection system, and the  
3 service water systems.

4 The Buried Pipe Program has a risk ranking  
5 methodology that has risk-ranked all buried pipe  
6 segments according to their relative susceptibility  
7 and their consequence of failure. This is based on  
8 the National Association of Corrosion Engineers, also  
9 known as NACE, and EPRI guidance.

10 Susceptibility factors of the piping  
11 include cathodic protection, coating, physical  
12 considerations, materials, and corrosion parameters.  
13 The consequence-of-failure factors account for  
14 parameters such as whether the piping contains  
15 radiological or EPA-sensitive fluids, power  
16 production, or plant safety.

17 Currently, there are approximately 6,000  
18 individually risk-ranked segments in the Buried Pipe  
19 Program database.

20 Based upon the risk ranking, inspections  
21 are scheduled to investigate the condition of the  
22 buried piping. Any deficiencies identified during  
23 excavations and inspections are entered into the  
24 corrective action program. For the deficiencies  
25 assessed to be adverse to quality, the cause of the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 condition is determined and corrective actions are  
2 developed.

3 Extent-of-condition evaluations are  
4 performed and the need for additional inspections is  
5 evaluated, taking into account such things as similar  
6 configurations, environments, and operating  
7 experience.

8 We also review industry operating  
9 experience and enter that into our corrective action  
10 program. It is reviewed for applicability by the Hope  
11 Creek Buried Pipe Program Engineer.

12 In response to industry OE, the Nuclear  
13 Energy Institute, also known as NEI, established an  
14 industry initiative on buried piping. PSEG is  
15 participating in the industry initiative, and we are  
16 currently ahead of schedule in implementing important  
17 elements and attributes of that initiative.

18 We also participate in industry peer  
19 groups such as the Electric Power Institute's Buried  
20 Pipe Integrity Group and the National Association for  
21 Corrosion Engineers. I am on the Advisory Committee  
22 of the EPRI Buried Pipe Integrity Group, as well as I  
23 am a member of NACE.

24 Next slide, please.

25 CHAIRMAN SHACK: Just a question on that.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 One of the curious things is the Buried Pipe Program  
2 focuses on the external pipe, and it inspects the  
3 external pipe. If I look at the open cycle cooling  
4 water, they always inspect the inside of the pipe.

5 MR. MELCHIONNA: That is correct.

6 CHAIRMAN SHACK: Why don't I do some  
7 internal inspections on these systems, too?

8 MR. MELCHIONNA: And "these systems"  
9 meaning?

10 CHAIRMAN SHACK: The buried pipe systems  
11 that --

12 MR. MELCHIONNA: The buried pipe systems  
13 in general is what you are speaking to?

14 CHAIRMAN SHACK: Yes.

15 MR. MELCHIONNA: Well, the majority of  
16 that piping is fairly non-corrosive for the most part  
17 of the systems.

18 CHAIRMAN SHACK: The fire protection water  
19 is treated?

20 MR. MELCHIONNA: Freshwater is treated,  
21 yes.

22 CHAIRMAN SHACK: Freshwater? It's not  
23 just from the Delaware River?

24 MR. MELCHIONNA: That's correct. So, if  
25 you look at the internals of those piping systems, you

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 never see any, we don't see any issues.

2 CHAIRMAN SHACK: Do you put corrosion  
3 inhibitors in, nitrates, something?

4 MR. MELCHIONNA: On our freshwater  
5 protection system, I don't believe we put any  
6 inhibitors.

7 CHAIRMAN SHACK: Okay. It is just clean  
8 water or some sort of clean water?

9 MR. MELCHIONNA: As I understand it,  
10 correct.

11 CHAIRMAN SHACK: That's good enough.

12 MEMBER SIEBER: I thought the Delaware  
13 River in the location of the artificial island was  
14 somewhat brackish?

15 MR. MELCHIONNA: Yes, the river water  
16 itself, the cooling source we use for open cycle  
17 cooling itself is very brackish.

18 MEMBER ARMIJO: So, you use treated water?  
19 You don't use river water directly?

20 MEMBER SIEBER: Well, power water usually  
21 comes from your major source.

22 MR. MELCHIONNA: I think I'm going to ask  
23 Ed Keating to probably interject into this and add  
24 some clarity to this question.

25 MR. KEATING: Good afternoon. I'm Ed

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Keating. I'm with the license renewal team.

2 All of our fire water/freshwater is all  
3 groundwater taken from the PRM aquifer at Hope Creek  
4 at depths of about 900 feet below grade. The Delaware  
5 River water is only used for service water and cooling  
6 tower makeup.

7 MEMBER SIEBER: So, you're using wells as  
8 your fire water supply?

9 MR. KEATING: That's correct, sir. And  
10 there's no treatment of that water. It's not  
11 necessary based on the analytical results.

12 MR. MELCHIONNA: So, to further clarify  
13 your question, yes, the only brackish water that is  
14 used from the river is in the open cycle cooling  
15 system, which like we discussed prior to the meeting  
16 is 95 percent AL-6XN piping.

17 MR. KEATING: When he is saying "open  
18 cycle", he is talking about the cooling tower, which  
19 some people refer to as closed cycle.

20 MR. MELCHIONNA: And service water.

21 MR. KEATING: And service water, yes.

22 MEMBER ARMIJO: In these various  
23 categories of materials, how many inspections have you  
24 done since the plant has been operating and what have  
25 your findings been?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 MR. MELCHIONNA: So your question is with  
2 regard to license renewal systems?

3 MEMBER ARMIJO: Yes, or any other system  
4 that you happen to dig up opportunistically, you know,  
5 the carbon steel or the gray cast ductile iron.

6 MR. MELCHIONNA: Okay.

7 MEMBER ARMIJO: You know, just to get an  
8 idea of what you know already about this condition of  
9 the piping.

10 MR. MELCHIONNA: I understand. So for  
11 condensate storage tank system piping, that is  
12 stainless steel piping, and we have done guided wave  
13 examinations on those. We haven't seen any issues  
14 with the in-scope piping. Fire protection, we have  
15 done a number of -- we have done a guided wave  
16 inspection of that, also have not seen any issues.

17 We have a number of what we call  
18 opportunistic inspections when we have dug holes in  
19 the ground. So, any piping that was exposed, we  
20 haven't seen any age-related or corrosion-related  
21 issues with that piping.

22 MEMBER ARMIJO: And as far as your  
23 cathodic protection system, what has been the  
24 availability or percentage time in operation or not in  
25 operation?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. MELCHIONNA: Okay. So, on the in-  
2 scope piping, the cathodic protection availability has  
3 been -- we did a survey -- over 90 percent over the  
4 last five years.

5 MEMBER ARMIJO: Okay.

6 MEMBER SIEBER: Do you ever get any  
7 condenser tube leaks?

8 MR. MELCHIONNA: Yes, we have got  
9 condenser tube leaks.

10 MEMBER SIEBER: Does that put a lot of  
11 saltwater in your internal systems, including your  
12 stainless steel condensate storage tank?

13 MR. DAVISON: I will have Mr. Kopchick  
14 comment on that.

15 MR. KOPCHICK: Good afternoon. Bob  
16 Kopchick, PSEG Nuclear.

17 We do have condenser tube leakage. There  
18 are, obviously, operator abnormal operating procedures  
19 to address them. The condenser tube leaks, the in-  
20 leakage is from the brackish water we get from the  
21 Delaware River.

22 MEMBER SIEBER: Right.

23 MR. KOPCHICK: Historical guidance has  
24 changed over time. Typically, if I were to go back in  
25 the last five or six years, when we reached 1

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 microsiemen per centimeter, operators would isolate  
2 the water box. We would initiate actions to go find  
3 the leak. We have since revised that to 2  
4 microsiemens per centimeter as a must-do and a 1  
5 microsiemen per centimeter we assess performance of  
6 the condensate demineralizers and how much really time  
7 they have left on them or what the impact would be use  
8 on condensate demineralizer capabilities, as to  
9 whether or not we would isolate the box and then go  
10 and do a leak search.

11 MR. BARTON: What is your condenser tube  
12 material?

13 MR. KOPCHICK: Titanium.

14 MEMBER SIEBER: A pretty good pathway to a  
15 lot of stainless steel then.

16 MR. MELCHIONNA: Slide 11.

17 CHAIRMAN SHACK: Again, on your service  
18 water there, I notice you had one set of failures here  
19 where you were doing joints that you had to put the  
20 Weco seals on. I assume that was in that line in that  
21 pre-stress concrete piping?

22 MR. MELCHIONNA: That is correct. We had  
23 installed Weco seals.

24 CHAIRMAN SHACK: Now how did you find  
25 those leaking joints?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1                   MR. MELCHIONNA:     There was no leaking  
2 joints.   There was --

3                   CHAIRMAN SHACK:   Corrosion joints, okay.

4                   MR. MELCHIONNA:     Yes.     Each bell and  
5 spigot joint, it is pre-stressed concrete by about 900  
6 foot in the header.   Each joint is a bell and spigot.  
7     Each joint has an epoxy coating protecting that  
8 carbon steel bell ring in the pipe.   And 8913, or open  
9 cycle loop inspections, revealed blistering of that  
10 coating inside the pipe.

11                   So, our plan was to in an outage inspect  
12 all that piping, remove the coating that was  
13 blistered, examine the material.     And where we  
14 couldn't repair a joint, we covered it with this EPDM  
15 rubber Weco seal which is hydraulically expanded to  
16 the pipe with AL-6XN bands, and seal that joint for  
17 good.

18                   CHAIRMAN SHACK:   Thank you.

19                   MR. MELCHIONNA:     Continuing on, this table  
20 lists all five of the buried piping materials in-scope  
21 for license renewal.   These include carbon steel, gray  
22 cast iron, ductile cast iron, pre-stressed concrete  
23 pipe, and stainless steel.

24                   Column 2 shows the license renewal systems  
25 in which each material is present.   As shown in column

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 3, Hope Creek has committed to perform at least one  
2 excavation and direct visual inspection on each  
3 material grouping during each 10-year interval,  
4 beginning 10 years prior to the entering into the  
5 period of extended operation. In the case of carbon  
6 steel, at least two excavations and inspections will  
7 be performed each 10-year period.

8 This will ensure a comprehensive  
9 assessment of all in-scope buried piping material  
10 types at Hope Creek.

11 Next slide, please.

12 Hope Creek has one open item relating to  
13 buried piping, as Jim mentioned. The open item  
14 relates to the staff's need for additional information  
15 to evaluate how we consider recent operating  
16 experience into our Buried Piping Program.

17 We have considerable site-specific and  
18 recent industry operating experience in the  
19 development of our program and provided the staff with  
20 more information. We provided information about our  
21 operating experience and the excavations we have  
22 performed which showed the coating to be in good  
23 condition. We provided details on our planned  
24 inspection locations.

25 We provided information on the testing of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 our cathodic protection system. The cathodic  
2 protection system is tested annually, consistent with  
3 NACE guidelines.

4 We also provided details on the quality of  
5 our backfill.

6 MEMBER SIEBER: What percentage of the  
7 time or what capacity factor does your cathodic  
8 protection system have? What percentage of the time  
9 is it in service?

10 MR. MELCHIONNA: It is designed to be in  
11 service all the time.

12 MEMBER SIEBER: It's supposed to be 100  
13 percent.

14 MR. MELCHIONNA: A hundred percent.

15 CHAIRMAN SHACK: What is it?

16 MR. MELCHIONNA: Correct. For the server  
17 we indicated for in-scope piping, it is greater than  
18 90 percent over the past five years that we reviewed.

19 MEMBER SIEBER: Okay, but you have  
20 actually reviewed that? And how often do you check to  
21 see that it is operating?

22 MR. MELCHIONNA: Every two weeks we check  
23 volts and amps, compare that to acceptance criteria.  
24 Every two months, we do a walkdown of the rectifiers,  
25 looking for cable damage, degradation, and making sure

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 it is in working condition. And then, annually, we do  
2 the on/off and instant off potential service.

3 MEMBER SIEBER: Okay, thank you.

4 CHAIRMAN SHACK: This water is probably  
5 highly conductive.

6 (Laughter.)

7 MR. BARTON: You've probably got a good  
8 conductor.

9 MR. MELCHIONNA: We believe the  
10 information --

11 MR. BARTON: You have a separate power  
12 station to supply the --

13 MR. MELCHIONNA: We believe the  
14 information we have provided is sufficient to fully  
15 address the staff's request. Our submittal is  
16 currently under staff review.

17 Next slide, please.

18 In conclusion, the Buried Pipe Program  
19 will effectively manage the material condition and  
20 aging of buried piping at Hope Creek and will do so in  
21 a manner that will ensure continued safe operation.  
22 We feel we have a very comprehensive and robust  
23 program that will continue to develop and improve  
24 based on site and industry operating experience, the  
25 NEI industry initiative, participation in our industry

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 working groups, and through the development of any new  
2 technology and inspection techniques as they become  
3 available.

4 I will now turn the presentation over  
5 to --

6 MEMBER STETKAR: One quick one. This will  
7 be relevant to something later probably, also. I know  
8 you said you get your fire water and potable water  
9 from deep wells. What's the average groundwater level  
10 at the site, feet below plant grade? Zero?

11 (Laughter.)

12 MR. MELCHIONNA: I will ask George Seibold  
13 or Ed Keating to answer that question. They have the  
14 details.

15 MR. SEIBOLD: George Seibold, PSEG  
16 Nuclear.

17 The site grade is approximately 12 feet  
18 above sea level.

19 MEMBER STETKAR: Okay.

20 MR. SEIBOLD: And groundwater levels are 5  
21 to 10 feet below site grade.

22 MR. MELCHIONNA: I will give you a "for  
23 instance".

24 MEMBER STETKAR: Yes.

25 MR. MELCHIONNA: Just last week, we

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 uncovered two, we dug two excavations, 36-inch carbon  
2 steel pipe, not cathodically-protected, in wet soil.  
3 We had quite a few pumping operations to keep that  
4 hole dry. That piping, when we inspected it, it was  
5 in like-new condition. Once we looked at the coating,  
6 the coating was so tight to the pipe and the bolting  
7 after 30 years being in the ground, it was in  
8 excellent condition.

9 MEMBER STETKAR: And I am assuming the  
10 groundwater chemistry looks an awful lot like river  
11 water.

12 MR. MELCHIONNA: I don't know the exact  
13 numbers, but we did sample the soil and the water for  
14 analysis out of those excavations.

15 MR. SOSSON: No, it does not. George  
16 Seibold can provide additional detail on the  
17 groundwater.

18 MR. SEIBOLD: George Seibold, PSEG  
19 Nuclear.

20 We have got wells that we have taken  
21 groundwater samples from, and those wells generally  
22 range from as low as 80 parts per million to 5,000,  
23 and our service water system, being tidal, ranges up  
24 to maybe 11,000 parts per million.

25 MEMBER STETKAR: So you get some

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 filtration. This is chlorides you're talking?

2 MR. SEIBOLD: Yes.

3 MEMBER STETKAR: Yes. Thank you.

4 CHAIRMAN SHACK: Just out of curiosity  
5 again, how well is the AL-6X working?

6 MR. MELCHIONNA: I have seen nothing wrong  
7 with the AL-6X except, if you are familiar with sigma  
8 phase --

9 CHAIRMAN SHACK: Yes.

10 MR. MELCHIONNA: -- there are some  
11 material castings with like very thin plates of  
12 orifices; you might see some galvanic or crevice  
13 corrosion due to the sigma phase. But, overall, we  
14 had such tight manufacturing testing with that 6 moly,  
15 that there is literally no corrosion on it at all  
16 anywhere I have looked.

17 MEMBER ARMIJO: How long was that?

18 MR. MELCHIONNA: For Salem, it has been --  
19 both have it, but at Hope Creek since the early  
20 nineties. It looks brand-new every time you look at  
21 the piping.

22 MEMBER ARMIJO: Great.

23 CHAIRMAN SHACK: Almost worth the cost.

24 (Laughter.)

25 MR. SOSSON: Thank you, Jim.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Slide 14, please.

2 That concludes our discussion of the  
3 confirmatory and open items. I will discuss the topic  
4 of interest for Hope Creek, the Mark I containment.

5 Next slide, please.

6 Industry operating experience documents  
7 instances of corrosion on inaccessible exterior  
8 surfaces of the drywell shell of G.E. BWR Mark I  
9 containments. In response to this operating  
10 experience, we proactively performed confirmatory  
11 ultrasonic thickness measurements, also called UTs,  
12 for the drywell shell in 2007 and 2009.

13 The results of these inspections showed no  
14 loss of material due to corrosion. IWE inspections of  
15 the inside-to-drywell surface have also shown that the  
16 drywell is in good condition.

17 A small reactor cavity leak was identified  
18 in 2009 during the refueling outage. Follow-up  
19 inspections of the drywell shell in 2010 identified an  
20 area of interest that is being managed through our  
21 corrective action program and in accordance with our  
22 license renewal commitments. This leak and drywell  
23 shell inspection results will be discussed in greater  
24 detail later in this presentation.

25 Next slide, please.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1           This slide shows the containment house  
2 within the reactor building. The containment is still  
3 pressure vessels and consists of a drywell in the  
4 shape of an inverted lightbulb and a toroidal-shaped  
5 suppression chamber called the torus.

6           CHAIRMAN SHACK: Is there some sort of  
7 material that is in that air gap or is that really  
8 steel-to-concrete?

9           MR. SOSSON: No, it is a 2-foot air gap  
10 that has been --

11          CHAIRMAN SHACK: Two inches, rather.

12          MR. SOSSON: Oh, I'm sorry, a 2-inch air  
13 gap. Thank you.

14          (Laughter.)

15          That was verified during construction. It  
16 is truly an air gap.

17          MEMBER ARMIJO: There is no felt or any  
18 other material?

19          MR. SOSSON: No, there is no insulation or  
20 fill material. It is an air gap that would allow air  
21 and any potential reactor water to transition through.

22          MEMBER SIEBER: Could you point out where  
23 the reactor cavity leak was on that drum?

24          MR. SOSSON: Yes. My next slide will show  
25 exactly that.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER SIEBER: Okay.

2 MR. SOSSON: Above the foundation  
3 transitions of the drywell shell there is an air gap,  
4 nominally 2-inches wide, as we discussed, that  
5 separates the drywell vessel and the concrete drywell  
6 shield wall. There is no sand bed region or sand in  
7 the foundation transition zone in the air gap at the  
8 drywell shell.

9 At the bottom of the air gap, four  
10 equally-spaced drainlines around the perimeter of the  
11 drywell shell prevent any water from accumulating in  
12 the air gap.

13 MEMBER ARMIJO: Was that sand removed  
14 after construction or was it never put in in the sand  
15 bed region?

16 MR. SOSSON: We do not have a sand bed  
17 region. There was sand used during the forming  
18 operations, but that was all drained.

19 MEMBER ARMIJO: All removed?

20 MR. SOSSON: Yes.

21 MEMBER ARMIJO: So, you never operated  
22 with what was called a sand bed?

23 MR. SOSSON: That's correct.

24 MEMBER ARMIJO: Okay.

25 CHAIRMAN SHACK: And there is a seal

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 around the bottom of that air gap? Or it just comes  
2 down and then it's concrete?

3 MR. SOSSON: The bottom of the air gap is  
4 at the floor level inside the drywell, and there are  
5 four air gap drainlines at 90 degrees that I will  
6 discuss more.

7 CHAIRMAN SHACK: But is there a seal  
8 between the concrete and the steel shell as it goes  
9 down under?

10 MR. SOSSON: No, there is not.

11 George, can you?

12 MR. SEIBOLD: George Seibold, PSEG  
13 Nuclear.

14 No, there wasn't any seal provided. The  
15 top of the air gap was one of the four points when we  
16 poured the concrete around it.

17 MR. SOSSON: Thank you.

18 The exterior surface of the drywell shell  
19 is coated with an inorganic zinc to prevent corrosion.

20 The reactor cavity includes a bellows seal to allow  
21 flood-up for refueling.

22 Next slide.

23 This is a sketch that shows the probable  
24 path of a small reactor cavity leak into the drywell  
25 air gap that was identified during the 2009 refueling

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 outage. Note that this leak is not a leak in the  
2 containment, but a leak outside the primary  
3 containment that has the potential to occasionally wet  
4 the exterior surfaces of the drywell shell.

5 This small leak was identified at the  
6 reactor building concrete wall, penetration sleeve No.  
7 J13, and it formed a small puddle on the torus room  
8 floor.

9 It was confirmed that the leak only occurs  
10 when the reactor cavity is flooded up. The probable  
11 leakage path is through a weld defect in the reactor  
12 cavity seal plate through the air gap and exiting the  
13 gap at the J13 penetration sleeve. This is shown in  
14 more detail in the following two slides.

15 This is a sketch that shows, in blue, the  
16 probable leakage path at the reactor cavity seal area.

17 You can see the drawing from the bottom of the seal  
18 plate down along the side of the drywell shell.

19 The reactor cavity seal assembly provides  
20 a seal from the exterior of the drywell shell to the  
21 reactor cavity liner to permit flooding of the reactor  
22 cavity.

23 This detail shows the normal drains and  
24 the seal rupture drainlines. Lack of leakage into the  
25 seal rupture drainlines indicated the seal is not

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 located below the bellows assembly. The probable  
2 leakage path is through a small weld defect in the  
3 reactor cavity seal plate assembly or piping above the  
4 air gap region.

5 MEMBER ARMIJO: Do you have any idea how  
6 big that leak is?

7 MR. SOSSON: We don't have it quantified,  
8 but all the indications, as I will discuss, indicate  
9 that it is a very small leak, and the only leakage  
10 that we have seen coming out has basically formed  
11 puddles that self-evaporate in the 100-drop-a-minute  
12 range.

13 MR. BARTON: And this has been recently  
14 found, right?

15 MR. SOSSON: It was recently discovered in  
16 2009.

17 MEMBER STETKAR: Greg, I will ask the  
18 stupid question I have to ask. You're confident that  
19 your reactor cavity seal rupture drainlines are open?

20 MR. SOSSON: Yes. The cavity drainlines  
21 we do test. They run to an instrument that would fill  
22 up a float and cause a high-level alarm if we were  
23 getting water through there.

24 MEMBER STETKAR: No, but I mean --

25 MR. BARTON: They're not closed. There's

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 no valve that is shut someplace?

2 MEMBER STETKAR: Well, not a valve, that  
3 they're not necessarily just full of, to use a  
4 technical term, "gunk".

5 MR. SOSSON: George, would you like to  
6 provide some clarity on that?

7 MR. SEIBOLD: Yes. George Seibold, PSEG  
8 Nuclear.

9 That system is a completely welded system  
10 designed to handle radwaste. Currently, we are  
11 providing a design change to provide a port to assure  
12 us that that drainage is open. The instrumentation  
13 for that drainline is checked every 18 months  
14 electrically. So, once we provide a port in there, we  
15 can assure ourselves no blockage of that line.

16 MEMBER STETKAR: But, right at the moment,  
17 you don't know whether -- you have not tried to blow  
18 air or push water or do something through those lines  
19 to see, in fact, that they are open?

20 MR. STAVELY: I'm sorry. At this point,  
21 we haven't, that's correct.

22 MEMBER STETKAR: Okay.

23 MR. STAVELY: Because we don't have access  
24 to it. So, what we are installing is a test  
25 connection, so that we can, through that test

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 connection, actually add water to the pipe, verify the  
2 float mechanically lifts.

3 MEMBER STETKAR: Yes.

4 MR. STAVELY: And then, also, through that  
5 test connection, put enough water in the pipe to  
6 verify it's not blocked downstream, and then use an  
7 air source to verify that it is not plugged upstream.

8 MEMBER STETKAR: That would be a good  
9 idea. My only question is, you know, you have  
10 isolated the potential root cause for this leak based  
11 on the fact that you are not seeing the water out of a  
12 drainline that you don't necessarily know is open.

13 MR. STAVELY: This leak investigation has  
14 been systematic in the sense that we have not, even  
15 though we do not know at this point whether that  
16 drain, the cavity seal rupture drain is open, we  
17 continued with a path to implement a design change to  
18 be able to check it, as well as implemented a number  
19 of actions for this refueling outage to investigate  
20 the possible source on the seal plate.

21 MR. SEIBOLD: George Seibold, PSEG  
22 Nuclear.

23 This is one of our license renewal  
24 commitments for the IWE program.

25 MR. SOSSON: Okay. Yes, slide 19, please.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1                   This slide is a sketch that shows, in  
2 blue, the potential leakage path at the lower drywell  
3 at the J13 penetration area.

4                   A group of six drywell shell  
5 instrumentation penetrations, including penetration  
6 J13, are used for instrumentation lines entering the  
7 drywell. And they are shown in that matrix on the  
8 upper left.

9                   The penetration sleeves provide a path for  
10 the instrument lines through the reactor building  
11 shield wall. The J37 penetration sleeve is  
12 approximately 24 inches directly below the J13  
13 penetration sleeve.

14                  During the 2009 outage, the water leakage  
15 was found coming out of the shield wall at the J13  
16 penetration sleeve only.

17                  MEMBER SIEBER: But the normal design  
18 drain is the 4-inch drain below it?

19                  MR. SOSSON: That's correct.

20                  MEMBER SIEBER: That's probably 2 or 3  
21 feet below it?

22                  MR. SOSSON: That is approximately 8 feet  
23 below, yes.

24                  MEMBER SIEBER: Okay. So, they found a  
25 shorter path?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. SOSSON: That's correct.

2 MEMBER ARMIJO: Did they give you an idea  
3 of where the leak was in your seal area?

4 MR. SOSSON: Yes. Our data, it would be  
5 likely that the leakage would be occurring somewhere  
6 directly above J13 penetration area.

7 MR. STAVELY: We actually took a look; we  
8 boroscoped on each side. If you see that group of six  
9 penetrations, we boroscoped a number of times this  
10 outage in those penetrations. One of the purposes was  
11 to look to the right of J19 and the left of J13 and  
12 look back at the concrete, so that we have an idea as  
13 to what is the span of the leak.

14 And we looked at that, the span. You  
15 could see where the concrete was dry, where the  
16 concrete was wet and then where the concrete was dry.

17 So, we're looking in the 210-to-240 azimuth in terms  
18 of the leak span, and that matches up with one of the  
19 welds up at the seal plate on top.

20 MEMBER STETKAR: Greg, before you go on, I  
21 will ask the same stupid question about the air gap  
22 drains. Are there positive ways of determining that,  
23 indeed, those air gap drainlines are not blocked?

24 MR. SOSSON: Well, I'm going to actually  
25 discuss that later in the presentation.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1                   MEMBER STETKAR: Okay. Thanks. No, fine,  
2 go on.

3                   MR. SOSSON: Back in the 2009 outage,  
4 there was no water coming out of the J37 penetration,  
5 the one located right below the J13. Observations  
6 indicated that leakage was about a quarter-inch-wide  
7 trickle, and the leakage stopped when the reactor  
8 cavity was drained.

9                   Slide 20, please.

10                  The reactor cavity leak is small. Our  
11 goal is to identify the leakage source and repair it.

12                  Without our IWE program commitment, we have indicated  
13 a number of actions to monitor the leak and its  
14 effects until the leak is repaired. The actions  
15 include additional UTs, leakage monitoring, and  
16 drainline inspection and testing, as Jim and George  
17 pointed out.

18                  Slide 21.

19                  We are currently in a refueling outage at  
20 Hope Creek, and we have had the opportunity to  
21 implement our corrective action plan for this leak. I  
22 will provide you with an update on these actions that  
23 we have taken over the last two weeks.

24                  After the cavity was flooded up during the  
25 Hope Creek refueling outage, we observed the small

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 amount of leakage in the torus room below the  
2 instrumentation line penetration, as described  
3 earlier. Up to approximately 100 drops per minute  
4 total were coming from two adjacent penetrations, J13  
5 and J14, during the period while the reactor cavity  
6 was flooded.

7           Using a boroscope, the air gap between the  
8 drywell shell and the reactor building shield wall  
9 were inspected in the area of the J13 penetration.  
10 There were no obstructions in the air gap. A small  
11 amount of water was observed to be on the inside  
12 surface of the concrete shield wall, which bypassed  
13 the penetrations and continued down the concrete wall.

14       The leakage was not on the drywell shell at this  
15 point.

16           The inspection also showed that the water  
17 is not trapped against the drywell shell in the area  
18 of the J13 penetration. The drywell shell and  
19 penetrations visible from the boroscope inspections  
20 were all in good condition.

21           We have also performed daily monitoring of  
22 the air gap drains, but did not observe any water  
23 leaving the air gap drains. Since we didn't identify  
24 any water coming out of the air gap drains, we  
25 followed up further to do boroscope inspections of the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 air gap drains, and we did find that those drains are  
2 covered in all four locations. This is likely a  
3 situation that --

4 MEMBER STETKAR: By covered, you mean  
5 plugged?

6 MR. SOSSON: Yes, blocked.

7 MEMBER STETKAR: Okay.

8 MR. SOSSON: And it's likely that this  
9 occurred from construction. We have entered it into  
10 our corrective action process. This data is about  
11 within the last 72 hours. So, this is new  
12 information.

13 MEMBER SIEBER: Does that mean that it  
14 will be cleaned out before you start up?

15 MR. SOSSON: It is in our corrective  
16 action process.

17 If you can go back up to this slide, the  
18 air gap drains, the plugs would be located right where  
19 the cursor is now. It is about a 40-foot run of pipe.

20 So, in order to actually clear out these drains would  
21 require significant scaffold builds to remove the  
22 pipe.

23 So, it is in our action process. Our  
24 intent is to remove these, but I can't speak to the  
25 timeframe that we will do that. It is obviously a

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 nonconforming condition that we have to evaluate. And  
2 again, this is very new information.

3 MR. DAVISON: Greg will actually cover  
4 some of the things we looked at to make sure that,  
5 even if there were some water trapped in there, that  
6 wasn't impacting the integrity of the shell. So, he  
7 will cover that.

8 But, more importantly, whatever water does  
9 accumulate in that lower area, because now that we  
10 have confirmed that the air gap drains are blocked,  
11 the source is terminated after approximately 20 days.

12 We're in day 18, and we're already drained back down.

13 Then, with the heatup during normal operations and no  
14 source, that water will be quickly dissipated.

15 MEMBER SIEBER: Yes, the only word you  
16 forgot was "hopefully".

17 (Laughter.)

18 MR. DAVISON: But we do have concrete  
19 evidence that Greg will cover around what the  
20 condition of the shell is right now. We do know that.

21 MR. BARTON: Are you putting a moisture  
22 barrier at that juncture of the floor and drywell?

23 MR. SOSSON: Well, on the inside, there  
24 will be a moisture barrier installed on the inside at  
25 the drywell floor.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 MR. BARTON: There is none now? There  
2 never was one?

3 MR. SOSSON: There is none now. It is in  
4 very good condition.

5 George Seibold can amplify.

6 MEMBER STETKAR: Why don't we finish this  
7 one first? I've got a couple more questions --

8 MR. SOSSON: Okay.

9 MEMBER STETKAR: -- about the inside of  
10 the drywell.

11 MR. SOSSON: Okay.

12 MEMBER STETKAR: In some sense, you are  
13 going to talk about the condition of the drywell  
14 shell?

15 MR. SOSSON: Yes.

16 MEMBER STETKAR: Is there some chance that  
17 -- you know, you have discovered this leakage source  
18 because in some sense you are fortunate that the water  
19 found a pathway out through the J13 place where it  
20 could come out. How confident are you that there  
21 aren't other leakage positions that didn't have that  
22 fortunate pathway somewhere else in the other 358  
23 degrees, or whatever.

24 MR. SOSSON: That certainly can't be ruled  
25 out. But what I can say is, from the drywell floor to

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the drywell vent lines that go circumferentially  
2 around, the bottom of that drywell air vent is 1 foot  
3 5 inches, and there is an air gap between the drywell  
4 vent line and the concrete. So, if water was  
5 accumulating in the annulus region between the drywell  
6 shell and the concrete of the containment --

7 MEMBER STETKAR: It would come out through  
8 the gap in the drywell --

9 MR. SOSSON: Yes, and we have seen no  
10 indication anywhere else.

11 MEMBER STETKAR: Okay.

12 MR. SOSSON: And we have calculated it --

13 MEMBER STETKAR: But that interference  
14 isn't apparent on this.

15 MR. SOSSON: Yes, it's not clear on the  
16 drawing, and we calculated it would take 320 gallons  
17 of water in order to fill up before it would start  
18 spilling out, and we have not seen anything. So, if  
19 there is a leakage, it is so small that it either  
20 evaporates before it can fill up that high or there's  
21 no leak.

22 MEMBER STETKAR: Okay.

23 MEMBER ARMIJO: But that shell is coated  
24 with zinc all the way down to the point where it meets  
25 the concrete, where it is supported. And it is an

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 inspectable area, right? You can actually take a look  
2 at that area in the sand bed region? At least in some  
3 designs you certainly can access it.

4 MEMBER SIEBER: You can get it from the  
5 inside.

6 MEMBER ARMIJO: I am talking about the  
7 outside of the shell. Can you look at --

8 MEMBER SIEBER: Well, the outside is --

9 MR. DAVISON: George can walk you through  
10 what that looks like.

11 MEMBER ARMIJO: Okay.

12 MR. SEIBOLD: George Seibold, PSEG  
13 Nuclear.

14 The air gap region is fairly inaccessible.

15 (Laughter.)

16 That is why we are boroscoping it through  
17 these penetrations.

18 MEMBER ARMIJO: Okay.

19 MR. SEIBOLD: We did review construction  
20 reports, and we know the outside of the drywell shell  
21 was coated with an inorganic zinc after construction  
22 for the purpose of protecting the outside of the  
23 shell. But we really can't get in there to inspect  
24 it.

25 MEMBER ARMIJO: You can't take photographs

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 through your boroscope or anything like that?

2 MR. SEIBOLD: Well, we have taken  
3 boroscopes up through the J13 and J37 area. And as  
4 Jim said, the shell and the coating look to be in  
5 reasonable shape.

6 MR. STAVELY: It is an articulating  
7 boroscope, and when we turn the head around, we can  
8 see maybe 3 feet with the light we have from that.  
9 What we are considering, though, is getting a  
10 specialized camera that we can lower through the  
11 penetration opening, so that we can look at the area  
12 down.

13 So, even though it is an area that right  
14 now we can't see, we are exploring ways to look at  
15 that.

16 MEMBER SIEBER: Now that drawing sort of  
17 shows that, if you wanted to, right at the drywell  
18 floor on the inside, you could perhaps do a UT, but --

19 MR. STAVELY: We did test that and --

20 MEMBER SIEBER: -- my experience is that  
21 these kinds of drawings aren't all that accurate, and  
22 the air gap on the outside may go below where the  
23 floor is. So, you are sort of guessing about that.

24 MR. STAVELY: What we intend to do, we do  
25 intend, I said, to drop the camera -- or lower the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 camera.

2 (Laughter.)

3 MEMBER STETKAR: You might drop one or  
4 two.

5 MR. STAVELY: No, it's an expression.  
6 Lower the camera and then retrieve the camera.

7 One thing we haven't mentioned is the  
8 water chemistry. We have three samples of the water  
9 chemistry that is coming out of those penetrations.  
10 So, it is coming down the shield and the pH is on the  
11 order of 8.3 to 8.5. And that would be the type of  
12 water that would be at the bottom there.

13 MR. SOSSON: Which is consistent with it  
14 draining down across the concrete.

15 MR. DAVISON: George, do you want to --

16 MR. SEIBOLD: George Seibold, PSEG  
17 Nuclear.

18 The design of the drywell at the floor  
19 level is such that the drywell floor and the air gap  
20 are coincidentally the same.

21 MEMBER SIEBER: That is what it appears to  
22 be here, but in construction it is not always that  
23 way.

24 MR. SEIBOLD: Well, further evidence is  
25 that is where the outer skirt of the drywell also is

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 designed to hold up the drywell shell.

2 MEMBER SIEBER: Okay.

3 MR. SEIBOLD: So, it is kind of like that  
4 is where the air gap is allowing the drywell shell to  
5 move. Therefore, we are pretty confident that --

6 MEMBER SIEBER: But on the inside of the  
7 drywell, the concrete truck came in, they dumped some,  
8 smoothed it off, and that's where the joint ended up,  
9 however much was in the concrete. You don't know  
10 exactly where that level is.

11 MR. SEIBOLD: Well, you know, they  
12 maintain drawing tolerances and there is a  
13 potential --

14 MEMBER SIEBER: Yes.

15 MEMBER ARMIJO: Jack is skeptical.

16 (Laughter.)

17 MEMBER SIEBER: Yes, I have been on  
18 construction projects.

19 (Laughter.)

20 I know how it's done.

21 MR. SEIBOLD: Greg will also mention that  
22 we dig UT measurements 360 degrees at that junction.

23 MEMBER SIEBER: Okay.

24 MR. SOSSON: So, with regard to the  
25 ultrasonic testing done to investigate the possible

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 effects of the identified leakage, we did perform the  
2 UT exams of the shell in four areas from inside the  
3 drywell.

4 We examined the shell around the  
5 instrumentation penetration assembly where the water  
6 entered the torus room and was observed on the  
7 concrete wall in the air gap.

8 We performed the UT exams approximately 25  
9 feet above the instrumentation penetration area on an  
10 area where the drywell shell would be more likely to  
11 have been wetted by the leak due to the geometry of  
12 the drywell.

13 If you could just back up to slide 17?  
14 Seventeen, please.

15 So, elevation 122 corresponds to that top  
16 platform. So that we would surmise that that is where  
17 the drywell is being wetted. So, we took UT exams  
18 there.

19 Go back to the previous slide, please.

20 Additional UT inspections were performed  
21 directly below the instrumentation penetration area  
22 vertically down to the drywell floor area, which is  
23 equivalent to the elevation of the bottom of the air  
24 gap.

25 Finally, a set of UTs were performed on

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the shell near the floor around the entire  
2 circumference of the drywell.

3 With the exception of the lower portion of  
4 the plate directly below the instrumentation  
5 penetration assembly, all readings showed greater than  
6 nominal plate thickness, and I will discuss later on  
7 the next slide more detail of these UT results.

8 With respect to the leakage investigation  
9 activities, prior to the flood-up of the reactor  
10 cavity, we did perform a visual inspection of the seal  
11 plate area, the bellows area, and the reactor cavity  
12 liner. We saw no indication of the possible source of  
13 the leak.

14 Following refueling activities, the  
15 partial drain-down of the cavity, and prior to  
16 draining the outer bellows, a boroscope examination of  
17 the seal plate and bellows area for any indication of  
18 the leak is going to be performed. That will be done  
19 over the next couple of days. Following drain-down of  
20 the cavity, we will confirm that the leakage has  
21 stopped.

22 We are collecting as much information as  
23 possible this outage to facilitate continuing  
24 investigation to identify the cause of the leak and  
25 implement repairs.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 Next slide, please.

2 This is a complicated slide. This is a  
3 summary of our UT results for exams performed during  
4 2010 to investigate whether the leakage discussed has  
5 caused any impact on the drywell. The readings also  
6 provide a baseline for future UT measurements to  
7 determine any corrosion.

8 So, to orient you to this slide, we  
9 basically took, as I described earlier, areas of  
10 interest vertically above and below the J13  
11 penetration area. At 121 feet, which corresponded to  
12 that top platform I pointed out, UTs were taken at a  
13 1-foot-by-20-foot area to broadly bound above the J13  
14 penetration area. We took a total of 44 UTs. The  
15 average reading was 1.576 mils for the 1-foot 576  
16 inches for the 1.5-inch plate. As you see, all the  
17 readings were nominal.

18 MR. BARTON: 1.5 inches?

19 MR. SOSSON: Yes, 1.5 inches.

20 MR. BARTON: Thank you.

21 MR. SOSSON: Yes, thank you.

22 At elevation 97 feet, corresponding to  
23 that lower platform on the drywell drawing, we looked  
24 at an area 1 inch by 3.5 feet. We took a total of 20  
25 UT readings. And again, the average reading was 1.564

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 inches with the low reading still being above nominal.

2 MEMBER SIEBER: What is your mid-wall,  
3 about 8/10ths of an inch?

4 MR. SOSSON: The analyzed thickness is  
5 1.4375 inches, which is shown in the bottom 1.5-inch  
6 plate. Yes, the analyzed -- yes.

7 MEMBER SIEBER: Okay.

8 MR. SOSSON: Well, we will come back to  
9 that.

10 For the J13 penetration area, that is  
11 actually a 3-inch plate. We took readings across, we  
12 took 84 UT readings across that plate area. That is  
13 approximately 4-feet wide or 6-feet wide by about 4-  
14 feet high. And again, for the 3-inch-thick plate, the  
15 average readings were 3.110 inches. The lowest was  
16 3.066, all above nominal.

17 The lower readings were the 1.5-inch plate  
18 that go from just below the J13 penetration area to  
19 the floor. That plate, as was discussed earlier,  
20 actually goes down below the floor.

21 We highlighted the gray boxes to indicate  
22 our area of interest. As I referred, the lowest  
23 spillover point would be 1 foot 5 inches above the  
24 floor, according to this slide.

25 So, the slide results from the UT

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 performed in the three main areas; looking at the  
2 lower slide, you can see the results of the UT  
3 measurements. We took a total of 79 measurements.  
4 There were between seven and nine measurements taken  
5 on 10 different horizontal rows for that lower plate,  
6 with approximately 1 foot between each of the  
7 readings. The average values for the readings on each  
8 row are provided on the slide.

9 As you can see, although the average  
10 values are within the tolerance range, the readings  
11 near the bottom plate tend to be the lowest.  
12 Therefore, we have established this as an area of  
13 interest, and we will be examining this in future  
14 outages.

15 It is important to note that the  
16 individual and average thickness readings on the plate  
17 are above design plate thicknesses, which is the  
18 1.427.

19 MEMBER REMPE: What's the accuracy of this  
20 ultrasonic technique? What does the vendor claim?  
21 How accurate is it?

22 MR. ROBERTS: Good afternoon. Tom  
23 Roberts, PSEG Nuclear.

24 The accuracy of the ultrasonic testing,  
25 which is a standard straight-beam examination for

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 thickness, is plus or minus .01. So, any reading you  
2 have, you can go plus 1/minus 1.

3 MEMBER REMPE: Okay.

4 MEMBER ARMIJO: Did you have any  
5 interference down at the lower 2 inches? Because  
6 that's where your support skirt is on the other side  
7 there. Did you pick that up? Or did that interfere  
8 with your measurements at all?

9 MR. SEIBOLD: George Seibold, PSEG  
10 Nuclear.

11 Our UTs did not pick that up. We did  
12 plate sections down there, and they alternate between  
13 an 1.5-inch-thick plate to a 3-inch plate at the vent  
14 lines. And we also have stiffeners in that area. So,  
15 we had a UT around them to avoid them.

16 MEMBER ARMIJO: Okay.

17 MEMBER STETKAR: Just before, to make sure  
18 I understand this one, all of these UTs, though, were  
19 done in the area below the penetration assembly?

20 MR. SOSSON: Yes.

21 MEMBER STETKAR: Did you do any other UTs?

22 MR. SOSSON: Yes, we did 360 degrees --

23 MEMBER STETKAR: You did?

24 MR. SOSSON: -- at 1-foot intervals, 360,  
25 and in all other cases they were above nominal.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER STETKAR: At nominally floor level  
2 or?

3 MR. SOSSON: At floor level.

4 MEMBER STETKAR: At floor level?

5 MR. SOSSON: Yes.

6 MEMBER STETKAR: Okay. Thanks.

7 CHAIRMAN SHACK: Now did you see any  
8 variability that would indicate that this was a little  
9 bit lower than the others?

10 MR. SOSSON: Well, actually, the data  
11 indicated that this one plate appears to be a little  
12 lower. All the others were above an inch and a half,  
13 but this plate is uniformly a little thinner than the  
14 others. So, we have established this as an area of  
15 interest. Now this will be a good baseline for us to  
16 go in in future outages and to monitor.

17 MEMBER SIEBER: Now these readings are at  
18 the floor level? But the leakage drain was from an  
19 instrument line? Above that, did you do readings  
20 around that instrument line penetration?

21 MR. SOSSON: We did not take any readings  
22 in the upper cylinder of the containment, but we  
23 did --

24 MEMBER SIEBER: Well, that's in the lower  
25 half, where that line --

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. SOSSON: Yes, if you can go to slide  
2 17, please? I'm sorry, 17.

3 The highest readings that we took, we did  
4 take previous baseline readings in that upper  
5 cylinder, which I will show next. But, specifically,  
6 following this leak path, right where the cursor is  
7 now is the highest point where we were looking at  
8 specifically in 2010 as a followup.

9 If you go to slide 32, these are basic  
10 readings that we took through the containment, which  
11 this is a backup slide. It's not in your  
12 presentation.

13 But these are the results of some readings  
14 taken in 2007 and 2009, prior to knowing about the  
15 leak, so that we could assess drywall thickness  
16 proactively.

17 Back to slide 22?

18 Okay, moving forward on slide 23, in  
19 summary, the drywell shell is in good condition. The  
20 design includes adequate corrosion allowances to  
21 ensure the design margins are maintained through the  
22 period of extended operation.

23 A small reactor cavity leak is being  
24 managed in our corrective action program and in  
25 accordance with the license renewal commitments.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1                   We have effective aging management  
2 programs to ensure continued safe operation of the  
3 Hope Creek containment.

4                   I will now return the presentation to Paul  
5 Davison for closing.

6                   MR. BARTON: A question: if you never had  
7 a moisture shield, according to what I read, there was  
8 no moisture barrier at the floor to the drywell  
9 connection. Why are you now going to install one?

10                  MR. SOSSON: We are basically installing  
11 the moisture barriers as a good practice.

12                  And I will ask George Seibold to --

13                  MR. BARTON: Are you sure that maybe no  
14 water got between the concrete and the drywell over  
15 the years?

16                  MR. STAVELY: In the previous refueling  
17 outage in 2009, we cleaned and performed a VT1  
18 inspection of that junction.

19                  MR. BARTON: Of that joint?

20                  MR. STAVELY: Of that joint specifically.

21                  MR. BARTON: Okay.

22                  MR. STAVELY: And there was no indications  
23 of any significant corrosion or problems. Because we  
24 wanted to make sure before we put in a moisture  
25 barrier that we understood the surface. So, we

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 performed that in 2009.

2 MEMBER STETKAR: I mean you can only go a  
3 certain depth below where that joint is. What  
4 confidence for the lower part of the drywell, which is  
5 completely inaccessible, that the water hasn't seeped  
6 down in there over the years and has caused corrosion  
7 problems?

8 MR. BARTON: You haven't gone through,  
9 drilled a hole, put a UT probe against the drywell  
10 surface from the inside?

11 MR. STAVELY: There was no design gap in  
12 there. So, the concrete was poured directly against  
13 the shell.

14 George Seibold can provide a little bit  
15 more information.

16 MR. SEIBOLD: George Seibold, PSEG  
17 Nuclear.

18 During the 2009 outage that we did the VT1  
19 inspection, we probed that joint with a feeler gauge,  
20 and trying to see if there was a gap there. And in a  
21 few small spots, we got a 5-mil feeler gauge in there,  
22 but nothing thicker than 5 mils. And there was no  
23 indication of water or corrosion or concrete  
24 deterioration that would indicate corrosion in that  
25 joint.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1                   CHAIRMAN SHACK:     How regularly do you  
2 inspect that?

3                   MR. SEIBOLD:    As part of IWE, they inspect  
4 it, but they do a VT3.  As part of our assessment on  
5 the drywell, we wanted them to do a VT1 on that area.  
6     So, that was done in 2009.

7                   And as one of our commitments, we said  
8 that, as part of the IWE, after we install the  
9 moisture barrier, then they have to inspect the  
10 moisture barrier, which they weren't inspecting before  
11 because it didn't exist.

12                  MR. BARTON:     You are going to get an  
13 opportunity to look at some of that joint when you  
14 take the concrete out to put a moisture barrier in,  
15 right?

16                  MR. STAVELY:    No, we are not actually  
17 taking the concrete out, no.  We prepare the surface  
18 both on the concrete and the shell side, recoat it,  
19 and then apply the caulking material, the moisture  
20 barrier material on top of that.  So, we prepare the  
21 concrete and the shell.

22                  We implemented approximately 1/8th of that  
23 in the last week.  So, the remaining 7/8ths of the  
24 moisture barrier will be installed in the next  
25 refueling outage.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1           The reason we chose not to install it all  
2 this time was because it is a significant ALARA budget  
3 to be able to put in a moisture barrier on a plant  
4 that is already operating. So, we choose an area that  
5 would be in a lower-dose area where we could verify  
6 all our maintenance practices and any sort of tooling  
7 and shielding issues. So, when we do it in the next  
8 outage, we do it effectively and we manage our dose.

9           MR. SOSSON: Thank you. I will now return  
10 the presentation to Paul Davison for closing comments.

11           MR. DAVISON: Thanks, Greg.

12           Mr. Chairman, Subcommittee members, thank  
13 you for your interaction during our presentation  
14 today. As previously mentioned, we are very confident  
15 that our license renewal application reflects an aging  
16 management program that will continue the safe  
17 operation through the period of extended operation.

18           And pending any other additional  
19 questions, this will complete our presentation.

20           MEMBER STETKAR: A couple of questions.

21           CHAIRMAN SHACK: Please. Sure.

22           MEMBER STETKAR: You're ahead of schedule?

23           CHAIRMAN SHACK: Yes.

24           MEMBER STETKAR: Your structures  
25 monitoring program, there were enhancements made to

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 that program to add a relatively large number of  
2 structures. One of the ones that I noticed was the  
3 fire water tank foundation was added for the  
4 monitoring. I didn't go back and look at the scope of  
5 the program myself.

6 Is the condensate storage tank foundation  
7 monitored under that program?

8 MR. SOSSON: Yes.

9 MEMBER STETKAR: Thank you.

10 Also, in your structures, I think it was  
11 the structures monitoring program, there was an  
12 enhancement that says, "Enhanced parameters to be  
13 monitored for wooden components to include change in  
14 material."

15 Where do you have wooden structural  
16 members for license renewal in-scope components? This  
17 is a curiosity because, since you enhanced the program  
18 to add wood, you must have some wood somewhere. So,  
19 where is it?

20 MR. STAVELY: Hopefully not in  
21 containment.

22 (Laughter.)

23 MEMBER STETKAR: Not that you know of.

24 (Laughter.)

25 MR. SEIBOLD: George Seibold, PSEG

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Nuclear.

2 Out at the intake structure, we have  
3 wooden ice barriers to prevent ice to come in --

4 MEMBER SIEBER: They're on the outside of  
5 the --

6 MR. SEIBOLD: They are on the river side.

7 MEMBER SIEBER: Right.

8 MR. SEIBOLD: And they prevent ice from --

9 MEMBER SIEBER: That's common.

10 MEMBER STETKAR: I don't know how common  
11 it is, but fine.

12 (Laughter.)

13 CHAIRMAN SHACK: In California and  
14 Arkansas, they don't do much of it, but up north.

15 MEMBER STETKAR: Well, not necessarily  
16 wood, though. I mean it could be steel or it could be  
17 other kind of barriers, riprap.

18 MR. BARTON: You've gotten some corrosion  
19 in the inspections at your service water by on the  
20 river, underwater corrosion. Are there plans to go  
21 and fix that stuff?

22 MR. DAVISON: George Seibold, again, is  
23 the man with that answer.

24 MR. SEIBOLD: George Seibold, PSEG  
25 Nuclear.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1                   We have done the inspections, and we have  
2 noted some deterioration down there. We have provided  
3 operability determination, and we will be doing  
4 follow-up inspections to make sure those supports are  
5 maintained.

6                   We have in the past repaired some of those  
7 supports. So, we now have instituted a PM for when  
8 they de-water those bays, that we specifically -- they  
9 de-water the bays for mechanical components, and now  
10 we are making sure a structural engineer also goes  
11 down into the service water intake bays to do his  
12 inspections.

13                   MR. BARTON: Thank you.

14                   MR. SEIBOLD: And it is also one of the  
15 enhancements in the structural monitoring program  
16 that, besides those components, he just does general  
17 inspections of the de-watered bay.

18                   MR. BARTON: Thank you.

19                   In your small bore Class 1 piping  
20 inspection, you committed to do 100 percent inspection  
21 of all accessible Class 1 socket welds in the research  
22 system. How large a sample is that? Because you're  
23 talking about accessible. How many welds do you think  
24 you're talking about here?

25                   MR. SOSSON: We have the exact number.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Paul Cervenka?

2 MR. CERVENKA: My name is Paul Cervenka.  
3 I am a member of the license renewal project team.

4 That weld population is 60 welds.

5 MR. BARTON: Okay. I wanted to make sure,  
6 since you said it was accessible, it wasn't one to  
7 five.

8 (Laughter.)

9 Thank you, Paul.

10 MEMBER ARMIJO: Have you ever failed any  
11 of those welds?

12 MR. SOSSON: There has been, earlier in  
13 plant life, small bore socket failures which have been  
14 subsequently addressed by design improvements to  
15 change the structural residence --

16 MEMBER ARMIJO: Were they fatigue-related?

17 MR. SOSSON: Yes, they were high-cycle  
18 fatigue-related.

19 MEMBER ARMIJO: Okay.

20 MEMBER SIEBER: So you put supports in?

21 MR. SOSSON: Yes, we changed --

22 MEMBER SIEBER: You changed the length of  
23 the pendulum?

24 MR. SOSSON: Yes.

25 MEMBER SIEBER: Okay.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 CHAIRMAN SHACK: As I read that, I  
2 couldn't -- is that a periodic inspection or is that a  
3 one-time inspection?

4 MR. CERVENKA: Paul Cervenka, member of  
5 the license renewal project team.

6 The 60 welds will be inspected during a  
7 10-year period prior to the period of extended  
8 operations. So, if there are any problems, we will  
9 identify them upfront.

10 MEMBER STETKAR: Oh, is it only one? It's  
11 not --

12 MR. CERVENKA: It's all the time with 100  
13 percent recirc --

14 MEMBER STETKAR: Okay.

15 MR. STAVELY: And if we find any  
16 indications on those examinations, it goes in our  
17 corrective action program, and we are back at it.

18 MEMBER STETKAR: I have one last really  
19 off-the-wall question. In a fuel oil chemistry  
20 program there is an enhancement that says you're going  
21 to, for filtering for particulates, you are going to  
22 use a filter with a pore size of 3 microns, which,  
23 indeed, is consistent with the GALL recommendations,  
24 instead of 0.8 microns.

25 Now a lot of applicants are going to the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 smaller filter size recommended by a different ASTM  
2 standard to try to capture more particulates. You  
3 seem to be going in the opposite direction, at least  
4 the way I read it. And I was curious, why? Was that  
5 an active decision or is --

6 MEMBER ARMIJO: It still meets the  
7 requirement.

8 MEMBER STETKAR: I know it still meets the  
9 requirements, but I was curious why.

10 MR. STAVELY: Do you have the reference as  
11 to which --

12 MEMBER STETKAR: Well, I didn't have the  
13 LRA in front of me. It is AMPB-2.1.20, and I'm  
14 excerpting the stuff that I read out of the SER. So,  
15 I might be mischaracterizing it.

16 MR. STAVELY: I'm not sure. I think  
17 that's one we would have to get back, if we could get  
18 back to you at break?

19 MEMBER STETKAR: The way I read it, it  
20 sounded like -- I wasn't sure what you're using now,  
21 but the enhancement says the modification consists of  
22 using a filter with a pore size of 3 microns instead  
23 of 0.8 microns.

24 Then, because this is from the SER, it  
25 says the staff compared these enhancements to GALL and

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 concluded that 3 microns is consistent with GALL.

2 MR. STAVELY: If you would like, we can  
3 get an answer back for you on that.

4 MEMBER STETKAR: Page 101.

5 MR. STAVELY: Okay, I don't have that one  
6 with me.

7 MEMBER STETKAR: It is a real minor one.  
8 It just struck me because we have seen several where  
9 people have said, well, we are going to follow this  
10 other standard, and people have noted it as an  
11 exception, but the staff says, well, yes, it is an  
12 exception, but it is more conservative, so it is okay.

13 MR. STAVELY: We have an engineer right  
14 now looking for that.

15 Do you have an answer, Pete, or do you  
16 want a little more time?

17 MR. TAMBURRO: I could provide that at the  
18 break.

19 This is Pete Tamburro with the license  
20 renewal project team.

21 I will provide it after break.

22 MEMBER STETKAR: Okay. Thanks.

23 MEMBER SIEBER: What's the fuel oil tank  
24 material? Is that stainless?

25 Fuel oil, typically, all the water goes to

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the bottom of the tank, and the line that you usually  
2 use to sample is about 6 inches off the bottom. So  
3 you don't know whether you've got a layer of water  
4 down there or not.

5 A lot of people have stainless steel  
6 tanks, but that doesn't help because you have got  
7 concentrations over the years of chlorides down there.

8 MR. BARTON: The Boral Monitoring Program,  
9 how does that work? There's seven sites across the  
10 country. You're not one of them, but, yet, that  
11 supposedly is a program that is acceptable?

12 MR. STAVELY: The basis for our program is  
13 that BWR Boral coupons constitute a single population  
14 with common characteristics. So, if it is a single  
15 population, we can monitor the testing results at  
16 other BWRs with Boral, and ascertain the performance  
17 of our Boral through those.

18 The seven plants you are speaking about  
19 is, what we will do at least every two years for our  
20 commitment is we survey the plants, the BWR plants,  
21 that use Boral and ask if they have had a testing  
22 sequence since the last time we contacted them. And  
23 they request copies of the reports.

24 So, the plants that we can use from report  
25 to report may change. So we try to get the most

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 recent inspection data.

2 MR. BARTON: Okay.

3 MEMBER ARMIJO: But you don't do any  
4 evaluation yourself?

5 MR. STAVELY: So far, the way the program  
6 is set up, we monitor the inspection results at other  
7 plants. We also monitor any operational problems in  
8 our spent fuel cool racks; for example, difficulty  
9 inserting or removing a fuel assembly that could be  
10 traced to Boral problems.

11 We also monitor our water chemistry,  
12 including aluminum, boron, and lithium, to see if  
13 there's any signs of a chemical degradation of our  
14 Boral.

15 We have a set of triggers in our program  
16 that, if we hit a trigger, then we will sample, we  
17 will test our own coupons. So far, we have not hit  
18 any of those triggers, so we have not tested our  
19 coupons.

20 However, we still have the trees that are  
21 in the spent fuel cool racks, and we are radiating the  
22 trees, so that if we need to perform our own coupon  
23 inspections, the trees are representative and we can  
24 do our own coupons.

25 MR. BARTON: Okay. Thank you.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 CHAIRMAN SHACK: Any additional questions?

2 (No response.)

3 Well, then, thank you very much for a very  
4 good presentation.

5 And it's time for a break. We will even  
6 take a full 15 minutes, even though we are running  
7 late.

8 (Whereupon, the foregoing matter went off  
9 the record at 3:05 p.m. and went back on the record at  
10 3:20 p.m.)

11 CHAIRMAN SHACK: Let's come back into  
12 session.

13 If we can just hold up for a second, the  
14 licensee says -- or the applicant (laughter) would  
15 like to answer the questions. And I thought we would  
16 just do that before we started the staff's  
17 presentation.

18 MR. DAVISON: Yes, thank you. Paul  
19 Davison from PSEG Nuclear.

20 We are prepared to answer the three  
21 questions.

22 The first question will be answered by Mr.  
23 Randy Schmidt.

24 MR. SCHMIDT: Randy Schmidt, PSEG Nuclear.

25 There are 386 components in the IGSCC

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 program. The IGSCC program is an augmented program to  
2 the ASME Section XI ISI program. These 386 components  
3 were categorized in accordance with Generic Letter  
4 8801 --

5 MR. DAVISON: Excuse me, Randy.

6 Paul Davison from PSEG Nuclear.

7 Could you please restate the question for  
8 the record and for everyone, to make sure we are  
9 clear? Thank you.

10 MR. SCHMIDT: I believe the question was,  
11 what are these 368 welds and why so many?

12 CHAIRMAN SHACK: Yes, when you have  
13 essentially mitigated, I would have thought, with two  
14 things, which would get them off the augmented  
15 inspection list, because that was the real gist of my  
16 question.

17 MR. SCHMIDT: The majority of the 386  
18 components are IGSCC-resistant and classified as  
19 Category A.

20 CHAIRMAN SHACK: Oh, okay. Okay.

21 MR. SCHMIDT: Okay? So, they are still in  
22 the augmented program.

23 CHAIRMAN SHACK: They're still in the  
24 program, but --

25 MR. SCHMIDT: They're Category A. There's

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 364 components to Category A. So, there's only 22  
2 non-Category A.

3 CHAIRMAN SHACK: Okay. Okay, that's an  
4 understandable number.

5 MR. SCHMIDT: Okay.

6 CHAIRMAN SHACK: Thank you.

7 MR. TAMBURRO: My name is Pete Tamburro,  
8 and I work for the Hope Creek licensing renewal  
9 project.

10 The second question I am going to answer  
11 is, what are the materials of the tanks that store  
12 fuel, diesel fuel oil? They are all carbon steel  
13 tanks.

14 The third question related to, why did we  
15 go from a 3.0-micron specification to a 0.8  
16 specification? That's the other way around. I  
17 apologize.

18 It's really an improvement. With the 0.8-  
19 micron particulate, you are looking from zero to 0.8.

20 The new enhancement would look from a zero size to  
21 3.0 microns. So, we will be looking at larger  
22 particles with a wider range.

23 MEMBER STETKAR: Could you explain that to  
24 me, how that works? Why do you capture, why don't you  
25 capture -- let me say this: with a 3-micron filter

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 size, how can you capture 2.9-micron-sized particles?  
2 Don't they go through?

3 MR. TAMBURRO: That's right, and that's  
4 what you end up sampling. Your sample is on the other  
5 side of the pores, the pore side of the filter. It  
6 gets through, and that's what you send.

7 MEMBER STETKAR: I didn't know that was  
8 the way it was done. Because every other one that I  
9 have seen has said it is conservative to use the  
10 smaller filter size because you trap more of the  
11 particulates. So, therefore, you have evidence of a  
12 broader range of particulates.

13 MR. TAMBURRO: With the new method, you  
14 would have particulates from zero to 3.0 microns in  
15 diameter, the sample.

16 CHAIRMAN SHACK: Okay, it is a sampling  
17 program? It's not an actual filter of the fuel. It's  
18 the sampling program.

19 MEMBER STETKAR: Well, but the other ones  
20 give you -- I have not read the procedures. The other  
21 ones give you the impression that you collect stuff on  
22 the filter, and that's your sample.

23 CHAIRMAN SHACK: Yes.

24 MEMBER STETKAR: So, therefore, a 0.8-  
25 micron filter will collect more material, and that's

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 conservative. They always characterize a .8-micron  
2 filter size as a conservative compared to the GALL. A  
3 number of applicants have taken an exception to GALL.

4 By using the .8-micron filters, they have to justify  
5 the exception. The exception is, well, it's  
6 conservative because we will trap more stuff, and  
7 therefore, our sample will be more conservative. And  
8 I can understand, if you are sampling downstream from  
9 the filter, the reverse is true. So, okay.

10 CHAIRMAN SHACK: You are sure you are  
11 sampling downstream from the filter? You are not  
12 scraping the stuff off the filter and looking at it?

13 MR. TAMBURRO: We are sure we are sampling  
14 downstream of it.

15 CHAIRMAN SHACK: Okay. Thanks.

16 I think we can begin the staff's  
17 presentation.

18 Brian, are you going to have opening  
19 words?

20 MR. HOLIAN: Yes, I have just a few  
21 opening remarks.

22 Again, my name is Brian Holian. I am  
23 Director, Division of License Renewal.

24 At that table for the staff, once again,  
25 we have a couple of names I have mentioned, but I want

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 to mention a few more that we have sent up.

2 Bill Holston is a Senior Reviewer for  
3 buried piping. You have heard him at a couple of the  
4 previous Subcommittees on the previous plans, and has  
5 had the lead technical review on buried piping.

6 Dr. Allen Hiser is our Senior-Level  
7 Advisor in License Renewal. He is up there for  
8 support on a variety of issues, including the small  
9 bore and metal fatigue and other issues.

10 Bennett Brady, our Senior Project Manager  
11 for Hope Creek; Mike Modes, Senior Reactor Inspector  
12 out of Region I, and Arthur Cunanan, New Project  
13 Manager, helping us with slides today.

14 Also, we just want to highlight several  
15 Branch Chiefs. I don't often highlight them, but the  
16 three technical Branch Chiefs are all here today. In  
17 License Renewal, Raj Auluck, Jerry Dozier, and David  
18 Pelton, all in the audience here. They help us with a  
19 lot of the good RAIs that you see. We also have Meena  
20 Khanna from the Division of Engineering here.

21 We get support from several of the  
22 technical offices. So I wanted to highlight them, and  
23 members of their staff are here to assist in this  
24 staff's presentation.

25 A couple of comments, just from the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 earlier presentation.

2 One item that had come up on one of the  
3 questions was a little frustration brought up by the  
4 Committee on the manhole testing timeframe. I just  
5 wanted to comment kind of from my position on that.

6 We also did think, from the staff, that it  
7 was a little bit slow, the industry response to that.

8 So, how do we respond to that?

9 Well, one, we sick our technical Branch  
10 Chiefs on them and say, "Get those RAIs out quickly  
11 and ask them why they're not doing more in a quicker  
12 manner."

13 We coordinate with the region, where that  
14 is necessary, and Mike Modes will be able to give you  
15 a little information from their perspective on that.

16 We also kind of coordinate with NEI. We  
17 have quarterly meetings with NEI. We brought it up  
18 with them, and all the license renewal kind of  
19 community; the plants that are in or are going to come  
20 in attend those.

21 We still thought, even though they are  
22 here at these ACRS meetings often, that it was slow  
23 getting out, the message to get out and look in  
24 advance at these things.

25 From the industry's perspective, you know,

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the arguments I have heard were, "Well, we're not  
2 seeing it so much in our cable failure rates. So the  
3 safety significance is low."

4 I think they also, early on there, were  
5 trying to convince the staff that, well, we think we  
6 can kind of qualify that cable, even though it is not  
7 officially qualified.

8 So, those were a few of the things that  
9 they had. And also, maybe in this plant, a lot of  
10 them just didn't believe they would have water down  
11 there, I think. They were hoping they didn't.

12 I know in this plant I had seen some  
13 pictures that they actually had to carve up some  
14 roadways to get at it, if the pictures are right.  
15 They had to remove some asphalt to get at the covers,  
16 which then were large.

17 So, a lot of things might have added in,  
18 but I was glad that the Committee kind of picked up on  
19 that. From what I have seen from my perspective, I  
20 think the industry has the message on our audits.  
21 They have gotten out ahead and have now gotten to all  
22 of the manholes before we get to the site on our  
23 audits. That wasn't the case here a year, year and a  
24 half ago.

25 NEI did respond to some the staff's

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 concern on this with what they call the -- I had to  
2 write it down -- "regulatory issue resolution  
3 protocol". It is a new thing NEI was doing to try to  
4 get ahead and move faster on these issues. And these  
5 submerged cables was the first one of those.

6 And I will reserve any other judgment on  
7 whether that helped or not, but I wanted to comment on  
8 that from my perspective. We might get into that  
9 more.

10 Second, the applicant's presentation on  
11 drywell, I just wanted to give some kudos to my staff.

12 It was just a couple of days ago that I was briefed  
13 on this emerging inspection that they did in this  
14 outage. I wanted to give credit to Raj Auluck and his  
15 structural people, who have been pushing through the  
16 RAIs to get at and look at a lot of those issues, and  
17 get at UTs. So, hopefully, you see that in the SER,  
18 and the licensee seems to be still taking the good  
19 path.

20 That is not an open item, as we went into  
21 this. We might still have some RAIs. So, I'm giving  
22 the applicant the heads-up on that. As we have seen  
23 this latest operational experience, we will have some  
24 follow-up questions that even the Committee has asked  
25 and some more questions like that.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1           You know, small bore piping came up a  
2 little bit here again with the number, that Hope Creek  
3 volunteered to look at their small bore. That's good.

4           I just wanted to remind the Committee, a month ago  
5 when we were in here -- no, I'm sorry, a few weeks ago  
6 on GALL -- we had supplied this Subcommittee some  
7 more information on the GALL revision on small bore  
8 piping. We tried to get a little bit better from a  
9 couple of weeks ago, where we were on kind of the  
10 program for that. So, the Committee will be seeing  
11 that. I just wanted to mention that.

12           And then, finally, on buried piping, I  
13 will give the Committee a heads-up. As good as the op  
14 experience has been on the Hope Creek side, which you  
15 are hearing this month, it hasn't been too bad, and  
16 you heard some comments on pristine piping and that.

17           Salem is coming next month, and it's not  
18 as pristine. So, I just want to give you a heads-up  
19 on that, and the applicant on that. Salem had some  
20 tough operating experience, and they had no cathodic  
21 protection. So, the staff is still wrestling with  
22 them on kind of the proper position for next month,  
23 and that is Salem.

24           That's it. A little lengthy, but, with  
25 that, I will turn it over to Bennett Brady.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MS. BRADY: Thank you, Brian.

2 As Brian mentioned, I am Bennett Brady. I  
3 have been the Project Manager for the Hope Creek  
4 license renewal review.

5 I would also like to mention my boss and  
6 Branch Chief, Bo Pham, who is there at the table with  
7 Brian, and Arthur Cunanan, who has been my assistant  
8 in the license renewal review for Hope Creek and,  
9 also, for Salem.

10 Also, there are many members of our  
11 technical staff in the audience who participated in  
12 reviewing the application and going on the audits  
13 inspections that we have talked about.

14 Next slide.

15 The applicant has already covered  
16 practically all the topics I am going to talk about.  
17 So, I will try to be brief and not repeat any of the  
18 information they have given you. My discussion will  
19 focus more on our staff reviews and our findings.

20 This shows an outline of our presentation.  
21 It, more or less, followed our Safety Evaluation  
22 Report in its structure. I will talk very briefly  
23 about the overview of Hope Creek license renewal  
24 review, then move to Section 2, where we talk about  
25 the scoping and screening methods and the results.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1           And Mike Modes, the Chief Inspector for  
2 Region I for Hope Creek, will give his presentation  
3 and findings.

4           Then, we will go to Section 3, which is  
5 really the heart and meat of our SER, quite a long  
6 section in which we talk about the aging management  
7 programs and the aging management review results. And  
8 finally, Section 4, the time-limited aging analyses.

9           Next slide, please.

10           I believe the applicant has covered  
11 everything on this slide. I would just mention that  
12 we received the application on August 18, 2009, and we  
13 have proceeded pretty much on schedule in accepting  
14 the application and, then, our review, and coming here  
15 today to speak to you.

16           Next slide, please.

17           This slide shows the major audits and  
18 inspections that were conducted during this review and  
19 the time periods for our review. You will probably  
20 note that the time periods for each of these is a  
21 little bit longer than the usual. That is because we  
22 covered both Salem and Hope Creek, and that is being  
23 reviewed in two different SERs.

24           You will also note that our major audit,  
25 what we call the AMP audit, was in February, the 8th

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 to the 19th. People in this room will probably  
2 recognize this as "the Second Great Snow", also called  
3 the federal government holiday.

4 (Laughter.)

5 For our staff and for the applicant's  
6 staff, it was not a holiday. They kept working  
7 through that period. We were very pleased with that.

8 Next slide.

9 CHAIRMAN SHACK: They didn't have anything  
10 else they could do.

11 (Laughter.)

12 MS. BRADY: But they did a good job.

13 This is our overview of our SER. It was  
14 presented to the applicant on September 30, 2010. We  
15 have one open item, the piping, and two confirmatory  
16 items, which you have already heard some about these,  
17 the inaccessible low-voltage power cables. Both of  
18 these are relatively new issues, and both of them have  
19 arisen from the operating experience. And they have  
20 been presented; I think the first one is probably with  
21 the Cooper license renewal.

22 And then, our last confirmatory item  
23 concerned metal fatigue, in which we are asking the  
24 applicant to provide us a verification that the  
25 locations they selected for their environmentally-

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 assisted fatigue analyses were actually bounding for  
2 Hope Creek.

3 Next slide, please.

4 I would also mention that I should have  
5 mentioned just then that, in addition, we will talk  
6 some about our review of the reactor cavity leakage  
7 that the applicant discussed essentially and our  
8 review of their Section XI IWE program, also, which,  
9 as Brian mentioned, it is not an open item, but it is  
10 an item of interest and an item of continued  
11 discussion.

12 This Section 2 covers our review of the  
13 scoping and screening. The Section 2.1 covers their  
14 scoping and screening methodology. And then, Section  
15 2.2 is the results of their systems and structures  
16 that were screened into the license renewal review.  
17 And then, Sections 2.3, 2.4, and 2.5 present the  
18 results of the mechanical systems, the structures, and  
19 the electrical systems.

20 We didn't have any open items in this  
21 review that were additional components added to the  
22 reactor building and to the power protection system  
23 and other parts, as a result of our review.

24 At this point, I would like Michael Modes,  
25 the Region I Lead Inspector, to present you the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 results of their inspection.

2 MR. MODES: Thank you very much.

3 We performed three weeks of inspection  
4 covering both applications. We did that because there  
5 are always a large number of common aging management  
6 programs when you come to the site with multiple  
7 designs. Similarly, most done with two different  
8 designs had a substantial number of common aging  
9 management programs.

10 So, we tried to choose as many of those as  
11 time would give us, and we, then, tried to sample a  
12 set representatively unique to Hope Creek. And of  
13 course, as always, the 5054(a)(2) nonsafety affects  
14 safety. That takes one inspector an entire week to go  
15 through that, walk down various examples in order to  
16 ascertain whether the three-dimensional interactions  
17 have been accommodated by the applicant.

18 I selected the Boral Program to determine  
19 how the applicant was rolling in an Interim Staff  
20 Guidance and how they were dealing with that. In  
21 order to give it a broad look, we took a brief look at  
22 the feed and condensate system in order to find out  
23 how the aging management programs would address the  
24 aging that we either knew about or the applicant had  
25 discovered in a particular system.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Next slide.

2 These are just some of the examples of the  
3 walkdowns that we did for Hope Creek. We did many  
4 more for Salem as well, which you will hear about next  
5 month.

6 MR. BARTON: Let me ask you a question.  
7 When you walk down to the Hope Creek Station, what's  
8 your overall impression of the anterior condition of  
9 the station?

10 MR. MODES: Very good.

11 MR. BARTON: Thank you.

12 MR. MODES: Next slide.

13 So, one of the issues that came up was the  
14 applicant was following the GALL guidance in order to  
15 determine whether or not they might have selective  
16 leaching. And it was obvious to us, both in the  
17 applicant and based on our own experience with the  
18 facility over time, that they, in fact, had already  
19 experienced leaching.

20 This is, I think, an example of an  
21 applicant who is so good at what they're doing, these  
22 applications, they sometimes find themselves going up  
23 a blind alley. And once we point it out, "Although  
24 your following the GALL is absolutely appropriate and  
25 you did it perfectly, you do have it already, don't

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 you?" And they absolutely agreed, it was for them I  
2 think a "eureka" moment. And they reevaluated it very  
3 quickly and revised their application. But, overall,  
4 a very good application, and we didn't find any  
5 situations where they did not identify aging, and the  
6 54A2 program was very sound.

7 Thank you.

8 MEMBER SIEBER: Actually, it seemed to me  
9 like their analysis was pretty clean as far as based  
10 on what I have read. You did not find a lot of  
11 issues?

12 MR. MODES: No, we did not.

13 MR. HOLIAN: Yes, Bennett, this is Brian  
14 Holian, license renewal, just to add in, I meant to  
15 add that into my opening comments here also. You  
16 know, PSEG, other than I took issue with the cabling  
17 issue and the amount of time there, but, overall, they  
18 have utilized the Exelon team that we are very  
19 familiar with as kind of partners in the license  
20 renewal application. Mike Modes had seen many of the  
21 Exelon plants also come through license renewal. So,  
22 that team approach to this was very beneficial, we  
23 thought, to the application process.

24 MS. BRADY: Thank you, Michael.

25 Moving on to Section 3, in which we talk

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 about the aging management review and discuss the  
2 aging management programs and the results from our  
3 review, the staff in Section 3.0 reviews each of the  
4 applicant's aging management programs, compares these  
5 go GALL, and determines whether they are acceptable.

6 Then, in Sections 3.1 through 3.6, we  
7 reviewed all the line items, over 5000 I believe. We  
8 looked at the intended function of each component,  
9 anterior, environment, the aging management program  
10 the applicant selected, and the safe review, and  
11 determined whether these were acceptable. When they  
12 completely followed the GALL, it was pretty easy.  
13 There were some cases where we had to do more in-depth  
14 review, and these are discussed in our SER.

15 Next slide, please.

16 The applicants also presented this slide  
17 which shows the breakdown of the existing and new, and  
18 how they compared with GALL in terms of exceptions and  
19 enhancements. So, I won't go through that. If  
20 anybody wants to be checking my figures, they come out  
21 right, if you consider the fact that the plant-  
22 specific two programs there, the existing programs  
23 also have enhancements.

24 Moving on to our first open item, the  
25 buried piping and tanks inspection, this is one of the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 issues I mentioned before that has come from our  
2 review of recent operating experience. In response to  
3 this, we have sent out a generic RAI to all the  
4 current applicants asking them to give us their  
5 instances or failures they have had with leaks in  
6 their buried piping programs, and how are they  
7 adjusting their AMPs to take account of this  
8 experience.

9 And the second generic question was, have  
10 you considered the industry operating experience with  
11 buried piping and leaks and modified your AMP for  
12 this? We sent out the generic RAI. They provided  
13 their response on September 1. Since then, we have  
14 issued a follow-up RAI.

15 We found that we needed more information  
16 on the material of these pipes, whether they had  
17 cathodic protection. Did they have hazardous material  
18 in the pipes? And they sent their response in by  
19 Friday, October 29th, and the staff will be reviewing  
20 that.

21 The next item, please.

22 This is our confirmatory item that has  
23 already received an extensive amount of discussion.  
24 As I mentioned before, this was a late-arriving issue,  
25 and also it was based on the operating experience.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1           The GALL medium-voltage program came out  
2 in 2005 with GALL Revision 1. Since that time, the  
3 NRC has issued Generic Letter 2007-01 on inaccessible  
4 underground power cable failures.

5           In that Generic Letter, they asked  
6 licensees to report on any failures they had of cables  
7 over a much wider range. As a result of this, the  
8 staff found that there were failures in those lower-  
9 voltage ranges. And when we looked at the data and  
10 the distribution, we found that there were increasing  
11 failures and they seem to occur for plants for cables  
12 that have been in service from six to ten years.

13           In view of that, we asked that the  
14 applicants add these lower-voltage cables to their  
15 medium-voltage cable program, and we asked that they  
16 increase the frequency of their cable testing and  
17 manholes inspections to a minimum of every six years  
18 of testing the cables and a minimum of every year for  
19 inspecting the manholes. I think we have had a  
20 considerable discussion on that.

21           The applicant has submitted their change  
22 in the program. It includes these lower-voltage  
23 cables. It eliminates an exclusion that was in the  
24 GALL program for cables not exposed to significant  
25 voltage, and it increased the testing frequency of the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 cables to every six years, inspections of the manholes  
2 at least every year.

3 MEMBER STETKAR: Bennett, before you go to  
4 the next one, I would like to hear from the staff.  
5 This is an issue that we are discussing in the context  
6 of license renewal. The period of extended operation,  
7 if the license renewal is granted, does not start for  
8 another 15 years and five months from now.

9 What is the staff doing in the interim to  
10 address this issue? I don't know whether Michael is  
11 the best person or Brian, or someone. I understand  
12 what the applicant is proposing to do starting 15-and-  
13 a-half years from now. How are you following this  
14 issue today?

15 MR. DOUTT: Cliff Doutt, DLR.

16 That is the Part 50 question.

17 MEMBER STETKAR: Right.

18 MR. DOUTT: As far as operating here --  
19 and Mike can probably fill in, too -- but there was an  
20 inspection report. There was a violation, uncited,  
21 for the service water. There's corrective action that  
22 was implemented for that.

23 So, in the Part 50, there are corrective  
24 actions being done, which is either pumping the  
25 annulus out, defining the frequency, testing the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 cables, determining what test frequency is required,  
2 and going forward. All of that, essentially, should  
3 set up a baseline for license renewals to what this  
4 frequency would be.

5 When they revise the LRA to include low  
6 voltage, they get rid of the 25 percent exclusion and  
7 increase the test frequencies. Those are maximum.  
8 So, at some point, they are going to have to establish  
9 a frequency that fits whatever the operating  
10 experience is of the plant.

11 MEMBER STETKAR: Yes, I guess I understand  
12 that. And I understand that, right at the moment, I  
13 guess even as we speak, they are inspecting those  
14 service water ducts, I think they said weekly.

15 Is there anything -- and I don't know  
16 what capabilities you have in the reactor oversight  
17 process -- to address the issues of more proactive  
18 keeping the cables dry and the watering systems --

19 MR. HOLIAN: Yes, we also have Roy Mathew  
20 here also.

21 Go ahead, Cliff.

22 MEMBER STETKAR: It is a bit outside the  
23 scope of this meeting, but --

24 MR. HOLIAN: No, it is a good issue. We  
25 brought it up at previous meetings.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 This is Brian Holian, License Renewal.

2 Roy Mathew is here from the Division of  
3 Engineering.

4 This is an item that crosses Part 54 and  
5 Part 50 space. We have several of those, buried  
6 piping, and we feel we are leading in license renewal  
7 space now.

8 The NEI initiative is in-house. It's  
9 being reviewed. We have similar reviewers that work  
10 with license renewal staff, and we have a tech staff  
11 still looking at the industry initiative and what they  
12 will commit to, because we are very cognizant of we're  
13 capturing the plant's in-house, say on sand-buried  
14 piping. How am I getting the plants that went  
15 previously? So, the staff has those on our plate.

16 Here I know we mentioned it, but it has  
17 probably been at least four months ago, several  
18 meetings ago, that we did expand the ROP to have  
19 inspectors look at, now on a sampling basis, these  
20 manholes. So, that was an issue that crossed over  
21 several months back.

22 Roy, you might also talk with the issues  
23 we are doing with the Reg Guide on cable testing and  
24 that under Part 50.

25 MEMBER STETKAR: And quite honestly, I

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 wouldn't have brought it up necessarily in this forum  
2 if the period of extended operation were starting a  
3 year from now.

4 MR. HOLIAN: Yes, yes.

5 MEMBER STETKAR: But we are --

6 MR. HOLIAN: Extending time, yes.

7 MEMBER STETKAR: -- really, really far  
8 away right now.

9 MR. MATHEW: Yes, this is Roy Mathew from  
10 the Division of Engineering.

11 Actually, we are taking a number of  
12 actions from a Part 50 perspective. On the reactor  
13 oversight process, we have an inspection procedure to  
14 go back and look at manholes on a routine basis. We  
15 have identified some issues. We have issued,  
16 actually, a Region has issued several findings.  
17 That's another thing.

18 The staff portion from a Part 50 point of  
19 view is the licensees have to maintain the cables in  
20 the environment for which they are designed. So, as  
21 far as staff knows, all the cables are designed only  
22 for the right environment. So, if the licensees are  
23 violating that, we will enforce them. That is another  
24 thing we are doing, enforcement aspect through  
25 inspection.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1           Then, staff is issuing a Reg Guide to  
2 give, let's say, the staff version, which is  
3 consisting of mandating a condition monitoring  
4 program. The Reg Guide is going to give the criteria  
5 or the limits for a good condition monitoring. So,  
6 that involves testing and all kinds of attributes that  
7 consist of good cable condition, much broader.

8           That Reg Guide is already issued. We got  
9 comments from the industry. We are in the process of  
10 finalizing it. Most likely, that will be issued by  
11 January of next year.

12           MEMBER STETKAR: Michael, if you could,  
13 just make a note that we probably would like to see  
14 that.

15           MR. BENSON: Okay.

16           MR. MATHEW: Anybody else have any other  
17 questions?

18           MEMBER STETKAR: No, thanks.

19           MR. MATHEW: Okay.

20           MEMBER STETKAR: Thank you very much.

21           MS. BRADY: Thank you. If there are no  
22 other questions, we received the licensee's commitment  
23 on this, and it contains the four elements that we  
24 have been seeking.

25           Next slide, please.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1           On this topic, already we talked a lot  
2 about it, and I thought I would talk a little bit  
3 about our staff review of this, the ASME Section XI,  
4 IWE program and the reactor cavity leakage.

5           This issue probably had more RAIs, follow-  
6 up RAIs, and discussion than any of the other issues  
7 during our review. We were concerned about the leak  
8 from the penetration and why it was caused, what was  
9 causing it.

10           During our review, we asked the applicant  
11 to do a number of modifications to this program. I  
12 think the original IWE Section XI program had six  
13 enhancements to it. When we got through, there were  
14 10 enhancements.

15           In response to our questions, they agreed  
16 to monitor the penetration sleeve and repair it, if  
17 possible, and if not possible, to continue to look  
18 into the cause of it. They also committed to do UT  
19 inspections of the drywell.

20           They have informed us. We have had two  
21 briefings since this recent outage in which they have  
22 told us about the leaks. We are very pleased to see  
23 that there are some fruits coming from our persistence  
24 on their monitoring and UT. We think this will be  
25 helpful to them in planning their future inspections

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 at the next outage. We will continue having  
2 discussions with them and listening to what their  
3 plans are addressing this issue.

4 Are there more questions of the staff?

5 (No response.)

6 Next slide, please.

7 The last major section of our SER concerns  
8 the time-limited aging analysis. We have one  
9 confirmatory item from this section.

10 Next slide.

11 That concerns the metal fatigue analyses.

12 The applicant, in selecting the locations of their  
13 metal fatigue analysis and the environmentally-  
14 assisted fatigue analyses, had used the suggested  
15 locations in NUREG/CR-6260. This is all of the  
16 generic locations for the environmentally-assisted  
17 fatigue analyses.

18 When we were reviewing the SER, we noted  
19 that there were some other components that had higher  
20 cumulative usage factors than those that were actually  
21 selected for the environmentally-assisted fatigue  
22 analyses. We have asked the applicant to verify that  
23 the locations selected were bounding compared to other  
24 locations that they might have selected. And I think  
25 the applicant said that we will be receiving their

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 response around the middle of this month.

2 CHAIRMAN SHACK: Okay. Well, I had what I  
3 questioned before. Do you think using the CUF from  
4 the design basis calculations is a good way to pick  
5 bounding locations?

6 MS. BRADY: That is a good question.

7 (Laughter.)

8 DR. HISER: We find it hard to ignore if  
9 they have a location that has a very high CUF, .8, for  
10 example, and using a location that has a CUF of .00-  
11 something. I mean it needs to be rationalized as to  
12 why the one location bounds the other.

13 CHAIRMAN SHACK: But you were expecting  
14 them to do all the 6260 locations plus --

15 MS. BRADY: Plus --

16 CHAIRMAN SHACK: -- additional locations?

17 DR. HISER: Right. The concern that we  
18 have is that there they may be plant-specific  
19 locations at Salem or at other plants that may be more  
20 bounding than 6260.

21 CHAIRMAN SHACK: But this way, you will at  
22 least have a reasonable sample of locations,  
23 including --

24 DR. HISER: That's correct.

25 CHAIRMAN SHACK: -- the 6260.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 DR. HISER: This is Allen Hiser, the  
2 Division of License Renewal.

3 CHAIRMAN SHACK: I must confess I don't  
4 have a better way of coming up with bounding  
5 locations, either, but I can always throw rocks at it.

6 (Laughter.)

7 DR. HISER: We don't want to throw rocks.  
8 We just want a good technical basis for why the way  
9 they have analyzed does bound the locations in the  
10 plant that could be important.

11 MS. BRADY: I would also like to mention  
12 that we have asked the same question for Salem on  
13 their analyses, and we will most likely be asking this  
14 to all future applicants.

15 DR. HISER: What we have found is plants  
16 have done 6260, the GALL report says "as a minimum",  
17 and that was where they terminated the discussion.  
18 Our concern is that there may be plant-specific  
19 locations again. So, we want licensees or applicants  
20 to address that.

21 MS. BRADY: The final slide.

22 On the basis of our review and pending  
23 satisfactory resolution of the open and confirmatory  
24 items, the staff determines that the requirements of  
25 10 CFR 54.29(a) have been met for the license renewal

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



1 of Hope Creek Generating Station.

2 That concludes my presentation. We will  
3 be coming back to the ACRS in March, I believe it is,  
4 with our final report.

5 DR. HISER: Can I just make one -- yes,  
6 one item that was discussed earlier today was the  
7 Boral program. I think the applicant indicated it was  
8 a program where they would not do plant-specific  
9 testing but would monitor information from other  
10 plants.

11 In a response dated May 11, they did  
12 indicate that they would modify their program to  
13 include testing of one coupon prior to PEO, and then  
14 one coupon every 10 years. So, they will be doing  
15 monitoring. That is the staff's expectation at all  
16 plants, that they either will have monitoring through  
17 coupons or they will do some in situ measurements.

18 MEMBER ARMIJO: And what kind of tests  
19 will they do?

20 DR. HISER: What they indicated here was  
21 conventional and neutron attenuation measurements.  
22 There again, it was just confirm that the assumptions  
23 in their criticality calculations are maintained.

24 CHAIRMAN SHACK: Are there any other  
25 questions for the staff?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 (No response.)

2 Well, if not, thank you very much for a  
3 concise and elegant presentation.

4 Adjourned.

5 (Whereupon, at 3:59 p.m., the proceedings  
6 in the above-entitled matter were adjourned.)

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701



# Hope Creek License Renewal

ACRS Subcommittee  
November 3, 2010



# Agenda

Introductions – Paul Davison, Vice President, Operations Support

Site Description – Greg Sosson, Director, Engineering Services

Operating History – Greg Sosson

License Renewal – Jim Stavely, Manager, License Renewal

- Inaccessible Power Cables Jim Stavely
- Environmentally Assisted Fatigue Jim Stavely
- Buried Piping Program Jim Melchionna

Topic of Interest:

- Mark I Containment Greg Sosson

Closing Comments – Paul Davison

# Site Description



# Hope Creek Operating History

Initial Operating License at 3293 MWt	1986
Hydrogen Water Chemistry	1993
Measurement Uncertainty Recapture to 3339 MWt	2001
Generator Step Up Transformer Replacement	2004
LP Turbine Rotor Replacements	2004
'B' Recirculation Pump Rotating Assembly Replacement	2006
Initial Noble Metals Treatment	2006
HP Turbine Rotor Replacement	2007
'A' Recirculation Pump Rotating Assembly Replacement	2007
Extended Power Uprate to 3840 MWt	2008
Unit Capacity Factor (18 month)	92.3%
LRA Submitted	08/18/2009
Current License Expires	04/11/2026



# License Renewal

Jim Stavely

Manager, License Renewal

PSEG Nuclear



- **33 Existing Aging Management Programs**
  - 16 programs had no changes required
  - 17 programs required enhancements to align with GALL
  - 7 of these 33 programs had exceptions
- **14 New Aging Management Programs**
  - 1 of these 14 programs had an exception



- **53 License Renewal Commitments**
- **Commitment Management**
  - Process consistent with NEI 99-04, Revision 0, “Guidelines for Managing NRC Commitment Changes”
  - Commitments tracked using SAP Database System
  - Implementing documents (e.g. procedures, work orders) annotated with commitment references
  - Implementation has begun well in advance of PEO
  - Station & Corporate positions created to coordinate commitment implementation

- **Confirmatory Items**

- **CI 3.0.3.1.20-1**

## **Inaccessible Power Cables**

The Staff and the Applicant have reached an agreement regarding the Applicant's proposed frequency for manhole inspections and cable testing

- **CI 4.3.5.2-1**

## **Environmentally Assisted Fatigue**

The Staff requested confirmation that the limiting location per NUREG-6260 was bounding as compared to other plant specific locations

- **Open Items**

- **OI 3.0.3.1.2-1**

## **Buried Piping Program**

The Staff required additional information to evaluate the Applicant's consideration of recent industry operating experience on buried and underground pipe leakage



## Hope Creek Buried Pipe Program (BPP)

James A. Melchionna  
Corporate BPP Program Manager  
PSEG Nuclear

# Buried Pipe Program

- Scope
  - Includes all buried piping systems at Hope Creek, 3 are in-scope for License Renewal
- Risk Ranking
  - The program has risk ranked all buried piping segments according to their relative susceptibility and consequences using NACE and EPRI guidance
- Inspections
  - Focused inspections based on risk rankings
  - Opportunistic inspections when excavations created for reasons other than pipe inspections
- Corrective Action Program
  - Off normal findings are entered into the site CAP
  - For deficiencies, cause is determined and corrective actions developed
  - Extent of condition based on inspections, similar configurations, and environments
  - Industry OE is reviewed and input into the CAP
- NEI Initiative
  - In response to industry operating experience, NEI has established an industry initiative on buried piping integrity (NEI 09-14)
  - PSEG is implementing the industry initiative

# Buried Pipe Program – License Renewal Inspections

Materials	Systems	Inspections Prior to PEO and Every 10 Years Thereafter
Carbon Steel	Fire Protection Service Water	Two
Gray Cast Iron	Fire Protection	One
Ductile Cast Iron	Fire Protection	One
Pre-stressed Concrete	Service Water	One
Stainless Steel	Condensate Storage & Transfer Fire Protection	One

- OI 3.0.3.1.2-1: Staff requires additional information to evaluate applicant's consideration of recent industry operating experience on buried and underground pipe leakage
  - Hope Creek provided information on October 29, 2010 in response to RAI B.2.1.24-02:
    - Provided details on planned inspections
    - Confirmed annual testing of the Cathodic Protection System
    - Provided details on the quality of backfill around buried piping

## Conclusions - Buried Pipe Program

- The BPP is comprehensive and robust
- The BPP will continue to develop and improve based on site and industry operating experience, the NEI initiative, and new technology
- The Program will manage the material condition of buried pipe
- The BPP is an effective aging management program to ensure continued safe operation



# Hope Creek License Renewal

Topic of Interest:

Mark I Containment

Greg Sosson

Director, Engineering Services


PSEG Nuclear




# Mark I Containment

- Conducted an assessment of the Mark I Primary Containment based on operating experience
- The Hope Creek Drywell is in good condition
  - Confirmatory UT readings were performed
  - One small reactor cavity leak
  - One drywell shell area of interest identified

# Mark I Containment




# Mark I Containment




# Drywell / Reactor Cavity Seal Area

DETAIL A



# Lower Drywell Area







# Reactor Cavity Leak

- Leakage is very small
- Goal is to identify the leakage source and repair the leak
- Actions initiated to monitor the leakage and its effects until the leak is repaired ( IWE Commitment 28 )
  - Perform ultrasonic thickness measurements of the drywell shell below penetration sleeve
  - Monitor water leakage when the reactor cavity is flooded up
  - Confirm the drywell air gap and reactor cavity seal rupture drain lines are clear and the monitoring instrumentation is functioning properly

# Reactor Cavity Leak – 2010 Refueling Outage Update

- Leakage identified at J-13 & J-14 penetrations when reactor cavity filled with water
- Performed boroscope exams in the J-13/14 penetration area
  - Confirmed no obstruction in the air gap
  - Small amount of leakage runs below J-13/14 penetration area but not on the drywell shell in the visible area
- Performed UT exams of shell above, around and below J-13/14 penetration area, and complete circumference of drywell shell at floor junction
  - UT measurements indicate greater than nominal plate thicknesses in all areas except lower portion of plate below J-13/14 penetration
- Actions underway to identify leakage source to allow repair

# Drywell Shell UT Summary of Potentially Wetted Area – 2010 Outage



Inches above floor	# of UT's	Average (inches)
96"	8	1.495"
84"	8	1.513"
72"	8	1.502"
60"	8	1.508"
48"	8	1.504"
36"	8	1.501"
24"	8	1.492"
14"	7	1.495"
8"	7	1.494"
2"	9	1.490"

**84 UT's**


High	3.269"
Ave	3.110"
Low	3.066"

**3.0" Plate Tolerance:**  
2.99" - 3.19"

**Analyzed Thickness:**  
2.9375"

**1.5" Plate Tolerance:**  
1.49" - 1.69"

**Analyzed Thickness:**  
1.4375"





## Conclusion - Drywell Condition

- Drywell is in good condition
- A small reactor cavity leak is being managed in the Corrective Action Program and in accordance with our license renewal commitments
- We have effective aging management programs to ensure continued safe operation



# Hope Creek License Renewal

ACRS Subcommittee  
November 3, 2010





**Advisory Committee on Reactor Safeguards (ACRS)  
License Renewal Subcommittee  
Hope Creek Generating Station (HCGS)**

**Safety Evaluation Report (SER)  
with Open Items**

November 3, 2010

Bennett M. Brady, Project Manager  
Office of Nuclear Reactor Regulation

# Presentation Outline

- Overview of HCGS license renewal review
- SER Section 2, Scoping and Screening review
- The Region I License Renewal Inspection
- SER Section 3, Aging Management Programs and Aging Management Review Results
- SER Section 4, Time-Limited Aging Analyses (TLAAs)

# Overview (LRA)

- License Renewal Application (LRA) submitted August 18, 2009
  - Applicant: PSEG Nuclear LLC (PSEG)
  - Facility Operating License No. NPF-57 expires April 11, 2026
- Approximately 40 miles from Philadelphia, PA and 8 miles from Salem, New Jersey,
- BWR with a Mark I containment.

# Audits and Inspections

- **Scoping and Screening Methodology Audit**
  - January 11-20, 2010
- **Aging Management Program (AMP) Audits**
  - February 8 -19, 2009
- **Region I Inspection (Scoping and Screening & AMPs)**
  - June 7 -10, June 21 – 24, and August 9 -12, 2010

# Overview (SER)

- Safety Evaluation Report (SER) with Open Items issued September, 2010
- SER contains 1 Open Item (OI):
  - Given recent industry events involving leakage from buried and underground piping, the staff needs additional information (OI 3.0.3.1.2-1)
- SER contains 2 Confirmatory Items (CIs):
  - Incorporation of inaccessible low voltage power cables in aging management program (CI 3.0.3.1.20-1)
  - Confirmation that locations selected for the environmentally assisted fatigue analyses were bounding for Hope Creek (CI 4.3.5.2-1)

# SER Section 2 Summary

## Structures and Components Subject to Aging Management Review

- Section 2.1, Scoping and Screening Methodology
  - Methodology is consistent with requirements of 10 CFR 54.4 and 54.21
- Section 2.2, Plant-Level Scoping Results
  - Systems and structures within the scope of license renewal are appropriately identified in accordance with 10 CFR 54.4
- Sections 2.3, 2.4, 2.5 Scoping and Screening Results
  - SSCs within the scope of license renewal are appropriately identified in accordance with 10 CFR 54.4(a), and those subject to an AMR in accordance with 10 CFR 54.21(a)(1)



# Regional Inspection

- Three Weeks of Inspection
  - Most of the Common Aging Management Programs for Hope Creek and Salem.
  - Representative Unique Programs
  - 54.4(a)(2) Nonsafety Affects Safety
  - Selected Boral Program to determine response to Interim Staff Guidance
  - Selected System – Feed and Condensate

# Regional Inspection

## Example Walkdowns

Auxiliary Building Service/Radwaste Area

Auxiliary Building Control/Diesel Area, including B EDG

Reactor Building

Hope Creek Turbine Building

Traveling screen spray piping

30"-HZC-019 SACS Heat Exchanger Cross Tie

Fire Barriers

Fire Pumps

Switch Yard

# Regional Inspection

- The application provided operating experience indicating selective leaching had occurred
- Aluminum bronze and gray cast iron have experienced selective leaching
- The applicant re-evaluated the aging management for selective leaching and supplemented the license renewal applications

# Section 3: Aging Management Review

- Section 3.0 – Aging Management Programs
- Section 3.1 – Reactor Vessel & Internals
- Section 3.2 – Engineered Safety Features
- Section 3.3 – Auxiliary Systems
- Section 3.4 – Steam and Power Conversion System
- Section 3.5 – Containments, Structures and Component Supports
- Section 3.6 – Electrical and Instrumentation and Controls System

# SER Section 3

## 3.0.3 – Aging Management Programs

47 Aging Management Programs (AMPs) presented by applicant and evaluated in the SER

	Consistent with GALL	Consistent with exception	Consistent with enhancement	With exception & enhancement	Plant Specific
Existing (33)	13	3	11	4	2
New (14)	9	1			4

# **SER Section 3 Open Items**

## **Buried Piping and Tanks Inspection**

### **OI 3.0.3.1.2-1**

- Staff has noted a number of recent industry events involving leakage from buried and underground piping/tanks
- Staff is concerned about continued susceptibility to failure of buried/underground piping within the scope of license renewal
- Staff issued as RAI on August 6, 2010; applicant responded on September 1, 2010; staff issued a follow-up RAI on October 12, requesting additional information on material composition of piping, portions of piping that are cathodically protected, possible hazardous material in in-scope buried pipes, and quality of backfill
- Staff will review the RAI response received October 29

# **SER Section 3**

## **Confirmatory Item**

### **Inaccessible Low Voltage Power Cables**

#### **CI 3.0.3.1.20-1**

- Staff has noted a number of recent industry events where water or moisture has contributed to failures of inaccessible power cables at lower voltages (480 V to 2kV)
- Low voltage power cables response received October 7
  - Expanded scope of Inaccessible Medium Voltage Cables AMP to include low voltage power cables
  - Eliminated exclusion of cables not exposed to significant voltage
  - Increased testing of cables and inspection of manholes to at least every six years and every year, respectively.
- Staff has received the applicant's response and commitment

# **SER Section 3 Item of Interest**

## **Review of ASME Section XI, IWE Program and Reactor Cavity Leakage**

- The staff reviewed this program (SER Section 3.0.3.2.13) and the small leak from a penetration in the reactor drywell that occurs only when the reactor cavity is flooded
- In response to staff requests, the applicant agreed to enhance the ASME Section XI, IWE Program to
  - monitor the penetration sleeve and lower air gap drains for leakage daily during reactor cavity flood up and perform UT inspections of the drywell
  - identify the cause of the leakage and repair it before the period of extended operation or, if not possible, implement IWE augmented inspections and develop a corrosion rate from UT inspections
- The staff will reevaluate commitments based on the new operating experience and consider whether additional actions are required



# SER Section 4: Time-Limited Aging Analysis

- 4.1 Introduction
- 4.2 Reactor Vessel Neutron Embrittlement
- 4.3 Metal Fatigue Analysis
- 4.4 Environmental Qualification of Electrical Equipment
- 4.5 Concrete Containment Tendon Prestress Analysis (not applicable to Hope Creek)
- 4.6 Containment Liner Plate, Metal Containments, and Penetrations Fatigue Analysis
- 4.7 Other Plant-Specific TLAAAs

# **SER Section 4**

## **Confirmatory Item**

### **Environmentally Assisted Fatigue Analyses**

#### **CI 4.3.5.2-1**

- Analyses of the effects of reactor coolant system environment on fatigue life of components were performed for six generic locations identified in NUREG/CR-6260
- The staff noted that there were other components that had higher CUFs
- The staff asked the applicant to verify that the locations selected were bounding as compared to other plant-specific locations.
- The staff is awaiting the applicant's response.

## **Conclusion**

On the basis of its review and **pending satisfactory resolution of the open item and confirmatory items**, the staff determines that the requirements of 10 CFR 54.29(a) have been met for the license renewal of Hope Creek Generating Station.