

**V. C. SUMMER NUCLEAR
STATION
Alpha Hot Leg
Evaluation and Repair**

**Presented to the Office of
Nuclear Reactor Regulation (NRR)
Rockville, MD
November 21, 2000**




Agenda

- Introduction - Greg Halnon
- Characterization of Crack - Terry McAlister
- Repair Details - Framatome Technologies
- Root Cause Status and Schedule - Greg Halnon
- Closing Remarks - Steve Byrne



1403-PD-2



History To Date

- Identified Boric Acid Deposits
- PT Identified Apparent External Crack
- Video From Reactor Vessel Shows Suspicious Circumferential Indication
- External UT Inconclusive
- External Crack Replication Shows No External Macro Crack
- Weep Hole Identified



Status to Date


- Completed ID UT Examination On 11/5.
 - Shows 2.7” Axial Flaw ~ 9° Clockwise from TDC
 - Improved Visual results
- Completed ID Eddy Current Exam on 11/5.
- Completed External PT on 11/12.
 - No Axial Indications Identified
- Spartanburg NDE - RT, Eddy Current, Visual




Characterization of Flaw

Terry McAlister








45° / DUAL ELEMENT BAND OF HIGH AMPLITUDE
COMPLEX LOCALIZED RESPONSES INDICATING
POSSIBLE METALLURGICAL CHANGES OR WELD
REPAIR CAVITY



SUMMARY OF 37° RL DETECTIONS
CW AND CCW DIRECTIONS



SUMMARY OF 70° RL DETECTIONS
CW AND CCW DIRECTIONS



SUMMARY OF 37° AND 70° CW / CCW
OUTLET NOZZLE AT 25° VESSEL AZIMUTH

View From Reactor



Reconciliation of Information

OD UT Results

ID UT Results

Construction RT
Results

93 Inservice
Inspection Results

00 UT & Eddy
Current Results

87 UT

93 UT

Old Video


New Video



Reactor Nozzle Side

Piping Side






Piping Side

Reactor Nozzle
Side




Reactor Nozzle Side



Piping Side





Piping Side

Reactor Nozzle
Side






Piping Side

Reactor Nozzle
Side





RCS pipe side

Air bubble at top of pipe

ID crack

RX vessel nozzle side





Repair Method

Greg Halnon



Repair Method

- Spool Piece
 - Advantages
 - Flaw Preservation Maximized
 - Weld Removal Maximized for Study
 - Validate UT & Eddy Current Results
 - Extent of Condition Better Understood
 - Utilizes Technology From SG Replacements
 - Parallel Work Optimized From Early On



Repair Method

- Spool Piece
 - Challenges
 - Two Large Welds on Large Piece of Steel
 - Weld Shrinkage Effect on RCS
 - Branch Line Effects
 - Steam Generator Bracing
 - Volumetric Examinations
 - Limited Space in Sandbox
 - Dose, Time



Repair Method

- Initial spool piece decision based on:
 - circumferential flaw
 - poor weld contour
 - flaw limited to weld
- Acquired information:
 - axial flaw, approximately 2.7 inches long
 - some extension into the nozzle
- Re-addressed repair decision
 - Local repair alternative assessed and eliminated
 - Advantages: time, dose, eliminates SG movement and weld shrinkage questions
 - Challenges: Weld not removed, flaw preservation, technical justification difficult



Repair Details



Code Applicability - Welding

- ASME Section XI, 1989 Edition, No Addenda
- Construction Code, ASME Section III, 1971 Edition, w/Add. through W'71
- ASME Section XI Code Case N432 - Machine GTAW Temperbead
- Regulatory Guides
 - RG 1.31 - Control Of Stainless Steel Welding
 - RG 1.44 - Control Of The Use Of Sensitized Stainless Steel



RV Nozzle Repair Process

- STEP 1 - SPOOL PIECE REMOVAL
 - Block Piping & Steam Generator
 - Sever Spool at the RV Nozzle
 - Sever Spool on SG Side
 - Rig Out Spool Piece
 - Debur & Clean ID Surfaces
 - Install Shielding Plugs
 - Machine Counterbore



RV Nozzle Repair Process

- STEP 2 - BUTTER NOZZLE
 - Preheat
 - Deposit Counter Bore & ID Buildup
 - Deposit OD Buildup
 - Deposit Buttering on Nozzle
 - PWHT
 - Machine Face for NDE



RV Nozzle Repair Process


- STEP 3 - MACHINE WELD PREPS
 - Machine Buttered Spool Piece End on Shop Lathe
 - Machine Existing Pipe Prep Using Split Lathe
 - Machine Nozzle Prep Using Split Lathe
 - Survey Photogrammetrically & Perform Association
 - Cut Spool Piece to Length
 - Machine Final Spool Piece Prep on Shop Lathe




RV Nozzle Repair Process

- STEP 4 - INSTALL REPLACEMENT SPOOL PIECE
 - Fit Spool Piece
 - Install Purge Device & Purge ID
 - Progressively Tack and Weld Both Spool Welds to 3/4” Deposit
 - UT Root Area
 - Complete Alloy 52 Weld
 - Complete 308L Weld









SPOOL PIECE REMOVAL





RV NOZZLE BUTTERING





SPPOOL PIECE INSTALLATION



NG Welding Advantages

- Uniform Weld Quality
- High Performance Reliability
- Less Filler Material
- Shorter Welding Time
- Lower Radiation Exposure
- Less Shrinkage
- No ID Welding Required
- No ID Grinding




Nozzle Buttering NDE

- PT nozzle end and ID region after severing to ensure complete flaw removal
- PT final buttering and cladding
- UT final buttering from the OD surface and buttering face
- PT buttering after the weld prep has been machined



Nozzle Buttering Examination Technique




Spool Piece Buttering NDE

- PT prior to buttering
 - Complete ID surface,
 - OD for 2.0” from end to be buttered
 - End to be buttered
- PT first layer of buttering
- PT and UT the buttering face at $\frac{1}{2}$ the buttering thickness
- PT final buttering
- UT final buttering from the OD surface and buttering face
- PT buttering after the weld prep has been machined



Spool Piece Buttering Examination Technique




Nozzle to Pipe Weld NDE

- Intermediate UT at $\frac{3}{4}$ " weld thickness
 - Manual examination to ensure weld root integrity
 - Technique developed and demonstrated on partial weld mockup
- PT examination after final welding and surface prep
- Final UT after surface examination
 - Automated examination from the OD surface
 - Examination to satisfy the Section III and Section XI requirements
 - Examination based upon PDI qualified procedure, techniques, and equipment
 - Procedure includes the use of refracted longitudinal wave
 - Scan plans and examination angles developed to provide 100% coverage of the Section III and Section XI examination volumes
 - Procedure capabilities to be demonstrated on EPRI dissimilar metal weld mockup



Nozzle to Pipe Weld Examination Coverage




Pipe to Pipe Weld NDE

- PT examination of the weld prep prior to welding
 - UT in lieu of RT
 - Intermediate UT at $\frac{3}{4}$ " weld thickness
 - Manual examination to ensure weld root integrity
 - Technique developed and demonstrated on partial weld mockup
 - PT examination after final welding and surface prep
 - Final UT after surface examination
 - Manual examination
 - Examination performed with procedures, equipment, and personnel qualified to Appendix VIII, Supplement 2 requirements in accordance with the PDI program
 - Procedure modified to include the requirements to satisfy the Section III full volume requirements
 - 100% coverage of the Section III and Section XI examination volumes
-



Pipe to Pipe Weld Examination Coverage



NDE Code Compliance

- Nozzle to Pipe Weld
 - Examinations performed in accordance with the 1992 Edition of ASME Sections III and XI
- Pipe to Pipe Weld
 - Examinations performed in accordance with the 1992 Edition of ASME Section III and the 1995 Edition with 1996 Addenda of ASME Section XI



NDE

Demonstration/Qualification

- Intermediate UT at $\frac{3}{4}$ " Weld Thickness
 - Mockup welded to $\frac{3}{4}$ " weld thickness
 - Machined reflectors to represent lack of fusion at root and along face of weld to $\frac{3}{4}$ " thickness
- Final Nozzle to Pipe Weld NDE
 - Procedures based on PDI qualified techniques
 - EPRI dissimilar metal weld mockup
 - Demonstrate ability to detect cracks in buttering
 - Demonstrate ability to detect cracks in weld metal
- Final Pipe to Pipe Weld NDE
 - PDI qualified procedures



Integrated Strategy

Greg Halnon




Integrated Strategy


- Three Key Areas of Resolution

–Root Cause

–Repair


–Restart Justification





Root Cause Status

Rev. 9 - 11/16/00



Root Cause Approach

- Main Areas of Investigation
 - Crack Initiation
 - Crack Propagation
 - Organizational/programmatic
- Much Is Waiting on Fracture Analysis
- Schedule
 - First Week in December for Preliminary Report
 - Expect Specimen Arrival at Hot Cell This Week



Westinghouse Analysis

- As Received ID & OD Surface Examinations
- X-Ray, UT, and Eddy Current Non-Destructive Examinations.
- Destructive Examination Including
 - Metallographic Examinations
 - Fractographic Examinations
 - Chemistry Evaluations
 - Mechanical Property Examinations



Extent of Condition

- Weld Is Unique
 - First Weld During Construction
 - Extent and Method of Repairs During Construction
 - Complete ID Removal Combined With OD Weld
 - Made This Weld Similar to Ringhals Configuration
 - Materials Properties of Weld
 - Videos Show Extensive Cold Working of Material
 - Extensive Hand Grinding



Extent of Condition

- Other Legs
 - All Local Repairs. No Significant Concerns With Weld Techniques
 - Welds Reflect Original Design
 - Cold Legs Are Lower Stress and Lower Temperature Environment
 - No Other Indications of Leakage
- UT Of All Other Legs Have No Indications
 - 93 UT and 2000 UT Showed No Detectable Flaws
- Eddy Current Results Under Study



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555-0001
November 3, 2000

NRC Request for Information

Mr. Stephen A. Byrne
Vice President, Nuclear Operations
South Carolina Electric & Gas Company
Virgil C. Summer Nuclear Station
Post Office Box 88
Jenkinsville, South Carolina 29065

SUBJECT: VIRGIL C. SUMMER NUCLEAR STATION - CRACK IN WELD AREA OF REACTOR COOLANT SYSTEM (TAG NO. MB025)

Dear Mr. Byrne:

On October 24, 2000, the NRC Resident Inspector informally presented you with the following appearances and information needs listed below. The purpose of this letter is to publicly document this request for information.

1. The licensee should assess the ability of nondestructive examination at the Virgil C. Summer Nuclear Station (Summer) to detect, characterize, and size the crack in the hot leg. The licensee should either provide sufficient information to resolve this issue prior to restart or provide a schedule to resolve the issue.
2. The licensee should re-evaluate the 1993 Inservice Inspection (ISI) data in light of the assessment performed above. What is the impact of the assessment in Item 1 on the integrity of the other reactor coolant system hot legs and the cold legs?
3. The best expert available to the licensee will perform sufficient inspections and repairs to ensure an American Society of Mechanical Engineers Code acceptance document on all hot legs and cold legs are removed prior to plant restart such that the facility is brought back in conformance with the facility Code of record.

GENERIC INDUSTRY ISSUES - FOR APPROPRIATE INDUSTRY RESPONSE GROUP

1. Are techniques other than ultrasonic testing (UT) appropriate for assessing the integrity of the nozzle to pipe weld? How should these techniques be qualified?
2. What qualified UT techniques (i.e., inner diameter or outer diameter inspection, transducers, beam angle, type of wave, etc.) are used by industry (each UT vendor) to perform ISI of these types of welds? Describe how these techniques are capable of assessing the type of flaw found at Summer.

- Specific Analysis
- Industry Participation
- Require Failure Analysis Results
- Docket Answers Soon After Hot Cell Analysis Results



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555-0001
October 23, 2000

Mr. Steve Byrne
Vice President, Nuclear Operations
South Carolina Electric & Gas Company
Post Office Box 88
Jenkinsville, South Carolina 29065

SUBJECT: VIRGIL C. SUMMER NUCLEAR STATION - CRACK IN WELD AREA OF REACTOR COOLANT SYSTEM (TAG NO. MB025)

In an event report submitted to the NRC on October 12, 2000, you indicated that the Virgil C. Summer Nuclear Station plant personnel identified a crack in the "A" loop reactor system around the source of the leak. When investigating the source of the leak, circumferential cracks in the hot leg of the pipe.

On October 12, 2000, you provided a teleconference. We discussed the crack and your plan to assess the hot leg. Information was provided to the NRC on October 13, 2000, to help guide you in your public document the request for information. NRC inspection staff on October 13, 2000.

1. Based on the estimator
2. Describe the leak at Summer, and discuss
3. When was the survey? Also, discuss the technique(s) utilized. Provide your 50-percent, a



Schedule Milestones

<u>DATE</u>	<u>ACTIVITY</u>
This Week	Ship Weld to Westinghouse
Complete	STEP 1: Spool Piece Removal & Counterbore
This Week	STEP 2: Rebuttering of Nozzle
1 st Week Dec	STEP 3: Machine Weld Preps
2 nd Week Dec	STEP 4: Install Replacement Spool Piece
Early Dec	Data From Hot Cell Analysis
Mid Dec	Complete NDE on New Hot Leg Welds
Mid Dec	Normal Startup Sequence



Summary

- Industry Experts to Augment VCSNS Staff
- 3rd Party Reviews to Ensure:
 - Comprehensive Strategy
 - Technical Adequacy
 - Regulatory Compliance
- Failure Will Be Understood and Repaired Prior to Restart
 - Safety Foremost
 - Actions to Prevent Recurrence
 - Extent of Conditions Addressed



Closing Remarks

Steve Byrne

Vice President Nuclear Operations Division

