

V. C. SUMMER NUCLEAR STATION

Alpha Hot Leg Evaluation and Repair

**Presented at the
V.C. Summer Nuclear Station
Jenksville, SC
January 18, 2001**





SCE&G Agenda

- Overview & Defense in Depth - Greg Halnon
- Why We Are Safe
 - Repair of Pipe - Ron Clary
- What We Did To Ensure Safety
 - Root Cause - Gary Moffatt
 - Extent of Condition - Bob Waselus
- How Safety Margins Are Maintained
 - Future Actions - Mel Browne
- Summary - Greg Halnon



1403-PD-2













Facts

- Leak Was Very Small
- Below the Threshold for Radiation Instrumentation to Detect
 - Fuel Had a High Level of Integrity
- No Leakage Trends Indicated This Leak Existed.
- No Effect on Operation of the Plant



Integrated Strategy

- Root Cause ↔ Repair ↔ Compliance
- Industry Experts Augmented VCSNS Staff
- 3rd Party Reviews Ensured:
 - Comprehensive Strategy
 - Technical Approach
 - Regulatory Compliance
- Worked in Parallel With Refueling Activities



Integrated Strategy Results

- Key Conclusions
 - Root Cause of Alpha Hot Leg Crack: PWSCC With Extensive Weld Repairs in Inconel Alloy 82/182
 - Ultrasonic Inspection Did Not See Some Eddy Current Indications In Alpha Hot Leg
 - Other Welds Contain Some Eddy Current Indications
 - Technical Evaluation To Show Acceptable Operation
 - Future Inspections In Next Two Outages And Monitoring Enhancements To Provide Further Assurance



Defense In Depth


Programs, Equipment, Structures, and Human Performance Which Provide Diverse and Redundant Levels of Assurance for Prevention of a Safety Significant Event.





Plant Design Margins

During Construction of VC Summer



Defense in Depth

**C
h
a
l
l
e
n
g
e
t
o
s
a
f
e
t
y**



**C
h
a
l
l
e
n
g
e
t
o
s
a
f
e
t
y**



Defense in Depth

**C
h
a
l
l
e
n
g
e
t
o
s
a
f
e
t
y**



Continuous Monitoring


**C
h
a
l
l
e
n
g
e
t
o
s
a
f
e
t
y**



Defense in Depth

**C
h
a
l
l
e
n
g
e
t
o
s
a
f
e
t
y**


**C
h
a
l
l
e
n
g
e
t
o
s
a
f
e
t
y**



Defense in Depth

C
h
a
i
e
n
g
e
t
o
s
a
f
e
t
y


C
h
a
i
e
n
g
e
t
o
s
a
f
e
t
y



Defense in Depth

Trained Operators

C
h
a
i
n
g
e
t
o
s
a
f
e
t
y




C
h
a
i
n
g
e
t
o
s
a
f
e
t
y




Safety Analysis

C
h
a
i
n
g
e
t
o
t
s
a
f
e
t
y

C
h
a
i
n
g
e
t
o
s
a
f
e
t
y



**Ch
a
l
l
e
n
g
e
t
o
s
a
f
e
t
y**



**Ch
a
l
l
e
n
g
e
t
o
s
a
f
e
t
y**



End Point of This Effort

- Conclusion Is:
 - Alpha Hot Leg Is Unique
 - Commonalties in Other Welds Are Addressed
 - Plant Is Safe for Start Up:
 - Pipe and Welds Meet Code Requirements
 - Repair Bounds Probable Failure Mechanisms
 - Extent of Condition Is Evaluated
 - Ready for Continued Safe Operation



Why We Are Safe

Pipe Repair

Ron Clary

Manager, Plant Life Extension Project



Repair Strategy


- Remove Flaw
- Reduce Overall Stress in Weld
- Use Improved Materials
- Allow for Most Thorough Root Cause Evaluation



Spool Piece Repair

- Remove Section of Pipe Including Original Weld
- Create Two New Welds
- Narrow Groove Weld Design
 - Entire Weld Made Externally from Inside to Outside
 - Reduces ID Tensile Stresses
- Challenges
 - Limited Space for Repair Tooling & Personnel
 - Long Repair Process
 - Radiation Exposures






STEP 1 - SPOOL PIECE REMOVAL

- Sever Reactor Vessel Nozzle to Ensure All of Flaw Was Removed
- Sever Pipe About 12 Inches Away From Nozzle Cut
- Remove Section of Pipe to Send Offsite for Evaluation






STEP 2 - PREPARE NOZZLE

- Preheat the Nozzle
- Deposit New Inconel 52 Material (Buttering) on Nozzle Face Using Temperbead Process





STEP 3 - PREPARE NEW SPOOL PIECE


- Apply Inconel 52 Butter to One End
- Cut to Measured Length



STEP 4 - MACHINE WELD PREPS

- Buttered Nozzle
- Existing Pipe
- Both Ends of New Replacement Spool Piece






STEP 5 - INSTALL REPLACEMENT SPOOL PIECE

- Install New Spool Piece Into Open Section of Pipe
- Progressively Weld Both Spool Piece Welds Externally From ID to OD





Code Applicability

- ASME Section III
- ASME Section XI
 - ASME Section XI Code Case N432 - Machine GTAW Temperbead
- NRC Approved Relief Request for Inconel 52 Material
- Regulatory Guides
 - RG 1.31 - Control Of Stainless Steel Welding
 - RG 1.44 - Control Of The Use Of Sensitized Stainless Steel



Final Inspections & Examinations

- Volumetric Examination of New Welds
 - Radiograph
 - Ultrasonic
- Surface Examination of New Welds
 - Liquid Penetrant
- Visual Leakage Inspection at System Pressure



End Point of This Effort

- Conclusion Is:
 - Alpha Hot Leg Is Unique
 - Commonalties in Other Welds Are Addressed
 - Plant Is Safe for Start Up:
 - ✓ Pipe and Welds Meet Code Requirements
 - Repair Bounds Probable Failure Mechanisms
 - Extent of Condition Is Evaluated
 - Ready for Continued Safe Operation



What We Did To Ensure Safety

Root Cause

Gary Moffatt

Manager, Design Engineering




Alpha Hot Leg Root Cause

- Root Cause Team: 10 People / Technically Diverse Backgrounds
- Root Cause Problem Statement: Determine Why the Through Wall Crack Occurred
- Evaluation Technique:
 - Define Possible Failure Modes
 - Gather Evidence



Root Cause Failure Modes



- 30 Failure Modes
- 7 Org / Programmatic
- 5 Supported Failure Modes
- 4 Org / Programmatic Contributing Factors.




Root Cause Conclusions

- The Through Wall Crack in the Alpha Hot Leg Occurred Due To:
 - Primary Water Stress Corrosion Cracking
 - High Residual Stresses From Original Welding / Fabrication





Marking Sectioning Locations



Sectioning Layout of the Weld Spool Piece






Layout of the Sectioned Pieces


Metallurgical Analyses


- Surface Examinations
- Ultrasonic Non Destructive Testing
- Surface Examinations
- Ultrasonic Non-destructive Testing (UT)
- Eddy Current Non-destructive Testing (ECT)
- Metallographic Examinations
- Fractographic Examinations
 - Optical & Scanning Electron Microscopy (SEM)
- Chemistry Evaluations
 - Energy Dispersive X-ray Analysis
 - Microprobe Analysis
- Micro Hardness Measurements
- Local Residual Stress Measurements






Cross Section of Weld & Butter






Cross Section of Weld Showing Crack



Metallography Results of Axial Crack (7°)

Looking From the Nozzle Towards the Pipe.



**Metallography of Through Wall Crack at the ID Surface (7⁰)
Magnified 50x**

Metallurgical Test Results


- Some ET Indications Confirmed -- PWSCC Cracks Following Interdendritic Morphology.
- Some ET Indications Were Not Cracks
- Axial Through Wall Crack - Multiple Initiation Sites.
- Axial Crack Contained Within Weld, Butter, HAZ.
- Circumferential Crack Contained in Cladding.




Primary Water Stress Corrosion Cracking

- ✓ Environment
- ✓ Susceptible Material
- High Stresses







This is the start of the original weld. It was designed to be filled from the ID out toward the OD




The first pass was made per design but rejected




A bridge was laid in to stabilize the pipe




The rejected area was removed





Weld was reapplied from the bridge to the ID




The weld was then completed from the bridge to the OD



Cross Section of Weld/Butter






VC Summer "A" Hot Leg Reactor Nozzle to Pipe Weld Spool Piece (Looking OUT from the RV Centerline)



EPRI Typical Weld Finite Element Analysis Result

*VC Summer Nozzle
Stresses*

- As Designed
- ID Welded First
- ID Welded Last



Primary Water Stress Corrosion Cracking

- ✓ Environment
- ✓ Susceptible Material
- ✓ High Stresses



Repair Has Addressed Root Cause Issues

Issue

- Inconel 182 / 82
- Construction Weld
Process High Residual
Stresses

Resolution

- Used Inconel 52
- Narrow Groove Weld
Design, Welded ID to
OD, Reduced ID
Tensile Stresses



End Point of This Effort

- Conclusion Is:
 - ✓ Alpha Hot Leg Is Unique
 - Commonalties in Other Welds Are Addressed
 - Plant Is Safe for Start Up:
 - ✓ Pipe and Welds Meet Code Requirements
 - ✓ Repair Bounds Probable Failure Mechanisms
 - Extent of Condition Is Evaluated
 - Ready for Continued Safe Operation



Break



What We Did To Ensure Safety

Extent of Condition

Bob Waselus

Acting GM ,Strategic Planning



ASME Code Testing (NDE)

- 1993 ISI (UT) Showed No Reportable Indications
- 2000 UT Reported 1 Rejectable Flaw in the Alpha Hot Leg.
- The Other 5 Legs Had No Reportable Indication



Complimentary NDE

- Eddy Current (ET)
 - First Time Used for This Application in This Country
 - No Pretest Acceptance Standard nor Sizing Capability Were Set Due to the Research Nature
 - On Site Demo to Show Ability to Detect Surface Indications Under Ideal Conditions




Complimentary NDE

- Why Eddy Current Was Performed:
 - We Recognized and Discussed Before Starting the Risk of Not Being Able to Fully Explain Our Findings and That This Was Research
 - Assist in Developing a Full Picture of the Condition of the Welds to Understand the Extent of the Condition.
 - To Build on Experience From European Application of ET
 - We Believed It Was the Right Thing to Do.



What We Found

**ET Identified 139 Indications in the Nozzle
to Pipe Connections**




ET Analysis

- Preliminary Screening/Grouping of Raw Data.
 - Single Hit Indications
 - 0.125 Indexing
 - Non Quantifiable Indications (NQI)
 - Detected Only With Primary Probe
 - Different Signal Characteristics From Valid Indication




2001 ET Results




Lissajous from NQI 1 Indication in Nozzle N-95

2001 ET Results



Lissajous from Circumferential Indication in Nozzle N-335
(Axial: 125.00; Circ.: 326 deg. Actual)


2001 ET Results



Lissajous from Axial Indication in Nozzle N-145
 (Axial: 121.375; Circ.: 282 deg. Actual)




2001 ET Results



Lissajous from NQI 1 Indication in Nozzle N-95


Results

15 Relevant Indications




Spool Piece Removal

6 Relevant Indications



Cold Leg Temperature

4 Relevant Indications



ET Analysis

- ET Indications of Interest Are Greater Than 1/4 Inch in Length
- These Indications “Bound” the Smaller Indications in the Nozzles.
- 8 of the 9 Indications in Alpha Hot Leg Were Measured for Crack Length and Then Destructively Examined to Determine the Depth of the Crack.
- The 9th Indication (309 Degree, Axial) Was Preserved for Future Investigations/use.



ET Analysis

- The Aspect Ratio (AR) Was Determined by Dividing the Hot Cell As Measured Length by the As Measured Depth.
- Metallurgical Examination
 - ET “Overcalls” Small Indications (1/2 Inch or Less)
 - ET “Undercalls” Large Indications (1/2 Inch or Greater)
 - False Call Subsurface Iron/Titanium Inclusion
- ET Provides Length Only.



Indications in V. C. Summer RV Nozzle to Pipe Weld Regions

Loop	Leg	Circ. Location/ Orientation	Length (Eddy Current)	Length/Depth* (as measured)	Aspect Ratio
A	Hot (N25)	10 deg/axial	1.75	2.5/2.5	1.0
		11-14/circ	1.0	1.6/0.2	8.0
		12/axial	0.5	0.5/0.2	
		250/axial	>0.5	.750/.615	1.2
		252/axial	0.5	.350/.132	2.7
		255/axial	0.4	.275/.129	2.1
		260/circ	0.25	inclusion	None
		265/axial	0.6	.200/.090	2.2
		309/axial	0.25	Not measured	Not measured
C	Cold (N95)	200/circ.	0.5		
C	Hot (N145)	309/circ.	0.5		
B	Cold (N215)		No indications		
B	Hot (N265)	35/circ.	0.6		
		200.8/axial	0.25		
		348/axial	0.25		
A	Cold (N335)	326/circ.			

*Verified by destructive examination.



Extent of Condition Evaluation

- Determine Flaw Shape
- Know Maximum Allowable Flaw Size
- Crack Growth Rate
- Calculate Safe Conservative Time to Reach Allowable Flaw Size.



Flaw Shape Determinations

- ET Results Are Length Only
- Flaw Depth Was Determined From Destructive Examination of Alpha Hot Leg Indications
- Axial Flaws
 - 4 Flaws Measured
 - Average AR Is 1.8 (will use 2.0)
 - This Matches Observations at European Plant



Flaw Shape Determinations

- Circumferential Flaws
 - No Hot Cell Measurements Available to Apply
 - Axial AR Used Was 2.0
 - The Average Measured AR for Short Axial Flaws Is < 3.0
 - **The ASME Reference Flaw Shape AR Is 6.0**



Allowable Flaw Size

- Determined per ASME Section XI, IWB 3640
- Allowable Depths Determined for Axial Flaws and Circumferential Flaws
- The Maximum Allowable Flaw Size per Section XI is 75 Percent of the Wall Thickness



Crack Growth Calculations

- Fatigue Crack Growth - Very Small Predicted Growth, Even for 40 Years
- Stress Corrosion Crack Growth - Dominant Mode of Growth



Stress Corrosion Crack Growth

- Two Year EPRI Program Completed - 1998 & 1999
- 17 Specimens Tested From Three Welds
- Reference Law Developed by Westinghouse and Published As an EPRI Report, June 2000
- Calculations Completed For:
 - Axial and Circumferential Flaws
 - Several Flaw Shapes
 - Hot Leg and Cold Leg Locations



Conservative Operation Time

- Flaw Lengths Taken Directly From Eddy Current Indications for Other Legs
 - Axial: 0.25 Inches
 - Circumferential: 0.55 Inches (Avg.)
- Axial Flaws
 - AR = 2.0
 - Depth = 0.117 in.
- Circumferential Flaw
 - AR = 6.0
 - Depth = 0.09 in.



Conservative Operation Time

- Axial Flaw
 - **Allowable Service: 3.2 Years**
- Circumferential Flaw
 - (AR = 2.0) - Allowable Service = 14 Years
 - (AR = 3.0) - Allowable Service = 8.4 Years
 - **(AR = 6.0) - Allowable Service = 3.4 Years**
- Cold Leg Indications
 - Crack Growth Rate Is a Factor of 10 Slower, Due to Lower Temperature
 - Hot Leg Results Will Be Governing
 - Safe Operation Time at Least 25 Years



Conclusions

- ASME Section XI Evaluation Shows Acceptable Depths for Both Axial and Circumferential Flaws Are 75 Percent of the Wall Thickness
- Allowable Service Times Were Conservatively Determined Using Crack Growth Data Obtained Recently
- All Service Times Exceed 3.2 Years

However:



Using Additional Conservative Assumptions

- Assume AR of 1.0
- Assume ET Undercalls Large Cracks by 60%
- Apply To Longest Axial Indication (0.25")
- Time to Reach 75% Through Wall Would Be 1.9 Years.
- 1.9 Years Conservative Operation Baseline



End Point of This Effort

- Conclusion Is:
 - ✓ Alpha Hot Leg Is Unique
 - ✓ Commonalties in Other Welds Are Addressed
 - Plant Is Safe for Start Up:
 - ✓ Pipe and Welds Meet Code Requirements
 - ✓ Repair Bounds Probable Failure Mechanisms
 - ✓ Extent of Condition Is Evaluated
 - Ready for Continued Safe Operation



How Safety Margins Are Maintained


Future Actions

Mel Browne

Manager Nuclear Licensing



C
h
a
i
n
g
e
t
o
t
s
a
f
e
t
y



C
h
a
i
n
g
e
t
o
s
a
f
e
t
y



Future Actions

What Else Can We Do to Provide
Additional Confidence in Future
Operation?



Leakage Detection Program

- Leakage Detection Program Meets Current Standards
- Noble Gas Sampling of Reactor Bldg.
- Water Balance Inventory
- Computer Generated Warning Alarm
- Apply Lessons Learned to Visual Inspection Procedures



Refuel 13 Inspections

- Operating Interval of 15 Months
- Visual Inspections
- Perform Non-Destructive Exams
 - Potentially Susceptible Nozzles
 - Best Available Ultrasonic Tools & Techniques
 - Other Inspections Based on Industry Initiative
- Inform NRC of Results



Refuel 14 Inspections

- Operating Interval of ~16 Months
- Repeat Inspections & Expand Scope
 - Visual Inspections
 - Include All Other Reactor Vessel Nozzles
 - Best Available Ultrasonic Tools & Techniques
 - Other Inspections Based on Industry Initiative
- Support or Refute Assumptions
- Inform NRC of Results




Generic Issues

- Potentially Broader Issue?
 - V. C. Summer
 - International Experience
- Industry Response
 - NEI Letter
 - Materials Reliability Project



Generic Implications



- MRP Action Plan
 - Define Potential Generic Implications
 - Develop Action Plan
 - Obtain NRC Feedback
 - Obtain Approval
 - Advise NRC
- VCSNS Participating Fully



Summary and Questions

Greg Halnon

General Manager Engineering
Services



End Point of This Effort

- Conclusion Is:
 - ✓ Alpha Hot Leg Is Unique
 - ✓ Commonalties in Other Welds Are Addressed
 - ✓ Plant Is Safe for Start Up:
 - ✓ Pipe and Welds Meet Code Requirements
 - ✓ Repair Bounds Probable Failure Mechanisms
 - ✓ Extent of Condition Is Evaluated
 - ✓ Ready for Continued Safe Operation

