

Figures




Figure 1. Davis-Besse RPV Top of Head Section View




Figure 2. Davis-Besse RPV Top of Head Plan View




Figure 3. Davis-Besse CRDM Nozzle General Arrangement



Figure 4. Boric Acid and Iron Oxide on Vessel Flange at 12RFO

Nozzle 2 Corrosion Profile




Figure 5 Nozzle 2 Corrosion Area Location, Size, and Profile.




Figure 6. Cavity in Reactor Vessel Head Between Nozzle 3 and 11




Figure 7. Locations of Cracks and Corrosion on Davis-Besse RPV Head at 13RFO




Figure 8. Nozzle 1 Crack Locations and Sizing

Nozzle 2 Profile
Top-Down Data




Figure 9. Nozzle 2 Crack Locations and Sizing




Figure 10. Nozzle 3 Crack Locations and Sizing




Figure 11. Nozzle 5 Crack Locations and Sizing




Figure 12. Nozzle 47 Crack Locations and Sizing



Figure 13. Corrosion and Possible Impingement at Nozzle N-3

DAVIS-BESSE RFO-13




Figure 14. Nozzle 3 Clad Thickness Measurements




Figure 15. Hoop Stresses and Operating Condition Deflections in CRDM Nozzles 2-5

Source: EPRI/DEI




Figure 16. Location of Leaking Nozzles in B&W Design Plants




Figure 17. Distribution of Leaking Nozzles in B&W Design Plants




Figure 18. CRDM Nozzle Leakage Observed at Oconee 3




Figure 19. Unidentified Leak Rate at Davis-Besse (Cycle 13)




Figure 20. As-Found Locations of Boric Acid Deposits on Davis-Besse Vessel Head (10RFO to 13RFO)





Figure 21. Nozzle Crack Leakage Rate Calculation Results



Downhill Plane Nodes are 0's Series
Uphill Plane Nodes are 80,000's Series

Tube Node Series: 1's at Nozzle ID, 5's at Nozzle OD
Shell Node Series: 3's at Shell ID (merged w/tube OD) in weld region
6's at Shell ID above weld region
15's at edge of shell section

Node Numbers Increase by 100 up the length of the tube and shell
Node Numbers Increase by 1 along the tube and shell radius

Figure 22. Finite Element Model Boundary Conditions to Simulate Axial Crack




Figure 23. Crack Opening Displacement with the Crack Surface Nodes Released




Figure 24. Boric Acid Deposits on Top of Head at Start of 13 RFO





Figure 25. Corrosion Rate for EPRI Experiments (Proprietary)

Source: EPRU/DEI

Rev. 7 April 5, 2002



CRDM Flange Conditions

- 1) No leakage from flange gaskets
- 2) "Red" deposits under nozzle 3 flange
- 3) Difficult to get camera in place due to hard, brown, boric acid

RPV Flange Conditions

- 1) Significant flow of boric acid deposits from monsoholes in S-E quadrant
- 2) BA deposits extend around entire flange 1" deep max

RPV Head Conditions


- 1) Visual inspect 34/69 nozzles
- 2) Visual inspect 45/69 nozzles
- 3) BA deposits red and hard to break up (needed crossbar "haxe" like)
- 4) Minor BA deposits around outer nozzles
- 5) BA brittle, breaks easily
- 6) BA deposits at center of head

Figure 26. Timeline of Key Events Related to Reactor Vessel Head Boric Acid Corrosion

Root Cause Analysis Report


Figure 27. Events and Causal Factors Chart on Following 5 pages:

Documents and Responses




Possible Causes
 Primary Water Stress Corrosion Cracking
 Fabrication and inspection anomalies
 Thermal fatigue
 RCS chemistry control
 Resin Intrusions
 Other failure mechanisms

Alloy 600 nozzle susceptible to Primary Water Stress Corrosion Cracking



Industry Issue: Alloy 600 material heat M3935 has apparent higher susceptibility - nozzles 1-5



CRDM 37 flange has 2 small irregularities on face. CRDM 69 flange has slight erosion in outer gasket grooves


RPV head flange had excessive boron. Boron flow ran down flange & closure bolts

Justification: Inspection using high powered cameras preclude the need for inspection ports

Poor access to the RPV head & CRDM nozzles. Inspections not 100%

Inspection openings would allow a thorough inspection and cleaning of the head

Modifications



Justification: Cleaning RPV head during last 2 outages was successful without access ports


Ongoing industry concern involving corrosion of Inconel 600 CRDM reactor vessel nozzles

5/27/94 - All B&W plants except DB and ANO-1 have installed this modification


Justification: Inspection using high powered cameras preclude the need for inspection ports

Poor access to the RPV head & CRDM nozzles. Inspections not 100%


Inspection openings would allow a thorough inspection and cleaning of the head



NRC staff
assessment that
PWSCC is not an
immediate safety
concern for vessel
head penetrations



Radiation Monitors and Containment Air Coolers



Significant boric acid and iron oxide corrosion product in containment

12/29/00 - CAC cleaning frequency increased to about 8 weeks due to boron
 4/23/01 - RE4597BA filter changes frequent due to low flow. All filters contain Boron crystals
 10/20/01 - RE4597BA has abnormally dark brown discoloration
 10/22/01 - Iodine charcoal filter RE4597BA saturated in 19 hours (frequency had been rising)
 10/27/01 & many - RE4597AA/BA had boric acid and crystals and was rust colored
 11/2/01 - RE4597AA/BA charcoal filters replaced with blanks due to iodine saturation

Disconnect between ISI and boric corrosion control

Boric acid control form documents boric acid. Boric acid corrosion inspection not performed.

10/25/01 - Calculated RCS unid. leakage increasing following 10/20 downpower
 11/3/01 - Airborne activity & RCS unid. lk. in CTMT High after down power on 10/19 and 11/17
 11/12/01 - Increase in RCS unidentified leakage observed

4/7/00 - Boron found in CRDM nozzle area and top of insulation - assume CRDM leak at flange 3
 4/12/00 - Recommend to remove as much boron as Pos., contact B&WOG to justify not removing all deposits

Nozzle 3 underside caked with red boric acid deposits
 Solid rock hard boron found on head in southeast quadrant. Rest of boric acid on head is loose. Pressure washer used to clean some

5/16/00 - Did not identify through wall crack/leak or reactor vessel head degradation during outage


5/18/00 - End 12 RFO - Boric Acid not all removed from center of head


10/19/01-10/20/01 - Outage to work on secondary plant
 11/12/01 - Increase in RCS unidentified leakage observed

9/1/98 - MOD 94-0025 recommended for approval to 13RFO at WSC
 9/7/00 - MOD 94-0025 recommended for deferral to 14RFO at PRG

Access to RPV head restricted by Boric acid and insulation

Engineers voice comfortable with 13RFO schedule, RCS leakage source known and not on head, we have inspected any boric acid sitting on the head, dry condition and corrosion attack not an issue, delay to 13RFO does not add risk, however aging is a factor and the MOD should be addressed.





- | | | | |
|---|---------------------------------|---|---------------------------------|
| ○ | 1990 Repaired CRDM Flanges (23) | ○ | 1994 Repaired CRDM Flanges (8) |
| ● | 1991 Repaired CRDM Flanges (15) | ● | 1996 Repaired CRDM Flanges (10) |
| ⦿ | 1991 Leaking CRDM Flanges (7) | ☀ | 2000 Repaired CRDM Flanges (5) |
| ● | 1993 Repaired CRDM Flanges (15) | | |

Figure 28. Leaking Flanges Found and Repaired During Each Outage



Figure 29. Flange Leakage with Stalactite Formation from Insulation and Stalagmite Formation on top of Reactor Vessel Head (SRFO)




Figure 30. Flange Leakage Crusted On Side of Nozzles and Stalactites from Gaps in Insulation (8RFO)




Figure 31. Reddish Brown Boron Deposits Crusted on Side of Nozzle (8RFO)



Figure 32. Boron Deposits – Source Unclear (8RFO)




Figure 33. North Side of Reactor Vessel Head (10RFO)




Figure 34. Boron Deposits Near Top of Reactor Vessel Head (10RFO)



Figure 35: Typical Deposits for Periphery (10RFO)




Figure 36. Red Rusty Boric Acid Deposits on Vessel Flange at 12RFO



Figure 37. Boron Piled Under the Insulation (11RFO)

I HAVE NO PICTURES FROM 2000 OUTAGE.



Figure 38. Boric Acid Deposits with Heavy Iron Concentration on Underside of Nozzle 3 (13RFO)




Figure 39. 2000 Interferences with CRDM Flange Inspection




Figure 40. RE4597 Sample Location

CTMT Radiation Monitors RE4597AA/BA
(Combined Iodine Channels)




Figure 41. CTMT Radiation Monitors RE4597AA/BA
(Combined Iodine Channels)

CTMT Radiation Monitors RE4597AA & BA (Noble Gas Channels)




Figure 42. CTMT Radiation Monitors RE4597AA & BA (Both Noble Gas Channels)




Figure 43. Potential Effects of Boric Acid Deposits on Vessel Top Head Surface.




Figure 44. Crack Profile for Nozzle 3, Flaw #1

Attachment 1. Potential Evidentiary Request List

1. Metallurgical Samples From Nozzle 3

It is desirable to obtain the remaining section of Nozzle 3 from the elevation of the cut to the bimetallic weld to the CRDM nozzle flange. Note: The specimen should not be cleaned prior to input from the Root Cause Team. This specimen may be used for the following examinations and tests:

- a. Examination of external surface of nozzle looking for evidence of flow up through the annulus. Include high quality photographs
- b. Metallurgical examinations including chemistry, microstructure, etc.
- c. Hardness traverse through the wall thickness (similar to Ocone 3)
- d. Tensile properties at three locations through thickness (similar to Ocone 3)
- e. Others as identified

2. Non-destructive Inspections of Top Head Surface at Nozzle 3 Location

It is desirable to perform several non-destructive inspections of the top head surface:

- a. Priority 1: High quality photographs of the corroded areas adjacent to Nozzle 3. The purpose of the photographs is to show:
 - General extent of corrosion
 - Evidence of flow across clad and base metal surface
 - Evidence of possible impingement of steam jet on surfaces
- b. Priority 2: Casting impression of cavity. The purpose of the impression would be to further aid in identifying the boric acid corrosion mechanisms such as
 - Volume loss
 - Location of volume loss relative to leak
 - Undercutting of low-alloy steel at cladding interface (potential)

3. Specimens From Remaining Material at Nozzle 3 Location

It is desirable to remove specimens of the unsupported J-groove weld and adjacent areas of the unsupported clad. The priorities for these examinations are as follows:

- a. Priority 1: The section of the J-groove containing the downhill ($\approx 0^\circ$) crack should be removed. This specimen would be used to:
 - Determine the crack geometry (single crack, branches, etc.)
 - Determine the crack width
 - Assess flow induced erosion on the crack faces
 - Assess the potential for the crack to have started at the J-groove weld surface
 - Assess the potential for weld defects
 - Assess the clad thickness and integrity