U.S. Nuclear Regulatory Commission Operations Center Event Report

Page 1

General Ir	formation or Other (F	PAR)		Even	t #	45722
Rep Org:	OCONEE NUCLEAR	STATION	Notificati	ion Date / Time: 02/24/2010) 14:44	(EST)
Supplier:	DUBOSE NATIONAL	ENERGY SERVICES, IN	C. Eve	ent Date / Time: 02/17/2010	06:32	(EST)
			La	st Modification: 02/24/2010)	
Region:	1		Docket #:			
City:	SENECA	Agreen	nent State:	Yes		
County:			License #:			
State:	SC					
NRC Not	fied by: SANDRA SE	VERANCE N	otifications:	BRIAN BONSER	Ŧ	R2DO
HQ Ops	Officer: DONG HWA	PARK		PART 21 GROUP	ŧ	EMAIL
Emergency	/ Class: NON EMERC	GENCY				
10 CFR \$	Section:					
21.21	UNSPECIFIE	D PARAGRAPH				
		ж				
		·				
L				·		

POTENTIALLY DEFECTIVE STUD ATTACHMENT TO EMBEDED PLATES

"On February 17, 2010, Duke Energy (Duke) completed a reportability determination which concluded that a defect associated with Nelson Stud attachment to embed plates is reportable under Part 21. The embed plates with Nelson studs were procured safety-related from DuBose National Energy Services, Inc. (DuBose) on December 18, 2008. Receipt of the material began as early as August 1, 2009. When delivered to the on-site storage location, it was identified that a Nelson Stud was missing from one of the plates. Follow-up investigation and evaluation identified that automatically timed stud welding procedures/process control weaknesses in the areas of cleanliness and operator/equipment performance have resulted in cold weld joints and weld failures. Duke will provide follow up written notification within 30 days pursuant to Part 21.21(d)(3)(ii).

"Initial Safety Significance: None. The potentially defective embedded plates installed in the Protected Service Water (PSW) Building prior to this discovery have not been placed into service. These plates will be removed, abandoned, or re-engineered prior to placing the system in service. However, the embed plates described were to be used for a variety of QA Condition 1 functions, including reaction points for PSW Building structural steel framing and support/restraint of PSW electrical equipment. Depending upon the installation location of these embedded plates and the number and location of ineffectively attached Nelson studs, this deviation could have created a substantial safety hazard were it to remain uncorrected.

"Corrective Action(s):

- "1. Notified vendor (DuBose).
- "2. Re-work all embeds by installing a fillet weld on each stud.
- "3. Determine whether the installed embeds will be removed, abandoned, re-engineered.

The licensee notified the NRC Resident Inspector.

IE19

4

-4 !

4

.

General Information or Other (PAR)	Event #	45722
******	*****	*****

Attachment B

OMP 1-14

NRC Event Notification Worksheet

Page 2 of 2

Event Description

(Include systems affected, actuations and their initiating signals, causes, effect of event on plant, actions taken or planned, etc.) Event: On February 17, 2010, Duke Energy (Duke) completed a reportability determination which concluded that a defect associated with Nelson Stud attachment to embed plates is reportable under Part 21. The embed plates with Nelson studs were procured safety-related from DuBose National Energy Services, Inc. (DuBosc) on December 18, 2008. Receipt of the material began as early as August I, 2009. When delivered to the on-site storage location, it was identified that a Nelson Stud was missing from one of the plates. Follow-up investigation and evaluation identified that automatically timed stud welding procedures/process control weaknesses in the areas of cleanliness and operator/equipment performance have resulted in cold weld joints and weld failures. Duke will provide follow up written notification within 30 days pursuant to Part 21.21(d)(3)(ii).

Initial Safety Significance: None. The potentially defective embedded plates installed in the Protected Service Water (PSW) Building prior to this discovery have not been placed into service. These plates will be removed, abandoned, or re-engineered prior to placing the system in service. However, the embed plates described were to be used for a variety of QA Condition 1 functions, including reaction points for PSW Building structural steel framing and support/restraint of PSW electrical equipment. Depending upon the installation location of these embedded plates and the number and location of ineffectively attached Nelson studs, this deviation could have created a substantial safety hazard were it to remain uncorrected.

Corrective Action(s):

1. Notified vendor (DuBose).

2. Re-work all embeds by installing a fillet weld on each stud.

3. Determine whether the installed embeds will be removed, abandoned, or re-engineered.

Anything unusual or not understood?		Yes (Explain above)	\boxtimes	No
Did all systems function as required?	\boxtimes	Yes		No (Explain above)
Mode of operations until corrected: N/A		Estimated restart date:	N/A	

Does event result in a radiological release, RCS leak, or steam generator tube Yes (complete page 3) No leak?

Does the event result in any of the units experiencing a transient?

Yes (complete Oconce Plant Status sheet) X No

Notifications Plant Manager: Preston Gillagi NRC Resident: Y/N/will be W/N/will be Notified By Ret. Time: Notified By: James F. Time: 13:45 1131 ooper State(s): Y(N)will be Operations Superintendent Ed Bur A will be Notified By: Time: Notified By: James F. Loopar Time: 13:45 YN will be Local: Other Government Agencies: YN will be Notified By: Time: Notified By: Time: Media/Press Release: Y Nwill be Other: Y(N)will be Notified By: Time Notified By Time

Operations Shift Manager/Emergency Coordinator Approval:	Date/Time:
James 7 Loogen	2-24-10 14:15
NRC Notification Complete by Caller/NRC Communicator:	Date/Time:

Received at: 02/24/2010 14:42

02/24/10 14:42 FAX 2869

Attachment B

OMP 1-14

NRC Event Notification Worksheet

Page 1 of 2

NRC Event Notification Worksheet				
Notification Time	Facility or Organization	Unit	Caller's Name	Call Back #
· ·	Oconee Nuclear Station	1, 2, 3	Sandra Severance	ENS 256-9931
				(864) 873- 3466

NRC Operations Officer Contacted:	NRC Event Number:

.

Event Time/Zone	Event Date	Power/Mode Before	Power/Mode After
0632 EST	2/17/2010	N/A	N/A

Event Classifications	8-Hour Non-Emergency 10 CFR 50.72 (b) (3)
General Emergency	(ii) (A) Degraded Condition
Site Area Emergency	(ii) (B) Unanalyzed Condition
Alert	(xiii) Loss of emergency assessment
	capability/offsite communications
Unusual Event	(iv) (A) System Actuation
50.72 Non-emergency (see other columns)	🔲 RPS
72.75 Spent Fuel (ISFSI)	Containment isolation
73.71 Physical Security	ECCS
Transportation	EFW
20.2202 Material/Exposure	Containment spray/coolers
26.73 Fitness for Duty	Emergency AC (Keowee Hydro)
Other: Part 21.21(d)(3)(i)	(v) (A) Safe Shutdown Capability
	(v) (B) Residual Heat Removal Capability
1-Hour Non-emergency 10 CFR 50.72 (b)(1)	(v) (C) Control of radiological material
Deviation from TS per 50.54(x)	(v) (D) Accident Mitigation
	(xii) Transport contaminated person to offsite medical facility
4-Hour Non-Emergency 10 CFR 50.72 (b)(2)	

- (i) TS Required Shutdown
- (iv) (A) ECCS Discharge into RCS

(iv) (B) RPS Actuation (while critical)

(xi) News release/notification to other

government agencies