



DAVE BAXTER  
Vice President  
Oconee Nuclear Station

Duke Energy  
ON01VP / 7800 Rochester Highway  
Seneca, SC 29672

864-873-4460  
864-873-4208 fax  
dabaxter@dukeenergy.com

April 21, 2010

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287  
Licensee Event Report 269/2010-01, Revision 0  
Problem Investigation Process No. O-09-7536

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a)(1) and (d), attached is Licensee Event Report 269/2010-01, Revision 0, regarding inoperability of the Standby Shutdown Facility (SSF) Reactor Coolant Make-Up (RCMU) system letdown flow path, specifically on Oconee Unit 1, due to foreign material clogging a strainer. Units 2 and 3 were affected to a lesser degree, and the effect on those units is still under evaluation.

This report is being submitted in accordance with 10 CFR 50.73(a)(2)(i)(b) as operation prohibited by Technical Specifications and in accordance with 10 CFR 21.21 as a reportable defect. The report is not complete, and will be supplemented upon completion of additional testing and evaluation necessary to support the root cause and determination of safety impact of this event. At this time, this event is considered to be of no significance with respect to the health and safety of the public.

There are no regulatory commitments contained in this report other than the commitment to submit a supplement. Duke Energy expects to supply that supplement within 60 days, but does not consider that time frame to be a commitment.

Any questions regarding the content of this report should be directed to Randy Todd at 864-873-3418.

Sincerely,

*for* Dave Baxter, Vice President  
Oconee Nuclear Site

Attachment

Document Control Desk

Date: April 21, 2010

Page 2

cc: Mr. Luis Reyes  
Administrator, Region II  
U.S. Nuclear Regulatory Commission  
Marquis One Tower  
245 Peachtree Center Ave., NE, Suite 1200  
Atlanta, GA 30303-1257

Mr. John Stang  
Project Manager  
U.S. Nuclear Regulatory Commission  
Office of Nuclear Reactor Regulation  
Washington, D.C. 20555

Mr. Andrew Sabisch  
NRC Senior Resident Inspector  
Oconee Nuclear Station

INPO (Word File via E-mail)

1. FACILITY NAME: **Oconee Nuclear Station, Unit 1**      2. DOCKET NUMBER: **05000-0269**      3. PAGE: **1 OF 11**

4. TITLE: **Standby Shutdown Facility Letdown Line Orifice Strainer Blocked by Valve Gasket Material**

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
02	20	2010	2010	01	00	04	21	2010	Unit 2	05000 270
									Unit 3	05000 287

9. OPERATING MODE U1 1 U2 1 U3 1  10. POWER LEVEL U1 100 U2 100 U3 100	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)									
	<input type="checkbox"/>	20.2201(b)	<input type="checkbox"/>	20.2203(a)(3)(i)	<input type="checkbox"/>	50.73(a)(2)(i)(C)	<input type="checkbox"/>	50.73(a)(2)(vii)		
	<input type="checkbox"/>	20.2201(d)	<input type="checkbox"/>	20.2203(a)(3)(ii)	<input type="checkbox"/>	50.73(a)(2)(ii)(A)	<input type="checkbox"/>	50.73(a)(2)(viii)(A)		
	<input type="checkbox"/>	20.2203(a)(1)	<input type="checkbox"/>	20.2203(a)(4)	<input type="checkbox"/>	50.73(a)(2)(ii)(B)	<input type="checkbox"/>	50.73(a)(2)(viii)(B)		
	<input type="checkbox"/>	20.2203(a)(2)(i)	<input type="checkbox"/>	50.36(c)(1)(i)(A)	<input type="checkbox"/>	50.73(a)(2)(iii)	<input type="checkbox"/>	50.73(a)(2)(ix)(A)		
	<input type="checkbox"/>	20.2203(a)(2)(ii)	<input type="checkbox"/>	50.36(c)(1)(ii)(A)	<input type="checkbox"/>	50.73(a)(2)(iv)(A)	<input type="checkbox"/>	50.73(a)(2)(x)		
	<input type="checkbox"/>	20.2203(a)(2)(iii)	<input type="checkbox"/>	50.36(c)(2)	<input type="checkbox"/>	50.73(a)(2)(v)(A)	<input type="checkbox"/>	73.71(a)(4)		
	<input type="checkbox"/>	20.2203(a)(2)(iv)	<input type="checkbox"/>	50.46(a)(3)(ii)	<input type="checkbox"/>	50.73(a)(2)(v)(B)	<input type="checkbox"/>	73.71(a)(5)		
	<input type="checkbox"/>	20.2203(a)(2)(v)	<input type="checkbox"/>	50.73(a)(2)(i)(A)	<input type="checkbox"/>	50.73(a)(2)(v)(C)	<input checked="" type="checkbox"/>	OTHER (21.21)		
	<input type="checkbox"/>	20.2203(a)(2)(vi)	<input checked="" type="checkbox"/>	50.73(a)(2)(i)(B)	<input type="checkbox"/>	50.73(a)(2)(v)(D)		Specify in Abstract below or in NRC Form 366A		

12. LICENSEE CONTACT FOR THIS LER

FACILITY NAME: **Randy Todd**      TELEPHONE NUMBER (Include Area Code): **(864) 873-3418**

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
B	NB	V		Y					

14. SUPPLEMENTAL REPORT EXPECTED:  YES (If yes, complete EXPECTED SUBMISSION DATE)      NO

15. EXPECTED SUBMISSION DATE: MONTH **06**, DAY **21**, YEAR **2010**

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On 10/11/2009, while Unit 1 was in Mode 5, the Standby Shutdown Facility (SSF) Reactor Coolant Make-Up (RCMU) system letdown flow path failed a flow test. Subsequently, troubleshooting inspections found foreign material (FM), i.e., Grafoil FM from a Flowserve Model 1878 valve backseat gasket and "legacy" FM (particles of epoxy, austenitic stainless steel shavings, and a paint chip), upstream of an orifice strainer (strainer). The strainer and backseat gasket were removed. Based on inspection of similar valves, vendor assurance of no recorded similar gasket failures, and prior flow tests, the equivalent lines on Unit 2 and 3 were considered Operable.

On 2/18/2010 at 2250, while operating at 100% in Mode 1, Unit 2 SSF RCMU was declared inoperable due to recognition that the strainer could be partially blocked and might collapse during an event. Power was reduced to access the strainer. FM, including Grafoil, was found; the strainer was removed. On 2/23/2010, Unit 3 power was reduced to access the strainer. FM, including Grafoil, was found; the strainer was removed.

The root cause of this event is an inadequately selected strainer. Inadequate testing and FM from the backseat gasket contributed. The backseat gasket failure is reported as a Part 21 defect. The significance of this event is under review and pending further testing/analyses. A supplement will be submitted.

**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Oconee Nuclear Station, Unit 1	05000269	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 11
		10	- 01 -	00	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

EVALUATION:

BACKGROUND

This event is reportable per 10 CFR 50.73(a)(2)(i)(b) as operation prohibited by Technical Specifications and as a defect reportable under 10CFR 21.21.

The Standby Shutdown Facility (SSF) [EIS:NB] at Oconee Nuclear Station (Oconee) provides an alternate and independent means to achieve and maintain Mode 3 for all three of the Oconee Units following sabotage, turbine building flooding, or a design basis (10 CFR 50, Appendix R) fire. The SSF is credited as the coping source of alternate AC power and decay heat removal during a station blackout event and provides defense in depth for a tornado event.

The SSF System includes a Reactor Coolant Make-Up (RCMU) Pump, which is located in the lower level of each Unit's Reactor Building and which is powered and controlled from the SSF. During SSF scenarios, the RCMU system uses the Spent Fuel [EIS:DA] Pool associated with that unit as the source of inventory to supply Reactor Coolant Pump seal injection flow and make-up flow to compensate for normal Reactor Coolant (RCS) [EIS:AB] leakage and shrinkage which results from going from power operation to hot standby (Mode 3). After RCS volume has been restored, the RCMU Pump continues to supply seal injection flow and a letdown flow path is established to return water from the RCS to the Spent Fuel Pool to control pressurizer level.

The SSF RC Letdown Line flow path on each unit includes valve HP-426 in a one inch diameter, schedule 160 line. A flanged pressure-reducing orifice is located on each unit just downstream of valve HP-426. These orifices were initially selected in 1982 during the design of the SSF and purchased as part of a "steam trap drain orifice" assembly. The assembly included a one inch, 60 Mesh (9 mil or 228 micrometer (micron)) dome shaped wire strainer, with an integral flange gasket, mounted just upstream of the orifice plate. The orifices on the three units were resized to 0.240 inch diameter in 1994/1995, but equivalent strainers were retained in the design.

TS 3.10.1 addresses the SSF which is required to be operable in Modes 1, 2, and 3. Condition C allows the RCMU system to be inoperable with a seven day completion time.

EVENT DESCRIPTION

Unit 1 Event Details

On 10/11/2009, Unit 1 was in Mode 5 for 1EOC25, a scheduled refueling outage. Operations attempted to perform a flow verification test of the SSF RC Letdown Line. Operations was unable to meet the acceptance criterion. At this point, Operations considered the test failed. A problem investigation was initiated.

**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Oconee Nuclear Station, Unit 1	05000269	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 11
		10	01	00	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

On 10/19/2009, a visual inspection was performed as part of troubleshooting the failed test. Maintenance personnel found foreign material (FM) in the SSF RCMU letdown flow path between an orifice screen associated with the pressure-reducing orifice and valve 1HP-426. Some of the material was shipped to the Duke Energy Metallurgy and Welding Services Lab (MetLab) for material analysis. After removal of the FM, a visual inspection was performed using a Boroscope (performed by entering the pipe at the orifice flange); inspecting the pipe in both directions. There was no visual evidence of any further FM.

The formal MetLab report was provided on 10/20/2009. A primary component of the debris was graphite, consistent with graphite material used in valve packing and gaskets. Additional "legacy" FM included austenitic stainless steel shavings, and particles of epoxy.

On 10/22/2009, the problem investigation was formally upgraded to a root cause investigation.

On 10/23/2009, 1HP-426 was disassembled for inspection of the valve internals. The inspection revealed that a Grafoil gasket was missing from a location under the valve backseat. GRAFOIL® is a registered trademark of GrafTech International Holdings Inc.

On 10/25/2009, additional debris from the ONS Unit 1 SSF letdown line had been collected in two (2) sock filters, which were also submitted to the MetLab. The majority of the larger visible particles included irregular-shaped chunks of epoxy, shreds of grafoil, and one paint chip.

Although a new backseat gasket was installed in 1HP-426, an Engineering Change was processed to remove it and allow operation without a backseat gasket in place. Another Engineering Change was implemented to remove (delete) the orifice strainer from Unit 1. Both were implemented prior to returning the Unit 1 SSF letdown line to service.

The investigation team discussed the possible cause of the missing gasket with Flowserve. Flowserve indicated that they had received no reports of a missing or damaged backseat gasket with this type of valve.

NUREG-1022, Rev. 2, page 34 states; "An LER is required if a condition existed for a time longer than permitted by the technical specifications [i.e., greater than the allowed completion time] even if the condition was not discovered until after the allowable time had elapsed and the condition was rectified immediately upon discovery. This guidance is consistent with that previously given. (For the purpose of this discussion, it is assumed that there was firm evidence that a condition prohibited by technical specifications existed before discovery, for a time longer than permitted by technical specifications.)"

Because there was no "firm evidence" of when the line became blocked and the problem was designated to be a random occurrence, the Unit 1 event was initially determined to be not

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Oconee Nuclear Station, Unit 1	05000269	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 11	
		10	01	00		

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

reportable. Duke Energy did inform the industry about this issue via Nuclear Network as Operating Experience item OE30114 on 12/01/2009.

At the conclusion of the refueling outage Unit 1 entered Mode 1 (12/02/2009), and subsequently resumed normal power operations at 100% power.

Unit 2 and 3 Event Details

As part of the Unit 1 root cause evaluation, an extent of condition review was performed for the Units 2 and 3 SSF Letdown systems. Engineering reviewed data from prior SSF RCMU letdown line flow tests (Unit 2, tested 10/26/2008; Unit 3, tested 4/26/2009). The initial extent of condition review indicated that flow rates in the Unit 2 and 3 SSF letdown lines did not appear to be substantially affected. In December 2009, Engineering reviewed the original test data and began a re-analysis. As the methodology evolved, the review indicated that the flow on Unit 2, though acceptable by the procedure, was lower than expected. On 1/25/2010, a Problem Investigation Process (PIP) report was initiated and the formal Operability process entered. On 2/17/2010, a Prompt Determination of Operability concluded that Unit 2 was Operable.

On 02/18/2010, Operations and Engineering became aware of an additional concern that the blockage could result in high differential pressure (dP) across the strainer during a SSF event such that the strainer might collapse and further degrade letdown flow.

Since the impact of strainer deformation/collapse on the SSF letdown line flow rate could not be quantified, the conservative decision was made that a reasonable basis for operability did NOT exist, and the Unit 2 SSF RCMU system was declared INOPERABLE at 22:50 on 2/18/2010. Unit 2 power was reduced to approximately 20% to reduce dose for a containment entry to access the strainer. On 2/20/2010, the Unit 2 SSF letdown line strainer was removed. FM, including Grafoil, was found on the strainer.

On 2/23/2010, Unit 3 power was reduced to remove the SSF letdown line strainer. FM, including Grafoil, was found on the strainer.

Operating Experience item OE30789, dated 3/22/2010, provided an update to reflect additional information from Unit 2 and 3.

Based on the confirmation that at least some Grafoil material was released on all three units, Duke Energy reassessed the initial reportability determination. The existence of similar discrepancies in multiple lines indicates that it is inappropriate to assume the condition occurred at the time of discovery. The "event date" is considered to be 2/20/2010 based on the discovery of grafoil FM on the Unit 2 strainer, confirming that this issue went beyond a single random failure. The exact mechanism for release and transport of the Grafoil material is not fully understood at this time, and there remains no "firm evidence" as to when the Grafoil material was actually released from the valves into the system on each unit. The current conclusion, based on available data, is that the material could have been released

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Oconee Nuclear Station, Unit 1	05000269	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5	OF 11
		10	- 01 -	00		

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

any time following installation of this model valve (Unit 1, November 1995; Unit 2, April 1998; Unit 3, November 1998). Therefore, Duke Energy concludes that Unit 1 must be considered to have operated prior to discovery of this issue for a period longer than allowed by TS 3.10.1. The actual impact of the FM on Unit 2 and 3 past operability is still under evaluation. Until this evaluation is complete, Duke Energy considers that Units 2 and 3 were also affected, based on the existence of Grafoil on those units' strainers. Additional details related to Units 2 and 3 will be included in a supplement to this report.

A contributing cause of valve manufacturing deficiency was identified. Therefore, Duke Energy considers this issue to be a reportable defect as defined by 10 CFR 21. See Additional Information section below for information required by 10 CFR 21.21(d)(4)(i) - (viii).

CAUSAL FACTORS

The root cause of this event is an inadequately selected strainer, upstream of the SSF letdown orifice, which was susceptible to clogging when exposed to relatively small amounts of FM with a distinct composition and morphology as found in the Units 1 and 2 inspections. The sizes of the particles appear to play a role in blocking the 60 mesh orifice strainer (opening approximately 9 mils). It appears that fine particles, slightly larger than the 9 mil opening, tend to play a key role in blocking the flow path through the orifice strainer. The legacy FM, combined with the FM generated by the deterioration of a backseat gasket in an upstream valve contributed to this event. Additionally, testing proved to be unreliable in detecting degradation since it both identified (Unit 1) and failed to identify (Unit 2) the degraded state of the strainer. Further, this strainer was not identified separately on Oconee Flow Diagrams and did not have a unique equipment identifier. Although the strainer was listed in the SSF Design Basis Document (DBD), the potential for it to become blocked with relatively small amounts of FM was not understood. This lack of knowledge led to a lack of preventive maintenance, inadequate testing, and inadequate decisions over time. Finally, untimely and ineffective corrective actions from a previous issue led to the delay in identifying the clogging issue.

A significant portion of the FM on Unit 1 was determined to be Grafoil backseat gasket debris from upstream valve 1HP-426. Smaller quantities of the same material were found on Units 2 and 3, indicating that valves 2HP-426 and 3HP-426, which are the same model as 1HP-426, may have also released this material. No maintenance activities have occurred at Oconee that could have damaged the backseat gaskets. Potential causes of Grafoil release related to valve vendor issues were identified. One potential cause is improper assembly in such a way that the Grafoil backseat gasket was not centered and then became damaged when the backseat was screwed into place. Another potential cause is that the backseat did not have the correct amount of torque applied in manufacturing. These potential causes were acknowledged by the valve vendor. Another potential cause is that the valve, as designed, contains a gap directly below the gasket which potentially allows the gasket material to extrude during torquing such that flow forces could cause further deterioration of the Grafoil gasket in service. This additional potential cause has not been validated by the vendor, but inspections of valves in the Oconee warehouse showed deformation and extrusion.

**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Oconee Nuclear Station, Unit 1	05000269	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	6 OF 11	
		10	- 01 -	00		

**17. NARRATIVE** (If more space is required, use additional copies of NRC Form 366A)

Therefore, a vendor deficiency resulting in release of Grafoil is a contributing cause for this event.

**CORRECTIVE ACTIONS**

**Immediate:**

1. On Unit 1, the portions of the SSF RCMU letdown line near the strainer/orifice assembly were inspected. FM was found and removed. The strainer associated with the orifice was removed.

**Subsequent:**

1. The Extent of Condition focused on locating other strainer/orifice assemblies installed in the plant. The initial review consisted of a systematic electronic search on the key phrases "orifice" and "strainer," as well as searching for vendor documents in selected series which are associated with strainers. Other than the SSF letdown line application on all three units, this review did not identify any additional fluid system strainer/orifice combinations similar to the design described in this event.
2. Three spare valves, of the same type as 1, 2, 3HP-426, from the Oconee warehouse were inspected to determine the condition of the backseat gaskets and to evaluate the vendor practices for installing the gasket. All three valves' backseat gaskets were found intact but deformed.
3. Engineering implemented an Engineering Change to remove the backseat gasket from valve 1HP-426.
4. On Units 2 and 3, the portions of the SSF RCMU letdown line near the strainer/orifice assembly were inspected. FM was found and removed. The strainer associated with the orifice was removed.
5. The SSF RCMU Letdown flow test method for Unit 1 was revised to allow improved monitoring and trending capabilities.

**Planned:**

1. Engineering will create and implement calculations needed to support test acceptance criteria for the SSF letdown line test. Once calculations are developed, the test acceptance criteria (TAC), Design Basis Documents, and test procedures will be revised accordingly.
2. Engineering will change the frequency for the SSF RCMU Letdown flow test to every refueling outage.



LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Oconee Nuclear Station, Unit 1	05000269	10	01	00	7 OF 11

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

3. The SSF RCMU Letdown flow test method for Units 2 and 3 will be revised to allow improved monitoring and trending capabilities. (Unit 1 is complete. See subsequent action 5 above.)
4. Engineering will take actions necessary to ensure the SSF RCMU Letdown flow tests are performed during unit startup rather than shutdown to ensure proper function before unit startup.
5. Engineering will implement Engineering Changes to remove the backseat gaskets from valves 2HP-426 and 3HP-426.

Immediate Corrective Action 1 and Subsequent Corrective Action 4 were identified by the root cause report as Corrective Actions to Prevent Recurrence (CAPRs) of the root cause and are complete. Planned Corrective Actions 1, 2, 3, and 4 listed above were identified by the root cause report as CAPRs for contributing causes of this event. Additional corrective actions were identified within the Duke Energy corrective action program.

None of the listed planned corrective actions are considered NRC Commitment items. There are no NRC Commitment items contained in this LER other than the commitment to submit a supplement.

SAFETY ANALYSIS

With a blocked SSF RC letdown orifice strainer, the Unit 1 SSF RC letdown line was not capable of providing an adequate letdown flow path during an initiating event that requires operation of the SSF. Therefore, this problem resulted in a Maintenance Rule Functional Failure of the SSF System. On Units 2 and 3, the lines were affected to a lesser extent. The Maintenance Rule Functional Failure evaluations for Units 2 and 3 are still in progress.

The increased risk of operating in this condition is under evaluation and the results will be included in the supplemented report. There was no actual impact to the health and safety of the public. The clogged strainers have been removed, and no event occurred during the period of vulnerability that required use of the SSF.

ADDITIONAL INFORMATION

LER 269/2006-03 revisions 0 and 1 addressed FM found in the Reactor Building Emergency Sumps of all three Oconee units. That issue/event resulted in a 2007 "White Finding" which resulted in additional corrective actions related to FM. This current SSF letdown line event involves FM found as a result of testing which arose from that corrective action.

A recurring event determination was performed not only on the root cause for this event, but for the contributing causes as well. Per the criteria specified in the applicable Duke Energy administrative directive, the Oconee Problem Report (PIP) data base was searched using cause codes for the root and contributing causes for prior occurrences within the last five years. It was concluded that this

**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Oconee Nuclear Station, Unit 1	05000269	10	01	00	8	OF 11

**17. NARRATIVE** (If more space is required, use additional copies of NRC Form 366A)

event is not similar/recurring. That is, the corrective actions from the items found in the PIP data base were not ineffective in preventing this event.

There were no releases of radioactive materials, radiation exposures or personnel injuries associated with this event.

This Unit 1 event is considered reportable under the Equipment Performance and Information Exchange (EPIX) program. While the valve itself continued to function, the FM resulted in a flow blockage affecting the system function. The EPIX report labeled this as a failure of 1HP-426. The EPIX reportability for Units 2 and 3 is still under evaluation.

The following information is provided at this time to meet the requirements of 10 CFR 21.21(d)(4)(i) - (viii).

(i) Name and address of the individual or individuals informing the Commission.

Dave Baxter  
Vice President  
Oconee Nuclear Station  
7800 Rochester Highway  
Seneca, SC, 29672

(ii) Identification of the facility, the activity, or the basic component supplied for such facility or such activity within the United States which fails to comply or contains a defect.

Facility:

Oconee Nuclear Station

Basic component which fails to comply or contains a defect:

Size 1 inch Class 1878 socket welded globe valve with a threaded backseat (Flowserve Drawing No. W9524446, Rev. E). The Flowserve drawing identified part 101, the backseat gasket, as being made of Grafoil. GRAFOIL® is a registered trademark of GrafTech International Holdings Inc. The gasket is identified as non-QA in the Duke Energy spare parts system.

(iii) Identification of the firm constructing the facility or supplying the basic component which fails to comply or contains a defect.

Manufactured by:

Anchor Darling (now Flowserve Corp., Flow Control Division)

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Oconee Nuclear Station, Unit 1	05000269	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	9	OF 11
		10	01	00		

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

(iv) Nature of the defect or failure to comply and the safety hazard which is created or could be created by such defect or failure to comply.

Nature of the defect:

Grafoil gasket material was released from the valve into the flow path as foreign material (FM). Upon inspection the Grafoil backseat gasket on valve 1HP-426 was found to be missing.

The applicable Duke Energy purchase specification required these valves to be ASME Section III Class 1 as well as clearly stating that the component is important to nuclear safety. That is, the valve was purchased under the Duke Energy QA program, and is therefore subject to 10 CFR 21. The specification included the following:

"Valves shall be capable of safe, proper and continuous operation under the full range of pressure and temperature conditions without undue strain, corrossions, deterioration, leakage, vibration, or other adverse effects on function or structural integrity."

Based on discussions with the valve vendor, it was believed that the 1HP-426 gasket could have been damaged during backseat installation in manufacturing or that the 1HP-426 backseat did not have the correct amount of torque applied in manufacturing. Other mechanisms could exist for gasket damage or gasket deterioration with the valve in service. Any of these mechanisms could have caused Grafoil to be released from the valve. Since Grafoil release was subsequently found to have occurred on Units 2 and 3, valves 2HP-426 and 3HP-426 are the expected sources. This will be confirmed during the upcoming Unit 2 and 3 refueling outages.

Safety hazard which could be created by such defect:

The valve body did not deteriorate or lose function, but the backseat gaskets clearly deteriorated to the point that the gasket material was released into a system, becoming FM. In certain system configurations (e.g. fine mesh strainers), this FM could block flow paths.

Flow testing confirmed that the amount of Grafoil material found on the strainer on Unit 1 reduced system flow below the acceptable minimum. The actual impact on Units 2 and 3 is still under evaluation.

(v) The date on which the information of such defect or failure to comply was obtained.

The original discovery of Grafoil material on the Unit 1 strainer occurred on 10/19/2009. Based on initial information this was considered to be a random failure. Indications of a generic problem were confirmed upon inspection of the Unit 2 and 3 strainers on 2/20/2010 and 2/23/2010, respectively.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Oconee Nuclear Station, Unit 1	05000269	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	10	OF 11
		10	- 01	- 00		

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

(vi) In the case of a basic component which contains a defect or fails to comply, the number and location of all such components in use at, supplied for, or being supplied for one or more facilities or activities subject to the regulations in this part.

The three valves in this application (SSF RCMU letdown) are the only known instances of this defect. Duke Energy has identified a total of 55 valves of the same overall valve vendor model (but of various sizes) installed in various applications at Oconee. Each of the valves is being evaluated on a case by case basis to determine if removal of the backseat gasket is warranted.

Flowserve stated that they have supplied thousands of these valves with no reports of similar failures of this gasket. Duke Energy has no information on those valves/customers.

(vii) The corrective action which has been, is being, or will be taken; the name of the individual or organization responsible for the action; and the length of time that has been or will be taken to complete the action.

Corrective actions taken or planned:

Duke Energy has removed the downstream strainers in the three specific affected locations at Oconee.

Duke Energy has removed the backseat gasket from valve 1HP-426, and will remove it from 2,3HP-426 during the next refueling outage on Unit 2 and 3 respectively. As stated in (vi) above, each of the 55 similar valves at Oconee is being evaluated on a case by case basis to determine if removal of the backseat gasket is warranted.

Duke Energy informed the industry about this issue via Nuclear Network as Operating Experience item OE30114 on 12/01/2009 and updated that information via OE30789, dated 3/22/2010.

The vendor, Flowserve, was notified, performed a Part 21 evaluation, and concluded that this issue was not reportable. Duke Energy determined to report this issue under Part 21, since the issue would be addressed as an equipment failure in this LER.

Individual or organization responsible for the action:

The majority of corrective actions will be the responsibility of the Oconee Engineering Section. See page one of this LER for licensee contact information.

Length of time to complete the action:

The backseat gasket on valve 1HP-426 has been removed. It will be removed on valves 2HP-426 and 3HP-426 during the next refueling outages on Units 2 and 3

**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Oconee Nuclear Station, Unit 1	05000269	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	11 OF 11	
		10	- 01 -	00		

**17. NARRATIVE** (If more space is required, use additional copies of NRC Form 366A)

(currently scheduled to start 4/25/2010 and 10/23/2010 respectively). The completion schedule for the other corrective actions has not been finalized.

(viii) Any advice related to the defect or failure to comply about the facility, activity, or basic component that has been, is being, or will be given to purchasers or licensees.

As stated above, Duke Energy has provided information on this event to the industry via Nuclear Network. In addition, this LER, and planned supplement, will be submitted to the NRC. No other advice or notification is planned at this time.