Part 21 (PAR)

Event#

48745

Rep Org: DRESSER-RAND

**Notification Date / Time:** 02/12/2013 16:52

(EST)

Supplier: DRESSER-RAND

Event Date / Time: 02/01/2013

(EST)

Last Modification: 02/12/2013

Region: 1

Docket #:

License #:

City: WELLSVILLE

Agreement State:

Yes

County:

State: NY

NRC Notified by: D. G. MARTIN

Notifications: ANTHONY DIMITRIADIS

R1DO

**HQ Ops Officer:** DONALD NORWOOD

**BOB HAGAR** 

R4DO

**Emergency Class: NON EMERGENCY** 

PART 21 RX GROUP

E-MAIL

10 CFR Section:

21.21(d)(3)(i)

DEFECTS AND NONCOMPLIANCE

## PART 21 REPORT - DEFECTIVE RAW MATERIAL USED TO MANUFACTURE VALVE STEMS

Dresser-Rand is reporting that one of its vendors supplied annealed material instead of the specified heat-treated material. Dresser-Rand used the defective raw material to manufacture valve stems for Terry Type Emergency Feedwater pump drive turbines. Dresser-Rand has verified that the annealed material is not acceptable for the finished product.

The two customers (Wolf Creek Nuclear Plant and Callaway Nuclear Plant) that received the affected parts have been notified of this issue and have confirmed that the components in question are not in service at their facilities. The remaining material and affected parts have been quarantined at the Dresser-Rand plant in Wellsville, NY.

All questions should be addressed to: Joe Menichino Manager, Navy/Nuclear Product Engineering 37 Coat Street Wellsville, New York, 14895 Phone: (585) 596-3406 jamenichino@dresser-rand.com

## DRESSER-RAND

37 Coats Street Wellsville, NY 14895-0592 Ph: 585/596-3100 FAX: 585/593-5815

February 12, 2013

To:

NRC Operations Center Facsimile (301) 816-5151

In accordance with 10 CFR sec 21.21(d), Dresser-Rand Company hereby notifies the Commission that it has obtained information indicating that one of its vendors supplied defective material that is now in components at two licensed facilities.

The vendor inadvertently supplied annealed material instead of the specified heat-treated material. Dresser-Rand used the defective raw material to manufacture valve stems for Terry Type Emergency Feedwater pump drive turbines. Dresser-Rand has verified that the annealed material is not acceptable for the finished product.

The two customers that received the affected parts have been notified of this issue and have confirmed that the components in question are not in service at their facilities. The remaining material and affected parts have been quarantined at our plant in Wellsville, NY.

Our initial written report on this matter is attached. A final report will be provided in accordance with 10 CFR Part 21.

Please address all questions regarding this matter to:

Joe Menichino
Manager, Navy / Nuclear Product Engineering
Dresser-Rand Government Business Unit
37 Coat Street Wellsville New York 14895
T: (585) 596-3406 / M: (585) 307-4125 / F: (585) 596-3319
jamenichino@dresser-rand.com

Sincerely,

D. G. Martin General Manager

Attachment: Initial Report No. 45

## INITIAL REPORT 10CFR PART 21 REPORT OF A POTENTIAL SAFETY HAZARD

Report No.

PREPARED BY:	J.A. Menichino	Date:	2-1-2013
TITLE:	Mgr, Navy/Nuclear Product Engineering	File No:	Various
PART NAME:	Inconel Valve Stem	Type: Part No: Dwg. No: Rev. Level:	See List, Pg. 2 See List, Pg. 2 See List, Pg. 2
DESCRIPTION O	F DEFECT:	1	
Raw material heat treatment condition must be validated. Inconel valve stems are made from heat treated AMS 5663M Inconel Bar raw material. Vendor certification for certain heat numbers of this material indicate annealed condition was supplied.			
ENGINEERING EVALUATION & RECOMMENDATIONS:			
<ul> <li>1- Identify all AMS 5663M raw material heat numbers supplied in the annealed condition.</li> <li>2- Identify all DR part numbers that were made using the affected heat numbers.</li> <li>3- Investigate the impact of the use of annealed versus heat treated raw material for all items made from this heat of raw material. Justify use of the annealed alternate material or proceed with a recall if the annealed alternate material is found to be unacceptable.</li> <li>4- If the annealed raw material is acceptable this is not a reportable safety hazard.</li> <li>5- If the annealed raw material is unacceptable this is a reportable safety hazard (recall).</li> <li>6- If recall is required identify all customers that purchased parts made the from the affected heat number(s) of this raw material.</li> <li>7- If recall is required notify customers and recall non-compliant parts.</li> <li>8- If recall is required complete DR Final Report NNSOP1200F1</li> <li>Evaluation/Recommendation Prepared By: J.A. Menichino</li> <li>Title: Mgr, Navy/Nuclear Product Engineering</li> <li>Date: 2/1/2013</li> <li>Approved By: Dale Smith</li> </ul>			
Title: _(	Government Business Unit Director	_ Date: <u>⊜</u> ∫v	1/2013
DISPOSITION, CHECK ONE:			
Yes, this constitutes a safety hazard and requires a Final Report be prepared (EF-066)			
No, this does not constitute a safety hazard and does not require any further reporting.			
Reviewed by D-R Wellsville Responsible Officer: Signature:			
Title:	GM	Date: 2	/12/13
RETURN TO MANAGER NUCLEAR PRODUCT ENGINEERING			