

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

April 21, 2014

U.S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D.C. 20555

Serial No. 14-195  
NAPS/JHL  
Docket Nos. 50-338  
50-339  
License Nos. NPF-4  
NPF-7

**VIRGINIA ELECTRIC AND POWER COMPANY (DOMINION)**  
**NORTH ANNA POWER STATION UNITS 1 AND 2**  
**INTERIM PART 21 NOTIFICATION REPORT**

Pursuant to 10 CFR 21.21(a)(2), Dominion is providing the required 60-day interim report for identification of a defect. During pre-installation bench testing of a Basler Motor Operated Control (Potentiometer) it was determined that the potentiometer was not functioning properly. The attachment to this letter provides the information requested by 10 CFR 21.21(a)(2).

This letter does not establish any new commitments. Should you have any questions or require additional information, please contact Mr. Thomas Shaub at (804) 273-2763.

Very truly yours,



Mark D. Sartain  
Vice President - Nuclear Engineering

Commitments made in this letter: Expected Final Part 21 Submittal Date: June 30, 2014

Attachment

IE19  
NRR

cc: Regional Administrator  
U.S. Nuclear Regulatory Commission, Region II  
Marquis One Tower  
245 Peachtree Center Ave., NE  
Suite 1200  
Atlanta, Georgia 30303-1257

NRC Senior Resident Inspector  
North Anna Power Station

Dr. V. Sreenivas  
NRC Project Manager – North Anna  
U. S. Nuclear Regulatory Commission  
One White Flint North, Mail Stop 08 G-9A  
11555 Rockville Pike  
Rockville, Maryland 20852-2738

Ms. M. C. Barillas  
NRC Project Manager – Surry  
U. S. Nuclear Regulatory Commission  
One White Flint North, Mail Stop 08 G-9A  
11555 Rockville Pike  
Rockville, Maryland 20852-2738

Mr. J. E. Reasor  
Old Dominion Electric Cooperative  
Innsbrook Corporate Center, Suite 300  
4201 Dominion Blvd.  
Glen Allen, Virginia 23060

**Attachment**

**Interim Part 21 Notification**

**Basler Motor Operated Control (Potentiometer)**

**Virginia Electric and Power Company (Dominion)**

**North Anna Power Station Units 1 and 2**

**Interim Part 21 Notification - Basler Motor Operated Control (Potentiometer)**

Responsible Officer: Mark D. Sartain, Vice President – Nuclear Engineering  
5000 Dominion Blvd.  
Glen Allen, Virginia 23060

Event Date: February 21, 2014  
Unit Name: North Anna Power Station

Component Information (as applicable):

Manufacturer: Basler Motor Operated Control (Potentiometer)  
Part Number: Part No. 9072300102

Description: During return to service testing of an Emergency Diesel Generator (EDG) following preplanned maintenance, manual voltage control was determined to be inoperable and the EDG was subsequently secured. Troubleshooting identified a failed Motor Operated Control (Potentiometer) also referred to as an MP unit. The cause of the failure of the installed MP unit was determined to be a result of the maintenance activities during the recent outage for the EDG. The failed unit was removed from service and a new MP unit was obtained from stock. The new MP unit failed to operate properly during pre-installation bench testing (operated correctly and then locked up). A second new MP unit was obtained from stock, successfully bench tested, installed, and the EDG was returned to service.

The failed MP unit obtained from stock was a Basler Motor Operated Control (Potentiometer), Model No. MOC2013 and Part No. 9072300102. The function of the MP unit is to allow for manual control of voltage by the control room operator when aligning the EDG in the parallel mode of operation. This is considered a course adjustment controller as compared to the fine adjustment of the voltage regulator or Automatic Voltage Regulator (AVR). The system is also configured with a back up or redundant manual control Motor Operated Controller (auto-transformer) also referred to as the MOT.

Causes: The cause of the MP unit failure that was obtained from stock is unknown.

Immediate Corrective Actions: Material Number 42109345 (quantity 1) has been put in restricted stock.

The MP unit that failed bench testing was returned to the vendor for analysis and cause determination.

The following MP units have been issued from stock:

<u>Work Order Number</u>	<u>Issued</u>	<u>Quantity</u>
59079061601	05/12/08	1
59079061501	04/30/08	1
59079050301	03/20/08	1
59079050401	06/13/08	1
59102702868	02/21/14	2 (this is the batch where one failed)

Expected Final Part 21 Submittal Date: June 30, 2014