

Part 21 (PAR)

Event # 50545

<b>Rep Org:</b> AMETEK SOLIDSTATE CONTROLS	<b>Notification Date / Time:</b> 10/16/2014 16:34 (EDT)		
<b>Supplier:</b> AMETEK SOLIDSTATE CONTROLS	<b>Event Date / Time:</b> 10/16/2014 (EDT)		
	<b>Last Modification:</b> 10/17/2014		
<b>Region:</b> 3	<b>Docket #:</b>		
<b>City:</b> COLUMBUS	<b>Agreement State:</b>	Yes	
<b>County:</b>	<b>License #:</b>		
<b>State:</b> OH			
<b>NRC Notified by:</b> ROBERT GEORGE	<b>Notifications:</b>	WILLIAM COOK	R1DO
<b>HQ Ops Officer:</b> JEFF ROTTON		DAVID AYRES	R2DO
<b>Emergency Class:</b> NON EMERGENCY		LAURA KOZAK	R3DO
<b>10 CFR Section:</b>		MARK HAIRE	R4DO
21.21(d)(3)(i) DEFECTS AND NONCOMPLIANCE		PART 21 GROUP	EMAIL

## PART 21 - INSUFFICIENT SPOT WELD ON WIRE WOUND RESISTOR

The following information was excerpted from a facsimile from AMETEK Solidstate Controls:

Ohmite 5 watt, 470 ohm wire wound resistor with component Date Code 1201 is mounted on a printed circuit board installed in power supplies manufactured by Ametek Solidstate Controls.

"Component Description: Ohmite 5 watt, 470 ohm wire wound resistor with Date Code 1201

"Problem You Could See: Internal open - (100 hour burn-in performed)

"Probable Cause: Insufficient spot weld on the wire wound resistor

"Effect on System Performance: Resistor opens

"Action Required: Notify NRC and affected utilities. Prepare replacements.

"Ametek Solidstate Controls Corrective Action Taken: Notified affected utilities of the potential defect and advised that the power supplies be returned to our factory. Further corrective action will be to install new boards with unaffected resistors, retest, perform 100 hour burn in and return."

Person notifying the NRC: Mr. Robert George, Director of Quality, 875 Dearborn Drive, Columbus, OH 43085, Telephone: (614) 846-7500

\*\*\* UPDATE ON 10/17/14 AT 0755 EDT FROM ROBERT GEORGE TO DONG PARK \*\*\*

1E19  
NRR

The affected plants are Waterford, Indian Point and Salem.

Notified R1DO (Cook), R2DO (Ayres), R3DO (Daley), R4DO (Allen) and Part 21 group via email.

\*\*\*\*\*

## **FAX COVER SHEET**

**AMETEK**

### **SOLIDSTATE CONTROLS**

#### **Quality Assurance**

875 Dearborn Drive, Columbus, OH 43085 U.S.A.  
Telephone: 614-846-7500 1-800-635-7300 Fax: 614-885-3990

**TO:** U.S. Nuclear Regulatory Commission Operations Center  
**FROM:** Robert E. George  
**FAX:** 301-816-5151  
**DATE:** October 16, 2014  
**PAGES:** 3 (including this cover sheet)

**SUBJECT:** Notification of Potential Defect -10CFR Part 21  
**ATTENTION:** Manager, Document Control Center

#### **MESSAGE:**

Ohmite 5 watt, 470 ohm wire wound resistor. This component with Date Code 1201 is mounted on a printed circuit board installed in power supplies manufactured by Ametek Solidstate Controls.

Please see the following attachments...

**NOTE:** The information contained in this FAX is confidential and/or privileged. If the reader of this message is not the intended recipient, any dissemination, distribution, or copying of this communication is prohibited. If this communication has been received in error, please notify us by telephone immediately so we can arrange for the return of the original(s). Thank you.



**SOLIDSTATE CONTROLS**

**Quality Assurance**

875 Dearborn Drive, Columbus, OH 43085 U.S.A.

Telephone: 614-846-7500 1-800-635-7300 Fax: 614-885-3990

E-mail: bob.george@ametek.com

*Robert E. George*

*Director of Quality*

**AMETEK**

October 16, 2014

U.S. Nuclear Regulatory Commission Operations Center  
Document Control Desk  
Washington, D.C. 20555

Subject: Notification of Potential Defect

Product: Ohmite 5 watt, 470 ohm resistor

Ametek Solidstate Controls is submitting the following report of a potential defect in accordance with the requirements of 10CFR, part 21.

Please contact me if you require any further information.

Best regards,

Robert E. George  
Director of Quality





SOLIDSTATE CONTROLS

**AMETEK**

**Component Description**

Ohmite 5 watt, 470 ohm wire wound resistor with Date Code 1201

**Problem You Could See**

Internal open – (100 hour burn-in performed)

**Probable Cause**

Insufficient spot weld on the wire wound resistor

**Effect on System Performance**

Resistor opens

**Action Required**

Notify NRC and effected utilities. Prepare replacements.

**Ametek Solidstate Controls Corrective Action Taken**

Notified affected utilities of the potential defect and advised that the power supplies be returned to our factory. Further corrective action will be to install new boards with unaffected resistors, retest, perform 100 hour burn in and return.