

### Status of Medical Events FY 2014

Donna-Beth Howe, Ph.D.

Medical Radiation Safety Team

March 19, 2015

.

# US.NRC Using New Nature Regulatory Commission Protecting People and the Environment 43 Medical events reported - FY 2013 46 Medical events reported - FY 2014

	FY13	<u>FY14</u>
35.200	0	1
35.300	2	3
35.400	15	5
35.600	10	10
35.1000	16	27



# **Medical Events**

The dose threshold for diagnostic events precludes reportable events most years.

Each year there are approximately 150,000 therapeutic procedures performed utilizing radioactive materials.



# **Medical Events 2014**

# 35.200 Medical events

1

Technetium-99m

- Administered entire multi dose vial 140 mCi to single patient
  - 6-7 cGY (rad) whole body

4



# **Medical Events 2014**

# 35.300 Medical events

3

Samarium 153

- · Administered 39 microcuries to skin of arm
- · Intended 100 microcuries intravenously

Radium - 223

- · Error in writing millicuries in written directive
- · administered micro curies



# 35.300 Medical Events

- 30 millicuries delivered to wrong patient
- Patient was given bracelet id of another patient
- · Authorized User did not use another identifier to confirm the patient was correctly identified
- 728 cGy(rad) to the thyroid

# **U.S.NRC**

# **Medical Events 2014**

### 35.400 Medical events

5

Gynecological

1

Prostate

**U.S.NRC** 

# 35.400 Medical Events

# Gynecological Cs-137

- Dislodged applicator
- Treatment time 49.5 hours planned 63.1
- · Treatment site received 78% of intended dose
- inner thighs received up to 1,509 cGy (rad) expected 652 cGy (rad).



# 35.400 Medical Events

# **Prostate**

4

- Air Kerma received 18,400 cGy (rad) instead of the prescribed 14,500 cGy (rad) medical physicist mistakenly ordered using mCi instead of the air kerma value.
- Some seeds inadvertently implanted into the scar tissue - 54% of prescribed dose delivered to treatment site

9

# U.S.NRC United States Nuclear Regulatory Commission

# 35.400 Medical Events

# Wrong Site - Ultrasound Issues

2

- Seeds implanted 3.5 cm inferior from the target location 29.31% of the prescribed dose was delivered to the target tissue.
- 88 seeds were implanted in penile bulb 34 seeds prostate gland attending urologist mistook the penile bulb for the prostate gland

10

35.600 Medical e	events		10	
HDR	9			
• Skin		2		
<ul> <li>Bronchial</li> </ul>		1		
<ul> <li>Not designated</li> </ul>		2		
<ul> <li>Pelvic</li> </ul>		1		
<ul> <li>OBGYN</li> </ul>		3		
Gamma knife	1			

U.S.NRC Usited State Nactor Regulatory Commission Protecting People and the Extrinoment  Medical Even	ts 2013				
35.600 Medical events					
HDR 9					
<ul> <li>Wrong Site</li> </ul>	3				
Wrong Patient	1				
<ul> <li>Decay correction</li> </ul>	1				
<ul> <li>Right patient wrong treatment plan</li> </ul>	1				
<ul> <li>Source Retraction</li> </ul>	1				
<ul> <li>Wrong dwell time</li> </ul>	1				
Wrong interpretation of dose per fraction	ction 1				
	1	2			



# 35.600 Medical Events

# **HDR Wrong Site**

3

- **OBGYN** wrong location during three treatment fractions of 700 cGy (rad) per fraction
- During follow-up visit burns observed to the skin on the patient's thighs and labia.
- The estimated skin dose received by the patient was 4,200 cGy (rad).
- the source was 100 mm short of the intended treatment site due to Source reference length error,.

U.S.NRC
United States Nuclear Regulatory Commission
Protecting People and the Environment

# 35.600 Medical Events

# **HDR Wrong Site cont.**

- Broncial/tracheal each fraction had two segments, a distal portion using a simple catheter and a proximal portion using a centering catheter.
- In 1<sup>st</sup> fraction the centering catheter was positioned incorrectly
- Treatment offset of 9 cm superior to the intended treatment site

14





# 35.600 Medical Events

# HDR Wrong Site cont.

- OBGYN first of three fractions vaginal cylinder position checked with planar digital x-ray image and unusual inferior cylinder placement was noted, attributed to special patient anatomy.
- On next fraction vaginal cylinder was approximately 5 cm superior to the first treatment..
- dose in 1<sup>st</sup> fraction to unintended tissue was 900 cGy (rad) and 100 cGy (rad) was to the intended tissue.

U.S.NRC
United States Nuclear Regulatory Commission

# 35.600 Medical Events

# HDR Wrong Patient – Skin

1

- physicist selected a different patient's treatment plan with shorter channel length
- The correct site and applicator were used
- Recognized error when time was too long manually stopped procedure
- Intended treatment site received less than half of the 500 cGy (rad) intended dose,
- Area adjacent to the intended site received a maximum dose of 2,300 cGy (rad) to a single point and 1,000 cGy (rad) to a 1 cm radius and 4.5 mm depth



# 35.600 Medical Events

# HDR Decay correction - Skin 1

- Decay corrected value for the source activity was used in data entry for the treatment plan.
- HDR software also corrected for decay in determining the exposure time for the fraction
- patient received approximately twice the prescribed 600 cGy (rad) during a skin treatment



# 35.600 Medical Events

# HDR Wrong Treatment Plan - 1

- Two Ir-192 high dose rate (HDR) fractions of 700 cGy (rad) each
- The patient returned for the second fraction and treatment plan for the first fraction instead of the second fraction was loaded.
- 700 cGy (rad) to 60% of intended dose received by planned volume.

18





# 35.600 Medical Events

# HDR Source retraction – Pelvic

- Received 5.94 cGy (rad) of the prescribed 300 cGy (rad),
- First fractions, unexpected resistance detected in moved to the second dwell position.
- HDR unit detected a delay and automatically retracted the source.
- The dummy source wire could not traverse the pathway and the treatment was abandoned.



# 35.600 Medical Events

# HDR Dwell time - unspecified

- Before third of six fractions an error was identified in planning the correct dwell position for the first two fractions.
- Corrective actions included updating procedures to provide all catheter measurements, producing a checklist of necessary equipment for the operating room, briefing staff physicists in utilizing the equipment, and hiring additional staff.



# 35.600 Medical Events

# HDR Wrong interpretation of dose per fraction – OBGYN 1

- Intended treatment was three fractions of 500 cGy (rad) each
- · During the second of three fractions error noted
- Treatment plan was set to deliver three fractions for a total of 500 cGy (rad)
- · Cause was attributed to human error.



# 35.600 Medical Events

### Gamma knife

1

- Two similar patients arrived and had head frames attached
- Scheduling change to treat only patient 2 was made with out communicating the change to nursing staff
- · Patient identification was not checked
- Physician realized mistake 2 minutes into the treatment
- 175 cGy (rad) to the wrong site.

22

U.S.NRC United States Nuclear Regulatory Commission Protecting People and the Environment	ledical E	vents 2014		
35.1000 Medical	events	28		
Perfexion		1		
I-125 Seed localization		1		
Y-90 Microspheres		24		
SirSphere®	15			
Therasphere ®	9			
Gliasite		1		
			2	

# U.S.NRC Used States Nature Regularry Committee Protecting Regular and the Environment Perfexion Treatment presc Treatment plann done for two pre Incorrect treatment The treatment s minute procedul Approximately 1

# 35.1000 Medical Events

• Treatment prescribed for left side of brain.

- Treatment planner set up plan for right side of brain as done for two previous treatments
- Incorrect treatment plan was reviewed and signed
- The treatment stopped at 1.72 minutes into the 19.14 minute procedure.
- Approximately 1,800 cGy (rad) deliver to wrong site.



# I-125 Seed localization

- received two I-125 seeds when only one was intended.
- · The patient had two marker clips, one for benign biopsy site and other for a papilloma.
- the benign site was marked with a 9.32 MBq (252 μCi) I-125 seed
- The unintended dose from two days seed placement was 61 cGy (rad) at 0.5 cm

- 3-Way Stopcock - Bubbles Contamination - Transfer error 1 - Occluded /kinked catheters 6 No Information

Y-90 Microspheres

SirSphere®

- Wrong site

- Written Directive

\*\*US.NRC 35.1000 Medical Events

15

1

2

25



# **♥U.S.NRC** 35.1000 Medical Events

# SirSphere® Wrong Site

2

# Duodenal Ulcer

- First of 3 treatments 36.2 mCi (1,339 MBq)
- Duodenum lesion and an ulcer that had developed seemingly as a result of microspheres migrating to the stomach.
- A biopsy of the affected region revealed synthetic beads.
- Aberrant hepatic arterial vasculature supplying the stomach.

**U.S.NRC** 35.1000 Medical Events

# SirSphere® Wrong Site cont.

# · Gastric fundus

- 1,100 cGy (rad) to the gastric fundus
- Prescribed microspheres to the right liver
- Stopped when unanticipated shunting was identified.

26



\*U.S.NRC

• 75 % under Dose

• 44.7 % under dose

itates Nuclear Regulatory C ing People and the Env. SirSphere®

# **US.NRC** 35.1000 Medical Events

35.1000 Medical Events

- Noticed bubbles in the administration line

interface - coagulation of microspheres.

- contamination on physician's glove and table

during the treatment and stopped.

- elevated readings at the catheter/vial

# SirSphere® Written Directive

- · Over dose 36,300 rad instead of 10,200 rad
  - Authorized user provided radiopharmacist with an incorrect version of the written directive treatment form
  - failure to follow all procedures and the defeat of normal checks and balances that should have identified the incorrect dosage

# \*US.NRC 35.1000 Medical Events

# SirSphere® 3 Way Stopcock 2

- 45.8 % under Dose
  - Majority of undelivered Y-90 in and around the 3-way stop
  - 3-way stop system was defective
- 29.7% under dose
  - Microspheres in the tubing near the stop cock valve
  - Dextrose not Saline

29



# 35.1000 Medical Events

# SirSphere®

- 34 % under Dose
  - Error transferring microspheres from the delivery vial to the dosing via.
- · 22.7 % under dose
  - Larger than expected amount of microspheres remained in the needle and tubing and did not reach the patient.

32



# SirSphere®

- · 22.5 and 30 % under Dose
  - Split dose, not detected until end of both.
  - Blockage in the delivery system.
- · 25 % under dose
  - catheter clogged halfway through the procedure
  - catheter removed, replaced, and remaining microspheres administered

# **USNRC** 35.1000 Medical Events

# SirSphere®

- · 41% under Dose
  - Same lobe but two different arterial pathways.
  - No microspheres delivered to second part.
  - Short arterial segment and the acute angle at the arterial origin, with possible manipulation or patient movement, resulted in a kink or fold

33

35



# 35.1000 Medical Events

# SirSphere ®


- 41.1% under Dose
  - blockage
  - Not problem with administration kit .
  - Significant number of kinks, bends, clots, and other blockages at catheter tip
- · 32.2 under Dose
  - last bolus could not be pushed through


**U.S.NRC** 

# 35.1000 Medical Events

# SirSphere®

- 38% under Dose
  - No information provided







# 35.1000 Medical Events

# Therasphere<sup>®</sup>

# Wrong site - Catheter Position Error

- Could not properly position the catheter for Segment IV
- Bilateral disease that would eventually require the treatment of both lobes
- 0.81 GBq (21.8 mCi) to Segment IV and 0.91 GBq (24.5 mCi) in the right lobe.



# 35.1000 Medical Events

# Therasphere®

# Reflux & Precipitated out

- 24 % under dose noted some reflux into the common hepatic artery/gastroduodenal artery.
- reduced flow rate during administration process, which resulted in the precipitation of microspheres along the outflow tube



# **USNRC** 35.1000 Medical Events

# Therasphere®

# Dosage error over dose

- · Written directive for 20 % less activity.
- · Reviewed treatment plan but verified standard activity not prescribed activity



# Therasphere®

- · 20% remained in vial
- · 44% under dose
  - Targeting vessel was flowing slowly
  - Microspheres to settle out prior to reaching the target.
- 73 % under dose
  - Wrong catheter kinking





# 35.1000 Medical Events

# Therasphere®

- 23.5% under dose
  - Microspheres adhered to the connector and first one inch of manufacturer supplied tubing
- 28.7% under dose
  - kink in the delivery catheter created blockage
  - thinner, more flexible catheter walls and a small internal catheter diameter were contributing factors.



# 35.1000 Medical Events

# **GliaSite**

- · No dose to treatment site
  - The balloon had not inflated incorrectly positioning a three-position stopcock
  - I-125 saline solution being diverted to another syringe instead of filling the balloon.
  - The stopcock was not part of the vendor's kit



# **Acronyms**

- FY Fiscal Year
- HDR High Dose Rate Remote Afterloader
- mCi millicurie
- MBq Mega Becquerel
- Pts Patients
- Y Yttrium
- I-131 lodine-131

U.S.NRC

United States Nuclear Regulatory Commission

Protecting People and the Environment

**QUESTIONS?**