03/23/2017 U.S. Nuclear Regulatory Commission Operations Center Event Report Page 1										
*** Th	is Event ha	as been	retracted	!!! ×	*** This Event has been retracted !!!					
Power	Reactor						Event	#	52480	
	Site: F	FITZPAT	RICK		Notification Date / Time: 01/10/2017 22:45 (EST)					
Unit: 1 Region: 1 State : NY Reactor Type: [1] GE-4						Event Date / Time: 11/10/2016 16:04 (EST) Last Modification: 03/23/2017				
Containn	nent Type:	MARKI	-							
∖ HQ Op Emerger	otified by:   os Officer:   ncy Class:   R Section:	DONALE	NORWOO	D	Notifications: ANTHONY DIMITRIADIS R1DO PART 21/50.55 REACTOREMAIL					
21.21(a)(2) INTERIM EVAL OF DEVIATION										
		-								
Unit So	cram Code	RX Crit	Init Power	Initial RX Mode		Curr Power	Current RX Mo	de		
1	<b>N</b>	Yes	67	Power Operation		67	Power Operatic	on —		
L			I					\$		

### PART 21 - FAILURE OF POWER SUPPLIES TO MEET VOLTAGE STABILITY SPECIFICATIONS

"This notification is a 10 CFR 21.21(a)(2) interim report for power supply model N-2ARPS-A6. Two instrument power supplies for the 'B' Residual Heat Removal (RHR) system were being bench tested prior to installation when it was discovered that they failed to meet Vendor Technical Manual specifications for voltage stability for varying loads. The deviation was a voltage drop of approximately 300mV. This did not meet the specification of less than 150mV when varying current from 5 amps (full load) to 2.5 amps. A second replacement power supply exhibited a similar 300 mV drop.

"James A. FitzPatrick (JAF) reviewed the work order instructions to determine if there was a deviation from the recommendations in the Foxboro technical manual F180-0309 Spec 200 Multinest Power Supply 2ARPS Series calibration. Since as-found voltage readings were within the required tolerance of the RHR instrument loops, the power supplies appear to have been capable to perform their intended function. However, this evaluation did not troubleshoot why the power supplies failed to meet the calibration requirements.

"The power supplies were sent to a repair vendor. The input from this vendor is expected to allow JAF to complete the evaluation per 10 CFR 21.21(a)(1) by March 21, 2017, and a notification for failure to comply or defect per 10 CFR 21.21(d)(3)(i) is expected by March 24, 2017, if necessary. This notification is being submitted as an interim report per 10 CFR 21.21(a)(2)."

The licensee notified the NRC Resident Inspector.

\*\*\* RETRACTED AT 1705 EDT ON 03/23/17 FROM MARK HAWES TO S. SANDIN \*\*\*

The licensee is retracting this report based on the following:

IE19 NRR

#### <u>03/23/2017</u>

#### U.S. Nuclear Regulatory Commission Operations Center Event Report

"The testing vendor Argo Turboserve Corp provided input to this condition in Non Conformance Report NC161. Engineering reviewed NC161 and discussed this condition with the vendor. The power supplies showed an initial drift following a 100 hour burn-in but continued operation was stable. Therefore, even though the initial voltage drift did not meet the power supply's calibration requirement in F180-0309, it would not be expected to drift significantly further. Engineering concluded that this condition will have a negligible impact on system components. Readings were steady and within the tolerance of the RHR instrument specification. Based on all current information, the component will function over its mission time of 100 days.

"Based on these results, a notification for failure to comply or defect per 10 CFR 21.21(d)(3)(i) is not required and the interim report per 10 CFR 21.21(a)(2) may be retracted."

The licensee informed the NRC Resident Inspector. Notified R1DO (Bickett) and Part 21 Group via email.

NRC	FORM	361
12-20	00)	

## U.S. NUCLEAR REGULATORY COMMISSION OPERATIONS CENTER

ŧ

# **REACTOR PLANT**

	EVENT NOTIFICATION WORKSHEET EN # 52480										
NRC OPERATION TELEPHONE NUMBER: PRIMARY 301-816-5100 or 800-532-3469*, BACKUPS [1st] 301-951-0550 or 800-449-3694*, [2nd] 301-415-0550 and [3rd] 301-415-0553 *Licensees who maintain their own ETS are provided these telephone numbers.											
NOTIFICATION TIME FACILITY OR ORGANIZATIO					UNIT	NAME OF CALLE				CALL BACK #	
17:05 James A. FitzPatrick			K 1 Mark Hawes				(315) 349-6664			49-6664	
ΕV	'ENT TIME & ZONE	EVENT DATE	PO	WER/MOD	EBEFORE			POWER/MODE AFTER			
10	6:04 ET	11/10/2016	67% / Mode 1			67% / Mode 1					
		SSIFICATIONS	1-Hr. Non-Emergency 10 CFR 50.72(b)(1)					D Capability	AINA		
	GENERAL EMERGEN								AINB		
	SITE AREA EMERGE					/ 10 CFR 50.72			.,.,	of Rad Release	AINC
		ALE/AAEC	_		S Required S/D		ASHU			t Mitigation	AIND
	UNUSUAL EVENT 50.72 NON-EMERGEI				CCS Discharge		ACCS ARPS		(xii) Offsite	omm/Asmt/Resp	AMED ACOM
╞	PHYSICAL SECURITY		냄님		Offsite Notification	,	ARPS			tional 10 CFR	
╞	MATERIAL/EXPOSUR		HL.			/ 10 CFR 50.72				Specified System A	
╞	FITNESS FOR DUTY	HFIT	┟─┥	1	Degraded Condit		ADEG.			fied Requirem	
7	· · · · · · · · · · · · · · · · · · ·	D REQMT. (see last column)	片		Jnanalyzed Cond		AUNA		10 CFR 21.21		NONR
	INFORMATION ONLY	· · · · · · · · · · · · · · · · · · ·	日		Specified System		AESF		``````````````````````````````````````		NONR
	•				DESC	RIPTION			•	· · · · ·	
This notification is a 10 CFR 21.21(a)(2) interim report for power supply model N-2ARPS-A6. Two instrument power supplies for the "B" Residual Heat Removal (RHR) system were being bench tested prior to installation when it was discovered that they failed to meet Vendor Technical Manual specifications for voltage stability for varying loads. The deviation was a voltage drop of approximately 300mV. This did not meet the specification of <150mV when varying current from 5 amps (full load) to 2.5 amps. A second replacement power supply exhibited a similar 300 mV drop. James A. FitzPatrick (JAF) reviewed the work order instructions to determine if there was a deviation from the recommendations in the Foxboro technical manual F180-0309 Spec 200 Multinest Power Supply 2ARPS Series calibration. Since as-found voltage readings were within the required tolerance of the RHR instrument loops, the power supplies appear to have been capable to perform their intended function. However, this evaluation did not troubleshoot why the power supplies failed to meet the calibration requirements. The power supplies were sent to a repair vendor. The input from this vendor is expected to allow JAF to complete the evaluation per 10 CFR 21.21(a)(1) by March 21, 2017, and a notification for failure to comply or defect per 10 CFR 21.21(d)(3)(i) is expected by March 24, 2017, if necessary. This notification is being submitted as an interim report NC161. Engineering reviewed NC161 and discussed this condition with the vendor. The power supplies showed an initial drift following a 100 hour burn-in but continued operation was stable. Therefore, even though the initial voltage drift did not meet the power supply's calibration requirement in F180-0309, it would not be expected to drift significantly further. Engineering concluded that this condition will have a negligible impact on system components. Readings were steady and within the tolerance of the RHR instrument specification. Based on all current information, the component will function ov											
Ba	Based on these results, a notification for failure to comply or defect per 10 CFR 21.21(d)(3)(i) is not required and the interim report per 10 CFR 21.21(a)(2) may be retracted.										

NOTIFICATIONS	YES	NO	WILL BE	ANYTHING UNUSUAL OR				
NRC RESIDENT	$\mathbf{\nabla}$			NOT UNDERSTOOD?	YES (Explain above)	✓ NO		
STATE(s)				DID ALL SYSTEMS		NO (Explain above)		
LOCAL				FUNCTION AS REQUIRED?	VES			
OTHER GOV AGENCIES		<b>V</b>		MODE OF OPERATION	ESTIMATED RESTART DATE:	ADDITIONAL INFO ON BACK		
MEDIA/PRESS RELEASE		N		UNTIL CORRECTED: N/A	(MM/DD/YYYY)	YES 🖌 NO		
NDO FORM 264 (42 2000)								

.

1