

14685 WEST 105TH STREET, LENEXA, KANSAS 66215-2003

o 913-888-2630 | d 913-956-3040 | f 913-312-3582

February 5, 2018

sorinc.com

Attn: Document Control Desk US Nuclear Regulatory Commission Washington, DC 20555-0001

### Subject: Final Report for Potential 10 CFR 21 Notification SOR Test Report 9058-102 Revision 2

References:

- 1. Nuclear Regulatory Commission Inspection Report of SOR Inc. No. 99900824/2017-01
- 2. SOR Test Report 9058-102 Revision 2

SOR is providing this report in accordance with 10CFR Part 21.21. This letter serves as a final report to our interim notification letter dated December 15, 2017.

#### (i) Name and address of individual informing the NRC:

Melanie Dirks Director of Quality SOR Inc. 14685 West 105<sup>th</sup> Street Lenexa, KS 66215-2003

(ii) Identification of the activity which fails to comply or contains a defect:

SOR Qualification Test Report 9058-102 Revision 2

(iii) Identification of the firm supplying the basic component which fails to comply or contains a defect: SOR Inc., 14685 West 105<sup>th</sup> Street, Lenexa, Kansas 66215.

# (iv) Nature of the potential failure to comply and the safety hazard which is created or could be created by such defect or failure to comply:

As a result of the referenced NRC NON in regards to SOR Test Report 9058-102, SOR has undergone a thorough review of the subject report. As a result of this review, SOR has identified the following reportable deviations:

- The Test Report did not account for all M&TE uncertainties. The following are affected:
  - o Qualified Life
  - o LOCA profile
  - o HELB1 profile
  - o HELB2 profile
- During qualification testing, observed Repeatability in excess of 1% of Span was not adequately addressed for some models. The following will be affected:
  - o Vacuum switches (post LOCA only)
  - o Temperature switches
- The Test Report presents data that is intended to provide a means to calculate reductions in qualified life depending on the conditions of the end use. However, there is a risk that this information could be overlooked by the end user. Following are the potential contributing factors to qualified life:
  - o Temperature rise due to electrical load on switch element
  - o Temperature rise on direct mount temperature switches due to elevated process temperature

SCOPE

With regards to all references in this report to the SOR model string, see below:

Example of Typical SOR Model String  $\frac{XXX}{1^{st}} \frac{XX}{2^{nd}} - \frac{XX}{3^{rd}} \frac{XXX}{4^{th}} - \frac{XX}{5^{th}} - \frac{XXX}{6^{th}} - \frac{XX}{7^{th}} \frac{XX}{8^{th}} \frac{XX}{9^{th}} \frac{NQ}{Last}$ 

 $1^{st}$  position = up to 3 characters

- $2^{nd}$  position = 2 characters
- $3^{rd}$  position = up to 2 characters
- $4^{th}$  position = up to 3 characters
- $5^{th}$  position = 2 characters
- $6^{th}$  position = 3 characters
- $7^{\text{th}}$  position = 2 characters
- 8<sup>th</sup> position = optional, may or may not have 2 alpha characters
- 9<sup>th</sup> position = optional, may or may not have 2 alpha characters

Last position = "NQ" or "NQX" designator

# In addition to configured model numbers, the following non-standard models are affected: 9013545, 9013761, 9013932, 9014202, 9014230

# SOR Models Not Affected by this Part 21 Notification

No Differential Pressure Switch models with 103, 131 or 141 in Position 1 No Pressure, Vacuum or Temperature switches affected with models strings ending in X6, X7, X12 and X13.

Details of the deviations are given below:

#### QUALIFIED LIFE

Due to unaccounted for inaccuracies of the temperate indicator used to monitor thermal aging, the qualified life will be revised from 20 years at a service temperature of 120°F to **20 years at a service temperature of 19.257°F**. This is generically based on the lowest activation energy of 1.05 eV for the phenolic used in the "Y" and "W" switch elements (3<sup>rd</sup> position in model designation) with an "NQ" or NQX" at the end of the model. Non-standard models 9013545 and 9013761 are also affected. The "B" and "BB" switch elements are unaffected due to the high activation energy of these switches.

#### LOCA, HELB1, & HELB2 PROFILES

NTS report 60162-93N (Appendix B of 9058-102) verified that as a minimum, the LOCA, HELB1, and HELB2 profiles (pressure and temperature) identified in the test plan were met during testing. However, actual values of autoclave pressure and temperature were not in all cases reported and that data is no longer available. Therefore, for conservatism, it is necessary to correct the profiles to take into account M&TE uncertainties. See below for the corrected profiles. All pressure, vacuum, and temperature switches which will be used in a LOCA or HELB environment and with model numbers ending in "NQ" or "NQX" should be evaluated taking into consideration these corrected profiles.

SOR Inc.

Page 2 of 12

٢

SOR Inc. Page 3 of 12

LOC	A Autocla	ave Pro	file (corre	ected for u	uncertaint	ies)
Time			Temperature (°F)		Pressure (psi)	
Minimum	Corrected Minimum	Units	Minimum	Corrected Minimum	Minimum	Corrected Minimum
0:00:00	0:00:00	( hrs : min : sec )	115	111	0	0
0:05:15	0:05:15		340	336	70	69
3:00:00	2:59:54		340	336	70	69
5:00:00	4:59:50		95	91	0	0
5:01:20	5:01:10		280	276	62	<61
5:02:00	5:01:50		280	276	62	61
5:02:30	5:02:20		340	336	70	<69
5:03:15	5:03:05		340	336	70	69
8:00:00	7:59:44		320	316	40	39
11:00:00	10:59:38		300	296	40	39
15:00:00	14:59:30		250	246	25	24
4	3.998	(days)	250	246	10	9
13.23	13.223		250	246	10	9

HELB 1	Autoclave	Profile (d	orrected	for uncert	ainties)
Time (hr:min:sec)		Tempera	ature (°F)	Pressure (psi)	
Minimum	Corrected Minimum	Minimum	Corrected Minimum	Minimum	Corrected Minimum
0:00:00	0:00:00	115	111	0	0
0:00:20	0:00:20	165	161	0	0
3:00:20	3:00:14	165	161	0	0
3:00:50	3:00:44	227	223	7	6
9:00:50	9:00:32	227	223	7	6
>9:00:50	>9:00:32	214	210	1.5	0.5
15:00:50	15:00:20	214	210	1.5	0.5
>15:00:50	>15:00:20	207	203	0	0
92:36:50	92:33:45	207	203	0	0

HELB 2 Autoclave Profile (corrected for uncertainties)					
Time (hr:min:sec)		Temperature (°F)		Pressure (psi)	
Minimum	Corrected Minimum	Minimum	Corrected Minimum	Minimum	Corrected Minimum
0:00:00	0:00:00	115	111	0	0
0:00:10	0:00:10	350	346	40	39
2:00:00	1:59:56	350	346	40	39
<3:48:00	<3:47:52	275	271	30	29
29:00:00	28:59:02	275	271	30	29

#### February 5, 2018 Nuclear Regulatory Commission VACUUM SWITCH REPEATABILITY

#### SOR Inc. Page 4 of 12

The standard SOR specification for repeatability on Vacuum Switches is +/-1% of Span. It is implied that this specification applies throughout the lifetime of the switch. However, qualification testing demonstrated that the repeatability of the Vacuum Switch is in excess of 1% after LOCA testing. While the repeatability is noted in the test report, it was not identified as an anomaly and therefore there was no disposition. For conservatism, it should be noted that **post-LOCA repeatability could be as high as 1.5%**. This only applies to models beginning with "54" (1<sup>st</sup> position in model number), with "TA" or "TX" housing (2<sup>nd</sup> position in model number), and ending with "NQ" or "NQX".

#### TEMPERATURE SWITCH REPEATABILITY

The standard SOR specification for repeatability on Temperature Switches is +/-1% of Span. It is implied that this specification applies throughout the lifetime of the switch. However, qualification testing demonstrated that the repeatability for Temperature Switches is in excess of 1% at numerous times throughout the test program. While the repeatability was previously noted in the test report, it was not identified as an anomaly and therefore there was no disposition. For conservatism, it should be noted that **repeatability could be as high as 1.5%**. This only applies to models beginning with "201", "203", "205", "207", "209", or "20X" (1<sup>st</sup> location in model number), and ending with "NQ" or "NQX". It also applies to non-standard models 9013932, 9014202, and 9014230.


### EFFECT OF ELECTRICAL LOAD ON QUALIFIED LIFE

This issue is addressed in SOR Test Report 9058-102, Section 9. If this was not previously been taken into account by the end user, it should be evaluated for every application. SOR will be adding the following supplemental information to Revision 3 of Test Report 9058-102 as an aid to help determine effects of electrical load on qualified life.

The SOR pressure, vacuum, and temperature switches are mechanical "On-Off" devices that do not require power to operate. Heat rise will only occur within the devices if the switch element contacts are closed and if there is enough current running through the closed contacts to create a rise in temperature in the current carrying wires and switch terminals. If there is enough temperature rise, this could reduce the qualified life of the switch. The following assumes worst case where the ambient temperature is at 119.257°F continuously, the contacts are closed at all times, and there is current running through the closed contacts continuously throughout the life of the switch.


For switches with a **"B" or "BB" switch element** (3<sup>rd</sup> position in the model string) **there is no effect** on qualified life under any load conditions due to the high activation energy of the phenolic in the switch element.

For switches with a **"W" switch element** (3<sup>rd</sup> position in the model string) and "NQ" or "NQX" at the end of the model string, the effect on qualified life would be as noted below. Non-standard models 9013545 and 9013761 are also affected. This is based on an activation energy of 1.32 eV.



### SOR Inc. Page 5 of 12

For switches with a "Y" switch element (3<sup>rd</sup> position in the model string) and "NQ" or "NQX" at the end of the model string, the effect on qualified life would be as noted below. This is based on an activation energy of 1.05 eV.



## EFFECT OF PROCESS TEMPERATURE ON THE QUALIFIED LIFE OF DIRECT MOUNT TEMPERATURE SWITCHES

This issue is addressed in SOR Test Report 9058-102, Section 8. If this has not previously been taken into account by the end user, it should be evaluated for every application. SOR will be adding the following supplemental information to Revision 3 of Test Report 9058-102 as an aid to help determine effects of process temperature on the qualified life of direct mount temperature switches.

This issue applies only to SOR direct mount temperature switches which are designated by **"201" or "20X"** (where "20X" = a non-standard direct mount temperature sensor) in the 1<sup>st</sup> position of the model string and an "NQ" or "NQX" at the end of the model string. It also applies to non-standard models **9013932 and 9014230**.

The graphs shown below can be used as an aide to determine the effect of elevated process temperature on qualified life for the age sensitive materials. These graphs are based on the testing that was performed in 9058-102, Section 8. The effect on qualified life for a particular material may or may not be relevant depending on the qualification requirements. For this reason, 9058-102, Section 8 defines the purpose for each of the materials shown in the graphs below.

Assuming worst case where an application requires full qualification (seismic and HELB), then the weak links and their effect on life can be summarized as follows;

#### "W" or "Y" Switch Element


Assume that the switch contains a "W" or "Y" switch element (3<sup>rd</sup> position in the model string). Then the qualified life could be calculated by the formula  $y=32.1569 e^{(-0.0055x)}$  where "y" is the qualified life in years (assuming 119.257°F ambient), and "x" is the process temperature in degrees Fahrenheit (assuming continuous exposure to this temperature). This formula represents the weak link up to a process temperature of 225.3°F at which point the weak link becomes the EPR O-ring environmental seal between the sensor and the body. Then the qualified life could be calculated by the formula  $y=170.3670 e^{(-0.0129x)}$ . This formula represents the weak link up to a process temperature of 520°F which is the highest rated over-range temperature available in an SOR nuclear qualified temperature switch.

# SOR Inc. Page 6 of 12

### "B" or "BB" Switch Element


Assume that the switch contains a "B" or "BB" switch element (3<sup>rd</sup> position in the model string). Due to the high activation energy of the "B" and "BB" switch elements, then the first and only weak link is the EPR O-ring used as an environmental seal between the sensor and the body. The qualified life would be calculated by the formula  $y=170.3670 e^{(-0.0129x)}$  where "y" is the qualified life in years (assuming 119.257°F ambient), and "x" is the process temperature in degrees Fahrenheit (assuming continuous exposure to this temperature). This formula represents the weak link up to a process temperature of 520°F which is the highest rated overrange temperature available in an SOR nuclear qualified temperature switch.


The graphs below are based on temperature measurements at 3 locations on the direct mount temperature switch; TC1, TC2, and TC3. Reference 9058-102, Section 8 for more details.



February 5, 2018 Nuclear Regulatory Commission

SOR Inc. Page 7 of 12





(v) The date on which the information of such failure to comply was obtained: February 2, 2018

(vi) In the case of a basic component which contains a defect or fails to comply, the number and location of these components in use at, supplied for, or may be supplied for, manufactured or being manufactured for one or more facilities or activities subject to the regulations in this part.

SOR does not have the capability to perform further evaluations to determine if a safety hazard exists as the specific customer application is unknown. The end user must confirm for each application that the corrected qualification values in this notification meet their requirements.

The following customers are potentially affected by this deviation based on the nuclear qualified models procured. The affected models were shipped after July 1993.

In accordance with the requirements of 10 CFR Part 21.21, the customers listed in the tables on the following pages are in the process of being notified by email and/or postal letter regarding this issue to allow them to evaluate this deviation and its potential safety hazard.

Company	Plant		
Ameren	Callaway		
American Electric Power (AEP)	Donald C. Cook		
Arizona Public Service Company (APS)	Palo Verde		
Bruce Power	Bruce, Ontario, Canada		
COIMSA	CFE, Mexico		
Comision Federal De Electricdad (CFE)	Laguna Verde, Mexico		
Dominion	Millstone		
Doosan	KHNP - Shin-Hanul, Korea		
Dremel, Inc.	Asco, Spain		
DTE Energy	Fermi 2		
Duke Energy	Catawba		
Duke Energy	Oconee		
	McGuire		
	Brunswick		
	Shearon Harris		
	H. B. Robinson		
	Crystal River		
Electrabel NV/SA	Doel, Belgium		
Liectiabel INV/SA	Tihange, Belgium		
Energy Northwest	Columbia		
Energy Northwest	Columbia		
	Dilerine		
Entergy Operations, Inc.	Pilgrim Waterford 3		
	Indian Point 2 & 3		
	River Bend		
	Vermont Yankee		
	James A. Fitzpatrick		
	Palisades		
<b>F</b>	Grand Gulf		
Ergytech	Asco, Spain		
F	Laguna Verde, Mexico		
Exelon	Braidwood		
	Byron Calvert Cliffe		
	Calvert Cliffs		
	Clinton		
	Dresden		
	LaSalle Limerick		
	Nine Mile Point		
	Oyster Creek		
	Peach Bottoms Quad Cities		
Fridanla Marca	Three Mile Island		
Fairbanks Morse	Beaver Valley		
	Peach Bottom		
First Energy Nuclear Operating Company	Davis- Besse		
	Perry		

Company	Plant
Florida Power & Light	St. Lucie
	Turkey Point
Fluids Control	Taiwan Power Company, Taiwan
GE-Hitachi Nuclear Energy Americas	Kernkraftwerk Leibstadt AG, Switzerland
	Limerick
	Brunswick
	Perry
	Susquehanna
	Takai 2, Japan
	TPC – Kuosheng, Taiwan
	Hatch
	KHNP – Shin-Kori 3 & 4, Korea
GE-Hitachi Nuclear Energy Canada	Bruce, Ontario, Canada
	Pickering, Ontario, Canada
	Darlington, Ontario, Canada
Hydro-Quebec	Gentilly II, Quebec, Canada
I&C Solutions	Los Alamos National Laboratory
Iberfluid	Asco, Spain
	Vandellos, Spain
	Confrentes, Spain
	Santa Anna De Garona, Spain
IMI CCI	KHNP – Shin-Kori 1 & 2, Korea
	KHNP – Shin-Wolsong 1 & 2, Korea
ISI Industrie Services International	Iberdola, Spain
	La Central Nuclear De Confrentes, Spain
Konan	KHNP, Korea
Korea Hydro & Nuclear Power Company (KHNP)	Ulchin 3, 4, 5 & 6, Korea
	Wolsong 1, 2, 3 & 4, Korea
	Yonggwang 3, 4, 5 & 6, Korea
	Kori 1 & 2, Korea
	Shin-Kori 3 & 4, Korea
National Technical Systems (NTS)	Millstone
Nebraska Public Power District (NPPD)	Cooper
NextEra Energy	Duane Arnold Energy Center
Nihon Koso	Bosch Rexroth, Japan
Nuklearna Elektrarna Krsko (NEK)	Krsko, NPP, Slovenia
Nutherm	Calvert Cliffs
Omaha Public Power District (OPPD)	Ft. Calhoun
Ontario Power Generation	Darlington, Ontario, Canada
	Pickering, Ontario, Canada
Parragon Energy Solutions	TVA Watts Bar
Petroprema	Electrabel, Belgium
PSEG Nuclear LLC	Salem
SLD	China

February 5, 2018

SOR Inc. Page 11 of 12

Company	Plant		
South Carolina Electric & Gas Company (SCE&G)	Virgil C. Summer		
Southern California Edison	San Onofre (SONGS)		
Southern Nuclear Operating Company	Edwin I. Hatch Alvin W. Vogtle Joseph M. Farley		
STP Nuclear Operating Company	South Texas Project		
Talen Energy	Susquehanna		
Tennessee Valley Authority	Watts Bar		
	Sequoyah		
	Browns Ferry		
Third Qinshan Nuclear	Qinshan, China		
Weir Valves & Controls (UK) Ltd.	Shin-Hanul, Korea		
	Barakah, UAE		
Westinghouse Electric (Combustion Engineering)	Yonggwang 3, 4, 5 & 6, Korea Kedo 1 & 2, Korea Ulchin, 3, 4, 5 & 6, Korea Shin-Wolsong 1 & 2, Korea Shin-Kori, 1, 2 & 3, Korea Barakah 1-4, UAE		
Wolf Creek Nuclear Operating Corp.	Wolf Creek		
Xcel	Prairie Island		
	Monticello		

(vii) The corrective action which has been, is being, or will be taken; the name and individual or organization responsible for the action; and length of time that has been or will be taken to complete the action.

SOR has conducted or is conducting the following corrective actions:

- Provided details in this report regarding the NQ models strings and non-standard models potentially affected
- Identified the contact list of customers potentially affected by this deviation within this notification
- Notifying the utilities as indicated with a copy of this notification attached targeting completion by February 8, 2018
- Revise and update test report 9058-102 to revision 3 targeting completion and availability by February 28, 2018

# (viii) Any advice related to the defect or failure to comply about the facility, activity, or basic component that has been, is being, or will be given to the purchasers or licensees.

See Item (iv) above. The end user must confirm for each application that the corrected qualification values in this notification meet their requirements.

# (ix) In the case of an early site permit, the entities to whom an early site permit was transferred: Not Applicable to this Part 21.

SOR Inc. Page 12 of 12

Should you have any additional questions regarding this matter, please contact:

For general inquiries: Linda Coutts Inside Sales Representative Email: <u>Icoutts@sorinc.com</u> Tel 913-956-3071

For technical inquiries: Mike Bequette Vice President of Engineering Email: <u>mbequette@sorinc.com</u> Tel 913-956-3040

Joe Modig Senior Engineer Email: <u>jmodig@sorinc.com</u> Tel 913-956-3046

Sincerely, SOR, Inc.

Milenii Dirton

Melanie Dirks Director of Quality Email: <u>mdirks@sorinc.com</u>