

## Peach Bottom 3

### 3Q/2012 Plant Inspection Findings

---

## Initiating Events

**Significance:** G Mar 31, 2012

Identified By: NRC

Item Type: NCV NonCited Violation

### **Untimely Corrective Actions Resulted in Spent Fuel Pool Boraflex Degradation Exceeding Design Limits**

The inspectors identified a PD that was determined to be a finding of very low safety significance (Green) involving a NCV of 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Action," for the failure by PBAPS to take timely corrective action to correct a condition adverse to quality and the inability to comply with Design Technical Specification (TS) 4.3.1.1.b which requires, in part, that spent fuel pool (SFP) storage racks are designed and maintained with keff less than or equal to 0.95. Specifically, although PBAPS was aware of degradation of neutron absorbing material (Boraflex) within the SFP storage racks since at least 1996, PBAPS did not take effective measures to adequately monitor or manage the degradation to assure sufficient margin to criticality was maintained. Rather, in 2010, PBAPS deferred corrective actions in the SFPs until 2014 based on an operability determination (OD) that concluded sufficient margin would exist until that time. However, the NRC concluded that the OD did not accurately project the rate of boron degradation, and used several non-conservative assumptions. In June 2011, after addressing the errors in the OD, PBAPS declared 117 spent fuel bundle rack storage cells inoperable since the estimated Boraflex degradation indicated that PBAPS had exceeded design TS 4.3.1.1.b.

The PD was more than minor because it was similar to IMC 0612, Appendix E, "Examples of Minor Issues," Example 3.j, which considers that an issue is more than minor if an engineering calculation error results in a condition where there is now a reasonable doubt on the operability of a system or component, or if significant programmatic deficiencies were identified with the issue that could lead to more significant errors if uncorrected.

Using IMC 0609, Attachment 4, "Phase 1 – Initial Screening and Characterization of Findings," the inspectors attempted to evaluate the risk significance of this issue. Applying the guidance in Table 3b, the inspectors made the assumption that the risk associated with this PD most appropriately impacted the Initiating Events cornerstone. A Region I Senior Reactor Analyst (SRA) determined that there were no probabilistic risk assessment tools currently available to adequately assess the risk of a SFP criticality event. Consequently, the inspectors followed the guidance in the Phase 1 SDP screening worksheet, Table 3b, Step 6, which states, in part, that where the SDP guidance is not adequate to provide reasonable estimates of a finding's significance, use IMC 0609, Appendix M, "SDP Using Qualitative Criteria."

Using Appendix M, the inspectors identified criteria and associated considerations that supported the overall qualitative risk assessment. On April 3, 2012, a Significance and Enforcement Review Panel (SERP) was conducted involving staff from Region I, the Office of Nuclear Reactor Regulation, and the Office of Enforcement to discuss the significance of this event. The SERP determined the PD and subsequent consequences resulted in a condition of very low safety significance (Green), based on an assessment using Appendix M attributes. This finding was also determined to have a cross-cutting aspect in the area of Problem Identification and Resolution - Evaluation [P.1(c)]. Specifically, Exelon did not properly evaluate a condition adverse to quality for operability in that the 2010 OD did not accurately predict the rate of Boraflex degradation and whether the issue challenged current SFP operability [P.1(c)]. (Section 40A2)

Inspection Report# : [2012002](#) (*pdf*)

---

## Mitigating Systems

**Significance:**  Jun 30, 2012

Identified By: NRC

Item Type: NCV NonCited Violation

### **Inadequate Test Control to Demonstrate RCIC System Design Basis Start-up Response Time**

The inspectors identified a NCV of very low safety significance of Title 10 Code of Federal Regulation (CFR) 50, Appendix B, Criterion XI, "Test Control," because Exelon conducted unacceptable pre-conditioning of the reactor core isolation cooling (RCIC) system during response time testing. The performance deficiency was related to Exelon's surveillance test (ST) procedure which required cold startup of RCIC to reach the rated pump discharge pressure and flow rate within 50 seconds. Exelon procedures required a 72 hour standby period between pump starts to ensure the pump cold start design criteria are satisfied without pre-conditioning. On numerous occasions, when the pump design parameters were not reached in less than 50 seconds on the first attempt, control room operators would routinely perform a second start attempt within a short period of time, typically less than one hour, to adjust the RCIC pump controls and attain the design values in less than or equal to 50 seconds. Exelon performed an extent of condition review of Units 2 and 3 RCIC cold start test data to ensure the current pump, valve, and flow results satisfied the response time testing requirements. The violation was entered into the corrective action program (CAP) as issue report (IR)1364066.

The performance deficiency was more than minor because it was similar to IMC 0612, Appendix E, "Examples of Minor Issues," example 2.a. Specifically, the RCIC cold start ST procedure was not implemented adequately to ensure that the RCIC pump design discharge pressure and flow were reached within the 50 second requirement on the first attempt. The inspectors evaluated the finding using IMC 0609, Attachment 4, "Initial Screening and Characterization of Findings," and determined the finding was of very low safety significance (Green) because all of the mitigating system barrier questions in Table 4.a resulted in a "no" response. The finding included a cross-cutting aspect in the area of Work Practices, Human Performance component, because Exelon did not effectively communicate expectations regarding procedural compliance and personnel following procedures. Specifically, Exelon took credit for the Unit 2 ST performed on April 7, 2011, which started and shutdown RCIC three times in less than 72 hours to satisfy the response time testing acceptance criteria. On January 20, 2011, the same test was performed for Unit 3, when the RCIC system was run two times prior to satisfying the acceptance criteria. Exelon did not identify the unacceptable pre-conditioning of the RCIC system start-up time for either test because personnel did not follow the In-service Testing (IST) Program Corporate Technical Position procedure. (Section 1R22) [H.4(b)]

Inspection Report# : [2012003](#) (*pdf*)

**Significance:**  Mar 31, 2012

Identified By: NRC

Item Type: NCV NonCited Violation

### **Inadequate Corrective Action to Address Emergency Diesel Generator Control Power Circuit Chronic Internal Faults**

The inspectors determined that PBAPS did not establish measures to promptly identify and correct a condition adverse to the quality related to the emergency diesel generator (EDG) control power circuit. The performance deficiency (PD) constituted a Green, self-revealing NCV of 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Action." Specifically, measures established to identify and correct chronic control power light socket assembly internal faults were inadequate. Consequently, on February 18, 2012, the E-1 EDG local control power station experienced a short circuit event during control power indicating light bulb replacement. PBAPS entered into this issue into the corrective action program (CAP) via issue report (IR) 1328736.

This finding was more than minor because it was associated with the equipment performance attribute of the Mitigating System cornerstone, and adversely affected the cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events and prevent undesirable consequences. Using IMC 0609, Attachment 4, "Phase 1 – Initial Screening and Characterization of Findings," the inspectors determined that this finding was of very low safety significance (Green) because it did not represent an actual loss of safety function for a single EDG train for a duration greater than its Technical Specification (TS) allowed outage time, and did not screen as potentially risk significant due to an external initiating event.

The inspectors determined that this finding had a cross-cutting aspect in the area of problem identification & resolution (PI&R), CAP, because PBAPS did not take appropriate corrective actions to address the adverse trend associated with chronic EDG control power circuit faults in a timely manner, commensurate with its safety significance [P.1(d)]. (Section 1R19)

Inspection Report# : [2012002](#) (*pdf*)

## **Barrier Integrity**

**Significance:**  Dec 31, 2011

Identified By: NRC

Item Type: NCV NonCited Violation

### **Untimely Corrective Action to Correct MOV Degraded Stem Lubrication**

The inspectors determined that PBAPS's failure to promptly correct a condition adverse to quality associated with a safety-related MOV constituted a Green, self-revealing NCV of 10 CFR, Appendix B, Criterion XVI, "Corrective Action." Specifically, corrective actions to prevent recurrence of MOV program testing failures due to degraded stem lubrication in 2009 were not performed in a timely manner to prevent the inoperability of a safety-related MOV due to degraded lubrication, as identified on September 22. [P.1(d)]

10 CFR 50, Appendix B, Criterion XVI, "Corrective Action," states, in part, that measures shall be established to assure that conditions adverse to quality are promptly identified and corrected. Contrary to the above, Exelon failed to promptly correct a condition adverse to quality associated with degraded stem lubrication on RWCU outboard isolation valve MO-3-12-018. Specifically, root cause evaluation 892191-08 required Exelon to change MOV stem lubrication from Exxon Nebula EP-1 to MOV Long Life, as a corrective action to prevent recurrence of multiple MOV program testing failures due to degraded stem lubrication identified in 2009. As a consequence of Exelon's failure to promptly correct this condition adverse to quality, MO-3-12-018 failed diagnostic testing due to degraded Exxon Nebula EP-1 stem lubrication on September 22, 2011. Because this finding is of very low safety significance and has been entered into Exelon's CAP under IRs 1266600 and 1266604, this violation is being treated as a Green

NCV consistent with the NRC Enforcement Policy. (NCV 05000277/2011005-01 and NCV 05000278/2011005-01, Untimely Corrective Action to Correct MOV Degraded Stem Lubrication)

Inspection Report# : [2011005](#) (pdf)

---

## Emergency Preparedness

---

## Occupational Radiation Safety

---

## Public Radiation Safety

**Significance:**  Dec 31, 2011

Identified By: NRC

Item Type: FIN Finding

### **Failure to Establish, Implement, and Maintain Adequate QA for Effluent and Environmental Monitoring**

The inspectors identified a Green finding associated with the failure to establish, implement, and maintain adequate quality assurance (QA) program elements in the area Enclosure 4 of effluent and environmental monitoring as required by Peach Bottom, Units 2 and 3 Technical Specification (TS), Section 5.4.1. Specifically, Exelon's QA program for effluent and environmental monitoring was not sufficient to ensure: 1) that both adequate and timely evaluation and assessment of changes described in the Public Land Use Census were conducted for purposes of dose validation and sampling program modification; 2) that changes in meteorological parameters, used for public dose projections and assessment, were promptly and adequately evaluated; and 3) that laboratory QA programs for effluent and environmental sample analysis measurement systems were adequate and implemented properly. Exelon placed these issues in its inp as Action Requests (ARs): 1226969, 1226202, 1299543, 1299476, 1302720, and 1303308.

The finding is more than minor because it is associated with the Public Radiation Safety cornerstone attribute of programs and processes and adversely affected the associated cornerstone objective in that failure to establish, implement, and maintain an adequate QA program in the effluents and environmental monitoring program area adversely affected the licensee's ability to ensure adequate protection of public health and safety. The finding was assessed for significance using IMC 0609, Appendix D, and determined to be of very low safety significance (Green) because: the issue was contrary to TSs and is a radioactive effluent release program deficiency; there was no indication of a spill or release of radioactive material on the licensee's site or to the offsite environs that would impact public dose assessment, and there was no substantial failure to implement the radioactive effluent release program. The licensee re-assessed the dose to members of the public from routine releases and determined that projected doses did

not, nor were likely to, exceed applicable limits, including as low as is reasonably achievable (ALARA) design specifications of 10 CFR Part 50, Appendix I; or 10 CFR 20.1301(e). The cause of this finding is related to the cross-cutting area of Human Performance, Work Practices, Aspect H.4(b) because the licensee did not ensure personnel followed procedure compliance requirements activities for effluent and environmental monitoring program. (Section 2RS06) tH.4(b)1.

"FIN 2011005-02 had been closed out as NCV 2011005-02 in Inspection Report (IR) 2012003, following the results of the Office of Investigation Inspection into this matter documented in IR 2012003, Section 4OA5."

Inspection Report# : [2011005](#) (*pdf*)

Inspection Report# : [2012003](#) (*pdf*)

---

## Security

Although the Security Cornerstone is included in the Reactor Oversight Process assessment program, the Commission has decided that specific information related to findings and performance indicators pertaining to the Security Cornerstone will not be publicly available to ensure that security information is not provided to a possible adversary. Other than the fact that a finding or performance indicator is Green or Greater-Than-Green, security related information will not be displayed on the public web page. Therefore, the [cover letters](#) to security inspection reports may be viewed.

---

## Miscellaneous

Last modified : November 30, 2012