

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

MAR 3 | 2000

EA 2000-023

Charles M. Dugger, Vice President Operations - Waterford 3 Entergy Operations, Inc. 17265 River Road Killona, Louisiana 70066-0751

SUBJECT:

WATERFORD 3 PREDECISIONAL ENFORCEMENT CONFERENCE

SUMMARY --- NRC INSPECTION REPORT 50-382/99-25

Dear Mr. Dugger:

This refers to the Predecisional Enforcement Conference conducted in the Region IV office on March 20, 2000, between your staff, Region IV personnel, and a representative of the Office of Enforcement. This meeting was held to discuss apparent violations associated with the reactor coolant draindown event which occurred on November 27, 1999. These apparent violations are documented in NRC Inspection Report 50-382/99-25. The attendance list, licensee presentation materials, and NRC handout are enclosed.

The results of our enforcement deliberations will be addressed by separate correspondence. The licensee did not identify any errors in the factual content of the inspection report.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter will be placed in the NRC's Public Document Room.

Should you have any questions concerning this matter, we will be pleased to discuss them with you.

Sincerely.

Ken E. Brockman, Director Division of Reactor Projects

Enclosures:

1. Attendance List

2. Licensee Presentation Material

3. NRC Handout

Template RGN-002

Docket No.: 50-382 License No.: NPF-38

cc w/enclosures:
Executive Vice President and
Chief Operating Officer
Entergy Operations, Inc.
P.O. Box 31995
Jackson, Mississippi 39286-1995

Vice President, Operations Support Entergy Operations, Inc. P.O. Box 31995 Jackson, Mississippi 39286-1995

Wise, Carter, Child & Caraway P.O. Box 651 Jackson, Mississippi 39205

General Manager, Plant Operations Waterford 3 SES Entergy Operations, Inc. 17265 River Road Killona, Louisiana 70066-0751

Manager - Licensing Manager Waterford 3 SES Entergy Operations, Inc. 17265 River Road Killona, Louisiana 70066-0751

Chairman Louisiana Public Service Commission One American Place, Suite 1630 Baton Rouge, Louisiana 70825-1697

Director, Nuclear Safety & Regulatory Affairs Waterford 3 SES Entergy Operations, Inc. 17265 River Road Killona, Louisiana 70066-0751

Ronald Wascom, Administrator and State Liaison Officer Louisiana Department of Environmental Quality P.O. Box 82215 Baton Rouge, Louisiana 70884-2215 Parish President St. Charles Parish P.O. Box 302 Hahnville, Louisiana 70057

Winston & Strawn 1400 L Street, N.W. Washington, D.C. 20005-3502 bcc to DCD (IE14; IE45)

bcc electronic distribution from ADAMS by RIV:

Regional Administrator (EWM)

DRP Director (KEB)

DRS Director (ATH)

Senior Resident Inspector (TRF)

Branch Chief, DRP/E (LJS)

Senior Project Engineer, DRP/E (GAP)

Branch Chief, DRP/TSS (LAY)

RITS Coordinator (NBH)

G. F. Sanborn, D:ACES (GFS)

K. D. Smith, RC (KDS1)

R. W. Borchardt, OE (RWB1)

bcc hard copy:

RIV File Room

OE:EA File, MS: O14E1

DOCUMENT NAME: R:_WAT\WT3-20MS-DRP.wpd

To receive copy of document, indicate in box: "C," = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:SPE:DRP/Q	C:DRP/D	D:DBP/
KMKennedy;df	PHHarrell &	KÉBrockman
3/ 3\ /00	3/ % /00	3/3 /00

OFFICIAL RECORD COPY

bcc to DCD (IE14; IE45)

bcc electronic distribution from ADAMS by RIV:

Regional Administrator (EWM)

DRP Director (KEB)

DRS Director (ATH)

Senior Resident Inspector (TRF)

Branch Chief, DRP/E (LJS)

Senior Project Engineer, DRP/E (GAP)

Branch Chief, DRP/TSS (LAY)

RITS Coordinator (NBH)

G. F. Sanborn, D:ACES (GFS)

K. D. Smith, RC (KDS1)

R. W. Borchardt, OE (RWB1)

bcc hard copy:

RIV File Room

OE:EA File, MS: O14E1

DOCUMENT NAME: R:_WAT\WT3-20MS-DRP.wpd

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:SPE:DRP/Q	C:DRP/D	D:D\$P /	
KMKennedy;df \	PHHarrell &	KÉBrockman	
3/ 3\ /00	3/\$\ /00	3/3 /00	

OFFICIAL RECORD COPY

ENCLOSURE 1

List of Attendees

NRC Attendees:

Ellis Merschoff, Regional Administrator

Ken Brockman, Director, Division of Reactor Projects (DRP)

Gary Sanborn, Director, Enforcement

Kriss Kennedy, Senior Project Engineer, Project Branch D, DRP Tom Farnholtz, Senior Resident Inspector, Project Branch D, DRP Terry Reis, Senior Enforcement Specialist, Office of Enforcement Leonard Willoughby, Project Engineer, Project Branch D, DRP Ryan Lantz, Reactor Inspector, Division of Reactor Safety (DRS)

William Jones, Senior Reactor Analyst, DRS Breck Henderson, Senior Public Affairs Officer

Rachel Carr, Inspector, DNMS

Richard Deese, Reactor Inspector, DRS

Nancy Salgado, Resident Inspector, Project Branch D, DRP Max Schneider, Resident Inspector, Project Branch B, DRP

Licensee Attendees:

Chuck Dugger, Vice President, Operations

Early Ewing, General Manager, Plant Operations

Everett "Chip" Perkins, Director, Nuclear Safety Assurance

Douglas Ortego, Operations Shift Superintendent

Al Wrape, Director, Engineering Randy Douet, Operations Manager


Chester Fugate, Technical Support Manager Jerry Holman, Safety Analysis Manager

Ed Lemke, Licensing Engineer Alan Harris, Engineering Manager John Sanchez, Mechanical Supervisor

Rowdy Oubre, Mechanical Maintenance Technician



Entergy Operations, Inc. - Waterford 3



Predecisional Enforcement Conference
LPSI Train B Inoperable
March 20, 2000





Introduction C. Dugger

Statement of Apparent E. Perkins

Violations

Low Pressure Safety Injection C. Fugate

System Overview

Reach Rods R. Douet

Sequence of Events D. Ortego

Corrective Actions R. Douet

Safety Significance J. Holman

Regulatory Perspective E. Perkins





INTRODUCTION

Chuck Dugger





STATEMENT OF APPARENT VIOLATIONS

Chip Perkins





Statement of Apparent Violations

A Technical Specification (TS 3.5.2) Violation occurred:

 Low Pressure Safety Injection Train B system inoperable for more than 72 hours

A Technical Specification (TS 6.8.1) Violation occurred:

Failure to place SI-417B in the procedure-specified position





Topics of Discussion

- LPSI System Overview
- Reach Rod Design, Maintenance and Failure
- Sequence of Events
- Safety Significance
- Regulatory Perspective





LOW PRESSURE SAFETY INJECTION SYSTEM OVERVIEW

Chester Fugate





The LPSI System is multi-purpose

- Large Break Loss Of Coolant Accident Injection
- Shutdown cooling
- The LPSI system independent from HPSI
- Two independent, 100% capacity trains




LPSI PUMP B - STANDBY MODE OUTSIDE INSIDE CONTAINMENT CONTAINMENT SD HX B cvcs RWSP 121B 120B 412B 1161B S X X S 1161A М 139B TO RCS LOOP 1A 106A 125B 106B M 143B 415B 网 TO RCS LOOP 1B LPSI PUMP B 138B 142B 129B 335 B SDC SD HX A LC 412A М cvcs -139A TO RCS LOOP 2A 125A LC <u> M</u> 336 A 143A 415A SDC -W LPSI 138A TO RCS LOOP 2B 129A PUMP A 336 B M 602B SIS SUMP

6 02A






LPSI PUMP B INJECTION MODE











REACH RODS

Randy Douet





Remote manual actuation of valve

- minimize radiation exposure
- minimize contamination
- physical location is difficult to access

Several configurations

- ◆ shafts
- universal joints
- slip joints
- gear boxes
- impactors





Typical Preventive Maintenance for Reach Rods

- ◆ inspect drive linkage
- ♦ lubricate universal joints
- check torque setting of friction clutch

Preventive Maintenance Inspection

- ♦ limited to four active, safety-related valves
 - + CS-111A & B, CS-117A & B





SEQUENCE OF EVENTS

Douglas Ortego





Sequence of Events

November 19, 1999

1627 SI-417B opened for RWSP recirculation (day shift)

1715 RWSP placed on recirc using LPSI Pump B

2235 RWSP recirc secured. SI-417B fails to close due to broken reach rod (night shift)

November 26, 1999

1255 Commenced plant shutdown to repair steam leak

1511 Plant enters Mode 3

2259 Plant enters Mode 4





Sequence of Events

November 27, 1999

0441 SDC Train B aligned in standby

0447 Valve SI-407B control switch taken to "Open"


RCS pressure and Pressurizer level begin to drop, RWSP level begins to rise.

Auxiliary Operator in Safeguards Room B reports LPSI Pump B abnormalities

O448 Pressurizer heaters trip at 28% Pressurizer level

Valve SI-407B control switch taken to "Close"





बुभावातिकाः है बेबत्साम खन

Tail


SI-407

SI-405

SI-401

जादर













Sequence of Events

O448 Charging Pump B automatically starts (two Charging pumps now running)

Valve SI-407B indicates closed. Indicated Pressurizer level is 1.9% (bottom of indicating range). RWSP average level 86% and rising

0448 RCP 2B and 1B secured

0449 Indicated Pressurizer pressure is 105 psia

O449 Auxiliary Operator in Safeguards Room B reports hearing another thud and observes LPSI Pump B slow and stop





-Sequence of Events

0452	Highest representative core exit thermocouple increased 15° F to 308° F (still subcooled)
0453	RWSP average level peaks at 86.5%
0457	Indicated Pressurizer level is 5% and rising
0507	HPSI Pump A started to make up to the RCS
0509	Charging pump suction shifted to RWSP. HPSI cold leg injection at 100 gpm to each RCS leg
0511	Hot leg injection initiated from HPSI Pump A at 50 gpm
0515	Secured hot leg injection






Sequence of Events

O516 Secured cold leg injection. Indicated Pressurizer level is 35%

O521 Core exit thermocouple 296° F and dropping. Plant conditions stable.


0533 Alert declared





- RCS experienced a rapid diversion of inventory and pressure for approximately one minute.
- The source was the LPSI/SDC System train B.
- The flow path was into the RWSP.
- The diversion was terminated by closing SI-407B.





- RCS conditions stabilized during procedurally driven actions in progress to restore inventory and pressure.
- No loss of RCS outside of any system was indicated.
- No radioactive release occurred.
- All fission product barriers were intact.





CORRECTIVE ACTIONS

Randy Douet





Corrective Actions - RCS Diversion

CAUSE: SI-417B reach rod uncoupled/valve mispositioned

Immediate/Short Term Actions

- Walked down SDC Train B piping and supports
- Walked down Pressurizer Surge Line piping and supports
- Performed radiological survey of RWSP floor plug
- Performed calibration check of Pressurizer wide range pressure instrument RC-IPT-0102A
- Sampled CCW and RCS for boron and radioactivity





Corrective Actions - RCS Diversion

Immediate/Short Term Actions

- Vented SDC Train B piping
- Performed confirmation run of LPSI B pump and obtained vibration data
- Evaluated Pressurizer Surge Line thermal gradient

RESULTS: RCS diversion bounded. No abnormalities identified. Returned SDC Train B to operable status.





Corrective Actions - RCS Diversion

Long Term Actions

 Revise reach rod operated valve position verification in procedure OP-100-009 - COMPLETE

Issue an Operational Experience notice to the industry - COMPLETE





Corrective Actions - Reach Rods

CAUSE: Inadequate maintenance

Immediate/Short Term Actions

- Closed SI-407B
- Identified problem with SI-417B and repaired reach rod
- Inspected accessible reach rods on safety related valves for common problems
- Determined reach rod assemblies which have PMC indication to use as an alternative method to verify correct positioning
- Issued a Daily Instruction to Operations Dept. personnel





Corrective Actions - Reach Rods

Long Term Actions

 Expand scope of PM program for reach rods to include all safety-related valves and provide more detailed inspection criteria. - COMPLETE

 Provide procedure for performing maintenance on rotohammers. No reuse of roll pins. - COMPLETE





Corrective Actions - Reach Rods

Long Term Actions

 Inspect and repair identified items on reach rods of safetyrelated valves.

 Evaluate roll pin adequacy for reach rod operated safetyrelated valve. - COMPLETE

RESULTS: Inspections identified issues from loose pins to bottomed-out position indicators. No additional failures identified.





Prior Opportunities to Identify

- Bottomed out indicating pin when valve operated on 11/19/99
- Procedure guidance for local verification
- Computer mimic displays not a missed opportunity
- Indicating counters
- Incomplete actions for CS-117A (1994)
- Inadequate use of information from ANO (1994 96)





SAFETY SIGNIFICANCE

Jerry Holman





- Risk during full power was negligible
- RCS diversion had low safety significance





Safety Significance - Full Power

- LBLOCA diversion of LPSI injection flow less than 800 gpm
- LBLOCA probability during 8 days is 1.1 x 10-6
- LBLOCA with failure of LPSI A is 5.5 x 10⁻⁸
- Actual Peak Linear Heat Generation Rate well below analysis value, so Peak Clad Temperature would be lower than current FSAR Analysis





Safety Significance - RCS Diversion

- Prompt Operator action to isolate
- HPSI injection available
- No predicted RCS voiding
- Core cooling maintained
- Greater than 20 minutes to core uncovery with no Operator action





Safety Significance Risk Assessment

Fail to Isolate AND Fail to Inject

Fail to isolate

0.1 ⇒ SI-407B fails to close

x 2 x 10⁻³ ⇒ Operator fails to close SI-405B or SI-401B

 $= 2 \times 10^{-4}$





Safety Significance Risk Assessment

Fail to inject

2 x 10⁻³ ⇒ Operator fails to start SI

+ 2 x 10⁻⁴ ⇒ HPSI A and HPSI B and LPSI A equipment failures

 $= 2.2 \times 10^{-3}$





Safety Significance Risk Assessment

Failure to isolate AND Failure to inject

$$(2 \times 10^{-4}) \times (2.2 \times 10^{-3}) = 4.4 \times 10^{-7}$$

Threshold for Low/Medium Significance is 1 x 10⁻⁵





REGULATORY PERSPECTIVE

Chip Perkins





Apparent Violation 1

LPSI Train B inoperable for more than 72 hours (TS 3.5.2)

- Violation was not willful
- Violation was self-revealing
- Violation had low actual safety significance
- Broad, comprehensive, and effective corrective actions completed or in progress to preclude recurrence of the root cause
- Broken reach rod gave false valve position indication





Apparent Violation 2

SI-417B not placed in the procedure-specified position (TS 6.8.1)

- Valve positioned by handwheel and local indication
- Failure of component resulted in undetected misposition.
- Root cause broken reach rod gave false indication of valve position
- Procedure/expectation could be improved to detect failures of this type
- Not a separate violation but the same as violation 1





Conclusion:

- Only one violation occurred
- Under the current regulatory framework, this violation could be considered a Level III
 - Deserving of mitigation due to:
 - Broad and comprehensive corrective actions
 - + Low actual safety significance in mode where TS applied
- Due to low safety significance, this should be a Level
 IV





Under the Revised Reactor Oversight Process the following evaluation would be made:

- For HFP Large LOCA event, Phase 2 SDP result is Green
 - results in a NCV with no civil penalty






Table 1 - Estimated Likelihood Rating for Initiating Event Occurrence During Degraded Period (taken from NuReg/CR-5499)

Row	Approx. Freq.	Example Event Type	Est. like	elihood	Rating
I	>1 per 1 -10 yr	Reactor Trip Loss of Condenser	Α	В	С
II	1 per 10 -10 ² yr	Loss of Offsite Power Total loss of main FW Stuck open SRV (BWR) MSLB (outside cntmt) Loss of 1 SR AC bus Loss if Instr/Cntrl Air Fire causing reactor trip	В	С	D
III	1 per 10 ² -10 ³ yr	SGTR Stuck open PORV/SV RCP seal LOCA (PWR) MFLB MSLB inside PWR containment Loss of 1 SR DC bus Flood causing reactor trip	С	D	Е
IV	1 per 10 ³ -10 ⁴ yr	Small LOCA Loss of all service water	D	E	F
V	1 per 10 ⁴ -10 ⁵ yr	Medium LOCA Large LOCA (BWR)	E	F	G
VI	<1 per 10 ⁵ yr	Large LOCA (PWR) ISLOCA Vessel Rupture	F	G	Н
			>30 days	3-30 d	<3 days
			I -	sure Time ded Condi	





Table 2 - Risk Significance Estimation Matrix

Remaining	Mitigation	Capability	(From	Step 2.3)
•				

Initiating	1	2	3	4	5	6	7
Event Likelihood (from Step	3 diverse trains	1 train + 1 system with redundancy	2 diverse trains	1 train + recovery of the failed train	1 train	Recovery of failed train	
2.2)	OR	OR	OR	OR	OR		
	2 systems each with redundancy	2 diverse trains +	1 system with	1 system with redundancy	with in redundancy in the control of		
		recovery of failed train	redundancy + recovery of failed train	(automatic initiation or no time contraints)			
			17 3		r 191 1 (1) 1 (1) 1 (1) 1 (1)		
Α		w	У	. I'			
В			W ·	У			
С				W	y !		
D					w	У	
E) i 1	W	У
<u> </u>							W
<u>G</u> H		14					



5.3 CHECKING VALVE POSITION (cont'd)

- 5.3.8 For valves with remote indicators on the RTGB <u>or</u> local control panels, these indicators may be used to determine actual valve position.
- 5.3.9 The checking of a valve normally operated by reach rod or other manual remote operator, should be done locally at the valve when possible. The valve position may be checked at the remote position indication if a local check would present a safety or radiation hazard, or otherwise conflict with ALARA or if the valve is not accessible for other reasons.
- 5.3.9 The checking of a remotely operated manual valve (reach rod) should be performed by observation of the post indicator pin or the dial indicator, as applicable, on the remote operator assembly. A valve will be considered properly positioned with no further verification required when the remote handwheel becomes tight or difficult to operate with the post indicator pin or dial indicator indicating the required position. For those remote operators with a post indicator pin, the pin should not be bottomed out or topped out against the valve operator pedestal.
 - 5.3.9.1 If a valve position indicator pin bottoms out or tops out during repositioning or if a dial indicator is not indicating correctly, then perform the following:
 - 5.3.9.1.1 Verify valve position by at least one of the following methods:
 - Local position indication,
 - Computer point indication, or
 - Verification of system parameters (flow, pressure, etc.)
 - 5.3.9.1.2 Generate a Caution Tag for the valve and hang the tag on the remote handwheel.
 - 5.3.9.1.3 Generate an MAI on the reach rod post indicator.
 - 5.3.9.1.4 Generate a Work Around on the valve position verification.

5.3 CHECKING VALVE POSITION (cont'd)

5.3.8 For valves with remote indicators on the RTGB or local control panels, these indicators may be used to determine actual value.

- The checking of a valve normally operated by reach rod or other manual remote operator, should be done locally at the valve when possible. The valve position may be checked at the remote position indication if a local check would present a safety or radiation hazard, or otherwise conflict with ALARA or if the valve is not accessible for other reasons.
- 5.3.10 When performing valve lineups, personnel should determine Operability of control valves by checking that:
 - A. Pins are removed from valve operators.
 - B. Air is available to pneumatically operated valves.
 - C. MAN-AUTO bypass levers are positioned to "AUTO".
 - D. All manual overrides are removed.
 - E. Power is available to control valve solenoids and/or motors. Power from PAC System can be verified by appropriate PAC Channel A(B)(AB)(NS) Condition Abnormal (E-2(E-3)(E-4) (D-4), Cabinet L) Annunciator clear.
- 5.3.11 Alternate verification techniques of valve positions may be used by the operator where specified by approved procedures or approved by the SS/CRS. Examples include:
 - Use of process parameters (flow, pressure)
 - Mechanical position indicators

ENCLOSURE 3

PREDECISIONAL ENFORCEMENT CONFERENCE AGENDA

CONFERENCE WITH ENTERGY OPERATIONS, INC. (EOI) WATERFORD STEAM ELECTRIC STATION, UNIT 3

MARCH 20, 2000

NRC REGION IV, ARLINGTON, TEXAS

1.	INTRODUCTIONS & OPENING REMARKS - NRC	ELLIS MERSCHOFF REGIONAL ADMINISTRATOR
2.	ENFORCEMENT PROCESS - NRC	GARY SANBORN DIRECTOR, ALLEGATIONS AND ENFORCEMENT STAFF
3.	APPARENT VIOLATIONS & REGULATORY CONCERNS - NRC	KEN BROCKMAN DIRECTOR, DIVISION OF REACTOR PROJECTS
4.	LICENSEE PRESENTATION - EOI	CHUCK DUGGER VICE PRESIDENT, OPERATIONS
5.	NRC CAUCUS (APPROXIMATELY 10 MINUTES)	
6.	RESUMPTION OF CONFERENCE	
7.	CLOSING REMARKS - EOI	CHUCK DUGGER VICE PRESIDENT, OPERATIONS
8.	CLOSING REMARKS - NRC	ELLIS MERSCHOFF REGIONAL ADMINISTRATOR

APPARENT VIOLATIONS*

PREDECISIONAL ENFORCEMENT CONFERENCE

ENTERGY OPERATIONS, INC.
WATERFORD STEAM ELECTRIC STATION, UNIT 3

MARCH 20, 2000

*NOTE: THE APPARENT VIOLATIONS DISCUSSED AT THIS PREDECISIONAL ENFORCEMENT CONFERENCE ARE SUBJECT TO FURTHER REVIEW AND MAY BE REVISED PRIOR TO ANY RESULTING ENFORCEMENT ACTION.

APPARENT VIOLATION

1. Technical Specification 3.5.2 requires that two independent emergency core cooling system (ECCS) subsystems be operable while in Modes 1, 2, or 3 (with pressurizer pressure greater than or equal to 1750 psia or RCS average temperature greater than or equal to 500 degrees F). Each operable ECCS subsystem is required to have an operable HPSI pump, an operable LPSI pump and an operable flowpath. One ECCS subsystem may be inoperable for 72 hours before a plant shutdown is required.

Contrary to this requirement, from November 19 to November 27, 1999, Low Pressure Safety Injection System Train B was inoperable as a result of Valve SI-417B being in the incorrect, open, position. This condition existed for approximately 7 days, which exceeded the allowed outage time.

APPARENT VIOLATION

2. Technical Specification 6.8.1.a states, in part, that written procedures shall be established, implemented, and maintained covering the applicable procedures recommended in Appendix A of Regulatory Guide 1.33, Revision 2, dated February 1978.

Regulatory Guide 1.33, Appendix A, Item 3.d, states, in part, that instructions for startup, shutdown, and changing modes of operation should be prepared for the emergency core cooling system.

Procedure OP-009-008, "Safety Injection System," Revision 15, Section 8.7, requires, in part, that Valve SI-417B be shut after completion of the evolution to recirculate water in the RWSP using the LPSI pump. Attachment 11.1 of this same procedure requires, in part, that the required position for Valve SI-417B is locked closed.

Contrary to the above, on November 19, 1999, operators failed to place Valve SI-417B in the locked closed position after they had completed recirculating the refueling water storage pool using Low Pressure Safety Injection Pump B. As a result, on November 27, 1999, as operators were placing shutdown cooling in service, approximately 5000 gallons of reactor coolant was inadvertently transferred from the reactor coolant system to the refueling water storage pool, causing a rapid a loss of level in the pressurizer and a partial depressurization of the reactor coolant system.