

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064 March 31, 2000

William T. Cottle, President and Chief Executive Officer STP Nuclear Operating Company P.O. Box 289 Wadsworth, Texas 77483

SUBJECT: PLANT PERFORMANCE REVIEW - SOUTH TEXAS PROJECT

Dear Mr. Cottle:

Template RGN-002

The purpose of this letter is to communicate our assessment of your performance and to inform you of our planned inspections at your facility. On March 2, 2000, we completed a Plant Performance Review (PPR) of South Texas Project. We conduct these reviews to develop an integrated overview of the safety performance of each operating nuclear power plant. We use the results of the PPR in planning and allocating inspection resources and as inputs to our senior management meeting (SMM) process. This PPR evaluated inspection results and safety performance information for the period from January 25, 1999, through February 11, 2000, but emphasized the last 6 months to ensure that our assessment reflected your current performance. Our most recent summary of plant performance at South Texas Project was provided to you in a letter dated September 16, 1999.

The NRC has been developing a revised reactor oversight process that will replace our existing inspection and assessment processes, including the PPR, SMM, and Systematic Assessment of Licensee Performance (SALP). We recently completed a pilot program for the revised reactor oversight process at nine participating sites and are making necessary adjustments based on feedback and lessons learned. We are beginning initial implementation of the revised reactor oversight process industry-wide, including your facility, on April 2, 2000.

This PPR reflects continued process improvements as we make the transition into the revised reactor oversight process. You will notice that the following summary of plant performance is organized differently from our previous performance summaries. Instead of characterizing our assessment results by SALP functional area, we are organizing the results into the strategic arenas embodied in the revised reactor oversight process. Additionally, in assessing your performance we have considered the historical performance indicator data that you submitted in January 2000 in conjunction with the inspection results. The results of this PPR were used to establish the inspection plan in accordance with the new risk-informed inspection program (consisting of baseline and supplemental inspections). Although this letter incorporates some terms and concepts associated with the new oversight process, it does not reflect the much broader changes in inspection and assessment that will be evident after we have fully implemented our revised reactor oversight process.

During the last 6 months, both units of South Texas Project operated at or near full power, but encountered several challenges. Unit 1 tripped during performance of main turbine trip testing. Unit 2, in addition to being shut down for refueling, required two significant power reductions as a result of a loss of low pressure feedwater heater condensate flow and to allow a weld repair on a water detection drain line under the main generator. Overall, South Texas Project continues to operate in a safe manner.

-2-

We did not identify any significant performance issues in the reactor safety, radiation safety, or safeguards strategic arenas. We did note that you were challenged by balance-of-plant problems during this assessment period. Replacement of the Unit 1 steam generators is considered a significant and unique activity that warrants inspection in addition to the baseline inspection program. As a result, additional inspections will be conducted during the replacement outage.

Enclosure 1 contains a historical listing of plant issues, referred to as the Plant Issues Matrix (PIM), that were used during this PPR process to arrive at our integrated view of your performance trends. The PIM for this assessment is grouped by the prior SALP functional areas of operations, maintenance, engineering, and plant support, although the future PIM will be organized along the cornerstones of safety as described in the revised reactor oversight process. The attached PIM includes items summarized from inspection reports or other docketed correspondence regarding South Texas Project. We did not document all aspects of licensee programs and performance that may be functioning appropriately. Rather, we only documented issues that we believe warrant management attention or represent noteworthy aspects of performance. In addition, the PPR may also have considered some predecisional and draft material that does not appear in the attached PIM, including observations from events and inspections that had occurred since our last inspection report was issued but had not yet received full review and consideration. We will make this material publically available as part of the normal issuance of our inspection reports and other correspondence.

Enclosure 2 lists our planned inspections for the period April 2000 through March 2001 at South Texas Project to allow you to resolve scheduling conflicts and personnel availability in advance of our inspector arrival onsite. The inspection schedule for the latter half of the period is more tentative and may be adjusted in the future due to emerging performance issues at South Texas Project or other Region IV facilities. Routine resident inspections are not listed due to their ongoing and continuous nature.

We will inform you of any changes to the inspection plan. If you have any questions, please contact me at (817) 860-8243.

Sincerely.

Josèph I. Tapia, Chiéf Project Branch A Division of Reactor Projects

Docket Nos.: 50-498 50-499 License Nos.: NPF-76 NPF-80

Enclosures:

1. Plant Issues Matrix

2. Inspection Plan

cc w/enclosures: T. H. Cloninger, Vice President Engineering & Technical Services STP Nuclear Operating Company P.O. Box 289 Wadsworth, Texas 77483

S. M. Head, Supervisor, Licensing Quality & Licensing Department STP Nuclear Operating Company P.O. Box 289 Wadsworth, Texas 77483

A. Ramirez/C. M. Canady City of Austin Electric Utility Department 721 Barton Springs Road Austin, Texas 78704

M. T. Hardt/W. C. Gunst City Public Service Board P.O. Box 1771 San Antonio, Texas 78296

D. G. Tees/R. L. Balcom Houston Lighting & Power Company P.O. Box 1700 Houston, Texas 77251

Jon C. Wood Matthews & Branscomb One Alamo Center 106 S. St. Mary's Street, Suite 700 San Antonio, Texas 78205-3692

A. H. Gutterman, Esq. Morgan, Lewis & Bockius 1800 M. Street, N.W. Washington, D.C. 20036-5869

G. E. Vaughn/C. A. Johnson Central Power & Light Company P.O. Box 289 Mail Code: N5012 Wadsworth, Texas 77483

INPO Records Center 700 Galleria Parkway Atlanta, Georgia 30339-5957

Bureau of Radiation Control State of Texas 1100 West 49th Street Austin, Texas 78756

Jim Calloway Public Utility Commission William B. Travis Building P.O. Box 13326 1701 North Congress Avenue Austin, Texas 78701-3326

John L. Howard, Director Environmental and Natural Resources Policy Office of the Governor P.O. Box 12428 Austin, Texas 78711-3189

Judge, Matagorda County Matagorda County Courthouse 1700 Seventh Street Bay City, Texas 77414

Mayor, City of Bay City City Hall 1901 Fifth Street Bay City, Texas 77414

Mayor, City of Palacios P.O. Box 845 Palacios City Hall Palacios, Texas 77465

James Mitchell, Sheriff Matagorda County 2323 Avenue E Bay City, Texas 77414

Federal Emergency Management Agency R. L. "Buddy" Young, Regional Director Region VI, Federal Center 800 North Loop 288 Denton, Texas 76201-3698

Office of the Governor Director, Environmental Policy State Liaison Officer P.O. Box 12428 Austin, TX 78756-3189

-6-

bcc to DCD (IE40)

bcc electronic distribution from ADAMS by RIV: Regional Administrator (EWM) DRP Director (KEB) DRS Director (ATH) Senior Resident Inspector (NFO) Branch Chief, DRP/A (JIT) Senior Project Engineer, DRP/A (DNG) Branch Chief, DRP/TSS (LAY) RITS Coordinator (NBH) B. Henderson, PAO (BWH) C. A. Hackney, RSLO (CAH) C. J. Gordon (CJG) DRS Branch Chiefs (GMG, DAP, JLP) W. D. Travers, EDO (WDT) W. M. Dean, Chief, NRR/DIPM/IIPB (WMD) R. K. Frahm, PPR Program Manager, NRR/ILPB (RKF) B. A. Boger, Associate Dir. for Inspection and Programs (BAB2) B. W. Sheron, Associate Dir. for Project Licensing and Technical Analysis (BWS) G. M. Tracy, Chief, Regional Operations Staff, OEDO (GMT) S. Richards, NRR Project Director (SAR) R. Gramm, Chief, Section 1, NRR/DLPM (RAG) J. Nakoski, NRR Project Manager (JAN1)

bcc hard copy: RIV File Room Record Center, INPO

To receive copy of	aoc	ument, indicate in bu	IX: C = COpy Without end	losules				 _
C:DRP/A	0	D:DRS/	D:DRP)	Signature			
JITapia;df 🛇	[ATHOWAI	KEBrocking	in l	JITapia	X_	1	
3/22/00	7	3/ 2/100	3/30/00		3/20/00	<u> </u>		
	7		OFFICIAL RECOR	D CO	PY	\overline{V}		

DOCUMENT NAME: S:\PPR 2000-01\PPR Letters\STP.wpd

-6-

bcc to DCD (IE40)

bcc electronic distribution from ADAMS by RIV: Regional Administrator (EWM) DRP Director (KEB) DRS Director (ATH) Senior Resident Inspector (NFO) Branch Chief, DRP/A (JIT) Senior Project Engineer, DRP/A (DNG) Branch Chief, DRP/TSS (LAY) **RITS Coordinator (NBH)** B. Henderson, PAO (BWH) C. A. Hackney, RSLO (CAH) C. J. Gordon (CJG) DRS Branch Chiefs (GMG, DAP, JLP) W. D. Travers, EDO (WDT) W. M. Dean, Chief, NRR/DIPM/IIPB (WMD) R. K. Frahm, PPR Program Manager, NRR/ILPB (RKF) B. A. Boger, Associate Dir. for Inspection and Programs (BAB2) B. W. Sheron, Associate Dir. for Project Licensing and Technical Analysis (BWS) G. M. Tracy, Chief, Regional Operations Staff, OEDO (GMT) S. Richards, NRR Project Director (SAR) R. Gramm, Chief, Section 1, NRR/DLPM (RAG) J. Nakoski, NRR Project Manager (JAN1)

bcc hard copy: RIV File Room Record Center, INPO

To receive copy o	1 400			<u> </u>	copy ma	iout cin	0000100	<u> </u>		0110100		1 = 110 0	
C:DRP/A	\square	D:E)RS/		D:DR	Ρ (P	Signatur	e 🗸	<u> </u>			
JITapia;df 🥄	\mathbf{K}	AT	Howal	1	KEBR	ockra	aĥ	JITapia	\bigcirc	2	1		
3/22/00	\square	3/ (L/XOO		3/3/0/	00 \	\mathcal{L}	3/20/00		<u> </u>			
	J			OFFIC	IAL RE	COR	DCO	PY		/			

DOCUMENT NAME: S:\PPR 2000-01\PPR Letters\STP.wpd

Page: 1 of 22 03/29/2000 17:21:42 IR Report 3

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

By Primary Functional Area

1

,

.

Region IV

02/09/2000 1990/21 Pri: OPS NRC NRC Pri: 3B Spurious AMSAC turbine trip highlighted system, procedure, and knowledge deficiencies. 02/09/2000 Sec: Sec: A spurious AMSAC turbine trip highlighted system, procedure, and knowledge deficiencies. 05/00040B South Texas 1 Sec: A spurious AMSAC turbine trip highlighted system, procedure, and knowledge deficiencies. 05/00040B South Texas 2 Sec: A spurious AMSAC turbine trip highlighted system, procedure, and knowledge deficiencies. 12/25/1999 1999020 Pri: OPS NRC NEG Sec: Sec: Sec: Sec: Coperators attempted to isolate the normal feel control valve for a low pressure feedwater heater without a procedure, major plant transient complicated by unidentified material condition of participation and boration, and then procedure, major plant transient complicated by unidentified material condition of participation and boration, and then procedure in use 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 3B Sec: Sec: Sec: Sec: Sec: Sec: 05000499 South Texas 1 Sec: Sec: Sec: Sec: Sec: Sec: 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 3B	Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
Sec: Sec: Sec: Sec: Sec: Sec: Sec: Ter: 3C A sputches turbine tig was caused by an exclusion of the ATWS (anticipated transient without screent) Militigation Orizont (AMSAC) shorth was the system automatically armed. The system was preparing to arm as obsoluted to submit the system was preparing to arm as obsoluted to submit the system was preparing to arm as obsoluted frow signal provided to AASC was about 6 percent lower than control room indications because it was not temperature compensated. The licensee decided to folder the industry practice of manually armed. The system provided to AASC was about 6 percent lower than control room indications because it was not temperature compensated. The licensee decided to folder the industry practice of manually arming AMSAC and there withing and the licensee decided to folder the industry practice of manually arming AMSAC and there withing and the licensee decided to folder the industry practice of manually arms of the approximation terming AMSAC and there within a two decider of manually arms of the system provided to AASC was about 6 percent lower than a major plant translent complicated by undentified material conditionally. Genetices at the informatical deficiencies. A reput power invicts and the system informatice with the system reparts are complicated by a percent for the folder. The action reparts are according and practices in the conditional was acceeded but not recognized material deficiencies. A reput power invicts and was acceeded but not recognized because the requirement was not for the folder the robust and practices in was an acceeded but not recognized because the requirement was not for the folder to acceed and but recognized material deficiencies of conditional was acceeded but not recognized because the requirement was not for the fole proted conditional was acceeded but not recognized beca	02/09/2000	1999021	Pri: OPS	NRC	NEG	Pri: 3B	Spurious AMSAC turbine trip highlighted system, procedure, and knowledge deficiencies.
Dockets Discussed: 05000499 South Texas 1 05000499 South Texas 2 Ter: 3C 12/25/1999 1999020 Pri: OPS NRC NEG Dockets Discussed: 05000499 South Texas 2 A feedwater heater factor and the owner than control room indicating within the system range products of a signify fighting and the low feedwater for the owner than control room indicating withing and products of the working the law resolution and the law resolution range thereader thaw resolution range the resolution range the l	02/03/2000		Sec:			Sec: 4A	A spurious turbine trip was caused by an actuation of the ATWS (anticipated transient without scram) Mitigation
05000498 South Texas 1 power processed Additionaly, operators were unevane that the feedwater flow signal provided to AMSAC was about 6 power full committee informatic and the intersee decided to follow the industry practice of manually arming AMSAC after verying no trip condition existed at a sightly higher power level than it would automatically arm to avoid future spurious trips. 12/25/1999 1999020 Pri: OPS NRC NEG Pri: B A feedwater heater tagout resulted in a major plant transient complicated by unidentified material conditionally, operators was not emperature or a low pressure feedwater heater, sin, part due to existing but unrecognized in sequentially isolating all three strings of low pressure feedwater heaters, in part due to positing but unrecognized insequentially isolating all three strings of low pressure feedwater heaters, in part due to positing but unrecognized insequentially isolating all three strings of low pressure feedwater heaters, in part due to positing but unrecognized to solate the normal level control valve for a low pressure feedwater heaters, in part due to positing but unrecognized by several automatic valve faulters. A reaction the material dentices. A read power reduction and braction, and then did so in a poort pocerting automater. This existing a poort eduction and bracters, and then did so in a poort pocerting and may of the procedures in use 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 38 Reactivity manipulations were not properly balanced between borations and rod insertion and, as a result, the rod insertion in mode and so can statement the researce or contribute and pressure transient was made more servere and Technical Spedictician coston statement for seconding the minimum memerature an	Dockets Disc	ussed:				Ter: 3C	System Actuation Circuit (AMSAC) shortly after the system automatically armed. The system provided operators no warning that a low feedwater flow condition was sensed and no warning that the system was preparing to arm as
05000499 South Texas 2 Pri: OPS NRC NEG Pri: 1B A feedwater hear control noom indications because it was not temperature compensated. The licensee decided to follow the industry practice of manually arming AMSC. after verifying no trip conditions existed at a slightly figher power level than it would automatically arm to avoid future spunous trips. 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 1B A feedwater heater fagout resulted in a major plant translent complicated by unidentified material conditions. 05000499 South Texas 2 Sec: Ter: 3C A feedwater heater fagout resulted in a major plant translent complicated by unidentified material conditions. 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 3B Reactivity manipulations was exceeded but not recognized because the requirement was not included in any of the procedures in use 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 3B Reactivity manipulations was a could be altomatic complicated by severe. 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 3B Reactivity manipulations was exceeded but not recognized because the requirement was not included in any of the procedures in use Necestro reactivity manipulations was exceeded but not recognized because the requirement was not included in any of the procedures in use 12/25/1999 1999020 Pri: OPS </td <td>05000498 Sou</td> <td>ith Texas 1</td> <td></td> <td></td> <td></td> <td></td> <td>power increased. Additionally, operators were unaware that the feedwater flow signal provided to AMSAC was</td>	05000498 Sou	ith Texas 1					power increased. Additionally, operators were unaware that the feedwater flow signal provided to AMSAC was
12/25/1999 1999020 Pri: OPS NRC NEG Pri: 18 A feedwater heater tagout resulted in a major plant transient complicated by unidentified material conditionation spectrom setting in a comparison of the procedure. This action resulted in a complexity in the procedure material deficiencies. A regin power reduction was necessary due to reduced condensate system flow, but ontrocomplex directed material deficiencies. A regin power reduction was necessary due to reduced condensate system flow, but ontrocom operators were slow to initiate a power reduction was necessary due to reduced condensate system flow, but ontrocom operators were slow to initiate a power reduction and other did so in a poorty coordinated manner. This event was complicated by several automatic valve failures. A reactor trip criterion intraded to protect equipment was exceeded but not recognized because the requirement was not included in any of the procedures in use 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 38 Reactivity manipulations made a routine transient more severe. 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 38 Reactivity manipulations made a routine transient constrol on dimension innot de to contrade severe and Technical Specification action statements for exceeding the minimum temperature for critically and departure from nucleate boiling minimum pressure were servered on system operability of ventilation equipments for secret or ordenta system flow on pressure transient was made more assure and Technical Specification and severe and pressure transient was readered the system minimum temperature for critically and departure from nucleate boiling minimum pressure werestered to their	05000499 Sou	ith Texas 2					about 6 percent lower than control room indications because it was not temperature compensated. The licensee decided to follow the industry practice of manually arming AMSAC after verifying no trip conditions existed at a slightly higher power level than it would automatically arm to avoid future spurious trips.
Sec: Sec: Sec: Sec: Sec: Coperators attempted to isolate the normal level control valve for a low pressure feedwater heater, in part due to existing but unrecognized material deficiencies. A rapid power reduction was necessary due to reduced condensate system flow, but control room operators were slow to initiate a power reduction and boration. and then due to existing but unrecognized material deficiencies. A rapid power reduction and boration. and then due to existing but unrecognized material deficiencies. A rapid power reduction and boration. and then due to existing but unrecognized material deficiencies. A reactor tip criterion intended to protect equipment was exceeded but not recognized because the requirement was not included in any of the procedures in use 12/25/1999 1999020 Pri: OPS Sec: NRC NEG Pri: 38 Sec: 32 Ter: 18 Reactivity manipulations made a routine transient more severe. 12/25/1999 1999020 Pri: OPS Sec: NRC NEG Pri: 50 Sec: Sec: 32 Ter: 18 Reactivity manipulations were not property balanced between borations and rod insertion in orde the rod insertion limit was closely approached. Operators chose to override a utomatic control ordi insertion in orde the rod insertion limit was closely approached. Operators chose to override a utomatic control ordi made more severe and Technical Specification action statements for exceeding the minimum temperature for criticality and departure from nucleate boiling minimum pressure were entered for brief periods. 12/25/1999 1999020 Pri: OPS Sec: NRC NEG Pri: 50 Sec: 10 Opera	12/25/1999	1999020	Pri: OPS	NRC	NEG	Pri: 1B	A feedwater heater tagout resulted in a major plant transient complicated by unidentified material condition
Dockets Discussed: 05000499 South Texas 2 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 38 Reactivity manipulations made a routine transient more savere. 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 38 Reactivity manipulations were not properly balanced between boration, and then the rod insertion included in any of the procedures in use 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 38 Reactivity manipulations made a routine transient more savere. 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 38 Reactivity manipulations were not properly balanced between borations and rod insertion in order to insertion in indice to preserve stude on a goory cooling at a main and the indice of a charcoal leak on operature for critically and departure from nucleate boling minimum pressure were entered for briet periods. 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 5C Operators failed to correctly determine the impact of a charcoal leak on operability of ventilation equipme critically as a departure for nucleate boling minimum pressure were entered for briet periods. 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 5C Operators failed to correctly determine the impact of a charcoal leak on operability of ventilation equipme critically periods. 05000499	12/20/1000		Sec:			Sec: 2A	Operators attempted to isolate the normal level control valve for a low pressure feedwater heater without a
05000499 South Texas 2 Pri: OPS NRC NEG Pri: 3B Reactivity manipulations made a routine transient more severe. 12/25/1999 199020 Pri: OPS NRC NEG Pri: 3B Reactivity manipulations made a routine transient more severe. 0cokets Discussed: Sec: Sec: Sec: Sec: Sec: Reactivity manipulations made a routine transient more severe. 12/25/1999 199020 Pri: OPS NRC NEG Pri: 3B Reactivity manipulations made a routine transient more severe. 0cokets Discussed: Sec: Sec: Ter: 1B Reactivity manipulations made a routine transient more severe. 12/25/1999 199020 Pri: OPS NRC NEG Pri: SC 0cokets Discussed: Sec: Sec: Operators failed to correctly determine the impact of a charcoal leak on operability of ventilation equipment more severe and Technical Specification action statements for exceeding the minimum temperature for criticality and departure from nucleate boiling minimum pressure were entrend for brief periods. 12/25/1999 199020 Pri: OPS NRC NEG Pri: SC Operators failed to correctly determine the impact of a charcoal leak on operability based on incomplete transient more severe and Technical Specification action statenemets for exselem incometable to presetor	Dockets Disc	ussed:				Ter: 3C	procedure. This action resulted in sequentially isolating all three strings of low pressure redwater heaters, in part due to eviating but unrecognized material deficiencies. A rapid power reduction was necessary due to reduced
12/25/1999 1999020 Pri: OPS NRC NEG Pri: 38 Reactivity manipulations made a routine transient more severe. Dockets Discussed: Sec: Sec: Sec: Sec: Reactor reactivity manipulations were not properly balanced between borations and rod insertion and, as a result, the rod insertion limit was closely approached. Operators chose to override automatic control rod insertion in orde to preserve shutdown margin. In doing so, the reactor collart system themperature and pressure ransient was made more severe and Technical Specification action statements for exceeding the minimum temperature for criticality and departure from nucleate boiling minimum pressure were entered for brief periods. 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 5C Operators failed to correctly determine the impact of a charcoal leak on operability of ventilation filter on December 3, 1999. It was enclosed boiling minimum pressure were entered for brief periods. 05000499 South Texas 1 Sec: Ter: 16 Operators identified a charcoal leak in the Train B fuel handling building emergency ventilation filter on December 3, 1999. It was enclosed because the leaks menoperability based on incomplete knowledge. Three and a half days later, the system engineer on August 23. In both cases, no Technical Specification fullition for Operation was exceeded because the leaks were quickly repaired. The licensee addressed the poor initial operability determinations in Condition Report 99-17218. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A	05000499 Sou	uth Texas 2					condensate system flow, but control room operators were slow to initiate a power reduction and boration, and then did so in a poorly coordinated manner. This event was complicated by several automatic valve failures. A reactor trip criterion intended to protect equipment was exceeded but not recognized because the requirement was not included in any of the procedures in use
Sec: Sec: Sec: Sec: Sec: Sec: Sec: Sec: Reactor reactivity manipulations were not properly balanced between borations and rod insertion and, as a result, the rod insertion init was closely approached. Operators chose to override automatic control rod insertion and, as a result, the rod insertion init was closely approached. Operators chose to override automatic control rod insertion and, as a result, the rod insertion init was closely approached. Operators chose to override automatic control rod insertion and, as a result, the rod insertion in orde more severe and Technical Specification action statements for exceeding the minimum temperature for criticality and departure from nucleate boiling minimum pressure were entered for brief periods. 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 5C Operators failed to correctly determine the impact of a charcoal leak on operability of ventilation equipme form nucleate boiling minimum pressure were entered for brief periods. 05000498 South Texas 1 Unit 2 operators failed to correctly determine the impact on system coreopability based on incomplete knowledge. Three and a half days later, the system engineer determined that the leak rendered the system inoperable until evaluated by the system engineer on August 23. In both cases, no Technical Specification Limiting Condition for Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A Plant Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25	12/25/1999	1999020	Pri: OPS	NRC	NEG	Pri: 3B	Reactivity manipulations made a routine transient more severe.
Dockets Discussed: Ter: 1B Ter: 1B the rod insertion limit was closely approached. Operators chose to overnoe automatic control of ansertion in order to preserve shufdown margin. In doing so, the reactor cooland system temperature and pressure transient was to preserve shufdown multiple south reas 1 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 5C Operators failed to correctly determine the impact of a charcoal leak on operability of ventilation equipme 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 5C Operators failed to correctly determine the impact of a charcoal leak on operability of ventilation equipme 05000498 South Texas 1 Sec: Sec: Viii 2 operators identified a charcoal leak in the Train B fuel handling building emergency ventilation filter on December 3, 1999. It was erroneously considered to have no impact on system operability based on incomplete knowledge. Three and a half days later, the system engineer determined that the leak the system inoperable. On August 19, 1999, a similar leak in Unit 1 was not recognized as rendering the system inoperable until evaluated by the system engineer on August 23. In both cases, no Technical Specification Limiting Condition for Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A Plant Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25/1999 1999020 Pri: OPS NR	12,20,1000		Sec:			Sec: 3C	Reactor reactivity manipulations were not properly balanced between borations and rod insertion and, as a result,
12/25/1999 1999020 Pri: OPS NRC NEG Pri: 5C Operators failed to correctly determine the impact of a charcoal leak on operability of ventilation equipme 12/25/1999 1999020 Pri: OPS NRC NEG Pri: 5C Operators failed to correctly determine the impact of a charcoal leak on operability of ventilation equipme Dockets Discussed: Sec: X Unit 2 operators identified a charcoal leak in the Train B fuel handling building emergency ventilation filter on December 3, 1999. It was erroneously considered to have no impact on system operability based on incomplete inoperable. On August 19, 1999, a similar leak in Unit 1 was not recognized as rendering the system inoperable until evaluated by the system engineer on August 23. In both cases, no Technical Specification Limiting Condition for Operation was exceeded because the leaks were quickly repaired. The licensee addressed the poor initial operability determinations in Condition Report 99-17218. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A Plant Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A Plant Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25/1999 1999020 Pri: OPS NRC PCS Fri: 5C Sec: 5B 05000498 South Texas 1 Sec: Sec:	Dockets Disc 05000499 So	ussed: uth Texas 2				Ter: 1B	the rod insertion limit was closely approached. Operators close to overhoe automatic control rod insertion in order to preserve shutdown margin. In doing so, the reactor coolant system temperature and pressure transient was made more severe and Technical Specification action statements for exceeding the minimum temperature for criticality and departure from nucleate boiling minimum pressure were entered for brief periods.
Sec: Sec: Sec: Number of the system Sec: Sec: Init 2 operators identified a charcoal leak in the Train B fuel handling building emergency ventilation filter on December 3, 1999. It was erroneously considered to have no impact on system operability based on incomplete knowledge. Three and a half days later, the system engineer determined that the leak rendered the system inoperable. On August 19, 1999, a similar leak in Unit 1 was not recognized as rendering the system inoperable until evaluated by the system engineer on August 23. In both cases, no Technical Specification Limiting Condition for Operations was exceeded because the leaks were quickly repaired. The licensee addressed the poor initial operability determinations in Condition Report 99-17218. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A Plant Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A Plant Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A The inspectors observed that the Plant Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A The inspectors observed that the Plant Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25/1999 1999020	12/25/1999	1999020	Pri: OPS	NRC	NEG	Pri: 5C	Operators failed to correctly determine the impact of a charcoal leak on operability of ventilation equipment
Dockets Discussed: December 3, 1999. It was eroneously considered to may be no impact on system operability based on incomplete knowledge. Three and a half days later, the system engineer determined that the leak rendered the system inoperable system inoperable. On August 19, 1999. a similar leak in Unit 1 was not recognized as rendering the system inoperable until evaluated by the system engineer on August 23. In both cases, no Technical Specification Limiting Condition for Operation was exceeded because the leaks were quickly repaired. The licensee addressed the poor initial operability determinations in Condition Report 99-17218. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A Plant Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A Plant Operations Review Committee and the Nuclear Safety Review Board were effective. 05000498 South Texas 1 Sec: Sec: Sec: 5B The inspectors observed that the Plant Operations Review Committee and the Nuclear Safety Review Board were effective in identifying and resolving problems and improving plant operations. Committee members actively challenged the plant staff with questions focused on asfety while reviewing plant procedure changes, safety evaluations, and modifications. Technical Specification requirements governing these committees were satisfied evaluations, and modifications. Technical Specification requirements governing these committees were satisfied	12/23/1999	1333020	Sec:			Sec: 1A	Unit 2 operators identified a charcoal leak in the Train B fuel handling building emergency ventilation filter on
05000498 South Texas 1 05000498 South Texas 1 05000499 South Texas 2 inoperable 05000499 South Texas 2 Pri: OPS 12/25/1999 1999020 Pri: OPS NRC Sec: Sec: Dockets Discussed: Ter: 5C Dockets Discussed: Ter: 5C Dockets Discussed: Ter: 5C	Dockets Disc	ussed:				Ter:	becomber 3, 1999. It was enoneously considered to have no impact on system operability based on incomplete knowledge. Three and a half days later, the system engineer determined that the leak rendered the system
05000499 South Texas 2 until evaluated by the system engineer on August 25. In both cases, no Technical Specification Limiting Condition for Operation was exceeded because the leaks were quickly repaired. The licensee addressed the poor initial operability determinations in Condition Report 99-17218. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A Plant Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A Plant Operations Review Committee and the Nuclear Safety Review Board were effective. Sec: Sec: Sec: 5B The inspectors observed that the Plant Operations Review Committee and the Nuclear Safety Review Board were effectively in identifying and resolving problems and improving plant operations. Committee members actively challenged the plant staff with questions focused on safety while reviewing plant procedure changes, safety evaluations, and modifications. Technical Specification requirements governing these committees were satisfied.	05000498 So	uth Texas 1					inoperable. On August 19, 1999, a similar leak in Unit 1 was not recognized as rendering the system inoperable
12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A Plant Operations Review Committee and the Nuclear Safety Review Board were effective. 12/25/1999 1999020 Pri: OPS NRC POS Pri: 5A Plant Operations Review Committee and the Nuclear Safety Review Board were effective. Sec: Sec: Sec: 5B The inspectors observed that the Plant Operations Review Committee and improving plant operations. Committee members actively effective in identifying and resolving problems and improving plant operations. Committee members actively challenged the plant staff with questions focused on safety while reviewing plant procedure changes, safety evaluations, and modifications. Technical Specification requirements governing these committees were satisfied.	05000499 So	uth Texas 2					until evaluated by the system engineer on August 23. In boin cases, no recrinical Specification Limiting Condition for Operation was exceeded because the leaks were quickly repaired. The licensee addressed the poor initial operability determinations in Condition Report 99-17218.
Sec: Sec: Sec: The inspectors observed that the Plant Operations Review Committee and the Nuclear Safety Review Board were effective in identifying and resolving problems and improving plant operations. Committee members actively challenged the plant staff with questions focused on safety while reviewing plant procedure changes, safety evaluations, and modifications. Technical Specification requirements governing these committees were satisfied.	12/25/1000	1999020	Pri: OPS	NRC	POS	Pri: 5A	Plant Operations Review Committee and the Nuclear Safety Review Board were effective.
Dockets Discussed: Ter: 5C 05000498 South Texas 1 South Texas 2	1212011335	1333020	Sec:			Sec: 5B	The inspectors observed that the Plant Operations Review Committee and the Nuclear Safety Review Board were
05000498 South Texas 1 05000498 South Texas 2	Dockate Die	cussed:		•		Ter: 5C	effective in identifying and resolving problems and improving plant operations. Committee members actively challenged the plant staff with questions focused on safety while reviewing plant procedure changes safety
account Tayor 2	05000498 Sc	outh Texas 1					evaluations, and modifications. Technical Specification requirements governing these committees were satisfied.
05000433 50001 18745 2	05000499 Sc	outh Texas 2					

By Primary Functional Area

.

*

.

Region IV SOUTH TEXAS PROJECT

Date	Source	Functional Area	D	Туре	Template Codes	item Title Item Description
12/25/1999	1999020-01	Pri: OPS	NRC	NCV	Pri: 3C	Procedures did not direct prompt entry into abnormal operating procedures or prompt power reduction or gi
Dockets Discussed: 05000499 South Texas 2		Sec:			Sec: 1B Ter:	Annunciator response procedures that indicated reduced condensate flow did not direct entry into the abnormal operating procedure for rapid load reduction. In addition, adequate procedural guidance was not provided for timing and flow rate of borations during a rapid load reduction to avoid loss of shutdown margin. These procedural inadequacies constitute multiple examples of procedures inappropriate to the circumstances and are a violation of 10 CFR Part 50, Appendix B, Criterion V. This issue was entered in the licensee's corrective action program as Condition Report 99-17296. This Severity Level IV violation is being treated as a noncited violation, consistent with Section VII.B.1.a of the NRC Enforcement Policy.
12/25/1999	1999020-02	Pri: OPS	NRC	NCV	Pri: 5C	Inadequate corrective actions from a similar event contributed to isolation of feedwater heaters.
Dockets Disc 05000499 Sol	ussed: uth Texas 2	Sec:			Sec: Ter:	Corrective actions for a previous uncontrolled power increase caused by improper operation without a procedure of a reheater drain tank level control system were too narrowly focused. Procedural guidance was only created for the reheater drain tank, even though the same guidance was needed for all feedwater heaters. The inadequate corrective actions were a violation of 10 CFR Part 50, Appendix B, Criterion XVI. This issue was entered in the licensee's corrective action program as Condition Report 99-17296. This Severity Level IV violation is being treated as a noncited violation, consistent with Section VII.B.1.a of the NRC Enforcement Policy.
12/25/1999	1999020-03	Pri: OPS	NRC	NCV	Pri: 3A	Failure to follow procedure resulted in inadvertent dilution of reactor coolant system.
Dockets Disc 05000499 So	u ssed: uth Texas 2	Sec:			Sec: Ter:	An inadvertent dilution of the reactor coolant system boron concentration caused a small increase in reactor power. The dilution resulted from an improper valve lineup while refilling the boron concentration monitor tank without a procedure. Operators quickly recognized the power increase and borated to restore power below 100 percent. The significance of the overpower transient was small due to the brief duration and small magnitude. The failure to utilize and follow the procedure for refilling the tank was a violation of 10 CFR Part 50, Appendix B, Criterion V. This issue was entered in the licensee's corrective action program as Condition Report 99-17762. This Severity Level IV violation is being treated as a noncited violation, consistent with Section VII.B.1.a of the NRC Enforcement Policy.
11/06/1999	1999018	Pri: OPS	NRC	NEG	Pri: 1A	THREE EXAMPLES OF POOR CONFIGURATION CONTROL BY OPERATORS
11/06/1999 1999018 Dockets Discussed: 05000498 South Texas 1 05000499 South Texas 2		Sec:			Sec: Ter:	Inspectors identified several problems with poor configuration control. A lock was not reinstalled on a motor operated valve breaker following maintenance to ensure the valve was not a source for a high energy line break; other administrative controls were adequate to prevent inappropriate operation of the valve, so no violation occurred. Operators failed to repressurize the control air header for Standby Diesel Generator 23 following maintenance, despite having an annunciator indicating the abnormal condition. The diesel tripped when it was started for post maintenance testing as a result; this was not a violation because the diesel was still out of service. Also, inspectors identified 37 motor control center switches, labeled as spares, which were in the ON position despite having no procedure to direct them to be placed in that position. The switches were energized but not connected to any load, so no safety issue existed.
11/06/1999	1999018	Pri: OPS	NRC	NEG	Pri: 1A	OPERATORS FAILED TO RECOGNIZE ENTRY INTO A TECHNICAL SPECIFICATION ACTION STATEMENT W
Dockets Dis 05000498 Sc 05000499 Sc	cussed: buth Texas 1 buth Texas 2	Sec:			Sec: Ter:	Inspectors identified that Unit 1 operators crosstied safety motor control centers E1A1 and E1A2, but failed to understand the requirements of and enter Technical Specification 3.8.3.1, action a. The condition existed briefly during post maintenance testing of the crosstie breaker, so the action statement was not violated.

Page: 3 of 22 03/29/2000 17:21:42 IR Report 3

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

By Primary Functional Area

1

٨

Region IV

Date	Source	Functional Area	ID	Туре	Template Codes	item Title item Description
11/06/1999	1999018	Pri: OPS	NRC	POS	Pri: 3A	MIDLOOP EVOLUTIONS PERFORMED IN CAREFUL MANNER IN UNIT 2
Dockets Disc 05000498 Sou	u ssed : ith Texas 1	Sec:			Sec: 1C Ter:	Reactor coolant system reduced inventory and midloop operations were performed in a controlled manner by operators who were knowledgeable and experienced in the evolution. Excellent supervisory oversight helped to effectively coordinate site activities and ensure the safe execution of this important evolution. The licensee conservatively stopped work on all jobs that had the potential to impact the evolution. Contingency actions were briefed in detail and assigned to specific personnel, and venting equipment was installed for immediate use
05000499 500	uth Texas 2					
11/06/1999	1999018	Pri: OPS	Licensee	POS	Pri: 5A	OPERATIONS SELF ASSESSMENT WAS PROBING, THOROUGH, AND BROAD IN SCOPE
Dockets Disc 05000498 Soi	ussed: uth Texas 1 uth Texas 2	Sec:			Sec: Ter:	The licensee conducted a thorough self assessment of plant operations. The assessment, performed by an experienced, multi-disciplined team of seven site people and seven industry peers, was broad in scope. The findings were self-critical, and were consistent with NRC observations.
11/00/1000	100019	Brit ODC	NBC		Pri: 54	INSPECTORS CONFIRMED LICENSEE ADEQUATELY CONTROLS POTENTIAL DRAINDOWN PATHS
11/06/1999	1999010	PII: UPS	NRC	P03	Sac	The inspectors confirmed that the licensee had adequately searched for potential draindown paths that could be
Dockets Disc 05000498 So 05000499 So	Dockets Discussed: 05000498 South Texas 1 05000499 South Texas 2				Ter:	created by operator error or equipment failures, and which could lead to a common-cause failure of residual heat removal and emergency core cooling system pumps during reduced inventory operations. The inspectors determined that the licensee had adequate administrative controls in place to reduce the likelihood of an inadvertent draindown of the reactor coolant system during reduced inventory operations.
11/06/1999	1999018-01	Pri: OPS	Licensee	NCV	Pri: 4A	SDG 22 RENDERED INADVERTENTLY INOPERABLE DUE TO DRAWING ERROR
Dockets Disc 05000498 So 05000499 So	u ssed: uth Texas 1 uth Texas 2	Sec:			Sec: 5A Ter:	Operators inadvertently rendered Standby Diesel Generator 22 inoperable while tagging out a portion of the starting air system for maintenance. A drawing error was not recognized until starting air was isolated to the entire system. Technical Specification requirements were quickly satisfied when the error was recognized. This issue was documented in Condition Report 99-13106. The inspectors determined that this was the first time the drawing error was identified or impacted system operability. Failure to have accurate system drawings was a violation of 10 CFR 50, Appendix B, Criterion V. However, this licensee identified and corrected violation will not be cited in accordance with Section VII.B.1.a of the Enforcement Policy.
09/24/1999	1999015	Pri: OPS	NRC	POS	Pri: 3B	LICENSEE'S EVALUATORS DEMONSTRATED HIGH COMPETENCE LEVEL
03/2 # 10000		Sec:			Sec:	The licensee's evaluators demonstrated high performance expectations for operators and sustained high levels of
Dockets Disc 05000498 So 05000499 So	c ussed: uth Texas 1 uth Texas 2				Ter:	competence in examination administration and operator performance assessment. Their threshold for generating constructive comments was low. Examination security was effectively maintained.
09/24/1999	1999015	Pri: OPS	NRC	STR	Pri: 3A	OPERATORS PERFORMED AT A HIGH LEVEL ON OPERATING TEST
	-	Sec:			Sec: 3B	The licensed operators performed at a high level during all portions of the biennial examinations with no crew or
Dockets Dise 05000498 Sc 05000499 Sc	cussed: outh Texas 1 outh Texas 2				Ter:	individual failure during the week of the inspection and only one crew failure during the previous four weeks, which was an overall improvement from that observed during the previous inspection. Communications and teamwork were strengths. During the dynamic scenarios, the operators advocated appropriate responses to changing plant conditions and as plant conditions deteriorated the shift management team conducted frequent briefings covering plant status and strategy for responding to events.

Page: 4 of 22 03/29/2000 17:21:42 IR Report 3

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

By Primary Functional Area

.

Region IV

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
09/13/1999	1999016	Pri: OPS	NRC	NEG	Pri: 3A	TWO EXAMPLES WHERE OPERATORS DID NOT DETERMINE THE OPERABILITY OF SAFETY RELATED EQI
		Sec:			Sec: 2A	inspectors identified two examples where operators did not determine the operability of safety-related equipment in
Dockets Discu	ussed:				Ter: 5A	a timely manner. Operators identified that charcoal was leaking out of the fuel handling building emergency ventilation exhaust filter bed, but did not properly communicate the magnitude of the shilled charcoal to the weekand
05000498 Sou 05000499 Sou	th Texas 1 th Texas 2					duty engineering staff. As a result, a performance test to determine the impact of the spille or operability was not conducted until Monday. The filter was found to have been operable. Similarly, operators did not properly communicate the symptoms of a failed power range nuclear instrument following a Unit 1 trip and, as a result, misdirected troubleshooting to find the problem. Specifically, operators did not indicate that all outputs from the instrument were affected. The instrument was declared operable after troubleshooting failed to identify a problem. During the subsequent startup, the instrument failed a channel check. Operators complied with the Technical Specifications, entered the applicable limiting condition for operation, and repaired the instrument.
09/12/1999	1999016	Pri: OPS	Self	NEG	Pri: 2A	UNIT 1 TRIPPED DUE TO A MATERIAL CONDITION DEFICIENCY IN THE TURBINE PROTECTION SYSTEM
		Sec:			Sec:	Unit 1 experienced a plant trip due to a material deficiency in the turbine protection system. While the licensee was
Dockets Discu	issed:				Ter:	a brief trip signal in Channel 2 at the same time operators were testing Channel 1. The switch was found to have
05000498 Sout	th Texas 1					been covered in dust and lint. The licensee's investigation of the trip was prompt and thorough.
08/07/1999	1999014	Pri: OPS	NRC	POS	Pri: 1B	Conservative decisions exhibited during Plant Operations Review Committee meeting
		Sec:	Nixe	100	Sec: 3A	Licensee management demonstrated a questioning attitude and conservative decision making during two position
Dockets Discussed: 05000498 South Texas 1 05000499 South Texas 2					Ter:	Plant Operations Review Committee meetings. Troubleshooting was properly focused, conducted safely, and identified the root cause of the June 27 trip. The plant was started up by knowledgeable operators with good safety focus.
07/15/1999	1999301	Pri: OPS	NRC	STR	Pri: 3A	Excellent examination was technically accurate and required no post exam changes.
		Sec:			Sec:	The licensee submitted an examination of excellent quality in that it was technically accurate, responsive to the
Dockets Discu 05000498 Sout 05000499 Sout	issed: Ih Texas 1 Ih Texas 2				Ter:	examination standards without significant changes from NRC review, and required no post examination changes to the grading keys. Detailed licensee process procedures contributed to excellent performance by the examination development and administration team.
07/15/1999	1999301	Pri: OPS	NRC	STR	Pri: 3B	All applicants passed exams and performed well on operating test.
		Sec:			Sec:	All 17 applicants passed the examinations and exhibited no broad knowledge or training weaknesses. The
Dockets Discu 05000498 Sout 05000499 Sout	ets Discussed:)498 South Texas 1)499 South Texas 2				Ter:	applicants performed well during the operating test while exhibiting good oversight and peer checking. Consistent with past observations, the applicants demonstrated strong communications skills throughout the operating test as did the plant control room personnel during special activities.
07/13/1999	1999014	Pri: OPS	NRC	POS	Pri: 1B	Rapid power reduction performed due to a fault in service water pump.
		Sec:			Sec: 3A	Unit 2 operators responded well to loss of a service water pump when the redundant pump was not available.
Dockets Discu 05000498 Sout 05000499 Sout	issed: th Texas 1 th Texas 2				Ter:	and allow for an orderly shutdown if the remaining pump was unable to carry the load. Extra operators were provided in the control room to assist and were skillfully directed as a team by the Unit Supervisor.

By Primary Functional Area

Region IV

SOUTH TEXAS PROJECT

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
06/28/1999	1999014	Pri: OPS	Self	NEG	Pri: 2A	Operators unnecessarily challenged by feedwater heater controller malfunction.
		Sec:			Sec:	After securing a low pressure feedwater heater drip pump for planned maintenance, the heater level control system
Dockets Disc 05000498 Sou 05000499 Sou	ussed: ith Texas 1 ith Texas 2				Ter:	behaved erraccally and led to the isolation of one low pressule neater string. Operators evaluated the situation and decided to disregard procedural guidance to reduce power to 90 percent with management concurrence. The heater string was restored in a reasonable time, and the procedure was clarified. This was an example of poorly performing balance of plant equipment challenging operators.
06/27/1999	1999014	Pri: OPS	Self	POS	Pri: 1B	Operators respond well to Unit 1 trip caused by loose wire in turbine control circuit.
		Sec:			Sec: 3A	Unit 1 operators responded well to a plant trip. All control rods inserted and plant systems responded as expected.
Dockets Disc 05000498 Sou 05000499 Sou	ussed: uth Texas 1 uth Texas 2			Ter: transient was caused b		transient was caused by a loose wire in the turbine control circuit.
06/26/1999	1999013-02	Pri: OPS	Licensee	NCV	Pri: 1B	Several dilutions made without determining plant response caused steam generator overpressure.
		Sec:			Sec: 3A	Operators failed to follow the plant startup procedure and caused a steam generator overpressure condition that
Dockets Disc 05000498 Soi 05000499 Soi	Dockets Discussed: 05000498 South Texas 1 05000499 South Texas 2				Ter:	was mingated when a steam generator power operated plant response or poreriors made several reactivity manipulations without properly determining the expected plant response or program did not provide specific guidance or limits on reactivity manipulations using the chemical control system. Operators focused on power changes and failed to recognize that temperature was out of limits. A noncited violation was identified for failure to follow the plant startup procedure while controlling coolant temperature, which was entered in the licensee's corrective action program under Condition Report 99-3690.
06/10/1999	1999008	Pri: OPS	NRC	POS	Pri: 5A	The corrective action process was effective, timely and properly prioritized, evaluated and resolved problem
		Sec:			Sec: 5B	The licensee implemented an effective and timely corrective action process that properly prioritized, evaluated and
Dockets Disc 05000498 So 05000499 So	a ussed : uth Texas 1 uth Texas 2				Ter: 5C	threshold for identifying conditions.
06/03/1999	1999013-01	Pri: OPS	NRC	NCV	Pri: 1A	Shift supervisor authorized deviating from procedure for vacuum fill of the residual heat removal system.
Dockets Disc 05000498 So 05000499 So	06/03/1999 1999013-01 Dockets Discussed: 05000498 South Texas 1 05000499 South Texas 2				Sec: 3A Ter:	Inspectors identified a noncited violation for failure to follow procedures by a shift supervisor when he authorized deviation from a procedure used to vacuum-fill the residual heat removal system. When the specified vacuum could not be attained, the shift supervisor erroneously believed that he could authorize continuing with the vacuum that could be attained, contrary to station procedures. This issue was entered into the licensee's corrective action program as Condition Report 99-8977. The inspectors also observed a poor work practice when an operator hit a system vent valve with a wrench to stop a minor seat leak.
05/16/1999	1999013	Pri: OPS	NRC	POS	Pri: 18	Unit 1 operators responded well to a plant trip caused by trip of reactor coolant pump.
		Sec:			Sec: 3A	Unit 1 operators responded well to a plant trip on loss of power to one of the reactor coolant pumps. All control rods
Dockets Dise 05000498 So 05000499 So	Dockets Discussed: 05000498 South Texas 1 05000499 South Texas 2				Ter: 3B	and quickly stabilized the plant in Mode 3.

Item Type (Compliance, Followup, Other), From 01/25/1999 To 02/11/2000

r . c

.

By Primary Functional Area

Region IV

SOUTH TEXAS PROJECT

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
05/15/1999	1999011	Pri: OPS	NRC	POS	Pri: 1A	Operators responded well to a feedwater transient and avoided a plant trip.
		Sec:			Sec: 3A	Reactor operators responded well to a feedwater flow transient and precluded a trip of the unit. Plant operators
Dockets Disc 05000498 Sou 05000499 Sou	ussed: uth Texas 1 uth Texas 2				Ter:	demonstrated good attention to detail during tagout activities. Reactor coolant system reduced inventory, midloop, and startup operations were performed in a deliberate and controlled manner by operators who were knowledgeable and trained in the evolution.
05/15/1999	1999011	Pri: OPS	NRC	POS	Pri: 1A	Reduced tagout errors demonstrated during outage.
		Sec:			Sec: 3A	The licensee made a demonstrable improvement in reducing tagout errors during the Unit 1 outage. Management
Dockets Disc 05000498 Sou 05000499 Sou	u ssed: ith Texas 1 ith Texas 2				Ter:	performed approximately 30,000 tagout-related activities without a significant error.
04/22/1999	1999018-02	Pri: OPS	NRC	NCV	Pri: 3C	THIMBLES INSERTED WITHOUT MEETING TS REQUIREMENTS FOR CORE ALTERATIONS
		Sec:			Sec: 3B	The inspectors identified one instance where the licensee inserted bottom mounted instrument thimbles into the
Dockets Disc 05000498 Sou 05000499 Sou	ussed: uth Texas 1 uth Texas 2				Ter:	communications with the control room established, or containment ventilations, without having containment integrity, communications with the control room established, or containment ventilation isolation operable. The licensee had used MERITS (a version of improved technical specifications) to procedurally define what constituted a core alteration in a way that conflicted with their own Technical Specifications. The safety significance of this issue was low since Improved Technical Specifications permit this condition. Failure to satisfy current Technical Specification requirements for core alterations was a violation. As a result of the inspectors findings the licensee wrote Condition Report 99-14640 to address the violation. This non-repetitive violation will not be cited in accordance with Section VII.B.1.a of the Enforcement Policy.
04/03/1999	1999006	Pri: OPS	NRC	POS	Pri: 1A	Operators performed shutdown well, including response to feedwater pump controller problems.
		Sec:			Sec: 1B	Operators performed well while shutting down Unit 1 for its scheduled refueling outage. Reactivity manipulations
Dockets Disc 05000498 Sou 05000499 Sou	ussed: ith Texas 1 ith Texas 2				Ter: 3A	were well controlled, with excellent support by reactor engineering personnel. Evolutions were well briefed and controlled. Operators responded well to steam generator water level transient caused by a feedwater pump controller problem.
04/03/1999	1999006	Pri: OPS	NRC	POS	Pri: 1A	Midicop and reduced inventory operations were performed well.
		Sec:			Sec: 3A	The front-end reactor coolant system reduced inventory and midloop operations were performed in a well controlled
Dockets Disc 05000498 Sou 05000499 Sou	Dockets Discussed: 05000498 South Texas 1 05000499 South Texas 2				Ter:	mariner. Excellent supervisory oversignt provided enective coordination of site activities and ensured the safe execution of this important evolution. Detailed procedures effectively implemented relevant corrective actions and commitments. Contingency actions were briefed in detail and assigned to specific personnel and equipment was prestaged. Significant precautions were taken to inform personnel of the restrictions of activities to protect critical equipment.
04/03/1999	1999006	Pri: OPS	NRC	POS	Pri: 3B	Licensed operator requalification evaluated scenarios were challenging.
		Sec:			Sec: 3A	Licensed operator requalification evaluated scenarios were observed to challenge operators. Each crew observed
Dockets Disc 05000498 Sou 05000499 Sou	u ssed: uth Texas 1 uth Texas 2				Ter:	uennneeeeee eppopnete avouen response, even viassiiidauon, and prompt reporting.

Item Type (Compliance, Followup, Other), From 01/25/1999 To 02/11/2000

Page: 7 of 22 03/29/2000 17:21:42 IR Report 3

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

۰.

By Primary Functional Area

Region IV

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
03/29/1999	1999011-01	Pri: OPS	Licensee	NCV	Pri: 3A	Control room HVAC system placed in wrong mode due to inadequate communication.
03/23/1000		Sec:			Sec: 1A	On March 29, 1999, the licensee discovered that inadequate verbal communication resulted in the performance of
Dockets Disc 05000498 So	u ssed: uth Texas 1				Ter:	an incorrect procedure section. Operators placed the control room heating, ventilation, and all conditioning system in filtered recirculation mode and not in recirculation and filtered make-up mode in violation of Technical Specification 3.3.2.10.c Action 27. This violation is being treated as a noncited violation and is captured in the licensee's corrective action program as Condition Report 99-4632 (LER 498/99003).
02/12/1000	1999006-01	Pri: OPS	NRC	NCV	Pri: 1B	Failure to recognize entry into TS 3.0.3 during loss of offsite power to two trains with inoperable DG.
03/12/1999	1999000 01	Sec:	1110		Sec: 3A	Operators did not understand the Technical Specification requirements for supplying offsite power to the engineered
Dockets Disc 05000499 So	: ussed : uth Texas 2				Ter: 3B	safety feature buses. As a result, they lated to enter rectinical specification 3.0.3 and take the required 1 hour actions to prepare to shut the plant down when offsite power was lost to Trains B and C while Standby Diesel Generator 22 was inoperable. When the Technical Specification 3.0.3 entry was recognized, operators incorrectly concluded that offsite power requirements were being met. However, compliance was not restored for another hour and a half, when offsite power was connected to Trains B and C. The inspectors noted that reconstruction of the event, particularly decision making, was significantly hampered because operators did not make log book entries or record adequate notes during the event. This was a violation of Technical Specification 3.0.3. This Severity Level IV violation is being treated as a noncited violation, consistent with Appendix C of the NRC Enforcement Policy. This noncited violation is in the licensee's corrective action program as Condition Report 99-3690.
02/10/1000	1000006-02	Pri: OPS	Self	NCV	Pri: 2A	Failure to perform required checks after racking out breaker caused inoperable DG for two weeks.
03/12/1999	1999000-02	Sec:	0011		Sec: 3A	When a switchyard breaker failed, Unit 2 experienced a loss of offsite power to Trains B and C equipment. The
Dockets Dis 05000499 Sc	Dockets Discussed: 05000499 South Texas 2				Ter:	output breaker for Standby Diesel Generator 22 failed to close automatically because an essential chiller breaker cell switch failed to provide a necessary permissive input. Operators had failed to recognize that the diesel had been inoperable for 2 weeks because they did not perform the procedurally required checks. This was a violation of Technical Specification 6.8.1. This Severity Level IV violation is being treated as a noncited violation, consistent with Appendix C of the NRC Enforcement Policy. This noncited violation is in the licensee's corrective action program as Condition Report 99-3690.
	1000006 03		NRC	NCV	Pri: 1B	Loss of bus procedure inadequate for the circumstances.
03/12/1999	1999000-03	FIL OF S			Sec: 3C	During the loss of offsite power to Unit 2 Trains B and C, operators quickly recognized that the diesel breaker failed
Dockets Dis 05000499 S	cussed: outh Texas 2	366.			Ter:	to shut automatically and manually shut it to restore power to Train B equipment. While this action was appropriate, it was in conflict with the loss of bus procedure. This loss of bus procedure was generic to all buses and, as a result, was very long, cumbersome to use, and did not place a priority on restoring offsite power to the engineered safety feature buses. This was a violation of 10 CFR Part 50, Appendix B, Criterion V, for failure to provide procedures appropriate to the circumstances. This Severity Level IV violation is being treated as a noncited violation, consistent with Appendix C of the NRC Enforcement Policy. This noncited violation is in the licensee's corrective action program as Condition Report 99-3713.
	1000002	Pri: OPS	Self	NEG	Pri: 3A	Unit 2 reactor trip due to operator error during ground isolation
02/20/1999	1999002	FIL UFS	001		Sec: 3B	On January 21, 1999, an automatic Unit 2 reactor trip occurred while operators were conducting electrical ground
Dockets Dis 05000498 S 05000499 S	cussed: outh Texas 1 outh Texas 2	386.			Ter: 1B	isolation. The operator was in the wrong electrical panel when he inadvertently deenergized turbine trip circuitry. Although tack of self-checking was the root cause of this event, not having a formal process or procedure for ground isolation, and operator knowledge deficiencies in electrical theory were contributing factors to this event.

By Primary Functional Area

Region IV

Date	Source	Functional Area	ID	Туре	Template Codes	item Title Item Description
02/20/1999	1999002	Pri: OPS	NRC	POS	Pri: 1A	Marked improvement in control room log entries.
		Sec:			Sec:	The inspectors noted a marked improvement in consistency and level of detail provided in control room log entries.
Dockets Discu	ussed:				Ter:	Limiting condition for operation action entries were clearly recorded, regardless of the expected length of time the action was expected to be in effect.
05000498 Sou 05000499 Sou	th Texas 1 th Texas 2					
02/20/1999	1999002	Pri: OPS	NRC	POS	Pri: 1B	Simulator training sessions were well performed.
		Sec:			Sec:	The inspectors observed that licensed operator simulator training sessions were well performed and with good
Dockets Discussed: 05000498 South Texas 1 05000499 South Texas 2					Ter:	control of each session by the training staff. Operators made good use of briefs and status updates. Postscenario discussions were self-critical and operations management personnel frequently participated. The material condition of the simulator was good. However, the inspectors observed that operators frequently did not maintain logs or other routine documentation in the simulator that were required in the plant.
02/20/1999	1999002-02	Pri: OPS	Licensee	NCV	Pri: 1A	Failure to meet TS requirements for inoperable standby diesel generator
		Sec:			Sec: 2A	On January 15, 1998, review of failure analysis on standby diesel generator 21 voltage regulator and instantaneous
Dockets Discussed: 05000499 South Texas 2					Ter: 5A	preposition board determined the diesel generator had been inoperative from December 26, 1997 until December 30, 1997. TS 3.8.1.1 actions to verify offsite power were not taken because the condition was not recognized until the failure analysis was completed. This nonrepetitive, licensee identified and corrected violation is being treated as a noncited violation, consistent with Section VII.B.1 of the NRC Enforcement Policy. LER 50-499/98001-00.
02/11/1999	1999002	Pri: OPS	NRC	NEG	Pri: 1A	Power increase caused by steam plant work without a procedure
		Sec:			Sec: 1C	Operators caused a power increase while attempting to adjust the level controller for Moisture Separator Reheater
Dockets Discu 05000498 Sou 05000499 Sou	ussed: th Texas 1 th Texas 2				Ter:	the potential for a positive reactivity increase, this evolution was conducted with an inadequate prejob brief and, without a procedure, supervision or peer checking. Self-checking opportunities were missed by not placing a water level sight-glass in service to monitor tank level during the evolution.
12/25/1999	1999020	Pri: MAINT	NRC	POS	Pri: 3A	Maintenance was well performed.
		Sec:			Sec: 2A	The maintenance and surveillance activities observed were well controlled and carefully performed. High quality
Dockets Disc	ussed:				Ter:	prejob briefings were consistently observed. Operators and technicians were very knowledgeable of their assigned tasks. The inspectors observed that the preparation and maintenance activities for repairing a hydraulic leak on a
05000498 Sou 05000499 Sou	ith Texas 1 ith Texas 2					main turbine throttle valve on line were carefully coordinated. The necessary plant conditions were established and practiced on the simulator, and the repair work was practiced on a mock-up. Troubleshooting efforts for load instabilities on Standby Diesel Generator 23 were thorough and prompt, and the potential for a common mode failure was promptly determined not to exist.
11/06/1999	1999018	Pri: MAINT	NRC	POS	Pri: 2B	ERROR-FREE FUEL HANDLING REVERSED PREVIOUSLY IDENTIFIED DECLINING TREND
		Sec:			Sec: 3A	The inspectors observed fuel handling activities during the Unit 2 outage were performed in a careful manner.
Dockets Disc 05000498 Sou 05000499 Sou	u ssed: ith Texas 1 ith Texas 2				Ter:	Improved emphasis on altention to detail during rule positioning was effective in reversing a previously observed declining trend in performance in this area.

.

By Primary Functional Area

Region IV

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
10/10/1999	1999018	Pri: MAINT	Self	NEG	Pri: 2A	A LOSS OF MSR REHEAT STEAM DUE TO A CONTROLLER FAILURE WAS COMPLICATED BY MULTIPLE BO
Dockets Discu 05000498 Sout 05000499 Sout	ssed : h Texas 1 h Texas 2	Sec:				A controller power supply for both moisture separator reheaters failed. This caused the loss of reheat steam because the redundant power supply, although set per vendor instructions, was set too low to function properly. Operators performed a rapid power reduction to protect the main turbine blades from moisture damage. The operators' response was complicated by five steam plant motor operated valves which were mechanically bound or had limit switch problems that required manual action. Material condition deficiencies of balance of plant equipment both initiated and complicated this event.
09/25/1999	1999018	Pri: MAINT	Self	NEG	Pri: 2A	UNCONTROLLED POWER INCREASED DUE TO DEGRADING STEAM LEAK IN BOP EQUIPMENT
Dockets Discu 05000498 Soul 05000499 Soul	i ssed: h Texas 1 h Texas 2	Sec:			Sec: 3A Ter:	The licensee identified a steam leak in a balance of plant instrument line that caused the instruments to sense less than actual steam line pressure. While planning a repair, the leak degraded to the point where the affected instruments opened turbine drains. Despite prompt operator action to limit the magnitude of the transient, this material deficiency in non-safety equipment caused an uncontrolled reactor power increase from 99 percent to 100.15 percent.
09/25/1999	1999018	Pri: MAINT	Self	NEG	Pri: 2A	UNCONTROLLED POWER INCREASE ABOVE 100 PERCENT DUE TO POOR CONTROLS WHILE RETURNING
Dockets Discussed: 05000498 South Texas 1 05000499 South Texas 2		Sec:			Sec: 3A Ter:	Following a transient caused by a leaking steam pressure instrument line in Unit 1, a temporary modification was installed to bypass the leaking line. Maintenance personnel valved in the pressure instruments, causing power to increase from 100 percent to 101.97 percent before operator action turned power. The inspectors concluded that the licensee's temporary modification package and the associated work package did not provide precautions to properly restore the instrument line to service. Operator response was quick and effective. Stringent controls and precautions for work with the potential to affect reactor power were not implemented.
09/18/1999	1999016	Pri: MAINT	NRC	POS	Pri: 3A	MAINTENANCE WAS WELL PERFORMED
Dockets Discu 05000498 Sou 05000499 Sou	issed: In Texas 1 In Texas 2	S PRI: MAINT NRC POS Sec:			Sec: 2B Ter:	The maintenance and surveillance activities observed were carefully performed and well controlled. High quality prejob briefings were consistently observed. Operators and technicians were very knowledgeable of their assigned tasks. A reactor coolant loop flow transmitter was recalibrated after careful deliberations to effectively balance the reactor trip potential with the required instrument accuracy to support reactor safety. New fuel receipts were well supported and supervised. A control rod dimensional tolerance problem was resolved by working closely with the fuel vendor.
07/21/1999	1999014-01	Pri: MAINT	Self	NCV	Pri: 2B	Fuel handling error results in two bundles colliding without damaging fuel.
		Sec:			Sec: 3A	Operators moving fuel within the spent fuel pool became distracted while conducting informal training and failed to
Dockets Discu 05000499 Sou	issed: th Texas 2				Ter:	lowered it onto another bundle. This event was caused by inattention and improper verifications. Fuel handling movements were not stopped as required by procedure after the incident. This event was the fourth fuel handling event onsite recently, indicating a weakness in attention to detail while moving fuel. Continuing examples of fuel handling events indicated that the corrective actions program was not adequately dealing with the declining trend. Failure to follow Procedure 0PEP02-ZM-0005 was a violation of Technical Specification 6.8.1. This Severity Level IV violation is being treated as a noncited violation, consistent with Appendix C of the NRC Enforcement Policy. This violation is in the licensee's corrective action program as Condition Report 99-10645.

•

-

By Primary Functional Area

Region IV

SOUTH	TEXAS	PRO	JECT
-------	-------	-----	------

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
07/13/1999	1999014	Pri: MAINT	Self	NEG	Pri: 2B	Worker damages service water pump, necessitating rapid power reduction.
Dockets Discu 05000498 Sou 05000499 Sou	a ssed : th Texas 1 th Texas 2	Sec:			Sec: 3A Ter:	A worker chipping rust at the plant intake structure caused a fault in a service water pump when the tool penetrated the conduit. Since the standby pump was removed for planned maintenance, this necessitated a rapid power reduction to reduce heat load on the system in order to avoid tripping the turbine. The licensee was evaluating work controls necessary to avoid working in the vicinity of important equipment when redundant trains are removed from service, as well as evaluating the material condition of equipment located at the intake structure.
06/26/1999	1999013	Pri: MAINT	NRC	POS	Pri: 1C	Work performed during maintenance and surveillance activities was well conducted.
Dockets Discu 05000498 Sou 05000499 Sou	ussed : th Texas 1 th Texas 2	Sec:			Sec: 3A Ter:	Work performed during maintenance and surveillance activities was well conducted and thorough. The licensee demonstrated safe and conservative action during maintenance activities. Technicians were experienced and knowledgeable of their assigned tasks, equipment performance, and the significance of the systems being worked.
05/15/1999	1999011	Pri: MAINT	NRC	NEG	Pri: 3A	Minor problems in fuel handling due to lack of attention to detail.
Dockets Discu 05000498 Sou 05000499 Sou	u ssed: th Texas 1 th Texas 2	Sec:			Sec: Ter:	Fuel handling was adequately performed. However, lack of attention to detail contributed to minor problems. These included: improperly inserting a fuel bundle in the core such that it caused another bundle to lean; inadvertently removing a poison panel from the spent fuel pool storage rack while removing a fuel bundle; and forgetting to remove a positioning handcrank before moving the refueling bridge electrically, throwing the handcrank free. Additionally, the licensee was unable to identify the source of a minor fuel leak during fuel inspection activities. Analysis of the laotopes present in water samples demonstrated that the leak was very small and the licensee believed that it was located in a bundle that was to be discharged from the core. However, indications of a continued fuel leak were identified in the reconfigured core after the return to power.
05/15/1999	1999011	Pri: MAINT	NRC	POS	Pri: 3A	Maintenance and surveillance activities were well performed, exceptional brief for on-line maintenance.
Dockets Discu 05000498 Sou 05000499 Sou	u ssed : th Texas 1 th Texas 2	Sec:			Sec: 3B Ter:	Maintenance and surveillance activities were well performed. Technicians were experienced and knowledgeable of their assigned tasks, equipment performance, and the significance of the systems being worked. An exceptionally detailed prejob brief was conducted which stressed plant safety and conservatism during on-line maintenance for the Unit 1 feedwater regulating valve controllers. Supervisors and system engineers were frequently monitoring job and equipment performance.
05/10/1999	1999014-02	Pri: MAINT	Licensee	NCV	Pri: 2A	NCV issued for exceeding allowed outage time for turbine driven auxiliary feedwater pump
Dockets Disc 05000498 Sou	u ssed: th Texas 1	Sec:			Sec: 3A Ter:	Maintenance performed on a flow control motor operated valve for the steam driven auxiliary feedwater pump resulted in the valve being inadvertently left in an inoperable state. Testing performed following the original valve work was clearly inadequate to identify this maintenance-induced failure. The inspectors concluded that the valve was degraded but would have functioned to refill the steam generator. Plant risk was not affected, based on licensee and NRC calculations. The staff concluded that this event was a violation of Technical Specification 3.7.1.2 of lesser significance in accordance with Supplement 1 to the Enforcement Policy. This Severity Level IV violation is being treated as a noncited violation consistent with Appendix C of the NRC Enforcement Policy. This violation is in the licensee's corrective action program as Condition Reports 99-7742 and 99-7743. This closed LER 498/99005-00.

Page: 11 of 22 03/29/2000 17:21:42 IR Report 3

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

e.

By Primary Functional Area

Region IV

Date	Source	Functional Area	ID	Туре	Tempiate Codes	item Title Item Description
04/09/1999	1999010	Pri: MAINT	NRC	NEG	Pri: 2B	The inspector noted specific deficiencies in weld practices related to interpass temperatures.
		Sec:			Sec: 3A	The inspector noted specific deficiencies: (1) welding procedure specification and work instructions did not provide
Dockets Disc	cussed:				Ter:	clear guidance when to verify interpass and preheat temperature, (2) an inconsistency was noted among craft and inspection personnel as to when interpass temperature should be monitored or verified, and (3) a poor work practice
05000498 Sc	outh Texas 1					was identified when a welder did not have all necessary equipment and tools (i.e., temperature stick or pyrometer) in
05000499 Sc	outh Texas 2					the immediate area to perform a task. Condition Report 99-5468 was initiated to address these observations
04/09/1999	1999010	Pri: MAINT	NRC	POS	Pri: 2A	External material condition of the Unit 2 component cooling water system was good.
		Sec:			Sec: 2B	The external material condition of the Unit 2 component cooling water (Train B) system piping, valves, and the ring
Dockets Dis	cussed:				Ter:	duct was good, in that no visible oil or excessive water reaks were noted. Overall appearance of the safety-related trains and components was excellent, in that they were color-coded and labeled for proper identification
05000498 Sc	outh Texas 1					
05000499 Sc	outh Texas 2					
04/09/1999	1999010	Pri: MAINT	NRC	STR	Pri: 2B	Licensee had a well defined first 10-year inservice examination program plan.
		Sec:			Sec:	The licensee had developed a well-defined first 10-year inservice examination program plan for Units 1 and 2, in that
Dockets Dis	cussed:				Ter:	code cases implemented, and changes to the examination plan were clearly delineated. The licensee was
05000498 Sc	outh Texas 1					implementing the program plan requirements in accordance with the requirements of 10 CFR 50.55a.
05000499 So	outh Texas 2					
04/03/1999	1999006	Pri: MAINT	NRC	NEG	Pri: 1A Fuel bundle placed on top of filters.	Fuel bundle placed on top of filters.
		Sec:			Sec: 3A	New fuel receipt inspections in Unit 1 were well conducted, utilizing proper supervision and procedural controls.
Dockets Dis	cussed:				Ter:	However, fuel movements within the spent fuel pool in Unit 2 were not controlled as well. A fuel bundle was placed in a storage location that contained used fuel pool filters. The fuel bundle was undergoaded but the filters were
05000498 So	outh Texas 1					compressed, making them difficult to remove. The licensee had not documented the storage locations of the filters
05000499 So	outh Texas 2					and had not coordinated storage of the filters with fuel storage. No violations of NRC requirements were identified.
04/01/1999	1999006	Pri: MAINT	NRC	NEG	Pri: 3A	Local leak rate testing caused false indication in only available reactor vessel level indication.
		Sec:			Sec:	Following reactor vessel floodup from front-end midloop, local leak rate testing caused the only available level
Dockets Dis	cussed:	000.			Ter	indicator (a sightglass) to indicate lowering level. A test boundary valve with known seat leakage allowed test
05000498 Sc	outh Texas 1					rescheduled to be performed during the period when the sightglass was required for plant control
05000499 So	outh Texas 2					
	4000004 04	Deli MANT			Pri: 28	Inadequate reliability performance measures for 8 risk-significant systems.
02/25/1999	1999004-01	Pri: MAINT	NRC	NUV	C	Inspectors identified inspectors and a sector and a sector sector sector sectors identified inspectors the sectors identified inspectors the sectors is a sector se
		Sec:			20C:	result of the inadequate performance measures, the 480Vac load center system for both units was allowed to
Dockets Dis	cussed:				Ter:	degrade beyond the probabilistic risk assessment assumed performance without the licensee having provided
05000498 S	outh Texas 1					adequate technical justification for not having established goals, or appropriate corrective actions. This was a
05000499 S	outh Texas 2					Appendix C of the NRC enforcement policy (EA 99-058). This violation is in the licensee's corrective action program as documented by Condition Record 99-2925.

·]

By Primary Functional Area

Region IV

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
02/20/1999	1999002	Pri: MAINT	NRC	POS	Pri: 2B	Online outages to conduct 18 month and 5 year EDG inspections were well coordinated
Dockets Disco 05000498 Sou 05000499 Sou	u ssed : ith Texas 1 ith Texas 2	Sec:			Sec: Ter:	Maintenance and surveillance activities were thorough and well performed. Extended online outages to conduct 18-month and 5-year inspections for two emergency diesel generators were well coordinated and promptly completed. The licensee identified and corrected several emergent equipment problems without significantly impacting the outage durations.
12/25/1999	1999020	Pri: ENG	NRC	POS	Pri: 4B	Good engineering evaluations supported the movement of new steam generators.
Dockets Discu 05000498 Sou 05000499 Sou	u ssed : ith Texas 1 ith Texas 2	Sec:			Sec: Ter:	The licencee's engineering evaluations for the movement and storage of replacement steam generators were thorough and appropriately detailed. Replacement steam generator transport was performed in accordance with the licensee's plan without incident or damage.
11/06/1999	1999018	Pri: ENG	NRC	NEG	Pri: 4B	SOME 50.59 EVALUATION ASSUMPTIONS FOR PERFORMING FREEZE SEALS AND REPAIRS TO THIMBLE :
		Sec:			Sec: 5B	The inspectors reviewed the 50.59 evaluation and work documents for performing freeze seals and repairs to hottom mounted instrument thimble seals. The inspectors identified some of the
Dockets Discu 05000498 Sou 05000499 Sou	u ssed: ith Texas 1 ith Texas 2				Ter:	evaluate the job were not translated into prerequisites in the work documents that would have ensured that the 50.59 evaluation remained valid.
09/18/1999	1999016	Pri: ENG	NRC	POS	Pri: 5B	EXCELLENT SUPPORT OF OPERATIONAL PROBLEM BY SYSTEM ENGINEERING
		Sec:			Sec: 5C	System engineering personnel provided excellent response following the failure of a reactor coolant system hot-leg
Dockets Discu 05000498 Sou 05000499 Sou	ussed: th Texas 1 th Texas 2				Ter:	inoperable, removed the bad input, and performed a thorough evaluation of the impact of the problem on the design basis operation of the system.
08/07/1999	1999014	Pri: ENG	NRC	POS	Pri: 48	Good engineering evaluation for impact of containment isolation valve leakage
		Sec:			Sec: 2A	Reactor containment building cooling water systems in both units had leaking containment isolation valves that
Dockets Discu 05000498 Sou 05000499 Sou	u ssed: th Texas 1 th Texas 2				Ter:	good evaluation of the radiological monitoring and impact of the measured leakage, which remained within regulatory limits.
06/26/1999	1999013	Pri: ENG	NRC	NEG	Pri: 4B	No reactor engineers available during power ascension contributed to steam generator overpressurization
		Sec:			Sec: 3A	The inspectors noted that there were no reactor engineers available after attaining criticality to provide support to
Dockets Discu 05000498 Sou 05000499 Sou	u ssed: th Texas 1 th Texas 2				Ter:	reactor engineer departed. Reactor engineering personnel contributed to the steam generator overpressure event by providing incorrect guidance with regard to reactivity manipulations for controlling reactor power distribution.

By Primary Functional Area

Region IV SOUTH TEXAS PROJECT

Date	Source	Functional Area	łD	Туре	Template Codes	item Title Item Description
05/15/1999	1999011	Pri: ENG	NRC	POS	Pri: 4B	Steam Generator manway leak repairs were effective.
		Sec:			Sec:	Leak repairs to the Steam Generator 1D secondary side manway covers were effectively implemented using
Dockets Discu	Dockets Discussed:				Ter:	of the impact of the modification. The leak sealing program effectively incorporated industry guidelines and lessons
05000498 Sout	h Texas 1 h Texas 2					learned and included adequate controls to minimize injection of sealant material into the process stream.
05000499 500						
05/15/1999	1999011	Pri: ENG	NRC	WK	Pri: 48	Plant modification problems identified during outage.
Dockets Discu 05000498 Sout 05000499 Sout	i ssed : h Texas 1 h Texas 2	Sec:			Sec: Ter:	During the Unit 1 retueing outage, proceeds with three plant modifications were identified. The Standby Diesel Generator 11 digital governor control circuit modification included a design error such that a relay simultaneously received conflicting demands, causing rapid relay failure. A modification to the main feedwater regulating valve control circuit did not ensure sufficient tuning of system response, which caused feedwater flow oscillations. Operator response was hampered by excessively slow feedwater regulating valve operation in manual mode because the valve response characteristics had been modified. A modification to replace the reactor trip switches resulted in the switches not functioning as required, preventing the closing of the reactor trip breakers. The license failed to adequately verify the configuration of the new switches before installation, which was a minor violation due to the low safety significance. These examples demonstrated a weakness in the control of plant modifications.
04/06/1999	9904140134	Pri: ENG	NRC	LIC	Pri: 4C	STPNOC pursued an aggressive and multi-faceted approach to resolve the incomplete rod insertion issue.
Dockets Discu 05000498 Soul 05000499 Soul	ussed: Ih Texas 1 Ih Texas 2	Sec:			Sec: Ter:	The staff reviewed the licensee's June 25, 1998, Unit 1 Cycle 8 and Unit 2 Cycle 6 incomplete control rod insertion (IRI) evaluation criteria and also reviewed the material that STPNOC presented in a January 26, 1999, meeting to discuss the resolution of the IRI problem at STP. Prior to making fuel design changes, STPNOC addressed the IRI problem by limiting burnup in rodded fuel assemblies and with an aggressive rod drop testing plan. The staff found that the evaluation criteria (for rod drop testing) in the June 25, 1998, letter was acceptable. To further address the IRI problem, STPNOC conducted or sponsored post-irradiation examinations, mechanical analysis of span/assembly bow, fuel analysis of the previous and improved fuel designs, and an independent review of the IRI analyses. STPNOC also made several fuel design changes. Overall, STPNOC has pursued an aggressive and multi-faceted approach to resolve the IRI problem.
04/03/1999	1999006	Pri: ENG	NRC	POS	Pri: 4B	Calculations were of good quality.
		Sec:			Sec:	Several engineering calculations performed in support of the Unit 1 outage were reviewed and assessed to be of
Dockets Discu 05000498 Sou 05000499 Sou	u ssed: th Texas 1 th Texas 2				Ter:	good quality. However, decay neat calculations performed in support or earlier entry into a midloop condition were completed late in the outage preparation process, and the outage schedule was built assuming the calculations would demonstrate adequate heat removal capability.
04/03/1999	1999006	Pri: ENG	NRC	POS	Pri: 4B	Rod control system modification was successfully implemented.
		Sec:			Sec:	The licensee successfully implemented a modification to the rod control system to minimize unnecessary automatic
Dockets Disc 05000498 Sou 05000499 Sou	u ssed: ith Texas 1 ith Texas 2				Ter:	comprehensive and adequately addressed applicable accidents analyses. The postmodification testing was appropriate for the modification.

By Primary Functional Area

Region IV

Date	Source	Functional Area	ID	Туре	Tempiate Codes	Item Title Item Description
03/27/1999	1999011-02	Pri: ENG	Licensee	NCV	Pri: 4C	Source range monitors not checked for long term degradation required by Technical Specification.
		Sec:			Sec:	On March 27, 1999, the licensee discovered that the source range monitors were not properly surveillance tested in
Dockets Disc	ussed:				Ter:	enther unit. Specification, long term degradation had not been properly checked as required by Technical Specification 4.3.1.1.6. This violation is being treated as a noncited violation and is captured in the licensee's
05000498 So	uth Texas 1					corrective action program as Condition Report 99-4429 (LER 498;499/99002)
03000499 30						
03/17/1999	1998019	Pri: ENG	NRC	NEG	Pri: 4B	The engineers had not performed a thorough comparison review of the UFSAR to the TS bases.
		Sec:			Sec: 3A	The engineers had not performed a thorough comparison review of the Updated Final Safety Analysis Report with the technical specification bases. This was demonstrated by the failure to include the use of the residual boot
Dockets Disc	ussed:				Ter:	removal system pumps for core heat removal in the safety analysis report. This oversight was a concern because it
05000498 So 05000499 So	uth Texas 2					could mislead personnel in the review of changes associated with 10 CFR 50.59, "Changes, Tests and Experiments."
03/17/1999	1998019	Pri: ENG	NRC	NEG	Pri: 4B	Changes to RHR and CCW were not evaluated for impact on design basis.
		Sec:			Sec: 3A	The evaluation of the effect of plant configuration changes with respect to satisfying the design basis was lacking in
Dockets Disc	ussed:				Ter:	instances where modifications were performed on the residual heat removal system and component cooling water pumps without consideration of the effects on system performance of the improved performance of the modified
05000498 So	uth Texas 1					pumps.
05000499 So	uth Texas 2					
03/17/1999	1998019	Pri: ENG	NRC	NEG	Pri: 4B	Design engineering failed to properly consider uncertainties in the performance of RHR flow calculations.
		Sec:			Sec: 4A	Design engineering failed to properly consider random and non-random uncertainties in the performance of residual
Dockets Disc	ussed:				Ter: 3A	rupture accident scenario (which was reviewed); however, improper consideration of both types of uncertainties
05000498 So	uth Texas 1					could have a more significant effect on other instrument loops that were not reviewed.
					Del: 40	
03/17/1999	1998019	Pri: ENG	NRC	NEG	Pri: 4()	Galculations were adequate but lacked rigor and contained minor errors.
Deskata Dise		Sec:			Sec: 3A	in general, the reviewed calculations (approximately so electrical, instrumentation, and mechanical) were adequate; however, a number of minor errors and a lack of rigor to ensure quality were identified.
05000498 So	uth Texas 1				ler:	
05000499 So	uth Texas 2					
03/17/1999	1998019	Pri: ENG	NRC	POS	Pri: 4B	System engineer demonstrated good knowledge when he identified possible loss of all RHR trains.
		Sec:			Sec: 3A	The identification of a problem involving the possible loss of all three residual heat removal system trains
Dockets Disc	cussed:				Ter: 4A	demonstrated a good integrated system operational knowledge by the system engineer.
05000498 So	uth Texas 1					
05000499 Sc	uth Texas 2					

Υ.

,

By Primary Functional Area

Region IV

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
03/17/1999	1998019	Pri: ENG	NRC	POS	Pri: 4C	The program to address the Y2K concerns appeared to be adequate.
		Sec:			Sec: 3A	On the basis of a brief review, the program to address the concerns associated with the effects on computer
Dockets Disc	ussed:				Ter:	programs which could occur upon the change of date at the end of the 1999 appeared to be adequate.
05000498 So	uth Texas 1					
05000499 So	uth Texas 2					
03/17/1999	1998019-02	Pri: ENG	Licensee	NCV	Pri: 3A	Required service tests of class 1E batteries were not performed in 1995 and 1997.
		Sec:			Sec: 4B	The failure to perform the required service tests for the Unit 2 Class 1E batteries, Trains B and D, in 1995 and 1997, was identified as a violation of Technical Specification 4.8.2.1d. The corrective actions taken, and proposed in the
Dockets Dis 05000499 Sc	c ussed: uth Texas 2				Ter: 3B	event report adequately address the cause of this technical specification violation. This Severity Level IV violation is being treated as a Non-Cited Violation, consistent with Appendix C of the NRC Enforcement Policy.
03/17/1999	9903180037	Pri: ENG	NRC	LIC	Pri: 4C	Technical content of amendment application was exceptionally thorough.
00/11/1000		Sec:			Sec:	Amendment nos. 104 and 91 to STP licenses revised the spent fuel pool criticality analysis and rack utilization
Dockets Dis	cussed:				Ter:	schemes by allowing credit for spent fuel pool soluble boron. The NRC staff found that the technical content of the application was exceptionally thorough, especially when considering its volume and complexity. However, the staff
05000498 Sc	outh Texas 1					found administrative errors in the Technical Specifications proposed with the initial application.
05000499 So	outh Texas 2					
03/11/1999	1999005	Pri: ENG	NRC	POS	Pri: 4B	Safety and engineering evaluations for replacement of the Unit 1 steam generators were of high quality.
		Sec:			Sec:	Safety evaluations and an engineering evaluation report supporting replacement of the Unit 1 steam generators
Dockets Dis	cussed:				Ter:	requirements, and were of high quality.
05000498 So	outh Texas 1					
02/20/1999	1999002	Pri: ENG	NRC	POS	Pri: 48	Reactor engineering provided excellent support during control rod position changes.
02,20,000		Sec:			Sec:	Reactor engineering personnel provided excellent support to operators during a periodic change to the full-out
Dockets Dis	cussed:				Ter:	position of control and shutdown roas. The associated configuration changes to the rod control and plant computer systems were independently verified and appropriately documented. A reactor engineer provided a detailed briefing
05000498 S	outh Texas 1					of the procedure and the expected plant response. Control room operators were very knowledgeable and
05000499 S	outh Texas 2					
01/27/2000	2000001	Pri: PLTSUP	NRC	POS	Pri: 3A	An effective radiological effluent control program was maintained.
		Sec:			Sec: 3C	Overall, an effective radiological effluent control program was in place. The 1997 and 1998 Annual Radioactive
Dockets Dis	cussed:				Ter:	trend in the radioactivity released through liquid effluents. Whole-body dose to the public from radiological effluent
05000498 S	outh Texas 1					releases for 1997 and 1998 were less than 1 percent of the yearly regulatory limit. Sampling and analysis
05000499 S	outh Lexas 2					high and hig

By Primary Functional Area

,

Region IV

SOUTH TEXAS PROJECT

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
01/27/2000	2000001-01	Pri: PLTSUP	NRC	NCV	Pri: 3A	Failure to survey and control radioactive material released from the radiologically controlled area.
Dockets Disc 05000499 So	c ussed : uth Texas 2	Sec:			Sec: 3C Ter:	A violation of Technical Specification 6.8.1.a was identified for failure to survey and control radioactive material released from the radiologically controlled area. This Severity Level IV violation is being treated as a noncited violation, consistent with Section VII.B.1.a of the NRC Enforcement Policy. Condition Report 99-16737 was written to document this issue.
01/27/2000	2000001-02	Pri: PLTSUP	NRC	NCV	Pri: 5A	Failure to perform an audit of the Offsite Dose Calculation Manual.
		Sec:			Sec: 5C	A violation of Technical Specification 6.8.1.g was identified for failure to perform an Offsite Dose Calculation Manual
Dockets Disc 05000498 So 05000499 So	c ussed : uth Texas 1 uth Texas 2				Ter:	audit within 24 months of document and obtain the approval of the Director of Quality to schedule an audit at a later date. This Severity Level IV violation is being treated as a noncited violation, consistent with Section VII.B.1.a of the NRC Enforcement Policy. The licensee wrote Condition Report 00-1346 to document this issue.
12/25/1999	1999020	Pri: PLTSUP	NRC	NEG	Pri: 3A	Fire watches were not meeting the intent of hourly inspection timing.
		Sec:			Sec:	The inspectors observed that the licensee was implementing the compensatory hourly fire watch program within
Dockets Dise 05000498 So 05000499 So	c ussed: wth Texas 1 wth Texas 2				Ter:	regulatory requirements. However, the inspectors found that he watch personnel were, in some instances, performing fire watch inspections at the end of one hour and the beginning of the following hour. In one case, the area inspection was performed twice within 10 minutes, with 1 hour 47 minutes elapsing since the earlier inspection. Licensee management stated that this practice did not meet their expectations and promptly conducted training to clarify expectations and eliminate this practice.
12/25/1999	1999020	Pri: PLTSUP	NRC	NEG	Pri: 3A	A poor initial dose assessment was performed by the licensee.
		Sec:			Sec: 5B	The inspectors determined that the licensee's initial assessment of the dose received while refilling a shield tank
Dockets Dise 05000498 So 05000499 So	Dockets Discussed: 05000498 South Texas 1 05000499 South Texas 2				Ter:	around a neuron source utilized electronic dustinetry which did not register neutron dose. A technician had refilled a shield tank around a 3.88 Curie neutron source in response to a low level alarm. Although some loss of shielding resulted from the low level, the licensee subsequently performed a conservative estimate and determined that the dose received was small.
11/06/1999	1999018	Pri: PLTSUP	NRC	POS	Pri: 4C	CORE BARREL REMOVAL IN UNIT 2 DEMONSTRATED EXCELLENT PLANNING AND DOSE CONTROLS
		Sec:			Sec: 3A	The highly radioactive Unit 2 core barrel was successfully removed for inservice inspection using excellent planning
Dockets Disc 05000498 So 05000499 So	c ussed: ruth Texas 1 ruth Texas 2				Ter:	and dose controls. The job was completed with minimal dose and without incident. Health Physics performance during the Unit 2 refueling outage was consistent with the good performance of the prior Unit 1 outage.
11/06/1999	1999018	Pri: PLTSUP	Licensee	POS	Pri: 5B	GOOD COORDNATION BETWEEN CHEMISTRY AND OPERATIONS WHEN RCS BORON SAMPLE RESULTS (
		Sec:			Sec:	The cooldown of Unit 2 was appropriately delayed when chemistry sample results for reactor coolant system boron
Dockets Dise 05000498 Sc 05000499 Sc	c ussed: outh Texas 1 outh Texas 2				Ter:	concentration up not agree with cremical additions. Operations and chemistry personnel coordinated well. Chemistry personnel thoroughly evaluated sources of dilution and analytical error before concluding that the problem was a related to analytical limitations in the lab equipment. The cooldown was performed only when proper shutdown margin was confirmed.

.

2

.

By Primary Functional Area

Region IV

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
09/18/1999	1999016	Pri: PLTSUP	NRC	POS	Pri: 5B	EMERGENCY RESPONSE DRILL WAS CHALLENGING AND EFFECTIVE
		Sec:			Sec:	The emergency drill effectively exercised the response capabilities of the licensee. The emergency response
Dockets Discu	issed:				Ter:	team's promization or actions was enecute in comparing the simulated problems. The technical support center team demonstrated initiative by brainstorming ways to mitigate a simulated release when traditional methods were
05000498 Sout	h Texas 1					ineffective.
05000499 Sout	h Texas 2				······································	
08/19/1999	1999012	Pri: PLTSUP	NRC	POS	Pri: 1C	Effective assessment aids.
		Sec:			Sec:	Assessment aids provided effective assessment of the perimeter detection zones. The video capture system
Dockets Discu	issed:				Ter:	
05000498 Soul	th Texas 1					
05000499 Sou						
08/19/1999	1999012	Pri: PLTSUP	NRC	POS	Pri: 1C	Security, access authorization, and fitness for duty audits were effective.
		Sec:			Sec:	The audits of the security program, the access authorization program, and the fitness-for-duty program were effective thorough, and intrusive.
Dockets Discu	issed:				Ter:	
05000498 Sout	th Texas 1					
05000499 300						
08/19/1999	1999012-01	Pri: PLTSUP	Licensee	NCV	Pri: 1C	IMPROPER GRANTING OF UNESCORTED ACCESS, MULTIPLE OCCURRENCES
		Sec:			Sec: 3B	A violation was identified for failure to review and consider all background investigation information prior to granting unescorted plant access, as required by Paragraph 4.1.2 of the physical security plan and Paragraph 4.1 of
Dockets Discu	issed:				Ter:	Licensee Procedure OHRP01-ZA-0001, Revision 3. On three occasions, the licensee improperly granted
05000498 Sou	th Texas 1					been conducted. On two additional occasions, the licensee's reevaluation resulted in continuation of individuals'
03000433 300	In TCAUS 2					unescorted access. This Severity Level IV violation is being treated as a noncited violation, consistent with
						Condition Reports 99-8275, 99-6371, and 99-7237. This closes LER 99-S01-00.
08/19/1999	1999012-02	Pri: PLTSUP	Licensee	NCV	Pri: 1C	FAILURE TO MAINTAIN POSITIVE CONTROL OF A VITAL AREA KEY
		Sec:			Sec: 3B	A violation was identified for failure to maintain positive control of a vital area key, as required by Station Procedure
Dockets Discu	ussed:				Ter:	OPGP03-ZS-0005. This Severity Level IV violation is being treated as a noncited violation, consistent with Annendix C of the NRC Enforcement Policy. This violation is in the licensee's corrective action program as
05000498 Sou	th Texas 1					Condition Report 99-8375. This closed LER 99-S02-00.
05000499 Sou	th Texas 2					
08/19/1999	1999012-03	Pri: PLTSUP	Licensee	NCV	Pri: 1C	FAILURE TO PROPERLY REVITALIZE A UNIT 1 VITAL AREA
		Sec:			Sec: 3B	A violation was identified for failure to properly revitalize Unit 1 standby diesel generator No. 11, as required by the
Dockets Disc	ussed:				Ter:	security pran. This Seventy Level IV violation is being treated as a honorited violation, consistent with Appendix C of the NRC Enforcement Policy. This violation is in the licensee's corrective action program as Condition Report
05000498 Sou	th Texas 1					99-9227. This closes LER 99-S03-00.
05000499 Sou	th Texas 2					

By Primary Functional Area

;

Region IV SOUTH TEXAS PROJECT

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
06/26/1999	1999013	Pri: PLTSUP	NRC	POS	Pri: 3A	Security activities including plant access and support to operations were performed well.
		Sec:			Sec:	Security activities including plant access and support to plant operations and maintenance were well performed.
Dockets Disc	ussed:				Ter:	
05000498 Sou	th Texas 1					
05000499 Sou	ith Texas 2					
05/15/1999	1999011	Pri: PLTSUP	NRC	POS	Pri: 1A	Radiological work practices and low level contamination control declining trends reversed.
		Sec:			Sec:	The licensee successfully reversed the declining performance trend observed during the previous outage in the area
Dockets Disc	ussed:				Ter:	of radiological work practices and low level contamination controls. Planning and staffing of health physics support of work were significantly improved. Contamination control improvements were effective in reducing the approach of
05000498 Sou	ith Texas 1					low level contamination from the reactor containment building. Shielding and dose controls were effective in
05000499 Sol	ith Texas 2					maintaining outage collective dose below budget.
05/15/1999	1999011	Pri: PLTSUP	NRC	POS	Pri: 1A	Unit 1 core barrel removal for inservice inspection demonstrated excellent planning and dose control.
		Sec:			Sec:	The highly radioactive Unit 1 core barrel was successfully removed for inservice inspection using excellent planning
Dockets Disc	ussed:				Ter:	and dose controls. Contingency planning for the evolution was extensive. The job was completed with minimal
05000498 Sou	ith Texas 1					
05000499 Sou	th Texas 2					
05/06/1999	1999009	Pri: PLTSUP	NRC	STR	Pri: 1C	The licensee has implemented a sustained highly effective emergency preparedness program.
		Sec:			Sec: 3B	The licensee has implemented a sustained highly effective emergency preparedness program. This was evidenced
Dockets Disc	ussed:				Ter:	by good operational and emergency plan implementation skills, continuing emergency facility readiness, an effective training program, and sound program oversight. Close coordination with offsite officials remained on impact at
05000498 Sou	th Texas 1					aspect of the licensee's program.
05000499 Sou	th Texas 2					
04/09/1999	1999007	Pri: PLTSUP	NRC	POS	Pri: 2B	Housekeeping throughout the radiological controlled area was good.
		Sec:			Sec:	Housekeeping throughout the radiological controlled area was good. In general, areas were free of debris; tools and
Dockets Disc	ussed:				Ter:	equipment staged for work activities were propeny controlled.
05000498 Sou	th Texas 1					
05000499 Sou	th Texas 2					
04/09/1999	1999007	Pri: PLTSUP	NRC	POS	Pri: 3B	Effective controls were implemented to prevent the spread of radioactive materials.
		Sec:			Sec: 3C	Effective controls were implemented to prevent the spread of radioactive materials. Workers exiting the radiological
Dockets Disc	ussed:				Ter:	Radiation protection personnel provided appropriate and timely direction to workers who elegend the personnel provided appropriate and timely direction to workers who elegend the personnel in the second se
05000498 Sou	th Texas 1					monitoring equipment. Radiation workers used good health physics practices during the removal of potentially
05000499 Sou	in rexas 2					containsities crousing. Good controls to prevent the spread of radioactive contamination were in place.

í

By Primary Functional Area

Region IV

Date	Source	Functional Area	ID	Туре	Template Codes	item Title Item Description
04/09/1999	1999007	Pri: PLTSUP	NRC	POS	Pri: 5A	An effective quality assurance program was maintained for radiation protection.
		Sec:			Sec: 5C	An effective quality assurance program was maintained. The primary auditor was well qualified to perform radiation
Dockets Discu	ussed:				Ter:	protection audits/assessments. The audit and monitoring reports were comprehensive and provided management with a good assessment of the radiation protection program. The station identified radiological concerns and issues
05000498 Sou	th Texas 1					at the proper threshold which provided management with a good perspective to assess the radiation protection
05000499 500	th Texas 2					
04/09/1999	1999007	Pri: PLTSUP	NRC	STR	Pri: 3B	Overall, external exposure control program was effectively implemented.
		Sec:			Sec: 3C	Overall, the external exposure control program was effectively implemented. High radiation areas were properly
Dockets Discu	ussed:				Ter:	survey maps were written clearly and provided station workers with the appropriate controls and radiological
05000498 Sou	th Texas 1					information to safely accomplish assigned tasks. An excellent pre-job as low as is reasonably achievable (ALARA)
04/09/1999	1999007	Pri: PLTSUP	NRC	STR	Pri: 3B	A good internal exposure control program was in place.
		Sec:	,		Sec: 3C	A good internal exposure control program was in place. Continuous air monitors, portable air samplers, and high
Dockets Discu	ussed:				Ter:	conditions and limit airborne exposures during work evolutions. No problems were identified with the whole-body
05000498 Sou	th Texas 1					counting and internal dose assessment programs.
05000499 500	th rexas z					
04/09/1999	1999007	Pri: PLTSUP	NRC	STR	Pri: 3B	A good ALARA program was maintained.
		Sec:			Sec: 3C	A good ALARA program was maintained. The 1999 Unit 1 refueling outage dose goal of 160 person-rem was
Dockets Discu	ussed:				Ter:	managers and the ALARA committee were appropriately involved in establishing outage exposure coals
05000498 Sou	th Texas 1					Chemistry controls reduced reactor coolant system dose rates by about 10 percent.
05000499 Sou	th Lexas 2					
04/09/1999	1999007-01	Pri: PLTSUP	NRC	NCV	Pri: 3A	Failure to follow radiation work permit instructions.
		Sec:			Sec:	Two examples of a violation of Technical Specification 6.8.1 were identified which involved the failure to follow
Dockets Discu	ussed:				Ter:	Condition Reports 99-5232 and 99-5374. These Severity Level IV violations are being treated as a non-cited
05000498 Sou	th Texas 1					violation, consistent with Appendix C of the NRC Enforcement Policy.
05000499 500						
04/09/1999	1999007-02	Pri: PLTSUP	NRC	NCV	Pri: 3A	Failure to perform a survey
		Sec:			Sec:	A violation of 10 CFR 20.1501(a) was identified involving the failure to perform a radiological survey. This Severity
Dockets Discu	ussed:				Ter:	Policy. This violation was placed in the licensee's corrective action program as Condition Report 99-5232
05000498 Sou	th Texas 1					
05000499 Sou	m rexas z					

e

By Primary Functional Area

Region IV

Data	•	Functional			Template	item Title
Date	Source	Area	ID	Туре	Codes	Item Description
04/03/1999	1999006	Pri: PLTSUP	NRC	POS	Pri: 2A	Emergency preparedness drill provided effective training.
Deskate Disc		Sec:			Sec: 3B	An emergency preparedness drill was observed and was found to provide effective training. The se
05000498 Sou	ussed: th Texas 1				Ter:	response organization was appropriately focused on accident mitigation and measures to protect public health and
05000499 Sou	th Texas 2					services a service of an end of a good working condition.
04/03/1999	1999006	Pri: PLTSUP	NRC	POS	Pri: 2B	Outage dose reduction and contamination control showed significant improvemente
Dockets Discu	iseod:	Sec:			Sec: 3A	Significant improvements over previous outage performance were demonstrated in dose reduction and
05000498 Sout	isseu. Ib Texas 1				Ter:	mockup training, low dose waiting areas, newly manufactured shielding that and engineering controls including:
05000499 Sout	th Texas 2					and covered floor grating areas to prevent spread of contamination.
02/25/1990	1000000	0.1.0.00				
02/23/1999	1999003	Pri: PLTSUP	NRC	POS	Pri: 5A	Good, effective audit and quality monitoring reports of the rad. environmental program were performed
Dockets Discu	scadi	Sec:			Sec:	Good, effective audit and quality monitoring reports of the radiological environmental monitoring program was
05000498 Sout	h Texas 1				Ter:	with an overview of the radiological environmental and meteorological monitories provide management
05000499 Sout	h Texas 2					actions were closed in a timely manner; however, some actions were closed before all items were completed
02/25/1999	1000002					
02/20/13335	1333003	Pri: PLISUP	NRC	STR	Pri: 3A	Overall, radiological environmental monitoring program was effectively implemented.
Dockets Discus	ssed:	9ec:			Sec: 3B	Overall, the radiological environmental monitoring program was effectively implemented in accordance with the
05000498 South	n Texas 1				Ter: 4C	reservoir continued to trend down. The operation of South Texas Project Nuclear Station station with the
05000499 South	n Texas 2					buildup of radioactivity off site. Descriptive radiological environmental monitoring program implementing procedures
02/25/1999	1000002	Deix Di Torre				
02/20/1000	1333003	Ph: PLISUP	NRC	STR	Pri: 3A	Good meteorological monitoring program was in place, exceeded guidance of Regulatory Guide 1 23
Dockets Discus	ssed:	5ec:			Sec: 3B	A good meteorological monitoring program was in place. The performance of the meteorological monitoring
05000498 South	Texas 1				Ter: 4C	Supervision and guidands contained in Regulatory Guide 1.23.
05000499 South	Texas 2					
02/20/1999	1999002	Pri DI TSUD	NPC		Del: 40	
		Sec:	NRC	FU3	Piii (C	Excellent live mengning training was provided offsite to fire brigade teams.
Dockets Discus	sed:					tailored to mimic plant areas and equipment to maximize training regime and effecting training facility was
05000498 South	Texas 1				107:	was involved in the training.
05000499 South	Texas 2					

Page: 21 of 22 03/29/2000 17:21:42 IR Report 3

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

By Primary Functional Area

Date	Source	Functional Area	ID	Туре	Template Codes	item Title Item Description
02/20/1999	1999002	Pri: PLTSUP	NRC	POS	POS Pri: 1C Good sampling and analysis techniques during routine sampling.	Good sampling and analysis techniques during routine sampling.
0212011333	1000002	Sec:			Sec: The inspectors observed good sampling and analysis techniques along with strict procedural adhered and the chemistry technicians during routine sampling. Laboratory equipment was modern and in good control of the sampling.	
Dockets Disc	ussed:				Ter:	
05000498 Sou	uth Texas 1					
05000499 Sou	uth Texas 2					

•

Region IV

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX By Primary Functional Area

1 I Ì

		Legend				
Type Codes:	Temp	Template Codes:		Functional Areas:		
BU Bulletin	1A	Normal Operations	OPS	Operations		
CDR Construction	1B	Operations During Transients	MAINT	Maintenance		
DEV Deviation	1C	Programs and Processes	ENG	Engineering		
EEI Escalated Enforcement Item	2A	Equipment Condition	PLTSUP	Plant Support		
IFI Inspector follow-up item	2B	Programs and Processes	OTHER	Other	-	
LER Licensee Event Report	3A	Work Performance				
LIC Licensing Issue	3B	KSA				
MISC Miscellaneous	3C	Work Environment				
MV Minor Violation	4A	Design				
NCV NonCited Violation	4B	Engineering Support				
NEG Negative	4C	Programs and Processes				
NOED Notice of Enforcement Discretion	5A	Identification				
NON Notice of Non-Conformance	5B	Analysis				
OTHR Other	5C	Resolution				
P21 Part 21	.					
POS Positive						
SGI Safeguard Event Report						
STR Strength	ID Co	des:	- L			
URI Unresolved item	NRC	NRC				
VIO Violation	Self	Self-Revealed				
WK Weakness	Licer	isee Licensee	1			

EEIs are apparent violations of NRC Requirements that are being considered for escalated enforcement action in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Action" (Enforcement Policy), NUREG-1600. However, the NRC has not reached its final enforcement decision on the issues identified by the EEIs and the PIM entries may be modified when the final decisions are made.

URIs are unresolved items about which more information is required to determine whether the issue in question is an acceptable item, a deviation, a nonconformance, or a violation. A URI may also be a potential violation that is not likely to be considered for escalated enforcement action. However, the NRC has not reached its final conclusions on the issues, and the PIM entries may be modified when the final conclusions are made.

Page 1 of 2

03/30/2000 16:28:14

SOUTH TEXAS PROJECT Inspection / Activity Plan 04/02/2000 - 03/31/2001

. . . .

					No. assigned	Planned Dates		Inspection
Units	Inspection Ac	tivity	Title	on Site	to Procedure	Start	End	Туре
	RPBA17 -	DRILL	EVALUATION	2				
12	IP 7111406		Drill Evaluation		2	04/02/2000	06/24/2000	Baseline Inspections
., =	SGR2 -	STEA	M GENERATOR REPLACEMENT INSPECTION	2				
1	IP 50001		Steam Generator Replacement Inspection		2	04/02/2000	07/01/2000	Regional Initiative
	RPBA13 -	TEMP	ORARY PLANT MODIFICATIONS	2				
1.2	IP 7111123		Temporary Plant Modifications		• 2	04/02/2000	03/31/2001	Baseline Inspections
	EMB -	SGRI	- CUTTING, WELDING, NDE	2				
1	IP 50001		Steam Generator Replacement Inspection		1	04/03/2000	04/07/2000	Regional Initiative
	EMB -	ISI		2				
1.2	IP 7111108		Inservice Inspection Activities		2	04/03/2000	04/08/2000	Baseline Inspections
	SGRI -	STEA	M GENERATOR REPLACEMENT INSPECTION	2				
1	IP 50001		Steam Generator Replacement Inspection	_	1	04/10/2000	04/14/2000	Regional Initiative
	SGRI -	STEA	M GENERATOR REPLACEMENT INSPECTION	2				_
1	IP 50001		Steam Generator Replacement Inspection		1	04/17/2000	04/21/2000	Regional Initiative
	RPBA21	EQUI	PMENT ALIGNMENT	2		05/07/0000		
1	IP 7111104		Equipment Alignment	•	2	05/07/2000	06/24/2000	Baseline Inspections
	SGRI	STEA	M GENERATOR REPLACEMENT INSPECTION	2	4	A		
1	IP 50001		Steam Generator Replacement Inspection		1	05/08/2000	05/12/2000	Regional Initiative
	PBA-TI	- TI-144	4, PI DATA REVIEW	1		054400000		
1,2	IP 2515/14	4	Performance Indicator Data Collecting and Reporting Process Review		1	05/14/2000	08/05/2000	Safety Issues
	SGRI	- STEA	M GENERATOR REPLACEMENT INSPECTION	2		05456000		-
1	IP 50001		Steam Generator Replacement Inspection		I	05/15/2000	05/19/2000	Regional Initiative
	OB-PIR	- PIR IN	NSPECT	5		004040000	00/00/0000	
1,2	IP 71152		Identification and Resolution of Problems		4	06/19/2000	06/23/2000	Baseline Inspections
	PSB-RP1	- RAD	MONITORING INSTR	•	4	06/26/2000	08/00/00000	
1, 2	IP 7112103	3	Radiation Monitoring Instrumentation	1		00/20/2000	00/30/2000	Baseline Inspections
	PSB-RP7	- ENVI	RONMENTAL MONITORING	•	1	09/25/2000	00/20/2000	Decelle a fer a stat
1, 2	IP 7112203	3	Radiological Environmental Monitoring Program	2	T	03/23/2000	09/29/2000	Baseline Inspections
	PSB-S1	- RESP	P TO CONT EVENTS, SEC PLAN, AND PIV	_	2	09/25/2000	00/20/2000	Decelies less stires
1,2	IP 711300	3	Response to Contingency Events (Protective Strategy and Implementation of P		2	09/25/2000	09/29/2000	Baseline inspections
1, 2	IP 7113004	4	Security Plan Changes		2	09/25/2000	09/29/2000	Baseline inspections
1,2	IP 71151		Performance Indicator Verification	2	2	09/23/2000	09/29/2000	Baseline Inspections
	PSB-EP1	- DRIL	L/EXERCISE PERF, EAL/EP, AND PIV	-	2	10/16/2000	10/20/2000	Desellar
1,2	IP 711140	1	Exercise Evaluation		<u>د</u>	10/16/2000	10/20/2000	Daseline inspections
1,2	IP 711140	4	Emergency Action Level and Emergency Plan Changes		2	10/10/2000	10/20/2000	Baseline Inspections
1,2	IP 71151		Performance Indicator Verification		2	10/10/2000	10/20/2000	Baseline Inspections
	This report of	loes not	include INPO and OUTAGE activities.					
	This report s	hows or	nly on-site and announced inspection procedures.					•

Page 2 of 2

03/30/2000 16:28:14

SOUTH TEXAS PROJECT Inspection / Activity Plan 04/02/2000 - 03/31/2001

, 010

.

r		Title	No. of Staff on Site	No. assigned to Procedure	Plannec Start	Dates End	Inspection Type
Units	Inspection Activity						
	RPBA32 - EMER	GENCY EXERCISE AND EVALUATION	2	0	10/16/2000	10/20/2000	Peopline Inconstions
1,2	IP 7111401	Exercise Evaluation	•	2	10/10/2000	10/20/2000	baseline inspections
	RPBA25 - ADVE	RSE WEATHER	2	0	11/10/0000	00/10/2001	Deceline Inconstinue
1,2	IP 7111101	Adverse Weather Protection		2	11/12/2000	02/10/2001	baseline inspections
	PSB-RP2 - ALAR	A PLANNING/CONTROL 1	I I	•	11/12/0000	11/17/0000	Desetting to see the
1,2	IP 7112102	ALARA Planning and Controls		I	11/13/2000	11/1//2000	Baseline inspections
	PSB-RP3 - EFFLU	JENTS	1		10/04/0000	10/00/0000	
1,2	IP 7112201	Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		1	12/04/2000	12/08/2000	Baseline Inspections
	PSB-S2 - ACCE	SS AUTH/CONTROL	1		10/04/0000	40/00/0000	
1,2	IP 7113001	Access Authorization Program (Behavior Observation Only)		1	12/04/2000	12/08/2000	Baseline Inspections
1, 2	IP 7113002	Access Control (Search of Personnel, Packages, and Vehicles: Identification ar		1	12/04/2000	12/08/2000	Baseline Inspections
	PSB-RP4 - RAD	ATERIAL PROCESSING/SHIPPING	1		10/10/0000		
1,2	IP 7112202	Radioactive Material Processing and Transportation		1	12/18/2000	12/22/2000	Baseline Inspections
	RPBA22 - EQUI	PMENT ALIGNMENT	2	•			_
2	IP 7111104	Equipment Alignment		2	12/31/2000	02/10/2001	Baseline Inspections
	RPBA18 - DRILL	. EVALUATION	2	•	10/04/00000		_
1,2	IP 7111406	Drill Evaluation		2	12/31/2000	03/31/2001	Baseline Inspections
	PSB-RP5 - ALAR	A PLANNING/CONTROL 2	1				
1, 2	IP 7112102	ALARA Planning and Controls		1	01/02/2001	01/06/2001	Baseline Inspections
	PSB-RP6 - ACCE	ISS TO RAD SIGN AREAS AND PIV	1				
1, 2	IP 7112101	Access Control to Radiologically Significant Areas		1	01/29/2001	02/02/2001	Baseline Inspections
1,2	IP 71151	Performance Indicator Verification		1	01/29/2001	02/02/2001	Baseline Inspections
	EMB - MAIN	TENANCE RULE IMPLEMENTATION	1				
1,2	IP 7111112B	Maintenance Rule Implementation		1	02/05/2001	02/09/2001	Baseline Inspections
	EMB - 50.59		1				
1,2	IP 7111102	Evaluation of Changes, Tests, or Experiments		1	02/26/2001	03/02/2001	Baseline Inspections