United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

By Primary Functional Area

Functional Template Item Title ID Date Source Codes Item Description Area Type 01/31/2000 1999009 Pri: OPS NRC Pri: 1A Cold weather preparations. MISC Sec: Sec: Cold weather preparations were performed in accordance with instructions contained within approved procedures and were completed in a timely manner and without error. Provisions to ensure systems, such as heat tracing, remained **Dockets Discussed:** Ter: operable and were adequate. 05000263 Monticello 01/31/2000 1999009-01 Pri: OPS NRC NCV Pri: 1C Inappropriate change to an emergency operating procedure. Sec: Sec: 4B Changes made to the "Secondary Containment Control" emergency operating procedure introduced non-conservatism and did not meet the intent of the safety evaluation performed by the engineering department. A non-cited violation of **Dockets Discussed:** Ter: 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," was issued because changes 05000263 Monticello made to the procedure did not provide appropriate guidance for responding to high radiation conditions within secondary containment. The NRC tracking number for the non-cited violation is 50-263/1999009-01(DRP). Furthermore, a condition report was not generated when the engineering department became aware of the procedural inadequacy. 01/11/2000 1999008 Pri: OPS NRC POS **Pri:** 1A Command and control. Sec: Sec: Operators demonstrated an increased level of alarm awareness, application of management expectations, and command and control during routine control room evolutions. **Dockets Discussed:** Ter: 05000263 Monticello 01/06/2000 1999009 Pri: OPS Pri: 1A NRC MISC Reactor shutdown activities. Sec: Sec: 3A Reactor shutdown and refueling activities were performed in accordance with instructions contained in approved procedures by qualified and well-trained operators. **Dockets Discussed:** Ter: 05000263 Monticello 12/07/1999 1999008 Pri: OPS POS Pri: 2A High pressure coolant injection system inoperable. Licensee Sec: Sec: 1A The licensee appropriately declared the high pressure coolant injection (HPCI) system inoperable, entered a 14-day limiting condition for operation, isolated and depressurized the HPCI steam line, and made a 4-hour non-emergency **Dockets Discussed:** Ter: 5A notification when they identified that a HPCI steam line support was loose. 05000263 Monticello 10/23/1999 1999007 Pri: OPS Pri: 1A NRC POS Conduct of operation during power changes. Sec: Sec: 3A Planned and unplanned reactor power reductions were performed in a controlled manner. Operator response to annunciators had improved since the previous inspection period. **Dockets Discussed:** Ter: 05000263 Monticello

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
10/16/1999	1999007	Pri: OPS	NRC	NEG	Pri: 1B	Untimely update of abnormal operating procedures.
		Sec:			Sec: 3A	Although the values specified in an abnormal operating procedure for decreasing condenser vacuum were conservative,
Dockets Discu	ssed:				Ter:	the inspectors were concerned that this procedure, which required operators to insert a manual scram under certain
05000263 Monticello						
08/25/1999	1999301-01	Pri: OPS	NRC	NCV	Pri:	Failure to maintain examination integrity.
		Sec:			Sec:	While the licensee had established appropriate procedures to control test material integrity, the examination team
Dockets Discussed: 05000263 Monticello				Ter:	identified a lack of plant staff understanding regarding current examination security measures that resulted in an examination compromise. The licensee took appropriate short-term corrective actions to prevent any additional exam compromise. This Severity Level IV violation of 10 CFR 55.49, which requires all applicants, licensees, and facility licensees to not engage in any activity that compromises the integrity of any application, test, or examination required by 10 CFR 55, which includes initial NRC licensing examination activity, is being treated as a Non-Cited Violation with a tracking number of 50-263/99301-01(DRS).	
08/13/1999	1999006	Pri: OPS	NRC	POS	Pri: 1A	Use of risk during operations.
		Sec:			Sec: 3A	The licensee properly considered risk during maintenance work and postponed the repair of a power supply in the rod
Dockets Discussed: 05000263 Monticello					Ter: 2B	position information system. The maintenance was postponed because concurrent maintenance that was scheduled on load center 109 increased the potential for a reactor trip (scram) coupled with a loss of rod position indication.
08/12/1999	1999005	Pri: OPS	NRC	NEG	Pri: 1A	Improper throttling of isolation valves.
		Sec:			Sec: 3A	The overall conduct of operations was performed in accordance with procedures and management direction in a
Dockets Discussed: 05000263 Monticello					Ter:	safety-conscious manner. However, the inspectors identified an equipment operator work practice of throttling isolation valves for certain pressure gauges in order to dampen pressure oscillations while they took readings. This practice was not in accordance with management expectations.
08/10/1999	1999005-01	Pri: OPS	NRC	NCV	Pri: 3A	Failure to write a condition report when test requirements not met.
		Sec:			Sec: 4C	A Non-Cited Violation (NCV) of 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings,"
Dockets Discussed: 05000263 Monticello					Ter: 5A	was identified for the failure to initiate a Condition Report, as required by administrative procedures, on two separate occasions when the 12 core spray pump motor cooler flow rate did not meet the acceptance criterion contained in the "Emergency Core Cooling Systems Pump Motor Cooler Flush" surveillance test procedure. The NRC tracking number for this issue is NCV 50-263/99005-01(DRP).
08/04/1999	1999005	Pri: OPS	NRC	MISC	Pri: 1A	Conduct of power changes.
		Sec:			Sec: 3A	A control rod pattern adjustment was conducted by operators in a controlled and deliberate manner. Reactivity
Dockets Discu	ssed:				Ter:	adjustments were made in accordance with procedural requirements.
05000263 Mon	ticello					

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
07/01/1999	1999004	Pri: OPS	NRC	POS	Pri: 1A	Reactor startup.
		Sec:			Sec: 3A	A reactor startup on May 27, 1999, was performed in accordance with approved procedures. Infrequent evolution
Dockets Discu 05000263 Mon	ssed: ticello				Ter: 3B	briefings performed for the startup were thorough and comprehensive. Reactor thermal limits were properly monitored throughout the startup.
07/01/1999	1999004	Pri: OPS	NRC	POS	Pri: 1C	Procedural controls.
		Sec:			Sec: 3A	During a reactor startup with one average power range monitor bypassed per trip system, the licensee had procedural
Dockets Discussed: 05000263 Monticello					Ter:	requirements in place to ensure that the minimum number of average power range and associated intermediate power range nuclear instruments remained operable.
05/20/1999	1999003	Pri: OPS	NRC	POS	Pri: 3A	Good pre-job brief for reactor startup.
					Sec:	A reactor startup on April 28 was performed in accordance with approved procedures. Pre-job briefings for the startup
Dockets Discussed:					Ter:	were thorough and comprehensive.
05000263 Mon	ticello					
05/20/1999	1999003-01	Pri: OPS	NRC	NCV	Pri: 1A	Report of high pressure coolant injection system inoperability not made within 4 hours as required by 10 CFR
Dockets Discussed: 05000263 Monticello		Sec:			Sec: 5A Ter:	The licensee declared associated equipment inoperable and entered the appropriate Technical Specification limiting conditions for operation when the 13 emergency service water (ESW) pump did not start during routine surveillance testing. A Non-Cited Violation for a failure to make a non-emergency 4-hour report to the NRC within the specified time was identified. Following the return of the 13 ESW pump to an operable condition, the inspectors identified that the operators were not aware that the pump discharge check valve continued to leak and could affect operability. The tracking number for this Non-Cited Violation is 50-263/99003-01(DRP).
05/20/1999	1999003-02	Pri: OPS	NRC	NCV	Pri: 1B	Failure to provide a detailed procedure for the use of the feedwater pump high level trip bypass switch.
Dockets Discu 05000263 Mon	Dockets Discussed: 05000263 Monticello				Sec: 3A Ter:	Operators were initially unaware that the main steamlines had flooded due to their reliance on an improperly programmed SPDS (safety parameter display system) level indication in conjunction with some deficiencies in operators knowledge associated with reactor vessel water level instrumentation. Main steamlines were inadvertently flooded wher operators inappropriately bypassed reactor feedwater pump high level trips during a scram recovery. Operators had used an informal method for combating similar transients that had been encouraged during simulator training. The training department failed to proceduralize the informal method and operators failed to challenge the use of this non-proceduralized method. A Non-Cited Violation was issued for the failure to update Technical Specification required procedures, specifically, the use and operation of the reactor feed pump trip bypass switch. The tracking number for this Non-Cited Violation is 50-263/99003-02(DRP).
05/20/1999	1999003-03	Pri: OPS	NRC	NCV	Pri: 1B	Inadequate procedural controls for the use of mode switch.
		Sec:			Sec: 2A	Operators exacerbated a reactor scram when they failed to place the mode switch in shutdown in a timely manner,
Dockets Discu 05000263 Mon	ssed: ticello				Ter: 3A	resulting in a main steamline isolation. A Non-Cited Violation was identified in that procedural guidance for a reactor scram did not direct operators to place the mode switch in shutdown after a scram and before reactor pressure dropped below 840 pounds per square inch gauge. The tracking number for this Non-Cited Violation is 50-263/99003-03(DRP).

By Primary Functional Area

MONTICELLO Functional Template Item Title ID Date Source Codes Item Description Area Type 05/20/1999 1999003 Pri: OPS NRC Pri: 1B Reactor scram due to equipment failure. NEG Sec: MAINT Sec: 2A A reactor scram occurred on low reactor water level due to a failure of the digital feedwater control system. Although several complications were associated with scram recovery actions and resulted in inadvertently flooding the main **Dockets Discussed:** Ter: steam lines, reactor water level was eventually stabilized in the normal shutdown band. Proper NRC notifications were 05000263 Monticello made. 04/08/1999 1999002 Pri: OPS NRC NEG Pri: 2A Weak operability evaluation. Sec: Sec: 1A The licensee's initial operability determination conducted for a degraded bellows leak detection system for a safety relief valve was not thorough. The subsequent review, performed after the inspectors raised concerns, was thorough and **Dockets Discussed:** Ter: 4B appropriately concluded the valve was operable. 05000263 Monticello 04/08/1999 1999002 Pri: OPS NRC POS Pri: 2A Safety parameter display system loss. Sec: Sec: A loss of the safety parameter display system associated with an unplanned outage of the plant process computer was reported to the NRC headquarters operations center in accordance with plant procedures. The inspectors found that **Dockets Discussed:** Ter: procedures and reporting requirements were appropriate. 05000263 Monticello 04/08/1999 1999002 Pri: OPS NRC POS Pri: 3B Shift technical advisors. Sec: Sec: A licensee review of shift technical advisor training indicated that shift technical advisors were trained and qualified as required by the associated training program. Inspectors sampled the requirements and found no deficiencies. Dockets Discussed: Ter: 05000263 Monticello

04/08/1999	1999002	Pri: OPS	NRC	POS	Pri: 1A	Response to drywell leak.		
Dockets Discussed: 05000263 Monticello		Sec: ENG	: ENG		Sec: 2A Ter:	The licensee properly responded to a momentary increase in the drywell unidentified leak rate. The inspectors found the evaluation and the determination of the cause to be comprehensive and accurate.		
03/12/1999	1999010	Pri: OPS	NRC	MISC	Pri: 3A	Crew performance.		
Sec:				Sec: 3B	The operating shift crew observed by the inspectors passed the operating portion of the requalification examination.			
Dockets Discussed: 05000263 Monticello			Ter:	Ine licensee evaluators' findings and conclusions on the crew's performance during the dynamic simulator evaluation generally agreed with the inspectors' overall assessment. Although the inspectors identified some weaknesses pertaining to procedure use and crew communications, the aggregate individual performance deficiencies did not adversely impact the crew's ability to implement necessary mitigating actions to safely control the plant during emergencies.				

Region III

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

By Primary Functional Area

Functional Template Item Title ID Date Source Codes Item Description Area Type 03/12/1999 1999010 Pri: OPS NRC Pri: 3B Requal material. MISC Sec: Sec: The requalification examination material contained the necessary quantitative and qualitative attributes to provide an effective evaluation of operator skills. However, the inspectors noted some opportunities to enhance the material to Dockets Discussed: Ter: better probe and evaluate operator responsibilities and performance. In particular, dynamic simulator scenarios and 05000263 Monticello JPMs (job performance measures) could have been more challenging. 03/12/1999 1999010 Pri: OPS NRC MISC Pri: 3B Exam security. Sec: Sec: The licensee administered the annual regualification examinations according to program guidance and the examinations were consistent with regulatory guidelines. The licensee satisfactorily maintained examination security throughout the **Dockets Discussed:** Ter: examination period; however, the inspectors noted that an added security posting on the outer door leading into the 05000263 Monticello simulation facility room was needed. Also, no significant simulator performance or fidelity issues were identified. 03/12/1999 1999010 Pri: OPS Pri: 3B NRC MISC Operator remediation. Sec: Sec: The remediation program contained adequate measures to ensure individual and crew performance weaknesses were identified, assigned, and remediated prior to resumption of licensed duties. **Dockets Discussed:** Ter: 05000263 Monticello 03/12/1999 1999010 Pri: OPS NRC MISC Pri: 3B Operator physical examination requirements. Sec: Sec: The operators' license conditions were in conformance with program guidance and regulatory requirements of 10 CFR 55.21 for biennial physical examinations. Dockets Discussed: Ter: 05000263 Monticello 03/12/1999 1999010 Pri: OPS NRC NEG Pri: 3A Operator past performance problems. Sec: Sec: 3B Based on the review of past documents, licensed operators had demonstrated some past performance deficiencies pertaining to procedure adherence, communications, and command and control. Consequently, during this Dockets Discussed: Ter: 3C regualification inspection, the inspectors noted several instances in which operators demonstrated similar deficiencies 05000263 Monticello in procedure use and communications. The licensee's operator continuing training program and the operations department were continuing to address these issues at the conclusion of the inspection. 03/12/1999 1999010 Pri: OPS NRC Pri: 3A Shift manager duties. NEG Sec: Sec: 3C The inspectors, through observations and review of simulator scenario regualification examinations and discussions with licensee personnel, noted difficulties in the shift manager's (SM) ability to simultaneously implement the duties of the **Dockets Discussed:** Ter: SM, emergency director (ED), and shift technical advisor (STA) roles during plant emergency conditions. In addition, 05000263 Monticello during a plant fire casualty, the SM would also assume the duties of the shift supervisor. The licensee indicated that they were reviewing further actions to streamline the functions of the SM.

Region III

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

MONTICELLO						
Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
03/12/1999	1999010	Pri: OPS	NRC	POS	Pri: 3A	Control room activities.
		Sec:			Sec: 3B	Control room operators demonstrated an appropriate level of attentiveness to the operating panels and were
Dockets Discussed:		Ter:	knowledgeable of plant conditions. The inspectors considered the implementation of an end-of-shift briefing (post-shift briefing) as a positive practice, in general, operative conducted control room activities in a professional manager			
05000263 Mor	ticello					
03/12/1999	1999010	Pri: OPS	NRC	POS	Pri: 3B	Operator requal training feedback.
		Sec:			Sec:	The licensee's feedback process, that included training department self-assessment and Quality Assurance group
Dockets Discussed: 05000263 Monticello					Ter:	audits, was satisfactorily implemented. The licensee conducted good, self-critical audits which provided constructive feedback into both the initial license operator training and licensed operator requalification training programs. However, the licensee's operations department had not yet implemented a formal self-assessment program.
03/12/1999	1999010	Pri: OPS	NRC	POS	Pri: 3B	Self-contained breathing apparatus for operators.
		Sec:			Sec:	The licensee appropriately maintained self-contained breathing apparatus (SCBA) for licensed operators as required by
Dockets Discussed:					Ter:	10 CFR 50, Appendix R and station procedural requirements. All licensed operators had current SCBA medical examinations. SCBA training, and SCBA fit-testing.
05000263 Mor	iticello					
02/22/1999	1999001	Pri: OPS	NRC	MISC	Pri: 1A	Operator response to Group IV isolation.
		Sec:			Sec: 3A	The high pressure coolant injection system responded as expected to the Group IV isolation signal received
Dockets Discu 05000263 Mor	issed: iticello				Ter: 2B	unexpectedly during surveillance testing. Operators correctly implemented the abnormal procedure for the Group IV isolation. The licensee made a four-hour report in accordance with 10 CFR 50.72, and initiated a condition report associated with this event.
02/22/1999	1999001	Pri: OPS	NRC	NEG	Pri: 2A	Service water configuration.
		Sec:			Sec:	Inspectors identified a minor failure with maintaining the service water radiation monitor system configuration as
Dockets Discu	issed:				Ter:	required by procedure when operators did not restore the system to a normal line-up upon completion of system
05000263 Monticello						nusning.
02/22/1999	1999001	Pri: OPS	NRC	POS	Pri: 1B	Operator response to loss of building negative pressure.
		Sec:			Sec:	Operators demonstrated good communications, control room demeanor, and procedure use when emergency operating
Dockets Discu 05000263 Mor	issed: iticello				Ter:	procedures were implemented on a loss of reactor building negative pressure.

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

		Functional			Template	Item Title
Date	Source	Area	ID	Туре	Codes	Item Description
01/31/2000	1999009	Pri: MAINT	Licensee	POS	Pri: 3B	Non-destructive testing for welds properly assessed.
		Sec:			Sec: 3A	The licensee demonstrated a good questioning attitude while resolving non-destructive examination issues associated
Dockets Discu	ssed:				Ter:	with welds on sections of replaced residual heat removal service water system piping.
05000263 Monticello						
01/31/2000	1999009	Pri: MAINT	NRC	POS	Pri: 3C	Performance of maintenance.
		Sec:			Sec: 3A	Good communications skills, technician knowledge, use of three-part communication, self-checking, and engineering
Dockets Discus	ssed:				Ter:	involvement were observed during maintenance activities.
05000263 Monticello						
01/27/2000	1999009	Pri: MAINT	Licensee	NEG	Pri: 3A	Near-miss tagging error.
		Sec:	2.0011000		Sec: 2B	Inappropriate assumptions associated with maintenance on a motor-operated valve resulted in safety tags being
Dockets Discussed:				Ter:	removed prior to the completion of maintenance on the valve. This "near-miss" safety tagging error was entered into the	
05000263 Monticello						licensee's corrective action program for tracking and resolution. Aggressive immediate and followup corrective actions were initiated.
01/11/2000	01/11/2000 1999008 Pri: MAINT NRC I		MISC	Pri: 4B	Power uprate procedure.	
		Sec:			Sec: 3C	Procedures that required changes as a result of the recent reactor power level increase (rerate), which remained
Dockets Discus	ssed:				Ter:	outstanding after the rerate, were properly controlled to prohibit use or were identified as having no impact on plant
05000263 Mont	ticello					
11/17/1999	1999008	Pri: MAINT	Self	MISC	Pri: 2B	Reactor core isolation cooling system 4-hour notification.
		Sec:			Sec: 3A	The licensee appropriately made a 4-hour non-emergency report to the NRC when they discovered a problem with a
Dockets Discu	ssed:				Ter: 2A	reactor core isolation cooling (RCIC) system flow indicator that could have affected RCIC system operability. When
05000263 Mont	ticello				from performing its function, the licensee retracted the 4-hour notification.	
11/04/1999	1999007-05	Pri: MAINT	NRC	NCV	Pri: 2B	Safety-related non-MCC (motor control center) molded case circuit breakers (MCCB) not periodically overcurre
		Sec:			Sec:	A testing program to ensure that safety-related 120-volt alternating current molded case circuit breakers would perform
Dockets Discus	ssed: ticello				Ter:	as designed did not exist and a non-cited violation was issued. (Associated item URI 50-263/99005-02(DRP)). The NRC tracking number for this issue is NCV 50-263/99007-05(DRP).
	-					

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

By Primary Functional Area

Functional Template Item Title ID Date Codes Item Description Source Area Type 10/19/1999 1999007-03 Pri: MAINT NRC NCV Pri: 3A Failure to initiate 10 CFR 50.72, 4-hour report for reactor core isolation cooling system inoperability. Sec: Sec: 5A A non-cited violation was identified for a failure to notify the NRC of the inoperable RCIC, a reportable event, within the allotted time. Additionally, system engineers initially failed to consider all likely possibilities associated with improperly Dockets Discussed: Ter: sized gaskets installed in RCIC. The NRC tracking number for this issue is 50-263/1999007-03(DRP). 05000263 Monticello 10/19/1999 1999007-04 Pri: MAINT Self NCV Pri: 2B Failure of work order to restore reactor core isolation cooling system per procedures. Sec: Sec: 3A An inoperable reactor core isolation cooling (RCIC) system resulted from installation of an incorrect flange gasket upstream of the RCIC turbine governor valve. A non-cited violation was identified for inadequate maintenance Dockets Discussed: Ter: procedures associated with troubleshooting the inoperable valve. The NRC tracking number for this issue is NCV 05000263 Monticello 50-263/1999007-04(DRP). 09/23/1999 1999006 Pri: MAINT Pri: 3A NRC MISC Conduct of surveillance activity. Sec: Sec: 4B Activities specified in surveillance test procedures were performed in a professional and thorough manner by qualified Dockets Discussed: technicians and operators who completed the activities in accordance with procedural requirements, using proper Ter: 2B radiation protection practices with radiation protection technicians present as required, calibrated test equipment, good 05000263 Monticello self-checking techniques, three-way communications, and good communications with the control room. Supervisors and system engineers frequently monitored job progress. 09/23/1999 1999006-01 Pri: MAINT Licensee NCV Pri: 2B Single failure vulnerability of the residual heat removal system when in suppression pool cooling mode. Sec: Sec: 4B The licensee identified that with the residual heat removal system in the suppression pool cooling mode an accident event sequence existed that could result in the number of available emergency core cooling system pumps being less **Dockets Discussed:** Ter: than that assumed in the USAR. Because the licensee had not previously identified this potential problem, plant 05000263 Monticello operating procedures had not been written to require entry into an LCO. This procedure inadequacy was identified as a non-cited violation. (LER 50-263/99-02-00) The NRC tracking number for this issue is NCV 50-263/99006-01(DRP). High pressure coolant injection (HPCI) system to be declared inoperable with MO-2071 [HPCI Test Return Isola 09/23/1999 1999006-02 Pri: MAINT NCV Pri: 2A Licensee Sec: Sec: 2B The licensee identified that the HPCI test return valve was unable to close against maximum expected differential pressure during certain assumed accident sequences. Because the HPCI system would be inoperable with this valve Dockets Discussed: Ter: open, an LCO should have been entered whenever this valve was opened during plant operations. Because the licensee 05000263 Monticello had not previously identified this potential problem, plant operating procedures had not been written to require entry into the LCO. (LER 50-263/99-07-00) The NRC tracking number for this issue is NCV 50-263/99006-02(DRP). 08/12/1999 1999005 Pri: MAINT NRC MISC Pri: 2A Standby gas treatment system material condition. Sec: Sec: 2B Material condition of the accessible portions of Division B of the standby gas treatment system and accessible portions of the reactor building service water radiation monitor system was adequate. Minor drawing and equipment labeling Dockets Discussed: Ter: issues with Division B of the standby gas treatment system were brought to the attention of the licensee and entered 05000263 Monticello into the corrective action program.

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

By Primary Functional Area

Functional Template Item Title ID Date Source Area Codes Item Description Type 08/12/1999 1999005 Pri: MAINT NRC Pri: 3A Conduct of surveillance. MISC Sec: Sec: 4B Activities specified in surveillance test procedures, including tests involving torus vacuum breakers and main steamline isolation instrumentation, were performed in a thorough manner by gualified technicians and operators and were Dockets Discussed: Ter: 2B performed in accordance with procedures and management direction in a safety-conscious manner. Supervisors and 05000263 Monticello system engineers frequently monitored job progress. 08/12/1999 1999005 Pri: MAINT NRC POS Pri: 3A Conduct of maintenance. Sec: Sec: 4B Work performed during maintenance activities, including maintenance involving an emergency diesel generator and the control room ventilation system, was thorough and performed in accordance with procedures and management direction Dockets Discussed: Ter: 2B in a safety-conscious manner. Maintenance supervisors and system engineers were involved in the oversight of these 05000263 Monticello activities. 07/01/1999 1999004 Pri: MAINT POS Pri: 3A Maintenance overtime. NRC Sec: Sec: Controls on overtime utilization were adequately implemented by the licensee for the maintenance staff that the inspectors assessed. The licensee's control of overtime met the Technical Specification administrative requirements **Dockets Discussed:** Ter: governing overtime. 05000263 Monticello 07/01/1999 1999004 Pri: MAINT NRC POS Pri: 3A Surveillance tests and valve lineups. Sec: Sec: 5C Surveillance tests and valve lineups associated with reactor startup were performed by qualified individuals using approved procedures. Deficiencies identified during the performance of activities were properly dispositioned and Dockets Discussed: Ter: corrected. 05000263 Monticello 07/01/1999 1999004 Pri: MAINT NRC POS Pri: 2A Operability of service water pumps. Sec: ENG Sec: 4B Operability of safety-related service water pumps was properly assessed after sandblasting material was introduced into the vicinity of the equipment through the ventilation system during the preparation of the building exterior for painting. Dockets Discussed: Ter: 05000263 Monticello 05/20/1999 1999003 Pri: MAINT Pri: 2B NRC NEG Impact of temporary modification on high pressure coolant injection system. Sec: OPS Sec: 4C The licensee did not evaluate the impact of a temporary modification to the high pressure coolant injection system steam drains prior to performance of surveillance testing. During the testing, the configuration of the modified drains **Dockets Discussed:** Ter: resulted in the receipt of an alarm that was normal for the condition, but not indicated as "expected" in the surveillance 05000263 Monticello test procedure.

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

By Primary Functional Area

Functional Template Item Title ID Date Source Area Codes Item Description Type 04/08/1999 1999002 Pri: MAINT NRC Pri: 2B Deficient level of detail in a procedure. NEG Sec: Sec: The inspectors noted a deficiency with the level of detail of instructions in the procedure followed for the calibration of relays associated with the safeguard bus degraded voltage protection, in that a short duration, 125-volt direct current **Dockets Discussed:** Ter: ground resulted and relay technicians experienced difficulty in the setup of the voltage test source. 05000263 Monticello 04/08/1999 1999002 Pri: MAINT NRC POS Pri: 3A Control rod drive hydraulic accumulator level switch work. Sec: Sec: Replacement of a control rod drive hydraulic accumulator level switch was performed by knowledgeable technicians who followed instructions in approved procedures. **Dockets Discussed:** Ter: 05000263 Monticello 04/08/1999 1999002-02 Pri: MAINT Pri: 2B High pressure coolant injection system Group IV isolation during surveillance test. Licensee NCV Sec: Sec: During the performance of the quarterly high pressure coolant injection (HPCI) surveillance test, a high steam flow signal isolated the steam to the HPCI turbine. The surveillance test was terminated. The high steam flow signal was **Dockets Discussed:** Ter: not caused by any piping integrity problems. The cause of this event was an inadequate surveillance procedure. The 05000263 Monticello surveillance procedure steps did not ensure that the high steam flow setpoint would be avoided. This failure to have an adequate procedure was considered a Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," and is being tracked as 50-263/99002-02(DRP). LER 50-263/99-001-00. 02/22/1999 1999001 Pri: MAINT Pri: 2B NRC MISC Maintenance on scram pilot valves. Sec: Sec: The inspectors observed the maintenance, isolation restoration, and post-maintenance testing associated with work order 9903983, "Install New Diaphragms into Scram Solenoid Pilot Valves," and identified no deficiencies. **Dockets Discussed:** Ter: 05000263 Monticello 02/22/1999 1999001 Pri: MAINT NRC Pri: 2A Residual heat removal system material condition. POS Sec: OPS Sec: The material condition of the residual heat removal (RHR) system was good. The adequacy of general housekeeping for "B" RHR pump room came into question when a partially burned swipe was found under the 14 RHR pump motor **Dockets Discussed:** Ter: heater. The cognizant system engineer promptly addressed the operability issue concerning 14 RHR pump and the 05000263 Monticello other RHR equipment discrepancies that were identified. Operations took adequate actions to address the plant housekeeping issues. 01/31/2000 1999009 Pri: ENG NRC MISC Pri: 4B Report of historical performance indicators. Sec: Sec: A brief review of the historical performance indicators submitted to the NRC, and subsequent interviews with engineers indicated that a problem may exist with the accuracy of the data. Dockets Discussed: Ter: 05000263 Monticello

By Primary Functional Area

Region III MONTICELLO

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description			
01/31/2000	1999009	Pri: ENG	NRC	NEG	Pri: 4A	Heat exchanger testing methodology inaccuracies.			
Dockets Discu	Sec: Dockets Discussed:		Sec: 3B Ter:	The licensee's methodology for performing residual heat removal heat exchanger efficiency tests did not provide adequate controls on the service water flow rate parameters established for conducting the test. The licensee corrected the deficiency and successfully confirmed the operability of the associated heat exchangers.					
03000203 1001	licello								
01/08/2000	1999009	Pri: ENG	NRC	POS	Pri: 4B	Conservative applications of risk to refueling plan.			
		Sec:			Sec: 3A	The inspectors concluded that the licensee conservatively applied shutdown risk concepts during the planning and			
Dockets Discussed: 05000263 Monticello			Ter:	execution of the refueling outage. The implementation of the outage plan was conducted effectively and in a controlled manner.					
11/02/1999	1999008	Pri: ENG	NRC	WK	Pri: 4B	Standby liquid control system weak procedure.			
	Sec:			Sec: 5B	The standby liquid control system relief valve remained operable with some valve seat leakage. The failure to document				
Dockets Discussed: 05000263 Monticello					Ter:	the amount of leakage that was acceptable was considered a weakness.			
09/23/1999	1999006	Pri: ENG	NRC	NEG	Pri: 4A	Non-conservative assumption in engineering calculation.			
	Sec:			Sec: 4B	A safety review performed by the licensee to show that the 12 core spray pump remained operable did not use the most				
Dockets Discu 05000263 Mon	ssed: ticello				Ter:	conservative pump conditions as calculation inputs. However, the margin to exceeding bearing design temperatures remained large and no operability concerns were identified.			
09/23/1999	1999006-03	Pri: ENG	NRC	NCV	Pri: 4C	Stroke time of AO-2379 in 1998 exceeded acceptance criterion but valve was not declared inoperable.			
		Sec:			Sec:	A review by the inspectors of the corrective action program as it related to inservice testing identified several potential			
Dockets Discussed: 05000263 Monticello					Ter:	weaknesses and one failure to declare the "reactor building to torus vacuum breaker" inoperable when it did not meet acceptance criteria. A non-cited violation was issued for failure to follow procedural requirements after the breaker did not meet inservice testing acceptance criteria. The NRC tracking number for this issue is NCV 50-263/99006-03(DRP).			
08/12/1999	1999005	Pri: ENG	NRC	NEG	Pri: 3A	Communication between engineers and operators.			
		Sec:			Sec: 4B	Due to poor communications between engineers and operators, reactor operators were uninformed for more than 12			
Dockets Discu 05000263 Mon	ssed: ticello				Ter: 4C	hours about the resolution of a condition where the 12 core spray pump motor cooler flow rate did not meet a surveillance test procedure acceptance criterion.			

By Primary Functional Area

MONTICELLO						
Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
07/01/1999	1999004	Pri: ENG	NRC	MISC	Pri: 4B	Y2K review.
Dockets Discussed: 05000263 Monticello		Sec:			Sec: Ter:	The inspectors conducted an abbreviated review of Y2K activities and documentation using Temporary Instruction (TI) 2515/141, "Review of Year 2000 (Y2K) Readiness of Computer Systems at Nuclear Power Plants." This Temporary Instruction is closed.
07/01/1999	1999004	Pri: ENG	NRC	NEG	Pri: 2A	Emergency diesel generator speed control.
		Sec:			Sec: 4B	The engineering department had not fully evaluated the impact of configuring the emergency diesel generator with the
Dockets Discussed: 05000263 Monticello					Ter:	droop set above zero in the standby mode. Procedural enhancements and an adjustment of one breaker thermal overload setpoint were performed to further ensure operability of safety-related equipment. An engineering evaluation was initiated to reconfigure the emergency diesel generator controls to have droop set at zero when the emergency diesel generator was in the standby mode, precluding the continual evaluation of component operability as equipment degraded or was repaired.
07/01/1999	1999004	Pri: ENG	NRC	NEG	Pri: 4B	High-energy line break operability determinations.
Dockets Discussed: 05000263 Monticello		Sec:			Sec: Ter:	Operability determinations for equipment susceptible to failure during a high-energy line break were incomplete and did not include an assessment of the full spectrum of potential single failures as required by the safety analysis report. Rather than perform the complex analysis required to determine equipment operability for the additional single failures not previously analyzed, the licensee elected to correct the deficiency by reinforcing the degraded structure that caused the adverse condition.
05/20/1999	1999003	Pri: ENG	NRC	MISC	Pri: 4B	Engineering evaluation of service water pump trip.
Dockets Discu 05000263 Mon	issed: ticello	Sec:			Sec: Ter:	Investigations into the cause of the 13 emergency service water pump trip were appropriately scoped. No discrepancies were identified with troubleshooting activities or the operability determination.
05/20/1999	1999003	Pri: ENG	NRC	NEG	Pri: 4B	Weak safety review of cover on the spent fuel pool.
Dockets Discussed: 05000263 Monticello		Sec:			Sec: Ter:	The licensee's safety review of the installation of a fabric cover over the spent fuel pool was weak in that it did not address whether water buildup on the top of the fabric could cause it to fall into the spent fuel pool and block the spent fuel pool cooling flow path.
05/20/1999	1999003-04	Pri: ENG	NRC	NCV	Pri: 2A	Failure of licensee to verify the adequacy of the design of the safety relief valve air system.
Dockets Discu 05000263 Mon	05/20/1999 1999003-04 Dockets Discussed: 05000263 Monticello				Sec: 4A Ter:	Engineers failed to evaluate the safety relief valve air system components when they identified conditions that had the potential to render the system inoperable. The issue was characterized by the inspectors as a Non-Cited Violation, with a tracking number of 50-263/99003-04(DRP).

Region III

By Primary Functional Area

Functional Template Item Title ID Date Source Area Codes Item Description Type 04/08/1999 1999002 Pri: FNG NRC POS Pri: 4B Engineering support for root valve repair. Sec: Sec: 3A Engineering and safety evaluations for inhibiting the reactor protection system bypass function for the turbine stop valve closure and turbine control valve fast closure scram were comprehensive. No safety significant issues were identified. **Dockets Discussed:** Ter: Engineering and supervisory involvement were observed throughout the evolution. 05000263 Monticello 04/08/1999 1999002 Pri: ENG NRC POS Pri: 4B Engineering involvement in maintenance. Sec: Sec: 5B When the inspections of control rod drive hydraulic accumulator pressure switch internals indicated past leakage, the system engineer demonstrated good follow-through by having technicians inspect other instruments to aid in **Dockets Discussed:** Ter: determining the extent of the problem. 05000263 Monticello 02/22/1999 1999001 Pri: ENG NRC Pri: 4B 10 CFR 50.59 report. MISC Sec: Sec: In general, the summaries in the Monticello periodic "Report of Changes, Tests, and Experiments," provided sufficient detail to determine that the licensee's conclusion that the changes did not involve unreviewed safety questions was **Dockets Discussed:** Ter: reasonable. 05000263 Monticello 01/14/2000 2000002 Pri: PLTSUP NRC POS **Pri:** 4C As low as is reasonably achievable (ALARA) controls. Sec: Sec: Refueling outage 19 activities were well planned and utilized effective ALARA controls. Accrued dose was consistent with completed work including emergent activities. Drywell shielding and scaffolding support work was well conducted. Dockets Discussed: Ter: Workers exhibited good work practices and radiation protection management and technicians' work oversight was 05000263 Monticello effective. 01/14/2000 2000002 Pri: 4C Pri: PLTSUP NRC POS Internal exposure control program. Sec: Sec: The inspector concluded that the licensee maintained an effective internal exposure control program. Whole body counting systems were appropriately used and well maintained. The licensee's actions following the discovery of alpha Dockets Discussed: Ter: contaminants in the primary system components were considered appropriate. 05000263 Monticello 01/14/2000 2000002 Pri: PLTSUP Pri: 4C NRC POS Radiation postings. Sec: Sec: Radiological postings and controls were well maintained and associated surveys were well performed. During walkdowns, the inspector observed good work practices and observed no significant, radiological impediments to **Dockets Discussed:** Ter: routine work. 05000263 Monticello

United States Nuclear Regulatory Commission PLANT ISSUE MATRIX

By Primary Functional Area

Functional Template Item Title ID Date Source Area Codes Item Description Type 01/14/2000 2000002 Pri: PI TSUP NRC POS Pri: 4C Control of locked high radiation areas. Sec: Sec: Access to High Radiation Areas (HRAs), Locked High Radiation Areas (LHRAs), and Very High Radiation Areas (VHRAs) were well controlled and associated keys were properly issued and accounted for by RP staff. Dockets Discussed: Ter: 05000263 Monticello 11/04/1999 1999007 Pri: PLTSUP NRC POS Pri: 3A Good as low as is reasonably achievable planning. Sec: Sec: Appropriate planning for replacement of a broken pipe hanger resulted in dose being as low as is reasonably achievable. **Dockets Discussed:** Ter: 05000263 Monticello 09/23/1999 1999006-04 Pri: PLTSUP Pri: 4C NRC NCV Technical specification (TS) 25 percent extension allowance applied to non-TS required surveillance frequen Sec: Sec: The method for tracking surveillance testing requirements afforded the opportunity to apply 25 percent time extensions allowed for Technical Specification surveillance requirements to non-Technical Specification requirements. A non-cited **Dockets Discussed:** Ter: violation of NRC requirements was identified for a failure to inventory special nuclear material at a frequency not to 05000263 Monticello exceed 12 months. The NRC tracking number for this issue is NCV 50-263/99006-04(DRP). 1999004 07/01/1999 Pri: PLTSUP NRC NEG Pri: 1C Dosimeter alarm setpoint. Sec: Sec: Although personnel were responsible to monitor their own accumulated dose, the licensee did not lower electronic dosimeter alarm setpoints to reflect radiological conditions during plant shutdown, a poor practice. Dockets Discussed: Ter: 05000263 Monticello 06/24/1999 1999011 Pri: PLTSUP NRC POS Pri: 1C 1999 Emergency Plan exercise. Sec: Sec: 3A Overall licensee performance during the 1999 Emergency Plan exercise was very good. Dockets Discussed: Ter: 05000263 Monticello 06/24/1999 1999011 Pri: PLTSUP Pri: 1C NRC POS Self-critiques following termination of the exercise were generally good. Licensee critique findings were con Sec: Sec: 5A Self-critiques following termination of the exercise were generally good. Licensee critique findings were consistent with **Dockets Discussed:** the NRC evaluation team's findings. Ter: 5B 05000263 Monticello

By Primary Functional Area

Region III

MONTICELLO

Date	Source	Functional Area	ID	Туре	Template Codes	Item Title Item Description
06/24/1999	1999011	Pri: PLTSUP	NRC	POS	Pri: 3A	Performance in simulator control room, technical support center, operations support center, and emergency
Sec:						Performance in the simulator control room, technical support center, operations support center, and emergency
Dockets Discussed:				Ter:	operations facility during an emergency plan exercise was effective.	
05000263 Mon	05000263 Monticello					
02/22/1999	1999001	Pri: PLTSUP	NRC	POS	Pri: 1C	Radiation protection control of decontamination efforts.
	Sec:				Sec:	Radiation protection activities associated with the inadvertent contamination and subsequent decontamination of the
Dockets Discussed: 05000263 Monticello			Ter:	fuel pool ventilation duct work were thorough. Technicians demonstrated good exposure minimization practices during event initial response and radiation work permit planning. Effective communications were observed during the pre-job briefing associated with decontamination activities.		

By Primary Functional Area

Legend

Type Co	odes:	Temp	late C	odes:	
BU	Bulletin	1A	Norm	al Operations	
CDR	Construction	1B	Oper	ations During Tra	nsie
DEV	Deviation	1C	Prog	rams and Process	ses
EEI	Escalated Enforcement Item	2A	Equip	oment Condition	
IFI	Inspector follow-up item	2B	Prog	rams and Process	ses
LER	Licensee Event Report	ЗA	Work	Performance	
LIC	Licensing Issue	3B	KSA		
MISC	Miscellaneous	3C	Work	Environment	
ΜV	Minor Violation	4A	Desi	gn	
NCV	NonCited Violation	4B	Engir	neering Support	
NEG	Negative	4C	Prog	rams and Process	ses
NOED	Notice of Enforcement Discretion	5A	Ident	ification	
NON	Notice of Non-Conformance	5B	Anal	ysis	
OTHR	Other	5C	Reso	lution	
P21	Part 21				
POS	Positive				
SGI	Safeguard Event Report				
STR	Strength	ID Co	des:		
URI	Unresolved item	NRC		NRC	
VIO	Violation	Self		Self-Revealed	
WK	Weakness	Licen	see	Licensee	

Functional Areas: OPS Operations MAINT Maintenance ENG Engineering PLTSUP Plant Support OTHER Other

EEIs are apparent violations of NRC Requirements that are being considered for escalated enforcement action in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Action" (Enforcement Policy), NUREG-1600. However, the NRC has not reached its final enforcement decision on the issues identified by the EEIs and the PIM entries may be modified when the final decisions are made.

URIs are unresolved items about which more information is required to determine whether the issue in question is an acceptable item, a deviation, a nonconformance, or a violation. A URI may also be a potential violation that is not likely to be considered for escalated enforcement action. However, the NRC has not reached its final conclusions on the issues, and the PIM entries may be modified when the final conclusions are made.