

**James S. Baumstark**  
Vice President  
Nuclear Engineering

Consolidated Edison Company of New York, Inc.  
Indian Point 2 Station  
Broadway & Bleakley Avenue  
Buchanan, New York 10511

Internet: baumstarkj@coned.com  
Telephone: (914) 734-5354  
Cellular: (914) 391-9005  
Pager: (917) 457-9698  
Fax: (914) 734-5718

April 24, 2000

Re: Indian Point Unit No. 2  
Docket No. 50-247  
LER 00-03-00

Document Control Desk  
US Nuclear Regulatory Commission  
Mail Station PI-137  
Washington, DC 20555-0001

The attached Licensee Event Report 00-03-00 is hereby submitted in accordance with the requirements of 10 CFR 50.73.

Very truly yours,



Attachment

C: Mr. Hubert J. Miller  
Regional Administrator - Region I  
US Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Mr. Jefferey Harold, Project Manager  
Project Directorate I-1  
Division of Reactor Projects I/II  
US Nuclear Regulatory Commission  
Mail Stop 14B-2  
Washington, DC 20555

Senior Resident Inspector  
US Nuclear Regulatory Commission  
PO Box 38  
Buchanan, NY 10511

IE22

<b>NRC FORM 366</b> (6-1998)	<b>U.S. NUCLEAR REGULATORY COMMISSION</b>	<b>APPROVED BY OMB NO. 3150-0104 EXPIRES 06/30/2001</b> Estimated burden per response to comply with this mandatory information collection request: 50 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Forward comments regarding burden estimate to the Records Management Branch (T-6 F33), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, and to the Paperwork Reduction Project (3150-0104), Office of Management and Budget, Washington, DC 20503. If an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.
<b>LICENSEE EVENT REPORT (LER)</b>  (See reverse for required number of digits/characters for each block)		

<b>FACILITY NAME (1)</b> Indian Point No. 2	<b>DOCKET NUMBER (2)</b> 05000-247	<b>PAGE (3)</b> 1 OF 5
--	---------------------------------------	---------------------------

**TITLE (4)**  
Steam Generators 21 and 24 Classified as Category C-3 per Technical Specification Table 4.13-1

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
03	23	2000	2000	-- 03	-- 00	04	24	2000	FACILITY NAME	DOCKET NUMBER

<b>OPERATING MODE (9)</b>	N	<b>THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)</b>									
<b>POWER LEVEL (10)</b>	O	20.2201(b)	20.2203(a)(2)(v)	50.73(a)(2)(i)	50.73(a)(2)(viii)						
		20.2203(a)(1)	20.2203(a)(3)(i)	X 50.73(a)(2)(ii)	50.73(a)(2)(x)						
		20.2203(a)(2)(i)	20.2203(a)(3)(ii)	50.73(a)(2)(iii)	73.71						
		20.2203(a)(2)(ii)	20.2203(a)(4)	50.73(a)(2)(iv)	X OTHER						
		20.2203(a)(2)(iii)	50.36(c)(1)	50.73(a)(2)(v)	Specify in Abstract below or in NRC Form 366A						
20.2203(a)(2)(iv)	50.36(c)(2)	50.73(a)(2)(vii)									

<b>LICENSEE CONTACT FOR THIS LER (12)</b>	
<b>NAME</b> Richard T. Louie, Nuclear Safety & Licensing	<b>TELEPHONE NUMBER (Include Area Code)</b> 914 734-5678

<b>COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)</b>									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
X	AB	SG	W351	Y					

<b>SUPPLEMENTAL REPORT EXPECTED (14)</b>				<b>EXPECTED SUBMISSION DATE (15)</b>		
X	<b>YES</b> (If yes, complete EXPECTED SUBMISSION DATE).	NO		MONTH	DAY	YEAR
				06	30	2000

**ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)**

On March 23, 2000, Indian Point Unit 2 steam generator inspection results were classified as Category C-3 in accordance with Technical Specification Table 4.13-1. Indian Point Unit 2 was manually shutdown on February 15, 2000 due to the detection of a primary to secondary leak in 24 steam generator. Eddy current inspections of all active steam generator tubes were subsequently initiated following the plant shutdown. On March 23, with approximately 90 percent of the inspections performed, 21 and 24 steam generators were determined to have more than 1 percent of their tubes inspected defective. Per Technical Specification Table 4.13.1, a steam generator would be classified as Category C-3 if more than 10 percent of the total tubes inspected were degraded, or if more than 1 percent of the tubes inspected were defective. The majority of the indications were located at the support plate intersections and at Row 2 U-bend areas. Several improved inspection techniques have been used to assess steam generator tube degradation, including ultrasonic testing and use of high frequency eddy current inspection probes. These inspections are currently ongoing. Recent evaluations have also confirmed that the root cause for the tube failure in 24 steam generator was Primary Water Stress Corrosion Cracking (PWSCC) in the apex of the U-bend region of the tube identified as Row 2 Column 5.

This report is being made per 10 CFR 50.73(a)(2)(ii)(A) as a condition that resulted in the nuclear power plant being in an unanalyzed condition that significantly compromises plant safety. Pursuant to 10 CFR 50.72(b)(2)(I), this condition was reported to the NRC on March 23, 2000.

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Indian Point No. 2	05000-247	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 5
		2000	-- 003	-- 00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

PLANT AND SYSTEM IDENTIFICATION:

Westinghouse 4-Loop Pressurized Water Reactor

EVENT IDENTIFICATION:

Steam Generators 21 and 24 Classified as Category C-3 per Technical Specification Table 4.13-1

EVENT DATE:

March 23, 2000

REFERENCES:

Condition Report (CR) No. 200002049

PAST SIMILAR EVENTS:

None

EVENT DESCRIPTION:

On March 23, 2000, Indian Point Unit 2 steam generator inspection results were classified as Category C-3 in accordance with Technical Specification Table 4.13-1 and a 10 CFR 50.72 notification to the NRC was made.

Indian Point Unit 2 was manually shutdown on February 15, 2000 due to the detection of a primary to secondary leak in 24 steam generator. Eddy current inspections of all active steam generator tubes were subsequently initiated following the plant shutdown. On March 23, with approximately 90 percent of the inspections completed, steam generators 21 and 24 were determined to have more than 1 percent of the tubes inspected defective. Per Technical Specification Table 4.13.1, a steam generator would be classified as Category C-3 if more than 10 percent of the total tubes inspected were degraded, or if more than 1 percent of the tubes inspected were defective. The majority of the indications were located at the support plate intersections and at row 2 U-bend areas.

On March 31, 2000, a 50.72 follow-up notification regarding the status of in-situ pressure testing on 24 steam generator was made. Although originally reported as a failure of the three-delta pressure requirement, subsequent review of test data concluded that the required performance criteria were met. This testing is required to support preparation of the Condition Monitoring Operational Assessment.

Currently both eddy current inspections and in-situ pressure testing of the steam generators remain in progress.

**LICENSEE EVENT REPORT (LER)**  
**TEXT CONTINUATION**

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Indian Point No. 2	05000-247	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 5
		2000	-- 003	-- 00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

EVENT ANALYSIS:

This report is provided in accordance with Technical Specification Table 4.13-1 which requires NRC notification if more than one steam generator is classified as Category C-3. On March 23, 2000, eddy current inspection results on 21 and 24 steam generators were determined to be Category C-3. In 21 steam generator, a total of 41 indications (40 at the support plate intersections and 1 in the U-bend) were detected. In 24 steam generator, a total of 39 indications (36 at the support plate intersections and 3 in the U-bend) were detected. 100 percent eddy current tube examinations of all active steam generator tubes are currently being conducted.

Degradation Assessment

The following active degradation mechanisms were previously identified at Indian Point 2:

- 1) Denting at TSP (tube support plate) intersections
- 2) Pitting in the sludge pile region at the TTS (top of tubesheet)
- 3) VOL (volumetric) indications in the sludge pile region
- 4) PWSCC in the roll expanded regions
- 5) PWSCC and ODSCC at the TSP intersections
- 6) ODSCC in the tube crevice region
- 7) PWSCC in Row 2 U-bends
- 8) Tube wear at AVB (anti-vibration bar) intersections

Primary Water Stress Corrosion Cracking (PWSCC) in the Row 2 U-bend region was first observed during the 1997 examinations. The location of the primary to secondary leakage in 24 steam generator was determined to be at the U-bend apex of the Row 2 Column 5 (R2C5) tube. Evaluations have concluded that the root cause of the tube failure was Primary Water Stress Corrosion Cracking (PWSCC). This conclusion was based upon a review of previous and present eddy current test data, industry experience, and evaluation of the maximum tube stresses consistent with inside diameter cracking. The current inspections have identified additional indications of Outside Diameter Stress Corrosion Cracking (ODSCC) / intergranular attack (IGA) in the tube crevice region. Consequently, the original examination program for this region has been expanded. Data acquisition and analysis currently remains in progress.

A contributing factor which led to the occurrence of the R2C5 tube failure was the inability to detect a relatively large discontinuity during the 1997 inspections. This was principally due to the geometry of the low row U-bends, and to the presence of deposits on the tubes. Review of the 1997 data indicates that background noise in the eddy current signal masked the flaw in the R2C5 tube. Masking of the flaw was due to signal distortion (noise) caused by deposits (magnetite, copper) on the tube end, and potentially, ovalization of the tube. A reduction in this noise level was achieved during the current inspections with the use of a high frequency 800 kHz Plus Point probe.

**LICENSEE EVENT REPORT (LER)**  
**TEXT CONTINUATION**

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
Indian Point No. 2	05000-247	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 5
		2000	-- 003	-- 00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

**Stress Evaluations**

A preliminary analysis of the low row U-bends, R2, R3 and R4, was initiated with the objective to evaluate the sensitivity of the tube stresses to pinching of the straight legs resulting from hourglassing of the tube support plate flowslots. The results of this analysis support the observation that the leak is due to PWSCC at the apex of the tube, since the point of maximum predicted stress is at the apex of the extrados of the tube. The stress results also indicate that Row 3 tubes are expected to be less susceptible to PWSCC due to the larger TSP displacement required to reach the maximum stress condition, and because of the lower displacement of the tube legs due to TSP hourglassing as compared to the Row 2 tubes.

**Inspection Techniques**

Several improved inspection techniques have been used to assess steam generator tube degradation and to establish corrective actions to reduce the probability of future tube degradation. These techniques include the qualification and use of a high frequency, 800 kHz Plus Point probe to supplement the conventional Plus Point low row U-bend examinations, ultrasonic testing of select sludge pile indications, stress analysis modeling of the upper tube support plate and U-bend area, and the installation of new hillside ports in 21 and 24 steam generators to further evaluate degradation at the sixth tube support plate.

**Pluggable Tube Summary**

Based upon the inspection results conducted to date, the total number of additional pluggable tubes is approximately 465. This represents an overall average plugging equivalent of 15 percent. The overall average percent plugging equivalent following the 1997 inspection was 10.2 percent. Pending completion of the current inspections, additional tubes may be designated for plugging.

**Condition Monitoring Operational Assessment**

This assessment is currently being developed and when finalized, a summary of its results will be provided in a supplement to this report.

**EVENT SAFETY SIGNIFICANCE:**

This report is being submitted in accordance with Technical Specification Table 4.13-1 which requires NRC notification if more than one steam generator is classified as Category C-3. The actual safety consequences and implications of this required notification are not significant. Based upon the analysis of data collected during the current inspections, an assessment of the plant's steam generators, including degradation mechanisms, will be performed. A summary of the results of the Condition Monitoring Operational Assessment will be provided in a supplement to this report.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Indian Point No. 2	05000-247	2000	-- 003	-- 00	5 OF 5

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

CORRECTIVE ACTION:

In accordance with Indian Point Unit 2 Technical Specification 4.13, steam generator tubes not considered acceptable for continued service shall be plugged or repaired. A comprehensive report detailing the results of the current examinations, including corrective actions, will be submitted to the NRC in accordance with Technical Specification 4.13.C.2.