

Lew W. Myers Senior Vice President Beaver Valley Power Station P.O. Box 4 Shippingport, PA 15077-0004

> 412-393-5234 Fax: 724-643-8069

May 23, 2000 L-00-066

Beaver Valley Power Station, Unit No. 1 Docket No. 50-334 License No. DPR-66 LER 99-012-01

United States Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Licensee Event Report supplement is submitted:

LER 99-012-01, 10 CFR 50.73(a)(2)(i), "Inoperability of Loop 1 Over Temperature Delta Temperature Function and Resulting Non-Compliance with Technical Specification 3.3.1.1, Table 3.3-1, ACTION 7, Item a."

This supplement provides more detail on this event.

Mars. Rearran for

Lew W. Myers

Attachment



LER 99-012-01 L-00-066 Page 2

 cc: Mr. H. J. Miller, Regional Administrator United States Nuclear Regulatory Commission Region 1 475 Allendale Road King of Prussia, PA 19406

Mr. D. S. Collins BVPS Project Manager United States Nuclear Regulatory Commission Washington, DC 20555

Mr. David M. Kern BVPS Senior Resident Inspector United States Nuclear Regulatory Commission

Mr. J. A. Hultz Ohio Edison Company 76 S. Main Street Akron, OH 44308

INPO Records Center 700 Galleria Parkway Atlanta, GA 30339-5957

Mr. L. E. Ryan Bureau of Radiation Protection Department of Environmental Protection RCSOB-13th Floor P.O. Box 8469 Harrisburg, PA 17105-8469

Manager, Nuclear Licensing and Operations Support Virginia Electric & Power Company 5000 Dominion Blvd. Innsbrook Tech. Center Glen Allen, VA 23060

Ms. Mary E. O'Reilly FirstEnergy Legal Department 76 South Main Street Akron, OH 44308

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION (6-1998) LICENSEE EVENT REPORT (LER)						APPROVED BY OMB NO. 3150-0104 EXPIRES 06/30/2001 Estimated burden per response to comply with this mandatory informati collection request: 50 hrs. Reported lessons learned are incorporated into licensing process and fed back to industry. Forward comments regarding burc estimate to the Records Management Branch (T-6 F33), U.S. Nucli										
		(Se di	e reverse f igits/chara	or required Icters for ec	i numbei ach bloc	r of ;k)			Regui Reduc DC 20 contro require	atory ction 0503. of nur ed to	r Commission, Washingtor Project (3150-0104), Office . If an information collecti mber, the NRC may not o respond to, the information	 DC 2055: of Manager on does not conduct or collection. 	5-0001, and ment and B display a c sponsor, an	I to the Paperwork udget, Washington urrently valid OME nd a person is not		
FACILITY	Y NAN	ЛЕ (1)		<u></u>					DOCI		NUMBER (2)		PAGE (3)	>		
	Bea	ver Va	lley Po	ower St	ation	1 Unit	1				05000334		1 (OF 6		
TITLE (4)	I1 No	noperabi on-Compl	lity of iance w	Loop 1 ith Tech	Over T nical	'emperat Specifi	ure l catio	Delta on 3.	Tem 3.1.	ipe:	rature Functi Table 3.3-1,	on and ACTIC	l Resul	lting Item a.		
EVE	INT D	ATE (5)	LE	R NUMBER (5)	REP	ORT D	ATE (7)			OTHER FAC	ILITIES IN\	/OLVED (8)		
MONTH	DAY	YEAR	YEAR SEQUENTIAL REV NUMBER NU			MONTH	DAY	YEA	VR I	FACII N/A	LITY NAME		DOCKET NUMBER			
9	15	99	99	012	01	05	23	200	0	FACII	LITY NAME		DOCKET NUMBER			
OPERAT	ring	1	1 20 220	THIS REPC	ORT IS SUBM	AITTED PURSU/		THE REQU	IREMEN		OF 10 CFR §: (Check of	one or mo	10re) (11)			
POW	· (9)		20.220	3(a)(1)		20.2203(0)(2)(V)			X	50.73(d)(2)(i)		50.73(a)(2)(viii)			
LEVEL (10)	100	20.220	3(a)(2)(i)		20.2203(a)(3)(ii)				50.73(a)(2)(iii)		73.71	u)(2)(X)		
				3(a)(2)(ii)		20.2203(a)	1)(4)				50.73(a)(2)(iv)	. <u></u>	OTHER	!		
			20.2203	20.2203(a)(2)(iii))				50.73(a)(2)(v)					
			20.220	s(a)(2)(IV)		50.36(C)(2	<u>د</u>				50.73(a)(2)(VII)					
	г 	r. s. (Cosgrov	re, Mana	ager]	Licens	ing 	FAILURE D	DESCRIE	BED 1	(724)	-682 	-5203			
CAUS	CAUSE SYSTEM		COMPONENT MANUFACTURER			REPORTABLE TO EPIX	REPORTABLE CAUS TO EPIX CAUS			SYSTEM COMPONEN MANU T			IFACTURER REPORTABL TO EPIX			
YE	YES		SUPPLEMENTAL REPORT EXPECTED ((14)	(14) NO			EXPECTED MO SUBMISSION			DAY	YEAR		
(lf	yes, c	:omplete E)	(PECTED SU	CTED SUBMISSION DATE).			X				DATE (15)	<u> </u>				
ABSTRAC (Tim At 1 Temp the Tech chan cali Loop	r (Limi es r 130 erat N41 nica nel brat 1 (to 1400 span provided hours (OT power r al Speci within tion pro	ces, i.e., appr l are app on 9/16/2 'DT) chan ange dra fication six hou: oblem wi annel bi	oximately 15 s proximate 99, it we nnel had awer, at n (TS) 3 rs, was : th the N stables	ingle-spac e) as dis been 0245 .3.1.1 not me 41C be were t	covered inopera hours o , Table t. Even mch boa ripped,	that ble, n 9/1 3.3 t di: rd D(at)	t the sinc 15/99 -1, t scove elta- 0941	Loo e ca . As o tr ry o Flux hour	p lil ip ccu	1 Over Temper bration and r uch, ACTION 7 the bistable urred during eter. To perm on 9/16/99. T	ature eturn , Item s of a repair it thi herefo	Delta to ser a. of in inor of a s repa ore, at	I rvice of perable air, the t event I		
disc is r The draw tech is a 0.27	over epor inop er, nici ttr: 34 v	ry the T rtable p due to lans (ut buted t volts di	'S requi: er 10 C) Loop 1 (personn) fility no o misrea .rect cu:	red action FR 50.73 OTDT chan el error on-licen ading the rrent (V	on to (a)(2) nnel ro by th sed) d e test DC) wa	trip the (i)(B). esulted e invol- uring t equipm s misre	fror ved : he ca	annel m mis Instr alibr input s 0.2	bis -cal umen atio dig 374	ib tal tal	bles was bein ration of the tion and Cont on 9/15/99. T al voltmeter.	y met. N41 p rol (I he per This	This ower n &C) sonnel occurn	event range l error red when		
The was even to t self disc incl	N41 decl t wa he i -che usse udec	power r ared op is discu nvolved cking t d with d equipm	ange dra erable a ssed wit l I&C teo echniquo I&C teo ment adju	awer was and N41 w th the in chnician es. This hnicians ustment	calib: was rei nvolve s, as LER a: and I intera	rated an turned d I&C to a refre- nd less &C Supe- ctions	nd re to se echn sher ons : rvis(in ge	eturn ervic ician to e learn ors o enera	ed t e, a s. S nsur ed f f bo l.	o s t el: ron th	service, the 1448 hours on f-checking tr their awarene m this event Units. These	Loop 1 9/16/ aining ss of have b discu	OTDT 99. Th was g adequa een ssions	channel nis given ate		

_

•

- -----

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION	<u></u>								
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION									
FACILITY NAME (1)	DOCKET (2)) LER NUMBER (6) PAGE							
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER					
Beaver Valley Power Station Unit 1	05000334	99	012	01	2	OF	6		
TEXT (If more space is required, use additional copies of NRC Form 366, PLANT AND SYSTEM IDENTIFICATION	A) (17)				-				
Beaver Valley Power Station (BVPS) Westinghouse Pressurized Water Reac Reactor Trip System (RTS) {JC} Excore Nuclear Instrumentation Syst Delta-flux Indicator NI-NI-41C {IG/	Unit 1 tor em (NIS) {: XI}	IG}							
Times provided are approximate.							ļ		
INITIAL CONDITIONS									
Unit 1: Mode 1, 100% Reactor Power									
EVENT DESCRIPTION									
At 1134 hours on September 14, 1999 Specification (TS) Table 3.3-1 was Power Range Neutron Flux drawer N41 updating the current flux map data. accordance with Maintenance Surveil "Power Range Neutron Flux Channel N defeated the N41 input to the quadr following redundant inputs to QPTR N44. Due to removal of N41 from se (TSSR) 4.2.4. was entered, which re is within the limit once within 12 thereafter.	, ACTION 7 entered due (channel 1 N41 was r lance Proce 41 Refuelin ant power t remained op rvice, TS S quires ver hours and e	of T e to l) fr remov edure ng Ca cilt perab Surve ifica every	echnical removing om servi ed from 1MSP- 2 libratio ratio (Q le: N42, illance tion tha 12 hour	Reactors ce for service .03-I, n." T PTR). N43, Require t the s	or e, Th anc eme QPT	in 3 ne 1 ent TR			
At 1809 hours (same day), the N41 input to the QPTR was restored in accordance with 1MSP-2.03-I. This was done to allow manual calculation of QPTR to comply with TSSR 4.2.4. In addition, while investigating an indication problem with the N41 delta flux bench board meter, NI-NI-41C, it was (wrongly) suspected that isolation amplifier NM301 {AMP/XI}, Westinghouse Model Number 6065D75G01, in the N41 instrument drawer input to the meter was defective and required replacement.									
The N41 input to the Loop 1 Over Techannel remained inoperable pending amplifier NM301 and the input to th completion of 1MSP-2.03-I. NM301 w	mperature I repair inv e N41C Delt as replaced	Delta volvi: ca-Fl l; ho	Tempera ng isola ux meter wever, N	ture (tion and I-NI-4	OTI 1C)T	L		

NRC FORM 366A (6-1998)	U.S. NUCLEAR REGULATORY COMMISSION							
LICEN	SEE EVENT REPORT (LER) TEXT CONTINUATION							
	DOCKET (2) NUMBER (2)	LER NUMBER (6)				PAGE (3)		
			YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Beaver Val	ley Power Station Unit 1	05000334	99	012	01	3	OF	6
TEXT (If more space is i	required, use additional copies of NRC Form 366	6A) (17)						

EVENT DESCRIPTION (continued)

would not calibrate and remained out of service. In accordance with TSSRs 4.2.1.1 and 4.2.1.2 for determining axial flux difference (AFD), delta flux logging continued with the remaining three operable delta-flux meters NI-NI-42C, 43C, and 44C. In addition, the required actions of TS 3.3.1.1, Table 3.3-1 were exited, with exception of ACTION 7 for OTDT, which remained in effect.

MSP-2.03-I for power range drawer N41 was completed, at 0245 hours on September 15, 1999, the N41 drawer was returned to service and ACTION 7 for OTDT of TS Table 3.3-1 was exited. However, NI-NI-41C would still not calibrate and the indicator remained out of service. Determination of the AFD, in accordance with TSSRs 4.2.1.1 and 4.2.1.2, continued using operable redundant Delta-Flux meters NI-NI-42C, 43C, and 44C.

At 0941 hours on September 16, 1999, the N41 drawer was removed from service and the Loop 1 OTDT bistables were tripped, in accordance with ACTION 7 of TS Table 3.3-1. This was done to permit repair of the NI-NI-41C meter calibration problem. During this repair activity it was discovered, at 1130 hours on September 16, 1999, that the Loop 1 OTDT Reactor Trip System trip function was inoperable when the N41 power range drawer was previously returned to service, at 0245 hours on September 15, 1999. As such, when N41 was returned to service on September 15, 1999, ACTION 7 of TS Table 3.3-1 was unknowingly not met. However, at the time of event discovery, the TS required action to trip the Loop 1 OTDT bistables was already in effect, since 0941 hours, as described above.

It was subsequently determined that the indication problem with NI-NI-41C resulted from mis-calibration of the N41 drawer and did not involve a defective isolation amplifier. The N41 power range drawer was then calibrated and returned to service, the OTDT channel was declared operable and N41 was returned to service, at 1448 hours on September 16, 1999.

REPORTABILITY

TS 3.3.1.1, Table 3.3-1, ACTION 7, Item a. specifies that with the number of OPERABLE OTDT channels one less than the total number of channels (3), POWER OPERATION may proceed provided the inoperable channel is placed in the tripped condition within 6 hours and the MINIMUM CHANNELS OPERABLE (2) requirement is met. Therefore, at 0245 hours on September 15, 1999, when the N41 drawer was returned to service and ACTION 7 of TS Table 3.3-1 was exited, the MINIMUM

NRC FORM 366A (6-1998) U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2) NUMBER (2)		LER NUMBER (5)	I	PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Beaver Valley Power Station Unit 1	05000334	99	012	01	4	OF	6

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

REPORTABILITY (continued)

CHANNELS OPERABLE requirement of the TS table was met. However, the required action of tripping the bistables of the inoperable channel, per Item a. of TS Table 3.3-1 ACTION 7 was not met. This condition existed until the channel bistables were tripped, at 0941 hours on September 16, 1999. This non-compliance with TS requirements is applicable to the 30 day LER reporting criteria of 10 CFR 50.73(a)(2)(i)(B).

CAUSE OF EVENT

The inoperability of the Loop 1 OTDT Reactor Trip System trip function resulted from mis-calibration of the N41 power range drawer due to personnel error by the involved Instrumentation & Control (I&C) technicians (utility non-licensed) during the MSP on September 15, 1999. This occurred during the detector 120% ion current adjustment when the as-found value of 0.2734 volts direct current (VDC) for the as-found input test signal to N41 detector B current meter was misread as 0.2374 VDC. Based upon the use of this misread value, the N41 power range drawer was adjusted and unknowingly returned to service not functioning within calibration tolerance. The indication problem with the N41 delta flux bench board meter also resulted from the mis-calibration of the N41 power range drawer.

The problem with the N41 delta-flux meter, NI-NI-41C, was incorrectly diagnosed by the involved I&C Supervisor (utility non-licensed). This diagnosis was based on the belief (after troubleshooting was performed) that the meter was defective. The problem identified with the meter after the mis-calibration of the N41 power range drawer provided an opportunity to identify the mis-calibration of the drawer prior to restoring the channel to service.

SAFETY IMPLICATIONS

During the time period of approximately 31 hours that the N41 input to the Loop 1 OTDT channel setpoint was inoperable and the channel bistables were not tripped, the other two OTDT channels remained operable and would have functioned to provide the 2-out-of-3 channels needed to accomplish the OTDT function. Therefore, this event had minimal effect on the health and safety of the public.

If it is postulated that another OTDT channel would not have functioned properly during this period, the mis-calibrated OTDT channel would have functioned as follows: when the mis-calibrated N41 power range drawer was returned to service, a false signal between

NRC FORM 366A (6-1998)	U.S. NUCLEAR REGULATORY COMMISSION							
LICEN	SEE EVENT REPORT (LER) TEXT CONTINUATION							
	DOCKET (2)	LER NUMBER (6)				PAGE (3)		
			YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Beaver Val	ley Power Station Unit 1	05000334	99	012	01	5	OF	6

<u>SAFETY IMPLICATIONS</u> (continued)

+12% and +14% was injected into the Loop 1 OTDT setpoint. This false signal would have made the setpoint conservative, in response to a power transient which forced the delta flux in the positive direction, since the channel would trip earlier than designed. However, the channel response to a power transient, which forced the delta flux in the negative direction would be non-conservative since the channel would trip later than designed. In this case, the OTDT setpoint penalty would not have reduced the Loop 1 OTDT setpoint until actual delta flux had reached approximately -35%, which would be outside the allowable setpoint of between -23 and +11%.

The reactor trip system is designed to be diverse and redundant. As such, there are numerous backup and overlapping signals to the OTDT for accidents credited in the Updated Final Safety Analysis Report. Examples of the backup and overlapping signals to OTDT include over power delta temperature, pressurizer pressure and level, steam generator pressure and level, and neutron flux. In response to these accidents, OTDT is typically not the first protection signal encountered. Exceptions to this are a loss of external electrical load and an uncontrolled withdrawal at power with a small reactivity rate of a rod control cluster assembly. These accidents have backup protection from other trip signals.

CORRECTIVE ACTIONS

- 1. This event was discussed with the involved I&C technicians.
- 2. Self-checking training has been given to the involved I&C technicians, as a refresher to ensure their awareness of adequate self-checking techniques.
- 3. This LER and lessons learned from this event have been discussed with I&C technicians and I&C Supervisors of both Units. These discussions included equipment adjustment interactions in general.
- 4. Enhancements to the I&C technician training program regarding peer/self checking techniques will be evaluated and identified enhancements will be incorporated into the training program as part of the systematic approach to training process.

NRC FORM 366A (6-1998) U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2) NUMBER (2)		LER NUMBER ((6)		PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Beaver Valley Power Station Unit 1	05000334	99	012	01	6	OF	6

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

CORRECTIVE ACTIONS (continued)

5. A review of recent BVPS events, including this event, will be performed and lessons learned from the events will be provided to selected personnel. This action is part of an effort to better utilize actual BVPS operating experience to improve the overall performance of the station.

The above actions will be tracked and completed as part of the corrective action program.

PREVIOUS SIMILAR EVENTS

A review of LERS for BVPS Unit 1 and Unit 2 within the past two years, for occurrences attributed to misreading test equipment, did not reveal a previous similar occurrence.