

Richard B. Abbott Vice President Nuclear Engineering Phone: 315.349.1812 Fax: 315.349.4417

June 12, 2000 NMP2L 1970

United States Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

RE: Docket No. 50-410 Licensee Event Report 00-11

Gentlemen:

In accordance with 10 CFR 50.73 (a)(2)(i)(B), we are submitting Licensee Event Report 00-11, "Missed Technical Specification for Primary Containment Integrity Due to a Failure to Revise a Surveillance Procedure After Issuing an Engineering Change Notice."

Very truly yours,

Richard Ballot

Richard B. Abbott Vice President, Nuclear Engineering

RBA/CES/tmk Attachment

cc: Mr. H. J. Miller, NRC Regional Administrator, Region I Mr. G. K. Hunegs, NRC Senior Resident Inspector Records Management

LICENSEE EVENT REPORT (LER) ESTIMAT REQUEST RECORDS COMMISS CISTO DAM						APPROVED OMB NO. 3130-0104 EXPIRES: TIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION QUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE CORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY MMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT												
FACILITY NAME (I) DOCKET NUMBE								r NUMBER	(150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503									
Nine M	Nine Mile Point Unit 2 0500041							0041	0				0	1 OF 04				
TITLE (4) Missed Technical Specification for Primary Containment Integrity Due to a Failure to Revise a Surveillance Procedure After Issuing an Engineering Change Notice																		
EVI	ENT DAT	E (5)		LER N	UMBER	R (6)			REPO	RT DA	.TE(7)		OTHE	R FACILIT	IES INVO	OLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUI NUI	ENTIAL ABER		REVISIO NUMBE	ON M ER	IONTH	DAY	YEAR	FACILI	ГҮ NAME	s	DOCKET NUMBER(S)			
05	12	00	00	1	1		00		06	12	00	N/A					_	
												N/A						
(	OPERATING MODE (9) 1 THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)								(11)									
POWER	e level 100	(10)		b) a)(1)			0.2203(a 0.2203(a	a)(2)(v) a)(3)(i)		$\boxtimes$ 50.73(a)(2)(i) $\square$ 50.73(a)(2)(viii) $\square$ 50.73(a)(2)(ii) $\square$ 50.73(a)(2)(x) $\square$ 50.73(a)(2)(ii) $\square$ 72.71								
$ \begin{array}{ c c c c c c c c } & & & & & & & & & & & & & & & & & & &$			0.2203(a 0.2203(a 0.36(c)(1 0.36(c)(2	a)(3)(1) a)(4) 1) 2)			□ 50.73(a)(2 □ 50.73(a)(2 □ 50.73(a)(2 □ 50.73(a)(2	75.71     OTHER     (Specify in Abstract below and in Text, NRC     Form 366A)										
						L	LICENSE	E CONTA	ACT FOR T	I HIS LE	IR (12)	~ /		1				
NAME											TELEPHONE NUMBER							
Stephen Geier - Manager Unit 2 Engineering							(315) 349-7887											
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																		
CAUSE	ST	ISTEM	COMPONENT MANUFAC- TURER TO EPIX		CA	JSE	SYSTEM COMPON		NENT MANUFAC- TURER		FAC- ER	REPORTABLE TO EPIX						
SUPPLEMENTAL REPORT EXPECTED (14)							EXPECT	ED	мо	ONTH	D	AY	YEAR					
UYES (If yes, complete EXPECTED SUBMISSION DATE)							DATE (15)											

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On May 12, 2000, with the plant at 100 percent power, Niagara Mohawk Power Corporation identified that since initial plant startup, the Primary Containment Isolation Valve 2RHS\*V192 was not being verified closed every 31 days as required by Technical Specification Surveillance Requirement 4.6.1.1.b. Not performing the surveillance requirement resulted in not meeting Technical Specification 3.6.1.1, which requires that primary containment integrity be restored within 1 hour or be in at least hot shutdown within the next 12 hours and in cold shutdown within the following 24 hours.

The cause was that an engineering change notice was not implemented into all affected documents (i.e., the surveillance procedure). An opportunity was missed to identify and correct the deficiency when Niagara Mohawk Power Corporation did not properly address a recommendation from a General Physics audit of containment penetrations.

Valve 2RHS\*V192 was verified locked closed, and the surveillance procedure was revised to include the valve. Also, a General Physics audit of containment penetrations was reviewed for any other additional containment integrity issues.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION			APPROVED OMB NO. 3150-0104 EXPIRES:									
LICENSEE EVEN TEXT CON	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.								TION Y CT			
FACILITY NAME (1)	FACILITY NAME (1) DOCKET NUMBER (2)			LER NUMBER (6) PAGE (3								
			YEAR		SEQUENTIAL NUMBER		REVISION NUMBER					
Nine Mile Point Unit 2	05000410		00	-	11	-	0 0	02	OF	04		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

# I. <u>DESCRIPTION OF EVENT</u>

In 1986, Engineering Change Notice RHS-084 was issued to change the position of Valve 2RHS\*V192 from normally open to normally locked closed. This change made Valve 2RHS\*V192 a containment isolation valve that is required to be verified closed once every 31 days (Technical Specification Surveillance Requirement 4.6.1.1.b). The associated drawing was changed to show the valve locked closed, but Procedure N2-OSP-CNT-M001, "Primary Containment Penetration Verification Test," was not revised to add Valve 2RHS\*V192 to the list of valves required to be verified closed once every 31 days.

In November 1993, an audit of containment penetrations was conducted by General Physics. The audit contained a recommendation to add Valve 2RHS\*V192 to Procedure N2-OSP-CNT-M001. However, Niagara Mohawk Power Corporation (NMPC) failed to implement this recommendation, because the valve was inadvertently missed during the implementation of corrective actions.

On May 12, 2000, with the plant at 100 percent power, NMPC identified that since initial plant startup, the Primary Containment Isolation Valve 2RHS\*V192 was not being verified closed every 31 days as required by Technical Specification Surveillance Requirement 4.6.1.1.b. Not performing the surveillance requirement resulted in not meeting Technical Specification 3.6.1.1, which requires that primary containment integrity be restored within 1 hour or be in at least hot shutdown within the next 12 hours and in cold shutdown within the following 24 hours. After identifying the missed surveillance, the valve position was checked and found locked closed.

# II. CAUSE OF EVENT

The cause was that NMPC did not revise all affected documents when Engineering Change Request RHS-084 was issued (i.e., surveillance procedure). An opportunity was missed to identify and correct the deficiency when NMPC did not properly address a recommendation from a General Physics audit on containment penetrations.

NRC FORM 366A U.S. NUCLEAR REGULATORY COMMISSION			APPROVED OMB NO. 3150-0104 EXPIRES:									
LICENSEE EVEN TEXT CONT	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.											
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6) PA					PAGE (3)	GE (3)				
			YEAR		SEQUENTIAL NUMBER		REVISION NUMBER					
Nine Mile Point Unit 2	05000410		00	-	11	-	00	03	OF	04		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

# III. ANALYSIS OF EVENT

This event is reportable in accordance with 10 CFR 50.73(a)(2)(i)(B), which requires a report for any operation or condition prohibited by the plant's Technical Specifications. Technical Specification Surveillance Requirement 4.6.1.1.b requires that primary containment integrity shall be demonstrated, in part, by verifying, once every 31 days, all primary containment penetrations not capable of being closed by operable containment automatic isolation valves and required to be closed during accident conditions are closed by valves, blind flanges, or deactivated automatic valves secured in position. Valve 2RHS\*V192 is not an automatic isolation valve and the penetration path associated with Valve 2RHS\*V192 must be closed during accident conditions. Since the valve was not verified closed once every 31 days and the action statement for Technical Specification 3.6.1.1 was not met, this is a Technical Specification violation.

The engineering change notice issued in 1986 required the valve to be locked closed. Since initial plant startup, the valve position has been verified closed in accordance with plant procedures after completion of local leak rate tests, during the integrated leak rate test, and during system valve line-ups following the refueling outages.

On May 12, 2000, when the valve position was checked, it was found locked closed. Based on plant procedures and finding the valve locked closed, there is reasonable assurance that Valve 2RHS\*V192 has not been left open or unlocked when required by Technical Specification 3.6.1.1.

NMPC performed a probabilistic risk analysis for this condition and determined that it is non-risk significant.

Based on the information provided above, there were no adverse safety consequences as a result of this event. The missed Technical Specification Surveillance Requirement 4.6.1.1.b did not pose a threat to the health and safety of the general public or plant personnel.

# IV. CORRECTIVE ACTIONS

- 1. NMPC verified that Valve 2RHS\*V192 was locked closed.
- 2. NMPC revised Procedure N2-OSP-CNT-M001 to include Valve 2RHS\*V192 as a locked closed valve whose position is to be verified once every 31 days.
- 3. NMPC reviewed the General Physics audit to determine if any additional containment integrity issues exist. Two potential issues were identified and will be evaluated by June 26, 2000.
- 4. The current design change control process has been significantly enhanced since 1986.

NRC FORM 366A	C FORM 366A U.S. NUCLEAR REGULATORY COMMISSION			APPROVED OMB NO. 3150-0104 EXPIRES:									
LICENSEE EVEN TEXT CON	ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.												
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)					PAGE (3)						
			YEAR		SEQUENTIAL NUMBER		REVISION NUMBER						
Nine Mile Point Unit 2	05000410		00	-	11	-	0 0	04	OF	04			
				•									

TEXT (If more space is required, use additional NRC Form 366A's) (17)

# V. ADDITIONAL INFORMATION

- A. Failed components: none
- B. Previous similar events:

Licensee Event Report 97-14 documents a Technical Specification violation due to a 1994 modification package that did not identify the need to revise the rod sequence control system test procedure. The corrective actions for Licensee Event Report 97-14 consisted of reviewing test procedures for the rod worth minimizer system and other system test procedures where actual plant configuration is used to prove functionality/operability during testing. The corrective action from Licensee Event Report 97-14 would not have identified the missing valve from Procedure N2-OSP-CNT-M001.

C. Identification of components referred to in this license event report:

Components	IEEE 803A Function	IEEE 805 System ID
Primary Containment	N/A	NH
Valve	ISV	NH
Penetration	PEN	NH