

Entergy Operations, Inc. P. O. Box 756 Port Gibson, MS 39150 Tel 601 437 6409 Fax 601 437 2795

William A. Eaton Vice President, Operations Grand Gulf Nuclear Station

July 25, 2000

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: Grand Gulf Nuclear Station Docket No. 50-416 License No. NPF-29 Failure to Comply with Technical Specification 3.0.3 LER 2000-001-00

GNRO-2000/00054

Ladies & Gentlemen:

Attached is Licensee Event Report (LER) 2000-001-00 which is a final report. Should you have any questions or require additional information regarding the contents of this report, please contact the licensing representative listed on the attached LER.

Yours truly,

William ASafn

WAE/MJL

attachments: 1. LICENSEE-IDENTIFIED COMMITMENTS 2. LER 2000-001-00 cc: (See Next Page) July 25, 2000 GNRO-2000/00054 Page 2 of 2

CC:

Ms. J. L. Dixon-Herrity, GGNS Senior Resident (w/a)

Mr. D. E. Levanway (Wise Carter) (w/a)

Mr. L. J. Smith (Wise Carter) (w/a)

Mr. N. S. Reynolds (w/a)

Mr. H. L. Thomas (w/o)

Mr. Ellis W. Merschoff (w/2) Regional Administrator U.S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011

Mr. S. P. Sekerak, NRR/DLPM/PD IV-I (w/2) Attn: ADDRESSEE ONLY U.S. Nuclear Regulatory Commission One White Flint North, Mail Stop O7-D1 11555 Rockville Pike Rockville, MD 20852-2378

ATTACHMENT 1 TO GNRO-2000/00054 LICENSEE-IDENTIFIED COMMITMENTS

Letter #:	GNRO-2000/00054				
		ТҮРЕ			SCHEDULED
	COMMITMENT		ONE- TIME ACTION	CONTINUING CONTINUING COMPLIANCE	COMPLETION DATE (If Required)
necessary to o drain sump m 3.4.7. • 04-1-02- RESPOI • 06-IC-1F DRAIN S FUNCTI • 17-S-06-	procedures reviewed and revise clarify requirements for drywell f onitoring operability to satisfy TS 1H13-P680-4A1-E3, ALARM NSE INSTRUCTION 245-M-0001, DRYWELL FLOO SUMP LEVEL SWITCH ONAL TEST -5, TECHNICAL SPECIFICATI MENTATION LOOP LOGIC	floor S LCO R	YES		N/A
operations shi	event will be discussed with ift personnel to ensure requirem of drywell floor drain monitoring		YES		N/A

(6-1998) LICENSEE EVENT REPORT (LER)							Estimated burder request: 50.0 hrs and fed back to Management Br 20555-0001, au Management an display a current	BY OMB NO. 31 n per response to co . Reported lessons le ndustry. Forward corm anch (T-6 F33), U.S. N Id to the Paperword d Budget, Washington ly valid OMB control ni equired to respond to,	mply with thi arned are inc iments regard luclear Regul k Reduction , DC 20503. umber, the NI	is mandatory info orporated into the ling burden estim atory Commissio Project (3150 If an information RC may not cond	ormation collection licensing process late to the Records n, Washington, DC -0104), Office o collection does no				
FACILITY I	• •									DOCKET NUME	ER (2)	F	PAGE (3)		
	Gulf	Nuclea	r Statio	on, Unit 1		~]0	5000-416		1 (of 7	
TITLE (4) E pilura	a to C	omply	with T	echnical S	nacif	icati	on 3 0 3	2							
				LER NUMBER		icali		, RT DA1	E (7)	1	OTHER FAC	I ITIES IN			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL	REVI		MONTH	DAY	YEAR	FA	CILITY NAME		DOCKET	UMBER	
	L			NUMBER	NUM	BER			ļ		N/A		N/.		
06	28	2000	2000	001	0	n	07	25	2000	11	CILITY NAME		DOCKET N	_	
OPERA	1			1					1	<u>n</u>	• 10 CFR § (Chec	k one or m			
MODE	E (9)	1		20.2201(b)	Ī		20.2203			(50.73(a)(2)(i)		50.73(a)(2)(viii)		viii)	
POW	ER		2	20.2203(a)(2))(i)		20.2203	<u>````````</u>		50.73(a)		5	0.73(a)(2)(×)	
LEVEL	. (10)	100		20.405(a)(1)(20.2203(a)(3)(ii)		50.73(a)	and the second se	73.71				
			2	20.2203(a)(2)	(ii)		20.2203	B(a)(4)		50.73(a)	(2)(iv)		DTHER		
			2	20.2203(a)(2)	(iii)	-	50.36(c)(1)			50.73(a)	(2)(v)	Specify	cify in Abstract below or in NRC Form 366A		
			2	20.2203(a)(2)	(iv)		50.36(c			50.73(a)	(2)(vii)				
						LICE	INSEE CO	NTACT	FOR T	HIS LER (12)					
NAME		arcon/S	onior Li	icensing Sp	ociali	ct				TELEPHONE 601-437	NUMBER (Include A	ea Code)			
Michae									T EAU I	L	D IN THIS REPO	DT (12)			
CAUSE	SYSTE		MPONENT	MANUFAC			REPORTABL		CAUS		COMPONENT		IFACTURER	REPORTABLE	
							TO EPIX							TO EPIX	
														+	
		SUI	PPLEME	I NTAL REPOR		ECTE	D (14)		<u> </u>	EX	PECTED	MONTH	I DAY	YEAR	
SUPPLEMENTAL REPORT EXPECTE YES			······	XN	NO		BMISSION								
				MISSION DATE).	otoby 11	E oinal	L .		an linco		ATE (15)	1			
On	June	28, 20	000 bei	tween 141	0 to ⁻	1424	l, for a p	period	of 14	i minutes,	operators di iting Condition				

3.4.7, specifically Required Action F. Entry into LCO 3.4.7, Required Action F is required if there is no operable Reactor Coolant System (RCS) Leakage Detection Instrumentation. LCO 3.4.7 Required Action F requires immediate entry into LCO 3.0.3 which requires a shutdown to be initiated within one hour. Failure to perform the Technical Specification LCO actions was not discovered until June 29, 2000 at 1745 at which time a Condition Report (CR-GGN-2000-0931) was written and root cause investigation was initiated. The requirements of TS 3.4.5 for Reactor Coolant System (RCS) Operational Leakage were met throughout the event since the remainder of the calculation process for drywell floor drain sump inleakage remained operable throughout this event. The described condition has no effect on core damage frequency as it does not impact potential core damage initiators or any of the systems that would be utilized for mitigation following potential initiators.

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)		LER NUMBER (6	6)	PAGE (3)
		YEAR	SEQUENTIAL	REVISION	
			NUMBER	NUMBER	
Grand Gulf Nuclear Station, Unit 1	05000-416	2000	001	00	2 OF 7

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

A. Reportable Occurrence

On June 28, 2000 between 1410 to 1424 for a period of 14 minutes operators did not recognize the need to take the actions of Technical Specification (TS) Limiting Condition for Operation (LCO) 3.4.7, Required Action F. Required Action F requires immediate entry into LCO 3.0.3. LCO 3.0.3 requires action to be initiated to shutdown within 1 hour. At 1425 the conditions for entry into LCO 3.4.7, Required Action F no longer applied due to realignment of systems. Failure to perform the Technical Specification LCO Required Actions was not discovered until June 29, 2000 at 1745 at which time a Condition Report (CR-GGN-2000-0931) was written and root cause investigation was initiated. It is important to note that the 14-minute period was well within the required shutdown time requirement of one hour as stated for LCO 3.0.3.

This event was considered to be a condition prohibited by the plant's Technical Specifications and therefore is reportable pursuant to 50.73(a)(2)(i)(B).

B. Initial Conditions

At the time of the event the Unit OPERATIONAL CONDITION was MODE 1, Power Operation. Reactor Power was at 100 percent and Reactor Coolant Temperature was 527 degrees Fahrenheit.

C. Description of Occurrence

On June 28, 2000, between 1410 to 1424, all Reactor Coolant System (RCS) Leakage Detection Instrumentation [IJ], as required by TS LCO 3.4.7, was inoperable. LCO 3.4.7 requires three leak detection systems to be operable which include: drywell floor drain sump monitoring, one channel of either drywell atmospheric particulate or atmospheric gaseous monitoring, and drywell air cooler condensate flowrate monitoring.

The drywell air cooler condensate flowrate monitoring system was declared inoperable on May 1, 2000 (LCO#2000-0449). LCO 3.4.7, Condition C, was entered requiring a channel check of drywell atmospheric monitoring on an eight-hour frequency. An engineering evaluation had been initiated per CR-GGN-2000-0601 and initial troubleshooting had not resolved the problem. Additional troubleshooting is planned for RF11 per maintenance action item (MAI) 278052.

The drywell floor drain sump monitoring system was inoperable on June 28, 2000 from about 1100 to 1430 as a result of "LDS Trouble" alarm malfunction. During the time that this alarm malfunctioned, it was not recognized that the drywell floor drain sump monitoring system should have been considered inoperable. Therefore, the appropriate LCO (3.4.7 Condition A) was not entered. Review of possible alarm causes per the alarm response instruction (ARI) indicated that the alarm was not valid. MAI 281073 was initiated at 1233 to identify the problem with "LDS Trouble" alarm (P680-4A1-E3). The reason for the malfunctioning alarm was not known at the time, however, it was suspected to be a multiplexer (MUX) problem. The alarm was entered into the deficient equipment identification log book and a red tape was installed to identify this as a problem alarm.

NRC FORM 366A

(6-1998)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)		LER NUMBER (6)	PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Grand Gulf Nuclear Station, Unit 1	05000-416	2000	001	00	3 OF 7

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Since the "LDS Trouble" alarm has no reflash capability, having this alarm malfunction would have masked any valid alarm signal due to drywell floor drain sump inleakage. The inleakage computer point was not affected, and was checked when the alarm first came in. The requirements of TS 3.4.5 for Reactor Coolant System (RCS) Operational Leakage were met throughout the event. Except for the alarm function, the remainder of the calculation process for drywell floor drain sump inleakage remained operable throughout this event.

The drywell atmospheric particulate and the atmospheric gaseous monitoring fission product monitoring system became inoperable briefly due to surveillance being performed. Surveillance 06-OP-1D23-Q-0001-01 required stroking of valves which caused drywell atmospheric particulate and the atmospheric gaseous monitoring fission product monitoring system to become inoperable for about 14 minutes, requiring entry into LCO 3.4.7, Conditions B and D.

At about 0900 on June 29, 2000, the shift was informed that the "Q" MUX power supply failure, that had been ongoing, had the potential to render the alarm "LDS Trouble" inoperable. At this time, further discussions began regarding the malfunction of an alarm on system operability. After discussions with Licensing, CR-GGN-2000-931 was initiated for a formal evaluation of the issue. Licensing subsequently concluded that the alarm is required for system operability, and that LCO 3.0.3 entry conditions were met on June 28, 2000 between 1410 to 1424. Specifically, failure of the LDS Trouble alarm meant we did not meet the CHANNEL FUNCTIONAL TEST Surveillance Requirement (SR) 3.4.7.2. Failure to meet SR 3.4.7.2 meant the drywell floor drain sump monitoring system was inoperable. Combined with the other inoperable Reactor Coolant System (RCS) Leakage Detection Instrumentation, LCO 3.0.3.

D. Apparent Cause

The apparent cause is procedural guidance was less than adequate to identify the "LDS Trouble" alarm on 1H13P680 as being a Technical Specification required alarm and thus required for OPERABILITY of the drywell floor drain sump monitoring system per TS 3.4.7. In December 1999, an existing LDS Trouble Alarm was tied to a new computer point which monitors drywell floor drain leakage. Use of the LDS Trouble alarm using the new computer point was procedurally addressed, however, the LDS Trouble alarm was not clearly identified as required for TS OPERABILITY.

Two procedures were revised to address the floor drain monitoring requirements, but did not provide enough guidance to lead onshift personnel to recognize that given the equipment status that existed on June 28, 2000, the LDS Trouble alarm was inoperable and LCO 3.4.7 Condition A should have been entered. These procedures are the Alarm Response Instructions and the Drywell Floor Drain Sump Level Switch Functional Test (06-IC-1P45-M-0001). An additional procedure, Technical Specification Instrumentation Loop Logic, is used as an aid in clarifying logic functions and technical specification requirements for plant instrumentation. This procedure had not yet been revised to reflect the new alarm function installed in December 1999.

NRC FORM 366A

(6-1998)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL	REVISION	
			NUMBER	NUMBER	
Grand Gulf Nuclear Station, Unit 1	05000-416	2000	001	00	4 OF 7

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

E. Corrective Actions

Immediate Corrective Actions:

CR 2000-0931 was initiated when it was realized that LCO 3.0.3 conditions were inadvertently entered. Since the entry conditions no longer existed at that time, no actual LCO report was written.

Long Term Corrective Actions:

- The following procedures will be reviewed and revised as necessary to clarify requirements for drywell floor drain sump monitoring operability to satisfy TS LCO 3.4.7.
 - 04-1-02-1H13-P680-4A1-E3, ALARM RESPONSE INSTRUCTION
 - 06-IC-1P45-M-0001, DRYWELL FLOOR DRAIN SUMP LEVEL SWITCH FUNCTIONAL TEST
 - 17-S-06-5, TECHNICAL SPECIFICATION INSTRUMENTATION LOOP LOGIC
- Details of this event will be discussed with operations onshift personnel to ensure requirements for operability of drywell floor drain monitoring are understood.

F. Safety Assessment

The described condition has no effect on core damage frequency as it does not impact potential core damage initiators or any of the systems that would be utilized for mitigation following potential initiators.

G. Additional Information

The applicable Technical Specification pages (3.4-16 through 3.4-18) have been attached to this LER for clarification purposes.

Energy Industry Identification System (EIIS) codes are identified in the text within brackets [].

3.4 REACTOR COOLANT SYSTEM (RCS)

3.4.7 RCS Leakage Detection Instrumentation

- LCO 3.4.7 The following RCS leakage detection instrumentation shall be OPERABLE:
 - a. Drywell floor drain sump monitoring system;
 - b. One channel of either drywell atmospheric particulate or atmospheric gaseous monitoring system; and
 - c. Drywell air cooler condensate flow rate monitoring system.

APPLICABILITY: MODES 1, 2, and 3.

ACTIONS

	CONDITION		REQUIRED ACTION	COMPLETION TIME	
Α.	Drywell floor drain sump monitoring system inoperable.		.0.4 is not applicable.		
		A.1	Restore drywell floor drain sump monitoring system to OPERABLE status.	30 days	
Β.	Required drywell atmospheric monitoring system inoperable.	B.1	Analyze grab samples of drywell atmosphere.	Once per 12 hours	

(continued)

ACTIONS ((continued)

	CONDITION		REQUIRED ACTION	COMPLETION TIME
C.	C. Drywell air cooler condensate flow rate monitoring system inoperable.		opplicable when the red drywell atmospheric pring system is rable.	
		C.1	Perform SR 3.4.7.1.	Once per 8 hours
D.	Required drywell atmospheric monitoring system inoperable.	LCO 3	.0.4 is not applicable.	
	AND	D.1	Restore required	20.4
	Drywell air cooler condensate flow rate monitoring system		drywell atmospheric monitoring system to OPERABLE status.	30 days
	inoperable.	<u>OR</u>		
		D.2	Restore drywell air cooler condensate flow rate monitoring system to OPERABLE status.	30 days
Ε.	Required Action and	E.1	Be in MODE 3.	12 hours
	associated Completion Time of Condition A,	AND		
	B, C, or D not met.	E.2	Be in MODE 4.	36 hours
F.	All required leakage detection systems inoperable.	F.1	Enter LCO 3 0.3.	Immediately

.

SURVEILLANCE REQUIREMENTS

		SURVEILLANCE	FREQUENCY
SR	3.4.7.1	Perform CHANNEL CHECK of required drywell atmospheric monitoring system.	12 hours
SR	3.4.7.2	Perform CHANNEL FUNCTIONAL TEST of required leakage detection instrumentation.	31 days
SR	3.4.7.3	Perform CHANNEL CALIBRATION of required leakage detection instrumentation.	18 months

.