J. Barnie Beasley, Jr., P.E.

Vice President Vogtle Project Southern Nuclear Operating Company, Inc.

40 Inverness Center Parkway P.O. Box 1295

Birmingham, Alabama 35201

Tel 205.992.7110 Fax 205.992.0403



January 4, 2001

Docket No.: 50-424

LCV-1504

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

> VOGTLE ELECTRIC GENERATING PLANT LICENSEE EVENT REPORT 1-2000-04 PROCEDURE INADEQUACY LEADS TO REACTOR TRIP DURING SURVEILLANCE TESTING

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73, Southern Nuclear Operating Company hereby submits a Vogtle Electric Generating Plant licensee event report for a condition that occurred on Unit 1 on December 9, 2000.

Please contact this office if you have any questions.

Sincerely,

. D. Beasicy, Jr.

JBB/BHW

Enclosure: LER 1-2000-04

cc: Southern Nuclear Operating Company

Mr. J. T. Gasser Mr. M. Sheibani

SNC Document Management

U. S. Nuclear Regulatory Commission

Mr. L. A. Reyes, Regional Administrator

Mr. Ramin R. Assa, Vogtle Project Manager, NRR

Mr. J. Zeiler, Senior Resident Inspector, Vogtle

IFDA

| LICENCEE SVENT DEPORT (LER) | | | | | | info into rega | APPROVED OMB NO. 3150-0104 EXPIRES: 06/30/2001 Estimated burden per response to comply with this mandatory information request: 50 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Forward comments regarding burden estimate to the Records Management Branch (T-6 F33), U.S. Nuclear Regulatory Commission, Washington, DC 20555- | | | | | | | | | | | | | | | | | | | | |
|--|---|-------------------|------------------|-------------|----------------------|----------------------|---|--|---------------------|------------|----------------|---------|--------|----------|---------|---------------|-------|---------|--------|-------|------|-------|------------------|---------|----------|-------------------|------------|
| (See reverse for required number of digits/characters for each block) Ma | | | | | | | Mar coll NR | 0001, and to the Paperwork Reduction Project (3150-0104). Office of Management and Budget, Washington, DC 20503. If an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection. | | | | | | | | | | | | | | | | | | | |
| FACILITY NAME (1) | | | | | | Ю | DOCKET NUMBER (2) PAGE | | | | AGE (3) | H | | | | | | | | | | | | | | | |
| | e Electr | ic C | Gen | eratin | g Plant | Un | it 1 | | | | | | | | | 0 | 5 | 0 | 0 | 0 | 4 | 2 | 4 | 1 | OI | - | 4 |
| PROC | EDUR | ΕΠ | ٧A | DEQU | J ACY L I | EAI | OS ' | ТО | REA | C 7 | TOR TR | IP I | DUI | RIN | G S | UR | VI | EIL | LA | N | CE | TE | S | ΓΙΝ | G | | |
| EVEN MONTH DA | T DATE (5) | | Ę | LEF YEAR | R NUMBER (6) | DEVIC | ION I | | REPORT | DA | TE (7) YEAR | FAC | II ITV | NAME | | 0 | THE | R FA | CILITI | ES II | NVOL | | | IMPE | | | |
| MONTH | TEAT | ` | - | TEAR | SEQUENTIAL NUMBER | REVIS NUMB | ER | MONT | n DAT | L | TEAN | FAC | ILII 1 | NAME | | DOCKET NUMBER | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | 0 | 5 | 0 | 0 | 0 | | |
| 1 2 0 | 9 2 0 0 | 0 (| 2 (| 0 0 0 | 0 0 4 | 0 | 0 | | | | | FACI | ILITY | NAME | | | | | | | 0 | 5 | 0 | 0 | 0 | | |
| OPERATIN | G | | T | HIS REPOR | RT IS SUBMITTE | ED PU | RSUA | NT TO | THE RE | QUI | REMENTS OF | 10 CF | R •: | (Check | one c | r mo | re) (| (11) | | | | | | | | | |
| MODE (9) | 1 | | _ | 20.2201(| b) | | | 2 | 20.2 203 (a |)(2) | (v) | | | 50.73 | 3(a)(2) | (i) | | | | | 1 | 50. | 73(a | a)(2)(v | ii) | | |
| POWER 20.2203(a)(1) | | | 20.2203(a)(3)(i) | | | 50.73 | 50.73(a)(2)(ii) | | | | 50.73(a)(2)(x) | | | | | | | | | | | | | | | | |
| LEVEL (10) 1 0 0 20.2203(a)(2)(i) | | 20.2203(a)(3)(ii) | | | | 50.73(a)(2)(iii) 73 | | | | 73.7 | 73.71 | | | | | | | | | | | | | | | | |
| | | | | 20.2203(| a)(2)(ii) | | | 2 | 20.2203(a |)(4) | | | X | 50.73 | 3(a)(2) | (iv) | | | | | | ОТ | HEF | 3 | | | |
| 11 | | ٠٠.: <u>ا</u> | | 20.2203(| a)(2)(iii) | | | 5 | 50. 36(c) (1 |) | | | | 50.73 | 3(a)(2) | (v) | | | | | | Spe | ecity | in Ab | stract l | pelow | |
| | | | | 20.2203(| a)(2)(iv) | | | 5 | 50.36(c)(2 | !) | | | | 50.73 | 3(a)(2) | (vii) | | | | | | or in | NR | C Forn | 366A | | |
| | | | | | | | | LI | CENSEE | CO | NTACT FOR | THIS LI | ER (12 | 2) | | | | , | | | | | _ | | | | |
| NAME | | _ | | | | | | ~ ^ | | | ~ 1. | | | | | | | 鬥 | | | | | | de are | a code | |) 9 |
| | | <u> </u> | 1eh | idi She | eibani, Ni | | | | | _ | | | | | | | | <u></u> | 0 | 0 | | 0 4 | ے | 0 . | | | <i>J</i> 9 |
| | 1 | | | | COMPLET | E ON | | | | OMI | PONENT FAIL | URE D | ESCR | RIBED II | N THIS | REF | ORT | (13) | | | 1 | | | | | | |
| CAUSE | SYSTEM | CC | OMPC | ONENT | MANUFACTUR | RER | | PORT TO EF | | | | | CAUS | SE | SYST | ЕМ | C | OMP | ONEN | ΝT | MAN | NUFA | CTU | IRER | | PORTAI TO EPI) | |
| | | | | | | Ì | | | • | | 144 | ŀΓ | | | | | | | | | | | | | | | |
| | | | | | | | | - | | | 34.14 | | | | | | | | | | | | | | | | |
| | · | | | St | JPPLEMENTAL | REPO | RT E | (PECT | ED (14) | | | | | | | Г | EXI | PEC1 | ED | | MON | νTH | | PΑΥ | | YEAR | |
| YES (II | YES (If yes, complete EXPECTED SUBMISSION DATE) X NO SUBMISSIC DATE (15 | | | | | | | | | X | NO | | | | | | | | | | | | | | | | |

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-space typewritten lines) (16)

On December 9, 2000, plant personnel were conducting a test of the solid state protection system (SSPS), Train B, per procedure 14421-1, "Solid State Protection System And Reactor Trip Breaker Train B Operability Test." The Balance of Plant operator (BOP) proceeded through the procedure steps in an orderly fashion to section 5.3. When the BOP performed step 5.3.1, "PLACE the MEMORIES Switch to Position 9," an automatic reactor trip occurred at 1015 EST.

The root cause of this event was a procedure inadequacy. A recent change to procedure 14421-1 had moved a portion of the testing from procedure section 5.8 to section 5.3. However, this change bypassed a procedure step to place the Input Error Inhibit switch in the "Inhibit" position, which had previously been performed prior to beginning the section 5.8 testing. The failure to place this switch into "Inhibit" allowed the reactor trip test signals to enter SSPS trip logic and complete an actual reactor trip. Procedure 14421-1 was revised to move the section 5.3 testing back to section 5.8 and testing was completed satisfactorily.

| NRC | FORM | 366A |
|-------|------|------|
| (6-19 | 98) | |

U.S.NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| FACILITY NAME (1) | DOCKET NUMBER (2) | | PAGE (3) | | |
|---|-------------------|---------|----------------------------|--------|--|
| | | YEAR | SEQUENTIAL REVISION NUMBER | | |
| Vogtle Electric Generating Plant - Unit 1 | 05000424 | 2 0 0 0 | | 2 OF 4 | |

TEXT (If more space is required, use additional copies of NRC Form 366A)(17)

A. REQUIREMENT FOR REPORT

This report is required per 10 CFR 50.73 (a)(2)(iv) because an unplanned actuation of the reactor protection system (RPS) occurred.

B. UNIT STATUS AT TIME OF EVENT

At the time of this event, Unit 1 was in Mode 1 (Power Operation) at 100 percent of rated thermal power. Other than that described herein, there was no inoperable equipment that contributed to the occurrence of this event.

C. DESCRIPTION OF EVENT

On December 9, 2000, plant personnel were conducting testing of the solid state protection system (SSPS), Train B, per procedure 14421-1, "Solid State Protection System And Reactor Trip Breaker Train B Operability Test." The Balance of Plant operator (BOP) proceeded through the procedure steps in an orderly fashion to section 5.3, "SAFETY INJECTION RESET TIMING CIRCUIT TEST." When the BOP performed step 5.3.1, "PLACE the MEMORIES Switch to Position 9," an automatic reactor trip occurred at 1015 EST.

All control rods inserted. The main feedwater system isolated and the auxiliary feedwater (AFW) system actuated as designed. Control room operators throttled flow to the steam generators to control water levels and limit the reactor coolant system's cooldown rate. The unit was stabilized in Mode 3 (hot standby). The NRC Operations Center was notified of this event at 1240 EST.

D. CAUSE OF EVENT

The direct cause of the event was placing the Memories switch to position 9. This allowed reactor trip test signals to process through the SSPS and trip the reactor. The root cause of this event was a procedure inadequacy. A recent change to procedure 14421-1 had moved the SAFETY INJECTION RESET TIMING CIRCUIT TEST from procedure section 5.8 to section 5.3. This was done to accommodate more efficient use of instrument and controls (I&C) personnel. However, this bypassed a procedure step to place the Input Error Inhibit switch in the "Inhibit" position, which had previously been performed prior to beginning the section 5.8 testing. The failure to place this

| NRC | FORM | 366A |
|-------|-------------|------|
| (6-19 | 98) | |

U.S.NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| FACILITY NAME (1) | DOCKET NUMBER (2) | | PAGE (3) | | |
|---|-------------------|---------|----------------------------|------------------|--|
| | | YEAR | SEQUENTIAL REVISION NUMBER | | |
| Vogtle Electric Generating Plant - Unit 1 | 05000424 | 2 0 0 0 | | 3 OF 4 | |
| | 0 | | | 3 4 | |

TEXT (If more space is required, use additional copies of NRC Form 366A)(17)

switch into "Inhibit" allowed the reactor trip test signals to enter SSPS trip logic and complete an actual reactor trip.

Contributing to the procedure inadequacy were failures to:

- 1. Move the steps within the procedure accurately.
- 2. Utilize a departmental technical review.
- 3. Perform an adequate second person review.
- 4. Ensure an adequate procedure change process was being followed per procedural guidance.

E. ANALYSIS OF EVENT

When the automatic reactor trip occurred, the main feedwater system isolated and the auxiliary feedwater system actuated as designed. Control room operators responded properly to control feedwater to the steam generators and stabilize the unit in mode 3. Based on these considerations, there was no adverse effect on plant safety or on the health and safety of the public as a result of this event.

F. CORRECTIVE ACTIONS

- 1) Procedure 14421-1 was revised to move the section 5.3 testing back to section 5.8. Testing was then completed satisfactorily. This and other SSPS testing procedures will be revised by March 22, 2001 to clarify the input error inhibit switch function.
- 2) The requirements and expectations of a quality technical review will be discussed with personnel that write or review procedures by March 31, 2001.
- 3) The procedure review matrix will be updated by March 31, 2001 to ensure that procedures requiring interdepartmental reviews are properly identified.
- 4) The Operations Training Advisory Committee will review the SSPS training segment and make necessary changes by February 22, 2001.

| NRC FORM 3 | 66A |
|------------|-----|
| (6-1998) | |

U.S.NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| FACILITY NAME (1) | DOCKET NUMBER (2) | | PAGE (3) | | |
|---|-------------------|---------|----------------------------|--------|--|
| Vogtle Electric Generating Plant - Unit 1 | | YEAR | SEQUENTIAL REVISION NUMBER | | |
| | 05000424 | 2 0 0 0 | | 4 OF 4 | |

TEXT (If more space is required, use additional copies of NRC Form 366A)(17)

G. ADDITIONAL INFORMATION

- 1) Failed Components: None
- 2) Previous Similar Events: None
- 3) Energy Industry Identification System Code:
 Solid State Protection System JG
 Main Feedwater System SJ
 Auxiliary Feedwater System BA