Bryce L. Shriver Vice President – Nuclear Site Operations PPL Susquehanna, LLC P.O. Box 467, Berwick, PA 18603 Tel. 570.542.3120 Fax 570.542.1477 blshriver@pplweb.com



DEC 2 8 2000

4.2

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Station P1-137 Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION LICENSEE EVENT REPORT 50-388/00-005-00 PLA - 5271 FILE R41-2

Docket No. 50-388 License No. NPF-22

Attached is Licensee Event Report 00-005-00. This event was determined reportable per 10CFR50.73(a)(2)(iv) in that unplanned actuations of Engineered Safety Features occurred due to the loss of the primary power supply to the Division 2 Reactor Protection System power distribution panel when the downstream Electrical Protection Assembly breaker tripped.

Bryce L. Shriver Vice President – Nuclear Site Operations

Attachment

- cc: Mr. H. J. Miller Regional Administrator U. S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406
- cc: Mr. S. L. Hansell Sr. Resident Inspector U. S. Nuclear Regulatory Commission P. O. Box 35 Berwick, PA 18603-0035



NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION APPROVED BY OMB NO. 3150-0104							104								
LICENSEE EVENT REPORT (LER)						ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATION COLLECTION REQUEST: 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (T-6 F33), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON. DC 20555-0001 AND TO THE									
		(S	See reve digits/cl	rse for required haracters for ea	number ch block	of )			PAPERW WASHIN	ORK REDUCT GTON, DC 201	ION PROJECT (3150 503.	0104), OFFI	CE OF MANA	GEMENT AND BUDGET	
FACILITY N/	AME (1)	Stoom		in Station . Us					DOCKE		2)		]	PAGE (3)	
ousque		Jean	relecti	ic Station - Or	111 2					05	000388			1 OF 4	
ESF Act	tuatio	ns Due	To RP	S EPA Breaker	<sup>.</sup> Trip				<u> </u>				<u></u>		
EVEN	IT DATE	E (5)		LER NUMBER (6	)	REPO	RT DAT	E (7)	<u> </u>		OTHER FACILI	TIES INV	OLVED (8	1	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILIT	Y NAME			DOCKET N	UMBER	
12	05	- 00-		005										05000	
12	05	00	00	005	00	12	28	00	FACILIT	Y NAME			DOCKET N		
OPERA	TING		THIS RE	PORT IS SUBMIT	TED PUR	SUANT T	O THE R	EQUIRE	MENT	S OF 10 0	CFR §: (Check	one or n	nore) (11	)	
	(9) CD		20.	2201(b)		20.2203	3(a)(2)(v)			50.73	(a)(2)(i)		50.7	'3(a)(2)(viii)	
LEVEL	(10)	100	20.	2203(a)(1) 2203(a)(2)(i)		20.2203	3(a)(3)(i) 3(a)(3)(ii)			50.73	(a)(2)(ii) a)(2)(iii)		50.7	'3(a)(2)(x)	
			20.:	2203(a){2)(ii)		20.2203	B(a){4)			( 50.73	a)(2)(iv)		отн	ER	
			20.	2203(a)(2)(iii)		50.36(c)	(1)			50.73	a)(2)(v)		Specify in	Abstract below	
			20.:	2203(a)(2)(iv)		50.36(c)	(2)			50.73	a)(2)(vii)		or in Mile	Form SODA	
NAME					LICEN	SEE CON	FACT FO	R THIS	LER (1	2)					
Joseph .	J. Met	ter - Nu	Iclear L							E	570 / 542-18	373			
CAUSE	SY	STEM	COMPON	ENT MANUFACTU	RER REF	PORTABLE	NENT F	CAUS		SYSTEM	THIS REPORT (	13) MANUE	ACTURER	PERCETARI S	
X				6080											
						·									
· · · · · · · · · · · · · · · · · · ·															
		SU	JPPLEME	NTAL REPORT E	XPECTED	(14)		<u> </u>		EXI SUB	ECTED MISSION	MONT	H DA	Y YEAR	
X YES (If yes,	, compl	ete EXPE	CTED SU	JBMISSION DATE	E).		NO			DA	TE (15)	06	15	01	
ABSTRACT	T (Limit	to 1400	) spaces,	i.e., approximate	ly 15 sing	gle-spaced	l typewr	itten lin	es) (16	5)		<u>I</u>			
At 07: React Protect actual function while it signal The protect 12/9/0 cause Engine composite health	00 on cor Pro- ctions a oned p invest s were rimary 0. Th of fai eered onents or sa	Decer Detection Assem and oth Droperl igation e reset v powe le susp lure. T Safety s functi fety of	mber 5 n Syste bly (EF her aut y in re- of the by 08 r source bect fai by 08 r source bect fai he even y Featu the pu	5, 2000 with L em (RPS) power PA) breaker trong omatic system sponse to the event took p took to the event took p took p too	Init 2 in wer dis ipped. minitiat event. lace. lace. stigation ers we am EP. ble und . Since per des	Mode tributior This re tions. F . The "I There w on resu re rese A logic ler 10C e all Eng ign, the	1 at 10 pane sulted RPS as B" dist rere no lted in t and a card w FR50. gineer ere we	00% p I was I in Pr s well ributic repla ligne vas re 73(a) ed Sa re no	oower lost v imary as ot on pai ceme d to th turne (2)(iv) fety F safet	, the pr vhen th v Conta her pla nel was s of abl ont of th ne "B" of d to the in that Feature y conse	imary powe in downstre inment Isol nt systems s swapped f normalities ie downstre distribution e manufactu unplanned (ESF) syst equences of	er supp ation S and co to alter and al am EF panel urer to actua rems a r comp	oly to th ectrical System ompone rnate po rnate po ll isolati PA logic at 18:1 determ tions of nd promise	e "B" ents ower on card. 1 on ine f	

-

NRC FOR	VI 366A
(6-1998)	

#### U.S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT (LER)

TEXT (	CONT	'INUA	TION
--------	------	-------	------

FACILITY NAME (1)	DOCKET LER NUMBER (6)							
	05000	YEAR	SEQUENTIAL NUMBER	NUMBER		···		
Susquehanna Steam Electric Station - Unit 2	388	00	005 -	- 00	2	OF	4	
		JL						

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

# **EVENT DESCRIPTION**

At 07:00 on December 5, 2000 with Unit 2 in Mode 1 at 100% power, the primary power supply to the "B" Reactor Protection System (RPS; EIIS Code: JC) power distribution panel was lost when the downstream Electrical Protection Assembly (EPA) breaker tripped. This power interruption resulted in an RPS Half-SCRAM, Primary Containment Isolation System (EIIS Code: JM) actuations and other automatic system initiations. RPS as well as other plant systems functioned as designed in response to the event. The major actuations were as follows:

- 1) Reactor Building HVAC (EIIS Code: VA) Zone II and Zone III (Unit 2) isolated.
- 2) Reactor Water Cleanup System (EIIS Code: CE) inlet isolation valves closed.
- 3) Cooling water isolation valves to the Reactor Recirculation Pumps (EIIS Code: CC) closed.
- 4) "A" & "B" Standby Gas Treatment Systems (EIIS Code: BH) auto initiated.
- 5) "A" Control Room Emergency Outside Air Supply System (EIIS Code: VI) auto initiated.

The "B" RPS distribution panel was supplied by alternate power while the Operations personnel reset isolation signals and the cause of the trip was investigated. All isolation signals were reset by 08:15. The primary power EPA breakers were reset and aligned to the "B" distribution panel at 18:11 on 12/9/00 after replacement of the downstream EPA logic card.

### CAUSE OF EVENT

The loss of power to the "B" RPS bus was due to an unexpected trip of the downstream primary power supply EPA breaker. The upstream EPA breaker did not trip which is the expected system response. The EPA breakers are in series and a trip of an upstream breaker would cause the downstream breaker to trip also, because of power loss to the downstream breaker. However, a trip of the downstream breaker does not cause the upstream breaker to trip. Investigation by Maintenance personnel (non-licensed, utility) of the downstream EPA logic card and breaker concluded that the trip was caused by an intermittent failure of the downstream EPA logic card which could not be replicated onsite. The voltage of the Unit 2 "B" primary power supply was monitored for anomalies for several days. None were recorded. The downstream logic card was replaced. The suspect card was returned to the manufacturer to determine cause of intermittent failure.

## **REPORTABILITY/SAFETY CONSEQUENCES ANALYSIS**

This event was determined to be reportable under 10CFR50.73(a)(2)(iv) in that unplanned actuations of Engineered Safety Features (ESF) occurred when the Unit 2 "B" primary power supply downstream RPS EPA breaker tripped.

NRC FORM 366A			U.S. NUCLEAR REGULAT	ORY COMMISSION	
LICENSEE EVENT REPORT (LER)					
	TEXT CONT	TINUATION			
FACILITY NAME (1)		DOCKET	LER NUMBER (6)	PAGE (3)	
		05000	YEAR SEQUENTIAL REVISION		

			ELIT ROMDEN	~/	•	AOF (2	,
	05000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Susquehanna Steam Electric Station - Unit 2	388	00	005	00	3	OF	4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

The safety function of the EPA card and breaker assembly is to interrupt power to the RPS buses in the event of overvoltage, undervoltage, or under-frequency conditions. RPS is designed such that a loss of power to the RPS buses results in power loss to other protective logic, which in turn results in plant systems aligning to their safe, conservative positions.

Since all ESF systems and components functioned properly and per design, there were no safety consequences or compromises to the health or safety of the public.

At the time of the event, the reactor was in Mode 1 at 100% power and shutdown cooling was not required. Had this event occurred with the Unit in Cold Shutdown or Refueling, shutdown cooling would have been temporarily lost due to the automatic isolation of the RHR Shutdown Cooling suction line.

In accordance with the guidance provided in NUREG 1022, Revision 1, Section 5.1.1, the required submission date for this report is January 4, 2001.

## **CORRECTIVE ACTIONS**

The following corrective actions for this event have been completed:

The "B" RPS bus was placed on its alternate power supply and all isolations were reset within 1 hour and 15 minutes of the downstream primary supply EPA breaker tripping. An investigation was commenced to determine the cause of the EPA breaker trip. The EPA logic card circuit and trip function of the downstream card was checked and found to be normal. The 'B' RPS Motor-Generator (M/G) set was found in a normal run condition with normal output voltage and the generator output breaker closed. Although an onsite investigation of the downstream EPA logic card did not indicate any failed components, it was concluded that the trip was caused by an intermittent failure on the card that could not be replicated onsite. The suspect card was replaced. The voltage of the Unit 2 "B" primary power supply was monitored for anomalies for several days. None were recorded.

#### The following corrective actions for this event will be completed:

The suspect EPA card was returned to the manufacturer to determine cause of the intermittent failure and the appropriate actions will be taken in response to the manufacturer's evaluation.

### Historical corrective actions:

Approximately 6 years ago, efforts were completed to perform component lifetime upgrades for EPA logic cards with limited lifetimes used at the station. This effort was intended to ensure all EPA logic cards had acceptable component lifetimes to prevent intermittent failures. All EPA cards used at the station since that time either had component upgrades or were new models already containing upgraded components. Concurrent with the EPA card upgrades, modifications to decrease ambient temperatures within the EPA logic card cabinets were also completed to reduce temperature induced failures.

NRC	FORM	366A
(6-1998	3)	

#### U.S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET LER NUMBER (6)					PAGE (3)		
	05000	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				
Susquehanna Steam Electric Station - Unit 2	388	00	005	00	4	OF	4	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

## **ADDITIONAL INFORMATION**

Failed Component Information:

Component - EPA Logic Card

Model - 148C6118G003

Manufacturer - General Electric

Past Similar Events:

A review of past Licensee Event Reports (LERs) for the station identified thirteen previous events where spurious EPA breaker trips resulted in ESF actuations. This is the first event since significant preventative measures were taken to prevent spurious EPA breaker trips.

UNIT 1 (Docket No. 50-387/License No. NPF-14)

LER 92-007	LER 87-024
LER 92-001	LER 86-029
LER 91-006	LER 86-023
LER 91-004	LER 83-172
LER 90-005	

UNIT 2 (Docket No. 50-388/License No. NPF-22)

LER 91-008	LER 90-007
LER 91-007	LER 88-005