



W. R. McCollum, Jr.  
Vice President

**Duke Power**  
Oconee Nuclear Site  
7800 Rochester Highway  
Seneca, SC 29672  
(864) 885-3107 OFFICE  
(864) 885-3564 FAX

January 18, 2001

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555-0001

Subject: Oconee Nuclear Station, Unit 1  
Docket No. 50-269  
Steam Generator Inservice Inspection  
Steam Generator Tube Plugging and Repair 30-day Report

As required by Technical Specification 5.6.8, a, this letter provides the number of tubes plugged or repaired during the Steam Generator (SG) Tube Inservice Inspection for the Unit 1 Cycle 19 refueling outage. One hundred percent (100%) of the Unit 1 SG Tubes were inspected with bobbin coil eddy current testing (ECT) probes, and tubes with indications were subsequently inspected with Motorized Rotating Pancake Coil (MRPC) probes.

There were no tubes repaired by sleeving in either steam generator. No tubes were repaired by reroll in the lower tubesheet. The tables below identify the number of tubes removed from service by plugging and the number of tubes repaired by rerolling in the upper tubesheet.


<u>Steam Generator</u>	<u>Number of Tubes Plugged</u>
A	76
B	154

<u>Steam Generator</u>	<u>Number of Tubes Rerolled</u>
A	75
B	*129

\* 128 of these tubes remain in service, one tube was plugged.

If there are any questions you may contact R. C. Douglas at (864) 885-3073.

Very Truly Yours,

  
W. R. McCollum, Jr.  
Site Vice President

A001

USNRC Document Control Desk  
January 18, 2001

Page 2

cc: Mr. L. A. Reyes  
Regional Administrator, Region II

Mr. M. C. Shannon  
Senior Resident Inspector

Mr. D. E. Labarge  
ONRR, Senior Project Manager

Mr. V. R. Autry  
DHEC