

SEP 19 1975

Distribution:

Docket SVarga  
 NRC PDR CHEbron  
 Local PDR AEsteen  
 ORB#4 rdg DEisenhut  
 OELD Abernathy  
 OI&E (3) ACRS (16)  
 NDube  
 BJones  
 JMcGough  
 JSaltzman  
 RIngram  
 MFairtile  
 RWReid  
 KRGoller  
 SKari  
 WOMiller  
 BScharf  
 TJCarter  
 PCollins

Docket No. 50-333

Power Authority of the State of New York  
 ATTN: Mr. George T. Berry  
 General Manager & Chief Engineer  
 10 Columbus Circle  
 New York, New York 10019

Re: FitzPatrick

Gentlemen:

Cracks have been detected in the collet housings of the control rod drives at Dresden Unit 3, Browns Ferry 1, and Vermont Yankee. The problem appears to be a stress assisted corrosion problem that may be generic to most boiling water reactors. In light of this experience, we believe that appropriate changes to technical specifications for this type reactor are needed that will prohibit extended operation with immovable rods. Accordingly, unless you inform us in writing within 20 days of the date of this letter that you do not agree with this course of action, including your reasons, we plan to initiate steps to issue the enclosed change to the technical specifications of your facility. A copy of our related safety evaluation on this matter is enclosed.

Sincerely,

*(Signature)*

Robert W. Reid, Chief  
 Operating Reactors Branch #4  
 Division of Reactor Licensing

Enclosures:

1. Technical Specifications
2. Safety Evaluation

cc: See next page

*disputed 9/25*

*RC*

	(1)	(2)	(4)	(3)		
OFFICE >	ORB#4	ORB#4 <i>WBF</i>	ORB#4 <i>WBF</i>	OELD		
SURNAME >	<i>Ingram/dg</i>	Fairtile/dg	RWReid	<i>Wallo/dg</i>		
DATE >	9/18/75	9/18/75	9/18/75	9/19/75		

Power Authority of the State  
of New York

cc w/enclosures:

Scott B. Lilly, General Counsel  
Power Authority of the  
State of New York  
10 Columbus Circle  
New York, New York 10019

Arvin E. Upton, Esquire  
LeBoeuf, Lamb, Leiby and MacRae  
1757 N Street, NW.  
Washington, D. C. 20036

Lauman Martin, Esquire  
Senior Vice President  
and General Counsel  
Niagara Mohawk Corporation  
300 Erie Boulevard West  
Syracuse, New York 13202

Mr. Z. Chilazi  
Power Authority of the  
State of New York  
10 Columbus Circle  
New York, New York 10019

J. Bruce MacDonald, Deputy  
Commissioner and Counsel  
New York State Department of  
Commerce and Counsel to the  
Atomic Energy Council  
99 Washington Avenue  
Albany, New York 12210

Ecology Action  
c/o Richard Goldsmith  
Syracuse University  
College of Law  
E. I. White Hall Campus  
Syracuse, New York 13210

Ms. Suzanne Weber  
R.D. #3, West Lake Road  
Oswego, New York 13126

Oswego City Library  
120 East Second Street  
Oswego, New York 13126

Mr. Robert P. Jones, Supervisor  
Town of Scriba  
R. D. #4  
Oswego, New York 13126

Mr. Alvin L. Karkau  
Chairman, County Legislature  
County Office Building  
46 East Bridge Street -  
Oswego, New York 13126

cc w/enclosures & incoming:  
Dr. William E. Seymour  
Staff Coordinator  
New York State Atomic Energy  
Council  
New York State Department of  
Commerce  
112 State Street  
Albany, New York 12207

Mr. Paul Arbesman  
Environmental Protection Agency  
26 Federal Plaza  
New York, New York 10007

Anthony Z. Roisman, Esquire  
Berlin, Roisman & Kessler  
1712 N Street, NW  
Washington, D.C. 20036

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

SAFETY EVALUATION BY THE OFFICE OF NUCLEAR REACTOR REGULATION

SUPPORTING AMENDMENT TO LICENSE NO. DPR-59

AND

CHANGES TO THE TECHNICAL SPECIFICATIONS

INOPERABLE CONTROL ROD LIMITATIONS

POWER AUTHORITY OF THE STATE OF NEW YORK

NIAGARA MOHAWK POWER CORPORATION

JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

INTRODUCTION

On June 27, 1975, Commonwealth Edison Company (CE) informed NRC that cracks had been discovered on the outside surface of the collet housings of four control rod drives at Dresden Unit 3<sup>(1)</sup>. The cracks were discovered while performing maintenance of the control rod drives; the reactor was shutdown for refueling and maintenance. In a letter dated July 3, 1975, CE informed us that if the cracks propagated until the collet housing failed, the affected control rod could not be moved<sup>(2)</sup>. In a meeting with representatives of General Electric (GE) and CE we were advised that further inspections revealed cracks in 19 of the 52 Dresden 3 control rod drives inspected, in one spare Dresden 2 control rod drive, in one Vermont Yankee spare control rod drive and in two GE test drives<sup>(3)</sup>. In a report dated July 30, 1975, after additional rod drives were inspected, CE stated that cracks had been found in 24 of 65 drives inspected<sup>(4)</sup>. Recently, the Tennessee Valley Authority reported that cracks were found in the collet housing of

- (1) Telegram to J. Keppler, Region III of the NRC, June 27, 1975, Docket No. 50-249.
- (2) Letter from B. B. Stephenson, Commonwealth Edison Company to James G. Keppler, U. S. Nuclear Regulatory Commission, July 3, 1975, Docket No. 50-249.
- (3) Memo from L. N. Olshan, Division of Technical Review (DIR) to T. M. Novak, DIR, "Meeting on Cracks Found in Dresden 3 Control Rod Drive Collet Retainer Tubes," July 18, 1975.
- (4) Letter from B. B. Stephenson, Commonwealth Edison Company to James G. Keppler, U. S. Nuclear Regulatory Commission, July 30, 1975, Docket No. 50-249.

seven of nineteen drives inspected at Browns Ferry 1 and Vermont Yankee found cracks in the collet housing of 4 of 10 control rod drives inspected. Because a number of control rod drives have been affected, because complete failure of the drive collet housing could prevent scram of the affected rod, and because we do not consider existing license requirements adequate in view of the collet housing cracks experienced, we have concluded that the Technical Specifications should be changed for those reactors with control rod drive designs susceptible to collet housing cracks. The change should assure that reactors which could be affected would not be operated for extended periods of time with a control rod which cannot be moved.

#### DESCRIPTION

The control rod drive is a hydraulically operated unit made up primarily of pistons, cylinders and a locking mechanism to hold the movable part of the drive at the desired position. The movable part of the drive includes an index tube with circumferential grooves located six inches apart. The collet assembly which serves as the index tube locking mechanism contains fingers which engage a groove in the index tube when the drive is locked in position. In addition to the collet, the collet assembly includes a return spring, a guide cap, a collet retainer tube (collet housing) and collet piston seals. The collet housing surrounds the collet and spring assembly. The collet housing is a cylinder with an upper section of wall thickness 0.1 inches and a lower section with a wall thickness of about 0.3 inches. The cracks occurred on the outer surface of the upper thin walled section near the change in wall thickness.

#### 1. Consequences of Cracking

The lower edges of the grooves in the index tube are tapered, allowing index tube insertion without mechanically opening the collet fingers, as they can easily spring outward. If the collet housing were to fail completely at the reported crack location, the coil collet spring could force the upper part of the collet housing and spring retainer upward, to a location where the spring and spring retainer would be adjacent to the collet fingers. The clearance between the collet fingers and the spring when in this location will not permit the collet fingers to spring out of the index tube groove. This would lock the index tube in this position so that the control rod could not be inserted or withdrawn.

The failure of some control rods to operate has previously been evaluated and the Technical Specifications presently allow a limited number of rods, as discussed later in Section 4, to be inoperable. If more than these rods are inoperable or if the scram reactivity rate is too small or if shutdown reactivity requirements are not met, the existing Technical Specifications require the reactor to be brought to a cold shutdown condition. Reactor power operation with these rods inoperable would not involve a new hazards consideration nor would it endanger the health and safety of the public.

## 2. Probable Cause of Cracking

The cause of the cracking appears to be a combination of thermal cycling and intergranular stress corrosion cracking. The thermal cycling results from insertion and scram movements. During these movements hot reactor water is forced down along the outside of the collet housing, while cool water is flowing up the inside and out of flow holes in the housing. These thermal cycles are severe enough to yield the material, leaving a high residual tensile stress on the outer surface.

The collet housing material is type 304 austenitic stainless steel. The lower portion of the collet housing has a thicker wall and its inner surface is nitrided for wear resistance. In 1960-61, similar drives using high hardness 17-4 PH material for index tubes and other parts were found to have developed cracks. The problem caused GE to switch to nitrided stainless steel. The nitriding process involves a heat treatment in the 1050 F to 1100 F range, which sensitizes the entire collet housing, making it susceptible to oxygen stress corrosion cracking.

The cooling water used in the drives is aerated water. This water contains sufficient oxygen for stress corrosion to occur in the sensitized material if it is subjected to the proper combination of high stresses and elevated temperatures.

We believe that the cracking is caused by a combination of thermal fatigue and stress corrosion. GE has determined that both full stroke insertion and scram will cause high thermal stress. The cracks are completely intergranular and extensively branched, indicating that corrosion is a major factor. The type of thermal cycling, plus the buildup of corrosion products in the cracks between cycles probably results in a ratcheting action. This is also indicated by the "bulged" appearance of the cracks on the OD.

### 3. Probability of Early Failure

We believe that the cracking is progressive and is cycle dependent. Although the details of the cracking process are still not clear, we have not identified any mechanism that would cause rapid cracking with progression to complete circumferential failure.

The axial loads on the housings are very low at all times so that through wall cracks would have to progress at least 90% around the circumference before there would be concern about a circumferential failure. Although one housing at Dresden 3 had three cracks which nearly joined around the circumference, no cracks at Dresden 3 were through wall and none of the housings examined approached the degree of cracking necessary for failure. The collet housing has three flow holes in the thin section equally spaced around the circumference. The observed cracks have been confined primarily to the areas below and between the holes and near the area where the wall thickness of the collet housing changes. Since all the cracks except those located at the change in wall thickness are fairly shallow and since those at the change in wall thickness are largely confined to the circumferential area between holes, the net strength of the cracked housings is still far greater than necessary to perform their function.

A test drive at GE that had experienced over 4000 scram cycles had a more extensive developed crack pattern. Although the satisfactory experience with this cracked test housing is encouraging, its performance may not be correlated directly to that of drives in service, as this test drive was subjected to lower temperatures, and possibly less severe thermal cycles than could be encountered in actual service. The cracks were first noticed on the test drive after about 2000 cycles - many more cycles than the cracked housings at Dresden 3 had experienced.

The chance that a large number of collet housing would fail completely at about the same time is very remote. This is primarily true because the distributions of failures by cracking mechanisms such as stress corrosion and fatigue are not linear functions. That is, failure is a function of log time or log cycles. Distribution of failures of similar specimens generally follow a log normal pattern, with one to two orders of magnitude in time or cycles between failures of the first and failures of the last specimen. As no collet housing has yet failed, we are confident that there would be very few, if any, failures during the next time period corresponding to the total service life to date.

#### 4. Changes to Technical Specifications

Existing limiting conditions of operation allow operation to continue with up to one inoperable control rod in any 5 x 5 array. Existing surveillance requirements specify that daily surveillance of the condition of all fully or partially withdrawn rods would not have to begin until three rods are found inoperable. The surveillance requirements also specify that if it is determined that a control rod cannot be inserted, the reactor shall be brought to a Cold Shutdown Condition within 24 hours to perform a shutdown margin test. If the shutdown margin requirements are determined to be met the reactor may be returned to operation with the rod which is incapable of being inserted. We do not consider that these existing requirements sufficiently limit the possibility of operating for an extended period of time with a number of rod drive mechanisms which cannot be moved. We have therefore concluded that the Technical Specifications should be changed as discussed below.

One stuck control rod does not create a significant safety concern. However, if a rod cannot be moved and the cause of the failure cannot be determined, the rod could have a failed collet housing. A potentially failed collet housing would be indicative of a problem which could eventually affect the scram capability of more than one control rod. Since the cracks appear to be of a type which propagate slowly, it is highly unlikely that a second control rod would experience a failed collet housing within a short period of time after the first failure. Therefore, Section 3.3.A.2 (Reactivity Margin Inoperable Control Rods)

should be expanded to preclude reactor startup and/or continued power operation with a partially or fully withdrawn control rod which cannot be moved with drive or scram pressure, unless (1) investigation has demonstrated that the cause of the failure is not a failed control rod drive mechanism collet housing, and (2) adequate shutdown margin has been demonstrated.

Until permanent corrective measures are taken to resolve the potential for stuck control rods due to failed collet housings, we believe that these additional specifications provide reasonable assurance that an unacceptable number of control rod collet housing will not fail during

operation. Upon completion of the investigations being performed by GE, additional corrective actions may permit revision of these requirements.

CONCLUSION

We have concluded, based on the considerations discussed above, that: (1) there is reasonable assurance that the health and safety of the public will not be endangered by operation in the proposed manner, and (2) such activities will be conducted in compliance with the Commission's regulations and the issuance of this amendment will not be inimical to the common defense and security or to the health and safety of the public.

Dated: SEP 19 1975



- a. Control rods which cannot be moved with control rod drive pressure shall be considered inoperable. If a partially or fully withdrawn control rod drive cannot be moved with drive or scram pressure, the reactor shall be brought to the Cold Shutdown condition within 24 hours and shall not be started unless (1) investigation has demonstrated that the cause of the failure is not a failed control rod drive mechanism collet housing, and (2) adequate shutdown margin has been demonstrated as required by Specification 4.3.A
- b. The control rod directional control valves for inoperable control rods shall be disarmed electrically.
- c. Control rods with scram times greater than those permitted by Specification 3.3.C.3 are inoperable, but if they can be inserted with control rod drive pressure they need not be disarmed electrically.

- a. Each partially or fully withdrawn operable control rod shall be exercised one notch at least once each week when operating above 50 percent power. In the event power operation is continuing with three or more inoperable control rods, this test shall be performed at least once each day, when operating above 50 percent power.
- b. A second licensed operator shall verify the conformance to Specification 3.3.A.2.d before a rod may be bypassed in the Rod Sequence Control System.
- c. Once per week check status of pressure and level alarms for each accumulator.

d. Control rods with a failed "Full-in" or "Full-out" position switch may be bypassed in the Rod

Sequence Control System and considered operable if the actual rod position is known. These rods must be moved in

d. When it is initially determined that a control rod is incapable of normal insertion, an attempt to fully insert the control rod shall be made. If the control rod cannot be fully inserted  $\sigma$

shutdown margin test shall be made to demonstrate under this condition that the core can be made sub-critical for any reactivity condition during the remainder of the operating cycle with the analytically determined, highest worth control rod capable of withdrawal, fully withdrawn, and all other control rods capable of insertion fully inserted. If Specification 4.3.A.1 is met, reactor startup may proceed.

sequence to their correct positions (full in on insertion and full out on withdrawal).

- e. Control rods with inoperable accumulators or those whose position cannot be positively determined shall be considered inoperable.
  
- f. Inoperable control rods shall be positioned such that Specification 3.3.A.1 is met. In addition, during reactor power operation, no more than one control rod in any 5 x 5 array may be inoperable (at least 4 operable control rods must separate any 2 inoperable ones). If this specification cannot be met the reactor shall not be started, or if at power, the reactor shall be brought to a cold condition within 24 hr.

the control cell geometry and local  $k_{\infty}$ . Therefore, an additional margin is included in the shutdown margin test to account for the fact that the rod used for the demonstration (the analytically strongest) is not necessarily the strongest rod in the core. Studies have been made which compare experimental criticals with calculated criticals. These studies have shown that actual criticals can be predicted within a given tolerance band. For gadolinia cores the additional margin required due to control cell material manufacturing tolerances and calculational uncertainties has experimentally been determined to be 0.38%  $\Delta k$ . When this additional margin is demonstrated, it assures that the reactivity control requirement is met.

## 2. Reactivity Margin - Inoperable Control Rods

Specification 3.3.A.2 requires that a rod be taken out of service if it cannot be moved with drive pressure. If the rod is fully inserted, it is in a safe position of

maximum contribution to shutdown reactivity. If it is in a non-fully inserted position, that position shall be consistent with the shutdown reactivity limitation stated in Specification 3.3.A.1. This assures that the core can be shut down at all times with the remaining control rods assuming the strongest operable control rod does not insert.

Inoperable bypassed rods will be limited within any group to not more than one control rod of a (5x5) twenty-five control rod array. The use of the individual rod bypass switches in the Rod Sequence Control System (RSCS) to substitute for a failed full in or full out position switch will not be limited as long as the actual position of the control rod is known.

Also if damage within the control rod drive mechanism and in particular, cracks in drive internal housings, cannot be ruled out, then a generic problem affecting a number of drives cannot be ruled out. Circumferential cracks resulting from stress assisted intergranular corrosion have occurred in the collet housing of drives at several BWRs. This type of cracking could occur in a number of drives and if the cracks propagated until severance of the collet housing occurred, scram could be prevented in the affected rods. Limiting the period of operation with a potentially severed rod will assure that the reactor will not be operated with a large number of rods with failed collet housings.

B. Control Rods

1. Control rod drop accidents as discussed in the FSAR can lead to significant core damage. If coupling integrity is maintained, the possibility of a rod drop accident is eliminated. The overtravel

position feature provides a positive check as only uncoupled drives may reach this position. Neutron instrumentation response to rod movement provides a verification that the rod is following its drive. Absence of such response to drive movement could indicate an uncoupled condition. Rod position indication is required for proper function of the RSCS and the Rod Worth Minimizer (RWM).

2. The control rod housing support restricts the outward movement of a control rod to less than 3 in. in the extremely remote event of a housing failure. The amount of reactivity which could be added by this small amount of rod withdrawal, which is less than a normal single withdrawal increment, will not contribute to any damage to the Primary Coolant System. The design basis is given in subsection 3.8.2 of the FSAR, and the safety evaluation is given in subsection 3.8.4. This support is not required if the Reactor Coolant System is at atmospheric pressure since there would then be no

driving force to rapidly eject a drive housing. Additionally, the support is not required if all control rods are fully inserted and if an adequate shutdown margin with one control rod withdrawn has been demonstrated, since the reactor would remain subcritical even in the event of complete ejection of the strongest control rod.

3. The RSCS and the RWM System restrict withdrawals and insertions of control rods to those listed prespecified control rod sequences which are established to assure that the maximum individual control rod worth prior to withdrawal shall be less than  $1.25\% \Delta k$ . These sequences are developed prior to initial operation of the unit to limit the reactivity worths of control rods in the core, and together with the integral rod velocity limiters, limit potential reactivity insertion such that the results of a control rod drop accident will not exceed a maximum fuel energy content of 280 cal/gm, reference Sections 3.6.6, 7.17, and 14.6.2 of the FSAR and NEDO-10527 and Supplement 1 to