

Exelon Generation Company, LLC Byron Station 4450 North German Church Road Byron, IL 61010–9794 www.exeloncorp.com

Nuclear

April 23, 2001

LTR: BYRON 2001-0065

File: 3.11.0530

United States Nuclear Regulatory Commission Attention: Document Control Desk Washington, DC 20555-0001

Byron Station, Unit 2

Facility Operating License No. NPF-66

NRC Docket No. STN 50-455

Subject:

Steam Generator Tube Repairs Performed During the Byron Station Unit 2,

Cycle 9 Refueling Outage

Pursuant to Item a. of Technical Specification 5.6.9, "Steam Generator (SG) Tube Inspection Reports," we are reporting the number of SG tubes plugged or repaired during the Byron Station Unit 2, Cycle 9 Refueling Outage (B2R09).

A 100% full length eddy current inspection was performed on SG 2B. No inspections were performed on SGs A, C and D.

Based upon the results of this inspection, SG 2B was classified as inspection category C-1 in accordance with Technical Specification 5.5.9.c, "Inspection Results Classification." A total of four tubes were plugged in SG B during the Byron Station Unit 2 Cycle 9 Refueling Outage. The tube plugging distribution in the steam generators is summarized in the table below.

Steam Generator	Tubes Plugged this Outage (B2R09)	Tubes Plugged Previously	Total Tubes Plugged*
2A	0	50	50
2B	4	109	113
2C	0	41	41
2D	0	19	19
Total	4	219	223

^{*} Each SG contains 4570 tubes

A079

Byron Ltr. 2001-0065 April 23, 2001 Page 2

If there are any questions regarding this information, please contact P. Reister, Regulatory Assurance Manager, at (815) 234-5441, extension 2280.

Respectfully,

Richard P. Lopriore Site Vice President

Byron Nuclear Generating Station

RPL/JS/GS/rf/dpk

Regional Administrator - NRC Region III CC:

NRC Senior Resident Inspector – Byron Station NRC Project Manager – NRR – Byron Station Office of Nuclear Facility Safety – IDNS