

Exelon Generation Company, LLC
Dresden Nuclear Power Station
6500 North Dresden Road
Morris, IL 60450-9765

www.exeloncorp.com

10CFR 50.55a(g)(5)(iii)

March 14, 2001

PSLTR: 01-0025

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

Dresden Nuclear Power Station, Units 2 and 3
Facility Operating License Nos. DPR-19 and DPR-25
NRC Docket Nos. 50-237 and 50-249

Subject: Relief Request for Bolting Removal when Leakage is detected at Bolted Connection for Control Rod Drive (CRD) Housing during System Pressure Test

In accordance with 10 CFR 50.55a, "Codes and standards," paragraph (a)(3)(i), Dresden Nuclear Power Station (DNPS) is requesting approval of a proposed alternative to existing American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code, Section XI, "Rules for Inservice Inspection of Nuclear Power Plant Components," on the basis that the proposed alternatives provide an acceptable level of quality and safety.

The requested alternatives involve bolting removal when leakage is detected at bolted connection for Control Rod Drive (CRD) Housing during System Pressure Test. The justification for this request is attached and demonstrates that the proposed alternative would provide an acceptable level of quality and safety, as required by 10 CFR 50.55a(a)(3)(i).

These requested alternatives are for the third period of the third Inservice Inspection Interval for both Units 2 and 3. For Unit 2, the third Inservice Inspection Interval began on March 1, 1992, and the projected end date is January 19, 2003. For Unit 3, the Third Inservice Inspection Interval began on March 1, 1992, and the projected end date is October 31, 2002.


To support a fall 2001 refueling outage for Unit 2, we are requesting approval of these proposed alternatives by October 12, 2001.

ADH 1/1

U.S. Nuclear Regulatory Commission
March 14, 2001
Page 2

Should you have any questions concerning this letter, please contact Mr. D.F. Ambler at (815) 942-2920 extension 3800.

Respectfully,



Preston Swafford
Site Vice President
Dresden Nuclear Power Station

Attachment: Relief Request, PR-20, "Bolting Removal when Leakage is detected at Bolted Connection for Control Rod Drive (CRD) Housing during System Pressure Test"

cc: Regional Administrator – NRC Region III
NRC Senior Resident Inspector – Dresden Nuclear Power Station

ISI Program Plan
Dresden Nuclear Power Station Units 2 & 3, Third Interval

RELIEF REQUEST NUMBER: PR-20
(Page 1 of 2)

COMPONENT IDENTIFICATION

Code Class:	1
References:	Table IWA-5250 (a)(2)
Examination Category:	B-P
Item Number:	B15.ST and B15.OT
Description:	Bolting Removal when Leakage is detected at Bolted Connection for Control Rod Drive (CRD) Housing during System Pressure Test

CODE REQUIREMENT

IWA-5250 (a)(2) requires that if leakage occurs at a bolted connection, the bolting shall be removed, VT-3 visually examined for corrosion, and evaluated in accordance with IWA-3100.

BASIS FOR RELIEF

Pursuant to 10 CFR 50.55a, "Codes and standards," paragraphs (a)(3)(i), relief is requested on the basis that the proposed alternatives provide an acceptable level of quality and safety.

Control Rod Drive (CRD) housing leakage has been primarily observed at Dresden Nuclear Power Station (DNPS) when the primary system was pressurized prior to reaching normal operating temperature range during system pressure testing.

There are a total of 177 drives in each unit. Current maintenance practice requires that existing bolting be discarded and replaced with new bolting which has been subjected to a fluorescent MT and VT-1 examination. Bolting removed from exchanged drives has not revealed significant degradation caused by inservice corrosion. However, a number of CRD bolts were rejected during the course of these examinations because of linear indications found in the head-to-shank transition region. Metallurgical analyses of some of these rejected bolts at DNPS revealed shallow and innocuous defects caused by the manufacturing process at maximum depth of 0.036 inch with no sign of crack initiation or propagation. DNPS will continue to discard existing bolting and replace with new bolting, or perform a VT-1 examination of existing bolts prior to reinstallation. This will ensure degraded bolting is not installed during CRD maintenance.

There are eight (8) CRD bolts in each drive. In the unlikely event that a bolt might fail due to manufacturing defects, a drive would not separate from its housing. In accordance with an analysis performed by General Electric Co. for Commonwealth

ISI Program Plan
Dresden Nuclear Power Station Units 2 & 3, Third Interval

RELIEF REQUEST NUMBER: PR-20
(Page 2 of 2)

BASIS FOR RELIEF (Con't)

Edison (ComEd) Company in 1991 as few as three (3) uniformly distributed and unflawed bolts can support all imposed loads and maintain the applicable ASME Code stress limits. Alternatively, the applicable ASME Code stress limits can be maintained with eight (8) bolts having defects that are 0.157 inch deep and extend 360° around each bolt shank circumference.

Relief is requested from the requirements specified in IWA-5250 (a)(2) of the 1989 ASME Section XI for CRD bolts on the basis that significant degradation of CRD bolting has not been experienced at DNPS, that significant margin to failure has been shown, and that replacement of existing bolting with new bolting, or VT-1 examination of existing bolting, prior to reinstallation as required by Table IWB-2500-1 on CRD bolting when disassembled for maintenance, will provide an acceptable level of quality and safety.

PROPOSED ALTERNATE PROVISIONS

As an alternate examination, DNPS will replace existing bolting with new bolting, or VT-1 examine existing bolting prior to reinstallation during scheduled drive exchanges. CRD bolts will not be removed for a VT-3 examination when leakage is detected at the CRD housing flange connection during the conduct of the system pressure tests in accordance with IWB-5000.

APPLICABLE TIME PERIOD

Relief is requested for the third ten-year interval of the Inservice Inspection Program for DNPS Units 2 and 3.