

W. R. McCollum, Jr. Vice President **Duke Energy**

Oconee Nuclear Station 7800 Rochester Highway Seneca, SC 29672 (864) 885-3107 OFFICE (864) 885-3564 FAX

May 7, 2001

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: Oconee Nuclear Station Docket Nos. 50-287 Licensee Event Report 287/2001-02, Revision 0 Problem Investigation Process No.: 0-01-0786

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a)(1) and (d), attached is Licensee Event Report 287/2001-02, Revision 0, concerning operation in a condition prohibited by Technical Specifications. One required Reactor Building Cooling Unit was discovered to have been inoperable longer than the allowed action time.

This report is being submitted in accordance with 10 CFR 50.73 (a)(2)(i)(b). This event is considered to be of no significance with respect to the health and safety of the public.

There are no NRC commitment items contained in this LER.

Very truly yours,

R. McCol



Attachment

Document Control Desk Date: May 7, 2001 Page 2 cc: Mr. Luis A. Reyes Administrator, Region II U.S. Nuclear Regulatory Commission 61 Forsyth Street, S. W., Suite 23T85 Atlanta, GA 30303 Mr. D. E. LaBarge U.S. Nuclear Regulatory Commission Office of Nuclear Reactor Regulation Washington, D.C. 20555

Mr. M. C. Shannon NRC Senior Resident Inspector Oconee Nuclear Station

INPO (via E-mail)

÷

NRC FORM 366 (1-2001)	;		U.S. N	UCLEAR RE	GULA	TORY		APP EXP	RO IR	VED BY ES 6-30	OMB N -2001	10. L	31	50-01	04
LICE	SEE (See rev digits/	EVEN	TRE required no s for each	PORT (LI umber of block)	ER)		Estimat request and fee Manage 20555-I Informa	ted burden 50 hours. back to i ement Bran 0001, or by tion and Re	per Rei ndus ich (inte egula	response to co ported lessons k try. Send comm T-6 E6), U.S. N ernet e-mail to tory Affairs, NEC	omply with earned are nents rega luclear Reg bjs1@nrc. OB-10202 (this n incorpording b gulatory gov, an (3150-0	nanda orated ourden / Con id to 1 104),	tory inform into the lic estimate mission, V he Desk O Office of M	ation collection eensing process to the Records Vashington, DC officer, Office of anagement and
FACILITY NAME	[1]						DOCK		R (2)			PAGE	(3)		
Oconee N	uclea	ar St	atio	n, Unit	:3			()50	- 287				1 OF	9
TITLE (4) Cont	ainme	nt Co	oler	Inoperab.	le I	Due to	o Des	ign, E	lxc	eeds Tecl	ı Spec	Tin	ıe		
EVENT	DATE (5)		LE	R NUMBER (6))	RE	PORT D	ATE (7)	—	0	THER FAC	ILITIES	S INVO	OLVED (8)	
MO		VEAR	VEAR		REV	мо	DAY	YFAR	FA	CILITY NAME		DOCK	ет NL 50-	JMBER	
00		2004	2001		00	05	07	2001	FA	CILITY NAME		DOCK	ET NL	JMBER	
03	07	2001	2001	- 01 -	00					FOUR		:D S+ //	Chook	all that ann	NA (14)
OPERATI	NG	5		THIS REPORT		BMITTEL) PUKSL			50 73(a)(2)(ii		<u>7K 9: ((</u> 5() 73(a	$\frac{1}{2}(2)(ix)(A)$)
	a)	<u> </u>	20.	2201(b)		20.220	13(a)(4)	(1)	┢	50.73(a)(2)(ii	<u>i)</u>).73(a	a)(2)(x)	
POWER	2 .0)	00	20.	2203(a)(1)	+	50.36	(c)(1)(i)(A)	\square	50.73(a)(2)(iv	/)(A)	73	3.71(a	a)(4)	
	•/		20.	2203(a)(2)(i)		50.36	(c)(1)(ii)	(A)		50.73(a)(2)(v)(A)	73	3.71(a	a)(5)	
			20.	2203(a)(2)(ii)		50.36	(c)(2)			50.73(a)(2)(v)(B)	0	THE	∕in ∆hstra	et below or in
		1	20.	2203(a)(2)(iii)		50.46	(a)(3)(ii)			50.73(a)(2)(v)(C)	N	RC F	orm 366A	
			20.	2203(a)(2)(iv)	ı I	50.73	(a)(2)(i)(A)		50.73(a)(2)(v)(D)				
			20.	2203(a)(2)(v)	X	50.73	(a)(2)(i)(B)		50.73(a)(2)(v	ii)				
	100		20.	2203(a)(2)(vi)		50.73	(a)(2)(i)(C)		50.73(a)(2)(v	iii)(A)				
			20.	2203(a)(3)(i)		50.73	(a)(2)(ii)	(A)		50.73(a)(2)(v	iii)(B)				
				LIC	CENS	EE CON	TACT	FOR THIS	LE	R (12)					
NAME									TE	LEPHONE NUM	IBER (Inclu	ude Are	a Cod	e) ວາດາ	
L.E. Nich	olson,	Regu	lator	y Compli	ance	e Man	ager				(864)	00	C	5292	<u>.</u>
		COMPL	ETE ON	E LINE FOR	EACH	COMP	ONENT	FAILURE		SCRIBED IN		PORT	(13)		
CAUSE	SYSTEM	1 co	MPONENT	MANU- FACTURER	RE	PORTABL	.E	CAUSE		SYSTEM	COMPON	NENT	FA	MANU- CTURER	REPORTABLE TO EPIX
в	ВК		мо	Reliance		Y									
	SU	PPLEM	ENTAL F	EPORT EXP	ECTE	D (14)	10000		Ť	EXPEC	ſED	MOI	NTH	DAY	YEAR
YES (If y	es, com	lete EXI	PECTED	SUBMISSIO	N DAT	ГЕ).	XI	10		SUBMISS DATE (5ION 15)				
ABSTRACT (imit to 14		esie a	oproximately '	15 sin	ale-spa	ced type	written lin	es)	(16)					· · · · · ·
	2/7/	200 Space	wh i		10 3m	IIni	+ 3	was i	n,	Mode 6.	the	Uni	i.t.	3 "B"	
Bos	J///	2001, Dui ¹	, wiii Idina	Coolir		Tinit	(38	RRCI	r)	stator	tempe		-ur	e	
Rea	ICLOI	BUL.			.rg		10) 10)	ring	2	apodial	toot	-	Th.	~ 3B	
exc	ceede	a the	e_ope	rabiti	-У	エエ(((ユ) っ	L du	.r r ng	a	special		 	111	2 JD 1 1 4 4	
RBC	CU wa	s deo	clare	d inope	era	bie.	An	inve	ST	igation	i tear	n ee	ouc.	Tuaea	
tha	ata	manu:	factu	iring de	efi	cien	су с	of the	: 3	B RBCU	moto	r, 1	ıns	talle	a
on	12/1	9/19	99, n	night ha	ave	pre	vent	ed pr	op	er oper	ration	n ur	nde	r	
cei	rtain	acc	ident	condit	tio	ns.	Thi	s eve	nt	: is bei	ng re	ероі	rte	d as	
900	erati	on i	nao	condition	on '	proh	ibit	ed by	ΥТ	echnica	l Spe	ecif	Eic	ation	s.

The root cause of this event is vendor design/manufacturing deficiency. Corrective actions include replacement of the affected motor and a specification change for future replacement motors. This event is considered to have no significance with respect to the health and safety of the public.

EVALUATION:

BACKGROUND

This event is reportable per 10CFR 50.73(a)(2)(i)(b) as operation in a condition which was prohibited by Technical Specifications (TS) due to one required Reactor Building Cooling Unit (RBCU) [EIIS:BK] being inoperable longer than allowed by TS.

The RBCU System is one of two independent Engineered Safeguards (ES) Systems provided to remove heat from the Reactor Building (RB) atmosphere following an accident. The other system is the Reactor Building Spray (RBS) [EIIS:BEI] System.

The capacity of each of these systems is designed to remove heat from the RB to reduce pressure following a Loss Of Coolant Accident. During normal plant operation, RBCUs "A" and "C" operate in the high-speed mode to help cool the RB in conjunction with the Reactor Building Auxiliary Coolers. RBCU "B" is not typically operated during normal operation. During an emergency, the RBCU System mode of operation changes automatically. The ES System is activated when the RB pressure reaches 3 psig. Upon actuation, the fan motors associated with RBCUs "A" and "C" change from high to low speed and the fan motor associated with RBCU "B" is started at low speed. All three RBCUs then operate continuously to circulate the RB steam-air mixture past the cooling coils to transfer heat from the RB atmosphere to the Low Pressure Service Water System (LPSW) [EIIS:BI] which is supplied from Lake Keowee (the ultimate heat sink).

Several years ago, Oconee initiated a program for scheduled refurbishment and or replacement of RBCU motors due to aging concerns. Prior to the events described below, several RBCU motors had been replaced with refurbished/rebuilt motors. Two RBCUs (1C and 1B) had new motors installed in 6/1999 and 4/2000 respectively. A replacement schedule called for additional replacements with new motors over the next several years.

In November 2000, unexpectedly high stator temperatures were observed on the Unit 1 "B" RBCU. The 1B RBCU was determined to be operable but was replaced due to loss of margin. A Failure Investigation Team (FIP) was formed to investigate the problem. The stator temperatures on the other Unit 1 RBCUs were found to be

LICENSEE EVENT REPORT (LER)							
FACILITY NAME (1)	DOCKET (2) NUMBER (2)		LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Oconee Nuclear Station, Unit 3	050- 287	2001	 - 02 -	00	3	OF	9
NARRATIVE (If more appear is required, use additional conis	s of NRC Form 3664) (17)					

NDC FORM 266AU S. NUCLEAR REGULATORY COMMISSION

acceptable. As a result of inspections and continuing investigation of this Unit 1 event, the Mechanical Systems Engineering section initiated plans to test the RBCUs on the other two Oconee Units. Engineering developed a correlation between motor supply voltage and current at low speed as a preliminary "screen" to determine if motor stator temperature data was needed to further assess RBCU motor condition.

Although the RBCU motors are equipped with installed thermocouples to monitor stator temperatures, these thermocouples are normally not connected to any remote monitoring equipment. In order to measure and observe the stator temperatures, test instruments must be connected within the reactor building. Each RBCU has a single vibration sensor mounted on the fan housing that provides an alarm in the control room when vibration exceeds its setpoint. Detailed vibration analysis requires mounting and monitoring of a number of sensors on the fan motor inside the housing. Therefore, troubleshooting requires a special test procedure to control installation and monitoring of the test equipment and to control the operating configuration (number and speed of operating fans, etc.).

TS 3.6.5 requires, in part, that two RBS trains and three RBCUs be Operable in Modes 1 and 2. Should one of these five cooling trains be inoperable, it must be restored to Operability within 7 days per TS 3.6.5 Required Action B.1. If Required Action B.1 is not met, Condition D must be satisfied by placing the Unit in Mode 3 within the next 12 hours.

At time of discovery of this event, Unit 3 was shutdown in Mode 6 with no safety systems or components out of service that would have contributed to this event.

EVENT DESCRIPTION

Unit 3 was shutdown on 2/16/01 for a scheduled maintenance outage.

On 2/26/01, voltage and current data were taken on the Unit 3 RBCU motors. The results on the 3A and 3C RBCU motors were acceptable. Data for the 3B RBCU indicated the need to verify actual stator temperatures.

DOCKET (2) NUMBER (2)	L	ER NUMBER (6)			PAGE (3)
	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
050- 287	2001	- 02 -	00	4	OF	9
	DOCKET (2) NUMBER (2) 050- 287	DOCKET (2) NUMBER (2) YEAR 050- 287 2001	DOCKET (2) NUMBER (2) LER NUMBER (6) YEAR SEQUENTIAL NUMBER 050-287 2001 02	DOCKET (2) NUMBER (2) LER NUMBER (6) YEAR SEQUENTIAL NUMBER REVISION NUMBER - - - 050-287 2001 02 00	DOCKET (2) NUMBER (2) LER NUMBER (6) YEAR SEQUENTIAL NUMBER REVISION NUMBER 050-287 2001 02 00 4	DOCKET (2) NUMBER (2) LER NUMBER (6) PAGE (3) YEAR SEQUENTIAL NUMBER REVISION NUMBER REVISION NUMBER 050-287 2001 02 00 4 OF

On 3/7/01, while Unit 3 was in Mode 6, a special test was initiated on the 3B RBCU to monitor motor stator temperatures during operation with all three of the RBCUs at the low (emergency) speed. After running in low speed for approximately 4 hours, the stator temperature data for the 3B RBCU exceeded the stator temperature acceptance limit.

Engineering made the recommendation that the 3B RBCU be considered inoperable and that the motor be replaced. Engineering further concluded that the motor should be considered inoperable since installation in December 1999, after extensive evaluation determined that the problem was a design configuration and tolerance issue. Therefore, Oconee Unit 3 operated with one inoperable RBCU between 12/19/99, when the 3B RBCU was declared operable following completion of replacement of the previous motor, and 2/16/01 when Unit 3 was shutdown for maintenance. This duration exceeds the seven day out-of-service time allowed by TS 3.6.5.

CAUSAL FACTORS

Duke Engineering has concluded that the high stator temperature on the 3B RBCU Motor was due to saturation of the magnetic circuit at low speed due to their unique two-speed winding design. Two design issues caused the stator temperature to exceed operability limits:

- a) a generic issue affecting all RBCU motors, which is lack of sufficient cross-sectional area of the magnetic circuit components (i.e. insufficient core iron) and
- b) a specific issue affecting the 1B and 3B RBCUs, which is a larger than normal air gap between the stator and rotor.

Motor magnetic materials (core components) have a characteristic such that the Ampere-turns required to generate a given flux density (flux divided by the area) is linear up to a given flux. The condition at this flux density is known as saturation of the magnetic circuit. Once this point is exceeded, the Ampere-turns needed to increase flux becomes non-linear and motor heat generation (proportional to the square of the current) increases significantly. In order to keep the size of a motor within reason, it may be economical or practical to design the magnetic circuit to operate a reasonable amount above the linear saturation line.

LICENSEE EVENT REPORT (LER)	JN						
FACILITY NAME (1)	DOCKET (2) NUMBER (2)	L	ER NUMBER (6)			PAGE ((3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Oconee Nuclear Station, Unit 3	050- 287	2001		00	5	OF	9
NADDATINE (If more successive days additional appiana	ENDC Form 2664) /47\					

The root cause of this event is design deficiency by the vendor. As a result of the FIP team investigation, Duke determined that the original RBCU Motors were marginally designed with respect to saturation of the magnetic circuit in the stator. The motor manufacturer, the fan qualifier and supplier, and Duke Power Engineering personnel were unaware that the design was marginal prior to these events.

One result of the marginal design is that nominal voltage values produce an exaggerated stator temperature response. The RBCU motors (nameplate voltage of 575 VAC) were specified for use at a nominal 600 VAC with an expected post-accident range of 540-614 VAC (i.e +/- 6% of nameplate rating). The RBCU motors operating at low speed were found to reach saturation conditions at around 95%-100% of rated voltage due to their specific two-speed winding design. Therefore, RBCU motor temperature response becomes non-linear at rated voltage, and thus can exhibit higher than desired stator temperatures, especially at the high end of the allowed terminal voltage range.

Another result of the marginal design is that the machine is extremely sensitive to larger than design air gap lengths. Because this sensitivity was not recognized, unsatisfactory tolerances were allowed which worsened the stator temperatures at higher voltages and resulted in marginal or unacceptable performance. Also, there was not appropriate guidance to monitor stator temperatures after maintenance or during normal operation. This conclusion is further supported by the fact that a new motor was manufactured after 1998 with a larger than nominal air gap (a deviation from nominal in the order of 0.005 inch) as shown by manufacturer's inspection and test The manufacturer's Engineering Department deemed it to be data. It was installed as the 1B RBCU motor in April within tolerance. 2000. Special testing in November 2000, as mentioned in the Background section, identified that its operation was marginal so it was replaced in December 2000.

The 3B RBCU motor also had larger than normal air gap between the stator and rotor, with a deviation from nominal in the order of The fact that the 3B RBCU had the largest gap caused 0.010 inch. the 3B RBCU motor to reach stator temperatures in excess of the operability limit.

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSION (1-2001) LICENSEE EVENT REPORT (LER) DOCKET (2) PAGE (3) NUMBER (2) LER NUMBER (6) FACILITY NAME (1) REVISION SEQUENTIAL NUMBER YEAR NUMBER Oconee Nuclear Station, Unit 3 050-287 2001 02 00 6 OF 9

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Duke Engineering has concluded that this design issue applies only to RBCU motors operating at low speed and is due to certain aspects of this specific two-speed winding design.

CORRECTIVE ACTIONS

Immediate:

1. The 3B RBCU motor was replaced. Motor stator temperature monitoring was included during Post-Maintenance Testing and demonstrated acceptable stator temperatures.

Subsequent:

- Screening of the Unit 2 RBCUs found acceptable stator temperatures based on the voltage/current correlation. As a result, all nine (9) installed RBCU motors at Oconee have now been tested or screened for acceptable stator temperatures.
- 2. Duke and the vendors have addressed the design issues raised in this report. The specification for new RBCU motors has been revised to assure that new replacement RBCU motors have greater margin to operate with acceptable stator temperatures.

Planned:

- 1. A report containing the results of the Duke Failure Investigation Process for the high stator temperatures of the 1B and 3B RBCU is being sent to the appropriate vendors.
- 2. A proposed revision to the directive that specifies Post-Maintenance Testing requirements (WPM 501) will be reviewed for acceptance. This revision addresses enhancements to testing requirements for motors following replacement.
- 3. The maintenance procedure specifically applicable to RBCU motor replacements will be revised to routinely require measurement of motor stator temperatures for future RBCU motor replacements.

There are no NRC Commitment items contained in this LER.

NRC FQRM 366AU.S. NUCLEAR REGULATORY COM (1-2001) LICENSEE EVENT REPORT (LEF	nmissio R)	N						
FACILITY NAME (1)		DOCKET (2) NUMBER (2)	L	ER NUMBER (6)			PAGE	(3)
			YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Oconee Nuclear Station, Unit	t 3	050- 287	2001		00	7	OF	9
Oconee Nuclear Station, Unit	t 3	050- 287	2001	- 02 -	00	7	OF	9

SAFETY ANALYSIS

During a design basis event (i.e. LOCA or steam line break inside containment), the 3B RBCU would have started and would have contributed to the mitigation of the event. Provided that station voltages remained at median values or with-in acceptable undervoltage limits, the 3B RBCU would have been capable of performing its safety function.

However, if voltages were higher than normal, the stator temperatures might exceed the temperature for which the motor has been qualified in a steam and pressure environment, even though it would not have exceeded the demonstrated thermal capabilities of the insulation system. Therefore, it could be anticipated that the 3B RBCU would initially contribute to the mitigation of the event, but might fail later in the event. As a result, Engineering has concluded that there is reasonable doubt that the 3B RBCU would have performed successfully for the full mission time after a design basis event.

The Oconee UFSAR takes credit for two of the three RBCUs operating after an event (thus allowing for a single failure of the third RBCU). Testing performed on the 3A and 3C RBCUs indicated acceptable stator performance. Therefore, the 3A and 3C RBCUs are considered to have been operable for the period that the 3B RBCU has been inoperable.

In addition, an evaluation was performed of the capability of each of these RBCUs to transfer heat in the post-accident environment. This evaluation considered the capability of the available containment heat removal systems and components to meet the containment heat removal requirements using actual initial conditions (such as containment and ultimate heat sink temperatures, cooling coil fouling coefficients, etc.) for the period that the 3B RBCU is now considered inoperable. This evaluation concluded that either remaining RBCU alone was capable of handling the required heat load. Therefore, the RBCU system was still capable of performing the required safety function, even with an additional assumed failure. As a result of this conclusion, this event is not a safety system functional failure.

NRC FORM 366AU.S. NUCLEAR REGULATORY COMMISSIO (1-2001) LICENSEE EVENT REPORT (LER)	N		
FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)	PAGE (3)
		YEAR SEQUENTIAL REVISION NUMBER NUMBER	
Oconee Nuclear Station, Unit 3	050- 287	 2001 _ 02 _ 00	8 OF 9

The primary role of the RBCUs is long term prevention of containment overpressurization. The RBCU function is only weakly correlated to the large early release frequency (LERF). The LERF for Oconee is dominated by containment bypass sequences, in particular the interfacing system loss of coolant accidents, which are not affected by RBCU operation. The only influence of the RBCUs on the core damage frequency (CDF) is as an alternative means of cooling the containment sump water indirectly by cooling the containment atmosphere, thereby reducing the reliance on the LPI coolers. The unavailability of a single RBCU does not measurably increase the estimated CDF for Oconee. Therefore, the impact on CDF and containment performance, including LERF, was evaluated to be insignificant.

Therefore, there was no actual impact on the health and safety of the public due to this event.

ADDITIONAL INFORMATION

A review of events over the previous three years found several instances of RBCU motor problems. A December 1999 failure of the 3B RBCU was reportable under 10 CFR 50.73 (reference LER 287/1999-02). The cause of that event was significantly different from this event and the corrective actions would not be expected to prevent this event. Also, there is some similarity to the November 2000 1B RBCU event, which is described in the Background section above. However, this event was initiated by installation of a motor with an unknown design deficiency prior to the November 2000 event, and was discovered as a result of the on-going corrective actions from the November 2000 event. Therefore, this is not considered a recurring event.

This event is considered reportable under the Equipment Performance and Information Exchange (EPIX) program. The RBCUs were initially purchased from, and certified by, Joy Manufacturing Company (presently Howden Buffalo, New Philadelphia Division). The RBCU motors are 150/75 HP, 1200/600 RPM, 575 VAC, Model 600276-3, NEMA Frame Number D5005 and were made by Rockwell International, Reliance Electric Division. The 3B RBCU motor that is the subject of this report had been rebuilt on-site prior to installation.

FACILITY NAME (1)	DOCKET (2) NUMBER (2)		ER NUMBER (6)			PAGE	(3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
conee Nuclear Station, Unit	3 050-287	2001		00	9	OF	9

Energy Industry Identification System (EIIS) codes are identified in the text within brackets [].