



**Pacific Gas and
Electric Company**

David H. Oatley
Vice President
Diablo Canyon Operations

Diablo Canyon Power Plant
P.O. Box 56
Avila Beach, CA 93424

805.545.4350
Fax: 805.545.4234

May 21, 2001

PG&E Letter DCL-01-062

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Docket No. 50-323, OL-DPR-82
Docket No. 50-275, OL-DPR-80
Diablo Canyon Units 2 and 1
Licensee Event Report 2-2001-001-00

Degraded Wires in 4.16-kV Vital Buses Due to Bending at Cubicle Door Hinges

Dear Commissioners and Staff:

PG&E is submitting the enclosed licensee event report regarding degraded wires in 4.16-kV vital breaker cubicles. The suspected cause(s) of this condition could have prevented fulfillment of a safety function in two or more trains. The report also addresses PG&E's failure to enter Technical Specification 3.0.3 with both offsite power sources inoperable concurrent with an inoperable emergency diesel generator for Unit 2 Vital Bus H.

These events were considered to be of very low risk significance and did not adversely affect the health and safety of the public.

Sincerely,

David H. Oatley

cc: Ellis W. Merschoff
David L. Proulx
Girija S. Shukla
Diablo Distribution
INPO

Enclosure

WEC/2246/N0002125

IE22

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Diablo Canyon Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 2 3	PAGE (3) 1 OF 12
--	---	----------------------------

TITLE (4)

Degraded Wires in 4.16-kV Vital Buses Due to Bending at Cubicle Door Hinges

EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)									
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MO	DAY	YEAR	FACILITY NAME					DOCKET NUMBER					
03	22	2001	2001	- 0 0 1 -	0 0	05	21	2001	Diablo Canyon Unit 1					0 5 0 0 0 2 7 5					

OPERATING MODE (9) 1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR: (11) <div style="display: flex; justify-content: space-around;"> <div>X 10 CFR 50.73(a)(2)(ix)(A)</div> <div>X OTHER 50.73(a)(2)(i)(B)</div> </div> (SPECIFY IN ABSTRACT BELOW AND IN TEXT, NRC FORM 366A)														
POWER LEVEL (10)															
1 0 0															

LICENSEE CONTACT FOR THIS LER (12)

Roger Russell - Senior Regulatory Services Engineer	TELEPHONE NUMBER	
	AREA CODE 805	NUMBER 545-4327

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

SUPPLEMENTAL REPORT EXPECTED (14)					EXPECTED SUBMISSION DATE (15)		MON	DAY	YR
<input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)					<input type="checkbox"/> NO		11	16	01

ABSTRACT (Limit to 1400 spaces. i.e., approximately 15 single-spaced typewritten lines.) (16)

On March 14, 2001, a broken wire was identified in a trip circuit for the Containment Spray Pump (CSP) 2-2 Breaker. As part of continued inspections, additional degraded wires were found on March 22, 2001, in the CSP 1-1 Breaker. While Units 1 and 2 were in Mode 1 (Power Operation) at 100 percent power, PG&E determined the cause of degraded wires could have prevented the fulfillment of a safety function of two or more trains or channels in different systems. The condition is reportable per 10 CFR 50.73(a)(2)(ix)(A).

On March 25, 2001, during wire repairs on Unit 2 Bus H, with Unit 2 in Mode 1 at 100 percent power, Technical Specification (TS) 3.8.1, "AC Sources – Operating," was violated when all three power sources to Vital Bus H were inoperable for greater than 1 hour, and operators did not enter TS 3.0.3 as required by condition J of TS 3.8.1. This condition is reportable per 10 CFR 50.73(a)(2)(i)(B).

PG&E believes that the wire degrades as a result of bending when the cubicle doors are opened and closed. A failure analysis is in progress to confirm the root cause. Corrective actions will be formulated based on the failure analysis results.

Operators did not enter TS 3.0.3 due to incomplete and inconsistent procedural guidance. Applicable procedures will be revised and operators will be trained on the condition that made the power system inoperable.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)								LER NUMBER (6)						PAGE (3)		
									YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2001	-	0	0	1	-	0	0	2 OF 12

TEXT

I. Plant Conditions

Units 1 and 2 have operated in various modes and at various power levels with the degraded wire conditions described below. Unit 2 was in Mode 1 (Power Operation) at 100 percent power during the time the offsite power systems and Diesel Generator (DG) 2-2 were inoperable and PG&E failed to enter Technical Specification (TS) 3.0.3.

II. Description of Problem

A. Background

Vital 4.16-kV Switchgear

The vital 4.16-kV metal-clad switchgear, manufactured by General Electric, contains buses, breakers, relays, control switches, and control and indication wiring for proper distribution of 4.16-kV electrical power (EB) to all engineered safety feature (ESF) equipment, including the emergency core cooling system pumps and vital 4.16-kV electrical feeder circuits (EB)(BU). The breakers are required to close upon receipt of the appropriate signal to start the associated ESF pump or energize the bus. These breakers are required to open upon overcurrent conditions. They are also required to open upon a loss of offsite power and reclose upon restoration of power to the vital buses from the DGs (EK).

Each breaker is housed in its own cubicle. Access to each cubicle is through a hinged door. Mounted on the doors of the various cubicles are relays (for example, undervoltage and overcurrent) and various control switches (for example, transfer, control, and feature cut-out). The wiring to the door-mounted devices is routed across the hinge area from the front corner of the cubicle walls onto a door-mounted wire loom. The wire loom is a metal clamping device that spreads and holds the wires when the doors are opened and closed to minimize wear. The wire addressed in this LER is factory-installed #10 and #12 AWG, with Type TA insulation, NEMA Class K (high strand) copper wire. The stranded wire provides flexibility and minimizes strain-hardening of the wire as doors are opened and closed. In some cases the factory-installed wire has been replaced with newer wire as part of equipment upgrades other design changes.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)									LER NUMBER (6)						PAGE (3)		
										YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3		2001	-	0	0	1	-	0	0	3 OF 12

TEXT

Diesel Generators

Each unit has three DGs that supply power to the 4.16-kV vital buses (EB) whenever offsite power is either unavailable, or bus voltage degrades below a point at which required loads would become inoperable.

Offsite Power Supplies and Double Sequencing

Two sources of offsite power are available to Diablo Canyon Power Plant (DCPP): the 500-kV system and the 230-kV startup power system (EA). The DCPP main generator (EL) feeds the 500-kV system during normal operation and supplies power to the house loads, including the 4.16-kV vital buses, through the auxiliary transformers (XFMR). This source of power to plant loads is known as auxiliary power.

The 230-kV startup power system is a dedicated standby/startup power source that can provide power to the plant through the startup transformers (SUTs). This system is available as a backup source of power to the vital buses if auxiliary power is lost. The 230- to 12-kV SUT has a load tap changer (LTC) on the 12-kV side of the transformer that is operated either in automatic or manual. The LTC allows the 12-kV voltage to be maintained if 230-kV voltage fluctuates. The LTC is normally in automatic, and the secondary voltage is maintained at 107.5 percent of normal (when not supplying loads). This ensures that adequate voltage is maintained to house loads following an automatic transfer to startup power.

Vital buses can be manually transferred from auxiliary to startup power for operational or maintenance purposes. However, compensatory measures must first be taken, in accordance with Operating Procedure (OP) J-2:VIII, "Guidelines for Reliable Transmission Service for DCPP," to ensure continued operability of the startup power source. Compensatory measures include defeating the auto-start of the standby condensate/condensate booster pump set and cutting out the auto-transfer feature of one 12-kV non-vital bus (either D or E). Each non-vital 12-kV bus carries one 13,000 horsepower circulating water pump and two 6,000 horsepower reactor coolant pumps. The procedure also requires that when operating the LTC in manual, that the LTC be placed in the 7, 8, or 9 tap position. These measures ensure that the SUT maintains adequate secondary voltage to accommodate the loading that occurs upon automatic transfer from auxiliary power to startup power.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)								LER NUMBER (6)						PAGE (3)		
									YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2001	-	0	0	1	-	0	0	4 OF 12

TEXT

OP J-6A:II, "Transferring 4160 Volt Banks," provides the sequence of steps to perform the actual manual transfer. The procedure requires that operators take manual control of the LTC on the 230- to 12-kV SUT, reduce output voltage to match the bus voltage, and then make the transfer. Unless a 12-kV bus, carrying the large reactor coolant pumps and a circulating water pump loads, is being supplied by startup power, the LTC is left in manual.

With a vital bus being supplied by startup power and the LTC in manual at a reduced voltage level, the startup power source may be inoperable. This inoperability is due to the potential for a double sequencing event to occur. The sequence of events characterized as "double sequencing" is summarized as follows:

- A loss-of-coolant accident (LOCA) causes a safety injection signal resulting in automatic transfer of vital buses to startup power and auto start of all DGs,
- ESF loads sequence onto the vital buses,
- the main generator trips after 30 seconds,
- the non-vital 12- and 4-kV buses transfer to startup power, causing a large voltage drop on the startup bus,
- the decreased startup bus voltage causes the second-level-under voltage relays to actuate after a time delay,
- load shed relays strip all loads from the vital buses, and the buses are transferred to the DGs, and
- ESF loads resequence onto the vital buses.

Because the ESF loads do not remain on the startup power system and are sequenced onto the DGs, the startup power system is considered to be inoperable.

Technical Specifications

The Limiting Condition for Operation for TS 3.8.1 states:

The following AC electrical sources shall be OPERABLE:

- a. Two qualified circuits between the offsite transmission network and the onsite Class 1E AC Electrical Power Distribution System; and
- b. Three diesel generators (DGs) capable of supplying the onsite Class 1E power distribution subsystem(s)

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)								LER NUMBER (6)						PAGE (3)		
									YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2001	-	0	0	1	-	0	0	5 OF 12

TEXT

Condition J of TS 3.8.1 requires plant personnel to immediately enter TS 3.0.3 when one or more DGs are inoperable coincident with two required offsite circuits inoperable.

B. Event Description

On March 14, 2001, during routine functional testing of relays associated with Containment Spray Pump (CSP) 2-2, PG&E personnel determined the pump breaker in Cubicle 52-HH-9 would not trip on an overcurrent condition. Inspection and initial trouble shooting identified a broken overcurrent trip wire between the hinged cubicle door and the interior of the cubicle. The broken wire was subsequently replaced and the breaker returned to service.

On March 16, 2001, PG&E established a plan to inspect the Unit 1 and Unit 2 4.16-kV vital switchgear cubicles for evidence of additional wire degradation. The plan called for inspections during the associated bus/train scheduled maintenance windows.

On March 21, 2001, PG&E began inspections of the breaker cubicles on both Units. No additional degraded wires were identified during inspection activities on that day.

On March 22, 2001, PG&E personnel identified degraded wires in Unit 1 Cubicle 52-HG-7 for CSP 1-1. One wire was identified to have exposed and broken strands, and a second wire was identified with damaged insulation. The wires were subsequently replaced.

On March 25, 2001, preparations began for transferring 4.16-kV Vital Bus H to startup power to inspect the auxiliary power feeder breaker. The prerequisite compensatory measures were taken, the LTC on the SUT 2-1 was placed in manual, the voltages were matched, and at 0142 PST, Vital Bus H was transferred to startup power. The LTC was left in manual, in the tap-4 position, because operating personnel believed that leaving it in a higher setting would cause an unacceptable voltage condition on Bus H.

On March 25, 2001, at 0143 PST, 4-kV Breaker 52-HH-13 (and thus the 500-kV offsite power system to Bus H) was declared inoperable for the inspection. At approximately 0205 PST, degraded wires affecting the load-shed function of breakers for Residual Heat Removal Pump 2-2 and CSP 2-2 were identified in the cubicle. The cubicle door was closed while corrective maintenance work orders were prepared. As the affected

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)									LER NUMBER (6)						PAGE (3)		
										YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2001	-	0	0	1	-	0	0	6	OF 12

TEXT

pumps might not shed during a load-shedding event, DG 2-2 was conservatively declared inoperable at 0205 PST and placed in manual. (Subsequent evaluations concluded that sufficient strands of conductors were intact to enable DG 2-2 to perform its intended safety function.) The cubicle door was reopened between 0500 and 0530 PST to replace the degraded wires. At 0851 PST, the cubicle door was closed, the clearance was reported off, and the DG was declared operable. At 0858 PST, auxiliary power to Bus H was declared operable.

On the dayshift of March 25, 2001, inspections of the auxiliary feeder breakers continued, with Unit 2 Bus F, Breaker 52-HF-13. Compensatory measures were taken, the tap changer was placed in manual, and the bus was transferred to startup power. Due to high voltage on 480 V Bus F, the LTC was adjusted down to restore the 480-V bus voltage to normal. At that time, the Unit 1 Shift Foreman questioned if the startup power supply was still operable. Maintenance was contacted and instructed not to open the auxiliary power breaker cubicle door until the question could be answered. Operators subsequently declared the startup power inoperable, performed the required surveillance, and transferred Bus F back to auxiliary power.

On March 25, 2001, PG&E engineering personnel determined that while the 230-kV to 12-kV SUT LTC was in tap-4 position, the 230-kV startup power system was inoperable. This is because under worst-case loading conditions, the low voltage on the secondary side of the transformer, concurrent with a LOCA, could result in double sequencing of the ESF loads.

Thus, with the 230-kV offsite power system inoperable concurrent with DG 2-2 and auxiliary power to Bus H inoperable, operating personnel should have entered TS 3.0.3, in accordance with condition J of TS 3.8.1. The condition existed for approximately 4 hours while the clearance was active on Bus H Breaker 52-HH-13 and work was in progress (from 0453 PST to 0851 PST). The condition is reportable to the NRC in accordance with 10 CFR 50.73(a)(2)(i)(B).

On March 28, 2001, with the exception of eight breakers (two per Unit) determined to be operable, the wiring inspections were completed on the Units 1 and 2 vital 4.16-kV cubicles and breakers. A total of 15 wires were identified and replaced because they were either degraded or nonfunctional.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)									LER NUMBER (6)						PAGE (3)		
										YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2001	-	0	0	1	-	0	0	7	OF 12

TEXT

PG&E determined that none of the failed or degraded wires alone had made a train inoperable, nor could they have credibly prevented the fulfillment of an entire safety function. However, given the number of degraded wires discovered, and assuming the condition had not been identified and corrected, additional failures could have occurred resulting in potentially overloading a DG. Although the degraded wires did not cause a plant problem, they caused a common condition that presented the potential to prevent the fulfillment of the safety functions of trains in different systems. Therefore, on March 30, 2001, PG&E determined that the condition was reportable to the NRC in accordance with 10 CFR 50.73(a)(2)(ix)(A).

C. Inoperable Structures, Components, or Systems that Contributed to the Event

None.

D. Other Systems or Secondary Functions Affected

None.

E. Method of Discovery

Degraded Wire

PG&E personnel discovered a broken wire in Unit 2 Cubicle 52-HH-9 during routine scheduled functional testing of an overcurrent relay for CSP 2-2. This discovery prompted further investigations for similar degraded or broken wires. The potential generic implications were identified upon discovery of a second degraded wire on March 22, 2001.

TS 3.0.3 Entry

On March 25, 2001, maintenance and operating personnel were preparing for inspection of the auxiliary power feeder breaker on Unit 2 4.16-kV Vital Bus F. When the 230- to 12-kV SUT LTC was placed in manual and adjusted to the tap-4 position to compensate for high voltage on the 230-kV startup power system, the Unit 1 Shift Foreman questioned whether the startup power source was operable.

F. Operator Actions

None.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)									LER NUMBER (6)						PAGE (3)		
										YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2001	-	0	0	1	-	0	0	8	OF 12

TEXT

G. Safety System Responses

None.

III. Cause of the Problem

A. Immediate Cause

Degraded Wire

Wire was abnormally degraded in service.

TS 3.0.3 Entry

Operations personnel manually placed SUT LTC in the tap-4 position.

B. Root Cause

Degraded Wire

PG&E believes the condition resulted from short-radius bending of the wire near the edge of the wire looms. Bending occurs during the periodic opening and closing of the cubicle doors for operational or maintenance purposes. During bending, the wire becomes strain-hardened which causes the strands to break under subsequent bending.

PG&E is performing a failure analysis of selected specimens of the degraded and broken wires to confirm the exact cause of failure. The results of the failure analysis will be provided in a supplemental LER.

TS 3.0.3 Entry

There was incomplete and inconsistent guidance provided in the procedures. A table in OP J-2:VIII only recommended the tap positions to which the LTC should be adjusted when transferring buses to the startup power system. Additionally, a caution in OP J-6A:II discussed overvoltage conditions that could occur on the 480-V and 4.16-kV buses when the SUT LTC is returned to automatic. Thus, operators manually adjusted the LTC to match voltages, transferred the buses to startup power, and left the LTC in the tap-4 position to maintain normal voltage conditions. The operators failed to recognize that in this condition, the startup power source was inoperable.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)									LER NUMBER (6)						PAGE (3)		
										YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2001	-	0	0	1	-	0	0	9	OF 12

TEXT

C. Contributory Cause

Degraded Wire

None.

TS 3.0.3 Entry

None.

IV. Analysis of the Event

Degraded Wire

The following table identifies the degraded wires, their functions, and the effects of the degraded conditions.

Degraded Wire Table

Cubicle/Breaker & Component	Wire Condition	Wire Function	Effect
52-HH-9 CSP 2-2	Broken trip wire	Trip circuit from overcurrent relay 51HH9.	Wouldn't protect bus given a fault in motor or cables.
52-HG-7 CSP 1-1	2 wires degraded	Current circuit from CT to overcurrent relay 51HG7. Spare wire – no function.	None. First wire would have performed its safety function. Second wire was a spare.
52-HH-15 Safety Injection Pump 2-2	Partially broken current wire	Current circuit from CT to overcurrent relay 51HH15.	None. Relays on other two phases would trip given a two-phase fault.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)									LER NUMBER (6)						PAGE (3)		
										YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2001	-	0	0	1	-	0	0	10	OF 12

TEXT

Degraded Wire Table – Cont.

52-HF-7 DG 1-3	8 wires degraded	2 spare wires for abandoned Unit 2 alarm circuit. 1 wire for coil circuit for overcurrent auxiliary relay 51XHF7. 2 wires for C phase ammeter and overcurrent relay 51HF7 current circuit. 1 wire for A phase ammeter and overcurrent relay 51HF7 current circuit. 2 wires for ground sensor auxiliary relay 50NXHF7 alarm circuits.	None. Wires were degraded but operable.
52-HH-13 Auxiliary power feeder breaker	2 wires degraded	2 wires from the load shed relay 27XHHT; 1 to RHR 2-2, and the other to CSP 2-2.	None. Wires were degraded but operable. Loads would still shed.
52-HF-12 Component Cooling Water Pump 2-1	Partially broken	1 wire on trip circuit from overcurrent relay 51HF12.	None. Wire was degraded but operable. Trip function would still occur.

As indicated in the table, thirteen of fifteen wires were identified as being degraded but operable. One wire was degraded in the cubicle for Safety Injection Pump 2-2. However, there was no effect, as the relays on the other two phases would have tripped the breaker given an overcurrent condition. One wire was broken in the cubicle for CSP 2-2 and would not have performed its function. In the latter case, another independent single failure would still be required to render a 4.16-kV vital bus inoperable (for example, a fault on the cable or motor for CSP 2-2). Single failures of this type are assumed in the accident analyses of the Final Safety Analysis Report. In this case, the two remaining 4.16-kV vital buses would have been available to perform their safety-related functions. Therefore, the condition was considered to be of very low risk significance and did not adversely affect the health and safety of the public.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)								LER NUMBER (6)						PAGE (3)		
									YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3	2001	-	0	0	1	-	0	0	11 OF 12

TEXT

TS 3.0.3 Entry

A PG&E analysis indicated that the adverse effect of double sequencing is a slight increase in peak containment pressure. This pressure increase would result from delays in effective operation of containment fan coolers and CSPs. This analysis has shown that the increase is well within the design and licensing basis of DCP. Therefore, the condition was considered to be of very low risk significance and did not adversely affect the health and safety of the public.

V. Corrective Actions

A. Immediate Corrective Actions

Degraded Wire

The degraded wire that was initially discovered in Unit 2 Cubicle 52-HH-9 was replaced. Inspections were subsequently conducted on the 4.16-kV vital switchgear cubicles for both Units, and all degraded wires were replaced.

TS 3.0.3 Entry

None required.

B. Corrective Actions to Prevent Recurrence

Degraded Wire

Corrective actions to prevent recurrence will be formulated following failure analysis of the degraded wire specimens. PG&E will submit a supplemental LER when these corrective actions are determined.

TS 3.0.3 Entry

- OP J-2:VIII will be revised to clearly indicate the acceptable positions that the LTC on the 230- to 12-kV SUT must be manually placed to maintain operable conditions when buses are transferred to startup power.
- OP J-6A:II has been revised to allow for preplanned evolutions that may cause overvoltage conditions on vital 4.16-kV and 480-V buses for up to 12 hours.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)									LER NUMBER (6)						PAGE (3)		
										YEAR	SEQUENTIAL NUMBER				REVISION NUMBER			
Diablo Canyon Unit 2	0	5	0	0	0	3	2	3		2001	-	0	0	1	-	0	0	12 OF 12

TEXT

3. Operator training will be conducted on this event, including the effects of double sequencing on vital equipment response times and LOCA conditions.

VI. Additional Information

A. Failed Components

Degraded Wire

The degraded wire was factory-installed #10 and #12 AWG, Type TA insulation, NEMA Class K (high strand) copper wire.

TS 3.0.3 Entry

None.

B. Previous Similar Events

Degraded Wire

None.

TS 3.0.3 Entry

In LER 1-95-007-01 (PG&E Letter DCL-96-158, dated August 6, 1996), PG&E describes a condition in which the 230-kV offsite power source was unable to meet its design requirements for all conditions. The report addressed potential double sequencing resulting from degraded conditions on the 230-kV transmission system caused by continued load growth. A number of corrective actions were taken to address the conditions, including a modification to the component cooling water system. However, the corrective actions noted in this LER would not have prevented operators from failing to recognize the inoperable conditions caused by a low setting on the SUT tap changer.