

# EXHIBIT 34

Case No. 2-1998-023

J/46

EXHIBIT 34

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950248

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION

The following is additional information as to the Central Laboratory metallurgical testing and evaluation of the failed ice basket screws. This information was obtained from a memorandum from Terry Woods to J. E. Maddox (RIMS No. L29 981020 801).

L29 981020 301

J. E. Maddox, EQB 1A-WBN

WATTS BAR NUCLEAR PLANT ICE CONDENSER SCREWS

Attached for your information is a copy of the report which reconciles primarily technical differences in TVA Central Laboratory documents, issued during the June 1995 timeframe, regarding Watts Bar ice condenser screws. The reconciliation effort identified two important findings which were associated with omission of technical data from reports issued. However, it is concluded that these omissions were inadvertent, and that laboratory test results indicate overall metallurgical core properties of the screws were adequate for the intended application.

Terry R. Woods  
Chief Metallurgical and Codes Engineer  
LP 4H-C

TRW:DM  
Attachment  
cc (Attachment)

- J. G. Adair, EQB 2N-WBN
- M. A. Cooper, LP 3K-C
- J. C. Kammeyer, EQB 2N-WBN
- Orley, PSC 1B-C
- ipert, LP 4G-C

EXHIBIT 34  
PAGE 1 OF 20 PAGE(S)

34, 2-1998-028

Signature

Date

10/26/98

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950248

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

RECONCILIATION OF WATTS BAR NUCLEAR PLANT (WBN)  
ICE CONDENSER BASKET SCREWS REPORT

Introduction

The purpose of this document is to provide reconciliation of differences in information contained in the June 2, 1995 report (first report), an intermediate endorsement on June 12, 1995, and the June 19, 1995 report (second report) from TVA Central Laboratory on Watts Bar ice condenser basket screws. This reconciliation will address differences in data and terminology presented in each document, and also assess the impact of inclusion or exclusion of information from either report. An itemized listing of these differences has been prepared by TVA Central Laboratories Metallurgical Section, and the results are shown in Attachment A. Also, Central Laboratories has prepared a detailed comparison of the similarities and difference in information for each screw sample set in each report. These results are given in Attachment B. The attachments were reviewed by the TVA Nuclear (TVAN) Chief Metallurgical Engineer and will be used in conjunction with each report as the basis for this reconciliation effort.

Discussion

The primary difference between the two reports center around information that was either included in, or excluded from, the second report which was dated June 19, 1995. More specifically, this reconciliation will address the following four items.

1. The second report deletes customer provided background statements.
2. The second report deletes the "bulletized" conclusion section which was contained in the first report, thereby, omitting some of the information that was contained therein.
3. Pertinent information regarding cracks found in a new screw from sample sets A and B, which was given in the first report, was omitted from the second report. Also, the second report differed in terminology when referring to the new screw from set "A".
4. Additional test data and results, which were not presented in the first report due to time restraints, along with data from additional testing (which was requested after issuance of first report), was presented in the second report.

A detailed discussion of each of these issues is provided as follows.

EXHIBIT 34

PAGE 2 OF 20 PAGE(S)

Signature

A Cherry

Date

10/26/98

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950248

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

Items 1 and 2

The deletion of information from the second report pertaining to Items 1 and 2 was based on the fact that much of the information was not, nor could be, substantiated through metallurgical laboratory testing. In referring to Item 1, Report 1 states that "the customer indicated that the screws were cyclically cooled and warmed between 15°F and room temperature. The customer also indicated that the screws were probably over-torqued when installed." In Item 2, the bulletized conclusion (2) also addresses possible over-torqueing, and contributes it to stresses higher than design limits. The conclusion (7) also states that thermal cycling may have initiated micro cracking. Based on a review of the first report during June 1995, no objective evidence from metallurgical testing or document review was provided regarding stresses exceeding design limits or that the ice condenser was thermally cycled. Upon discussion with Central Laboratory personnel, it was concluded that this information was included in the report based on verbal input from the customer and was not necessarily the results of any findings from laboratory analyses. It was also concluded and agreed to that Central Laboratory personnel did not have access to information regarding design limits nor did they have first hand knowledge pertaining to operational mode of the Watts Bar ice condenser. Therefore, it was jointly agreed between Central Laboratory personnel participating in this evaluation and the TVAN corporate and site engineering representatives to remove the above information from the June 19, 1995 (second report) since testing did not provide any objective evidence which could support those conclusions.

The remaining information captured in these bullets was essentially integrated into the text of the second report with few modifications.

Item 3

The next major issue pertains to omission of metallurgical data and results regarding pre-existing cracking in new screws. The first report states that "similar cracks were discovered in the new screw received in set "A" and in the transverse section of a new screw sample examined from set B." It also refers to Figure 7 which shows a 400X as polished transverse view of a crack present in a new screw from set B. However, in the second report, the terminology differed when addressing the new screw from set "A", and also there was a total omission of any information pertaining to cracking in the new screw from set B.

The second report refers to the new screw from set "A" as being "one whole screw that was not in service." This statement leads one to assume that the new screw and whole screw is "one in the same," indicating that it was a new screw directly from Power Stores. However, the assumption may be misleading, because there is no evidence that any new screws from set "A" were ever checked out of Power Stores and submitted to TVA Central lab for this evaluation. Upon conferring with site personnel, the screws origin could not be verified, but it is postulated that the screw was probably one of the screws that was retrieved from the ice condenser floor and submitted along with the fractured screws of set "A" for metallurgical evaluation. Examination of this screw showed evidence of what is considered to be fabrication induced cracking which was restricted to the case or surface hardened region. This finding was

Signature

*[Handwritten Signature]*

Date

10/26/98

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950248

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

documented in the first report and subsequent endorsement. The second report makes a comparison between features (fracture surface deposits) which indicate fabrication induced case cracking in set "G" screws and the whole screw from set "A". Therefore, based on the metallurgical evidence contained in the first report and the relative comparison which was discussed in the second report, it is concluded that the whole screw from set "A" most probably experienced cracking during the fabrication process.

The information regarding pre-existing cracking in a new screw from set "B" is contained in the first report only. Neither the endorsement or the second report mentions any evidence of cracking in this screw set. However, the evidence from the first report suggests that cracking did occur during the fabrication process. This should have been considered an important finding by the Central Laboratory Metallurgical Staff and should have been included in the second report which was issued to the site. Failure to include such pertinent information could impact or alter corrective actions employed to address this issue.

The primary reason provided by Central Laboratory personnel for omission of statements from the second report pertaining to cracking in the new set "B" screw is given as follows.

The first report was done on an emergency basis and all samples received were not completely analyzed. After issuing the first report a request was made to perform additional testing/analysis on those screws that were not addressed in the initial report. The results of the additional request was initially documented in the intermediate endorsement. However, after it was determined that a second report would need to be issued in order to address certain unsubstantiated information contained in the first report, it was decided to also incorporate the additional test results in the second report. In order to maintain the flow of the original report, the initial figure 7 was reconfigured to include these results. Figure 7 was selected because the cracking observed in the original figure 7 (depicting samples A and B) was similar to that observed in sample H and in the "whole screw A" depicted in the revised figure 7. Therefore this substitution of H instead of B documented a similar cracking mode but failed to capture the fact that the cracking observed in B was from a new screw.

An explanation pertaining to the omission of this information was documented by informal memorandum from "Delsa Frazier, Metallurgical Engineer Central Laboratory and Field Testing Services" to "Terry R. Woods" dated September 3, 1998. Based on the information provided in this memorandum, and subsequent interview of Central Laboratory personnel involved in this effort, the data pertaining to cracking in the new screw was inadvertently omitted from the second report during efforts to prevent duplication of similar failure mode while maintaining the flow of the first report.

Item 4

Additional testing was performed on screws from all sample sets after issue of the first report. This testing consisted of additional hardness measurements and metallographic examinations to further document the condition of the screw

Signature

*D. Perry*

Date

10/26/98

EXHIBIT

34

PAGE 4 OF 20 PAGE(S)

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950246

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

material. Also, Central Laboratory personnel performed impact type testing at room temperature and 15°F on screws from sets A, B, C, and G, and the results were issued in the second report.

The most important finding from additional metallography was that a slack quench microstructure was identified in certain portions of screws from sets B and H. This finding showed that the microstructure was not homogeneous throughout. A quenched and tempered (Q&T) microstructure is considered to be the preferred microstructure for this application because it yields optimum mechanical properties. Slack quenching results in a mixed microstructure (i.e., ferrite plus pearlite plus bainite) and tends to lower mechanical properties of the material. However, since some screws that contained cracks were not specifically examined for slack quenching, and some screws which were cracked showed cracking in the Q&T portion instead of slack quench region, it is inconclusive as to the role or effect this mixed microstructure may have played, if any, in the cracking of these screws.

Additional hardness testing showed values which were consistent with those presented in the first report. However, it is noted that the average core hardness in all screws tested from both the first and second report exceeded the Westinghouse Specification of 40 HRC. A comparison of these hardness values to the observed microstructure determined that the slightly higher average core hardness values did not have an adverse effect on the mechanical properties of the material.

Results of the screws that were broken in the lab, both at room temperature and 15°F, showed fracture surfaces that were consistent with surface hardening type heat treatments in medium carbon steels. A cleavage type fracture was noted (in general) in the hardened outer surface and void coalescence (ductile type failure) was noted (in general) in the core. Although surface cracking may have been previously observed in some of the screws, this testing, along with the micro-hardness traverse suggest that the overall heat treatment produced desirable core properties in the material.

Conclusion

The most important finding from the reconciliation effort was that information regarding possible fabrication induced cracking in a new screw (1 of 12) from set "B" was omitted from the second report. This information, if evaluated independently, may have suggested that a fabrication or process deficiency exist which could result in screws not meeting minimum required properties for the intended application. Also, key information regarding mixed microstructure and "impact type" testing was addressed in the second report and was not part of the first report. Its significance is that, although the mixed microstructure is not considered optimum, the laboratory impact test results along with hardness measurements indicates that the overall core metallurgical properties were adequate for the intended application. Each of these findings are important in that they should be considered when determining appropriate corrective action for adequately addressing this issue.

EXHIBIT 34  
PAGE 5 OF 20 PAGE(S)

Signature *D. Perry*

Date 10/26/98

ORIGINAL

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950248

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

ATTACHMENT A

CENTRAL LABORATORIES SERVICES (CLS)  
INVESTIGATION INTO DIFFERENCES IN WATTS BAR  
ICE CONDENSER BASKET SCREWS  
CLS REPORT 95-1021 DATED 6/2/95 (E13 950602 302)  
CLS REPORT 95-1021 DATED 6/19/95 (E13 950619 303)

1. First report states that the screws were zinc plated, while second report states that screws had a coating of zinc plating, cadmium plating, or zinc phosphate. The second report clarifies source of the screw description and also included that the customer requested verification of material type.
2. Wording on description of screws state that one was new (1<sup>st</sup> report) versus one had not been in service (2<sup>nd</sup> report).
3. First report contains statements from the customer (cyclically cooled between 15 deg F and room temperature) and the screws were probably over-torqued when installed. Second report does not state this.
4. Both reports list the chemical results that were found on a representative/typical screw, but second report states from which screw (screw "A") the data was reported. The second report states that the screws were probably zinc phosphate coated, but the data is listed in both reports.
5. The first report does not have microhardness traverse graphs included to indicate carburization, but both reports talk about higher carbon values than those for AISI 1022 steel and Table III, which shows a difference in case to core hardness which would indicate carburization.

Signature

L E Gerry

EXHIBIT 34

PAGE 6 OF 20 PAGES

Date 10/26/98

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950246

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

- 6. In the fractography section, both reports discussed the examination of screw "A" (failed) and a screw from "G". A different micrograph is shown in Figure 7 for new screw "A" (1<sup>st</sup> report) versus whole screw "A" (2<sup>nd</sup> report). The second report does not mention set "B" (figure 7), and the first report does not mention set "H" (figure 7). Figure 7 is different in each report.
- 7. The 1<sup>st</sup> report does not mention the particular screw in which the presence of zinc was found, but both talk about pre-existing cracks, laps at the tip, face and roots of every screw. But there is no mention in second report of fatigue.
- 8. More explanation was given in the second report concerning the other screws in which no photographic documentation is shown, but the information concerning the screws is given by saying that "similar cracks" were found both in the new and used screws."
- 9. The specific screws that were broken at CLS are not mentioned by name in the 1<sup>st</sup> report. Additional screws were broken at 15 deg F and reported in the second report (possibly additional info from customer). First report used the word "ductile" and "brittle" while the second report refers to it as "void coalescence" and "cleavage", respectively - both words indicating the same type of failure. The 2<sup>nd</sup> report discussed "quasi-cleavage", here again, the 1<sup>st</sup> report states "more ductile" and "more brittle," both stating a mixed mode of failure.
- 10. Because the additional time to do testing on set "H", "G", and "B", metallography was performed and reported in the 2<sup>nd</sup> report. A different microstructure was discovered showing slack quenching.
- 11. Possible conclusions were not bulleted in the 2<sup>nd</sup> report as in the 1<sup>st</sup>, but the lower ductility of the screws were mentioned in the 2<sup>nd</sup> report when cleavage or brittle fractures were discussed. No mention of high stress appears in the 2<sup>nd</sup> report, nor design limits.

Signature L. Perry

Date 10/26/98

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950248

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

- 12. The presence of stress concentrators is mentioned in both reports in the discussion of laps found at tips, face, and roots.
- 13. Corrosion is not mentioned in the 2<sup>nd</sup> report as a possible failure mechanism, but is mentioned at the beginning of the second report as being present in the threaded region.
- 14. Carbon content, higher values for some samples is mentioned in both reports, but no tie back to lower ductility expected in the 2<sup>nd</sup> report.
- 15. Pre-existing cracks (quench cracks) were mentioned in the 2nd report when the intergranular were discovered in the traverse section of the whole screw from set "A".
- 16. The second report does not mention thermal changes on the material, but tests were performed in the 2<sup>nd</sup> report to indicate that this was a concern (testing at 15 deg F).
- 17. The endorsement to the 1<sup>st</sup> report (E13 950612 303) lists which samples had a slack quenched microstructure.

Signature A. Perry

Date 10/26/98

EXHIBIT 34

PAGE 8 OF 20 PAGE(S)

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950248

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

ATTACHMENT B

INFORMATION ON SAMPLES FROM 95-1021

SAMPLE A - FRACTURED

1<sup>st</sup> Report:

- Received ten fractured screw heads
- Corrosion product observed on screws mostly in the threaded region
- Possibly case hardened -- higher carbon content and microhardness readings
- Screws failed in a brittle manner as indicated by the intergranular failure mode seen on all screws. Final fracture area was ductile
- Metallography showed a secondary intergranular crack above the fracture surface
- Lappings from the forming process was observed in the face and root and along pitch of the screws.
- General microstructure was tempered martensite.
- Factors leading to failure: lower ductility, over-torquing, stress concentrators, corrosive environment, quench cracks, thermal cycling.
- Failure mode was intergranular separation and the mechanism was stress overload

Endorsement of June 12, 1995

- Not mentioned.

2<sup>nd</sup> Report:

- Received ten screw heads that were in service
- Varying amounts of corrosion product was observed mostly in the threaded portion
- Chemistry was similar to 1022 carbon steel.
- Possible case hardened - higher carbon content and microhardness readings
- Fractography showed a intergranular failure, brittle surface. Final fracture area near the center of the shank was ductile.
- Metallography showed secondary intergranular cracks above the fracture surface
- Set "A" that was not in service - just says a crack not secondary crack.
- Microstructure is given as tempered martensite.
- Failure mode was intergranular separation.

Signature

A. Perry

Date

10/26/98

EXHIBIT 34

PAGE 9 OF 20 PAGE(S)

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950248

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

SAMPLE A - NEW OR NOT IN SERVICE

1<sup>st</sup> Report:

- One screw received
- Chemistry was similar to AISI 1022 carbon steel.
- Possibly case hardened - from chemistry
- Intergranular cracks (metallography) were found in tooth roots
- Laps and cracks were found in the new screws (not identified as to which new screw) - 2<sup>nd</sup> Paragraph, 2<sup>nd</sup> page
- New screw (not identified) was fractured in the laboratory to determine failure mode. Intergranular fracture in the case and mixed mode in the core was observed.
- General microstructure was tempered martensite

Endorsement of June 12, 1995:

- Cracks found in screw.
- Note that orientation was not the same on all samples, therefore cutting may have been done in an area that was not slack-quenched or did not have cracks.
- Could not be evaluated for metallography as destroyed in previous tests.

INFORMATION ON SAMPLES FROM 95-1021

SAMPLE A - NEW OR NOT IN SERVICE (Continued)

2<sup>nd</sup> Report:

- Whole screw that was not in service received for testing
- Chemistries similar to 1022 carbon steel, zinc phosphate coating found on surface
- Possibly case hardened - high carbon content and microhardness readings
- Intergranular cracks were discovered in a transverse section of the screw
- Lapped regions were discovered at the tip, face, and roots of every screw that was examined and is typical of the thread rolling process
- Whole screw fractured in the lab and failed by quasi-cleavage in the case and void coalescence in the core
- Microstructure was tempered martensite

Signature



Date

10/26/98

EXHIBIT 34

ORIGINAL

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950248

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

SAMPLE B - NEW SCREWS

1<sup>ST</sup> Report:

- Twelve screws received
- Possible case hardened at the thread tip - listed in text, but improperly identified in Table III
- Carbon steel - met carbon and sulfur requirements for AISI 1022
- Intergranular cracks found in transverse section
- All screws had laps from forming process
- Cracks in the thread roots
- General microstructure consisted of tempered martensite
- New screw (not identified) was fractured in the laboratory to determine failure mode. Intergranular fracture in the case and mixed mode in the core was observed

Endorsement of June 12, 1995:

- New set of twelve screws submitted for metallography
- No cracks found
- Slack-quenched microstructure
- Note that orientation was not the same on all samples, therefore cutting may have been done in an area that was not slack-quenched or did not have cracks.

2<sup>ND</sup> Report:

- Twelve new screws received
- Chemistry similar to 1022 carbon steel
- Case hardened at the tip not the root of the threads based on microhardness in Figure 3, improperly identified in Table III
- Laps found in the tip, face, and roots of the threads
- Simulated testing by fracturing samples at 15°F showed the failure mode to be void coalescence
- Microstructure consisted on tempered martensite
- Slack quenched region found in the thread roots

Signature



Date

10/26/98

EXHIBIT 34

PAGE 11 OF 20 PAGE 101

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950248

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

SAMPLE C

1<sup>ST</sup> Report:

- Two samples received
- Case hardened - higher carbon content
- May be 1022 carbon steel - carbon higher

INFORMATION ON SAMPLES FROM 95-1021

SAMPLE C - 1<sup>ST</sup> Report (Continued)

- All screws had laps from forming process
- Used screw not identified in simulated laboratory fracture testing that produced intergranular fracture at the case and mixed mode fracture at the core
- Tempered martensitic structure
- Used screws possibly harder due to higher carbon content

Endorsement of June 12, 1995:

- One of two samples contained cracks
- No slack quenched observed
- Note that orientation was not the same on all samples, therefore cutting may have been done in an area that was not slack-quenched or did not have cracks.

2<sup>ND</sup> Report:

- Two screws received
- Chemistry similar to 1022 carbon steel
- Case hardened based on carbon content
- Intergranular cracks found in thread roots
- Simulated testing by fracturing samples at 15°F showed the failure mode to be void coalescence
- Tempered martensitic structure

Signature



Date

10/26/98

EXHIBIT 34

PAGE 12 OF 20 PAGE(S)

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER60246

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

SAMPLE D

1<sup>ST</sup> Report:

- Two screws received
- Screws appeared to be case-hardened because of carbon amounts
- All screws examined have laps from forming process
- Used screw (not identified) in simulated laboratory fracture testing that produced intergranular fracture at the case and mixed mode fracture at the core
- Tempered martensitic structure
- Used screws possibly harder due to higher carbon content

Endorsement of June 12, 1995:

- No cracks found
- No slack quenching observed
- Note that orientation was not the same on all samples, therefore cutting may have been done in an area that was not slack-quenched or did not have cracks.

2<sup>nd</sup> Report:

- Two samples received
- Case hardened - microhardness results and chemistry has high carbon content
- Similar to 1022 carbon steel
- No cracks found in examined sections
- Laps found
- Tempered martensitic structure

INFORMATION ON SAMPLES FROM 95-1021

SAMPLE E

1<sup>ST</sup> Report:

- Two samples received
- Screws appeared to be case-hardened because of carbon amounts
- All screws examined have laps from forming process
- Used screw (not identified) in simulated laboratory fracture testing that produced intergranular fracture at the case and mixed mode fracture at the core
- Tempered martensitic structure
- Used screws possibly harder due to higher carbon content

Signature

*L. Perry*

Date

10/26/98

EXHIBIT 34

PAGE 13 OF 20 PARTS  
SAP 3.1.1 (04-06-98)

ORIGINAL

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950246

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

Endorsement of June 12, 1995:

- No cracks found
- No slack quenching observed
- Note that orientation was not the same on all samples, therefore cutting may have been done in an area that was not slack-quenched or did not have cracks.

2<sup>nd</sup> Report:

- Two samples received
- Case hardened -chemistry has high carbon content
- Similar to 1022 carbon steel
- Laps found
- Tempered martensitic structure

SAMPLE F

1<sup>st</sup> Report:

- Two samples received
- Screws appeared to be case-hardened because of carbon amounts
- All screws examined have laps from forming process
- Used screw (not identified) in simulated laboratory fracture testing that produced intergranular fracture at the case and mixed mode fracture at the core
- Tempered martensitic structure
- Used screws possibly harder due to higher carbon content

Endorsement of June 12, 1995:

- No cracks found
- No slack quenching observed
- Note that orientation was not the same on all samples, therefore cutting may have been done in an area that was not slack-quenched or did not have cracks.

2<sup>nd</sup> Report:

- Two samples received
- Case hardened -chemistry has high carbon content
- Similar to 1022 carbon steel
- Laps found
- Tempered martensitic structure

Signature

*A Perry*

Date

10/26/98

EXHIBIT

34

PAGE 14 OF 20 PAGES

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950246

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

INFORMATION ON SAMPLES FROM 95-1021

SAMPLE G

1<sup>ST</sup> Report:

- Two samples received
- Screws appeared to be case-hardened because of carbon amounts and microhardness results
- Intergranular cracks found in roots of threads
- Presence of zinc in cracks
- All screws examined have laps from forming process
- Used screw (not identified) in simulated laboratory fracture testing that produced intergranular fracture at the case and mixed mode fracture at the core
- Tempered martensitic structure
- Used screws possibly harder due to higher carbon content

Endorsement of June 12, 1995:

- No mention in this report

2<sup>ND</sup> Report:

- Two samples received
- Case hardened - microhardness results and chemistry has high carbon content
- Similar to 1022 carbon steel
- Intergranular cracks found in thread roots
- Presence of zinc in crack
- Laps found
- Screw fractured in the lab and failed by intergranular fracture in the case and mixed mode failure in the core.
- Tempered martensitic structure
- Could not be checked for slack quench as destroyed by other testing

Signature L. Perry

Date 10/26/98

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950248

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 1  
CLOSURE VERIFICATION (continued)

SAMPLE H

1<sup>st</sup> Report:

- Two samples received
- Screws appeared to be case-hardened because of carbon amounts
- All screws examined have laps from forming process
- Used screw (not identified) in simulated laboratory fracture testing that produced intergranular fracture at the case and mixed mode fracture at the core
- Tempered martensitic structure
- Softer than new screws

Endorsement of June 12, 1995:

- One sample had cracks
- One sample was slack quenched
- Note that orientation was not the same on all samples, therefore cutting may have been done in an area that was not slack-quenched or did not have cracks.

INFORMATION ON SAMPLES FROM 95-1021

SAMPLE H Continued

2<sup>nd</sup> Report:

- Two samples received
- Case hardened - microhardness results and chemistry has high carbon content
- Similar to 1022 carbon steel
- Intergranular cracks found in thread roots
- Laps found
- Slack quench structure observed
- Tempered martensitic structure

Both reports mention the fact that the samples that had been in service contained corrosion products.

Signature

*R. Berry*

Date

10/26/98

EXHIBIT 34

PAGE 16 OF 20 PAGE(S)

ORIGINAL

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950246

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 3  
CLOSURE VERIFICATION

The following is additional information regarding Westinghouse evaluation of the data collected from Corrective Actions number 1 and 2. This is in the form of a technical position relating to the two reports and issues that may have not been addressed in the closure of this PER in 1995. A PER was written to address these issues (98-013477-000), and to ensure a cross reference of the two PERs, this supplemental information is being provided.

Problem Evaluation Report 98-013477-000

As part of the corrective actions for Problem Evaluation Report WBPER950246, TVA Central Lab was requested to perform a metallurgical evaluation of Ice Condenser sheet metal screws. Central Laboratories Services issued two variations (June 02, 1995 & June 19, 1995) of the same technical report with the same identification number (Report No. 95-1021). In closure of WBPER950246, a statistical evaluation of the Ice Condenser system was performed by Westinghouse for a global qualification without addressing each specific issue identified in the metallurgical reports. This PER addresses the differences in the two reports and the information (i.e., manufacturing induced quench cracks and core hardness values in excess of design specification values) that was not specifically addressed in 1995. Refer to the attached "RECONCILIATION OF WATTS BAR NUCLEAR PLANT (WBN) ICE CONDENSER BASKET SCREWS REPORT", which provides a detailed evaluation of the two 1995 reports, and provides metallurgical details on the sheet metal screws analyzed by TVA.

There are 1944 ice basket columns in the WBN Westinghouse ice condenser containment system. Each column is 48 feet in length and contains eight mechanical connections with 12 sheet metal screws in each connection or 186,624 total screws (Ref 1). Considering the large number of screws installed in this system and the very small number of broken screw heads found in April of 1995, it was determined that a statistical evaluation performed by Westinghouse would provide adequate confidence that the ice condenser containment system would function as designed.

Based on a random distribution of failed ice basket sheet metal screws throughout the ice bed there is a one in seven million chance (probability equals  $1.43 \times 10^{-7}$ ) that 3 sheet metal screws could be missing from the same mechanical connection. Since the probability of 3 screws missing is so hypothetical, the evaluation was performed assuming 2 of 12 screws missing. The random distribution of failed ice basket screws was justifiable based on the fact that the entire ice bed was loaded and weighed utilizing the same procedures and operations used prior to the discovery of the broken screw heads (Ref 1).

The 1995 evaluation concluded, based on analysis, that the ice basket couplings were acceptable to perform their function against all design basis accident loads and surveillance loadings with a minimum of 10 sheet metal screws in lieu of the 12 specified (Ref 1). This analysis, coupled with the statistically low probability of missing more than two screws per connection, formed the basis for resolving the 1995 PER.

Signature



Date

10/26/98

EXHIBIT 34

PAGE 17 OF 20 PAGE(S)

PROBLEM EVALUATION REPORT (PER)  
CONTINUATION FORM

PER NO.: WBPER950246

REVISION: 0

PER CONTINUATION

SPECIFY block number being continued

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

D. SUPPLEMENTAL INFORMATION TO CORRECTIVE ACTION STEP 3  
CLOSURE VERIFICATION (continued)

After the 1995 evaluation was performed for WBN, problems with ice basket screws were identified again in January 1998 at the D. C. Cook Nuclear Power Plant. The finding of problems with ice basket screws at Cook resulted in the reexamination of the 1995 Westinghouse evaluation for WBN. Specifically, the metallurgical examinations performed by TVA in 1995 identified valuable information (i.e., manufacturing induced quench cracks and core hardness values in excess of design specification values - Ref 2) that was not specifically addressed in 1995. The Westinghouse statistical and analytical analysis justified the technical adequacy with 10 of 12 screws, but did not address the screw failure mode. TVA and Westinghouse have assessed the conclusions reached in 1995 (incorporating the findings of the 1995 metallurgical examinations) and determined that the results were and are still appropriate. Westinghouse has re-reviewed the metallurgical examinations performed by TVA in 1995 and concluded that all examined and tested screws were furnished by Westinghouse to Watts Bar and all had mechanical properties which would meet all design basis requirements (Ref 3). As concluded in the attached reconciliation report, the metallurgical evaluation of the WBN ice condenser screws indicated intergranular cracks in the case hardened surface; however, the laboratory impact test results along with hardness measurements indicates that the overall core metallurgical properties of the screws are adequate for the intended application.

Westinghouse has determined that approximately 6% of the sheet metal screw population may contain some sort of thread root cracking based on an evaluation of screws from D. C. Cook (Ref 3). Also, additional testing conducted by Westinghouse in 1998 has demonstrated that any 4 of the 12 (i.e., 33%) screws in each mechanical connection could be missing and still meet design requirements (Ref 3). Therefore, since the 182 screws identified (less than 0.1% of the total) as broken (170 in 1995 plus 12 in 1998), are significantly less than the 33%, it is concluded that the statistical evaluation performed in 1995 and the conclusion reached is still valid and does not represent an unresolved safety issue at Watts Bar Nuclear Plant.

REFERENCES:

1. Westinghouse report MSE-REE-1371 dated June 22, 1995 (available through closure package for - Problem Evaluation Report WBPER950246 - T42 961219 833).
2. Westinghouse letter NSD-NRC-98-5784 to NRC dated August 28, 1998 (T28 981021 800).
3. Westinghouse letter WAT-D-10560 to J. E. Maddox dated September 28, 1998 (T28 981008 800).

Prepared By: Howard A. Cusick

Date: October 21, 1998

Reviewed By: Lawrence E. Perry

Date: October 21, 1998

Signature



Date

10/26/98

PER CONTINUATION

SPECIFY block number being continued.

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

C.4 CLARIFICATION TO CAUSAL FACTOR ANALYSIS

Engineering reviewed the lab report of June 19, 1995 and concluded that this report supports the causal factor analysis and the apparent cause of this event as being the inadvertent over tightening of these screws.

D. CLARIFICATION TO CORRECTIVE ACTION STEP 3 COMPLETION  
VERIFICATION

The corrective action step 3 was for "NE to request Westinghouse to evaluate the data collected from corrective action numbers 1 & 2" and the corrective action completion verification statement stated "As evident from Westinghouse letter WAT-D-10048 (RIMS NO. T30950623836) Westinghouse evaluated the broken ice baskets screws and determined that the ice condenser may be considered operable for the defined deviations (see Tab G2)". Although Westinghouse did not mention the Central Laboratories Services reports in their WAT-D-10048, Westinghouse did receive the report via FAX on June 8, 1995. Westinghouse performed a statistical evaluation to establish the probability associated with two and three sheet metal screws missing from the same mechanical connection. Their statistical evaluation showed that the probability that 3 sheet metal screws are missing from the same mechanical connection was  $1.43 \times 10^{-7}$ . Consequently their evaluation focused on two sheet metal screws missing from the same mechanical connection. Their structural evaluation concluded that the connection is within allowable limits with two missing screws for DBA and seismic conditions.

D. CLARIFICATION TO CORRECTIVE ACTION STEP 4 CLOSURE  
VERIFICATION

Since a very small percentage (0.093%) of screws were found in the melt tank, and because WO# 950279100 inspected and replaced loose and missing screws as needed on accessible parts during the ice loading and weighing activity in Jan/Feb 1995, reasonable assurance existed that the screws were in place.

D. ADDITIONAL INFORMATION

Discussion with cognizant individuals revealed that no additional screws have been found in the melt tank during activities performed during the mid-cycle or the first refueling outage.

Signature  Date 12/2/97

ORIGINAL

PROBLEM EVALUATION REPORT (PER)  
Continuation Form

PER No.: WBPER950246  
LEVEL: NA  
REVISION: 0

PER CONTINUATION

SPECIFY block number being continued.

SUPPLEMENT TO PER CLOSURE PACKAGE (T42961219833)

*July 20 1997*  
*Sample*  
*PER - Lab -*  
*RIMS -*

CS EXTENT OF CONDITION

As stated in the Description of Condition the ice loading and ice weighing was completed prior to the discovery of the sheet metal screws in the melt tank. All ice baskets were lifted and weighed during the filling process. During this process one basket was dropped and reported in WBPER950026. This incident was unrelated to the screws and no other incidents occurred.

As stated in the closure package, all ice basket screws were potentially affected. Even though a small percentage (180 of approximately 194,400 or < 0.1%) of screws were discovered, an assessment of the structural adequacy for the Ice Condenser System with the described condition was required (results attached to PER).

Corrective Action Step 2 did remove several installed screws from Unit 1 ice condenser ice baskets. These screws along with some screws removed from stock were sent for testing and analysis. Westinghouse reviewed the testing and analysis and concluded that the ice condenser would be considered operable for the defined design deviation.

429-5965

Signature *L. Perry* Date 7/24/97