

July 24, 2001

Mr. Charles H. Cruse  
Vice President - Nuclear Energy  
Calvert Cliffs Nuclear Power Plant, Inc.  
Calvert Cliffs Nuclear Power Plant  
1650 Calvert Cliffs Parkway  
Lusby, MD 20657-4702

SUBJECT: CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT NOS. 1 AND 2 - REVIEW  
OF UPDATED FINAL SAFETY ANALYSIS REPORT, REV. 27 (TAC NOS.  
MB0386 AND MB0387)

Dear Mr. Cruse:

By letter dated October 24, 2000, Calvert Cliffs Nuclear Power Plant, Inc. submitted Revision 27 to the Calvert Cliffs Nuclear Power Plant Updated Final Safety Analysis Report (UFSAR). The NRC staff determined that two changes included in this revision needed further review: discussions related to license renewal and fuel assembly design.

#### License Renewal

Revision 27 contains a new Chapter 16 describing aging management programs and commitments required to be incorporated into the UFSAR in accordance with License Condition 2.F of the Calvert Cliffs renewed operating licenses. License Condition 2.F states that the next update of the UFSAR shall incorporate the UFSAR supplement submitted pursuant to 10 CFR 54.21(d), as amended and supplemented by the program descriptions contained in Appendix E to the Safety Evaluation Report Related to the License Renewal of Calvert Cliffs Nuclear Power Plant, Units 1 and 2, NUREG-1705. The list in Appendix E of the descriptions to be incorporated into the UFSAR was based on information provided in your letter dated December 6, 1999.

The staff found that 30 of the items listed in Appendix E were not incorporated into Revision 27 of the UFSAR. We discussed these items with your staff in a telephone call on November 20, 2000. Supplemental information was provided by your staff on November 28, 2000. Your staff stated that industry guidance contained in Nuclear Energy Institute (NEI) 98-03, "Guidelines for Updating Final Safety Analysis Reports," was used as the basis for not incorporating a number of the items. NEI 98-03 provides guidance for complying with the requirements of 10 CFR 50.71(e) to periodically update the UFSAR to incorporate changes and certain new information since the last UFSAR update. However, NEI 98-03 is not appropriate for deciding what information should be incorporated into the UFSAR when required by a license condition.

In reviewing the supplemental information provided by your staff and the NRC staff's bases for granting the renewed licenses, we agree that, although your December 6, 1999, letter proposed including these items in the UFSAR, these items did not need to be incorporated into the UFSAR for license renewal. These specific items were either not relied upon by the staff in making its reasonable assurance finding in accordance with 10 CFR 54.29 for issuing the renewed license, or involve commitments to complete an action that are already addressed by License Condition 2.G. In addition, License Condition 2.F provided for changes to programs described in Appendix E without prior NRC approval, pursuant to the requirements contained in 10 CFR 50.59. The enclosure to this letter provides a discussion of the staff's evaluation for each of these items.

Accordingly, the staff concludes that Revision 27 of the Calvert Cliffs UFSAR appropriately incorporates a summary description of the programs and activities for managing the effects of aging and the evaluation of time-limited aging analyses. The staff may verify that appropriate records are maintained at the plant supporting your basis for excluding the items described in the enclosure.

#### Fuel Assembly Design

UFSAR Section 3.2.3.5, "Fuel Assembly Design Limits" was modified by Revision 27 to include the following statement:

"A limited amount of blistering and spallation of the oxide layer is acceptable as long as 1 percent strain capability is preserved."

The staff has determined that this addition is not acceptable. We are aware that the Calvert Cliffs fuel has experienced some blistering and pre-spallation in recent cycles due to high duty and the use of Optin cladding. We have met with your staff and have concluded that the actions taken to address this condition are appropriate and acceptable. We are also aware that the situation should improve following replacement of the steam generators due to the increased flow through the core. In addition, it is our understanding that the Optin cladding will be replaced with Zirlo cladding, which is less susceptible to the problem, after Zirlo cladding is approved for use in Combustion Engineering reactors.

The staff does not consider operation of a reactor with blistering and spalled fuel "normal." Although a certain amount of fuel damage during normal operation is allowed for, and controlled through Technical Specification limits on coolant activity, the staff does not endorse or encourage routine operation with damaged fuel, as may be inferred through the inclusion of

C. Cruse

- 3 -

this statement in the UFSAR. Based on a telephone conference with your staff on June 29, 2001, it is our understanding that this statement will be removed in a future update of the UFSAR.

Sincerely,

**/RA/**

Donna Skay, Project Manager, Section 1  
Project Directorate 1  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket Nos. 50-317, 50-318

Enclosure: As stated

cc w/encl: See next page

this statement in the UFSAR. Based on a telephone conference with your staff on June 29, 2001, it is our understanding that this statement will be removed in a future update of the UFSAR.

Sincerely,

**/RA/**

Donna Skay, Project Manager, Section 1  
Project Directorate 1  
Division of Licensing Project Management  
Office of Nuclear Reactor Regulation

Docket Nos. 50-317, 50-318

Enclosure: As stated

cc w/encl: See next page

DISTRIBUTION:

PUBLIC PDI-1 Reading DSkay SLittle RCorreia  
RCaruso CGrimes

Accession Number: ML011930624

\*input provided by memos incorporated with no significant changes

OFFICE	PDI-1/PM	PDI-1/LA	PDI-1/ASC	SRXB:SC	RLSB:BC
NAME	DSkay	SLittle	RCorreia	RCaruso*	CGrimes*
DATE	7/23/01	7/23/01	7/23/01	07/03/01	04/23/01

**OFFICIAL RECORD COPY**

## **Evaluation of Appendix E Items not Included in the Calvert Cliffs Updated Final Safety Analysis Report (UFSAR)**

### Aging Management Programs

Table 1 lists 26 programs contained in Appendix E to the Safety Evaluation Report (SER) Related to the License Renewal of Calvert Cliffs Nuclear Power Plant, Unit Nos. 1 and 2 NUREG-1705, that were not incorporated into the UFSAR. These items relate to aging management programs for valve internals, stainless steel wire ropes, chains, damper seals, and fans. As documented in Section 3 of the SER, these components perform their intended function with moving parts or with a change in configuration or properties and are not subject to an aging management review pursuant to 10 CFR 54.21(a)(1)(i). In a letter dated November 12, 1998, the licensee stated that, although not required by the license renewal rule, an aging management review was performed for these components for its own benefit. The licensee inadvertently included these components and their associated aging management programs in the proposed list of items to be included in the UFSAR submitted by its December 6, 1999, letters and the staff subsequently included them in the Appendix E list.

Because these aging management programs involve intended functions performed by moving parts, they do not require aging management review and are not within the scope of license renewal as documented in Section 3 of the SER. Therefore, these items need not be included in the UFSAR for license renewal.

### Commitments

Table 2 lists 4 commitments contained in Appendix E that were not incorporated into the UFSAR. The licensee inadvertently included these commitments in the proposed list of items to be included in the UFSAR submitted by its December 6, 1999, letters and the staff subsequently included them in the Appendix E list.

Items 26, 78, and 82 require actions to be completed by July 31, 2014, for Unit 1, and August 13, 2016, for Unit 2. These commitments are consistent with the requirement in License Condition 2.G in the Calvert Cliffs, Units 1 and 2, renewed operating licenses for completing future actions listed in Appendix E. Therefore, License Condition 2.G should ensure that the commitments are implemented by the stated dates and the commitments need not be incorporated into the UFSAR.

Item 55 relates to managing aging effects associated with stress corrosion cracking (SCC) of the reactor vessel head closure seal leakage detection line. During the initial review of the renewal application, the staff believed that an aging management program was required for this line because of the potential for the line to refill if the reactor vessel seal leaks and the safety consequences of a leak of reactor coolant. In a letter dated October 22, 1999, the licensee provided additional information concerning this line stating that each line has an orifice in the vessel flange that limits flow rate from a break in the line to less than the normal reactor coolant system makeup capacity. These lines were removed from the scope of license renewal rule and an aging management program was no longer required. Therefore, this item need not be included in the UFSAR.

Enclosure

Item #	Components
<b>Table 1: 26 Programs in Appendix E not Included in Calvert Cliffs Updated FSAR</b>	
10	Stainless steel wire rope
14	Stainless steel and carbon steel wire rope and carbon steel chains
108	Check Valves (CKVs) and Control Valves (Cvs)
118	Cvs
123	CKV
124	Containment Isolation Valves (CIVs) of the Plant Air Subsystem
125	CKVs, Motor-Operated Valves (MOVs)
129	CKVs, Relief Valves (RVs), Hand Valves (Hvs)
131	CIVs exposed to well water
132	CIVs
133	CIVs exposed to treated water or gaseous waste
1073	Damper seals
175	Damper seals
181	Hvs
182	Damper seals
183	CIVs
184	CKVs, CVs, MOVs
193	Damper seals
196	Damper seals
211	CKVs in the gas return line to containment from the Post Accident Sampling System
215	CVs in the RCS hot leg sampling lines
216	Containment isolation solenoid valves (SVs) in the sample return lines from the reactor coolant sample hoods to the reactor coolant drain tank (TK)
221	Cvs
229	SDC header return isolation MOV outside containment and the SI leakoff return isolation HV
230	Loop inlet CKVs, SI header CKVs, and the SIT outlet CKVs.
258	Containment isolation HVs
<b>Table 2: 4 Commitments in Appendix E not Included in Calvert Cliffs Updated FSAR</b>	
26	Dome
55	Piping
78	Control Element Assembly Shroud and Bolts (shroud bolts only)
82	Applicable Components of Reactor Vessel Internals

Calvert Cliffs Nuclear Power Plant  
Unit Nos. 1 and 2

President  
Calvert County Board of  
Commissioners  
175 Main Street  
Prince Frederick, MD 20678

James P. Bennett, Esquire  
Counsel  
Constellation Energy Group  
P.O. Box 1475  
Baltimore, MD 21203

Jay E. Silberg, Esquire  
Shaw, Pittman, Potts, and Trowbridge  
2300 N Street, NW  
Washington, DC 20037

Mr. Bruce S. Montgomery, Director  
NRM  
Calvert Cliffs Nuclear Power Plant  
1650 Calvert Cliffs Parkway  
Lusby, MD 20657-4702

Resident Inspector  
U.S. Nuclear Regulatory  
Commission  
P.O. Box 287  
St. Leonard, MD 20685

Mr. Richard I. McLean, Manager  
Nuclear Programs  
Power Plant Research Program  
Maryland Dept. of Natural Resources  
Tawes State Office Building, B3  
Annapolis, MD 21401

Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Mr. Joseph H. Walter, Chief Engineer  
Public Service Commission of  
Maryland  
Engineering Division  
6 St. Paul Centre  
Baltimore, MD 21202-6806

Kristen A. Burger, Esquire  
Maryland People's Counsel  
6 St. Paul Centre  
Suite 2102  
Baltimore, MD 21202-1631

Patricia T. Birnie, Esquire  
Co-Director  
Maryland Safe Energy Coalition  
P.O. Box 33111  
Baltimore, MD 21218

Mr. Loren F. Donatell  
NRC Technical Training Center  
5700 Brainerd Road  
Chattanooga, TN 37411-4017