9.0 <u>Reference Documents</u>

The following reference documents apply to the inservice inspection performed during EOC18 (Outage 4) at Oconee 2.

Duke Energy Request for Relief 01-011

PIP O-00-03186

PIP O-01-01475

PIP O-01-01716

PIP O-01-01857

PIP O-01-02313

Fracture Mechanics Assessment Report (by Framatome ANP)

EOC18 Refueling Outage Report Oconee Unit 2 Section 9

Page 1 of 1 Revision 1 July 12, 2001

Duke Energy Corporation

Oconee Nuclear Station Units 2

Third 10-YEAR INTERVAL REQUEST FOR RELIEF NO. 01-011

Duke Energy Corporation has determined that conformance with certain ASME Section XI Code requirements is impractical. Therefore, pursuant to 10CFR50.55a(g)(5)(iii), Duke Energy requests relief from applicable portions of the code.

I. System/Component(s) for Which Relief is Requested:

A. Unit 2 Steam Generator A Primary Inlet Nozz	zzie-to-Vessel Wel	d
--	--------------------	---

<u>Unit</u>	ID Number	Item Number
2	2-SGA-WG25	B03.130.005

B. Unit 2 Steam Generator A Primary Inlet Nozzle-to-Vessel Inside Radius Section:

<u>Unit</u>	ID Number	Item Number
2	2-SGA-WG25	B03.140.005

C. Unit 2 Steam Generator A, Shell to Shell Weld

ID Number	<u>Item Number</u>
2-SGA-WG8-1	C01.010.001

D. Unit 2 Steam Generator A, Upper Tubesheet to Shell Weld

ID Number	Item Number
2-SGA-WG60	C01.030.001

E. Valve 2HP-120 to Pipe:

ID Number	<u>Item Number</u>
2HP-341-V1	C05.021.044

II. <u>Code Requirement:</u>

Examination Category B-D: Figure IWB-2500-7 (as modified by Code Case N-460). ASME Section V, Article 4, Paragraph T-424.1 states: "The volume shall be examined by moving the search unit over the examination surface so as to scan the entire examination volume."

Examination Category C-A: Figure IWC-2500-1 (a) or (b) (as modified by Code Case N-460). ASME Section V, Article 4, Paragraph T-424.1 states: "The volume shall be examined by moving the search unit over the examination surface so as to scan the entire examination volume."

Examination Category C-F-1: Figure IWC-2500-7. 10 CFR 50.55a(b)(2)(xv)(A) states: "When applying Supplements 2 and 3 to Appendix VIII, the following examination coverage criteria requirements must be used:

- (1) Piping must be examined in two axial directions and when examination in the circumferential direction is required, the circumferential examination must be performed in two directions, provided access is available.
- (2) Where examination from both sides is not possible, full coverage credit may be claimed from a single side for ferritic welds. Where examination from both sides is not possible on austenitic welds, full coverage credit from a single side may be claimed only after completing a successful single sided Appendix VIII demonstration using flaws on the opposite side of the weld."

10 CFR 50.55a(b)(2)(xvi)(B) states: "Examinations performed from one side of a ferritic or stainless steel pipe weld must be conducted with equipment, procedures, and personnel that have demonstrated proficiency with single sided examinations. To demonstrate equivalency to two sided examinations, the demonstration must be performed to the requirements of Appendix VIII as modified by this paragraph and 50.55a(b)(2)(xv)(A)."

III. Code Requirement from which Relief is Requested:

Examination Category B-D and C-A: Relief is being sought from the requirement to scan the entire examination volume.

Examination Category C-F-1: Relief is being sought from the requirement to perform examinations of stainless steel piping welds from one side using equipment, procedures, and personnel that have demonstrated proficiency with single sided examinations demonstrated to the requirements of Appendix VIII as modified by this paragraph and 50.55a(b)(2)(xv)(A).

IV. Basis for Relief:

A. Steam Generator 2A Nozzle-to-Vessel Weld 2-SGA-WG25 (Item B03.130.005) was examined to the maximum extent practical using ultrasonic techniques in accordance with the requirements of ASME Section XI, Appendix VIII, Supplements 4 and 6 of the 1995 Edition with the 1996 Addenda as administered by the Performance Demonstration Initiative (PDI). The qualifications were conducted on samples with access to both sides of the weld. Therefore, Duke Energy Corporation does not claim credit for a single sided examination. Reference Attachment A for a drawing of the Generator.

This weld is limited to 57.98% coverage of the required volume because of the nozzle configuration. In order to achieve more coverage, the nozzle would have to be re-designed to allow scanning from both sides of the weld.

B. Steam Generator 2A Nozzle-to-Vessel Inside Radius Section for welds 2-SGA-WG25 (Item B03.140.005) was examined to the maximum extent practical using ultrasonic techniques in accordance with the requirements of ASME Section XI, Appendix I of the 1989 Edition. Reference Attachment A for a drawing of the Generator.

This weld is limited to 70.21% coverage of the required volume. Limitations were caused by the ratio of the nozzle OD to the vessel thickness. When the nozzle OD is large in relation to the vessel thickness, less coverage can be obtained when scanning from the vessel side.

Nozzle inner radius sections were examined with the ultrasonic method to the maximum extent practical from the vessel wall. Calibration blocks and procedures were in accordance with ASME Section V, Article 4.

Duke Energy Corporation is investigating the use of computer modeling to resolve the coverage problem for future examinations.

C. Unit 2 Steam Generator A Shell to Shell Weld 2-SGA-WG8-1 (Item C01.010.001) was examined to the maximum extent practical using ultrasonic techniques in accordance with the requirements of ASME Section XI, Appendix VIII Supplements 4 and 6 of the 1995 Edition with the 1996 Addenda as administered by the PDI. Reference Attachment A for a drawing of the Steam Generator 2A.

This weld is limited to 50.89% coverage of the required volume because of the taper configuration. In order to achieve more coverage, the weld would have to be re-designed to allow scanning from both sides.

D. Unit 2 Steam Generator A Upper Tubesheet to Shell Weld 2-SGA-WG60 (Item C01.030.001) was examined to the maximum extent practical using ultrasonic techniques in accordance with the requirements of ASME Section XI, Appendix VIII Supplements 4 and 6 of the 1995 Edition with the 1996 Addenda as administered by the PDI. Reference Attachment A for a drawing of the Steam Generator 2A.

This weld is limited to 42.15% coverage of the required volume because of the configuration, and a support hanger and support pad interfering with UT scans. In order to achieve more coverage, the weld would have to be re-designed to allow scanning from both sides.

E. Valve 2HP-120 to Pipe Weld 2HP-341-V1 (Item C05.021.044) is limited to 61.34% coverage of the required volume because of the single sided access due to the valve configuration. In order to achieve more coverage, the valve configuration would have to be re-designed to allow scanning from both sides of the weld. Reference Attachment B for a drawing of the valve to pipe weld.

Reference Attachment C for copies of the examination records for welds addressed in this request.

V. <u>Alternate Examinations or Testing:</u>

The use of radiography as an alternate volumetric examination of the welds/components referenced in this request is not a viable option. Restrictions to performing radiography are primarily due to limited access for placement of film and component geometry. No additional examinations are planned during the current interval for ID Numbers: 2-SGA-WG25, 2-SGA-WG8-1, 2-SGA-WG60, 2HP-341-V1. Duke Energy Corporation will continue to use the most current ultrasonic techniques available to obtain maximum coverage for future examinations of these ID Numbers.

VI. Justification for the Granting of Relief:

General statement regarding C-F Piping Welds:

Current ultrasonic technology is not capable of reliably detecting or sizing flaws on the far side of austenitic weld configurations common to US nuclear plants. Duke Energy Corporation has demonstrated that the best available techniques were applied through the Performance Demonstration Initiative (PDI). The PDI Performance Demonstration Qualification Summary (PDQS) for austenitic piping certifies that examinations from one side are a "best effort". Therefore, coverage on the far side of the weld is not claimed.

The subject weld was examined to the maximum extent practical using ultrasonic techniques qualified in accordance with the requirements of ASME Section XI, Appendix VIII, Supplements 2 and 3 of the 1995 Edition with the 1996 Addenda as administered by the PDI.

Duke Energy will use pressure testing and VT-2 visual examination to compliment the limited examination coverage. The Code requires (reference Table IWB-2500-1, Item Number B15.030 and Table IWC-2500-1, Item Numbers C07.010 and C07.30) that a system leakage test be performed after each refueling outage for Class 1 items and a functional/system inservice test once each period for Class 2 items. Additionally a system hydrostatic test (reference Table IWB-2500-1, Item Number B15.031 and Table IWC-2500-1, Item Numbers C07.020 and C07.40) is required once during each 10-year inspection interval. These tests require a VT-2 visual examination for evidence of leakage. This testing will provide adequate assurance of pressure boundary integrity.

In addition to the above Code required examinations (volumetric and pressure test), there are other activities which provide a high level of confidence that, in the unlikely case that leakage did occur through these welds, it would be detected and isolated. Specifically, leakage from these welds would be detected by monitoring of the Reactor Coolant System (RCS), which is performed once each shift under procedure PT/1,2,3/A/0600/10, "RCS Leakage". This RCS leakage monitoring is a requirement of the Technical Specification 3.4.13, "Reactor Coolant System Leakage". Leakage is also evaluated in accordance with this

Technical Specification. The leakage could be detected through several methods. One method is the RCS mass balance calculation. Another method is by use of the Reactor Building air particulate monitor. This monitor is sensitive to low leak rates; the iodine monitor, gaseous monitor and area monitor are capable of detecting any fission products in the coolant and will make these monitors sensitive to coolant leakage. In addition to the radiation monitors, a level indicator in the Reactor Building normal sump also monitors leakage. Another check would be a loss of level in the Letdown Storage Tank.

Duke Energy has examined the welds/components referenced in this request to the maximum extent possible utilizing the latest in examination techniques and equipment. Duke Energy will continue to perform ultrasonic examination of all welds/components identified in Section I of this request to the maximum extent practical, within the limits of original design and construction, in accordance with the requirements of ASME Section V, Article 4, and ASME Section XI, Appendix I, of the 1989 Edition, and Code Case N-460. Appendix VIII as administered by the PDI will be used to examine piping and pressure vessel welds within the scope of the PDI qualified procedures. This will provide reasonable assurance of weld/component integrity. Thus, an acceptable level of quality and safety will have been achieved, and allowing relief from the aforementioned Code requirements will not endanger public health and safety.

These welds were rigorously inspected by radiography and liquid penetrant examination during construction and verified to be free from unacceptable fabrication defects. Duke Energy will continue to ultrasonically examine the welds, and inside radius sections, to the extent practical within the limits of original design and construction. This will provide reasonable assurance of weld/component integrity. Thus, an acceptable level of quality and safety will have been achieved and allowing relief from the aforementioned Code requirements will not endanger public health and safety.

The Code requires 100% volumetric examination of all Steam Generator Nozzle-to-Vessel Welds and Inside Radius. However, the taper on the nozzle side of the weld restricts scanning and prevents complete volumetric coverage of Steam Generator Nozzle-to-Vessel Weld 2-SGA-WG25. Therefore, the 100% volumetric examination is impractical. To meet Code examination requirements, modifications to the nozzles would be necessary to allow scanning from both sides of the weld. Modification to this portion of the reactor coolant system would be impractical. Duke Energy obtained 57.98% coverage of Steam Generator Nozzle-to-Vessel Weld 2-SGA-WG25 and 70.21% coverage of the Inside Radius. The Code requires 100% volumetric examination of all Steam Generator Shell to Shell Welds. However, taper configuration of the weld restricts scanning and prevents complete volumetric coverage of Steam Generator Shell to Shell Weld 2-SGA-WG8-1. Therefore, the 100% volumetric examination is impractical. To meet Code examination requirements, modifications to the nozzles would be necessary to allow scanning from both sides of the weld. Modification to this portion of the reactor coolant system would be impractical. Duke Energy obtained 50.89% coverage of Steam Generator Shell to Shell Weld 2-SGA-WG8-1.

The Code requires 100% volumetric examination of all Steam Generator Upper Tubesheet to Shell Welds. However, configuration of the weld and Supports restrict scanning and prevents complete volumetric coverage of Steam Generator Upper Tubesheet to Shell Weld 2-SGA-WG60. Therefore, the 100% volumetric examination is impractical. To meet Code examination requirements, modifications to the Steam Generator would be necessary to allow scanning from both sides of the weld. Modification to this portion of the reactor coolant system would be impractical. Duke Energy obtained 42.15% coverage of Steam Generator Upper Tubesheet to Shell Weld 2-SGA-WG60.

The Code requires 100% volumetric examination of the Valve 2HP-120 to Pipe Weld 2HP-341-V1. However, the valve configuration restricts scanning and prevents complete volumetric coverage of the above mentioned weld. Therefore, the 100% volumetric examination is impractical. To meet Code examination requirements, modifications to the configurations would be necessary to allow scanning from both sides of the weld. Modification of this nature would be impractical. Duke Energy obtained 61.34% coverage of the Valve 2HP-120 to Pipe Weld 2HP-341-V1.

Duke Energy obtained less than 90% coverage on all the items listed in Section I of this Request for Relief (actual percentage of coverage obtained for each item is shown in Section IV). It is recognized that this represents less than the required Code examination volume. However, this level of examination, in conjunction with the Code required VT-2 visual examination after <u>each</u> refueling outage for class 1 items and once each period for class 2 items and the 10-year hydrostatic test, provides reasonable assurance of the continued structural integrity of the subject welds/components.

Implementation Schedule: VII.

Duke Energy Corporation will continue to use ultrasonic examination procedures to obtain maximum coverage to the extent practical for inspections in future intervals of the item numbers referenced in Section I of this Request for Relief.

The following individuals were involved in the development of this request for relief:

B. W. Carney Jr., Oconee Engineering provided input to Sections V and VI of this request.


J. J. McArdle III, NDE Level III provided input for Sections II, III, IV, and V of this request.

L. C. Keith, Oconee ISI Plan Manager compiled and completed this request.

Sponsored By:

Approved By:

Rarry Co Keth Date: 7-11-01 <u>R. Juin Rhyne</u> Date: 7/11/01




IN CIRCLES		ONIOINAL	4/26/01 11/1 Barris	RELU	UUTLINE
	NO.	REVISION	DRUNIRV NDIAPPO DV	NG HO.	
			JUAVEIDATE DATE		

~

REV.

Attachment B Request for Relief 01-011

A	11 m-t	SPEC.	CRADE	Œ	SCAUP TIO	н	CONST.	\$12E	104.	
	35	SA 376	179334	PDE			SHES	5.		
8	\$\$	SA 182	F304	COLPLING	HALF (svi	FOR	 54*	12.21	NORTH 2-H
ç	\$\$	SA 182	F304	CAP ISVI			FOR	5	12.81	
0	\$\$	SA 182	F316	YALVE 2	71-1-1" 19-127	8M 24A-1179		<u>ېلې</u>	1.2	1 _ `
E					_				1	
F				ļ]	
0										
н				ļ			<u> </u>	······		
3									ļ	
<u> </u>										
<u>.</u>										
H				1						*(77)
N P									+	
0				 			┼┼		÷!	
R									┿━━┥	1
\$				<u> </u>			╆╍╍╁		+	1
Ť				+			+		÷{	
V				1			 		;	
۷	-			<u> </u>					†	1
۷				<u> </u>			t i		1	
x				1			† †		11	1
Y				1			Ť Ť			1
Z				1					1	1
					OTES					1
, VEL	DS YR	ANSFERA	CO FOAU	2-514-08	28-92					
				I D TOA	NCEED	CHAD	r			1 77.
ÓAID.V	an l		WE WE	LO TRA	NSFER	CHAR		2411	477415	2HP-119 774
0410.1 N.H0 7		ate x ve	<u>لا ۳۹۵۵۹۵</u> ۲. ۳۹۵۵۹۵	LO TRA	NSFER		r mi ne	2411	2070(3 30811	2HP-119 77 FS/2/51/61
7 7	7 8	512F X V4 215* 215*	WE 11 Transes 12 . 375 12 . 375 12 . 375		NSFER		r : wit ne	1180	277415 34943	2HP-119 FS/2/51/61
7 7 7 7	7 8 9	5.72. 5.72. 5.72. 2.72.	WE <u>x . 375</u> <u>x . 375</u> <u>x . 375</u> <u>x . 375</u>		NSFER Gete. C		i wit be		27 W.3 24 M.2	2HP-119 FS/2/51/61
7 7 7 8	7 9 4	5%. 5%. 5%. 5%.	WE <u>x</u> .375 <u>x</u> .375 <u>x</u> .375 <u>x</u> .375 <u>x</u> .375		NSFER		T i was the	11.60	277813 34982	FS/2/5:/G: /*
7 7 7 7	7 9 4 5	277. 277. 277. 277. 277.	WE <u>x . 375</u> <u>x . 375</u> <u>x . 375</u> <u>x . 375</u>		NSFER GREE				2 J W. 3 A MARA	CONT ON
7 7 7 8 8 8 8 8 8	7 9 4 5 6 A	5%. 5%. 5%. 5%. 5%. 5%. 5%.	WE x . 375 x . 375 x . 375 x . 375 x . 375 x . 375 x . 552 x . 552		NSFER		T : Via 1 . Die			FS/2/5:/G: /*
7 7 7 8 8 8 8 8 8 8 8 8 8 8	7 9 4 5 6 A 7	2.74. 2.74. 2.74. 2.74. 2.74. 2.74. 2.74. 2.74. 2.74. 2.74.	WE x . 375 x . 375 x . 375 x . 375 x . 375 x . 375 x . 552 x . 552 x . 552 x . 552		NSFER 5 Gods. cc 5 Sods. cc 5 Sod				4 v T w (3 T	CONT ON
7 7 8 8 8 8 8 8 8 8	7 9 4 5 6 A 7	5.4. 5.4. 5.4. 5.4. 5.4. 5.4. 5.4. 5.4.	WE x . 375 x . 375 x . 375 x . 375 x . 375 x . 375 x . 552 x . 552						4 (T () () ()) () () () () () () (CONT ON
7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8	7 8 9 4 5 6 A 7 8	5.4. 5.4. 5.4. 5.4. 5.4. 5.4. 5.4. 5.4.	WE x . 375 x . 375 x . 375 x . 375 x . 375 x . 375 x . 552 x . 552							CONT ON
7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8	7 8 9 4 5 6 A 7 8	5.4. 5.4. 5.4. 5.4. 5.4. 5.4. 5.4. 5.4.	WE x . 375 x . 375 x . 375 x . 375 x . 375 x . 375 x . 552 x . 552							FS/2/51/61
7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8	7 8 9 4 5 6 A 7 8	5.4. 5.4. 5.4. 5.4. 5.4. 5.4. 5.4. 5.4.	WE x . 375 x . 375 x . 375 x . 375 x . 375 x . 375 x . 552 x . 552		NSFER Godo. ve Soloris					FS/2/51/6: CONT ON - 2-HP-0293 * SEE NOTE 7
7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8	7 8 9 4 5 6 A 7 8	5.4. 5.4. 5.4. 5.4. 5.4. 5.4. 5.4. 5.4.	WE x . 375 x . 375 x . 375 x . 375 x . 375 x . 375 x . 552 x . 552		NSFER Godo. uz					FS/2/51/61
7 7 7 8 8 8 8 6 6 6 6 8 8 8 8 8 8 8 8 8	7 8 9 9 4 4 5 5 6 6 A A 7 7 8 8 9	2.22 2.22 2.22 2.22 2.22 2.22 2.22 2.2	WE 1 P(0003 X .375 X .275 X .375 X .375 X .375 X .552 X .552 X .552 X .552 X .552 X .552 X .552 X .552 X .552							FS/2/51/6: CONT ON - 2-HP-0293 * SEE NOTE 7
7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	7 9 9 4 5 5 6 7 8 9 9	24: 24: 24: 24: 24: 24: 24: 24: 24: 24:	WE 2 Pr(2043) X . 375 X . 375 X . 375 X . 375 X . 375 X . 552 X . 552 X . 552 X . 552 X . 552 X . 375 S . 542 X . 375 S . 544 L B . 94							FS/2/51/6: CONT ON - 2-HP-0293 * SEE NOTE 7
7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	7 9 9 4 5 6 6 A 7 8 9 9	24: 24: 24: 24: 24: 24: 24: 24: 24: 24:	WE 1 1×10×02 X .375 X .552 X .552 X .552 X .375 S .542 RAVDIG 0							FS/2/51/6: CONT ON - 2-HP-0293 * SEE NOTE 7
7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	7 8 9 4 5 5 6 A 7 8 9 9 1 1 4 1 5 5 1 1 1 1 1 1 1 1 1 1 1 1 1	212 Y UN 212 Y 213 Y 214 Y	WE 12 12(2) X .375 X .275 X .375 X .552 X .552 X .375 X .375 X .375 X .552 X .375 X<	E PACEECE E PACEECE E PACEECE	0 87 2 0 JODAT 2, 4					FS/2/51/6: CONT ON - 2-HP-0293 * SEE NOTE 7
7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	7 9 9 4 5 5 6 A 7 8 9 9	112 Y UN 235 235 235 235 235 235 235 235	WE 1 D(2003) X .375 X .275 X .375 X .375 X .375 X .552 X .555 X .555	E PACTECE E PACTECE LAST Try 	0 87 12 0 07 12 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0					FS/2/51/6: CONT ON - 2-HP-0293 * SEE NOTE 7
7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	7 9 9 4 5 6 6 A 7 7 8 9 9 4 5 6 A 7 7 8 9 9 4 4 5 5 6 6 A 7 7 8 8 9 9 4 4 5 5 6 6 6 7 7 8 8 9 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	είμε τ ν. είμε τ ν. είμε τ ν. είμε τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ	WE 1 D(DQC) X .375 X .375 X .375 X .375 X .552 X .552	E PACECEE LAST DX LOST DX LAST DX LAST DX ED-181A- RESS. 120 DNSIONS D	0 BY 2 0 D BY 2		2			FS/2/51/61 CONT ON 2-HP-0293 * SEE NOTE 7 **SEE NOTE 6
7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	7 9 9 4 5 6 6 A 7 7 8 9 9 4 5 6 A 7 7 8 9 9 4 4 5 5 6 6 A 7 7 8 8 9 9 4 4 5 5 6 6 6 7 7 8 8 9 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	είμε τ ν. είμε τ ν. είμε τ ν. είμε τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ τ	WE 1 D(DQC) X .375 X .375 X .375 X .375 X .552 X .552	LD TRA LA VAL NHER NHER LA VAL LA	0 BY 2 0 D BY 2		2			FS/2/51/61 CONT ON 2-HP-0293 * SEE NOTE 7 **SEE NOTE 6



			DI	JKE PC	WER	COM		٧Y			Exam Sta	art 1 [.]	105	Form	NDE-UT	-2A
	RASO	NIC E	XAMINA	TION D	ATA SHE	EET F	OR	PLANAR	REFLEC	TORS	Exam Fir	nish: 1	125	Re	evision 4	
Station	1.	(Oconee		Unit:	2	Cor	nponent/M	/eld ID: 2-	SGA-WG	25			Date:	5/17/0)1
Weld L	ength	(in.):	152	.8	Surface	Condi	tion:	AS (GROUND	Lo:	9.2.3	Surface 1	ſempera	ture:	7 <u>2</u> °.	F
				Maul				cans:				Pyromete Cal Due:			DE 2700	3
Examii	ner: Da	avid Zin	nmerman	David Kin	Level کے	:		5 🗆				Configura			e to Head	
Proced				Rev: C				т 🗆		от 🗆	dB			Flow		
		NDE-6		1		*) ⊠ <u>63</u>	3dB			N		to Surface:		_
	ation St 5, 0102		0:				60	T 🖾63	3dB				pplies t	to NDE-6		
								Other:	0°@	<u>)21</u> d	B	Skew An	gle:			
IND #	4	Max % Ref	Mp Max	W Max	L Max	L1		L2	W1	Mp1	W2	Mp2	Beam Dir.	Exam Surf.	Scan	Damps
			NOT W HIS SP			20%c HM, 50%c 100%	4 lac	20%dac HMA 50%dac 100%dac	20%dac HMA 50%dac 100%dac	20%dac HMA 50%dac 100%dac	20%dac HMA 50%dac 100%dac	20%dac HMA 50%dac 100%dac		O NOT THIS	WRITI SPACE	
NRI	0°													_		
NRI	60°										, ,			-		
<u>. </u>		L	A							·	•	L	I	<u>-</u> l	1	L <u></u>
Rema	⊰s: *F	C 00-0	8 (NDE-9	970)		·								,		
Limitat	ionst (s	see NE	E-UT-4)	⊠ 90%				ge obtaine						Sheet	c	of <u>13</u>
Reviev	ved By	H	\sqrt{N}	1000	Level:		Date		Authorized	, 			Date: 2 9 2001	Item N		
L		/Var	Y		D	•	/	1~1 (<u>e</u>	5	man	MH1 4		B03,1	30.005	

ĺ

Attachment C Request for Relief 01-011 Page 1 of 49

[

			DI	JKE PC	WER	COMF	PAN	١Y	<u> </u>		Exam Sta	art: 1	117	Form	NDE-UT	-2A
	RASO	NIC E	XAMINA	TION DA	ATA SHE	EET F	OR	PLANAR	REFLEC	TORS	Exam Fir	nish: 1	130	Re	evision 4	
Station	1:	(Oconee		Unit:	2	Con	nponent/M	Veld ID: 2-	SGA-WG	25			Date:	5/17/0)1
Weld L	ength	(in.):	152	.8	Surface	Condi	tion:	AS (GROUND	Lo:	9.2.3	Surface	Tempera	ture:	72°	F ·
			D. Leeper		Alevel	_	1	cans:					er S/N:		DE 2700	<u> 3</u>
Exami	ner: Ja	mes L.	Panel	me =	Level	: 11	4	5 🖾55	. <u>5</u> dB	70 🗆	dB		ation:			
Proced				Rev: 0	FC:		45	T 🖾 <u>55</u>	<u>.5</u> dB 7	OT 🗆	dB		62			
 				····	00	-08	60) 🗆	dB			<u> </u>	IOZZLE	to	HEAD	
Calibra		neet N	0:				60	Ţ 🗆	dB				Scan Applies t			
010209	6							Other:		d	В	Skew Ar	• •	0 1102.0	oo omy	
IND #	4	Max % Ref	Mp Max	W Max	L Max	L1		L2	W1	Mp1	W2	Mp2	Beam Dir.	Exam Surf.	Scan	Damps
		l.	NOT W HIS SP			20%d HM/ 50%d 100%	а ас	20%dac HMA 50%dac 100%dac	HMA 50%dac	20%dac HMA 50%dac 100%dac	HMA 50%dac	20%dac HMA 50%dac 100%dac	IN	O NOT		
NRI	45°			-						······································						
Remar	iks:	······································							· · · ·		·, ·	L		·	·	
1				⊠ 90%	-				d: yes 🗆					Sheet	<u> </u>	of <u>13</u>
Review	ved By	· · · · · · · · · · · · · · · · · · ·	and.	Mors	Level:] 5	Date 5./9	: F -01 c	Authorized		TPR (May	Date: 2 9 200	Item N B03.1	lo: 30.005	

Attachment C Request for Relief 01-011 Page γ of φq

ſ

	ISI LIMITATION REPORT	DUKE FUWEK CUMPANY ISI LIMITATION REPORT	1	Revision 1
Component/Weld ID: 2-SGA-WG25		Item No: B03 130 005	Remarks:	
	SURFACE	BEAM DIRECTION	NOZZLE CONFIGURATION	GURATION
LIMITED SCAN	1 1 2			
FROM L to L	INCHES FROM WO	0M WO		
ANGLE: 🖾 0 🖾 45 🖾 60 🗖 Other .		FROM DEG toDEG		
	SURFACE	BEAN: DIRECTION		
	1 2			
FROM L to L	- INCHES FROM WO	OM WO		
ANGLE: 0 0 45 0 60 0 Other		FROM DEG toDEG		
	SURFACE	BEAM DIRECTION		
LIMITED SCAN	1 1 2			
FROM L to L	INCHES FROM WO	DM WO to		
ANGLE: 0 0 45 0 60 0 Other		FROM DEG toDEG		
 NO SCAN LIMITED SCAN 	SURFACE	BEAM DIRECTION		
FROM L to L	INCHES FROM WO	OM WO to		
ANGLE: 0 0 45 0 60 0 Other		FROM DEG to		
Prepared By: // Auroly, 2	Level	Date: $OS/i7/c_i$ Sketch(s) attached	yes 🖾 no	Sheet <u>3</u> of 13
Reviewed By: Xn M	Date: 5/19/01	Authorized Inspector:	A start	Date: MAY 2 9 2001

Attachment C Request for Relief 01-011 Page 3 of 49

Attachment C Request for Relief 01-011 Page 4 of 49

		DUK		COMPAN	Y ·		NDE-91-1				
	Limited Examination Coverage Worksheet Revision 0										
	and an an a star with a local and a sec	y parametrika i pang 1963 ang 1964 nakeun	Examinati	on Volume	Area Defined	an a					
🗆 Bas	se Metal	\boxtimes	Weld	□ Near S	urface C	Bolting	Inner Radius				
		Area Calc	ulation		Vo	lume Calcula	tion				
18 SQ. 1	IN.		Cov	verage Calc	ulations						
Scan #	Angle	Beam Direction	Area Examined (sq in.)	Length Examined (៣.)	Volume	Volume Required (cu.in.)	Percent Coverage				
1	0	NA	15 7	152 8	2399	2750 4	87 22				
2	45	2	16 1	152.8	2460 1	24750 4	9 94				
3	45	1	3.4	152.8	519.5	2750.4	18.89				
4	60	2	16.9	152.8	2582.3	2750.4	93.89				
5	60	1	1.0	152.8	15.3	2750.4	0.56				
6	45	CW	8.4	152.8	1283.5	2750.4	46.67				
7	45	CCW	8.4	152.8	1283.5	2750.4	46.67				
8	60	CW	8.4	152.8	1283.5	2750.4	46.67				
9	60	CCW	8.4	152.8	1283.5	2750.4	46.67				
					13247.7	24753.6	53.52				

	Item No:	B03.130.005
Prepared By: Land Mauldui		Date: 5./7.01
Reviewed By: Hay Moss	Level: //	Date: 5-19-01
	ANII 22 Date 5/2 HSBI&I Co.	2

Attachment C Request for Relief 01-011 Page 5 of 49

50513

		DUKE		OMPANY	(NDE-91-1
	:		Revision 0				
والجندرة فيتخطره فري		ann darra a bar a bag Yalaring the bar dar ann					
🛛 Ba	se Metal		/eld	🗆 Near Su	rface 🗆	Bolting	Inner Radius
		Area Calcul	ation		Vol	ume Calcula	tion
73.7 SC	4. 113						
			Cov	erage Calcu	llations		
Scan #	Angle	Beam Direction	Cov Area Examined (sq.in.)	rerage Calcu Length Examined (in.)	Ilations Volume Examined (cu.in.)	Volume Required (cu.in.)	Percent Coverage
Scan #	Angle		Area Examined	Length Examined	Volume Examined	Required	Percent Coverage
		Direction	Area Examined (sq.in.)	Length Examined (in.)	Volume Examined (cu.in.)	Required (cu.in.)	
1	0	Direction	Area Examined (sq.in.) 40.6	Length Examined (in.) 152.8	Volume Examined (cu.in.) 6203.7	Required (cu.in.) 11261.4	55 09
2	0	Direction NA 1/2	Area Examined (sq.in.) 40.6 43.9	Length Examined (in.) 152.8 152.8	Volume Examined (cu.in.) 6203.7 7471 9	Required (cu.in.) 11261.4 11261.4	66.35

	ANII 49	Date 2124		
	b		Item No:	B03.130.005
Prepared By:	Lans Mauldui	Level:	TT	Date: 5./7-01
Reviewed By:	Dary Moss	Level:	11	Date: 5.19-0)
	Y I			


19

Attachment C Request for Relief 01-011 Page 6 of 4 9

6 05 13


		NDE-91-1						
1		Revision 0						
at 464,52.05 \$2.000 \$2.000 \$2.000 \$2.000	1	Exar	nination Vol	ume/A	rea Define	1	nie of the off particular	
Base Metal	\boxtimes	Weld	🗆 Ne	ar Sur	face	🗆 Bolting]	Inner Radius
	Area Ca	Iculation			V	olume Ca	lculat	ion
								1
							•	
			Coverage	Calcu	lations			
	Beam	Ar		ngth	Volume	Volu		
Scan # Angle	Directio	Exan ^{on} (sq		nined n)	Examined (cu in.)	Requ (cu	lirea .in)	Percent Coverage
BASE					33753 6	563	307	59.95
WELC					13247-7		53 6	53 52
					47001.3	810	60.6	57.98

	Z Date <u>S/22</u> 31&1 Co.	
	Item N	lo: B03.130.005
Prepared By: Law, Mauldur		Date: 5-/7-01
Reviewed By: Yan Mozs	Level: I	Date: 5-20-01




ANII La Date Sit


Attachment C Request for Relief 01-011 Page 7 of 49




ANII (Data 5/24
U213 2/74
HSBIALCO I



ANII <u>AZDate Zzs</u> HSBI&I Co




ANII Lad Date Sus HSBI&I Co



ANII AL Date Stry	í
HSBISI Co.	


2

.



ANII OL Data 922 HSBI&1 Co.

Co.



ANII C. Date Size HSBI&I Co.

	Ģ	
	f 01	
	lelie ∠	
c	ef H	
ner	st fc / fc	
Attachment C	Request for Relief 01-0 ⁻ age ノ午 of <i>ィ</i> タ	
łt	ja e	

Ξ

		DI	Exam St	art: 1	110	Form	NDE-UT	Г - 2А						
ULTRASONIC EXAMINATION DATA SHEET FOR PLANAR REFLECTORS									Exam Fi	nish: 1	125	R	evision 4	ł
Station:		Oconee		Unit:	2	Component	Weld ID: 2	2-SGA-W	G25			Date:	5/17/0	01
Weld Leng	h (in.):	152	.8	Surface	Condi	tion: AS	GROUND	Lo	o: 9.2.3	Surface ⁻	Tempera	ture:	72°	<u> </u>
Examiner:		71-				Scans:				Pyromete Cal Due:			DE 2700	8
Examiner:		X	Maula						70.5_dB	Configur			R RADIU	S
Procedure:	NDE-6	80 0	Rev: 2			45T 🗆	dB	70Т 🗆 _	dB	(Flow		
				N	/A	60 🖸	57dB			N		to		
Calibration	Sheet N	o:				60Т 🗆	dB					Surface:		
0102092						Othe		(dB	Skew An		co NDE-6 ス. <i>、</i> ぐ		
	Max % Ref	Mp Max	W Max	L Max	L1	L2	W1	Mp1	W2	Mp2	Beam Dir.	Exam Surf.	Scan	Damps
		NOT WI HIS SP			20%d HM/ 50%d 100%	A HMA ac 50%dac	HMA 50%dac	20%dac HMA 50%dac 100%dac	HMA 50%dac	20%dac HMA 50%dac 100%dac	D IN	O NOT	WRITI SPACE	1
NRI 60°														

Remarks:		······································	· · · · · · · · · · · · · · · · · · ·	
Limitations: (see NDE-UT-4) 90%	or greater coverage	obtained: yes 🗵 no 🗆		Sheet / of <u></u>
Reviewed By:	Level: Date:	Authorized Inspector:	Date:	Item No:
) Jan 11000	TB 5.19-	01 P.T. Stand	MAY 2 9 2001	B03.140.005

Attachment C Request for Relief 01-011 Page パケ of																	
nent C st for Re /5 of		RASO	NIC E	DU XAMINA		128		NDE-U1									
tachn Pques Ige /	Statio			Oconee		Unit:				Veld ID: 2		Exam Fil	nish: 1	145	R Date:	evision 4 5/17/0	
A R R S	Exam Exam Proce	iner: Ja iner: W dure: I ation SI	ames L. /infred C NDE-68	D. Leoper/ 80	ine 2 la	Level	:• 11	So 4 45 60	cans: 5 □ T □ 0 □ T □		70 🖾	dB	N	Tempera er S/N: ation:	ture: MCN 3/20/01 INNE Flow to Surface:	72 ° DE 2700 R RADIU S1 HEAD OD	<u>F</u> 8 S
	IND #	¥		Mp Max NOT WF HIS SP		L Max	L1 20%d HMA 50%d	ac	L2 20%dac HMA 50%dac	W1 20%dac HMA 50%dac	Mp1 20%dac HMA 50%dac	W2 20%dac HMA 50%dac	Mp2 20%dac HMA 50%dac	Beam Dir. DI	1		
	NRI	70°					100%c	uac	100%dac	100%dac	100%dac	100%dac	100%dac				

Remarks:	······································	
Limitations: (see NDE-UT-4) 90% or greater coverage obtained yes no		Sheet 2 of 24
Reviewed By: Level: Date: Authorized Inspector:	Date:	Item No:
Nay 11/020 5 5.19.01 0.7. FRANK	MAY 2 9 2001	B03.140.005

)


)

Attachment C Request for Relief 01-011 Page /6 of 49

ł

			NDE-91-1						
ann an a	Limited Examination Coverage Worksheet								Revision 0
				on Volu	me/A	rea Define	1		V al vali i sere an l'i va va si na va san di dan a sa sa sa di dan si na va sa di dan si na va sa di dan si n
🗆 Ba	se Metal		/eld	🗆 Nea	ır Sui	rface	Bolting	J	🗵 Inner Radius
		Area Calcul	ation			V	olume Ca	Icula	tion
4.7 SQ.		R CALCULATI			718.	SQ. IN. X 152.		•	
			Cov	verage C	alcu	lations			
Scan #	Angle	Beam Direction	Area Examined (sq.in.)	Leng Examii (in.	ned	Volume Examined (cu.in.)	Volu Requ (cu.)	ired	Percent Coverage
1	60/70	CW	3.3	152.8	8	504.24	718	16	70 21
2	60/70	CCW	33	152 8	9	504.24	718	-	70.21
						1008.48	1436	.32	70.21

	Item No:	B03.140.005
Prepared By: Laur Maultu:		Date: 5-17-01
Reviewed By: May Moss	Level: D	Date: 5-19-01
	ANII Date 5/24 HSBI&I Co.	3of 4



ANI	1 62 D	ate Inc
1	HSBI&I	Co.

.

DUKE POWER COMPANY ULTRASONIC DATA SHEET FOR PLANAR REFLECTORS IN FERRITIC PRESSURE VESSELS

Station:OCONEEUnit:ZComponent/Weld ID:Z-SGA-WGB-1Date:SourceWeld Length (in.):433.4Surface Condition:GEOUNDLo 9.7.1Exam Start:0930Exam Finish:1030

Procedure No:	Scans	Configuration		Calibration Sheet No:
NDE-620	70° <u>dB</u> Zone I 60° <u>75</u> dB Zone II	CIRC.	Surface Temp. <u>75 ° F</u>	0102064
Revision: <u>8</u>	60° <u>75</u> dB Zone III Axial	Scan Surface: OD	Pyrometer s/n: 27008	0102065
FC_00-07	60° <u>75</u> dB Zone III Circ.		Cal. Due Date: <u>8 2001</u>	

Indication #	2	MP _{mex}	% FSH	Lmax	Wmax	SU LOCATION	BEAM DIRECTION	SCAN	REMARKS
NRI	60°				-				KEMARAS
	ļ								
				ļ					
	<u> </u>								
	<u> </u>		·						
	<u> </u>	l					 		

> 90% Coverage obtained: yes no X (see NDE-UT-4) Limitation report is required

_Item No: 01.010.00 Examiner: <u>Jan Maullus</u> Level: <u>II</u> Date: <u>57:01</u> Examiner: <u>David K.B</u> Level: <u>II</u> Date: <u>5-12-01</u> Authorized Inspector: <u>5. Here</u> Level: ____ Date: _05/07/0 Date: 5-16-01

Page 1 of 8

Ł

DUKE POWER COMPANY ULTRASONIC DATA SHEET FOR PLANAR REFLECTORS IN FERRITIC PRESSURE VESSE

Station: OCONEE U	nit: Z	Component/Weld ID:	Z-SLA-W68-1	Date: <_7_
Weld Length (in.): 433.4	Surface Condition: (72000D Lo 9.7	Exam Start: 0930	Exam Finish: 1030

Procedure No:	Scans	Configuration		Calibration Sheet No:
NDE-620 70°	∠ dB Zone I 60° dB Zone II	Char	Surface Temp. <u>75</u> • <u>F</u>	0102066
B	dB Zone III Axial	LIRC.	Pyrometer s/n: 27008	
Revision: <u>B</u>		Scan Surface: OD		
FC 00-07 60°-	dB Zone III Circ.		Cal. Due Date: <u>82001</u>	

Indication #	2	MP _{mex}	% FSH	Lmax	Wmax	SU LOCATION	BEAM DIRECTION	SCAN	
NRI	70°							<u></u>	REMARKS
·····									
			ļ						
L	<u> </u>	L	1	[L		

> 90% Coverage obtained: yes no 🛛 (see NDE-UT-4) Limitation report is required

CO1.010.001 Item No: Mance Level: <u>I</u> Date: <u>J/2/2/</u> Examiner: <u>Level:</u> L Marco Level: <u>D</u> Date: <u>5-12-01</u> Authorized Inspector: <u>5-47-00</u> Examiner: Same Level: II Date: 5701 Reviewed by: Date: 5-16-01

Page $\frac{2}{2}$ of $\frac{8}{2}$

Attachment C Request for Relief 01-011 Page λo of $arphi \gamma$


1


	DUKE POW	'ER COMPANY		FORM NDE-UT-4			
	ISI LIMITATION REPORT						
Component/Weld ID: 2-SGA-WG8-1		Item No C01.010.001	Remarks:	 A set of the set of			
	SURFACE	BEAM DIRECTION	DUE TO TAPER	RCONFIGURATION			
☑ LIMITED SCAN	⊡ 1	□ 1 □ 2 □ cw □ ccw					
	I/A INCHES	FROM WO 0.0 to 0.7"					
		FROM 0 DEG to 360 DEG					
	SURFACE	BEAM DIRECTION	DUE TO TAPER	R CONFIGURATION			
LIMITED SCAN	⊡ 1 ⊡ 2	⊡ 1 ⊠ 2 □ cw □ ccw					
	I/A INCHES	FROM WO 0.0 to 1.0"					
ANGLE: 0 0 45 0 60 0 0th	er <u>60°RL</u>	FROM DEG toDEG					
	SURFACE	BEAM DIRECTION	DUE TO TAPER	R CONFIGURATION			
	☑ 1 ☑ 2	🗆 1 🗆 2 🗵 cw 🖾 ccw					
	VA INCHES	FROM WO to					
ANGLE: 0 0 45 0 60 0 0th	er <u>70°RL</u>	FROM 0 DEG to 360 DEG					
□ NO SCAN	SURFACE	BEAM DIRECTION	DUE TO TAPER	RCONFIGURATION			
LIMITED SCAN	∑ 1 2	🗆 1 🗖 2 🗵 cw 🖾 ccw					
	/A INCHES	FROM WO to1.1"					
		FROM 0 DEG to 360					
	Level: TTL	······································	yes 🗆 no	Sheet <u>3</u> of <u>8</u>			
Reviewed By: Jay Moss				Date: 5-16-01			
γ I ·							

Attachment C Request for Relief 01-011 Page ス/ of *49*


		NDE-91-1									
		*******	Revision 0								
	Examination Volume/Area Defined										
🖾 Bas	se Metal	J	Inner Radius								
	Area Calculation Volume Calculation										
SEE DRWGS ZONE 1 ZONE 1- 2.7 SQ. IN. 2.7 SQ. IN. X 433.5 IN = 1170.5 CU. IN. ZONES 2 & 3 - 8.6 SQ. IN ZONES 2 & 3 8.6 SQ. IN X 433.5 IN. = 3728.1 CU. IN. Coverage Calculations											
Scan #	Angle	Beam Directior		ea Le nined Exa	ngth nined in)	Volume Examined (cu in)	Volu Requ (cu	ired	Percent Coverage		
1	70°	1	2	2 43	3.5	953 7	117	05	81.48		
2	70°	2	1.	6 43	3.5	693 6	117		59 26		
3	70°	CW	1	0 43	3 5	433 5	• • 7	0.5	37 04		
4	70°	CCW	1.	.0 43	3.5	433.5	117	0.5	37.04		
5	60°	1	8.	.3 43	3.5	3598.1	372	8.1	96.51		
6	60°	2	7.	.9 43	3.5	3424.7	372	8.1	91.86		
7	60°	CW		5 43	3.5	216.8	372	8.1	5.82		
8	60°	CCW		5 43	3.5	216.8	372	8.1	5.82		
						9970.7	1959	94.4	50.89		

		Item No:	C01.010.001
Prepared By: Land Maudi			Date: 5-7-01
Reviewed By: Mar Mood	Level: D		Date: 5.12.01
			1 577 Date 576 HSBI&I Co.






___HSBI&I Co.



)

Ì



Form NUE-620

Revision 0

DUKE POWER COMPANY ULTRASONIC DATA SHEET FOR PLANAR REFLECTORS IN FERRITIC PRESSURE VESSELS

Station: Ocon	DEE Unit: II (Component/Weld ID: 2-55A	- 4660	Date: 05/16/01
Weld Length (in.)): 480.0 Surface Condition: AS	GROUND LO"X" AXIS		am Finish:1070
Procedure No: <u>NOE - 620</u> Revision: <u>8</u> FC <u>00 - 007</u>	Scans 70° <u>58.0</u> dB Zone I 60° dB Zone II 60° dB Zone III Axial 60° dB Zone III Circ.	Configuration <u>CIRC. MELD</u> Scan Surface: OD	Surface Temp. <u>70</u> ° <u>F</u> Pyrometer s/n: <u>MCJDE 2700</u> 8 Cal. Due Date: <u>8 20 01</u>	Calibration Sheet No:

Indication #	2	MP _{mex}	% FSH	Lmex	Wmix	SU LOCATION	BEAM DIRECTION	SCAN	
JRT.	70°							<u> </u>	REMARKS
	<u> </u>	· · · · · · · · · · · · · · · · · · ·		·					
·									
						1			
	<u> </u>					ļ			
								†	
	1								
		L	l		<u> </u>				

> 90% Coverage obtained: yes 🦳 no 🎽 (see NDE-UT-4) Limitation report is required

Item No: <u>(01.03</u>0.00) Examiner: Marin V. Were Level: <u>ZZ</u> Date: <u>5-16-01</u> Examiner: evel: <u>I</u>_Date: <u>5-16-01</u> MAY 2 9 2001 1025 Reviewed by: lan Date: 5-20.01 Authorized Inspector: CC7.C Level: Date: Page L of 18

DUKE POWER COMPANY ULTRASONIC DATA SHEET FOR PLANAR REFLECTORS IN FERRITIC PRESSURE VESSELS

Station: Ocover Un	it: I Component/Weld	ID: 2-567A-WG60	Date: $0 \leq / 1 \leq 1$
Weld Length (in.): 480.0	Curtary Constitution Official	\sim "X" $A_{X/S}$ Exam Start:	

Procedure No:	Scans 70° dB Zone I 60° <u>68 5</u> dB Zone II	Configuration	Surface Temp. <u>70</u> ° <u>F</u>	Calibration Sheet No: 0102090
Revision: 8	60° <u>72.5</u> dB Zone III Axial	Scan Surface: OD	Pyrometer s/n: MCJDE 27008	0102090
FC 00-007	60° <u>72. S</u> dB Zone III Circ.		Cal. Due Date: <u>820 (01</u>	


Indication #	2	MP _{max}	% FSH	Lmex	Wmaa	SU LOCATION	BEAM DIRECTION	SCAN	
	60	6.8	40	34'-8"		SZ	51	<u>д</u> К	REMARKS
	<u> </u>								
••••==••••••••••••••••••••••••••••••••	+								
	<u> </u>	l <u></u>				i			


> 90% Coverage obtained: yes

no 📕 (see NDE-UT-4) Limitation report is required

Level: <u>I</u> Date: <u>5:16.01</u> Examiner: Jumis 24 Item No: (01.030.00 Examiner: Date: 5/16/01 Level: I Level: <u>D</u> Date: <u>5-20-01</u> Authorized Inspector: <u>C.7</u> Reviewed by 2 9 2001 Toma Date: MAY

Page 2 of 18





Attachment C Request for Relief 01-011 Page 28 of 49

J


		JKE POWER						FC	RM NDE-UT-670A
Q1 11		BRATION SHE	ET FOF	R PLANA	AR FLA	WSIZING	3		Revision 3
	conee	Unit. 2	D.	ate 5/1	16/01	Sheet Nur	mber:	0102	098
Procedure:	PDI-UT-7	Rev: D	FC	D/A	Couplar	nt: UL	TRAGEL II	Batch N	o: 00325
Examiner: Jay A. Eato		>Level: II	Calibri	ation Bloc	k ID	504	70	· · · · · · · · · · · · · · · · · · ·	
Examiner: Gayle E. Ho REFERENCE BLOCK	user De Hour	Level: II	Calibra	ation Bloc	k Temp	: 72°	dea F		: 7/18/01
REFERENCE BLOCK		NSTRUMENT	I	<u> </u>	SE.	ARCH UNIT			ATOR BLOCK
ID: 97-5589	□ Staveley	Krautki	anier	T.; e:	Single	 Du	Jai 🔲		
	_			5 ze	.500	Freq:	2.25 Mhz	ID:	97-5589
Type: ROMPAS	- Model:	USK-7D				- КВ		Reflector Typ	e: SDH
Mat'l: CS	S/N:	32810-4022						CE-2:	N/A Div's
INSTRUMENT SETTING				-	<u>.</u>	0085LN		01-2.	N/A Div's
Jack: T 🗆 R 🗵				L		Wedge:	MSW-QC	Depth:	.75 in.
Range 14.1]	·····	·	ALIBRAT			<u> </u>		CABLES
Delay 5.6					/	1		ive Mode	
Vel128.3	80						Shear	\boxtimes	RG58 🗆
Units IN					1		Long.		RG174 🖾
Gain 60	Screen Div's (Tau)			\square			Bi-Moo	dal 🗌	# of connectors 0
Display FULL	Div			1					Length: 6'
Freq 1-5	40 <u>40</u>		\square			-	L		INITIAL CAL
Rej OFF						⊠ f	PATT		TIME INITIALS
Pulse HIGH				<u> </u>			M-PATT		1400 CK
Damping N/A							HALT		CAL CHECKS
RF/PRR HIGH	Depth(in)		! /	↓	<u>├</u> └	<u>↓</u> □ ₃	30-70-70 CE	-2 Div's	1430 K
Pulser		. <u>2</u> _	4	<u>ь</u>	8	10	5° Full V	"Mp	1500
Reviewed By:		Level: Date		Autho	rizod Inc			WIP	
Dau/	10000		20.01		rized Ins	A COLOR			MAY 2 9 200

)

1 4 OF 18


7

•



Reorder by Stock Code 89203

Attachment C Request for Relief 01-01 Page 31 of 49



DUKE POWER COMPANY	Form NDE-UT-
ULTRASONIC INDICATION RESOLUTION SHEET	Revision 1
Acceptance Standard: INDICATION #1 - 60° IS A SUBSURFACE INDICATION WITH AN a/t RATIO OF 3.8%. THE CC REPORTABLE PER ACCEPTANCE STANDARD: 1WB-3510-1. SEE THE ATTACHED CALCUL BEEN ISSUED FOR EVALUATION. SEE PIP+0-01-01857.	DE ALLOWS 2.2%. THIS INDICATI ATION SHEET. FORM QA 516A H/
Item No: - C01 030 001	
Item No: C01.030.001	
Item No: C01.030.001 Acceptable Indications: REPORTABLE - IND. #1 - 60°	
Acceptable Indications: REPORTABLE - IND. #1 - 60° Rejectable Indications:	data available
Acceptable Indications: REPORTABLE - IND. #1 - 60° Rejectable Indications:	data available Sheet <u>7</u> of

J

Attachment C Request for Relief 01-011 Page 33 of *ィ*タ

.....

I

	MPANY	FORM NDE-UT-4	
Component/Weld ID: 2-SGA-WG60	ISI LIMITATION REP	D: C01.030.001	Revision 1
□ NO SCAN ☑ LIMITED SCAN		BEAM DIRECTION	SUPPORT HANGER
FROM L to L44.0" ANGLE: 0 0 45 2 60 0 Other	INCHES FROM WO	9.0" to 16.0"	
D NO SCAN		BEAM DIRECTION	SUPPORT HANGER
FROM L 76.0" to L 84.0" ANGLE: □ 0 □ 45 ☑ 60 □ Other	FRC	9.0"to16.0" DEG toDEG	
□ NO SCAN ☑ LIMITED SCAN	SURFACE		SUPPORT HANGER
FROM L 116.0" to L 124.0" ANGLE: 0 0 45 60 Other		9.0" to <u>16.0"</u> DEG to <u>DEG</u>	
L NO SCAN	SURFACE		SUPPORT HANGER
FROM L 144.0" to L 152.0" ANGLE: □ □ 45 ⊠ 60 □ Other		9.0" to16.0" M DEG to	
	Level: <u></u> Date: 5		yes □ no Sheet <u>8</u> of <u>/8</u> DaMAY 2 9 2001

Attachment C Request for Relief 01-011 Page 3そ of チタ

,

	DUKE POWER COMPANY						
	ISI LIMITA	TION REPORT		Revision 1			
Component/Weld ID: 2-SGA-WG6	50	Item No: C01.030.001	Remarks:				
D NO SCAN	SURFACE	BEAM DIRECTION	SUPPORT HANGER				
☑ LIMITED SCAN		□ 1 □ 2 □ cw □ ccw					
FROM L	204.0" INCHES	FROM WO 9.0" to 16.0"					
ANGLE: □ 0 □ 45 ⊠ 60 □	Other	FROM DEG toDEG					
D NO SCAN	SURFACE	BEAM DIRECTION	SUPPORT HANGER	· · · · · · · · · · · · · · · · · · ·			
☑ LIMITED SCAN	□ 1 I 2	□ 1 □ 2 □ cw □ ccw					
FROM L _ 276.0" to L _	INCHES	FROM WO 9.0" to 16.0"					
ANGLE: □ 0 □ 45 ▷ 60 □	Other	FROM DEG toDEG					
D NO SCAN	SURFACE	BEAM DIRECTION	SUPPORT HANGER				
☑ LIMITED SCAN	□ 1 I 2	□ 1 □ 2 □ cw □ ccw					
FROM L	244.0" INCHES	FROM WO 9.0" to 16.0"					
ANGLE: 0 0 45 8 60 0	Other	FROM DEG toDEG					
□ NO SCAN	SURFACE	BEAM DIRECTION	SUPPORT HANGER	· ·			
IIMITED SCAN	□ 1 [□] 2	□ 1 □ 2 □ cw □ ccw					
FROM L	324.0" INCHES	FROM WO 9.0" to 16.0"					
		FROM DEG to					
Prepared By: Law May	ldu: Level: III	Date: 5-16.01 Sketch(s) attached	yes □ no S	heet 9_of_18			
Reviewed By: Day	Mon Date: 5.20	o - o / Authorized Inspector:	ETANA (DateMAY 2 9 20			
ΥŢ	-						

)

	DUKE POWI	ER COMPANY		FORM NDE-UT-4
	ISI LIMITAT	FION REPORT		Revision 1
Component/Weld ID: 2-SGA-WG6	60	ltem No C01.030.001	Rer	narks:
	SURFACE	BEAM DIRECTION	SUI	PPORT HANGER
☑ LIMITED SCAN	□ 1 □ 2	🖸 1 🗆 2 🗆 cw 🗔 ccw	/	
FROM L	364.0" INCHES	FROM WO9.0" to16.	0"	
ANGLE: 0 0 45 0 60 0		FROM DEG to		
	SURFACE	BEAM DIRECTION	SUF	PPORT HANGER
□ LIMITED SCAN	□ 1 □ 2	□ 1 □ 2 □ cw □ ccw	1	
FROM L to L	404.0" INCHES	FROM WO 9.0" to 16.	0''	
ANGLE: □ 0 □ 45 ⊠ 60 □		FROM DEG to		
	SURFACE	BEAM DIRECTION	SUF	PPORT HANGER
	□ 1 [□] 2	□ 1 □ 2 □ cw □ ccw	/	
FROM L 468.0" to L	472.0" INCHES F	FROM WO to16.	0"	
ANGLE: □ 0 □ 45 ⊠ 60 □		FROM DEG to		
	SURFACE	BEAM DIRECTION	SUF	PPORT PAD (48" IN LENGTH)
☑ LIMITED SCAN	□ ₁ □ ₂	□ 1 ⊠ 2 □ cw □ ccw	,	
FROM L 444.0" to L	_12.0" INCHES F	FROM WO to16,	0''	
ANGLE: □ 0 □ 45 ⊠ 60 □	Other	FROM DEG to		
		Date: 5./6.0/ Sketch(s) attach		□ no Sheet_/0_of_/8
Reviewed By: Jan / N	los Date: 5.20.	0) Authorized Inspector:	7.5	DathAY 2 9 2001
V				<i><i>y y a t a a a a a a a a a a</i></i>

	DUKE POWF	ER COMPANY		FORM NDE-UT-		
		Revision 1				
Component/Weld ID: 2-SGA-WG	60	Item No C01.030.001	Remarks:	Remarks:		
🗵 NO SCAN	SURFACE	BEAM DIRECTION	SUPPORT PAD			
		□ 1 ⊡ 2 □ cw □ ccw				
FROM L		FROM WO to16.0"				
		FROM DEG to DEG				
NO SCAN	SURFACE	BEAM DIRECTION	SUPPORT PAD			
	🖸 1 🗆 2	□ 1 ⊡ 2 □ cw □ ccw				
FROM L 166.0" to L	14.0" INCHES F	ROM WO to16.0"				
ANGLE: 🗆 0 🗆 45 🖾 60 🗆	Other 70°	FROM DEG toDEG				
NO SCAN	SURFACE	BEAM DIRECTION	SUPPORT PAD			
	🛛 1 🗖 2	🗆 1 🖾 2 🗔 cw 🗆 ccw				
FROM L		FROM WO to16.0"				
ANGLE: □ 0 □ 45 ⊠ 60 □] Other70°	FROM DEG toDEG				
	SURFACE	BEAM DIRECTION	SUPPORT PAD			
LIMITED SCAN	⊠ 1 □ 2	🗆 1 🖾 2 🗔 cw 🖾 ccw				
FROM L	404.0" INCHES F	FROM WO9.0" to16.0"				
		FROM DEG to				
		Date 5./6.0/ Sketch(s) attached	yes □ no	Sheet // of //		
Reviewed By: Jan / 1	Mors Date: 5-20-	-0] Authorized Inspector:	JE The	Date MAY 2 9		
		~ ~ ~ { ~ (~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	· · · · · · · · · · · · · · · · · · ·	£		

)

j

j

Attacnment C Request for Relief 01-011 Page 37 of *49*

		DUK	E POWER	COMP	ANY	7			NDE-91-1				
			Revision 0										
	Examination Volume/Area Defined												
⊠ Ba	☑ Base Metal ☑ Weld □ Near Surface □ Boltin							J	□ Inner Radius				
		Area Calc	ulation			Vo	olume Ca	lcula	tion				
ZONES	SEE DRWG. 17.7 SQ. IN. X 433.5 IN. = ZONES 2 & 3 7672.95 CU. IN 17.7 SQ. IN. .												
			C	overage (Calcu	lations							
Scan #	Angle	Beam Direction	Area Examined (sq in)	Leng Exam (in	ined	Volume Examined (cu.in.)	Volu Requ (cu	ired	Percent Coverage				
1	60	1	11.8	88		1038.4	155	7.6	66 67				
1	60	1	17.5	240	C	4200	42	48	98 87				
1	60	1	17.7	105	5	1867.35	1863	7 35	100.00				
2	60	2	17.7	193	.5	3424.95	3424	1.95	100.00				
2	60	2	0.0	240)	0	42	48	0.00				
3	60	CW	2.5	433	.5	1083.75	7672	2.95	14.12				
3	60	CW	2.5	433	.5	1083.75	7672	2.95	14.12				
						12698.2	307:	31.8	41.32				

	Item No	o: C01.030.001
Prepared By: have Maudu:	Level:	Date: 5/6-01
Reviewed By: Han Mos	Level:	Date: 5-20.01
	AN	II 60 Date Date

Attacnment C Request for Relief 01-011 Page 38 of *49*

			NDE-91-1				
			Revision 0				
1998 - Alfred (1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997	an amin'n an de same de mer	₩₩~+₽₩,₩₩.₩.₩.₩#############################	Examinatio	on Volume/A	rea Defined	and the second secon	n in seen franken in de fan
🛛 Bas	se Metal	⊠ W	eld	□ Near Sur	face 🗆	Bolting	Inner Radius
		Area Calcula	ation		Vol	ume Calcula	tion
SEE DRWG. ZONE 1 - 3.2 SQ. IN. X 433.3 ZONE 1 - 3.2 SQ. IN. 1387.2 CU. IN.						N. A 433.3 IN.	-
			Cov	erage Calcu	lations		
Scan #	Angle	Beam Direction	Cov Area Examined (sq in)	erage Calcu Length Examined (in)	l ations Volume Examined (cu in)	Volume Required (cu in.)	Percent Coverage
Scan #	Angle 70		Area Examined	Length Examined	Volume Examined	Volume Required	Percent Coverage
		Direction	Area Examined (sq in)	Length Examined (in)	Volume Examined (cu in)	Volume Required (cu in.)	
1	70	Direction 1	Area Examined (sq in) 3 2	Length Examined (in) 193.5	Volume Examined (cu in) 619.2	Volume Required (cu in.) 619.2	100.00
1	70 70	Direction 1	Area Examined (sq in) 3 2 2 3	Length Examined (in) 193.5 240	Volume Examined (cu in) 619.2 552	Volume Required (cu in.) 619.2 768	100.00 71.88
1	70 70 70	Direction 1 1 2	Area Examined (sq in) 3 2 2 3 3 2	Length Examined (in) 193.5 240 193.5	Volume Examined (cu in) 619.2 552 619.2	Volume Required (cu in.) 619.2 768 619.2	100.00 71.88 100.00


/]	Item No:	C01.030.001
Prepared By: Law Maudu	Level:	Date: 5./6.01
Reviewed By: Jan Moss	Level:	Date: 5.20.01
		ANII 40 Date 5 19 HSBI&I Co.


13 OF 18


Attachment C Request for Relief 01-01 Page 39 of 49


			NDE-91-1						
	!		Revision 0						
ing ang sana sa pang ang ang ang ang sana sa		a la antidada de la desarra de esta de la compositiva de la compositiva de la compositiva de la compositiva de	Exan	ninatio	on Volume/A	rea Define	d		
□ Base	Base Metal Weld Near Surface Bolting]	Inner Radius
		Area Cal	culation	<u>.</u>		V	olume Ca	Iculat	lion
				Cov	erage Calcu	lations		`	
				COV	-				
Scan #	Angle	Beam Direction	Exam	Area Length Volum amined Examined Examin sq in.) (in) (cu.in			Volu Requ (cu	uired	Percent Coverage
	70					2594.7	554		46 76
	60					12698.2 15292 9	307: 362:		41 32 42 15

	Item No:	C01.030.001
Prepared By: Lange Mauldy.	Level:	Date: 5-/6.01
Reviewed By: Yau Mos	Level: D	Date: 5-20.0/
		ANII Daty 171 HSBI&I Co.









Attachment C Request for Relief 01-011 Page 44 of 49

ł

Jconee リ


CALIBRATION SHEET # 0102005-45° & 60° # 0102011 - 60° L # COMPONENT I.D.# 2HP-341-V1 ITEM # C05.021.044 ANII 5200 Dates 52 HSB&I Co.

SHEET 1 OF 6

DUKE POWER COMPANY							Exam Sta	rt:	1408		ND	E-UT-3A				
ULTRASONIC EXAMINATION DATA SHEET FO						ET FOF	R LAMIN	AR REF	LECTO	rs [Exam Fin	ish:	1411		Re	evision 2
Station:		00	conee		Unit:	2	Component/Weld ID: 2HP-341-V1							D	ate:	1/30/01
Nominal N	Mater	ial Thicki	ness (in):		0.375		Weld Le	ength (in.)	: 9	9.03"	Surfa	ce Tempe	erature:		82	Deg F
Measured	d Mat	erial Thio	kness (ir	n):	.323''	ŕ	Lo:		9.1.1.1		Pyror	neter S/N	:	MCN	IDE 270)08
Surface C	Condi	tion:		AS GRO	UND		Calibrat	ion Sheel	No:		Cal D	Cal Due:			3/26/01	
Examiner	: Jar	nes L. Pa	anel Icm	. = 6	Leve	el: II	0102006	0102006			Confi	Configuration: Valve (Valve			HP-V23) to Reduce
Examiner			//		Z Levi		-					PIPEFic			VALV	E
Procedure	e:	NDE-		Rev: 1	Prc:	*						·	S2	_ to	S1	
	¥	Ampl ≥ rem BW LOB	L1 ≥ rem BW LOB	W1 ≥ rem BW LOB	Mp1 ≥ rem BW LOB	W2 ≥ rem BW LOB	Mp2 ≥ rem BW LOB	L2 ≥ rem BW LOB	W1 ≥ rem BW LOB	Mp1 ≥ rem BW LOB	W2 ≥ rem BW LOB	Mp2 ≥ rem BW LOB		am urf.		Damps
NRI 0)°								+		-					
												L Six Second				

Remarks: * 95-18 & 95-19					
		1	imitations see NDE-UT-4 🖾 None: 🗆	Sheet 2 of 6	
Reviewed By: Jan Mors	Level:	Date: 2 • 1 • 0 1	Authorized Inspector: Date: 5.7-01	Item No: C05.021.044	


Ţ



	DUKE POWER (COMPANY		FORM NDE-UT-4			
	ISI LIMITATION REPORT						
Component/Weld ID: 2HP-341-V1	lt	em No: C05.021.044	Remarks:				
🖾 NO SCAN	SURFACE	BEAM DIRECTION	DUE TO VALVE	CONFIGURATIION			
LIMITED SCAN		□ 1 ⊡ 2 □ cw □ ccw					
FROM L to LN/A							
ANGLE: 0 0 45 0 60 Other		FROM _ 0 _ DEG to _ 360 _ DEG					
		BEAM DIRECTION		· · · · · · · · · · · · · · · · · · ·			
LIMITED SCAN	□ 1 □ 2	□ 1 □ 2 □ cw □ ccw					
FROM L to L	INCHES FROM	1 WO to					
ANGLE: 0 0 45 0 60 0 Other							
	SURFACE	BEAM DIRECTION		·····			
LIMITED SCAN	□ 1 □ 2	□ 1 □ 2 □ cw □ ccw					
FROM L to L	INCHES FROM	1 WO to					
ANGLE: 0 0 45 0 60 0 Other							
	SURFACE	BEAM DIRECTION					
LIMITED SCAN	□ 1 □ 2	□ 1 □ 2 □ cw □ ccw					
FROM L to L	INCHES FROM	to to					
ANGLE: 0 0 45 0 60 0ther							
Prepared By: David K. Zimmerman	12 Level: II Da	ate 1/30/01 Sketch(s) attached 🗵	yes 🗆 no	Sheet 4 of 6			
Reviewed By: Jary Moss	Date: 2-1-01	Authorized Inspector: 5. Authorized		Date: 5-7-0/			

Ĵ

)



Attachment C Request for Relief 01-011 Page 49 of 49

			NDE	-91-1				
			Revi	sion 0				
Examination Volume/Area Defined								
🖾 Bas	se Meta	Bolting	🗆 In	ner Radius				
		Area Calcul	ation			Volume Cal	culation	
.12 in. X 1.0 in. = 0.12 sq.in. 0.12 sq.in. X 9.03 in. = 1.08 cu.in.								
			Cov	verage Ca	alculations			
Scan #	Angle	Beam Direction	Area Examined (sq in)	Lengt Examin (in-)	ed Examine	d Requ	red Perce	ent Coverage
1	60°	1	054	<u> </u>	0 49	1.0	8	
2	601	2	0	9.03	C	10	8	
3	45°	CW	.12	.12 9.03 1.08 1.0			8	
4	45°	CCW	.12	0.03	1.08	1.0	8	
		Shear Wave	Aggregate	Coveraç	ge 2.65	4.3	2	61.34
	60°L	Supplemental	Coverage					0.00
1	60°L	1	.066	9.03	0.6	1.0	8	55.56
								0.00

Shear Wave Aggregate Coverage = 61.34% Supplemental Coverage = 55.56% of 1 Scan (25%) = 13.89% of Total Weld

		Item No:	C05.021.044
Prepared By: David K. Zimmerman Paulit K.	Level:	11	Date: 1/30/01
Reviewed By: Lary Mauldw	Level: 🎵	7	Date: 2-/-01
		AN	II 2014 Date 5-7 HSBI&I Co.

 PIP Serial No:
 Action Category:
 LER No: Willing Comparison
 Other Report:
 Action Category:

 O-00-03186
 4

<u>Problem Identifi</u>	<u>cation</u>			
Discovered Time/Date:	07:42 08/31/2000	Occurred Time/Date:	13:00	
<u>Unit(s) Affected:</u> <u>Unit</u> <u>Mode</u> 2 1	%Power Unit Status Rema	<u>rks</u>		
<u>System(s) Affected:</u> PR	Purge			
Affected Equipment				
(No Equipment A	(ffected)			•
Location of Problem: Bldg:	Column Line:	Elev:		
Location Remarks:				
Method Used to Discover	Problem:			
<u>Srief Problem Description</u> EQUIPMENT SUPPORT I				

Detail Problem Description:

Operability Assessment:

The unit 2 filter # PR-FL-000A was inspected by P.H.Patel and Andy Wells of CEN/Civil on 8/31/00. The equipment is supported on 10 legs with a total of 20- $\frac{3}{4}$ " self drilled anchors. All anchors cannot be rotated by hand. However, five anchors have gaps between bolt head and washer varying from visual to about 1/16" and two bolts have this gap about 1/8" to $\frac{1}{4}$ ". There is a base plate that has a gap about $\frac{1}{2}$ " between concrete floor and the plate. Shims are installed at this base plate. The base plates have oversized holes. However, the drawing OM-201-0571 call for oversized 1-1/16" holes for $\frac{3}{4}$ " bolts. An inspection of other filter 2B and identical filters in units 1 and 3 have somewhat identical discrepancies. In addition, some bolts are missing for filter 1A and 3B in units 1 and 3 respectively. The Calculation OSC-1881 qualifies these equipments where the bolts are missing. The minimum factor of safety of anchorage with four missing bolts is still more than 27 against 5 required. Based on calculated safety factors in existing analysis and engineering judgement it is felt that the anchor bolts will still meet design basis requirements. A work order to add shims and washers at anchor bolts should correct the problem.

Last Updated By: PHP4260: PATEL, PARSHOTTAM H Team: RAH8344 Group: CEN Date: 08/31/2000

THIS PIP IS BEING WRITTEN TO DOCUMENT A REQUEST FOR ENGINEERING EVALUATION AND INSPECTION/REPAIR FOR EQUIPMENT ITEM #PR-FL-000A (AMERICAN AIR FILTER, 6th FLOOR PURGE/VENTILATION ROOM, UNIT 2). BASE PLATES ARE NOT BEARING ON CONCRETE, HAVE OVERSIZED HOLES AND ARE NOT SHIMMED. ANCHORS HAVE STACKED WASHERS AND, IN SOME CASES, ARE LOOSE. SIMILAR DISCREPANCIES EXIST ON UNIT 1, BUT THESE ARE DOCUMENTED ON A QAL-14A FORM FOR IN-SERVICE INSPECTION FOR THE UPCOMING UNIT ONE OUTAGE.

riginated By: PSE1290: EBERHART, PATMAN S Team: GER8996 Group: WCG Date: 08/31/2000

Other Units/Components/Systems/Areas Affected(Y,N,U): Y

Industry Plants Affected(Y,N,U): U

Immediate Corrective Actions:

Immediate Corrective Action Documents / Work Orders:

	<u>Indiv</u>	Team	Group	Date
Problem Identified By:	PSE1290 GER89	96 WCG		08/31/2000
Problem Entered By:	PSE1290 GER89	96 WCG		08/31/2000

Screening

Is the Problem Significant? No Action Category: 4

Condition Adverse to Quality:

. •

OEP No:

Other Report Nos:

Event Codes:

F3 Equipment Out of Norm

Screening Remarks:

This event has been reviewed by the CST and found not to meet the MSE significance criteria.

Screening members present for this review: Barry Loftis (ENG), Randy Todd (RGC), RD Burns (MNT & WCG), and Mike Pruitt (OPS).

Originated By: EHD8302: DUMMEYER, EDWARD H Team: RTB7310 Group: SRG Date: 08/31/2000

Assignments:

Responsible Groups(s) for Problem Evaluation:	Responsible Group	for Present Operability:	N/A
Responsible Group for Past Operability:	N/A		
Responsible Group for Reportability:	N/A		
Responsible Group for Overall PIP Approval:	WCG	Work Control	

Signature Type	Indiv	Team	Group	Date	
Screened By:	EHD8302	RTB7310	SRG	08/31/2000	

Present Operability

Responsible Group:

Status:

Sys/Comp Operable? (Y,N,C,E,T):

_ Required Mode:

Comments:

No Current Signatures For This Section

P	ast	0	<u>perability:</u>

Status:

Sys/Comp Operable?(Y,N,C,E,T):

Required Mode:

Comments:

No Current Signatures For This Section

Reportability

Responsible Group:

Status:

Problem Reportable(Y,N,E):

Reportable Per:

Comments:

No Current Signatures For This Section

Group:

N/A

Investig	ation	Rep	ort:
ATCT COULS	<i>a</i> ~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		<u></u>

Responsible Group:

Act Date:

Investigator:

Due Date: Date Due to VP or Sta. Mgr: Date Regulatory or Agency Rpt Due: Date Investigation Report Approved:

NRC Cause Codes:

Problem Evaluation

 Event
 Cause Code
 Cause Description
 Primary
 Causing Groups

Problem Evaluation From:

Corrective Actions

CA Seq. No: 1

	Resp Group	Status	Orig Group	Event Code	Prop CAC	Cause Code
-1	RES	Closed	RES	F3	B9	YYY

Proposed Corrective Action:

Per the operability assessment, "A work order to add shims and washers at anchor bolts should correct the problem." Therefore, this CA is initiated to document the origination of the required WR/WOs.

Originated By: SNS3927: SEVERANCE, SANDRA N Team: CAL7344 Group: CEN Date: 09/01/2000 Last Updated By: SNS3927: SEVERANCE, SANDRA N Team: CAL7344 Group: CEN Date: 09/15/2000

Signature Type	😒 Indiv 🔬 🖓	Team A	Group Sale	Date State State
Approval Assigned To:	CAL7344	CAL7344	RES	09/01/2000
Ready For Approval:	SNS3927	CAL7344	RES	09/15/2000
Approved By:	SNS3927	CAL7344	RES	09/15/2000

General:Outage: INNAGE 71 Mo

Mode: N/A

Other Tracking Processes

Type	Number TextWO	98311831 Install washers and shims: 1-PEN-ROOM-FLTR-A.	
WO	98336960	Install washers: 1-PR-FLTR-B.	. •
WO	98337015	Install washers/shims: 2-PR-FLTR-A & B.	
WO	98337079	Install washers/anchor: 3-PR-FL-A & B.	

Actual Corrective Action:
Priority: 12dActual CAC: B9Status: ClosedDue Date: 11/30/2000Following work orders are originated to add shims/washers and/or missing bolts.Due Date: 11/30/2000

WO# 98311831 for 1-PR-FL-000A. (this WO was originated due to noted ISI inspection discrepancy) WO# 98336960 for 1-PR-FL-000B. WO# 98337015 for 2-PR-FL-000A and 000B. WO# 98337079 for 3-PR-FL-000A and 000B.

Originated By: PHP4260: PATEL, PARSHOTTAM H Team: RAH8344 Group: CEN Date: 11/30/2000

Signature Type	Indiv	Team A Market was	Group	🗠 🕘 Date
Accepted By:	RAH8344	RAH8344	RES	09/18/2000
Assigned To:	PHP4260	RAH8344	RES	09/18/2000
Due Date:	11/30/2000			
Ready For Approval:	PHP4260	RAH8344	RES	11/30/2000
Approval Assigned To:	RAH8344	RAH8344	RES	11/30/2000
Approved By:	RAH8344	RAH8344	RES	11/30/2000

Final and Overall PIP Approval

Responsible Group: WCG Status: Closed

Signature Type	Indiv	Team	Group	Date	
Assigned To:			WCG	08/31/2000	
Approval Assigned To:	JNW8302	JNW8302	WCG	12/01/2000	
Approved By:	JNW8302	JNW8302	WCG	02/14/2001	

Any Supplemental Concurrence Signatures Above Do Not Affect PIP Closure.

Closure Document Type Closure Document No

Attachments

Generic Applicability

Responsible Group: Status: GO PIP No:

Assessment Remarks:

No Current Signatures For This Section

Failure Prevention Investigation

No FPI Records for this PIP.

<u>Remarks</u>

No Remarks for this PIP.

Maintenance Rule

No Maintenance Rule Records for this PIP.

End of the Document for PIP No: The status of this PIP is: The duration of this PIP was: O-0-3186 Closed 167 days

 PIP Serial No:
 Action Category
 LER No:
 Other Report:

 O-01-01475
 3

Problem Identification

Discovered Time/Date:	09:00 04/30/2001	Occurred Time/Date:	13:00 04/26/2001
Unit(s) Affected: Unit Mode 2 6	<u>%Power Unit Status Rema</u> 0 N/A	<u>rks</u>	
System(s) Affected: LPS	Low Pressure Service Wate	r	
Affected Equipment			
(No Equipment A	ffected)		
Location of Problem: Bldg: TB	Column Line:	Elev:	
Location Remarks:			
Method Used to Discover	Problem:		

ISI

Brief Problem Description:

Pipe support # 2-14B-1437A-SR38 is incapable of restraining its design seismic loads.

Detail Problem Description:

ISI identified that the lugs on S/R# 2-14B-1437A-SR38 on the east side of the Turbine Building wall are only 1/2" tall instead of 3" tall. This support has 2 lugs on each side of the TB/AB wall to restrain the pipe in the east/west (axial) direction. The 1/2" tall lugs are not tall enough to bear against the pipe sleeve and restrain the pipe in the west direction. The lugs on the west side of the TB/AB wall are 3" tall and do restrain the pipe in the east direction.

Thermal loads on this support are in the east direction and are being restrained. However, this support is incapable of restraining westerly seismic forces.

This problem was discovered by Engineering on 4/26/01, but impact on current operability requirements was not realized until 4/30/01. This support is located downstream of valve 2LPSW-251 on the 2A LPI Cooler discharge piping. This section of piping does have operability requirements during MODE 5 and 6.

Operability Assessment

An operability evaluation will be required. This piping is not clearly inoperable and there is a reasonable assurance this piping is Operable But Degraded/Nonconforming.

Originated By: PAW4981: WELLS, PHILLIP A Team: RAH8344 Group: MCE Date: 04/30/2001

Other Units/Components/Systems/Areas Affected(Y,N,U): N

Industry Plants Affected(Y,N,U): U

Immediate Corrective Actions:

Work order 98384067 has been initiated to repair these lugs and restore the support to design conditions.

Originated By: PAW4981: WELLS, PHILLIP A Team: RAH8344 Group: MCE Date: 04/30/2001

Immediate Corrective Action Documents / Work Orders: 98384067

	Indiv	<u>Team</u>	<u>Group</u>	Date
Problem Identified By:	PAW4981	RAH8344	MCE	04/30/2001
Problem Entered By:	PAW4981	RAH8344	MCE	04/30/2001

Screening

Is the Problem Significant? No Action Category: 3

Condition Adverse to Quality: Yes

OEP No:

Other Report Nos:

Event Codes:

Equipment Out of Norm

Screening Remarks:

F3

This event has been reviewed by the CST and found to meet the criteria for the selected action category.

Screening members present for this review: Sandy Severance (ENG), Sammy Oates (MNT & WCG), Randy Todd (RGC), and Mike Pruitt (OPS)

Originated By: EHD8302: DUMMEYER, EDWARD H Team: RTB7310 Group: SRG Date: 04/30/2001

Assignments:

Responsible Groups(s) for Problem Evaluation:	MCE
Responsible Group for Present Operability:	MCE
Responsible Group for Past Operability:	RGC
Responsible Group for Reportability:	RGC
Responsible Group for Overall PIP Approval:	MCE

Mech/Civil Eq. Eng. Mech/Civil Eq. Eng. Regulatory Compliance Regulatory Compliance Mech/Civil Eq. Eng.

Signature Type	Indiv	Team Team	Group	Date Date	
Screened By:	EHD8302	RTB7310	SRG	04/30/2001	

Present Operability

Responsible Group: MCE Status: Closed

Sys/Comp Operable? (Y,N,C,E,T): Y

Required Mode: 6

Comments:

Last Updated By: PCC2458: CHAU, PETER C Team: RAH8344 Group: MCE Date: 05/02/2001

- 1. Statement of Problem Support 2-14B-1437A-SR38 could not perform its design function.
- 2. Relation to QA Condition Both piping and support are QA 1.
- 3. Applicable codes And standards USAS B31.1 Code for Pressure Piping (1967).
- Evaluation Inputs/Methods Used USAS B31.1 Code.
 SUPERPIPE Computer Analysis.
- 5. Other Evaluation Criteria N/A
- 6. Applicable Licensing References UFSAR Section 9.2.2.2.3
- 7. Assumptions None.
- 8. References OSC-487 Rev. 30
- 9. Calculation/Evaluation

The piping system has been re-analyzed without the subject support. The results show that both piping and associated supports are below design allowable limits.

The piping and associated supports evaluation are documented in OSC-474 rev. 30.

- 10. Compensatory Actions Required for Operability None.
- 11. Conclusions
 - The piping and supports are operable.
 - The piping and associated supports have been reviewed and found to be within design limit.

Originated By: PCC2458: CHAU, PETER C Team: RAH8344 Group: MCE Date: 05/02/2001

Signature Type	Indiv	Team	Group	Date
Due Date:	05/03/2001			
Accepted By:	RAH8344	RAH8344	MCE	05/01/2001
Assigned To:	PCC2458	RAH8344	MCE	05/01/2001
Ready for Checked By:	PCC2458	RAH8344	MCE	05/02/2001
Checked By Assigned To:	BHJ8363	RAH8344	MCE	05/02/2001
Checked By:	BHJ8363	RAH8344	MCE	05/02/2001
Ready For Approval:	BHJ8363	RAH8344	MCE	05/02/2001
Approval Assigned To:	RAH8344	RAH8344	MCE	05/02/2001
Approved By:	RAH8344	RAH8344	MCE	05/02/2001
Evaluation Assigned To:	JAS7314	LEN2127	RGC	05/03/2001
Evaluated By:	JASMITH	LEN2127	RGC	05/08/2001

Past Operability:

Status: NotRequired RGC Responsible Group:

Sys/Comp Operable?(Y,N,C,E,T):

Required Mode:

Comments:

No Current Signatures For This Section

Reportability

Status: Closed Responsible Group: RGC

Ν Problem Reportable(Y,N,E):

Reportable Per:

Comments:

Operability eval has concluded that the inoperability of this support did not impact the operability of the system/train as a whole. Therefore, this event is not reportable.

Originated By: RPT7314: TODD, RANDALL P. Team: LEN2127. Group: RGC. Date: 05/08/2001

	Signature Type	Indiv .	Team	Group	Date
_	Assigned To:	RPT7314	LEN2127	RGC	04/30/2001
	Ready For Approval:	RPT7314	LEN2127	RGC	05/08/2001
	Approval Assigned To:	LEN2127	LEN2127	RGC	05/08/2001
	Approved By:	LEN2127	LEN2127	RGC	05/10/2001

Investigation Report:

Act Date: Responsible Group:

Investigator:

Group:

Due Date: Date Due to VP or Sta. Mgr: Date Regulatory or Agency Rpt Due: Date Investigation Report Approved:

NRC Cause Codes:

Problem Evaluation

Event	Code	Cause Description	Primary	Causing Gloups
53	X	UNKNOWN	Yes	UNK

OEDB Checked: No Problem Evaluation From: Resp. Group: MCE Status: Closed

Problem was created during original construction of this support. Even with discrepancy, piping meets design requirements. No problem evaluation is required. Likewise, no additional insights can be gained from performance of problem evaluation.

Originated By: RAH8344: HEINECK, ROBERT A Team: RAH8344 Group: MCE Date: 05/14/2001

OEDB Comments:

OEDB check is not needed to aid in resolution of this problem.

Originated By: RAH8344: HEINECK, ROBERT A Team: RAH8344 Group: MCE Date: 05/14/2001

Remarks Comments:

Signature Type	05/30/2001			
Assigned To:		RAH8344	MCE	05/02/2001
	RAH8344	RAH8344	MCE	-05/14/2001
Accepted By:	RAH8344	RAH8344	MCE	05/14/2001
Ready For Approval:	RAH8344	RAH8344	MCE	05/14/2001
Approval Assigned To: Approved By:	RAH8344	RAH8344	MCE	05/14/2001

Corrective Actions

CA Seq. No: 1

-					
	and the second	•••	Erent Code	$D_{ron}(\Delta)$	
Resp Group	Stotuc Status		EVCIIL COUR		Cause Code
Resp Gloup	Juano				3 (3 / 3 /
			17.2	20	YYY
MCE	Closed	MCE	r5	D7	
	CIUSCU	INCE			

Proposed Corrective Action:

Confirm that repairs to restore full capability of S/R 2-14B-1437A-SR38 are complete.

Originated By: RAH8344: HEINECK, ROBERT A Team: RAH8344 Group: MCE Date: 05/02/2001

Signature Type	Indiv	Team	Group	Date
	RAH8344	RAH8344	MCE	05/02/2001
Ready For Approval.		RAH8344	MCE	05/02/2001
Approval Assigned To:		RAH8344	MCE	05/02/2001
Approved By:	<u> </u>	KAH6544	Mee	

Mode: N/A General: Outage: 2EOC18

Number TextWO 98384067

Repair Lugs on S/R# 2-14B-1437A-SR38

Actual Corrective Action:

Other Tracking Processes

<u>Type</u>

Due Date: 05/24/2001 Status: Closed Actual CAC: B9 Priority: O2d Work order 98384067 was written to replace the deficient lugs on S/R# 2-14B-1437A-SR38. This work order is scheduled for implementation during startup at end of 2EOC18. The system was determined to be OPERABLE without this support. Therefore, no further actions are required for this corrective action.

Originated By: PAW4981: WELLS, PHILLIP A Team: RAH8344 Group: MCE Date: 05/24/2001

Signature Type	n Indiv	Team Team	Group Group	A B Date till Asia Lisen Corre
Accepted By:	RAH8344	RAH8344	MCE.	05/02/2001
Assigned To:	PAW4981	RAH8344	MCE	05/02/2001
Due Date:	05/24/2001			
Ready For Approval:	PAW4981	RAH8344	MCE	05/24/2001
Approval Assigned To:	RAH8344	RAH8344	MCE	05/24/2001
Approved By:	RAH8344	RAH8344	MCE	05/24/2001

Final and Overall PIP Approval

Responsible Group: MCE Status: Closed

Signature Type	Indiv	Team	Group	Date
Assigned To:			MCE	04/30/2001
Accepted By:	SNS3927	TDC7309	MCE	05/02/2001
Approval Assigned To:		RAH8344	MCE	06/07/2001
Approved By:	RAH8344	RAH8344	MCE	06/18/2001

Any Supplemental Concurrence Signatures Above Do Not Affect PIP Closure.

Closure Document Type Closure Document No

Attachments

Generic Applicability

Responsible Group: Status: GO PIP No:

Assessment Remarks:

No Current Signatures For This Section

Failure Prevention Investigation

Quality of CA:

Quality of Cause:

Resp Group: SRG

Status: Closed

Special Codes: N12

Comments

Signature Type	Indiv	Team	Group	Date
Assigned To:			SRG	04/30/2001
Ready For Approval:	RWVASSEY	RTB7310	SRG	05/15/2001
Approval Assigned To:	RTB7310	RTB7310	SRG	05/15/2001
Approved By:	RWVASSEY	RTB7310	SRG	05/15/2001

<u>Remarks</u>

No Remarks for this PIP.

MPFF: No

Maintenance Rule

Responsible Group: MCE

Status: Closed

	Maintenance Rule SSC		
SSC	Description	Risk Primary Significant System	
LPS	Low Pressure Service Water System	None Yes	

Equipment Group: C01 Applicable Unit: Unit 2 Functional Failure: No

Repetitive MPFF: No

Functional Failure Comments:

Per the Present Operability Section of this PIP, the piping and supports are presently operable. Thus, no functional failure occurred.

Originated By: VBB4478: BOWMAN, VANCE B Team: BGD7309 Group: MCE Date: 06/05/2001

MPFF Comments:

Repetitive MPFF Comments:

Reactor Trip: NoSafety System Actuation: No Loss of Heat Decay Removal: NoForce Outage Rate or Plant Transient: NoLoss Of Spent Fuel: No

Comments:

Signature Type	Indiv	Team	Group	Date	
Assigned To:	VBB4478	BGD7309	MCE	05/02/2001	
Due Date:	06/13/2001				
Ready For Approval:	VBB4478	BGD7309	MCE	06/05/2001	
Approval Assigned To:	BGD7309	BGD7309	MCE	06/05/2001	
Approved By:	BGD7309	BGD7309	MCE	06/05/2001	

End of the Document for PIP No: The status of this PIP is: The duration of this PIP was: O-1-1475 Closed 49 days

٠

 PIP Serial No:
 Action Category:
 ULER No:
 Other Report:

 0-01-01716
 3

Problem Identification

Discove	red Time/	<u>Date:</u>	16:28 0	5/10/2001	Occurred Time/Date:	13:00	
<u>Unit(s)</u>	Affected: Unit 2	<u>Mode</u> 6	<u>%Power</u> 0	<u>Unit Status Remar</u> 2EOC18 Refueling			
System	(<u>s) Affecte</u> MS	<u>.d:</u>	Main Ste	eam			
Affected	d Equipm	<u>ent</u>					
	(No Equ	ipment A	(fected)				
<u>Locatio</u>	<u>n of Prob</u> Bldg: R	<u>lem:</u>	Column	Line:	Elev:		
Location Remarks: 36" MS pipe riser to SG 2A at El. 854"							
	Method Used to Discover Problem: Routine Inservice Inspection.						
	roblem De		-		3		

Deficiency in constant spring support 01A-O-1481B-H11B.

Detail Problem Description:

Last Updated By: RAH8344: HEINECK, ROBERT A Team: RAH8344 Group: MCE Date: 05/21/2001

The constant spring support 01A-O-1481B-H11B has only two shear lugs taking vertical load, the other two shear lugs have gap between the pipe clamp and shear lugs which renders them in-active.

Specifically, the shear lug at North-West has .04" gap and shear lug at North-East has .16" gap according to ISI Item Number F01.022.002.

The subject support is used to restraint the 36" Main Steam piping from Penetration 26 to Steam generator 2A. It is shown on OFD-122A 2.1. The piping is qualified in OSC-1315-06 Rev. D10.

The piping is class F which is designed for dead weight, thermal, seismic, and water hammer loading. The design temperature and pressure are 630 F and 1050 psig respectively.

PIPING OPERABILITY ASSESSMENT.

The unit 2 is in refueling outage; therefore, there is no current operability concern.

t should be noted that the piping is past and present operable according to the stress calculation. With two shear lugs in services, the lug stress = 2 x 7548 = 15096 psi. Total EQ. 8 stress = 15096 psi + 6978 psi (pipe stress) = 22074 psi < 2 x 25400 = 50800 psi (operability allowable).

Additional Operability Assessment Information (Added by RAH 5-21-01): PIP 010-1910 documents a scheduling error that caused the work identified to resolve this ISI discrepancy to be deferred until the next refueling outage. Accordingly, the current operability section of this PIP needs to be completed to document a NCI because of exceeding design allowable stresses. This evaluation must be completed prior to entering Mode 4.

Originated By: PCC2458: CHAU, PETER C Team: RAH8344 Group: MCE Date: 05/10/2001

Other Units/Components/Systems/Areas Affected(Y,N,U): N

Industry Plants Affected(Y,N,U): U

Immediate Corrective Actions:

WO# 98386779 has been written to restore the subject support to its design configuration.

Originated By: PCC2458: CHAU, PETER C Team: RAH8344 Group: MCE Date: 05/10/2001

Immediate Corrective Action Documents / Work Orders:

	Indiv	<u>Team</u>	Group	Date
Problem Identified By:	PCC458C	RAH8344	MCE	05/10/2001
Problem Entered By:	PCC458C	RAH8344	MCE	05/10/2001

Screening

Is the Problem Significant? No	Action Category: 3	Condition Adverse to Quality: Yes
--------------------------------	--------------------	-----------------------------------

OEP No:

Other Report Nos:

Event Codes:

F3	Equipment Out of Norm
O2a	ASME SECTION XI

Screening Remarks:

This event has been reviewed by the CST and found to meet the criteria for the selected action category.

Screening members present for this review: Sandy Severance (ENG), RD Burns (MNT & WCG), Randy Todd (RGC), and Mike Pruitt (OPS).

Originated By: RWV1470: VASSEY, RAY W Team: RTB7310 Group: SRG Date: 05/14/2001

Assignments:

Responsible Groups(s) for Problem Evaluation:	MCE	Mech/Civil Eq. Eng.
Responsible Group for Present Operability:	MCE	Mech/Civil Eq. Eng.
Responsible Group for Past Operability:	N/A	
Responsible Group for Reportability:	RGC	Regulatory Compliance
Responsible Group for Overall PIP Approval:	MCE	Mech/Civil Eq. Eng.

Signature Type	Indiv	Team	Group	Date	
Screened By:	EHD8302	RTB7310	SRG	05/21/2001	

Present Operability

Responsible Group: MCE Status: Closed Sys/Comp Operable? (Y,N,C,E,T): T Required Mode: 4 Comments: Last Updated By: PCC2458: CHAU, PETER C Team: RAH8344 Group: MCE Date: 05/23/2001 1. Statement of Problem Two of the four shear lugs on the spring support 01A-0-1481B-H11B can not carry vertical load due to gaps betwwen pipe clamp and shear lugs. 2. Relation to OA Condition The piping and subject support are QA 1. 3. Applicable codes And standards USAS B31.1 Code for Pressure Piping (1967). 4. Evaluation Inputs/Methods Used SUPERPIPE Computer Program for piping analysis. LUGS Computer Program for shear lugs evaluation. 5. Other Evaluation Criteria None. 6. Applicable Licensing References UFSAR Chapter 10.3 "Main Steam System". 7. Assumptions None. 8. References 1) OSC-1315-06 Volume A. 2) ASME Appendices F 9. Calculation/Evaluation The shear lug stress is evaluated in Ref. 1. The lug stress is 7548 psi for four (4) shear lugs to carry the vertical load of 29834#. Since only two (2) lugs are actually carrying the load, the lug stress is 2 x 7548 psi = 15096 psi.

The piping material is SA155 KC 70 with a yield stress of 27600 psi at 650 F. Stress intensity Sm = 17500 psi @ 650F. It should be noted that 2 x yield is approximately equal to 3 x Sm in Table F-1322.2-1

EQ 8 stress = 6978 psi + 15096 psi = 22074 psi > 17500 psi	The lugs fail design limits.
EQ 9 stress = 7681 psi + 15096 psi = 22777 psi > 21000 psi	The lugs fail design limits.
EQ 9F stress = 7911 psi + 15096 psi = 23007 psi < 27800 psi	The lugs pass design limits.
EQ 10 stress = 2695 psi + 15096 psi = 17791 psi > 26250 psi	The lugs pass design limits.

The piping pass operable limits:

6978 psi + 7911 psi + 15096 psi = 29985 psi < 2 x 27600 psi = 55200 psi O.K.

10. Compensatory Actions Required for Operability

None.

11. Conclusions

The piping is operable with NCI which is the two shear lugs having gaps with the pipe clamp.

Originated By: PCC2458: CHAU, PETER C Team: RAH8344 Group: MCE Date: 05/23/2001

Signature Type # 55577	Indiv 📲 🖓	Team 👬 👘 👘	Group	Date 11 5 4 20 10
Due Date:	05/24/2001			
Accepted By:	RAH8344	RAH8344	MCE	05/22/2001
Assigned To:	PCC2458	RAH8344	MCE	05/22/2001
Checked By Assigned To:	BHJ8363	RAH8344	MCE	05/23/2001
Ready for Checked By:	PCC2458	RAH8344	MCE	05/23/2001
Checked By:	BHJ8363	RAH8344	MCE	05/23/2001
Ready For Approval:	BHJ8363	RAH8344	MCE	05/23/2001
Approval Assigned To:	RAH8344	RAH8344	MCE	05/23/2001
Approved By:	RAH8344	RAH8344	MCE	05/23/2001
Evaluation Assigned To:	JAS7314	LEN2127	RGC	05/24/2001
Evaluated By:	JAS7314	LEN2127	RGC	05/24/2001

Past Operability:

Responsible Group:

Status:

Sys/Comp Operable?(Y,N,C,E,T):

Required Mode:

Comments:

No Current Signatures For This Section

Reportability

Responsible Group: RGC Status: Closed

Problem Reportable(Y,N,E): N

Reportable Per:

Comments:

Per Operability Evaluation, the piping is still operable despite the hanger issue. Therefore, there is no los of safety function and this event is not reportable.

Originated By: RPT7314: TODD, RANDALL P Team: LEN2127 Group: RGC Date: 05/29/2001

Signature Type	Indiv	Team	Group	Date	
Assigned To:	RPT7314	LEN2127	RGC	05/22/2001	
Ready For Approval:	RPT7314	LEN2127	RGC	05/29/2001	
Approval Assigned To:	LEN2127	LEN2127	RGC	05/29/2001	
Approved By:	LEN2127	LEN2127	RGC	05/31/2001	

Investig	nation	Re	nort
mvesng	anon	ne	<u>pon.</u>

Responsible Group:		Act Date:
Investigator:	Group:	
Due Date: Date Due to VP or Sta. Mgr:		

Date Due to VP or Sta. Mgr: Date Regulatory or Agency Rpt Due: Date Investigation Report Approved:

NRC Cause Codes:

Problem Evaluation

Eve	ent Code	Course Descention 1		Causing Grou	ups
02:	a X	UNKNOWN	Yes	UNK	·

Problem Evaluation From: Resp. Group: MCE Status: Closed OEDB Checked: No

The lack of bearing between pipe support and welded lugs was likely caused during original construction, though that cannot be substantiated. No further cause evaluation is required because of the age of the problem and lack of benefit from further research.

Originated By: RAH8344: HEINECK, ROBERT A. Team: RAH8344. Group: MCE. Date: 05/29/2001

OEDB Comments:

No benefit from further research of this problem.

Originated By: RAH8344: HEINECK, ROBERT A Team: RAH8344 Group: MCE Date: 05/29/2001

Remarks Comments:

Signature Type	Indiv	Team	Group	Date	
Due Date:	06/09/2001				
Accepted By:	RAH8344	RAH8344	MCE	05/29/2001	
Assigned To:	RAH8344	RAH8344	MCE	05/29/2001	
Ready For Approval:	RAH8344	RAH8344	MCE	05/29/2001	
Approval Assigned To:	RAH8344	RAH8344	MCE	05/29/2001	
Approved By:	RAH8344	RAH8344	MCE	05/29/2001	

Corrective Actions

CA Seq. No: 1

Resp Group	Status	Orig Group	Event Code	Prop CAC	Cause Code
MCE	Closed	MCE	F3	J	YYY

Proposed Corrective Action:

insure that the operability assessment associated with this item is completed prior to entering Mode 4.

Per the problem description, "The constant spring support 01A-O-1481B-H11B has only two shear lugs taking vertical load, the other two

shear lugs have gap between the pipe clamp and shear lugs which renders them in-active. PIP 010-1910 documents a scheduling error that caused the work identified to resolve this ISI discrepancy to be deferred until the next refueling outage. Accordingly, the current operability section of this PIP needs to be completed to document a NCI because of exceeding design allowable stresses."

Originated By: SNS3927: SEVERANCE, SANDRA N Team: TDC7309 Group: MCE Date: 05/22/2001

Signature Type	Indiv (States)	ሩ 🕬 🖓 🕹 Team at 🖬 🛠 🐨 👘	Group 👬	ter the Date State Stat
Ready For Approval:	SNS3927	TDC7309	MCE	05/22/2001
Approval Assigned To:	TDC7309	TDC7309	MCE	05/22/2001
Approved By:	SNS3927	TDC7309	MCE	05/22/2001

General:Outage: 2EOC18 Mode: 4

Other Tracking Processes

<u>Type</u> <u>Number</u> <u>Text</u>

Actual Corrective Action:

Priority: O2a Actual CAC: J Status: Closed Current Operability Evaluation is complete. This corrective action is closed. Due Date: 06/05/2001

Originated By: RAH8344: HEINECK, ROBERT A. Team: RAH8344. Group. MCE. Date. 05/23/2001

	Signature Type	Indiv	Team	Group	Date
	Due Date:	06/05/2001			
	Accepted By:	RAH8344	RAH8344	MCE	05/22/2001
· ·	Assigned To:	PCC2458	RAH8344	MCE	05/22/2001
1	Ready For Approval:	RAH8344	RAH8344	MCE	05/23/2001
1	Approval Assigned To:	RAH8344	RAH8344	MCE	05/23/2001
	Approved By:	RAH8344	RAH8344	MCE	05/23/2001

CA Seq. No: 2

Resp Group	Status 🗐 📜	Orig Group	Event Code	Prop CAC	Cause Code
MCE	Closed	MCE	O2a	B9	YYY

Proposed Corrective Action:

Upon completion of Work Order to shim lugs on Unit 2 36" MS pipe, change the Current Operability Evaluation to reflect operable status. The Work Order is expected to complete during 2EOC19 refueling outage.

Originated By: RAH8344: HEINECK, ROBERT A Team: RAH8344 Group: MCE Date: 05/29/2001

Changed incorrect Unit 1 references to Unit 2.

Last Updated By: SNS3927: SEVERANCE, SANDRA N Team: TDC7309 Group: MCE Date: 07/05/2001

Signature Type - diaman	Indiv 🕰 🐗 👬 🖉 🖉 🖓	Team Transformer and the second		Date in the second second second
Approval Assigned To:	RAH8344	RAH8344	MCE	05/29/2001
Ready For Approval:	SNS3927	TDC7309	MCE	07/05/2001
Approved By:	SNS3927	TDC7309	MCE	07/05/2001
General:Outage: 2EOC19 Other Tracking Processes Type Number Text2a				
<u>Actual Corrective Action:</u> Priority: O2a	Actual CAC:	Status: Open	Due Date: 05/01/2	2002

Signature Type	Indiv	Team	Group	Date
Accepted By:	RAH8344	RAH8344	MCE	05/29/2001
Assigned To:	PCC2458	RAH8344	MCE	05/29/2001
Due Date:	05/01/2002			
Mgt Excepted By:	HDUMEYER	RTB7310	SRG	06/18/2001

Final and Overall PIP Approval

Responsible Group: MCE

Status: Screened

Signature Type	Indiv	Team	Group	Date Version	
Assigned To:			MCE	05/14/2001	
Accepted By:	SNS3927	TDC7309	MCE	05/15/2001	
Approval Assigned T	o:	RAH8344	MCE	05/17/2001	

Any Supplemental Concurrence Signatures Above Do Not Affect PIP Closure.

Closure Document Type Closure Document No

<u>Attachments</u>

Generic Applicability

Responsible Group: GO PIP No: Status:

Assessment Remarks:

No Current Signatures For This Section

Failure Prevention Investigation

No FPI Records for this PIP.

<u>Remarks</u>

No Remarks for this PIP.

Maintenance Rule

Responsible Group: MCE

Status: Closed

Maintenance	Rule SSC
mannee	Ruit 0000

SSC	Description +	Risk Significant	Primary System
MS	Main Steam System	None	Yes

Equipment Group: C01 Applicable Unit: Unit 2 Functional Failure: No MPFF: No Repetitive MPFF. No

Functional Failure Comments:

The MS system has several functions to supply steam to various components. The failure of this snubber did not affect the system's ability to supply steam as needed. Therefore this is not a functional failure.

Originated By: RSM2939: MANNING, ROBERT S Team: BGD7309 Group: MCE Date: 05/15/2001

MPFF Comments:

This is not a functional failure, therefore this is not a MPFF.

Originated By: RSM2939: MANNING, ROBERT S Team: BGD7309 Group: MCE Date: 05/15/2001

Repetitive MPFF Comments:

This is not a functional failure, therefore this is not a repetitive MPFF.

Originated By: RSM2939: MANNING, ROBERT S Team: BGD7309 Group: MCE Date: 05/15/2001

Reactor Trip: NoSafety System Actuation: No Loss of Heat Decay Removal: NoForce Outage Rate or Plant Transient: NoLoss Of Spent Fuel: No

Comments:

Signature Type	Indiv	Team	Group	Date	
Due Date:	06/13/2001				
Assigned To:	RSM2939	BGD7309	MCE	05/15/2001	
Ready For Approval:	RSM2939	BGD7309	MCE	05/29/2001	

Signature Type	Indiv and the second	A HAR WE Team AND A HAR A	Group Jake	Date States Jeans	Maran-
Approval Assigned To:	BGD7309	BGD7309	MCE	05/29/2001	
Approved By:	BGD7309	BGD7309	MCE	05/29/2001	

End of the Document for PIP No:	O-1-1716
The status of this PIP is:	Screened
The duration of this PIP was:	19 days

PIP Serial No: Action Category, Market Report Other Report O-01-01857 3

Problem Identification

Discovered Time/Date: 07:59 05/17/2001 Occurred Time/Date: Unit(s) Affected: %Power Unit Status Remarks <u>Unit</u> Mode 2 refueling n 6 System(s) Affected: Generator

GEN

Affected Equipment

(No Equipment Affected)

Location of Problem: Bldg: R

Elev: ~837

Location Remarks:

2A Steam Generator

Method Used to Discover Problem:

Ultrasonic Examination

Frief Problem Description:

A reportable indication was identified in the upper tubesheet to shell weld.

Column Line: n/a

Detail Problem Description:

There was no operability requirement for the SG's at the time of discovery in MODE 6. A formal Operability Evaluation is contained in ACA #1.

Last Updated By: RVH4032: HESTER, ROBERT V Team: RAH8344 Group: MCE Date: 05/25/2001

During ultrasonic examination (UT) of the upper tubesheet to shell weld (weld 2-SGA-WG60, ISI Item C01.030.001) a reportable indication was identified. The indication is located in the subsurface and is 5" long and 1/2" wide, exceeding the acceptance criteria.

Originated By: TJC0182: COLEMAN, TOMMY J Team: GES8270 Group: MNT Date: 05/17/2001

Other Units/Components/Systems/Areas Affected(Y,N,U): N

Industry Plants Affected(Y,N,U):_N

Immediate Corrective Actions:

Implement QA-516 Evaluation of ISI Indications.

Originated By: TJC0182: COLEMAN, TOMMY J Team: GES8270 Group: MNT Date: 05/17/2001

Team

mmediate Corrective Action Documents / Work Orders:

<u>Indiv</u>

Date

Group

'roblem Identified By: Problem Entered By:

TJC0182 GES8270MNT TJC0182 GES8270MNT

05/17/2001 05/17/2001

<u>Screening</u>

Is the Problem Significant? No

Action Category: 3

Condition Adverse to Quality: Yes

OEP No:

Other Report Nos:

Event Codes:

F3 Equipment Out of Norm ASME SECTION XI O2a

Screening Remarks:

This event has been reviewed by the CST and found to meet the criteria for the selected action category.

Screening members present for this review Sandy Severance (ENG), Richard Ledford (MNT & WCG), Randy Todd (RGC), and Mike Pruitt (OPS).

Originated By: RWV1470: VASSEY, RAY W Team: RTB7310 Group: SRG Date: 05/17/2001

Assignments:

Responsible Groups(s) for Problem Evaluation	WCG	Work Control
esponsible Group for Present Operability:	N/A	
Responsible Group for Past Operability:	N/A	
Responsible Group for Reportability:	N/A	
Responsible Group for Overall PIP Approval:	MNT	Maintenance M

Maintenance MECH/IAE

Signature Type	Indiv -	Team	Group	Date	
Screened By:	RWV1470	RTB7310	SRG	05/17/2001	

Present Operability

Responsible Group: Status:

Sys/Comp Operable? (Y,N,C,E,T):

Required Mode:

Comments:

No Current Signatures For This Section

Past Operability:

Responsible Group:

Status:

Sys/Comp Operable?(Y,N,C,E,T):

Required Mode:

Comments:

No Current Signatures For This Section

<u>Reportability</u>		
Responsible Group:	Status:	
Problem Reportable(Y,N,E):		
Reportable Per:		
Comments:		
No Current Signa	atures For This Section	
Investigation Report:		
Responsible Group:	Act Date:	
Investigator:	Group:	
Due Date: Date Due to VP or Sta. Mgr: Date Regulatory or Agency Rpt Due: Date Investigation Report Approved:		
.VRC Cause Codes:		

Problem Evaluation

	Code	Not Applicable		LINK
Event	Cause	Cause Description	Primary	Causing Groups

Problem Evaluation From: Resp. Group: WCG

Status: Closed

OEDB Checked: No

A subsurface indication, code allowable a/t ratio is 2.2%, the actual a/t ratio is 3.8% in the upper tubesheet to shell weld (2-SGA-WG-60, ISI Item C01.030.001). This weld was previously inspected in 2EOC11 without any reportable indications. The recording criteria in 1990 was to record any indications greater than 50% distance amplitude curve (DAC) using the shear wave technique. The recording criteria in 2001 uses EPRI standards and records indications 20% DAC using longitudinal wave technique. The recent inspection revealed the indication for the first time. Therefore, the indication is assumed to have always existed but undetected. The recent inspection uses much more sensitive recording criteria. Corrective Action 1 was created to use analytical evaluation to justify continued operation of the 2A Steam Generator. Additional examination of weld 2-SGA-WG-59 was performed in accordance with ASME Section XI IWC-2430 (Additional Examinations) and was acceptable.

PE performed by TJ Coleman.

Originated By: GES8270: SHERWOOD, GUY E Team: GES8270 Group: WCG Date: 05/19/2001

OEDB Comments:

<u>Remarks Comments:</u>

Due Date:	06/16/2001			
Accepted By:	RHL8302	RHL8302	WCG	05/17/2001
Assigned To:	GES8270	GES8270	WCG	05/17/2001
Ready For Approval:	GES8270	GES8270	WCG	05/19/2001
Approval Assigned To:	GES8270	GES8270	WCG	05/19/2001
Approved By:	GES8270	GES8270	WCG	05/19/2001

Corrective Actions

CA Seq. No: 1

Resp Group	Status	Orig Group	Event Code	Prop CA	C Cause Code
MCE	Closed	MCE	O2a	J	YYY

Proposed Corrective Action:

Perform ASME Section XI flaw evaluation prior to startup of Unit 2. Based upon initial assessment, determine if NRC review prior to startup would be prudent.

Originated By: RAH8344: HEINECK, ROBERT A Team: RAH8344 Group: MCE Date: 05/18/2001

Signature Type	Indiv	Team testing the second	Group	Date	网络拉斯
Ready For Approval:	RAH8344	RAH8344	MCE	05/18/2001	
Approval Assigned To:	RVH4032	RAH8344	MCE	05/18/2001	
Approved By:	RAH8344	RAH8344	MCE	05/18/2001	

General:Outage: 2EOC18 Mode: 4

Other Tracking ProcessesTypeNumberText

Actual Corrective Action:

Priority: O2aActual CAC: B3Status: ClosedDue Date: 05/24/2001FTI analysis, in their document number 32-5013026, OC-2 SG-A Weld WG60 Flaw Evaluation, concluded the flaw indication is acceptable for not
less than 12 future cycles of normal heatup and cooldown transients based on ASME Code Section XI rules for evaluation by analysis, including
allowance for upset and faulted conditions, assuming the geometry of the flaw as provided by Oconee, and conservative material properties.

Last Updated By: RVH4032: HESTER, ROBERT V Team: RAH8344 Group: MCE Date: 05/23/2001

Per Larry Nicholson, RGC Manager, NRC review of this flaw evaluation prior to startup is not needed. GL 91-18 gives explicit guidance on situations requiring NRC approval prior to startup.

FTI is scheduled to provide the calculation showing compliance with ASME Section XI, Subsection IWB 3600, by Wednesday, 5-23-01.

Driginated By: RAH8344: HEINECK, ROBERT A Team: RAH8344 Group: MCE Date: 05/22/2001

Signature Type - to	Indiv	Service Team	Group	Second Date Strange Strange
Accepted By:	RAH8344	RAH8344	MCE	05/18/2001
Assigned To:	RVH4032	RAH8344	MCE	05/18/2001
Due Date:	05/24/2001			
Ready For Approval:	RVH4032	RAH8344	MCE	05/23/2001
Approval Assigned To:	PAW4981	RAH8344	MCE	05/23/2001
Approved By:	PAW4981	RAH8344	MCE	05/23/2001

CA Seq. No: 2

Resp Group	Status	Orig Group	Event Code	Prop CAC	
MCE	Closed	MCE	O2a	A2	N/A

Proposed Corrective Action:

The Steam Generators have been determined operable for not less than 12 Heat Up/Cool Down cycles with the flaw described in the Problem Identification Section. Identify and revise any documents requiring revision as a result of a 12 cycle limit. In particular, identify the tracking process to ensure 12 cycles are not exceeded prior to SG replacement in 2EOC20.

Originated By: RVH4032: HESTER, ROBERT V Team: RAH8344 Group: MCE Date: 05/25/2001

			· · · · · · · · · · · · · · · · · · ·		52.58 M
Signature Type	Indiv	Team	Group	Date	
Ready For Approval:	RVH4032	RAH8344	MCE	05/25/2001	
Approval Assigned To:	RAH8344	RAH8344	MCE	05/25/2001	
Approved By:	RAH8344	RAH8344	MCE	05/29/2001	

General:Outage: N/A Mode:

Other Tracking Processes Type Number Text

Actual Corrective Action: Priority: I2b Actual CAC:

Status: Open

Due Date: 08/30/2001

Signature Type	Indiv	Team	Group	a Date
Accepted By:	RAH8344	RAH8344	MCE	05/29/2001
Assigned To:	DWP6037	RAH8344	MCE	05/29/2001
Due Date:	08/30/2001			

Final and Overall PIP Approval

Responsible Group: MNT Status: Screened

Signature Type	Indiv		Date
Assigned To:		MNT	05/17/2001

Any Supplemental Concurrence Signatures Above Do Not Affect PIP Closure.

Closure Document Type Closure Document No

Attachments

Generic Applicability

Responsible Group: Status: GO PIP No:

Assessment Remarks:

No Current Signatures For This Section

Failure Prevention Investigation

Quality of CA:	Quality of Cause:	Resp Group: SRG	Status: Closed
<u>Special Codes:</u> N11			

Comments

Signature Type	Indiv	Team	Group	Date	<u>. 1910</u>
Assigned To:			SRG	05/17/2001	
Ready For Approval:	HDUMEYER	RTB7310	SRG	05/21/2001	
Approval Assigned To:	RTB7310	RTB7310	SRG	05/21/2001	
Approved By:	HDUMEYER	RTB7310	SRG	05/21/2001	

<u>Remarks</u>

No Remarks for this PIP.

<u>Maintenance Rule</u>

Responsible Group: MCE

Status: Closed

	Maintenance Rule SSC		
SSC	Description	Risk Significant	Primary System
RC	Reactor Coolant System	None	Yes

Equipment Group: M06 Applicable Unit: Unit 2 Functional Failure: No MPFF: No Repetitive MPFF: No

Functional Failure Comments:

During ultrasonic examination (UT) of the 2A S/G upper tubesheet to shell weld (weld 2-SGA-WG60, ISI Item C01.030.001) a reportable indication was identified. The indication is located in the subsurface and is 5" long and 1/2" wide, exceeding the acceptance criteria. Based on the Problem Evaluation, this indication has probably always existed but was only identified now because of more

sensitive inspection criteria. This flaw does not prevent the S/G from performing its design function (RC.01) and the S/G continues to provide a barrier to prevent release of fission products from the RCS (RC.02). NOTE: With the existing flaw, the S/G is acceptable for 12 more startup/shutdown cycles which will ensure that this condition is acceptable until the S/G is replaced.

Therefore, this is NOT a Functional Failure.

Originated By: KRA7360: ALTER, KENT R Team: SDC3511 Group: MCE Date: 07/06/2001

MPFF Comments:

N/A. NOT a Functional Failure.

Originated By: KRA7360: ALTER, KENT R Team: SDC3511 Group: MCE Date: 07/06/2001

Repetitive MPFF Comments:

N/A. NOT a Functional Failure.

Originated By: KRA7360: ALTER, KENT R Team: SDC3511 Group: MCE Date: 07/06/2001

Safety System Actuation: No Loss of Heat Decay Removal: No Reactor Trip: No Loss Of Spent Fuel: No Force Outage Rate or Plant Transient: No

-1857

Comments:

Signature Type	Indiv	Team	Group	Date
Due Date:	07/10/2001			
Assigned To:	KRA7360	SDC3511	MCE	06/08/2001
Ready For Approval:	KRA7360	SDC3511	MCE	07/06/2001
Approval Assigned To:	SDC3511	SDC3511	MCE	07/06/2001
Approved By:	SDC3511	SDC3511	MCE	07/10/2001

End of the Document for PIP No:	O-1-1857
The status of this PIP is:	Screened
The duration of this PIP was:	0 days

 PIP Serial No:
 Action Category:
 LER No:
 Other Report:

 0-01-02313
 4

Problem Identification

Discovered Time/Date:	13:57 06/18/2001	Occurred Time/Date:	13:00				
Unit(s) Affected:UnitMode21	%PowerUnit Status Remark100Power Operation	<u>ks</u>					
System(s) Affected: FDW Feedwater							
Affected Equipment							
(No Equipment Af	fected)						
Location of Problem: Bldg: AB	Column Line: various	Elev: various					
Location Remarks: Throughout AB and TB							
Method Used to Discover Problem: Review of 2EOC18 ISI Discrepancies.							
<u>3rief Problem Description:</u> Many FDW pipe supports were designed for opposite pipe movements.							
Detail Problem Description	<u>:</u>						

Last Updated By: PCC2458: CHAU, PETER C Team: RAH8344 Group: MCE Date: 06/19/2001

Many FDW pipe supports have been designed for the opposite pipe movements (i.e. the pipe moves South but the pipe support have been designed for the pipe moving North). These supports should be revised in order to reflect the correct piping movements.

The piping movement discrepancy on the pipe support drawings were discovered during a review of 2EOC18 pipe support ISI discrepancies. In resolving the pipe support 2-03-0-551-H51 clearance issue, it was noted that the subject pipe support drawing shows a 1.781" movement toward North direction. A casual observation of the piping isometric reveals that the piping can not possibly move North at that location.

The FDW piping for unit 1 and 2 is similar in dimemsions but running opposite directions (the unit 1 running North and unit 2 running South). A review of the unit 2 piping calculation shows that the unit 2 FDW piping was analyzed as a mirror image of that of the unit 1. In other words, the exact math model for unit 1 FDW piping was used to analyze for unit 2 FDW piping. In doing so, The analysis output piping movements in the North- South directions must be reverved to compensate for mirror image methodology. The curent movements on many pipe support drawings are wrong due to failure to interpret analysis output corretly.

This is considered as a human error happening many years ago.

The affected piping calculation is OSC 454 rev. 18. The piping is class G and F terminating at penetation 25 and 27 which is shown on OFD 121B 2.3. The design temperature and pressure are 475F and 1275 psig respectively.

OPERABILITY ASSESSMENT.

Both the piping and pipe supports are acceptable for continuing operation without NCI.

The affected pipe supports have been reviewed by pipe support engineer and determined to be clearly operable within design allowable. The affected pipe supports are: 2-03-0-1401A-R3, R2, R15, R4, R13, R12, R14, R7, H4087, 2-03-0-551-DE001, and 2-03-0-1401C-DMB-0601.

There is no adverse impact on the piping system.

Originated By: PCC2458: CHAU, PETER C Team: RAH8344 Group: MCE Date: 06/18/2001

Other Units/Components/Systems/Areas Affected(Y.N.U): N

Industry Plants Affected(Y,N,U): U

Immediate Corrective Actions:

The affected pipe supports (a total 11) were reviewed and found to be acceptable.

Originated By: PCC2458: CHAU, PETER C Team: RAH8344 Group: MCE Date: 06/18/2001

Immediate Corrective Action Documents / Work Orders:

	<u>Indiv</u>	Team	Group	Date
Problem Identified By:	PCC458C	RAH8344	MCE	06/18/2001
Problem Entered By:	PCC458C	RAH8344	MCE	06/18/2001

<u>Screening</u>

```
Is the Problem Significant? No Action Category: 4
```

Condition Adverse to Quality: Yes

OEP No:

Other Report Nos:

Event Codes:

D6f Civil Calc F11 Equipment Misapplication

Screening Remarks:

This event has been reviewed by the CST and found to meet the criteria for the selected action category.

Screening members present for this review: Sandy Severance (ENG), RD Burns (MNT & WCG), Randy Todd (RGC), and Mike Pruitt (OPS).

Originated By: RWV1470: VASSEY, RAY W Team: RTB7310 Group: SRG Date: 06/19/2001

Assignments:

Responsible Groups(s) for Problem Evaluation:	Responsible Group	for Present Operability:	N/A
Responsible Group for Past Operability:	N/A		
Responsible Group for Reportability:	N/A		
Responsible Group for Overall PIP Approval:	MCE	Mech/Civil Eq. Eng.	

~	Signature Type	Indiv	Team	Group	Date	Raifi
	Screened By:	RWV1470	RTB7310	SRG	06/19/2001	

Present Operability

Responsible Group:	Status:
Sys/Comp Operable? (Y,N,C,E,T):	
Required Mode:	
Comments:	

No Current Signatures For This Section

Status:

Past Operability:

Responsible Group:

Sys/Comp Operable?(Y,N,C,E,T):

Required Mode:

Comments:

No Current Signatures For This Section

Reportability

Responsible Group: Status:

Problem Reportable(Y,N,E):

Reportable Per:

Comments:

No Current Signatures For This Section

Investigation Report:

Responsible Group:

Act Date:

Investigator:

Group:

Due Date: Date Due to VP or Sta. Mgr: Date Regulatory or Agency Rpt Due: Date Investigation Report Approved:

NRC Cause Codes:

Problem Evaluation

_	Cause	영화 지수는 영화 가지	성장 이 관계가 가지 않는 것					이야 같은?
	Event	Cause	Description	9942 H A	and M.N.	Primary C	ausing Groups	S
	Code			· [24] 美国的人主义				a tha firms

Problem Evaluation From:

Corrective Actions

CA Seq. No: 1

Resp Group	Status (7)	Orig Group	• City Event Code	Prop CAC/	Cause Code
MCE	Closed	MCE	D6f	Bla	YYY

N/A

Mode:

Actual CAC:

Proposed Corrective Action:

Generate a minor mod (or mods) to revise the affected pipe supports to reflect the correct piping movements. The affected supports are 2-03-0-1401A-R3, R2, R15, R4, R13, R12, R14, R7, H4087, 2-03-0-551-DE001, and 2-03-0-1401C-DMB-0601. Per the problem description, "Many FDW pipe supports have been designed for the opposite pipe movements (i.e., the pipe moves South but the pipe supports have been designed for the pipe moving North). Generate additional corrective actions as required.

Originated By: SNS3927: SEVERANCE, SANDRA N Team: TDC7309 Group: MCE Date: 06/19/2001

Signature Type	Indiv	Team	Стоир	Date	57. S
Ready For Approval:	SNS3927	TDC7309	MCE	06/19/2001	
Approval Assigned To:	TDC7309	TDC7309	MCE	06/19/2001	
Approved By:	SNS3927	TDC7309	MCE	06/19/2001	

General:Outage: N/A

Other Tracking ProcessesTypeNumberText

Actual Corrective Action:

Priority: I2d

Status: Open

pen

Due Date: 01/17/2002

Signature Type	Indiv	Team .	Group	Date
Accepted By:	RAH8344	RAH8344	MCE	06/21/2001
Assigned To:	PHP4260	RAH8344	MCE	06/21/2001
Due Date:	01/17/2002			

Final and Overall PIP Approval

Responsible Group: MCE Status: Screened

Signature Type	Indiv	Team	Group	Date
Assigned To:			MCE	06/19/2001
Accepted By:	SNS3927	TDC7309	MCE	06/19/2001

Any Supplemental Concurrence Signatures Above Do Not Affect PIP Closure.

Closure Document Type

Closure Document No

Attachments

Generic Applicability

Responsible Group: GO PIP No: Status:

Assessment Remarks:

No Current Signatures For This Section

Failure Prevention Investigation

No FPI Records for this PIP.

<u>Remarks</u>

No Remarks for this PIP.

Maintenance Rule

No Maintenance Rule Records for this PIP.

End of the Document for PIP No: The status of this PIP is: The duration of this PIP was:

O-1-2313 Screened 1 day



May 23, 2001 FANP-01-1372

Mr. Bob Hester Duke Energy Corporation Oconee Nuclear Station Mail Code ON03MC 7800 Rochester Highway Seneca, S.C. 29672 Fax: (864) 885-3402

Subject: Requested Evaluations of Flaw in "A" OTSG

Dear Mr. Hester:

In response of Duke Energy Corporation's request for engineering support of the recently discovered flaw in "A" OTSG during the Oconee Unit 2 outage, Framatome ANP (FRA-ANP) is pleased to submit the following engineering evaluations.

- OC-2 SG-A Weld WG60 Flaw Evaluation (Doc. No. 32-5013026)
- OTSG Upper Tubesheet-to-Shell Weld Stresses for Flaw Evaluation (Doc. No. 86-5013015-00)

If you have any questions about these evaluations, please contact the principle engineer, Ashok Nana at (804) 832-2393. You may also contact me at (804) 832-2432 or jleighliter@framatech.com.

Sincerely

John A. Leighliter Project Manager

cc: James McClure, Duke Energy, Oconee A. Nana, OF50

enc.

155 Mill Ridge Road, Lynchburg, VA 24502-4341 Telephone: 804-832-3000 Fax: 804-832-3660 Internet: http://www.framatech.com