

Entergy Nuclear Northeast Entergy Nuclear Operations, Inc. Indian Point 3 NPP P.O. Box 308 Buchanan, NY 10511 Tel 914 736 8001 Fax 736 8012

Robert J. Barrett Vice President, Operations-IP3

August 15, 2001 IPN-01-060

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Mail Stop O-P1-17 Washington, DC 20555-0001

Subject:

Indian Point 3 Nuclear Power Plant

Docket No. 50-286 License No. DPR-64

Special Report per Technical Specification 5.6.7

Due to an Inoperable Core Exit Thermocouple

Dear Sir:

The purpose of this letter is to provide a Post Accident Monitoring (PAM) Instrumentation report in accordance with Technical Specification (TS) 5.6.7 due to an inoperable core exit thermocouple (CET), H-5, in train A. There are twenty CETs (ten in each of two trains) distributed among the four quadrants of the core, that are qualified for post accident monitoring. TS 3.3.3 Table 3.3.3-1 requires two CETs per train in each of the four quadrants to be operable and restoration of the required inoperable channel to operable status in 30 days. If the required action and completion time can not be met, a report is to be submitted within 14 days addressing the information required by TS 5.6.7.

The alternate method of monitoring is to use the other CET in train A and the CETs in train B for this quadrant. There are currently three operable CETs in train B for this quadrant. The cause of the inoperability is undetermined. Some inspection and assessment of the cause of the CET inoperability was conducted, but completion of the inspection and assessment are limited due to the location of some of the cable connectors and CET itself that make them normally inaccessible during plant operation. The suspected cause may be a failed connection or cabling, however, the CET itself may have failed. The schedule to complete inspection and assessment, and to restore the instrument channel to operable status will be either during an outage of sufficient duration or the refueling outage currently scheduled to begin April 4, 2003. This will be accomplished by troubleshooting the inoperable channel, and repair or replacement implemented as applicable.

fool

Docket No. 50-286 IPN-01-060 Page 2 of 2

If you have any questions regarding this matter, please contact John Donnelly at (914) 736-8310.

Very truly yours,

Robert J. Barrett

Vice President, Operations

Indian Point 3 Nuclear Power Plant

cc: Mr. Hubert J. Miller

Regional Administrator

Region I

U.S. Nuclear Regulatory Commission

475 Allendale Road

King of Prussia, PA 19406-1415

Resident Inspector's Office

Indian Point 3 NPP

U.S. Nuclear Regulatory Commission

P.O. Box 308

Buchanan, NY 10511