

HSA

Historical Site Assessment

MYAPC

ID#	DATE	IDENTIFIER	LOCATION	DESCRIPTION	TYPE
1	23-Mar-90	UOR 90-030	I&C Hotshop	Mercury spill. 2 teaspoons of mercury from transmitters.	HAZ
2	29-Nov-94	UOR 94-105	Turbine Hall roof, and outside adjacent to P-2C	Oil spill from P-2C blew onto Turbine Hall roof. Approx. 3 tp 5 gals. recovered. 1 qt. of oil droplets blew to ground.	HAZ
3	17-Nov-88	UOR 124-88	Main Transformer Sump Trash boom/Screen wash trough	Pumped down transformer sump pit. Oil sheen of approx. 500 sq ft. seen in river.	HAZ
4	29-Oct-89	UOR 89-106	Spray Bld. 6' from outside. RWST Greenhouse	Fuel oil from leak in line to RWST furnace entered Spray Bld. during heavy rain.	HAZ
5	21-Feb-92	UOR 92-028	Circ Water Pump House	Oil spill of approx. 1 pint from crane operations.	HAZ
6	31-Mar-95	UOR 95-039	Back River/Circ Water Pump House	Oil spill. Approx. 1 quart to Back River from outfall of storm drain from C/W pump house.	HAZ
7	04-Apr-95	UOR 95-040	Circ Water P/H South side outside	Oil at Plant intake due to heavy rains carrying oil from previous spills and oil under crane.	HAZ
8	07-Dec-95	UOR 95-096	CTMT -2' Head L/D	BD-56 left open while filling sec. side of s/g. Water to the floor of Head L/D area.	HAZ
9	01-Jan-96	UOR 96-01	CTMT Loop 1 by RCM-11	Asbestos spill from broken pipe insulation.	HAZ
10	02-May-90	UOR 90-62	CTMT -2'	Water spill from sec. side s/g. Hydrazine level 230 ppm.	HAZ
11	02-Feb-97	from employee	Outside by Vehicle Barrier	Gasoline spill. Approx. 10 gal. in front of vehicle barrier.	HAZ
12		employee closeout interview	Under transmission lines	Sludge with some activity disposed of on site. Sludge was from Circ. Water Pumphouse intake screen.	RA D
13	05-May-86	Rad Inf. 86-268	Sewerage Treatment Plant	Radioactive water from Hot side sinks and decon shower go directly to the Sewerage Treatment Plant.	RA D
14	25-Apr-86	Rad Inf. 86-246	Bailey Point outside protected area fence	Contaminated dirt and asphalt from CTMT alleyway dumped on ground on point.	RA D
15	29-Aug-86	R.I.R. 86-01	Bailey Point outside protected area fence	Contaminated dirt and asphalt from CTMT alleyway dumped on Bailey point. 300 ccpm to 50 mr/hr found upon removal	RA D
16	24-Apr-86	R.C.I. 86-228	?	Unsurveyed item released. Grove released from RCA without a proper survey.	RA D
17	10-Apr-86	R.C.I. 86-191	HV-9 area pit	Contaminated area. HV-9 pit area is contaminated even though there are no contam. system components in area.	RA D
18	03-Apr-86	R.C.I. 86-135	Backyard	Contamination and Particles. Crane laying in backyard is contaminated with particles from Core Barrel & not wrapped	RA D
19	02-Apr-86	R.C.I. 86-132	CTMT Alleyway	Contaminated sand. Sand swept up from alleyway has spot reading 35mr/hr.	RA D
20	27-Mar-86	R.C.I. 86-111	RCA, TK-85 Cubicle	Contaminated water from leaking P-120/123 leaked onto clean floor.	RA D
21	13-Sep-84	R.I.R. 84-04	RCA / RCA roof	Airborne Contamination. High airborne in RCA with roof hatch opened. Fuel Rack work.	RA D

ID#	DATE	IDENTIFIER	LOCATION	DESCRIPTION	TYPE
22		Tech. file 19-11-4	Restricted Area	Radioactive particles. Machining on Core Barrel generated particles that got throughout the Plant. Many persons resulted.	RA D
23	02-Nov-83	R.I.R. 83-02	RCA building	Contaminated water and crud sprayed onto RCA floor.	RA D
24	10-Oct-85	UOR 79-85 & employee interview	CTMT Alleyway	PCC leak. CTMT Alleyway.	HAZ
25	25-Feb-87	R.I.R. 87-01	RWST Area outside	Contaminated water leaking from the RWST onto the ground running down the storm drain.	RA D
26	26-Apr-88	R.I.R. 88-04	RWST outside area	Contaminated water leaking onto ground from hole in plastic sleeving. 80 mrad/hr on ground. smears up to 135k dpm.	RA D
27	26-Nov-88	R.I.R. 88-23	CONDO inside Wiscasst Wall	Contaminated liquid leaking from CONDO due to being less than weather tight. Contaminated liquid samples outside bld.	RA D
28	17-Nov-89		Restricted Area	Hot Particles. Numerous hot particles found throughout the plant	RA D
29	06-Feb-90	R.I.R. 90-03	Cold Side Trailer	Contaminated wood found in Burns and Roe trailers. Other yellow painted wood found on the cold side. Contaminated snow found on clean side. Wood from planing operation.	RA D
30	07-Feb-90	R.I.R. 90-04	BWST Diked Area	Contaminated liquid in BWST diked area due to siphon heater leak and overflow.	RA D
31	19-Nov-92	R.I.R. 92-13	Cold side Tool Crib	Contaminated tools found in Cold side Tool Crib.	RA D
32	13-Jan-87		Baseball Field	Snow was removed from the restricted area and disposed of on the baseball field.	RA D
33	24-Jul-89		Wiscasset Wall	Contaminated liquids and items. Leaking barrels and unwrapped contam. items inside Wiscasset Wall.	RA D
34	20-Oct-89		Backyard by RCA bld.	Contaminated liquid spilled into backyard due to overflow of Tk-109.	RA D
35	18-Oct-90		RCA Roof, Roof Drains, Storm Drains	Contaminated equipment. A contaminated crane was stored on the RCA roof for several years.	RA D
36			Outside behind Gas House	Contaminated equipment. CEA extension shafts in degraded boxes were stored in a shed behind the Gas House. Shed and contents removed. Gravel from this area spread in "trailer park.	RA D
37			Outside in front of LSA building	Contaminated equipment. It has been rumored that minor contaminated spills have occurred in front of LSA building.	RA D
38	23-Feb-88	RIR 88-02	Outside at RWST	Contaminated liquid. Flange leak on RWST leaked water onto ground	RA D
39	22-May-87		Donut Trailer in CTMT Alleyway	Discrete Radioactive Particle found in the Donut Trailer.	RA D
40	04-May-87		Outside Backyard	Contamination Discrete Radioactive Particles found in backyard due to water dripping from CSB Shield being moved from CTMT.	RA D
41	30-Sep-85		CTMT Alleyway by Test Tanks	Discrete Radioactive Particles found in CTMT Alleyway.	RA D

ID#	DATE	IDENTIFIER	LOCATION	DESCRIPTION	TYPE
42	03-Oct-85		CTMT Alleyway	Discrete Radioactive Particles. Numerous DRP's found in CTMT Alleyway. Water being drained from valve in Steam and Valve House running to storm drain through area with particles.	RA D
43	12-Apr-84		Outside by RWST	Contaminated Insulation and from flange leak on RWST.	RA D
44	01-Apr-87		Equipment Hatch "Pit"	Contamination. Low levels of contamination (up to 925 dpm) was found in the Equipment Hatch Pit area.	RA D
45	22-Feb-87		Outside in front of LSA Bldg.	Hot Particles (up to 190 mr/hr) found outside in front of the LSA Bldg.	RA D
46	02-Feb-95	R.I.R. 95-16	Guardhouse/ I&C Training Lab	Radioactive Material. Reed switches (100k fixed) were improperly released from the R.A. and found by portal alarm at the Gatehouse. Additional surveys discovered equipment with smearable contamination in the I&C Training Lab.	RA D
47	01-Oct-95	R.I.R. 95-30	Gatehouse	Contaminated clothing. A worker with contaminated modesty garments was identified by alarm at Gatehouse portal monitor.	RA D
48	27-Jul-97	R.I.R. 96-11	Backyard in SFP Rerack bathtub	Contaminated spill. Approximately 100 gallons of water spilled out of old SFP rack when downended in bathtub in backyard.	RA D
49	16-Oct-97	R.I.R. 96-15	Cold side Tool Crib	Radioactive tools. Tools with fixed contamination found in the Coldside Tool Crib.	RA D
50	26-Apr-88	UOR 88-33	Outside RWST Siphon Heater piping	Contaminated Spill. Crack in the RWST siphon heater return line.	RA D
51	24-Feb-88	UOR 88-21	Outside at RWST siphon heater piping	Contaminated leak. Siphon heater return line isolation valve leak.	RA D
52	23-Feb-88	UOR 88-20	Outside at RWST siphon heater piping	Contaminated liquid leak. RWST siphon heater flange leak. 200 ml/min.	RA D
53	24-Oct-87	UOR 87-159	Outside at RWST siphon heater piping	Contaminated liquid leak. RWST siphon heater return line has a crack and leaks.	RA D
54	11-Oct-87	UOR-87-153	Outside at RWST siphon heater piping	Contaminated liquid leak into the RWST siphon heater sump well.	RA D
55	29-Mar-83	UOR 1983	Back River	Oil spill into the Back River. Approx. 40 gallons of oil from Tk-75 overfilled and spilled out of vent pipe onto roof. Oil to river via storm drain system.	HAZ
56	11-May-87	UOR-87-59	Backyard	Chromated water spill in backyard.	HAZ
57	14-Aug-85	UOR 85-55	Boiler Room	Mercury spill. 14 lbs of mercury spilled in aux. Boiler Room.	HAZ
58	06-Aug-85	UOR 85-42	X-1A and surrounding area	Oil spill from X-1A due to safety valve lifting. Oil on transformer and on gravel around transformer.	HAZ
59	30-Mar-84	UOR 1984	RWST down the Storm Drain	Contaminated liquid spill. Approx. 5000 gallons of water leaked from the RWST and went down the storm drain.	RA D
60	27-Feb-84	UOR ?	Aux. Feedpump Room outside to storm drain	Contaminated liquid spill. Wet vac barrel of contaminated water spilled in Aux F.P. Room and ran outside and down the storm drain.	RA D

ID#	DATE	IDENTIFIER	LOCATION	DESCRIPTION	TYPE
61	01-Jul-89		Backyard	Discrete radioactive particles found in outside areas while attempting to free release the area.	RA D
62	16-Nov-89		LSA bld./ Storm Drain	Contaminated liquid spilled in the LSA bld. some of which went down the storm drain.	RA D
63	01-May-88		RWST outside areas of previous spills	Contaminated soil. Surveys of excavated area around base of RWST.	RA D
64	08-Mar-95	UOR 95-25	Water Treatment & Outside Underground	Waste neutralization tank sump has crack and leaks. Discharge piping at Service Water connection eroded away.	HAZ
65	27-Nov-94	UOR 94-93	Outside by old underground Fuel oil tanks	Oil sheen seen on water puddle at area near the location of the old underground fuel oil storage tanks.	HAZ
66	30-Jun-94	UOR 94-47	Circ. Water Pump House Intake Structure	Oil sheen seen at Circ. Water Intake Structure., inside the boom.	HAZ
67	23-Jun-94	UOR 94-43	Spare Generator Storage Building	Kerosene spill. Kerosene spill in spare generator storage building.	HAZ
68	15-Apr-92	UOR 92-51	Outside near Water Treatment loading dock	Sodium Hydroxide spill. Approx. one half gallon NaOH spill.	HAZ
69	15-Mar-92	UOR-92-37	Outside by SCAT Tank	Sodium Hydroxide spill from leaking flange on tanker truck.4 gallons.	HAZ
70	06-Mar-92	UOR 92-34	Outside by C/W Pump House	Oil spill. Oil leakage from fuel truck onto ground. Approx. 1 quart.	HAZ
71	23-Jan-92	UOR 92-11	Outside at Baseball Field	Sewer line rupture at area near baseball field. Approx. 200 gallon leak.	HAZ
72	06-Dec-91	UOR 91-98	Underground Gasoline Storage Tank area	Gasoline levels in soil in area around underground storage tank are over DEP levels.	HAZ
73	01-Nov-91	UOR 91-92	Outside by DG-2	Oil Spill. Small oil spill approx.1 gallons.	HAZ
74	14-Aug-91	UOR 91-61	Outside by DG-2	Oil spill. Small oil spill outside by DG-2. Approx. 1 quart.	HAZ
75	09-May-91	UOR 91-39	Outside by X-1B	Oil leak from oil processing trailer.	HAZ
76	18-Feb-91	UOR 91-19	BWST diked area	Contaminated water. Leak from BWST siphon heater.Approx.12" of water in diked area.	RAD
77	09-Jan-91	UOR 91-05	BWST diked area	Contaminated water. Leak from BWST siphon heater.Approx.12" of water in diked area. Approx 2400 gallons.	RAD
78	19-Sep-90	UOR 90-124	RWST Greenhouse	Sodium Hydroxide leak. Approx.20 gallons of NAOH onto paved area.	HAZ
79	05-Jul-90	UOR 90-93	X-1B bermed area	Oil leak. Approx. 5 gallons.	HAZ
80	18-Apr-90	UOR 90-51	Outside	SCC leak while filling tank truck. Approx. 1 gallon of SCC (1000 ppm sodium chromate) went down the storm drain.	HAZ
81	15-Jan-90	UOR 90-07	Weir/diffusers/Backriver	Scs was pumped to the service water header and ultimately to the river. Approx. 20 gallons.	HAZ
82	20-Oct-89	UOR 89-102	Outside by RWST Greenhouse	Fuel oil spill. Leak in supply line to RWST Greenhouse furnace.	HAZ

ID#	DATE	IDENTIFIER	LOCATION	DESCRIPTION	TYPE
83		employee interview	Bailey Point	Storage area for large amount of items on tip of Bailey Point. Items included wood, scrap, trveling screens, dunnage from equip hatch.	RAD
84	05-Dec-88	UOR 135-88	Underground piping	SCC leak from underground pipe.	HAZ
85	17-Nov-88	UOR 124-88	Main Transformer Sump	Milky liquid found in the Main Transformer sump.	HAZ
86	02-Jun-88	UOR 43-88	BWST Drain lines and Storm Sewer	Drain lines from BWSt sump to the storm drain system found open.	RAD
87	27-May-88	UOR 42-88	RWST Siphon Heater return line	RWST siphon heater return line valve leaking to pavement.	RAD
88	22-May-88	UOR 39-88	RWST	Contaminated water from leak collection barrel on ground.	RAD
89	08-Nov-97	employee interview	Boiler Room Storage Cabinets	Mercury contamination.Expect to find residual mercury contamination in storage cabinets.	HAZ
90	09-Jun-89	AI-89-49-1	Turbine Hall Sumps	Low levels of activity found in all Turbine Hall sumps except for the service water heat exchanger. Also along railroad track rails.	RAD
91	15-Aug-89	isotopic analysis	CR-3	Activity found in bird droppings from CR-3.	RAD
92	02-Nov-88	tech file 01-08-04-02	Outside by RWST	Request for in place disposal of slightly contaminated soil around the RWST	RAD
93	31-Aug-89	tech file 01-08-04-02	Outside by RWST	Approval for in place disposl of residual contaminated soils at Maine Yankee	RAD
94	11-Mar-91	tech file 01-08-04-02	Outside by Circ. Water Pumphouse	Ferrous sulfate tank underground by the Circ. Water Pumphouse. Tank left in place until decommissioning.	HAZ
95			N/A	Various indexes and sorts. RIRs, UORs etc.	
96	15-Nov-96		Outside by CST	Flood relief drainage project soil sample analysis.	RAD
97	17-Nov-97		Information Center	NORM activity discovered by GTS Duratek on carpet at Information Center.	RAD
98	18-Nov-97		Outside by PWST	Cs-137 & Co-60 activity found in dirt next to the PWST.	RAD
99	02-Dec-97		Blowdown Heat Exchang.	30kdp m loose surface contam. found in E-100.	RAD
100	10-Dec-97		N-P-43 PAB 21'	1.2k dpm found inside piping at N-P-43	RAD
101	12-Dec-95		Outside by Warehouse	30k dpm cobalt 60 particle found in crack in pavement by warehouse.	RAD
102	20-Jan-98		Turbine Hall	5k to 50k dpm/100cm2 found inside valve SW-42, Test Tank overboard to Service Water system.	RAD
103	21-Jan-98		Turbine Hall	100 to 200 ccpm fixed contamination found inside SCC Pumps	RAD
104	21-Jan-98		Yard Area	Hydraulic oil spill from T&R trash truck <1 gallon	HAZ
105	22-Jan-98		Turbine Hall	List provided by GTS Duratek listing components having detectable activity, by direct frisk, which is >background.	RAD
106	01-Jan-73		Outside Areas	"Soil and sediment history in the vicinity of Maine Yankee"	RAD
107	01-Jan-75		Outside	"Measurements of radionuclides as a function of position in the estuary of the Maine Yankee Atomic Power Plant"	RAD

ID#	DATE	IDENTIFIER	LOCATION	DESCRIPTION	TYPE
108	07-Feb-74			A Radioactive Isotopic Characterization of the Environment Near Wiscasset, Maine: A Preoperational Survey in the Vicinity of the Maine Yankee Atomic Power Plant.	RAD
109	01-May-76		Outside	"Radioactive isotopic characterization of the environment near Wiscasset, Maine using pre and post-operational surveys in the vicinity of the Maine Yankee Nuclear Reactor"	RAD
110	30-Jan-98		Outside by Wier	Soil taken at Duratek sample location R900 01OL1 grid 130 has indication of Co-60 and Cs- 137.	RA D
111	22-Jan-98		Water Treatment Area	Isotopic analysis of TK-37, alum storage tank, sludge.	RAD
112	23-Jan-98		Site Characterization	Letter from H.G.Brack to NRC regarding deficiencies in site characterization and MARSSIM	RA D
113	01-Mar-81		Estuary	"The Environmental Behavior of Transuranic Nuclides Released from Water Cooled Nuclear Power Plants"	RAD
114	24-Jun-97		Estuary	Results of May 1994 clam and sediment sampling.	RAD
115	04-Oct-94		Outside	Licensed silt spreading area.	RAD
116			Back Bay	Photos Of water flow from MY prior to construction of weir.	RAD
117				Residual Radioactive Contamination from Decommissioning NUREG/CR-5512 Tech Basis for translating contam. levels to annual total effective dose equivalent.	RAD
118	02-Mar-98		Bailey Cove	Forebay, 11.2 pCi/gram at 0"-3", 5pCi/gm at 3"-6". GTS Duratek soil/sediment sample	RAD
119	04-Mar-98		Outside by PWST	Activity found in soil North West of the PWST. Area now covered with SFP "Island""pagoda".	RAD
120	06-Mar-98		Contractor Parking Lot	Soil samples taken in the contractor parking lot indicated elevated activity levels.	RAD
121	12-Mar-98		Outside across from the LLWSB	Cochrane's Corral. An area was established across from the LLWSB for temp. storage of trailers containing radmaterial	RAD
122	17-Mar-98		Wiscasset Landfill	Results of investigation into barrel filters from MY found at the Wiscasset landfill.	RAD
A				Spill Log	
B				Search Index	
C				No comment employee interview forms	
D				Misc. Items e.g., Old Index	

HSA ID# 1

UOR DATABASE - CONVERTED FROM OPERATIONAL EVENT DATABASE (OEDB)

1. TITLE: Mercury Spill in I&C Shop
MERCURY SPILL IN I+C SHOP
2. OEDB #: 1273 UOR #: 90-030 LER #: OTHER:
HPES #: N PRCE #:
3. TIME/DATE OF EVENT: 1130/3/23/90
ADDENDUM DATE
4. PLANT CONDITIONS:

OPERATING CONDITION (1-7): 7

5. DESCRIPTION OF OCCURENCE:

While setting steam flow transmitters in place for storage in the I&C shop, the transmitter tilted and approximately 2 teaspoons of mercury spilled on the floor. In order to avoid spreading the mercury, the area was roped off and a spill kit was obtained. The Industrial Safety and Hazardous Waste Coordinators were notified of the spill.

Spill cleanup was conducted by I&C personnel using the spill kit. They used protective gloves and goggles while cleaning up the mercury.

When industrial safety personnel arrived, they evacuated the I&C shop and began to sample the air for airborne mercury. Since none was detected, personnel were allowed back into the shop.

Cleanup continued with personnel wearing protective suits. The steam flow transmitters were placed in plastic bags to prevent further spills.

The flow transmitters were being removed from service in the auxiliary steam system because they are obsolete. Upon removal of the first transmitter, the Hazardous Waste Coordinator was notified of the hazard. The transmitter was stored in the I&C shop until it could be disposed. Later it was learned that there is no place for storing such items prior to disposal.

E-PLAN LEVEL

ENS: N (Y/N)

7. REPORTABILITY DETERMINATION: REPORTING CRITERIA; SHORT TERM
PROC. 1-26-1; EMERGENCY PLAN PROC. 2.50.0; LER (EXPLAIN)

QOD TREND CODE:

1
DECOM

2547-13-1

ATTACHMENT B
ATLAS DOCUMENT INPUT FORM

1. TITLE <u>UOR 90-030</u>		
<u>MERCURY SPILL IN I+C SHOP</u>		
2. DOCUMENT TYPE <u>Report</u>	3. DOCUMENT FORM <u>M</u>	
4. DOCUMENT LOCATION	5. RETENTION PERIOD	
6. TECHNICAL FILE NUMBER <u>11.14.6</u>	<u>1.8.4.2</u>	
7. DOCUMENT NUMBER		
8. REVISION NUMBER	9. DATE <u>3/23/90</u>	10. CLASSIFICATION TYPE <u>D</u>
11. TOPICAL INDUSTRY ISSUE		
12. KEYWORDS		
13. SUBJECT		
14. REFERENCE DOCUMENT		
15. SYSTEM CODE	16. COMPONENT CODE	
17. CYCLE NUMBER		
18. ORIGINATOR <u>OPS</u>		
19. RECEIVER		
20. VENDOR CODE		
21. ACCESSION NUMBER		
ACTION: ADD/REPLACE/DELETE (CIRCLE ONE)		

OPERATIONS DEPARTMENT
UNUSUAL OCCURRENCE REPORT (UOR)

1. GENERAL

- A. TITLE OF UOR: Mercury Spill in I&C Shop
- B. DATE/TIME OF EVENT: 3/23/90 1130
- C. DATE/TIME UOR COMPLETED: 3/23/90 1400

2. PLANT CONDITIONS AT TIME OF OCCURRENCE:

- A. OPERATING CONDITION (1-7): 7 B. REACTOR POWER (%) : 96
- C. TAVE (F): 565 D. PZR. PRESSURE (PSIG): 2231 E. PZR LEVEL (%) 56
PLANT TRIP? NO

3. NOTIFICATION

- A. IS NRC NOTIFICATION REQUIRED? N
(Justify "NO" answer in Discussion Section.)
- B. HAS PROCEDURE 2.50.0 BEEN CONSULTED? n/a
 - B.1 EMERG CONDITION DECLARED : n/a
 - B.2 DATE/TIME OF DECLARATION : n/a
- C. NRC NOTIFIED BY : n/a USING : n/a
 - C.1 DATE/TIME : n/a
- D. NRC RESIDENT NOTIFIED BY : Copy of UOR
 - D.1 DATE/TIME : n/a
- E. DUTY CALL OFFICER (DCO) NOTIFIED BY : Copy of UOR
 - E.1 DATE/TIME : n/a
- F. If event requires state notification; for example, release of hazardous liquid, unscheduled radioactive release, phone call to state police, plant trip, etc., notify state inspector by phone.
STATE INSPECTOR NOTIFIED BY : Copy of UOR
 - F.1 DATE/TIME : n/a
- G. If industrial safety concern, notify Industrial Safety Coordinator
ISC NOTIFIED BY : R. Higgins
 - G.1 DATE/TIME : 1130

2547-13-3

OPERATIONS DEPARTMENT
UNUSUAL OCCURRENCE REPORT (UOR)

4. DESCRIPTION OF OCCURRENCE/SEQUENCE OF EVENTS

While setting steam flow transmitters in place for storage in the I&C shop, the transmitter tilted and approximately 2 teaspoons of mercury spilled on the floor. In order to avoid spreading the mercury, the area was roped off and a spill kit was obtained. The Industrial Safety and Hazardous Waste Coordinators were notified of the spill.

Spill cleanup was conducted by I&C personnel using the spill kit. They used protective gloves and goggles while cleaning up the mercury.

When industrial safety personnel arrived, they evacuated the I&C shop and began to sample the air for airborne mercury. Since none was detected, personnel were allowed back into the shop.

Cleanup continued with personnel wearing protective suits. The steam flow transmitters were placed in plastic bags to prevent further spills.

The flow transmitters were being removed from service in the auxiliary steam system because they are obsolete. Upon removal of the first transmitter, the Hazardous Waste Coordinator was notified of the hazard. The transmitter was stored in the I&C shop until it could be disposed. Later it was learned that there is no place for storing such items prior to disposal.

THIS EVENT IS NOT REPORTABLE PER OP 1-26-1.

2547-13-4

OPERATIONS DEPARTMENT

UNUSUAL OCCURRENCE REPORT (UOR)

5. THE FOLLOWING SIMILAR OCCURRENCES WERE FOUND IN THE OEDB:

Two UOR's discussed mercury spills. UOR 85-055 & 89-114

6. IMMEDIATE CORRECTIVE ACTIONS


- Clean up mercury spill.
- Place flow transmitters in plastic bags to prevent further spills.

7. PRELIMINARY RECOMMENDATIONS FOR LONG TERM CORRECTIVE ACTION

-Develop a place for storing hazardous waste prior to disposal.

Isd

Haz. Waste.

Submitted by : 

Lisa M. Oesterling

Approved by: 

Noted by: 

Distribution:

- *PM (RWB)
- *APM/MMD (RFP)
- *MOD (AJC)
- *MTSD (RHN)
- *AMOD (JVW)
- *ATMOD
- *PSS
- *SOS
- *RO (2)
- *P,OPS (ETB)

- *State Inspector (PJD)
- *NRC RESIDENT (CFH/RCF)
- *MGR QPD (JCF)
- *AUGUSTA TELEX
- *NSS Section Head (3) 1
- *NE Section Head
- Operator Training Section Head (MDE)
- Specialty Training Section Head (RLB)
- *PED Section Head
- Required Reading System (before shift)
- VP Public Affairs (JDF)

* Distribute promptly by on-shift personnel, remainder of list distributed by Operations Department Admin Specialist

HSA ID# 2

UOR DATABASE - CONVERTED FROM OPERATIONAL EVENT DATABASE (OEDB)

1. TITLE: VAPOR EXTRACTOR EJ-5 OIL DISCHARGE TO TURBINE BUILDING ROOF.
2. OEDB #: 1955 UOR #: 94-105 LER #: OTHER:
HPES #: PRCE #:
3. TIME/DATE OF EVENT: 1150/11/29/94
ADDENDUM DATE
4. PLANT CONDITIONS:

OPERATING CONDITION (1-7): 7

5. DESCRIPTION OF OCCURENCE:

0830 Operator on rounds recorded EJ-5(seal oil) ejector vacuum of 3.8 in H2O(normal).
1150 Control room was notified oil droplets were visible on walkway outside near P-2C. PSS investigated and directed an operator to check vacuum on EJ-4(main lube oil) & EJ-5 vapor extractors. Operator found EJ-5 vacuum gauge pegged high (> 5in H2O). Operator adjusted damper approximately 1 in to bring vacuum back within specification. In order to adjust damper, a significant amount of force had to be applied to both "T" handle locking bolts in order to loosen them.
1230 Notified hazardous waste coordinator to evaluate reportability of oil spill and to initiate cleanup effort.
1320 Facilities personnel initiated cleanup of oil on roof. Approximately 3 to 5 gal of oil was recovered from the catch basin underneath the roof vent. The hazardous waste coordinator estimated that the equivalent of approximately one quart of oil blew onto the ground in droplet form. There was no accumulation of oil on the ground which could be recovered. Absorbent pads were placed around the catch basin and around the outfall pipe adjacent to the circ. water pump house. Some oil residue was found in the roof drain but there was no evidence of oil coming out of the outfall pipe.

E-PLAN LEVEL

ENS: N (Y/N)

7. REPORTABILITY DETERMINATION: REPORTING CRITERIA; SHORT TERM PROC. 1-26-1; EMERGENCY PLAN PROC. 2.50.0; LER (EXPLAIN)

Not reportable per 1-26-1. For oil spill of less than 10 gallons to ground ITEM 1 of FORM C-1, IMMEDIATE NOTIFICATION OF SPILLS is required to be filled out. This report is logged but

QOD TREND CODE:

2

ATTACHMENT 3

ATLAS DOCUMENT INPUT FORM

1. TITLE <i>unusual Occurrence Reports UOR's Vapor Extractor E-5 oil discharge to turbine building Root</i>		
2. DOCUMENT TYPE <i>Reports</i>	3. DOCUMENT FORM	
4. DOCUMENT LOCATION	5. RETENTION PERIOD	
6. TECHNICAL FILE NUMBER <i>1.8.4.2</i>		
7. DOCUMENT NUMBER		
8. REVISION NUMBER	9. DATE <i>11/29/1994</i>	10. CLASSIFICATION TYPE <i>"D"</i>
11. TOPICAL INDUSTRY ISSUE		
12. KEYWORDS		
13. SUBJECT		
14. REFERENCE DOCUMENT		
15. SYSTEM CODE	16. COMPONENT CODE	
17. CYCLE NUMBER		
18. ORIGINATOR <i>Operations</i>		
19. RECEIVER		
20. VENDOR CODE		
21. ACCESSION NUMBER		
ACTION: ADD/REPLACE/DELETE (CIRCLE ONE)		

OPERATIONS DEPARTMENT

UNUSUAL OCCURRENCE REPORT (UOR)

1. GENERAL

A. TITLE OF UOR: VAPOR EXTRACTOR EJ-5 OIL DISCHARGE TO TURBINE BUILDING ROOF.

B. DATE/TIME OF EVENT: 11/29/94 1150

2. PLANT CONDITIONS AT TIME OF OCCURRENCE:

OPERATING CONDITION (1-7): 7 PLANT TRIP ?N
REACTOR POWER (%): 100

3. DESCRIPTION OF OCCURRENCE & IMMEDIATE CORRECTIVE ACTIONS:

0830 Operator on rounds recorded EJ-5(seal oil) ejector vacuum of 3.8 in H2O(normal).

1150 Control room was notified oil droplets were visible on walkway outside near P-2C. PSS investigated and directed an operator to check vacuum on EJ-4(main lube oil) & EJ-5 vapor extractors. Operator found EJ-5 vacuum gauge pegged high (> 5in H2O). Operator adjusted damper approximately 1 in to bring vacuum back within specification. In order to adjust damper, a significant amount of force had to be applied to both "T" handle locking bolts in order to loosen them.

1230 Notified hazardous waste coordinator to evaluate reportability of oil spill and to initiate cleanup effort.

1320 Facilities personnel initiated cleanup of oil on roof. Approximately 3 to 5 gal of oil was recovered from the catch basin underneath the roof vent. The hazardous waste coordinator estimated that the equivalent of approximately one quart of oil blew onto the ground in droplet form. There was no accumulation of oil on the ground which could be recovered. Absorbent pads were placed around the catch basin and around the outfall pipe adjacent to the circ. water pump house. Some oil residue was found in the roof drain but there was no evidence of oil coming out of the outfall pipe.

4. THE FOLLOWING SIMILAR OCCURRENCES WERE FOUND IN THE OEDB:
(LIST SEARCH CRITERIA)

CRITERIA: "EJ-4, EJ-5, VAPOR EXTRACTOR"> no records found
:"OIL SPILL"> 26 records; UORs 89-035, 92-028, 92-095,
93-072, (94-038, 94-040
94-047 may be similar.)

5. REPORTABILITY DETERMINATION; REPORTING CRITERIA; SHORT TERM
PROC. 1-26-1; EMERGENCY PLAN PROC. 2.50.0; LER(EXPLAIN).

Not reportable per 1-26-1. For oil spill of less than 10
gallons to ground ITEM 1 of FORM C-1, IMMEDIATE NOTIFICATION OF
SPILLS is required to be filled out. This report is logged but
no offsite notifications are required.

5A. FITNESS FOR DUTY EVALUATED? NO (YES or NO)

5B. FOR CAUSE TEST REQUIRED? NO (YES or NO)

A For Cause Test is required as soon as possible after accidents involvi
a failure in individual performance where there is a resonable suspicion
that the worker's behavior contributed to those events which result in:

a. A personal injury.

b. A radiation exposure or release in excess of regulatory limits.

c. Actual or potential substantial degradation of the level of plant saf

5C. EVALUATE FOR 10 CFR 21 REPORTABILITY: NO (YES or NO)

6. SAFETY SIGNIFICANCE CLASSIFICATION: II

CATEGORIZE ACCORDING TO THE TIME REQUIRED FOR A RESPONSE FROM MANAGEMENT,
AFTER THE UOR HAS BEEN PRESENTED AT THE MORNING MEETING.

I: Corresponds to Work Order (WO) Priority Categories 1 thru 5.
May have Tech Spec or FSAR implications and a Safety Issues Concern
form may be needed. RESPONSE TIME is immediate or accelerated
e.g. 1400 of the same day when presented at the morning meeting.

II: Corresponds to WO Priority Category 6. RESPONSE Time
is 24 hours when presented at the Morning Meeting

III: Corresponds to WO Priority Category 7 thru 10.
A normal operational concern - routine.

7. NOTIFICATION:

	<u>Y/N</u>	<u>NOTIFIED BY</u>	<u>DATE/TIME</u>
ENS	N		
NRC RESIDENT INSPECTOR	N		
DUTY CALL OFFICER	N		
STATE INSPECTOR*	N		
INDUSTRIAL SAFETY COORDINATOR	N		

FOR: A) EMERGENCY CLASSIFICAION
B) UNSCHEDULED PLANT TRIP
OR SHUTDOWN

C) UNSCHEDULED RELEASES OF RADIOACTIVITY.
D) ANY STATE AGENCY IS NOTIFIED EXCLUSIVE
OF THE MONTHLY E-PLAN PHONE CHECKS.

8. SCREENING CRITERIA FOR CORRECTIVE ACTION:

- a. Does the event have a high probability of occurrence/recurrence and a potential high consequence with respect to Nuclear Safety, Personnel Safety, Regulatory Response, Production/Cost or Public Relations. **YES** (YES/NO)
- b. Does the event have a high probability of occurrence/recurrence or a potential high consequence where any additional occurrence/recurrence would be unacceptable. **YES** (YES/NO)

IF either 8.a or 8.b is YES, THEN go to Section 9; PSS and STA recommend type of Root Cause IAW 0-16-1.

IF both 8.a and 8.b are NO, THEN go directly to Section 10.

9. RECOMMENDED LEVEL OF ROOT CAUSE DETERMINATION: (Check one)

- DEPARTMENTAL ROOT CAUSE RC/PRCE
- INTERDEPARTMENTAL TEAM ROOT CAUSE RC/HPES
- RIR RADIOLOGICAL INCIDENT REPORT RC/Evnt Revw Bd
- RC/Alt Method

10. PRELIMINARY LONGER TERM ACTION ITEMS:

AI 94-105-1
Facilities

AI 94-105-2
Op. and
PED support.

- 1. Clean roof, roof drain and roof drain piping. SUDDEN
- 2. Perform a Root Cause to Determine the Reason for A change in the VACUUM & SYSTEM PERFORMANCE WHICH RESULTED IN THE OIL OVERFLOW

11. SOME GOOD QUESTIONS TO ASK DURING THE MORNING MEETING:

- a. Is this or another activity ongoing or likely to occur before corrective actions have been implemented? YES (YES/NO)
If so should we let it continue to occur without implementing some interim corrective measures? NO (YES/NO) *Expects RC & Temporary Dist. From ROFF VENT.*
- b. Did this event have the potential for serious personnel injury? NO (YES/NO) If serious injury had occurred would we be doing anything differently?
- c. If the problem involved a component required by technical specifications, was the opposite train component ever out of service during the period the component was inoperable? NO (YES/NO)
- d. Does anyone have any questions or concerns not previously discussed? NO (YES/NO)
- e. Should we put something on the "Nuclear Network"? NO (YES/NO)

SUBMITTED BY: P.T.EBERT

APPROVED BY/DATE: Samuel H. [Signature] 11-29-94

NOTED BY:

[Signature] 4/30/94

OPERATIONAL EVENT DATABASE

[[LAST UPDATE-10/08/94]]

44
941

O.E.D.B. #: 870
UOR # 89-035

EVENT DATE (Mo/Day/Yr) 4/6/89

EVENT TIME: 1500

OPERATING CONDITION: 7 (1-7)

ENS: y (Y/N)
E-PLAN LEVEL

Reference Documents (Leave blank if N/A)

SIC#:
L.E.R. #:
OTHER:

H.P.E.S. #:
P.R.C.E. #:

UOR TITLE Oil sheen detected on the Back River

DESCRIPTION:

An oil sheen was detected on the Back River in the vicinity of the circ water pump house. Source was believed to be from the fuel oil spill on 4/5/89. The fuel oil was leached from the roofing material and carried to the river via the storm sewer. Ref UOR 89-035, OEDB 869, by rainwater. The Hazardous Waster Coordinator contacted the Maine DEP and the US Coast Guard. The NRC was notified via ENS under 50.72(b)(2)(vi).

ADDENDUM TEXT

OPERATIONAL EVENT DATABASE

[[LAST UPDATE-10/08/94]]

O.E.D.B. #: 1623
UOR # 92-028

EVENT DATE (Mo/Day/Yr) 2/21/92
ADDENDUM DATE

OPERATING CONDITION: 1 (1-7)
TREND CODE (QPD): 19-M322-03

ENS: Y (Y/N)
E-PLAN LEVEL

EVENT TIME: 1520

Reference Documents (Leave blank if N/A)

SIC#:

L.E.R. #:

OTHER:

H.P.E.S. #:
P.R.C.E. #:

UOR TITLE

DESCRIPTION:

1530 - Control Room receives report of minor oil spill at Circ Water Pumphouse from crane operations during removal of sludge from "D"-Bay.

1600 - HAZ MAT Coordinator (S. Edgerly) confirms that spill is reportable to State DEP; but not to U.S. Coast Guard. Spill is on the ground and quantity is estimated at about one pint.

1615 - HAZ MAT Coordinator notifies State of Maine D.E.P. and advises that clean up in progress. D.E.P. satisfied with MY response.

1625 - Notified SNSI's office of call to D.E.P.

1635 - M. Murphy advised of offsite calls being made. No media attention expected.

1637 - NRC Resident's Office notified of offsite State notifications and impending Red Phone call.

1700 - AMOD advised of impending ENS call.

1721 - NRC notified via ENS/Red Phone per 10CFR50.72 (b) (2) (vi).

ADDENDUM TEXT

OPERATIONAL EVENT DATABASE

[[LAST UPDATE-10/08/94]]

O.E.D.B. #: 1694

UOR # 92-095

EVENT DATE (Mo/Day/Yr) 11/03/92

EVENT TIME: 1155

OPERATING CONDITION: 7 (1-7)

ADDENDUM DATE

ENS: Y (Y/N)

TREND CODE (QPD): EG-A335-E6

E-PLAN LEVEL

Reference Documents (Leave blank if N/A)

SIC#:

H.P.E.S. #:

L.E.R. #:

P.R.C.E. #:

OTHER:

UOR TITLE VISIBLE OIL SHEEN ON BACK RIVER DURING RAINSTORM

DESCRIPTION:

1155 - Security notified PSS of oil sheen on the back river by the circ pump house. PSS and Hazardous Waste Specialist investigated and determined the event to be reportable IAW the spill plan.

Facilities instructed to contain oil with boom and collect it with absorbent sheets.

Notifications made per the spill plan (see attached form).

During cleanup an oil sheen was found on the rain water entering the storm drain near the walkway where the transformer was cut up. Storm drain was covered; oil stopped from entering the river.

ADDENDUM TEXT

OPERATIONAL EVENT DATABASE

[[LAST UPDATE-10/08/94]]

O.E.D.B. #: 1793

UOR # 93-072

EVENT DATE (Mo/Day/Yr) 8/31/93

ADDENDUM DATE

EVENT TIME: 1200

OPERATING CONDITION: 1 (1-7)

ENS: Y (Y/N)

TREND CODE (QPD):

E-PLAN LEVEL

Reference Documents

(Leave blank if N/A)

SIC#:

L.E.R. #:

H.P.E.S #:

OTHER:

P.R.C.E. #:

UOR TITLE OIL SHEEN IN THE BACK RIVER

DESCRIPTION:

1200 - The control room was notified of an oil sheen in the Back River. The sheen was inside the boom for the pump house intake.

Investigation determined that the source was a sump in the southwest corner of the pump house.

An NPO secured the sump pump and cleaned up the oil with absorbant pads and swipes.

The source of oil may have been P-26A which had oil marks on its discharge head and base.

Notifications were made IAW the Maine Yankee Spill Plan.

ADDENDUM TEXT

OPERATIONAL EVENT DATABASE

[[LAST UPDATE-10/08/94]]

O.E.D.B. #: 1886

UOR # 94-038

EVENT DATE (Mo/Day/Yr) 6/15/95

ADDENDUM DATE

EVENT TIME: 1802

OPERATING CONDITION: 7 (1-7)

ENS: Y (Y/N)

TREND CODE (QPD):

E-PLAN LEVEL

Reference Documents (Leave blank if N/A)

SIC#:

H.P.E.S #:

L.E.R. #:

P.R.C.E. #:

OTHER:

UOR TITLE OIL SHEEN ON BACK RIVER

DESCRIPTION:

- 1802- Security notified the control room of a visible oil sheen on the Back River. The initial investigation confirmed that a sheen was inside the boom for the pump house intake but no source could be identified. After all the possible sources from the circ water pump house were checked, it was decided to check each of the storm drains in the area.
- 1910- The PSS identified the source of the sheen to be the "E" storm drain outfall on the North side of the circ water pumphouse. The storm drain had approximately 30 gpm of water flowing out onto oily absorbent pads and on into the river. The source of the water was determined to be the vacuum priming pump sump. The amount of oil spilled into the river was estimated to be one pint. The Hazardous Material Response Team was activated and clean absorbent pads from the spill response kit were placed under the outfall.
- 1940- Hazardous Material Response Team on site and placed additional absorbent materials around the outfall. The sheen subsequently dissipated.
- Notifications were made IAW the Maine Yankee Spill Plan.
- 2200- Grab sample from the vacuum priming sump indicated less than 1 ppm oil. Discovered oil sheen in storm drains "E2" "E3" and on wood walkway outside door by P-2C. Suspect source to be roof work on turbine building (roof drain runs into storm drain E-2).

ADDENDUM TEXT

OPERATIONAL EVENT DATABASE

[[LAST UPDATE-10/08/94]]

O.E.D.B. #: 1888

UOR # 94-040

EVENT DATE (Mo/Day/Yr) 06/18/94

ADDENDUM DATE

EVENT TIME: 0830

OPERATING CONDITION: 7 (1-7)

ENS: Y (Y/N)

TREND CODE (QPD): 1B-0211-D0

E-PLAN LEVEL N/A

Reference Documents (Leave blank if N/A)

SIC#:

H.P.E.S. #:

L.E.R. #:

P.R.C.E. #:

OTHER:

UOR TITLE OIL SHEEN ON BACK RIVER

DESCRIPTION:

0830 Industrial Safety Coordinator notified the Control Room about the presence of a small oil sheen on the Back River. The source appeared to be the same as described in UOR 94-038 (turbine building roof drains). Heavy rains from the previous evening prompted the event.

The HAZ MAT team responded and deployed an oil boom near the outfall of the storm sewer discharge that serves the turbine building roof drains.

Cleaned up oil sheen with absorbent pads.

Additional oil absorbent materials were placed around storm sewer outlet.

0900 Notifications were made to offsite agencies IAW the Maine Yankee Spill Plan.

ADDENDUM TEXT

OPERATIONAL EVENT DATABASE

[[LAST UPDATE-10/08/94]]

UCR
94-1

O.E.D.B. #: 1896

UCR # 94-047

EVENT DATE (Mo/Day/Yr) 06/30/94

ADDENDUM DATE

EVENT TIME: 1000

OPERATING CONDITION: 7 (1-7)

ENS: Y (Y/N)

TREND CODE (QPD): 1b-0340-01

E-PLAN LEVEL

Reference Documents (Leave blank if N/A)

SIC#:

L.E.R. #:

OTHER:

H.P.E.S #:

P.R.C.E. #:

UOR TITLE OIL SHEEN AT CIRCULATING WATER INTAKE STRUCTURE

DESCRIPTION:

NOTE: ALL TIMES ARE APPROXIMATE.

1000: A SLIGHT OIL SHEEN IS NOTED ON THE SURFACE OF THE WATER AT THE CIRCULATING WATER PUMP INTAKE STRUCTURE, INSIDE THE INSTALLED BOOM.

1100: CLEANED THE OIL SHEEN WITH ABSORBENT PADS.

1600 FOLLOWING DAY: NOTIFICATIONS WERE MADE TO OFFSITE AGENCIES IAW THE MAINE YANKEE SPILL PLAN. DUE TO THE EXTREMELY SMALL SIZE OF THE OIL SHEEN, IT WAS NOT IMMEDIATELY APPARENT THAT NOTIFICATION WAS REQUIRED; THUS ACCOUNTING FOR THE DELAY IN REPORTING.

ADDENDUM TEXT

HSA ID# 3

UOR DATABASE - CONVERTED FROM OPERATIONAL EVENT DATABASE (OEDB)

1. TITLE: Contents of sump pumped into river. Milky color caused discoloration of river. Some oil in pit. Considered to be emulsion.
MAIN TRANSFORMER DRAIN SUMP PUMP DOWN
2. OEDB #: 710 UOR #: 124-88 LER #: OTHER:
HPES #: PRCE #:
3. TIME/DATE OF EVENT: 2100/11/17/88
ADDENDUM DATE 11/18/88
4. PLANT CONDITIONS:

OPERATING CONDITION (1-7): 1

5. DESCRIPTION OF OCCURENCE:

Prior approval to pump down sump granted by H.W.C. Pump down stopped due to milky color. Some oil on surface of water in sump. No initial phone calls based on H.W.C. assessment. In the morning a sheen of oil developed on the river. The H.W.C. decided the State should be called and Thurs NRC were called also. At approximately 0900 on 11/18/88 a sheen of oil was noticed on the back river between the circ. water pumphouse trash boom and screen wash trough. The sheen occupied approximately 500 square feet. The Hazardous Waste Coordinator decided that because of the area involved, the oil spill should be reported to the Maine Dept. of Enviromental Protection and the US Coast Guard. These reports were made at 0930hrs and at 1000 hrs. The NRC was notified per 10CFR 50.72 (b)(2)(vi) as a condition that impacts the environment for which Maine Yankee made notification to other governmental agencies.

No releases were in progress when the oil sheen was noticed. It is believed that the oil originated from the transformer sump drain conducted earlier.

E-PLAN LEVEL

ENS: Y (Y/N)

7. REPORTABILITY DETERMINATION: REPORTING CRITERIA; SHORT TERM
PROC. 1-26-1; EMERGENCY PLAN PROC. 2.50.0; LER (EXPLAIN)

QOD TREND CODE:

HSA ID# 4

UOR DATABASE - CONVERTED FROM OPERATIONAL EVENT DATABASE (OEDB)

1. TITLE: OIL LEAKAGE INTO SPRAY BUILDING
OIL LEAKAGE INTO SPRAY BUILDING
2. OEDB #: 1203 UOR #: 89-106 LER #: OTHER:
HPES #: PRCE #:
3. TIME/DATE OF EVENT: 2130/10/29/89
ADDENDUM DATE 10/31/89
4. PLANT CONDITIONS:

OPERATING CONDITION (1-7): 7

5. DESCRIPTION OF OCCURENCE:

2130 Primary AO was making weekly tour of the Spray Building and noticed very strong odor of fuel oil upon entering building. While inspecting the lower level of the spray building the AO noticed that oil had seeped onto the -6 ft elevation NW corner by E-3A. This area had historically allowed inleakage of rainwater. (see photos)

The oil water mixture had flowed along the -6 ft level and entered the -11 ft pit area below E-3A. (see photos)

The spray building sump pumps were turned off and absorbent material was placed on the oil. The area around the spray building was inspected to ensure there was no current source of leaking fuel oil.

The source of the oil was probably the leak identified from the storage tank for the RWST enclosure furnace identified in UOR 89-102. At the time the smell of fuel oil in the spray building was identified as probably entering via HV-7.

Since the source of fuel oil was probably the oil leak identified earlier no additional reporting requirements exist.

-1000 OPERATIONS COMMENCED PUMPING WELL POINTS IN ORDER TO SAMPLE THE WELL POINTS FOR OIL.

-1210 HAZARDOUS WASTE COORDINATOR NOTIFIED MAINE DEP OF OIL SPILL.

-1215 HAZARDOUS WASTE COORDINATOR NOTIFIED NATIONAL RESPONSE CENTER OF OIL SPILL.

THESE CALLS WERE MADE AFTER JOINT DISCUSSION AND DECISION BETWEEN LICENSING AND THE HAZARDOUS WASTE COORDINATOR.

-1330 4 HOUR REPORT UNDER 50.72 (B)(2)(VI) WAS MADE TO THE NRC VIA THE ENS DUE TO AN EVENT RELATED TO THE PROTECTION OF THE ENVIRONMENT FOR WHICH NOTIFICATION TO OTHER GOVERNMENT AGENCIES WAS MADE.

AT THE TIME OF THE WRITING, 1500, NO OIL HAS BEEN OBSERVED IN WATER PUMPED FROM THE WELL POINTS.

E-PLAN LEVEL ENS: N (Y/N)

7. REPORTABILITY DETERMINATION: REPORTING CRITERIA; SHORT TERM
PROC. 1-26-1; EMERGENCY PLAN PROC. 2.50.0; LER (EXPLAIN)

N

QOD TREND CODE:

DECOM

4

2547.10.1

ATTACHMENT B

ATLAS DOCUMENT INPUT FORM

1. TITLE UOR 89-106 And Addendum oil Leakage Into Spray Bldg.		
2. DOCUMENT TYPE Report	3. DOCUMENT FORM M	
4. DOCUMENT LOCATION	5. RETENTION PERIOD	
6. TECHNICAL FILE NUMBER 11.14.6	1.8.4.2	
7. DOCUMENT NUMBER		
8. REVISION NUMBER	9. DATE 10/29/89	10. CLASSIFICATION TYPE D
Addendum 10/30/89		
11. TOPICAL INDUSTRY ISSUE		
12. KEYWORDS		
13. SUBJECT		
14. REFERENCE DOCUMENT		
15. SYSTEM CODE	16. COMPONENT CODE	
17. CYCLE NUMBER		
18. ORIGINATOR OPS		
19. RECEIVER		
20. VENDOR CODE		
21. ACCESSION NUMBER		
ACTION: ADD/REPLACE/DELETE (CIRCLE ONE)		

2547.10.2

File

OPERATIONS DEPARTMENT
 UNUSUAL OCCURRENCE REPORT (UOR)

1. GENERAL

- A. TITLE OF UOR: OIL LEAKAGE INTO SPRAY BUILDING
- B. DATE/TIME OF EVENT: 10/29/89 2130
- C. DATE/TIME UOR COMPLETED: 10/29/89 2400

2. PLANT CONDITIONS AT TIME OF OCCURRENCE:

- A. OPERATING CONDITION (1-7): 7 B. REACTOR POWER (%): 98
- C. TAVE (F): 574 D. PZR. PRESSURE (PSIG): 2235 E. PZR LEVEL (%) 58
- PLANT TRIP? NO

3. NOTIFICATION

- A. IS NRC NOTIFICATION REQUIRED? N
 (Justify "NO" answer in Discussion Section.)
- B. HAS PROCEDURE 2.50.0 BEEN CONSULTED? NO
 - B.1 EMERG CONDITION DECLARED : N/A
 - B.2 DATE/TIME OF DECLARATION : N/A
- C. NRC NOTIFIED BY : N/A USING : N/A
 - C.1 DATE/TIME : N/A
- D. NRC RESIDENT NOTIFIED BY : COPY OF UOR
 - D.1 DATE/TIME : N/A
- E. DUTY CALL OFFICER (DCO) NOTIFIED BY : COPY OF UOR
 - E.1 DATE/TIME : N/A
- F. AMOD NOTIFIED BY : COPY OF UOR
 - F.1 DATE/TIME : N/A
- NOTE : AMOD NOTIFY MOD
 PSS notify MOD IF AMOD not available
- G. IF industrial safety concern, notify Industrial Safety Coordinator
 ISC NOTIFIED BY : N/A
 - G.1 DATE/TIME : N/A

OPERATIONS DEPARTMENT
UNUSUAL OCCURRENCE REPORT (UOR)

4. DESCRIPTION OF OCCURRENCE/SEQUENCE OF EVENTS

2130 Primary AO was making weekly tour of the Spray Building and noticed very strong odor of fuel oil upon entering building.

While inspecting the lower level of the spray building the AO noticed that oil had seeped onto the -6 ft elevation NW corner by E-3A. This area had historically allowed inleakage of rainwater. (see photos)

The oil water mixture had flowed along the -6 ft level and entered the -11 ft pit area below E-3A. (see photos)

The spray building sump pumps were turned off and absorbent material was placed on the oil. The area around the spray building was inspected to ensure there was no current source of leaking fuel oil.

The source of the oil was probably the leak identified from the storage tank for the RWST enclosure furnace identified in UOR 89-102. At the time the smell of fuel oil in the spray building was identified as probably entering via HV-7.

Since the source of fuel oil was probably the oil leak identified earlier no additional reporting requirements exist.

2547.10.4

OPERATIONS DEPARTMENT
UNUSUAL OCCURRENCE REPORT (UOR)

5. IMMEDIATE CORRECTIVE ACTIONS

Secure spray building sump pumps and use absorbent material on oily water.
Ensured there is no current source of oil leakage.

6. PRELIMINARY RECOMMENDATIONS FOR LONG TERM CORRECTIVE ACTION

Pump PCC well point to determine if there is any oil in the ground water.

Conduct a thorough cleanup of the spray building floors and sump to ensure all oil is removed.

Determine long term plan to eliminate oil or collect leakage into spray building.

Submitted by : *Rodney Dee*


Approved by : *A. J. Murphy*

Noted by : *R. Blaine*

Distribution:

- | | |
|--------------------------|--|
| • PM/VPO (ETB) | • State Inspector |
| • APM/MOM (RFP) | • NEC RESIDENT (CFH) |
| • MOD (RWB) | • MGR QPD (JCF) |
| • AMOD (AJC) | • AUGUSTA TELEX |
| • ATMOD | • NSS Section Head (2) |
| • ATVPO (JMC) | Operator Training Section Head (MDE) |
| • MGR Tech Support (JER) | Specialty Training Section Head (RLB) |
| • PSS | PEO Section Head |
| • SOS | Required Reading System (before shift) |
| • RO (2) | VP Public Affairs (JDF) |

- Distribute promptly by on-shift personnel, remainder of list distributed by Operations Department Admin Specialist



Access to pit below E-3A
-6 ft elevation




Pit below E-3A
-11 ft elevation



Northwest Corner
By E-3A
-6 ft elevation



Close-up of NW
corner by E-3A
-6 ft elevation



Pit below E-3A
-11 ft elev

USE
89-106

File w/ UOR

2547-10-6

MY-0-3-76
Rev. 8
Page 3 of 3

ADDENDUM TO UOR 89-106

OPERATIONS DEPARTMENT

UNUSUAL OCCURENCE REPORT (UOR)

ADDITIONS TO UOR DATE OF ADDENDUM: 10/30/89

- 1000 Operations commenced pumping well points in order to sample the well points for oil.
- 1210 Hazardous Waste Coordinator notified Maine DEP of oil spill.
- 1215 Hazardous Waste Coordinator notified National Response Center of oil spill.

These calls were made after joint discussion and decision between licensing and the Hazardous Waste Coordinator.

- 1330 4 hour report under 50.72 (B)(2)(vi) was made to the NRC via the ENS due to an event related to the protection of the environment for which notification to other government agencies was made.

At time of writing, 1500, no oil has been observed in water pumped from the well points.

Submitted by: *[Signature]*
 Approved by: *[Signature]*
 Noted by: *[Signature]*

Distribution:

- | | |
|---|--|
| <ul style="list-style-type: none"> •PM/VPO (ETB) •APM/MOM (RFP) •MOD (RWB) •AMOD (AJC) •ATMOD •ATVPO (JMC) •MGR Tech Support (JEB) •PSS •(2) | <ul style="list-style-type: none"> •State Inspector •NRC RESIDENT (CFH) •MGR QPD (JCF) •AUGUSTA TELEX •NSS Section Head (2) Operator Training Section Head (MDE) Specialty Training Section Head (RLB) PED Section Head Required Reading System (before shift) VP Public Affairs (JDF) |
|---|--|

* Distribute promptly by on-shift personnel, remainder of list distributed by Operations Department Admin Specialist

File

2547-10.7

ADDENDUM to UOR 89-106 "OIL LEAKAGE INTO SPRAY BUILDING"

30 OCTOBER 1989

- 0100 - The PSS , after touri the spray building , decided that the 4-5 gallons of fuel oil seepage was an added fire consideration and should be corrected.
- 0130 - The DCO was called.
- 0130 - An operator was dispatched to the spray building to establish a foam application system and to act as a fire watch.
- 0145 - The fire protection coordinator was called in to direct establishing interim fire protection measures.
- 0220 - Personnel from plant services were called in to support the clean-up.
- A review of OP 1-26-1 reporting requirements indicates that there are no immediate reporting requirements. This assessment is based on the reprotability evaluation made for the fuel oil spill described in UOR 89-102 " Fuel Oil Spill from Storage Tank for RWST Enclosure Furnace" because this spill is considered to be the source of the oil seeping into the spray building.

RECOMMENDATION:

89-106-5

- A reevaluation of the fuel oil spill reportability should be made considering the current seepage into the spray building.


Submitted by *James M. Taylor*

Approved by : *Whant*

Noted by :

ADDENDUM TO WORK ORDER
 47.10.00

AREA OF F.O. LEAK
 AREA OF INGRESS
 LOWER SPRAY BUILDING



NEW NON-SAFETY
 FL-77 - PRE-FIL
 FL-78 - CHARCO
 FL-79 - HEPA F

HSA ID# 5

UOR DATABASE - CONVERTED FROM OPERATIONAL EVENT DATABASE (OEDB)

1. TITLE:

2. OEDB #: 1623 UOR #: 92-028 LER #: OTHER:
HPES #: PRCE #:
3. TIME/DATE OF EVENT: 1520/2/21/92
ADDENDUM DATE
4. PLANT CONDITIONS:

OPERATING CONDITION (1-7): 1

5. DESCRIPTION OF OCCURENCE:

1530 - Control Room receives report of minor oil spill at Circ Water Pumphouse from crane operations during removal of sludge from "D"-Bay.

1600 - HAZ MAT Coordinator (S. Edgerly) confirms that spill is reportable to State DEP; but not to U.S. Coast Guard. Spill is on the ground and quantity is estimated at about one pint.

1615 - HAZ MAT Coordinator notifies State of Maine D.E.P. and advises that clean up in progress. D.E.P. satisfied with MY response.

1625 - Notified SNSI's office of call to D.E.P.

1635 - M. Murphy advised of offsite calls being made. No media attention expected.

1637 - NRC Resident's Office notified of offsite State notifications and impending Red Phone call.

1700 - AMOD advised of impending ENS call.

1721 - NRC notified via ENS/Red Phone per 10CFR50.72(b)(2)(vi).
E-PLAN LEVEL ENS: Y (Y/N)

7. REPORTABILITY DETERMINATION: REPORTING CRITERIA; SHORT TERM
PROC. 1-26-1; EMERGENCY PLAN PROC. 2.50.0; LER (EXPLAIN)

MINOR OIL SPILL DURING C.W. PUMPHOUSE MAINTENANCE

Reportable under 10 CFR 50.72(b)(2)(vi) as a Four Hour, Non-Emergency Report (notification of other government agencies of an event related to protection of the environment).

QOD TREND CODE: 19-M322-03

5

DECOM

2004.3.1

ATTACHMENT B

ATLAS DOCUMENT INPUT FORM

1. TITLE <u>UOR 92-028</u>		
<u>Minor Oil Spill During C.W. Pump House Maintenance</u>		
2. DOCUMENT TYPE <u>Report</u>	3. DOCUMENT FORM <u>M</u>	
4. DOCUMENT LOCATION	5. RETENTION PERIOD	
6. TECHNICAL FILE NUMBER <u>11.14.6</u> <u>1.8.4.2</u>		
7. DOCUMENT NUMBER		
8. REVISION NUMBER	9. DATE <u>2/21/92</u>	10. CLASSIFICATION TYPE <u>D</u>
11. TOPICAL INDUSTRY ISSUE		
12. KEYWORDS		
13. SUBJECT		
14. REFERENCE DOCUMENT		
15. SYSTEM CODE	16. COMPONENT CODE	
17. CYCLE NUMBER		
18. ORIGINATOR <u>OPS</u>		
19. RECEIVER		
20. VENDOR CODE		
21. ACCESSION NUMBER		
ACTION: ADD/REPLACE/DELETE (CIRCLE ONE)		

CREW REVIEW/RQ

254-3-2

OPERATIONS DEPARTMENT
UNUSUAL OCCURRENCE REPORT (UOR)

1. GENERAL

- A. TITLE OF UOR: MINOR OIL SPILL DURING C.W. PUMPHOUSE MAINTENANCE
- B. DATE/TIME OF EVENT: 2/21/92 1520
- C. DATE/TIME UOR COMPLETED: 2-21-92 2030

2. PLANT CONDITIONS AT TIME OF OCCURRENCE:

OPERATING CONDITION (1-7): 1	PLANT TRIP ?N/A
REACTOR POWER (%): 0	PZR PRESSURE (psig): 14.7
Tave (deg F): 96	PZR LEVEL (%): 61

3. DESCRIPTION OF OCCURRENCE/SEQUENCE OF EVENTS:

1530 - Control Room receives report of minor oil spill at Circ Water Pumphouse from crane operations during removal of sludge from "D"-Bay.

1600 - HAZ MAT Coordinator (S. Edgerly) confirms that spill is reportable to State DEP; but not to U.S. Coast Guard. Spill is on the ground and quantity is estimated at about one pint.

1615 - HAZ MAT Coordinator notifies State of Maine D.E.P. and advises that clean up in progress. D.E.P. satisfied with MY response.

1625 - Notified SNSI's office of call to D.E.P.

1635 - M. Murphy advised of offsite calls being made. No media attention expected.

1637 - NRC Resident's Office notified of offsite State notifications and impending Red Phone call.

1700 - AMOD advised of impending ENS call.

1721 - NRC notified via ENS/Red Phone per 10CFR50.72(b)(2)(vi).

5. REPORTABILITY DETERMINATION: (EXPLAIN, INCLUDING REPORTING CRITERIA AND EMERGENCY PLAN INFORMATION. CO. MIT PROCEDURE 2.50.0).

Reportable under 10 CFR 50.72(b)(2)(vi) as a Four Hour, Non-Emergency Report (notification of other government agencies of an event related to protection of the environment).

6. SAFETY SIGNIFICANCE CLASSIFICATION: III
CATEGORIZE ACCORDING TO THE TIME REQUIRED FOR A RESPONSE FROM MANAGEMENT, AFTER THE UOR HAS BEEN PRESENTED AT THE MORNING MEETING.

Category I: Corresponds to Work Order (WO) Priority Categories 1 thru 5. May have Tech Spec or FSAR implications and a Safety Issues Concern form may be needed. RESPONSE TIME is immediate or accelerated e.g. 1400 of the same day when presented at the morning meeting.

Category II: Corresponds to WO Priority Category 6. RESPONSE TIME is 24 hours when presented at the Morning Meeting.

Category III: Corresponds to WO Priority Category 7 thru 10. A normal operational concern - routine.

7. IMMEDIATE CORRECTIVE ACTIONS:

1. Contain spill.
2. Commence clean-up.
3. Advise HAZ MAT
4. Assess reportability
5. Make required notifications.

8. ACTION ITEMS (LONG TERM):

~~1. Reassess NY policy for making ENG calls for such minor oil spills.~~

1. Complete submission of spill plan to state DEP.
Lic. NY.

9. NOTIFICATION:

	Y/N	NOTIFIED BY	DATE/TIME
ENS	Y	R. Maloney	1721: 2/21/92
NRC RESIDENT INSPECTOR DUTY CALL OFFICER	Y	R. Maloney	1637: 2/21/92
STATE INSPECTOR*	n		
INDUSTRIAL SAFETY COORDINATOR	Y	R. Maloney	1625: 2/21/92
	n		

- * NOTIFY THE SNI IN CASE OF A) EMERGENCY CLASSIFICATION
B) UNSCHEDULED PLANT TRIP OR SHUTDOWN.
C) UNSCHEDULED RELEASES OF RADIOACTIVITY.
D) ANY STATE AGENCY IS NOTIFIED EXCLUSIVE OF THE
MONTHLY E-PLAN PHONE CHECKS.

SUBMITTED BY: R.E. Maloney

APPROVED BY: _____

NOTED BY: _____

Distribution:

*PM (RWB)	*CED Manager (JRH)
*MMD (RLB)	*State Inspector (PJD)
*MOD (AJC)	*NRC RESIDENT (CSM/WTO)
*MTSD (RHN)	*MGR QPD (JCF)
*AMOD (JAN)	*AUGUSTA TELEX
*ATMOD	*NSS Section Head
*PSS	*MOPS (RRL)
*SOS	*RE Supervisor (DAR)
*RD	*Security - SAS (Shift Lieutenant)
*VP, OPS (ETB)	Operator Training Section Head (MDE)
*QPD Section Head (STL)	Specialty Training Section (HMS)
*MSP (MJV)	Required Reading System (before shift)
*PED Manager (CRS)	Public Affairs Director (MDM)

* Distribute promptly by on-shift personnel, remainder of list
distributed by Operations Department Admin Specialist

HSA ID# 6

UOR DATABASE - CONVERTED FROM OPERATIONAL EVENT DATABASE (OEDB)

1. TITLE: OIL SHEEN ON BACK RIVER
2. OEDB #:2045 UOR #: 95-039 LER #: OTHER:
HPES #: PRCE #:
3. TIME/DATE OF EVENT: 1156/3/31/95
ADDENDUM DATE
4. PLANT CONDITIONS:

OPERATING CONDITION (1-7): 1

5. DESCRIPTION OF OCCURRENCE:

3/31/95

1156 SECURITY NOTIFIED THE CONTROL ROOM OF A VISIBLE OIL SHEEN ON THE BACK RIVER. THE INITIAL INVESTIGATION BY THE PSS INDICATED THE SOURCE OF THE SHEEN TO BE THE E STORM DRAIN OUTFALL ON THE NORTH SIDE OF THE CIRC WATER PUMPHOUSE. PLANT SERVICES WAS NOTIFIED AND THE SPILL TEAM RESPONDED. LEAVES IN THE STORM DRAIN OUTLET APPEARED TO BE BLOCKING AND FILTERING THE OIL.

1215 ABSORBENT PADS PLACED UNDER THE OUTFALL.

MOD NOTIFIED OF SPILL. THE TURBINE HALL ROOF CATCH BASIN DRAIN SIGHT GLASS AND THE PIPE OUTLET TO THE TURBINE HALL SUMP WERE CHECKED AND NO OIL RESIDUE WAS DETECTED. IT WAS SUBSEQUENTLY DETERMINED THAT THE VAPOR EXTRACTOR CATCH BASIN INSTALLATION STILL HAD SOME MINOR WORK TO BE COMPLETED AND THE ROOF PLUGS WERE STILL INSTALLED IN THE BASINS. THE CATCH BASINS WERE FOUND TO BE FULL WATER AND THEY HAD A LAYER OF OIL ON TOP OF THE WATER.

THE LIGHT OIL WHICH DISCHARGED INTO THE RIVER SPREAD AND DISSIPATED RAPIDLY. THE ESTIMATED AMOUNT WAS LESS THAN 1 QUART.

IN ADDITION TO THE NOTIFICATIONS LISTED IN SECTION 7, THE STATE OF MAINE DEPARTMENT OF ENVIRONMENTAL PROTECTION WAS NOTIFIED AT 1252 AND THE NATIONAL RESPONSE CENTER WAS NOTIFIED AT 1315.

1445 AFTER OBTAINING CONCURRENCE FROM CED, THE CATCH BASIN PLUGS WERE REMOVED AND THEIR CONTENTS WERE DRAINED TO THE TURBINE HALL SUMP.

1600 FACILITIES SETTING UP TO FLUSH ROOF DRAINS TO REMOVE ANY RESIDUAL OIL.

QOD TREND CODE:

6

ATTACHMENT 3

ATLAS DOCUMENT INPUT FORM

1. TITLE <i>unusual Occurrence Reports UOR's</i> <i>Oil Sheen on Back Kenev</i>		
2. DOCUMENT TYPE <i>Reports</i>	3. DOCUMENT FORM	
4. DOCUMENT LOCATION	5. RETENTION PERIOD	
6. TECHNICAL FILE NUMBER <i>1.8.4.2</i>		
7. DOCUMENT NUMBER		
8. REVISION NUMBER	9. DATE <i>03/31/1995</i>	10. CLASSIFICATION TYPE <i>"D"</i>
11. TOPICAL INDUSTRY ISSUE		
12. KEYWORDS		
13. SUBJECT		
14. REFERENCE DOCUMENT		
15. SYSTEM CODE	16. COMPONENT CODE	
17. CYCLE NUMBER		
18. ORIGINATOR <i>Operations</i>		
19. RECEIVER		
20. VENDOR CODE		
21. ACCESSION NUMBER		
ACTION: ADD/REPLACE/DELETE (CIRCLE ONE)		

MEMORANDUM

UCR
95-039

CORPORATE ENGINEERING DEPARTMENT

TO: TEDD M. GIFFORD
DATE: APRIL 5, 1995
FROM: MATTHEW J. MARSTON *mgj*
FILE: MJM-95-003
SUBJECT: AI-95-039-3 TURBINE HALL ROOF DRAIN MOD ACTION ITEM RESPONSE

REFERENCES:

- a. UCR 94-038, "Oil Sheen on Back River", dated June 15, 1994.
- b. UOR 94-040, "Oil Sheen on Back River", dated June 18, 1994.
- c. Memo from Matthew J. Marston to Robert H. Nelson, "Oil Sheen on the Back River - Root Cause No. CED-RC-94-005", file no. MJM-94-011, Rev. 1, dated October 31, 1994.
- d. Letter from James R. Hebert to Frank Gehrling, Maine DEP, "Oil Spill Reports for Very Small Spills (all one pint or less) Occurring on June 15, 18, and 30, 1994", file no. JRH-94-173, dated August 9, 1994.
- e. Technical Evaluation 365-94, "Turbine Hall Roof Drain Modifications".
- f. Work Order 94-4232-00.
- g. UCR 95-039, "Oil Sheen on Back River", dated March 31, 1995.

This memo is written to address concerns with regard to an overboard discharge of oil. Of specific interest are the reasons behind the fact that the installation of new roof drains intended to preclude such a discharge were not completed and why Plant Management was not aware of the fact that they were not completed. In addition, a summary of the status of other outstanding CED Projects is provided.

BACKGROUND:

References a. and b. were issued to document two separate instances of small oil spills observed on the Back River. As a result of these incidents, a tygon hose was installed to direct the North vapor extractor roof drain to the Turbine Hall Sump and a Root Cause Analysis (Reference c.) was performed. The Root Cause for the spills was determined to be a malfunction of a mechanical position stop on a discharge blast gate associated with the Seal Oil Vapor Extractor (EJ-5). The failure of the stop allowed the blast gate to become full open resulting in a high EJ-5 discharge flow. The higher than normal discharge flow carried with it a high oil content that was in turn deposited on the Turbine Hall Roof. Since the roof drains are routed to the yard storm drains, the oil from EJ-5 was discharged into the river.

The overboard oil spills were reportable and in the written report submitted to the State (Reference d.), Maine Yankee committed to the installation of a segregated drain system that would direct the drainage from bermed areas surrounding both the EJ-5 discharge and the Lube Oil Vapor Extractor (EJ-4) discharge to the Turbine Hall Sump. This modification would ensure that future malfunctions would not result in overboard discharges of oil. The required modifications were evaluated and approved in Technical Evaluation 365-94, "Turbine Hall Roof Drain Modifications" (Reference e.) as a "Facilities Modification", and the installation work commenced.

On Saturday, March 31, 1995, a third UOR (Reference g.) was issued as a result of an overboard discharge of oil. The source of the oil was again determined to be the Turbine Hall Roof Drains.

DISCUSSION:

With regard to the roof drain installation, the following information is provided:

1. A "Facilities Modification" may be installed without the use of a Job Order. As such, the controls associated with "Job Order Commitments" for control of partially modified systems do not apply.
2. Work Order 94-4232-00 (Reference f.) was signed-on by an OPS SCS as "work approved without White Tags" with the noted exception that the Turbine Hall Crane bus bars must be tagged out during Manlift operation. Since the vapor extractors posed no personnel safety hazard, tagging of this equipment was not considered.
3. The temporary tygon hose was installed on the North vapor extractor roof drain without the use of Yellow Tags (consistent with procedural requirements). The Operations Department tracked the status of the tygon hose in their Day-to-Day Operating Concerns.
4. Inflatable plugs were installed in the two berm area roof drains to preclude drainage through the partially installed piping during the course of drain installation and the temporary tygon hose was removed. This was done without the use of White or Yellow Tags (consistent with procedural requirements). Plant Management was informed of this requirement via discussion at the Morning Management Meeting by CED Management.
5. As a result of the required work locations, a Manlift was brought on site that would allow installation of the new roof drains without constructing a large amount of scaffolding. The Manlift travel path was to the South of the Turbine Hall Crane Bay. On January 14, 1995, while working to complete the roof drain work, the Cianbro Manlift malfunctioned and was removed from service until repairs could be completed.

6. Since the tygon hose was removed and the new drain piping appeared to be complete, OPS removed the associated Day-to-Day Operating Concern from their list.
7. On January 14, 1995, the plant was tripped due to the detection of a ground in the Main Generator. As a result of the ground, Main Generator disassembly was initiated. Westinghouse was mobilized to support the disassembly and, as described on the Turbine Deck Laydown Plan, the Westinghouse tool connex boxes were placed on the South and West sides of the crane bay.
8. Staging for the North end roof drain work would have resulted in interferences with handling of the tools and equipment involved in turbine and generator maintenance in the crane bay and for crane operation over the Main Generator. In addition, staging on the Turbine Deck for the South end roof drain work would have interfered with laydown for turbine and generator maintenance, crane operation, and Engineered Lift crane inspections.
9. With the plant shutdown, the risk of an additional oil spill was considered to be minimal. With the concurrence of CED Management, it was decided to defer completion of the drains until Manlift access could be restored.
11. On March 20, 1995, the oil system was inspected and the results of the inspection were used to verify the Main Generator Center alignment.
12. A review of all other CED Projects that were currently in progress or that otherwise remained open was performed to verify that partially completed mods were adequately controlled. The following table lists the results of the investigation:

PROJECT DESCRIPTION	EDCR/ WO/FAC MOD	PROJ. ENG.	STATUS	WTO	REMARKS
PRIOR CYCLES					
MAIN GENERATOR RENEWAL	EDCR	CHG	OPEN	YES	TURNING GEAR AIR MOTOR.
WATER TREATMENT UPGRD	EDCR	MJM	OPEN	YES	I-6 SAMPLE LINE TO SILICA ANALYZER
SERVICE BUILDING MODS.	EDCR	FSD	OPEN	NO	WORK COMPLETED.

UOR
95-

CONCLUSIONS:

1. Communications in both directions between CED and OPS could have been improved. In this case, CED did not inform OPS that the modification was delayed and could not be completed until access to the roof from the Turbine Deck could be restored, consult OPS during the decision making process, or re-schedule the completion of the roof drain work. In addition, OPS assumed that the drains were complete and did not verify this fact (either by review of the applicable Work Order or by querying the cognizant engineer) prior to dropping the Day-to-Day Operating Concern and operating the vapor extractors.
2. The Root Cause of the vapor extractor malfunction that results in oil being discharged to the roof has not been corrected.
3. Nobody involved (OPS, CED, Facilities, Licensing) established administrative controls for the vapor extractors or drains through White or Yellow Tagging to preclude a spill.
4. There is no process in place for the release of plant equipment that is affected by a partially completed Work Order (outside the design control system).
5. A review of other CED projects indicates that there does not appear to be any other similar situations that could result in inadvertent operation or unexpected outcomes.

RECOMMENDATIONS:

1. Plant Management should re-emphasize communication between all organizations within the company. Of particular importance are instances where plans, schedules, or conditions change significantly.
2. Correct the cause of the vapor extractor malfunctions (OPS/PEO/MAINT).
3. Obtain PORC permission for release of the partially modified roof drain (similar to the Job Order process)(CED).
4. Complete the roof drain modifications as soon as practicable (AI 95-039-0 - CED).
5. Close AI 95-039-03 to this memo.

c: P.C. Sheldon
C.R. Shaw
UOR 95-039
File

OPERATIONAL EVENT DATABASE

[[LAST UPDATE ON 3/26/95]]

UOR
95-03

E.D.B. #: 1886

UOR # 94-038 VENT DATE (Mo/Day/Yr) 6/15/94

ADDENDUM DATE

EVENT TIME: 1802

OPERATING CONDITION: 7NS: Y/N)

TREND CODE (QPD):

E-PLAN LEVEL

Reference Documents leave blank if N/A)

SIC#:

H.P.E.S #:

L.E.R. #:

P.R.C.E. #:

OTHER:

UOR TITLE OIL SHEEN ON BACK RIVER

DESCRIPTION:

1802- Security notified the control room of a visible oil sheen on the Back River. The initial investigation confirmed that a sheen was inside the boom for the pump house intake but no source could be identified. After all the possible sources from the circ water pump house were checked, it was decided to check each of the storm drains in the area.

1910- The PSS identified the source of the sheen to be the "E" storm drain outfall on the North side of the circ water pumphouse. The storm drain had approximately 30 gpm of water flowing out onto oily absorbent pads and on into the river. The source of the water was determined to be the vacuum priming pump sump. The amount of oil spilled into the river was estimated to be one pint. The Hazardous Material Response Team was activated and clean absorbent pads from the spill response kit were placed under the outfall.

1940- Hazardous Material Response Team on site and placed additional absorbent materials around the outfall. The sheen subsequently dissipated.

Notifications were made IAW the Maine Yankee Spill Plan.

2200- Grab sample from the vacuum priming sump indicated less than 1 ppm oil. Discovered oil sheen in storm drains "E2" "E3" and on wood walkway outside door by P-2C. Suspect source to be roof work on turbine building (roof drain runs into storm drain E-2).

ADDENDUM TEXT

OPERATIONAL EVENT DATABASE

[[LAST UPDATE ON 3/26/95]]

C.D.B. #: 1793

UOR # 93-072 VENT DATE (Mo/Day/Yr) 8/31/93

ADDENDUM DATE

EVENT TIME: 1200

OPERATING CONDITION: INS: Y/N

TREND CODE (QPD):

E-PLAN LEVEL

OTHER: [faded text]

UOR TITLE OIL SHEEN IN THE BACK RIVER

DESCRIPTION:

Investigation determined that the source was a sump in the southwest corner of the pump house.

An NPO secured the sump pump and cleaned up the oil with absorbant pads and swipes.

The source of oil may have been P-26A which had oil marks on it. Notifications were made IAW the Maine Yankee Spill Plan.

ADDENDUM TEXT

OPERATIONAL EVENT DATABASE

[[LAST UPDATE ON 3/26/95]]

E.D.B. #: 1694

UOR # 92-095 VENT DATE (Mo/Day/Yr) 11/03/92

ADDENDUM DATE

EVENT TIME: 1155

OPERATING CONDITION: 7NS: Y/N)

TREND CODE (QPD): EG-A335-E6-PLAN LEVEL

Reference Documents seave blank if N/A)

SIC#:

H.P.E.S #:

L.E.R. #:

P.R.C.E. #:

OTHER:

UOR TITLE VISIBLE OIL SHEEN ON BACK RIVER DURING RAINSTORM

DESCRIPTION:

1155 - Security notified PSS of oil sheen on the back river by the circ pump house. PSS and Hazardous Waste Specialist investigated and determined the event to be reportable IAW the spill plan.

Facilities instructed to contain oil with boom and collect it with absorbent sheets.

Notifications made per the spill plan (see attached form).

During cleanup an oil sheen was found on the rain water entering the storm drain near the walkway where the transformer was cut up. Storm drain was covered; oil stopped from entering the river.

ADDENDUM TEXT

X.

OPERATIONAL EVENT DATABASE

[[LAST UPDATE ON 3/26/95]]

E.D.B. #: 870

UOR # 89-035 VENT DATE (Mo/Day/Yr) 4/6/89

EVENT TIME: 1500

ADDENDUM DATE

OPERATING CONDITION: 7NS: Y/N)

TREND CODE (QPD):

E-PLAN LEVEL

Reference Documents save blank if N/A)

SIC#:

H.P.E.S #:

L.E.R. #:

P.R.C.E. #:

OTHER:

UOR TITLE Oil sheen detected on the Back River

DESCRIPTION:

An oil sheen was detected on the Back River in the vicinity of the circ water pump house. Source was believed to be from the fuel oil spill on 4/5/89. The fuel oil was leached from the roofing material and carried to the river via the storm sewer. Ref UOR 89-035, OEDB 869, by rainwater. The Hazardous Waster Coordinator contacted the Maine DEP and the US Coast Guard. The NRC was notified via ENS under 50.72(b)(2)(vi).

ADDENDUM TEXT

OPERATIONAL EVENT DATABASE

[[LAST UPDATE ON 3/26/95]]

E.D.B. #: 1888

UOR # 94-040VENT DATE(Mo/Day/Yr)06/18/94

EVENT TIME: 0830

ADDENDUM DATE

OPERATING CONDITION: 7NS: Y/N)

TREND CODE (QPD):1B-0211-D0-PLAN LEVEL N/A

Reference Documents leave blank if N/A)

SIC#:

H.P.E.S #:

L.E.R. #:

P.R.C.E. #:

OTHER:

UOR TITLE OIL SHEEN ON BACK RIVER

DESCRIPTION:

0830 Industrial Safety Coordinator notified the Control Room about the presence of a small oil sheen on the Back River. The source appeared to be the same as described in UOR 94-038 (turbine building roof drains). Heavy rains from the previous evening prompted the event.

The HAZ MAT team responded and deployed an oil boom near the outfall of the storm sewer discharge that serves the turbine building roof drains.

Cleaned up oil sheen with absorbent pads.

Additional oil absorbent materials were placed around storm sewer outlet.

0900 Notifications were made to offsite agencies IAW the Maine Yankee Spill Plan.

ADDENDUM TEXT

OPERATIONS DEPARTMENT
UNUSUAL OCCURRENCE REPORT (UOR)

1. GENERAL

A. TITLE OF UOR: OIL SHEEN ON BACK RIVER

B. DATE/TIME OF EVENT: 3/31/95 1156

2. PLANT CONDITIONS AT TIME OF OCCURRENCE:

OPERATING CONDITION (1-7): 1 PLANT TRIP ?N
REACTOR POWER (%): 0

3. DESCRIPTION OF OCCURRENCE & IMMEDIATE CORRECTIVE ACTIONS:

3/31/95

-1156 Security notified the control room of a visible oil sheen on the Back River. The initial investigation by the PSS indicated the source of the sheen to be the "E" storm drain outfall on the North side of the circ water pumphouse. Plant services was notified and the spill team responded.

Leaves in the storm drain outlet appeared to be blocking and filtering the oil.

-1215 Absorbent pads placed under the outfall.

MOD notified of spill. The turbine hall roof catch basin drain sight glass and the pipe outlet to the turbine hall sump were checked and no oil residue was detected. It was subsequently determined that the vapor extractor catch basin installation still had some minor work to be completed and the roof plugs were still installed in the basins. The catch basins were found to be full water and they had a layer of oil on top of the water. ^A _{of}

The light oil which discharged into the river spread and dissipated rapidly. The estimated amount was less than 1 quart.

CHEMISTRY TOOK A SKIM SAMPLE OF THE OIL.

In addition to the notifications listed in section 7, the State of Maine Department of Environmental Protection was notified at 1252 and the National Response Center was notified at 1315.

-1445 After obtaining concurrence from CED, the catch basin plugs were removed and their contents were drained to the turbine hall sump.

-1600 Facilities setting up to flush roof drains to remove any residual oil.

4. THE FOLLOWING SIMILAR OCCURRENCES WERE FOUND IN THE OEDB:
(LIST SEARCH CRITERIA)
Criteria: "Oil Spill River"> 6 records; UOR 94-038, UOR 93-072
UOR 92-095, UOR 89-035, UOR 94-040 similar
5. REPORTABILITY DETERMINATION; REPORTING CRITERIA; SHORT TERM
PROC. 1-26-1; EMERGENCY PLAN PROC. 2.50.0; LER (EXPLAIN).
The Maine Yankee Spill Plan requires the National Response Center and the State DEP to be notified. The event is therefore reportable under 50.72(b)(2)(vi). Not LER reportable or reportable per 2.50.0.

5A. FITNESS FOR DUTY EVALUATED? NO (YES or NO)

5B. FOR CAUSE TEST REQUIRED? NO (YES or NO)
A For Cause Test is required as soon as possible after accidents involving a failure in individual performance where there is a reasonable suspicion that the worker's behavior contributed to those events which result in:
a. A personal injury.
b. A radiation exposure or release in excess of regulatory limits.
c. Actual or potential substantial degradation of the level of plant safety

5C. EVALUATE FOR 10 CFR 21 REPORTABILITY: NO (YES or NO)

6. SAFETY SIGNIFICANCE CLASSIFICATION: III
CATEGORIZE ACCORDING TO THE TIME REQUIRED FOR A RESPONSE FROM MANAGEMENT, AFTER THE UOR HAS BEEN PRESENTED AT THE MORNING MEETING.

- I: Corresponds to Work Order (WO) Priority Categories 1 thru 5. May have Tech Spec or FSAR implications and a Safety Issues Concern form may be needed. RESPONSE TIME is immediate or accelerated e.g. 1400 of the same day when presented at the morning meeting.
- II: Corresponds to WO Priority Category 6. RESPONSE Time is 24 hours when presented at the Morning Meeting
- III: Corresponds to WO Priority Category 7 thru 10. A normal operational concern - routine.

7. NOTIFICATION:

ENS
NRC RESIDENT INSPECTOR
DUTY CALL OFFICER
STATE INSPECTOR*
INDUSTRIAL SAFETY COORDINATOR

<u>Y/N</u>	<u>NOTIFIED BY</u>	<u>DATE/TIME</u>
Y	PETE EBERT	3/31/95-1351
Y	PETE EBERT	3/31/95-1348
Y	RON HOWARD	3/31/95-1515
Y	DAVE HULBERT	3/31/95-1340
Y	MURRAY HOWARD	3/31/95-1158

* FOR: A) EMERGENCY CLASSIFICATION
B) UNSCHEDULED PLANT TRIP OR SHUTDOWN

C) UNSCHEDULED RELEASES OF RADIOACTIVITY.
D) ANY STATE AGENCY IS NOTIFIED EXCLUSIVE OF THE MONTHLY E-PLAN PHONE CHECKS.

8. SCREENING CRITERIA FOR CORRECTIVE ACTION:

- a. Does the event have a high probability of occurrence/recurrence and a potential high consequence with respect to Nuclear Safety, Personnel Safety, Regulatory Response, Production/Cost or Public Relations. **NO** (YES/NO)
- b. Does the event have a high probability of occurrence/recurrence or a potential high consequence where any additional occurrence/recurrence would be unacceptable. **NO** (YES/NO)

IF either 8.a or 8.b is YES, THEN go to Section 9; PSS and STA recommend type of Root Cause IAW 0-16-1.

IF both 8.a and 8.b are NO, THEN go directly to Section 10.

9. RECOMMENDED LEVEL OF ROOT CAUSE DETERMINATION: (Check one)

- | | |
|-----------------------------------|-----------------|
| DEPARTMENTAL ROOT CAUSE | RC/PRCE |
| INTERDEPARTMENTAL TEAM ROOT CAUSE | RC/HPES |
| RIR RADIOLOGICAL INCIDENT REPORT | RC/Evnt Revw Bd |
| RC/Alt Method | |

10. PRELIMINARY LONGER TERM ACTION ITEMS:

- 1. Finish oil catch basin installation modification.
 - 2. Consider establishing periodic checks of outfalls for blockage or oil indications AND SHOULD WE REEVALUATE THE CLEANING FREQUENCY RECOMMENDATIONS?
 - 3. EVAL. THE DECISIONS MADE AND REASON FOR STOPPING THE SOB
 - 4. WHAT SHOULD OF BEEN DONE TO PREVENT THE POTENTIAL/ACTUAL RELEASE.
- Handwritten notes on left margin:*
 AT 95-039-1
 CWD
 AT 95-039-2
 CWD E/S
 AT 95-039-3
 CWD

11. SOME GOOD QUESTIONS TO ASK DURING THE MORNING MEETING:

- a. Is this or another activity ongoing or likely to occur before corrective actions have been implemented? No (YES/NO) Ball Removed.
If so should we let it continue to occur without implementing some interim corrective measures? Yes (YES/NO) ON LINE MODS ARE DONE w/ EXCEPTION OF THIS - CWD TO VERIFY.
- b. Did this event have the potential for serious personnel injury? No (YES/NO) If serious injury had occurred would we be doing anything differently?
- c. If the problem involved a component required by technical specifications, was the opposite train component ever out of service during the period the component was inoperable? N/A (YES/NO)
- d. Does anyone have any questions or concerns not previously discussed? No (YES/NO)
- e. Should we put something on the "Nuclear Network"? No (YES/NO)

SUBMITTED BY: P.T.EBERT

APPROVED BY/DATE: [Signature] 3-31-95

NOTED BY: [Signature] 4/3/95

HSA ID# 7

UOR DATABASE - CONVERTED FROM OPERATIONAL EVENT DATABASE (OEDB)

1. TITLE: OIL SHEEN ON BACK RIVER
2. OEDB #:2046 UOR #:95-040 LER #: OTHER:
HPES #: PRCE #:
3. TIME/DATE OF EVENT: 1430/4/4/95
ADDENDUM DATE
4. PLANT CONDITIONS:

OPERATING CONDITION (1-7): 1

5. DESCRIPTION OF OCCURRENCE:

1450 THE CONTROL ROOM WAS NOTIFIED THAT A SLIGHT OIL SHEEN WAS VISIBLE AT THE INTAKE STRUCTURE. THE HAZARDOUS WASTE COORDINATOR AND INDUSTRIAL SAFETY COORDINATOR WENT TO THE INTAKE STRUCTURE AND WERE ABLE TO TRACK THE SHEEN BACK TO A LOCATION ON LAND AT THE SOUTH SIDE OF THE CIRC WATER PUMP HOUSE. THEY DETERMINED THE SOURCE TO BE A LOCATION OF PREVIOUS SPILLS AND ACUMULATED OIL UNDER A CRANE. THEY CONCLUDED THAT THE RAIN THAT HAD BEEN FALLING FOR MOST OF THE DAY HAD CAUSED THE OIL TO BECOME MOBILE, TRAVELING TO THE WATER'S EDGE AND ONTO THE WATER SURFACE. NOTE: THE OIL BOOM WAS IN PLACE AT THE INTAKE STRUCTURE AND ALL OF THE OIL SHEEN WAS OBSERVED TO BE CONFINED WITHIN THE BOOM.

1515 THE HAAZARDOUS WASTE COORDINATOR BRIEFED THE PSS AS TO THE STATUS OF THE OIL SHEEN.

1520 PLANS WERE MADE FOR A BOAT TO BE DISPATCHED TO CLEAN THE WATER SURFACE AT THE INTAKE STRUCTURE, AND TO MONITOR THE EFFECTIVENESS OF THE OIL ABSORBING PADS THROUGH THE NIGHT.

QOD TREND CODE:

HSA ID# 8

1. TITLE: SMALL WATER FLOOD AT CTMT -2 ELEVATION.

2. NUMBER: 95-096

4. PLANT CONDITIONS:

3. TIME/DATE OF EVENT: 0232 12/07/95

REACTOR POWER : 0%

PLANT TRIP? N

OPERATING CONDITION (1-7): 1

5. DESCRIPTION OF OCCURRENCE:

Note: 1-104-14.2 PLACING S/G #2 IN WET LAY-UP AND S/G #2 LOW PRESSURE TUBE LEAK TEST was in progress and stable at 0100.

At 1630 on 12/06/95 1-104-14.3 PLACING S/G #3 IN WET LAY-UP AND S/G #3 LOW PRESSURE TUBE LEAK TEST was started in order to fill #3 S/G to below the feed ring. The procedure was *on hold* until the #3 level transmitter could be placed into service.

I&C completed backfilling the #3 S/G level transmitters at 0145 on 12/07/95.

At 0216 #3 S/G filling commenced by continuing with 1-104-14.3 using P-25A.

At 0232 filling of S/G #3 was stopped due to slow response of wide range S/G level. Wide range level appeared to not be responding given the amount of water pumped in. (Wide range level slowly increased from zero to 55 inches over the course of the next hour).

At 0237 a report was made to the control room about water on the floor of the head lay down area on the CTMT -2 elevation.

PW-A-78 was shut to stop pressurization of #2 S/G (since 1-104-14.2 was also ongoing). Fire protection issues associated with PW-A-78 were considered. An NPO found water coming out of BD-56. BD-56 had been tagged open to prevent the possibility of wetting #1 S/G while filling #2 and #3 S/G. The NPO was directed to verify BD-52 and 53 on #2 S/G and BD-54 and 55 on #3 S/G shut. BD-54 and 55 were found tagged open. The White Tag Order was cleared and the valves were shut. Water stopped flowing from BD-56.

The water on the -2 elevation was cleaned up.

6. OEDB SEARCH:

KEY WORD:	HITS:	SIMILAR EVENTS:
1. Spill	63	UOR 90-062 and others described wet lay-up spills associated with #3 S/G.
2. S/G Fill	3	3 similar events including UOR 90-062 describe spills associated with wet lay-up.

7. REPORTABILITY DETERMINATION: REPORTING CRITERIA; SHORT TERM PROC. 1-26-1; EMERGENCY PLAN PROC. 2.50.0; LER (EXPLAIN).

The event is not reportable IAW 1-26-1 or the Maine Yankee Spill Plan. No radiological consequences were associated with this event. No equipment damage was involved and procedures appear to have been followed.

8. FITNESS FOR DUTY:

8.1 FITNESS FOR DUTY EVALUATED? YES

8.2 FOR CAUSE TEST REQUIRED? NO

A For Cause Test is required as soon as possible after accidents involving a failure in individual performance where there is a reasonable suspicion that the worker's behavior contributed to those events which result in:

- a. A personal injury.
- b. A radiation exposure or release in excess of regulatory limits.
- c. Actual or potential substantial degradation of the level of plant safety

HSA ID# 9

1. TITLE: ASBESTOS SPILL IN CONTAINMENT

2. NUMBER: 96-001

4. PLANT CONDITIONS:

3. TIME/DATE OF EVENT: 0320/1-1-96

REACTOR POWER : 0%

PLANT TRIP? N

OPERATING CONDITION (1-7): 1

5. DESCRIPTION OF OCCURRENCE:

0320- Control room notified by maintenance that there was an asbestos spill in loop one in the vicinity of RC-M-11. Further discussion with maintenance personnel disclosed that an approximately 20 foot length of asbestos insulation on what appeared to be a 1 in. stem leakoff line from RC-M-11 was split open and spilling asbestos. In addition there were other areas in all three loops where the protective cover had worn off asbestos insulation as a result of workers standing on the insulation or contact during work in the area.

Safety, assistant outage manager and plant management notified of situation. Access to the loops was restricted until condition is corrected.

5. DESCRIPTION(Cont*d)

6. OEDB SEARCH:

KEY WORD:	HITS:	SIMILAR EVENTS:
1. Asbestos	5	None
2.		
3.		
4.		

7. REPORTABILITY DETERMINATION: REPORTING CRITERIA; SHORT TERM PROC. 1-26-1; EMERGENCY PLAN PROC. 2.50.0; LER (EXPLAIN).

Reportable to Department of Environmental Protection(for spills involving more than 3 linear feet of material). May be reportable to Environmental Protection Agency if detailed inspection determines more than 260 feet or 160 square feet of asbestos-containing material spillage occurred.

HSA ID# 10

UOR DATABASE - CONVERTED FROM OPERATIONAL EVENT DATABASE (OEDB)

1. TITLE: S/G #3 WET LAYUP RECIRCULATION SPILL
S/G #3 WET LAYUP RECIRCULATION SPILL
2. OEDB #: 1318 UOR #: 90-062 LER #: OTHER:
HPES #: N PRCE #:
3. TIME/DATE OF EVENT: 1330/5/2/90
ADDENDUM DATE
4. PLANT CONDITIONS:

OPERATING CONDITION (1-7): 1

5. DESCRIPTION OF OCCURENCE:

S/G #3'S Wet Lay-up recirculation system takes a suction from its main steam line through a hose connected to MS-246 and discharges back to the SG via another hose through blowdown valves BD-149, BD-T-145, BD-T-146 and BD-30. The recirc system has a suction isolation valve SGR-31 and discharge valves on the filter by-pass SGR-36 and on the filter outlet SGR-37.

4/25-2225 SG #3 in WLU recirc.

4/29-2100 SG #3 off recirc.

4/29-2349 Tagging order 878-90 issued to isolate drain BD-T-145 for repair(DR 506-90). BD-149 tagged open(apparantly skid end of hose was disconnected to allow it to be used to drain the blowdown piping through BD-149). No tags hung on SGR valves.

5/2 Ops Day Orders direct that all recirc systems be activated to allow sampling by chemistry.

5/2-1330 Operator had completed putting S/G #1 onto recirculation and was preparing to do S/G #3. He found that the discharge hose from the skid had been disconnected at the skid and was hanging from BD-149 to the floor below. The skid is on the 20' level of CTMT and BD-149 is in the overhead underneath the 20' level(approximately 20' above the -2' level). BD-T-145 is not visible from BD-149 area.

The operator called Control Room and asked what to do. He was told to go ahead and reconnect the hose. Once the hose was reconnected, the operator opened the suction and discharge valves at the skid and water began to gravity feed to the blowdown line. Before the pump was placed in service, the Control room was notified that water was spilling out BD-T-145. The operator was contacted and he shut the discharge valve.

5/2-1545 Control Room was notified that a worker had been soaked when the hydrazine treated water (230ppm) spilled out BD-T-145.

5/2-1700 ISC notified of incident and initiated testing to insure there is no airborne hydrazine hazard.

E-PLAN LEVEL ENS: N (Y/N)

7. REPORTABILITY DETERMINATION: REPORTING CRITERIA; SHORT TERM PROC. 1-26-1; EMERGENCY PLAN PROC. 2.50.0; LER (EXPLAIN)

QOD TREND CODE:

HSA ID# 11

From: Aldo Capristo
To: Characterization File
Date: 8/28/97 6:32am
Subject: Charaterization Info

I was told about a gasoline spill of about 10 gallons that occurred about 4-6 months ago in front of the vehicle barrier. As it sounds, a vehicle was parked awaiting access and it began leaking fuel. Speedy dry was used and that was it.

Note - Dennis - I suppose you will be the keeper of this stuff? Please let me know. As I get more, I will forward to you.

a.c. 4530

HSA ID# 12

IDENTIFIED RADIOLOGICAL ISSUES FOR FURTHER CHARACTERIZATION

Issue Description	Date	Status
Leak in RWST siphon return line to ground	1988	~600 ft ³ of soil removed and disposed as LLW ~NRC approves residual under 10 CFR § 20.302(a) on 8/31/89
Residual slightly contaminated soil under LLW storage area in vicinity of yard crane	1992	~Area evaluated and characterized by YNSD 10/92 (MYP #92-1173) and 1/93 (MYP # 93-0054) ~IAW 10 CFR § 50.75(g) placed in decommissioning plan file 4/12/93 (JHA-93-27)
Spreading of slightly contaminated silt from base of intake racks in unused area under transmission lines	1992-97	~MDEP issued Dredge Spoil Utilization Permit S-20814-SS-A-N ~MDHE accepted practice 5/24/95 (R.J. Schell Ltr to MDEP)

QUESTIONNAIRE FOR MAINE YANKEE SITE CHARACTERIZATION

NAME Bob Henjuel EMPLOYED FROM 5/87 TO PRESENT

CURRENT TITLE TRAINING MANAGER DEPT TRAINING
 (Leave the above blank if you choose to remain anonymous.)

PLEASE CIRCLE THE APPROPRIATE ANSWER CONCERNING ACTIVITIES AT MAINE YANKEE. ARE YOU AWARE, OR WERE YOU ASSOCIATED WITH ANY OF THE FOLLOWING ACTIVITIES:

- | | | |
|--|---|-------------------------------------|
| 1. A spill of Radioactive Material on the plant site? | Yes | No |
| 2. Inappropriate storage or control of Radioactive Material on the plant site? | <input checked="" type="radio"/> Yes | <input type="radio"/> No |
| 3. An effort to cover over or isolate Radioactive Material on the plant site? | <input type="radio"/> Yes | <input checked="" type="radio"/> No |
| 4. A spill of Asbestos Material on the site? | <input checked="" type="radio"/> Yes | <input type="radio"/> No |
| 5. Inappropriate storage or control of Asbestos Material on the plant site? | <input type="radio"/> Yes | <input checked="" type="radio"/> No |
| 6. An effort to cover over or isolate Asbestos Material on the plant site? | <input type="radio"/> Yes | <input checked="" type="radio"/> No |
| 7. A spill of Petroleum Products on the plant site? | <input checked="" type="radio"/> Yes | <input type="radio"/> No |
| 8. Inappropriate storage or control of Petroleum Products on the plant site? | <input type="radio"/> Yes | <input checked="" type="radio"/> No |
| 9. An effort to cover over or isolate Petroleum Products on the plant site? | <input type="radio"/> Yes | <input checked="" type="radio"/> No |
| 10. A Chemical spill on the plant site? | <input checked="" type="radio"/> Yes | <input type="radio"/> No |
| 11. Inappropriate storage or control of Chemicals on the plant site? | Yes <input checked="" type="radio"/> No | |
| 12. An effort to cover over or isolate Chemicals on the plant site? | <input type="radio"/> Yes | <input checked="" type="radio"/> No |
| 13. Any Raw Lead inadequately stored or contained on the plant site? | <input type="radio"/> Yes | <input checked="" type="radio"/> No |

If you answered YES to any of the above questions, please add the appropriate details (date, time, location, etc.) related to the questions above. If you know of or have a concern about any other Hazardous Material associated with Maine Yankee, please attach that information as well. Return this completed form to Dennis Hickey of Radiation Protection.

- (2) All items were very specific in nature and have been adequately resolved, i.e. ICI tips
- (4) Very limited items which were adequately resolved, i.e. asbestos insulation on ~~the~~ reactor coolant system piping.
- (7) Very specific issues which were properly resolved, i.e. spill of heating oil in space generator storage shed.
- (10) Very specific issues which were adequately resolved, i.e. underground sewage water system leakage.

Note: One issue which has been mentioned is the sludge which was disposed of on-site which contained some activity levels. I'm not sure of the form of

0305.03.1

ATTACHMENT B
ATLAS DOCUMENT INPUT FORM

1. TITLE <i>Licensed Silt Spreading AREA</i>	
2. DOCUMENT TYPE <i>Correspondence</i>	
3. DOCUMENT FORM <i>MF</i>	
4. DOCUMENT LOCATION	
5. RETENTION PERIOD	
6. TECHNICAL FILE NUMBER <i>01.08.04.02</i>	
7. DOCUMENT NUMBER	
8. REVISION NUMBER	
9. DATE <i>10/04/1994</i>	
10. CLASSIFICATION TYPE <i>D</i>	
11. TOPICAL INDUSTRY ISSUE	
12. KEYWORDS	
13. SUBJECT	
14. REFERENCE DOCUMENT	
15. SYSTEM CODE	
16. COMPONENT CODE	
17. CYCLE NUMBER	
18. ORIGINATOR <i>Admin/Licensing</i>	
19. RECEIVER	
20. VENDOR CODE	
21. ACCESSION NUMBER	
ACTION: ADD/REPLACE/DELETE (CIRCLE ONE)	

Maine Yankee

RELIABLE ELECTRICITY SINCE 1972

329 BATH ROAD • BRUNSWICK, MAINE 04011 • (207) 798-4100

asi
1) my-ME
2) 15.1
3) 1.8.4.2

2505-53-475

October 4, 1994
JRH-94-209

Mr. Robert Schell
Radiological Health Program
Division of Health Engineering
Department of Human Services
State House Station # 11
Augusta, ME 04333

RESPONSIBLE TO Diehl Hebert
RESPONSE N/A
NRC DUE DATE N/A

Subject: Licensed Silt Spreading Area

Reference: Dredge Spoil Utilization License, S-20814-SS-A-N, July 15, 1992

Dear Mr. Schell:

As has been discussed in conversations between you and Leann Diehl, Maine Yankee is spreading marine silt removed from the intake area at the Maine Yankee site in accordance with the referenced MDEP license. This silt has trace levels of radionuclides that were previously released, in accordance with our U.S. Nuclear Regulatory Commission operating license, to the circulating water system discharge.

The attached report, Evaluation of Sediment Removed from Maine Yankee's Intake Bays, September 1994, includes an analysis of the pathways and radiological health impacts of the spreading of this material. The report concludes that this spreading activity does not present any threat to the health and safety of MY employees or members of the public.

We trust that we have supplied all needed information and we plan to proceed with spreading as outlined in the referenced license and the attached report. Please contact John Arnold, 207-798-4213, should you have questions or comments.

Very truly yours,

James R. Hebert, Manager
Licensing & Engineering Support Department

JHA/mwf

General Dist. w/o enc.
[Stamp with fields for TO, FROM, DATE, and other administrative markings]

2507.52.3

**EVALUATION OF SEDIMENT
REMOVED FROM MAINE YANKEE'S INTAKE BAYS**

September, 1994

Major Contributors: F. X. Bellini
J. W. Bisson

2505.140.1479
2505.503.5

EXECUTIVE SUMMARY

Maine Yankee (MY) land-spreads sediment from the MY plant circulating water system intake bays on the plant site pursuant to a land spreading license issued by the state of Maine Department of Environmental Protection (DEP). These bays are dredged during each refueling outage. Trace levels of radionuclides have been detected in this sediment. The radioactivity originates from NRC licensed liquid effluent from the plant circulating water discharge. The sediment spreading is subject to determination and licensing by the Maine DEP.

This report analyzes the potential radiological consequences of spreading which are quite minimal. Evaluated scenarios include those for sediment already removed as well as for sediment which will accumulate over the remainder of the current plant license.

On-site spreading of the sediment was chosen because there is:

- no health risk to plant workers or the general public
- no environmental impairment
- limited migration of radionuclides from the placement area
- no long lived radionuclide (greater than 35 years half-life)
- no material containing total activity greater than $5.0E-5 \mu\text{Ci}/\text{gram}$
- no material in a form likely to be recycled.

In addition, the area chosen is under the direct control of MY site management and security. Sediment placement and documentation will be done in accordance with requirements in 10CFR20.2002 and 10CFR50.75(g).

A detailed calculation, MYC-1647 (Reference 6) was performed to conservatively evaluate various potential (likely and unlikely) exposure pathways of the silt spreading. Using conservative assumptions for sediment volume and radioactivity content, results indicate the maximum expected exposure would be about 0.7 mrem/yr via direct dose from the ground. Although unlikely, exposure due to wind suspension, drinking of ground water, and ingesting crops, fish and shellfish were also examined. Potential exposure for these pathways was found to be about an order of magnitude lower

than that for direct ground dose.

These documents are developed in accordance with YNSD Environmental Engineering Department procedure YA-REG-230, a procedure developed to evaluate such activities.

150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200

TABLE OF CONTENTS

EXECUTIVE SUMMARY iii

LIST OF FIGURES vi

LIST OF TABLES vii

1.0 INTRODUCTION 1

2.0 MATERIAL DESCRIPTION 3

 2.1 Physical Properties of the Sediment 3

 2.2 Volume and Mass of the Material 3

 2.3 Physical Description of the Material 4

 2.4 Special Characteristics 5

 2.5 Chemical Properties of the Sediment 6

 2.6 Radiological Properties and Estimate of Radionuclide Activities 6

 2.7 Operational Factors 8

3.0 DESCRIPTION OF THE METHOD FOR LAND SPREADING 9

 3.1 Sediment Generation and Preparation for Spreading 9

 3.2 Method of Land Spreading 10

 3.3 Location 10

 3.4 Credible Accidents and Prevention Measures 12

4.0 EVALUATION OF RADIOLOGICAL IMPACTS OF SEDIMENT PLACEMENT 13

 4.1 Potential Exposure Pathways 13

 4.2 Evaluation of Dose Rates and Doses 14

 4.2.1 Direct Dose Rate and Dose 14

 4.2.2 Dose Due to Wind Suspension 15

 4.2.3 Estimation of Waterborne Pathway Doses 16

 4.2.4 Estimation of Dose Via Ingestion 16

5.0 ENVIRONMENTAL IMPACT ASSESSMENT 17

6.0 LICENSE AMENDMENT INFORMATION 18

7.0 SUMMARY 19

REFERENCES 20

25054502

1.0 INTRODUCTION

The Maine Yankee Atomic Power Company (MY) herein documents its radiological analysis of on-site land spreading of river sediment and related debris routinely removed from the cooling water intake structure. This material contains very low levels of radioactivity which are attributable to NRC licensed plant liquid effluent discharges. Documentation is provided here in accordance with standard recommendations contained in 10 CFR 20.2002 and Reference 1.

The source of this material is the routine cleaning of the Circulating Water System Intake Bay and related piping. Sediment and mussel shells settle from water taken from the Back River, adjacent to the Maine Yankee Atomic Power Station. Some 10 to 20 yds³ of this material accumulate every 15 to 18 months. In addition, a small increment of such sediment, generated from cleaning of Service Water pipes, is also occasionally included for land spreading. This Service Water pipe debris is very similar to the material removed from the Intake Bay.

The radiological character of these materials has been quantified by testing of samples. The non-radiological chemistry of the material is addressed by sampling in keeping with state regulations and the state DEP license (Reference 2).

Due to nature of the subject material and the very low concentrations of radioactivity in it, there are no convenient and cost-effective methods to remove or reduce the radioactivity. Thus, on-site spreading is a low cost, minimal consequence option for this material. Selection of this option implies that no further radiological monitoring of the spreading area is warranted. Criteria for this include:

- The land-spreading of the material presents no health risk to the public or MY employees.
- Significant radionuclides in the material have short half lives (NRC Office of Nuclear Reactor Regulations proposes 35 years or less).
- Sediment is not in a physical form that damages or endangers the spreading area environment.

- The nuclides in the material are mostly fission and activation products such as Co-58, Co-60, Ag-110m and Cs-137.
- Total activity concentration is less than $5.0E-5$ μ Ci/gram.
- The material is in a form that is very unlikely to be recycled.
- The radionuclides are in a form that will limit their migration from the spreading area.

Because all these criteria are met, land spreading is the best on-site method for the handling of sediment/debris that results from intake bay cleaning.

2505.40.1424
2505.53.11
TT. 29. 5052

2.0 MATERIAL DESCRIPTION

2.1 Physical Properties of the Sediment

MY is a 860 MWe (net) PWR which has been in operation since 1973. The plant's Circulating Water system provides ocean water for condenser cooling, drawn from the adjacent Back River. Sediment accumulates in the Circulating Water System Intake Bays as a normal consequence of water intake flow (420,000 gpm) from the river. Routine sediment and debris removed from this intake structure is the source of most of the material to be spread. Less than one percent of the recently accumulated debris is from a one-time cleaning of Service Water pipe, done in preparation for pipe lining. This debris is very similar in character to the rest of the subject material.

The total volume of sediment removed from Intake Bays during the 1993 outage was examined to determine the nature of the material. The sediment consists of silt with mussel shells and minor amounts of sand. Traces of marine organic constituents including seaweed, and clay-sized materials are also present, although the material is low in plasticity. The sediment is unconsolidated and friable. Reference 3 includes grain size analyses and description of three grab-samples of sediment taken from the Intake Bays in February of 1992.

The material designated as debris from the Circulating Water System Intake Bays consists mostly of mussel shells, similar to those which are distributed throughout the sediment. Other debris from the scaling of the Service Water pipe consists of fine-grained sediment with iron corrosion products. It is, like the Intake Bay sediment, soft, friable and non-plastic.

These materials have been tested in accordance with Maine Department of Environmental Protection (DEP) requirements for land disposition and they meet all relevant chemical criteria for land application of sludge and residuals, as detailed in Reference 4 and Section 2.5 of this report. A state license for its placement was issued to MY by the DEP July 16, 1992 (Reference 2).

2.2 Volume and Mass of the Material

The estimated dewatered volume of the subject materials is based on field measurements of sediment and debris removed during the fall outage of 1993. This material, recently removed from the

Intake Bay, and the Service Water Pipe debris have been placed on a 25 ft. by 125 ft. area within the designated 3 acre area (Figure 1). The average depth of sediment is estimated as 3 inches. Spreading of the materials is such that about 75% of the 25 ft. by 125 ft. area is covered.

The volume of the material removed from the Intake Bays during the 1993 MY outage is thus estimated to be approximately 22 yds³. This amount is considered by plant staff to be relatively high compared to the amount removed during previous outages. The volume of Service Water pipe debris is estimated to be about 0.1 yd³. Already placed during the 1992 outage is an estimated 11 yds³ of similar material.

Based on these estimates the total volume of material to be spread on-site over the remaining licensed life of the plant is conservatively estimated as 292 yds³, the sediment accumulated from 14 (12 future) outages. As a conservative estimate, the projected volume for the 12 future outages was based on the high volume removed during the 1993 outage. The estimated density of this silt-like material, 1.8 g/cm³, is not expected to change for future removals. Therefore, the total mass of material which will be removed from the Intake Bays is estimated to be 408,969 kg.

2.3 Physical Description of the Material

The sediment consists of silt with mussel shells and minor amounts of sand. Traces of marine organic constituents including seaweed, and clay-sized materials are also likely to be present, although the material is low in plasticity. The material is generally loose and friable, but it consolidates into a stable mass that supports plant growth. It can thus be fully stabilized so that rain or runoff will not cause significant erosion. In addition, its physical properties and its situation will greatly impede atmospheric suspension under dry conditions.

The Service Water pipe debris is similar in physical character to the sediment, except that it contains iron corrosion products and no mussel shells.

As an aid to obtaining representative samples, they were taken with access available to the entire volume of material produced from the 1993 outage. This entire volume of material was visually compared with samples to provide assurance that they were representative of the subject materials.

Samples were taken from both the sediment and debris portions of the material, as described previously.

2.4 Special Characteristics

Samples of the subject material were analyzed for the presence of gamma-emitting radionuclides. Gamma spectroscopy analysis was performed by the Yankee Atomic Environmental Laboratory using established procedures and a lower limit of detection appropriate for the counting geometry for soil samples. Although several samples were negative, three plant-related radionuclides (Ag-110m, Co-58, Co-60) and one atmospheric testing and plant produced nuclide (Cs-137) were found to be present in very low concentrations in some samples. Average concentrations for these four radionuclides, based on analytical results, are presented in Section 2.6.1.

The half-life for each detected radionuclide is provided in Table 1. The concentrations of two of the detected radionuclides, Ag-110m and Co-58, will decrease significantly within a few years due to their very short half-lives. Concentrations of the other radionuclides, Co-60 and Cs-137, will be present longer, although their concentrations will also decrease with time. Therefore the already very low hazard associated with placement and on-site retention of the subject material will further diminish by radioactive decay.

Furthermore, the material will be located on licensee-owned and controlled land. MY's operating license remains in effect for at least the next 15 years, and the site will be subject to additional years of NRC License control beyond the end of plant life to decommission the plant.

The natural chemical properties of the radionuclides in question tend to bind them tightly to sediment particles, impeding their movement through soil. Retardation factors for movement of the radionuclides through soil are provided in Table 1. The retardation factors represent the delay with which radionuclides are expected to move compared to the rate of rain water or ground water movement through soil. Due to this very slow movement, radioactive decay will diminish the presence of each of these radionuclides long before any significant migration can occur.

Given the form of the material, mostly a silty soil, it is highly unlikely to be disturbed due to

any intrinsic value. It is neither a good structural material, nor a particularly fertile soil.

2.5 Chemical Properties of the Sediment

As described above, the sediment consists of silt with some mussel shells, minor amounts of sand and traces of marine organic constituents. Some clay-sized materials and trace organics are also assumed to be present, although the material is low in plasticity. The sediment may occasionally vary from mostly silt to material that is mostly sand. Its mineralogy is inferred to be typical of New England ocean shoreline/river sediment with a general mineral composition of mostly silica dioxide (quartz) with minor amounts of other silicate minerals.

Trace element chemical analyses have been performed on samples of the sediment and underlying soil, in accordance with DEP regulations. Tables 2 and 3 include results of these analyses which include determinations for heavy metals, oil and grease, volatile components and PCB's. None of these components is present in the sediment in concentrations which exceed the DEP criteria for land application of sludge, as set forth in Reference 4. The sediment thus presents no known chemical hazard, given its proper situation, as outlined in the state license allowing it to be land-spread, Reference 2.

2.6 Radiological Properties and Estimate of Radionuclide Activities

The basis for radiological characterization of the sediment is a set of sample analyses presented in Table 4. This includes 8 samples from sediment and debris removed from the Intake Bays during the outage of the fall of 1993. Table 5 presents gamma spectroscopy data for Service Water pipe debris (0.1 yds³), also removed during the 1993 outage. Table 6 presents sample analyses for underlying soil in the spreading area.

Four radionuclides are present in the 1993 Intake Bay material samples. These are a metastable isotope of silver 110 (Ag-110m), cobalt 58 (Co-58), cobalt 60 (Co-60), and cesium 137 (Cs-137). The measured concentrations of Cs-137 fall within the range of Cs-137 soil concentrations associated with fallout from weapons testing in the 1950's and 60's, and this could easily be the source for this nuclide. Naturally occurring radionuclides in the soil include potassium 40 (K-40).

beryllium 7 (Be-7) and actinium-thorium 228 (AcTh-228).

Total radionuclide activities were estimated from the analytical results from the 1993 Intake Bay material samples. Average radionuclide concentrations (shown in Table 4) were conservatively based on only those samples with detected quantities of radioactivity less naturally occurring nuclides. The total radionuclide activities were then developed using these average concentration values, an assumed material density, 1.8 g/cc (Reference 5), and the estimated volume of the 1993 Intake Bay material (22 yds³). The total radionuclide activities are presented in Table 7.

The data from the Service Water Pipe samples (Table 5) were not used because (i) the measured concentrations were lower than the conservatively estimated average concentrations for the Intake Bay material, and (ii) the volume of the Service Water Pipe material was small compared to the volume of Intake Bay material (about 0.1%). Therefore, the radiological consequence associated with the small volume of Service Water pipe debris was bounded by the consequences from the Intake Bay material.

The concentrations of radionuclides in Intake Bay material removed during 1992 is assumed to be the same as that for 1993 Intake Bay material. Volume of 1992 material is estimated as 11 yds³, half of the 1993 volume. The total activities for the 1992 and 1993 Intake Bay material already in place in the spreading area are shown in Table 7.

Since there is routine removal of material from the Intake Bay during plant outages, the radiological evaluation (Reference 6) also examined the dose consequences associated with anticipated future spreading of Intake Bay material. The average radionuclide concentrations for the 1993 Intake Bay material, as well as the 1993 volume, were assumed to be representative of the Intake Bay material which may be removed during each future outage. The evaluation examined the consequences associated with the accumulated Intake Bay material from a total of 14 outages occurring 15 months apart. Radionuclide activities were adjusted for decay and were also assumed to be homogenous within each volume. The total radionuclide activities at the end of 14 outages (1992, 1993, plus 12 future outages) are presented in Table 7.

2.7 Operational Factors

Plant operations are not expected to be affected in any way by the on-site spreading of the subject material. No changes in the plant Technical Specifications are required and no effect on plant operation will occur due to this program.

2505, 63, 147
2505, 40, 1460

3.0 DESCRIPTION OF THE METHOD FOR LAND SPREADING

3.1 Sediment Generation and Preparation for Spreading

The immediate source of the subject sediment is settlement of particles from sea water in the MY plant Circulating Water system intake structure. Water enters this structure from the Back River. The structure of the intake bay consists of four concrete cells, about 25 by 45 feet and about 20 feet deep. Water flows continuously into these cells when system pumps operate.

The source of the radionuclides in this sediment is licensed releases of effluent from the plant through the discharge of the Circulating Water system. This source is a known and well documented one. A previous configuration of the Circulating Water system discharge caused accumulation of measurable concentrations of radionuclides into Bailey Cove, a small bay on the opposite side of Bailey Point, the peninsula on which the plant site is located (Reference 7). All concentrations released are well within allowable limits for discharge. However, the natural morphology of the river causes some of the elements to disperse in small measure in the river-bottom sediment, rather than in the huge volume of water which daily tidal flux caused to flow past the plant.

Sediment is removed from the Circulating Water Intake Bays during planned plant outages. These occur about every 18 months. Temporary storage of material is done as needed, and release for spreading takes place when warranted by results of analyses and site conditions. This has occurred twice, in 1992 and in 1993, and is expected to occur during each future outage.

No treatment of the sediment is used or warranted. No convenient and cost-effective methods exist to remove or reduce the radioactivity due to nature of the subject material and the very low concentrations of radioactivity in it.

Each batch of sediment will be visually examined and described. Non-radiological chemical analysis of each the land spreading area is conducted annually in keeping with DEP requirements as outlined in Reference 2.

Appropriate records will be kept to represent the material, its origin, handling, and placement. These records should include material source and volume documentation, contractor records, results

14005-10-1104
2505-52-10

of sample analyses, analysis of sample data, and records of placement location and procedures. Data similar to that presented here should be generated for each quantity of sediment placed.

3.2 Method of Land Spreading

MY Work Order 92-5074, parts 01 through 04, is used to control the work done to accomplish sediment removal from intake bays and placement. A contractor is retained to dredge sediment from the Intake Bays using a pump truck. The sediment is mixed with a considerable amount of water during this process and is thus handled like a liquid for the purposes of its dredging and initial placement. An area of the site removed from regular traffic and activities is designated as a Land Application Area and used only for this specific purpose (Figure 1).

The procedure for spreading of sediment includes steps to:

- (a) dredge sediment from the Intake Bays per MY Work Order 92-5074,
- (b) transport soil to the spreading area,
- (c) temporarily stabilize the soil to prevent its erosion,
- (d) spread¹ the soil at a thickness not to exceed 3-4 inches, so as not to kill underlying vegetation,
- (e) retain suitable records, and
- (f) provide DEP with required reports.

Details of specific measures included in Reference 3 should be used to guide the process.

Handling of sediment should be governed by normal plant procedures.

3.3 Location

A drawing of the spreading area is shown in Figure 1. The area is located in the area of the transmission line which runs north out of the MY plant switchyard. The total land area used for spreading of sediment involves about 3 acres (131,000 ft²). This area is of more than sufficient size to accept all of the material presently accumulated and all which can be expected to accumulate for

¹ Spread only during the growing season, when frost or snow do not cover the ground with temporary storage provided as outlined in Reference 5.

the balance of the plant license term.

This land is part of the 740 acre MY site. No regular activity takes place in this area. Plant workers are rarely required to enter this area, and it is seldom traversed by any other persons. Access to the area is monitored by site security personnel. This ownership and supervision by MY staff represent barriers to inappropriate site use.

Vegetation growth in the area is maintained and woody plant herbicide applied tri-annually for transmission line maintenance. For the purposes of this spreading work maintenance makes security easier and prevents sediment erosion.

Release of radionuclides due to wind or water erosion will be insignificant. The humid climate, the flat topography of the area, and vegetative cover will almost completely prevent fluvial erosion. The vegetation also presents a significant wind-break, impeding any wind erosion process.

The MY site spreading area meets or exceeds all state regulations. Accordingly, the material will not be stockpiled or spread within 1000 feet of a public water supply, within 300 feet of a private water supply or over a sand and gravel aquifer, or within 300 feet of the ocean shoreline. The closest public potable water source is the well used as a source for the MY plant, 1000 feet distant from the spreading area (Figure 1). The closest private dwelling is 1500 feet away and across Bailey Cove, which forms a hydrologic barrier to ground water flow in that direction beyond that feature. Reference 3 identifies that no sand and gravel aquifers are located within two miles of the MY plant. In addition, no wells can be located in surficial deposits down-gradient of the site without the knowledge and permission of MY.

The physical environment of the spreading site consists of a man-made early-successional field established through the prior spreading of sediment excavated for the construction of the MY plant (Reference 8). It is beneath and around the MY plant's electric transmission lines as they exit the switchyard. The fill was obtained from bedrock and soil foundation excavations for plant structures, clayey bottom sediments from Montsweag Bay, and other construction materials. This fill ranges from 5 to 15 feet thick. Natural soil underlying the fill consists of the clay-silt Presumpscot formation which

has a thickness of 10 or more feet thick in the spreading area (Reference 8). Bedrock occurs beneath the Presumpscot.

The form of the sediment in no way impairs the spreading area environment. No physical or administrative barriers exist to prevent present or future use of this area for these purposes. The plant's Environmental Statement (Reference 14, pg. III-19), issued in 1972, had originally identified that sediment captured in the intake structure would be suitably placed on plant property.

3.4 Credible Accidents and Prevention Measures

This report and Reference 6 conclude that highly favorable conditions exist for on-site placement of sediment. There is no expectation that any measurable migration of radionuclides will occur from the subject material. It thus poses no potential hazard for significant accidents. No radiological monitoring of the spreading site is thus proposed or warranted.

It is recommended that procedures be followed to guide future dredging and placement of the subject materials, as outlined in Section 3.2.

DATE: 09/15/88

4.0 EVALUATION OF RADIOLOGICAL IMPACTS OF SEDIMENT PLACEMENT

4.1 Potential Exposure Pathways

The most likely exposure pathway is the direct external exposure to the material after placement. The radiological evaluation (Reference 6) determined annual direct doses for two time periods: during the operating lifetime of the plant, and after site closure. The targeted area for spreading is approximately 3 acres of owner-controlled land.

Members of the public have very limited and infrequent access to the area, and their occupation time would be curtailed by plant security during the operating life of the plant. The radiological evaluation (Reference 6) calculates direct dose to a worker based on a conservative occupation time of 2000 hours (one full work year). It is unlikely that actual occupation times for MY workers would exceed more than just a few hours per year. Actual occupation times for members of the public are likely to be significantly shorter. Therefore, determination of a maximum direct dose for a worker present in the area for 8 hours per day for 50 work weeks provides a bounding direct dose for a member of the public while the spreading area remains under the ownership of the licensee. The direct dose to an individual after site closure is based on a conservative occupancy time of 8760 hours and accounts for radioactive decay over a 20 year period.

Reference 6 also examined the potential for exposure due to wind-induced suspension of Intake Bay material. This pathway is unlikely to affect a member of the public because (i) MY's intent is to spread the material so as not to inhibit growth of underlying vegetation, (ii) the vegetation cover would then reduce the chances of significant amount of suspension and erosion of the Intake Bay material, and (iii) reported values for resuspension factors due to wind resuspension are low (Reference 10). The radiological consequences via inhalation were examined for workers who would be responsible for spreading the Intake Bay material.

Less likely potential exposure pathways which were also examined include radionuclide migration through the soil to surface water for exposure via ingestion of fish and shellfish, uptake by edible plants, and ingestion of ground water from a hypothetical well within the spreading area.

Although addressed in the radiological evaluation, the possibility of exposure via these pathways is considered remote due to the location of the MY plant. For example, receiving water is not likely to be used for drinking or irrigation purposes (Reference 9). Nevertheless, the consequences from all conceivable waterborne pathways to a hypothetical member of the public were examined.

Included as part of the assessment of the waterborne exposure pathway is the potential for exposure due to drinking of ground water in the spreading area. Although there is currently no possible means for an individual to site a well in the subject spreading area, this pathway is assessed as a matter of providing a thorough assessment of all potentially significant pathways.

As a potential future exposure pathway, the radiological consequences due to ingesting vegetables grown on the spreading area was examined. Evaluation of this pathway assumed that a fraction of the radioactivity remaining after 20 years finds its way into vegetables which are subsequently ingested by a hypothetical individual.

4.2 Evaluation of Dose Rates and Doses

4.2.1 Direct Dose Rate and Dose

The radiological evaluation (Reference 6) examined the dose consequences from direct exposure to three volumes: (1) the volume of the 1993 Intake Bay material (approximately 583 ft³), (2) the volume of Intake Bay material removed during 1992 and 1993 (approximately 872 ft³), and (3) the accumulated volume of Intake Bay material from 14 outages (approximately 7875 ft³). Various spreading thicknesses were used in the direct dose rate calculations.

The highest direct dose rate, 3.44×10^{-4} mrem/yr, was associated with a 10-inch spreading thickness for the 1993 Intake Bay material. The estimated direct dose rates from this material ranged from 1.38×10^{-4} mrem/hr (for 1 inch thickness) to 3.43×10^{-4} mrem/hr (for 12 inch spreading thickness). Dose rate estimates decreased once the spreading thickness was greater than 10 inches. For all spreading thicknesses, the estimated dose rates represented only a small fraction of the 2 mrem/hr limit established in 10CFR20 for an unrestricted area (<0.02%). The maximum annual dose was obtained by applying a 2000 hour exposure period (ignoring decay) to the highest dose rate. The

resulting maximum annual dose (0.69 mrem) is less than 0.02% of the radiation worker exposure limit and less than 1% of the 10CFR20 exposure limit for a member of the public.

Although the maximum direct dose rate is associated with a spreading thickness of 10 inches, it is doubtful that a 10 inch spreading thickness will allow growth of underlying vegetation. Therefore, it is recommended that a spreading thickness of 3-4 inches be used (see Section 3.2). A 3-inch spreading thickness would result in a lower dose rate ($2.6E-4$ mrem/hr) and would also increase the likelihood for growth of underlying vegetation.

The Intake Bay material will be spread on owner-controlled land, which means that occupancy time is under the supervision and control of the licensee. When a 3-inch spreading thickness is procedurally required (see Section 3.2), the maximum annual dose for a worker or a member of the public is 0.5 mrem. Conservatism in this dose estimate is maintained by assuming an occupancy time of 2000 hours (1 work year). Whether compared to occupational limits or limit for members of the public, the resulting conservative maximum annual dose estimate is only a very small fraction (less than 1%) of exposure limits established in 10CFR20.

The estimated direct dose to a hypothetical individual who was assumed to inhabit the spreading area 20 years into the future was based on the total activity in the Intake Bay material accumulated from 14 outages (1992, 1993, plus 12 future outages). In addition, the calculation accounted for radioactive decay over a 20 year period and incorporated a conservative occupancy time of 1 year (8760 hours). In 20 years, the direct dose rate in the spreading area is estimated to be $7.4E-5$ mrem/hr, significantly lower than the 2 mrem/hr limit established in 10CFR20 for an unrestricted area. Moreover, the corresponding maximum annual direct dose to an individual would be 0.6 mrem, which is significantly lower than the 10CFR20 radiation exposure limit for a member of the public (<1%).

4.2.2 Dose Due to Wind Suspension

The inhalation dose for plant workers was examined by radionuclide on two levels: (1) the committed effective dose equivalent (CEDE), and (2) the maximum committed dose equivalent (CDE)

20250516 2:11:11

to any organ. The estimated CEDE was 3.1×10^{-3} mrem, and the estimated CDE was 1.5×10^{-2} mrem. Both doses were based on the very conservative assumptions, given in Reference 6, in order to determine bounding doses via this unlikely exposure pathway. Even under very conservative assumptions, the inhalation of suspended Intake Bay material neither presents a health hazard nor significantly contributes to the total dose from the material.

4.2.3 Estimation of Waterborne Pathway Doses

The dose to a hypothetical individual who would ingest ground water from the location of the sediment spreading was also examined as part of the radiological evaluation (Reference 6). Results show that dose rates are extremely low with all dose peaks less than 0.1 mrem/yr for a hypothetical maximally exposed individual who would consume 730 liters of ground water from a well in the worst-case location.

4.2.4 Estimation of Dose Via Vegetation Ingestion

This potential exposure pathway was examined in Reference 6 by assuming that an individual ingests vegetables grown in a garden located in the spreading area after site closure (i.e., in 20 years). Under this scenario, the residual radioactivity in the soil reaches the vegetables via root uptake. The annual dose via ingestion of these vegetables was estimated to be 4×10^{-4} mrem/yr (0.0004% of 10CFR20 limit for a member of the public).

5.0 ENVIRONMENTAL IMPACT ASSESSMENT

No adverse environmental impacts will result from placement of sediment, as proposed, on the site. A number of specific characteristics of the material make this true. The plant-related radioactivity in this sediment derives from radionuclides which have half lives of 30 years or less. The material is in a chemical and physical form that poses no hazard to the environment. The natural properties of the radionuclides and the underlying soils are such that migration from the spreading site will be completely prevented. The total activity over the remaining licensed life of the plant will amount to less than $5.5E-5$ Ci dispersed in approximately 7875 ft³ of sediment. The material is placed in a location which is under the direct control of plant management.

7.0 SUMMARY

The placement of subject material does not present any threat to the health and safety of MY employees or members of the public. The radiological consequences of on-site placement of the Intake Bay material have been conservatively estimated. Exposure to the material potentially results in a dose which is a very small fraction of the applicable limits.

Accumulation of sediment in the Intake Bays takes place continuously. Removal of this material is a required and recognized maintenance activity performed during each refueling outage (15-18 months). No special changes to existing scheduling or planning are needed to implement a placement program.

RU
UN
CO
S
E
R
V
I
C
E




Table 1
Half-Life and Retardation Factor* Data
for Radionuclides Found in Samples

Radionuclide	Half-Life (yrs)	Retardation Factors (RF)	RF Data Source
Cs-137	30.0	173 to 7200	Reference 12
Co-58	0.19	600	Reference 13
Co-60	5.26	860 to 3600	Reference 12
Ag-110M	0.70	2000	Reference 13

* Retardation factors represent a time-delay factor for travel of radionuclides through a soil. These compare with fully soluble substances, which have a retardation factor of 1.

2005.03.21.00

Table 2
1993 Inorganic Chemical Analyses of Soil Samples.

Analysis	Underlying Soil 9/1/92	Underlying Soil 8/23/93*	Underlying Soil 10/22/93	Intake Sediment 10/22/93	SW Pipe Debris 9/7/93	ME DEP Limits, CH. 567
pH	5.88	7.88	7.63	7.73	4.36	NA
Cation Exchange Capacity	14	34	22	35	25	NA
potassium	3700	4000	5000	3800	5000	NA
phosphorus	1030	1100	1000	1600	1000	NA
magnesium	5800	7800	6400	6200	2000	NA
calcium	33000	36400	10700	125900	7400	NA
cadmium	<0.2	<0.2	<0.2	<0.2	<0.2	10
chromium	57	61	61	46	28	1000
copper	21	61	24	87	90	1000
lead	6	30	6	20	4	700
mercury	0.02	0.08	0.01	0.15	0.06	10
nickel	26	35	40	45	<1	200
zinc	60	100	70	72	136	2000
arsenic	10.1	6.2	8.3	7.4	2.4	NA

Elemental concentrations are in mg/kg, dry weight.

Table 3
1992 Inorganic Chemical Analyses of Soil Samples.

Analysis	S-1 2/12/92	S-2 2/12/92	S-3 2/12/92	ME DEP Limits, CH. 567
cadmium	<0.2	<0.2	<0.2	10
chromium	44	56	66	1000
copper	610	440	500	1000
lead	32	27	26	700
mercury	0.13	0.29	0.26	10
nickel	32	37	31	200
arsenic	8.4	13.9	13.4	NA
PCB's	<100 ug/kg	<100 ug/kg	<100 ug/kg	10
Total Solids	62.07%	40.98%	38.17%	NA
Total Volatile Solids	6.81%	15.35%	12.35%	NA
Oil & Grease	0.08%	0.23%	0.22%	NA

Elemental concentrations are in mg/kg, dry weight, except as noted.

Table 4
1993 Sediment and Debris Sample Data.

Sample No. and Source	Radionuclide Concentrations, $\mu\text{Ci/g}$				
	Ag-110M	Co-58	Co-60	Cs-137	Total
SE-2 8/23/93 Intake Bay Debris	3.8E-8	6.3E-8	6.6E-8	6.3E-8	2.3E-7
SE-4 9/6/93 North End Soil	3.3E-8	ND	4.4E-8	1.0E-7	1.8E-7
SE-5 9/6/93 South End Soil	2.3E-8	ND	5.7E-8	8.3E-8	1.6E-7
SE-7 10/22/93 North End #1: Soil	ND	ND	ND	1.2E-7	1.2E-7
SE-8 10/22/93 North End #2: Debris	ND	ND	2.6E-8	4.0E-8	6.6E-8
SE-9 10/22/93 Middle #3: Soil	ND	ND	ND	ND	---
SE-10 10/22/93 South End #4: Soil	ND	8.0E-8	2.2E-7	2.4E-7	5.4E-7
SE-11 10/22/93 Mussel Shells	ND	ND	ND	ND	---
Average	3.1E-8	7.2E-8	8.3E-8	1.1E-7	3.0E-7

ND: Not Detected

2505-63-04
 2505-63-04

Table 5
1993 Service Water Pipe Debris Sample Data.

Sample No. and Source	Radionuclide Concentrations, $\mu\text{Ci/g}$				
	Ag-110M	Co-58	Co-60	Cs-137	Total
SE-3 9/6/93 SW Pipe Debris	ND	5.7E-8	2.9E-8	ND	8.6E-8
SE-12 10/22/93 SW Pipe Debris	ND	2.5E-8	4.8E-8	3.3E-8	1.1E-7
Average	—	4.1E-8	3.9E-8	3.3E-8	1.1E-7

ND: Not Detected

Table 6
1993 Spreading Area Soil Sample Data.

Sample No. and Source	Radionuclide Concentrations, $\mu\text{Ci/g}$				
	Ag-110M	Co-58	Co-60	Cs-137	Total
SE-1 8/23/93 Spreading Area Underlying Soil	ND	ND	2.8E-8	6.9E-8	9.7E-8
SE-6 10/22/93 Land Spread '93 Spreading Area Underlying Soil Composite	ND	ND	ND	ND	---

ND: Not Detected

2505-67-36
 2505-10-11-1

Table 7
 Estimated Total Radionuclide Activities* in Intake Bay Material.

Material Volume (ft ³)	Ag-110m (Ci)	Co-58 (Ci)	Co-60 (Ci)	Cs-137 (Ci)	Total Ci
582.7 ^b	9.3E-7	2.1E-6	2.5E-6	3.2E-6	8.7E-6
872.3 ^c	1.1E-6	2.1E-6	3.6E-6	4.8E-6	1.2E-5
7875.0 ^d	1.3E-6	2.1E-6	1.5E-5	3.6E-5	5.4E-5

- * Total radionuclide activities are based on an average of results for only those samples in which there are detectable quantities of radionuclides (Table 4).
- ^b Volume of material removed during 1993. Radioactive decay not taken into account.
- ^c Sum of volumes removed during 1993 and 1992. Radioactive decay of 1992 material taken into account.
- ^d Estimated volume at end of 14 outages (i.e., 1992, 1993, plus 12 additional future outages). Radionuclide activity estimates account for decay.

HSA ID# 13

MAINE YANKEE ATOMIC POWER COMPANY

No. 816-268

- NOTICE OF RADIOLOGICAL CONTROLS INFRACTION
- OBSERVED GOOD WORK PRACTICE

Issued To Dept. Manager: R. Prouty Date: 5-5-86

Issued By: C. ORLICH

Violation Date: 5-1-86 Time: 0840 Location: Hot Side Wash Room

Individuals Involved:

The following Radiological Controls Infraction Good Work Practice is being brought to your attention by worker(s) under your supervisor.

- Improper use of protective clothing. EXPLANATION: Sink Drains go to sewage
- Failure to follow RWP instructions. treatment system. - sinks are used
- Poor Work Practice. for decontamination
- Improper frisking/failure to frisk. Decon showers also drain to
- Inadequate Contamination Control. treatment plant.
- Violation of station Radiological Controls procedures
- Other

Comments: refer to print 11550-FB-27D

REQUESTED ACTION (Completed by Rad. Controls Section Head):

Respond by 5-20-86 indicating the corrective action taken.

RESPONSE (to Radiological Controls Section Head):

SIGNATURE:

DATE:

Response by Dept. Manager Section Head Supervisor

68

HSA ID# 14

GDC

MAINE YANKEE ATOMIC POWER COMPANY

No. 86-246

- NOTICE OF RADIOLOGICAL CONTROLS INFRACTION
- OBSERVED GOOD WORK PRACTICE

Issued To Dept. Manager: T. Boulette Date: 4/25/86

Issued By: C.O. BRIEN

Violation Date: 4-11-86 Time: 1330 Location: BAILY POINT

Individuals Involved:

The following Radiological Controls Infraction is being brought to your attention by worker(s) under your supervisor. Good Work Practice

- Improper use of protective clothing
- Failure to follow RWP instructions
- Poor Work Practice
- Improper frisking/failure to frisk
- Inadequate Contamination Control
- Violation of station Radiological Controls procedures
- Other

EXPLANATION: PAVEMENT & GRAVEL FROM THE CONTAINMENT ALLEYWAY (WHICH IS CONTAMINATED) IS PILED OUT ON THE TIP OF BAILY POINT.

Comments: _____

REQUESTED ACTION (Completed by Rad. Controls Section Head):
Respond by 5/9/86 indicating the corrective action taken.

RESPONSE (to Radiological Controls Section Head):
There is no reason to suspect that gravel from the containment alleyway would be contaminated. Pavement from the alleyway was checked by Rad. Controls prior to and after removal from the
SIGNATURE: J. H. [Signature] DATE: 5-6-86

Response by Dept. Manager Section Head J.H. Supervisor

containment alleyway. A survey of the pile of gravel was conducted on 4-24-86 and no radiation or contamination was found on the exterior gravel and pavement on the pile. To make sure there is no contaminated gravel or pavement outside the Radiation Control area, the pile will be rechecked for contamination.

HSA ID# 15

RADIOLOGICAL INCIDENT REPORT

96-1
NUMBER

SECTION I

DATE AND TIME OF INCIDENT: Aug 29, 1986 11:00 AM

LOCATION: Tip of Bailey Point

HOW RADIATION CONTROLS WAS NOTIFIED: Mark Raeling (Radiological Cont. Tech.) Notified Site (J. H. ...)

PERTINENT DETAILS (Attach copies of surveys, samples, etc. as necessary for documentation):

While removing the sample pile from Bailey Point to the Radiation Control Area for sorting, approximately one liter of contaminated asphalt and gravel was found with radiation levels ranging from 300 counts per minute above background to 50 MR/HR contact. (See attached surveys.)

J. Cochran
PREPARER SIGNATURE

DATE 9-12-86 TIME 0800

SECTION II RADIOLOGICAL CONTROLS SECTION HEAD REVIEW

- This incident requires no further reports, documentation or followup
- This incident requires the following corrective action and/or notification or reports:

See Attached

J. Cochran
Rad Controls Section Head

DATE 9-12-86

- Route to:
1. Dept. Head EDB Dept.
 2. Plant Mgr. J.H. ...
 3. File (Return to Radiological Controls)

Radiology Co. Incident 86-1

During the 1985 refueling outage, the containment alleyway was dug up to work on PCC piping. The asphalt removed was suspected to be possibly contaminated due to being located inside the Radiation Control Area, there was no reason to suspect that the gravel under the asphalt should be contaminated. The accessible asphalt was surveyed by Health Physics Technicians and contaminated pieces were removed. After removing the contaminated asphalt from the gravel, each bucket load of gravel was surveyed with an RM-14 with a HP-210 probe for release from the Radiation Control Area. The gravel was supposed to be disposed of outside the established Radiation Control Area but inside the plant security fence. Approximately 75 yards of gravel was released from the Radiation Control Area on Oct 9 or 10th, 1985 and was taken outside the plant security fence thru gate #6 and dumped on the tip of Bailey Point. Radiological Control Supervisors were not aware that the asphalt and gravel had been removed outside the security fence and dumped on the tip of Bailey Point.

On Oct 30, 1985 it was brought to the

attestation of Radiological Control Supervisors that the confinement alleyway gravel was located at the top of Bailey Post located outside the plant security fence but on Morris Yankee property. A Radiological Controls Technician (Dobbin's Hickoy) was sent out on AT3 to survey the pile of gravel and asphalt to determine if the pile contained radionuclide material. A survey taken by Dobbin's Hickoy showed two spots on the gravel pile that indicated possible contamination above background using a RM-14 detector with HP-210 probe. (See attached survey) On 01/19/85, Dobbin's Hickoy and a Plant Service Worker removed approximately 2 a drum of contaminated asphalt and gravel from the bottom of the pit. A survey taken following the removal of contamination and gravel showed the existence of the pile to be less than 11 MRE/HR and free of contamination. (See attached survey). Based on the results of this survey, I (Gary Cochran) made the determination that the pile of gravel was not in violation of 10 CFR 20 requirements. On April 11, 1986, a Radiological Control Technician #86-246 was sent out to that contaminated asphalt and gravel was located outside the plant security fence

Jim Hummer and Gary Cochran using an RM-14 detector with HP-210 probe spot checked the exterior of the gravel pile and found no contamination or external radiation levels on the gravel pile. My response to the INFRACTION was that the pile of gravel would be brought back inside the Radiation Control Area to be re-surveyed using more sophisticated monitors that had been setup to monitor gravel being released from the Radiation Control Area. At this time I did not consider the gravel pile to be in violation of 10 CFR 20 due to previous surveys taken to release the gravel and a follow-up survey taken by Dennis Hickey.

On Aug. 26, 1986 I requested a thorough survey of the gravel pile to determine if any radioactive material would be found to justify bringing the gravel pile back inside the Radiation Control Area for additional surveys. The external survey taken Aug 26, 1986 showed several points on the pile to be above background radiation levels with a high reading at one location of 16,000 counts per minute. Based on finding these positive counts above background radiation levels, I confirmed by previous

decision that the gravel pits should be brought back on site and re-surveyed.

On Aug 29, 1986 the gravel pile was removed from Bailey Point to the Radiation Control Area. During the removal process approximately one liter of contaminated asphalt and gravel was found with a contact reading of 50 MR/HR. The reading at waist level from this material was less than .1 MR/HR.

Following the removal of the gravel pits the area was barricaded and posted as a Radiation and Contaminated Area.

Detailed radiation surveys of the area were taken Sept 2, 3, and 4th, 1986. The area was released on Sept 4, 1986 as being free of radiation and contamination.

Immediate Corrective Action

Upon finding a 50 MR/HR fault hole, the Bailey Point area was established as a Radiation Control Area. All of the gravel was removed from Bailey Point to the Radiation Control Area inside the plant.

LONG TERM CORRECTIVE ACTION

Radiological Control procedure 9.1.1 (PLA RADIOLOGICAL SURVEYS) will be revised to require written instructions approved

By Radiological Control Supervisor before
informed on attempt to remove them are
released from the Radiation Control
Area.

These instructions will be of a signed type, and
will be filed for future reference by the Radiological
Control
SIC

GDC

No. 84-274

NOTICE OF RADIOLOGICAL CONTROLS INFRACTION
 OBSERVED GOOD WORK PRACTICE

Issued To Dept. Manager: T. Bealoffe

Date: 9/25/86

Issued By: C.O. BRIEN

Location: Barley Point

Violation Date: 4-11-86

Time: 13:10

Individuals Involved:

The following Radiological Controls Infraction is being brought to your attention by worker(s) under your supervision. Good Work Practice

- Improper use of protective clothing
- Failure to follow RWP instructions
- Poor Work Practice
- Improper frisking/failure to frisk
- Inadequate Contamination Control
- Violation of station Radiological Controls procedures
- Other

EXPLANATION: PAVEMENT IS GRAVEL FROM THE SOUTHWEST ALLEYWAY (MARCH IS CONTAMINATED) IS PILES OUT ON THE TIP OF BARLEY POINT

Comments:

REQUESTED ACTION (Completed by Rad. Controls Section Head):
Respond by 5/19/86 indicating the corrective action taken.

RESPONSE (to Radiological Controls Section Head):

There is no reason to suspect that gravel from the contamination alleyway would be contaminated. Gravel from the alleyway was collected by Rad Controls prior to and after removal from the site.

SIGNATURE: [Signature] DATE: 5-6-86
Response by Dept. Manager Section Head Supervisor

Contaminated alleyway. A survey of the pile of gravel was conducted on 4-24-86 and the radiological contamination was found on the eastern gravel and pavement on the pile. It is noted that the gravel and pavement on the pile make sense since there is no contamination of gravel or pavement within the radiation control area. The pile will be rechecked for contamination.

MAINE YANKEE ATOMIC POWER COMPANY
GENERAL SURVEY FORM

Counter PJA Inst Type & No. E1404 S23

Date 8-29-66

Est.

Time 1100

Dist.

Tech. WVF

NOTE: All Dose Rate readings in MR/HR.
All Contamination readings are checked in DPM/100cm².

Area/Item Squad Pile on
Survey point

- ① GEN AREA DOSE RATE ON 4 AREAS PILE WITH
E140 AND HP270 PROBE 20.1 uE/HR
- ② RADIOACTIVE "CHIPS" IN PILE WGRS FOUND TRACING FROM
300 CM TO \rightarrow SDM²/HR ON CORNER WITH HP 210 PROBE
CHIP READING 750 uE/HR W/HP210 PROBE ~ 12 uE/HR & W/RO22A
THESE WERE PINNED IN A 55 GALS DRUM AS THEY
WERE FOUND
- ③ SAND PILE REMOVED TO AREA BETWEEN RUST & DUST
FOR PROCESSING
- ④ BULK OF PILE MOVED BY 1910 AREA WHERE PILE
WAS LOCATED IS STILL ZEPED OFF AS RADIATION
AREA, CONTAMINATION AREA. PENDING A ~~PROBE~~ COMPLETE
DETAILED SURVEY. A CENSARY SURVEY INDICATED
SOME "CHIPS" STILL NEED TO BE REMOVED.

[Handwritten signature]

GENERAL ELECTRIC ATOMIC POWER COMPANY
GENERAL SURVEY FORM

Inst. Type & No. KM 14 #5670

Date 10 20 55

Time 1300

Tech. PLM

BEST AVAILABLE COPY

NOTE: All Dose Rate readings in MR/HR
All Contamination readings are circled in DPM/100-cm²

Area Item

Control Outside Gate # 6

1 First counts in two spots 2000 & 3000

✓

MAINE YANKEE ATOMIC POWER COMPANY
GENERAL SURVEY FORM


Counter N/A Inst. Type & No. E-140 # 522 Date 26 AUGUST 77
EH. W/HP-210 probe Time 14:30
Bkg. RWP 86-8-114 Tech. AS/DN/SAC

NOTE: All Dose Rate readings in $\mu R/hr$: CPM

All Contamination readings are circled in DPM/100cm². (SAMPLES TAKEN IN MERIDIAN'S BEARERS)

PILE OF PF SHELLS
Area/Item PAINT PAINT SPRAY PILE S

AREA BKG @ 100 CPM



[Handwritten signature]


MAINE YANKEE ATOMIC POWER COMPANY

GENERAL SURVEY FORM

Counter N/A⁵⁷ Inst. Type & No. E-526/3544, 3571 Date 9/2/82
 Eff. N/A¹¹ Time 8:12:30 - 1900
 Bkg. N/A¹¹ Tech. JRT/RWE

NOTE: All Dose Rate readings in MR/HR.
 All Contamination readings are circled in DPM/100cm².

Area/Item Burley Point sand



Area from the dotted line down was direct frisked (100% of area).
~~Contaminated asphalt and specks were removed and the immediate areas~~
 were < 100cpm. The entire area was < 100cpm.

* Speck (100,000cpm)

MAINE YANKEE ATOMIC POWER COMPANY
GENERAL SURVEY FORM

Counter See Surveys Taken Sept 2, 3, and 4th. Inst. Type & No. _____ Date Sept 12, 19
 Eff. _____ Time 1300
 Bkg. _____ ~~Site~~ Cochran

NOTE: All Dose Rate readings in MR/HR.
 All Contamination readings are circled in DPM/100cm².

Area/Item AFTER Gravel Pile
Removal

Based on surveys taken by Radiological Control Technician on Sept 2, 3 and 4th, 1986 the gravel pile location on the Tip of Bailey Point has been released as free of radiation and contamination.


MAINE YANKEE ATOMIC POWER COMPANY
GENERAL SURVEY FORM

Counter _____ Inst. Type & No. E-140 = 522 Date 26 AUGUST 1986
Eff. _____ RWP 86-8-114 Time 14:30
Bkg. _____ Tech. AS/DH/SAC

NOTE: All Dose Rate readings in ^{SAC} ~~MR/HR~~ CPM
All Contamination readings are circled in DPM/100cm². (SAMPLES TAKEN IN MERINELLI BEAKERS)

PILE
OF
SHELLS

Area/Item BAILEY POINT SAND PILE SURF





MAINE YANKEE ATOMIC POWER COMPANY
GENERAL SURVEY FORM

Counter N/A Inst. Type & No. E-120 #3565 with Date 20 AUG 83
 Eff. N/A Long Time 0815
 Bkg. N/A RUP 86-8-114 Tech. WD

NOTE: All Dose Rate readings in MR/HR.
All Contamination readings are circled in DPM/100cm².

Area/Item Restored Area on Bailey Point
BKGD 40cpm

Photo 



FRISK 3FT OUT AROUND RESTORED AREA EXCEPT @ BOTTOM FRISK 10FT OUT ON DOWN GRADE < BKGD

MAINE YANKEE ATOMIC POWER COMPANY

GENERAL SURVEY FORM

Counter N/A
Eff. _____
Bkg. _____

Inst. Type & No. RM-14 #365


Date 1 SEPT 86
Time 1400
Tech. WB

BKGD 100 cpm

NOTE: All Dose Rate readings in MR/HR.
All Contamination readings are circled in DPM/100cm².

Area/Item #2 SAND Pile Area
Bailey Point

PLANT ↗



TO: G. D. Cochrane

Company/Location

June 25, 1986

FM: R. P. Wills

Company/Location

FILE 14.8.2

SUBJECT: Methodology for Release of Sand from the Radiation Control Area (Rev. 1)

Maine Yankee has in its controlled area, a sand pile which originated from the excavation of the PCC piping. Throughout this total project only one area was defined as a potential source of contamination. This area is the top few millimeters of sand directly underneath the hot top of an old high rad storage bunker. All hot top was removed as radwaste, and all excavated sand is being surveyed for removal to other locations within the plant protected area. In order to comply with our radwaste volume reduction goals, I have been tasked with the removal and release of this material.

The release of all material from the controlled area must meet the conditions of Procedure 9.1.1, section 7.3 "Release of Material from the Plant Radiation Control Area." This section states that three conditions must be fully satisfied: no alpha contamination above 100 DPM; no beta/gamma contamination above 1,000 DPM; and, all beta/gamma readings are less than 0.1 mr/hr. As an added assurance for the protection of plant personnel, we will perform an isotopic analysis of each 55 gallon drum we release from the radiation control area.

We have set up a frisking apparatus which consists of five RM-14/HP-210 probes. All friskers are source checked daily by a Rad Controls technician, and so logged. The sand is kept to a thin layer "less than or equal to two inches," and a present frisking speed no faster than two inches per second. All RM 14/HP-210 friskers will be set to alarm at 100 cpm above background with a maximum allowable background of 200 cpm. The conditions set forth in the above paragraph will assure compliance with two of the three required conditions, "less than 1,000 DPM beta/gamma and less than 0.1 mr/hr gamma." The alpha limits can be excluded by the understanding of the origin of this sand. It was never exposed to any material subject to fission products, and at Maine Yankee we have never seen an alpha contamination problem in any of our routine surveys.

Our last and most limiting condition for removal of this sand is the isotopic analysis performed on each cubic yard of sand (four - 55 gallon drums). Rad Controls with assistance from Chemistry will analyze a one liter sample of sand for each cubic yard of sand frisked clean and report all results to the Lead Radiological Controls Specialist, or the Hazardous Waste Coordinator. All sand samples identified as having any isotopes with an activity equal to or greater than 1/10 of the most limiting value for MPC limits for water in Table II of Appendix B of 10CFR20 will be removed as radioactive waste.

All other material is considered clean and may be removed out side the radiation controlled area, but not outside the plant restricted/protected area.

Robert P. Wills
Robert P. Wills
Hazardous Waste Coordinator

RPW:pab

cc: J. H. Garrity
E. T. Boulette
P. J. Dostie


2586M:RPW:pah

May 15, 1986


Operational Instruction for Removal of Sand
From the Radiation Control Area (RCA)

1. Initiate RWP each day.
2. Set up the conveyer belt.
3. Set up the sand height discriminator at one inch.
4. Obtain five RM-14/HP 210 probes from Rad Controls.
5. Source check all the RM-14s each day prior to use.
6. Set up the RM-14s and probes in a shielded rack over the conveyer belt.
7. Set the alarm point at 100 cpm above the background readings. Note: DO NOT frisk in an area where the background is greater than 200 cpm. If the background exceeds 200 cpm, contact the Hazardous Waste Coordinator (HWC).
8. Start the conveyer belt at a speed of two inches per second.
9. If you receive an RM-14 alarm, STOP the conveyer belt. Survey the area with RM-14/HP-210 probe to remove only the material causing the alarm.
10. Place the removed material into a radioactively labelled 55 gal drum.
11. All the drummed material will be disposed of according to the HWC's instruction.
12. All the sand that is released from the RCA will be relocated under Fred Klein's direction.
13. Notify the HWC of any problems.

Prepared By:


Robert P. Willis
Hazardous Waste Coordinator

Approved By:


Gary D. Cochrane
Rad Controls Section Head

RPW:pab

2265M:RPW

HSA ID# 16

MAINE YANKEE ATOMIC POWER COMPANY

No. 86-228

- NOTICE OF RADIOLOGICAL CONTROLS INFRACTION
- OBSERVED GOOD WORK PRACTICE

Issued To Dept. Manager: T. Boulette Date: 4-24-86

Issued By: C.A. Young

Violation Date: 4-11-86 Time: 0326 Location: H.P. CKPT

Individuals Involved:

S. Clukey

The following Radiological Controls Infraction is being
 Good Work Practice
brought to your attention by worker(s) under your supervisor.

- Improper use of protective clothing
- Failure to follow RWP instructions
- Poor Work Practice
- Improper frisking/failure to frisk
- Inadequate Contamination Control
- Violation of station Radiological Controls procedures
- Other

EXPLANATION: Allowing Release of Grove from ~~Hot~~ side RCA without Proper Survey.

Comments: Grove was checked only by smearing tires

REQUESTED ACTION (Completed by Rad. Controls Section Head):
Respond by 5-8-86 indicating the corrective action taken.

RESPONSE (to Radiological Controls Section Head):
Discussed need for dose rate measurements in addition to smearable contamination check

SIGNATURE: J. Hammer DATE: 5/13/86
Response by Dept. Manager Section Head J.H. Supervisor

CDEF

HSA ID# 17

MAINE YANKEE ATOMIC POWER COMPANY

No. 86-191

- NOTICE OF RADIOLOGICAL CONTROLS INFRACTION
- OBSERVED GOOD WORK PRACTICE

Issued To Dept. Manager: W. Paine J. Frothingham Date: 4-10-86

Issued By: C.A. Young

Violation Date: 4-9-86 Time: 0800 Location: HV-9 AREA

Individuals Involved:

Plant Services

The following Radiological Controls Infraction Good Work Practice is being brought to your attention by worker(s) under your supervisor.

- Improper use of protective clothing
 - Failure to follow RWP instructions
 - Poor Work Practice
 - Improper frisking/failure to frisk
 - Inadequate Contamination Control
 - Violation of station Radiological Controls procedures
 - Other
- EXPLANATION: Pit in HV-9 Area Remains Contaminated even though NO Radioactive Systems are in this Area.
- DONE 4/30/86 Johnson

Comments: We don't have anything to do with this but we've cleared it up.

REQUESTED ACTION (Completed by Rad. Controls Section Head):
Respond by 4-18-86 indicating the corrective action taken.

RESPONSE (to Radiological Controls Section Head):
This Area belongs to the operations Dept.

SIGNATURE: W. Paine DATE: 4-15-86

Response by Dept. Manager Section Head Supervisor

HSA ID# 18

Section Head QDE
 Supervisor P. Dostie

MY-HP-216-HG

No.: 86-135

MAINE YANKEE ATOMIC POWER COMPANY
NOTICE OF RADIOLOGICAL CONTROLS INFRACTION

Issued To: T. Brault Date: 4-3-86

Issued By: CA Young

Violation Date: 4-1-86 Time: 0830 Location: Backyard

Individuals Involved:

Rad Waste Coordinator

The following violation of radiological safety practices by workers under your supervision is being brought to your attention:

Improper use of protective clothing

Failure to follow RWP instructions

Failure to log in/out

Improper frisking/failure to frisk

Other: Crane laying in backyard is contaminated with Core Guard chips and is not covered in plastic or marked as radioactive.

REQUESTED ACTION (Completed by Rad. Controls Section Head):

FIRST NOTICE: Respond by 4/17/86 indicating the corrective action taken to prevent a recurrence.

SECOND NOTICE: Contact Rad. Controls Section Head by _____ to schedule a conference to include: Immediate Supervisor and individual(s) involved.

THIRD NOTICE: Contact Rad. Controls Section Head by _____ to schedule a conference to include: Immediate Supervisor, Section Head and individuals involved.

OTHER: _____

RESPONSE (to Radiological Controls Section Head):

I do not accept the responsibility of the Rad Waste Coordinator to investigate these chips from someone else. It is apparent to me that the responsibility of the department with all crane gear, especially since they did not contact HP to properly stop it to prevent the spread of contamination.

SIGNATURE: Pet Dostie

DATE: 4/5/86

0294F

P.S. The infraction should be directed at the responsible Dept. and removed

HSA ID# 19

Section Head ADC
 Supervisor J. Hummer

Mr 216-86

No.: 86-132

MAINE YANKEE ATOMIC POWER COMPANY
NOTICE OF RADIOLOGICAL CONTROLS INFRACTION

Issued To: T. Boulette Date: 4-2-86

Issued By: READING

Violation Date: 3-30-86 Time: 0600 Location: CTUT ALLY

Individuals Involved:
Rad. Cont. group

The following violation of radiological safety practices by workers under your supervision is being brought to your attention:

- Improper use of protective clothing
- Failure to follow RWP instructions
- Failure to log in/out
- Improper frisking/failure to frisk
- Other: 55 GAL DRUM CONTAINING SAND SWEEPED UP FROM GROUND HAS 1 SPOT READING 35 mR/H DRUM NOT MARKED RADIATION OR DOSE RATED - CORRECTED

REQUESTED ACTION (Completed by Rad. Controls Section Head):

- FIRST NOTICE: Respond by 4-15-86 indicating the corrective action taken to prevent a recurrence.
- SECOND NOTICE: Contact Rad. Controls Section Head by _____ to schedule a conference to include: Immediate Supervisor and individual(s) involved.
- THIRD NOTICE: Contact Rad. Controls Section Head by _____ to schedule a conference to include: Immediate Supervisor, Section Head and individuals involved.
- OTHER: _____

RESPONSE (to Radiological Controls Section Head):

Corrected on the spot.

SIGNATURE: J. Hummer

DATE: 4/10/86

0294F

HSA ID# 20

HY-HP-216-86

No.: 86-111

MAINE YANKEE ATOMIC POWER COMPANY
NOTICE OF RADIOLOGICAL CONTROLS INFRACTION

Issued To: R. Prouty Dept: Maint Date: 3/27/86
Issued by Robert Wilks

Violation Date: 3/27/86 Time: 1120 Location: RCA TK-85

Individuals Involved:
* Equipment *
P120 / P123 Leak

The following violation of radiological safety practices by workers under your supervision is being brought to your attention:

- Improper use of protective clothing _____
- Failure to follow RWP instructions _____
- Failure to log in/out _____
- Improper frisking/failure to frisk _____
- Other: These pumps leak contaminated water to the clean RCA floor causing a contamination problem.

REQUESTED ACTION (Completed by Rad. Controls Section Head):

- FIRST NOTICE: Respond by _____ indicating the corrective action taken to prevent a recurrence.
- SECOND NOTICE: Contact Rad. Controls Section Head by _____ to schedule a conference to include: Immediate Supervisor and individual(s) involved.
- THIRD NOTICE: Contact Rad. Controls Section Head by _____ to schedule a conference to include: Immediate Supervisor, Section Head and individuals involved.
- OTHER: _____

RESPONSE (to Radiological Controls Section Head):

LEAKS HAVE BEEN REPAIRED

SIGNATURE: [Signature] DATE: 4-26-86

0294f

HSA ID# 21

RADIOLOGICAL INCIDENT REPORT

84-9
NUMBER

SECTION I

DATE AND TIME OF INCIDENT: 9/17/89 Approx 11:30 AM
LOCATION: RCA Storage Area Fuel Back Disassembly
HOW RADIATION CONTROLS WAS NOTIFIED: Tech reported higher sample results

CONTINENT DETAILS (Attach copies of surveys, samples, etc., as necessary for documentation):

There were no regularity consequences of the attached air sample taken in the tank area even though the depth of the core was measured at the time.
This reporter prepared checklist document for the Tech which was performed.

[Signature]
REPORTER SIGNATURE

DATE: 9/17/89 TIME: 11:30

SECTION II RADIOLOGICAL CONTROLS SECTION LEAD REVIEW

This incident requires no further reports, documentation or followup reports.
 This incident requires the following corrective action and/or notification of reports:
Note: The physics area lead and measures were taken to prevent removable surface contamination for authors in the opening doors and the roof deck.

[Signature]
RADIATION CONTROLS SECTION LEAD

DATE: 9-17-89

- Route to: 1. Dept. head _____ Dept. _____
2. Plant Mgr. _____
3. File (return to radiological controls)

NAME: YANKEE

11-SEP-84 12:08:00

SAMPLE: RCA FUEL RACK DISASS
DATA COLLECTED ON 11-SEP-84 AT 11:50:13
DECAYED TO 0. DAYS, 2.7597 HOURS BEFORE THE START OF COLLECT.

R A D I O U C L I D E A N A L Y S I S R E P O R T

NUCLIDE	ACTIVITY CONCENTRATION IN UC/CC		DECAY CORRECTED	ERROR	ENERGY COMPARISON (KEV)	
	MEASURED	ERROR			EXPECT	DIFF
AG-110M	7.47E-09	+6.88E-11	7.47E-09	+6.88E-11	657.74	0.09
CO-58	3.09E-10	+2.10E-11	3.09E-10	+2.10E-11	884.67	0.06
CO-60	7.11E-09	+8.19E-11	7.11E-09	+8.19E-11	810.76	0.03
CS-136	4.35E-10	+2.76E-11	4.37E-10	+2.76E-11	511.01	0.65
CS-137	1.31E-09	+3.34E-11	1.31E-09	+3.34E-11	1332.46	0.13
F-18	4.66E-11	+9.12E-12	1.32E-10	+2.59E-11	1173.21	0.11
H3-203	5.22E-11	+1.05E-11	5.23E-11	+1.06E-11	818.50	-0.43
K-40	2.57E-10	+1.81E-10	2.57E-10	+1.81E-10	661.64	0.09
RH-24	1.83E-10	+2.42E-11	1.83E-10	+2.42E-11	511.01	0.65
H3-205	7.21E-09	+7.09E-11	7.21E-09	+7.09E-11	279.19	0.46
SR-90	3.56E-10	+2.41E-11	3.57E-10	+2.42E-11	1460.73	0.21
SO-128	5.29E-10	+4.82E-11	5.29E-10	+4.83E-11	834.83	-0.00
SE-75	9.13E-11	+1.36E-11	9.14E-11	+1.36E-11	658.17	0.34
BN-113	7.72E-11	+1.19E-11	7.72E-11	+1.19E-11	1690.94	0.31
TR-97	3.56E-10	+3.88E-11	3.56E-10	+3.88E-11	427.86	0.12
TOTAL	2.43E-08	+2.38E-10	2.50E-08	+4.05E-10	600.60	0.13
					264.67	0.00
					135.97	-0.04
					391.69	0.12
					743.41	0.87

STANDARD DEVIATION * 0.30

ERRR * 1.51 NEUTRON INTEGRATION
 MAXIMUM PERMISSIBLE ACTIVITY * 6.61E+01 UC/CC
 TOTAL MEASURED ACTIVITY * 2.40E-08 U+3.58E-10 UC/CC
 % TECH. SPEC. * 0.00 (+0.00)

ERROR ESTIMATION AT 1.00-SIGMA

PEAKS NOT USED IN ANALYSIS

CHANNEL	ENERGY KEV	NET AREA COUNTS	ERROR	CANNAIS SEC
242.59	121.05	467	11.6	4.29E+00
355.78	178.34	700	14.3	2.84E+00
894.25	446.93	2063	44.7	0.69E+01
927.09	463.54	440	14.1	1.26E+01
1020.24	509.92	264	11.1	2.70E+00
1041.23	520.47	1112	16.3	4.44E+01
1335.45	667.73	1487	19.1	1.03E+01
1474.40	737.10	2321	23.2	1.04E+02
1474.40	737.10	2751	27.5	2.27E+02

9/12/79

MULTIPLIER	MPC	TABLE II MPC (uCi/cm ³)	CONCENTRATION (uCi/cm ³)	RADONIDE
24.9	0.18	3 x 10 ⁻¹⁰	7.47 x 10 ⁻⁹	Ag-110m
23.7	0.62	3 x 10 ⁻¹⁰	7.11 x 10 ⁻⁹	Co-60
		5 x 10 ⁻¹⁰	1.31 x 10 ⁻⁹	Cs-137
		2 x 10 ⁻⁷	3.63 x 10 ⁻⁸	Nb-97

1/5 year annual average $\chi = 0.59 \times 10^{-5}$ rad/m³

According to E. T. Miller there is a gamma constant χ/Q value for a ground level release

Roof height = 14' x 14' = 196 ft² x 929 cm/ft³ = 1.821 x 10⁵ m³ of air per year for 3 km.

Assuming a 1 ft/sec exchange velocity

$$V = 1.821 \times 10^5 \text{ cm}^3 \times 2.54 \text{ cm}^3 \times 12 \text{ m} = 9.25 \times 10^4 \text{ cm}^3$$

$$\text{Ag-110m } Q \cdot V \cdot C_A = 9.25 \times 10^4 \text{ cm}^3/\text{sec} \times 7.47 \times 10^{-9} \text{ uCi/cm}^3$$

$$\text{Ag-110m } Q \cdot V \cdot C_A = 6.91 \times 10^{-4} \text{ uCi/sec} \times 10 \text{ m}^3/\text{sec} = 6.91 \times 10^{-3} \text{ uCi/sec}$$

$$\chi = 6.91 \times 10^{-10} \text{ uCi/sec} \times 2.59 \times 10^5 \text{ sec/m}^3 = 1.79 \times 10^{-4} \text{ uCi/m}^3$$

Site boundaries for Ag-110m
 For 1 ft/sec velocity at 3 km
 10 m³/sec

1 m = 100 cm
 1 m³ = 10⁶ cm³
 10⁵ m³ = 10¹¹ cm³

HSA ID# 22

19.11.4

The attached are out-of-date related personnel
communication reports. The difficulty experienced
with the large clip communication and tracking
if that communication is related to by these
reports. Daily and shiftly surveillance was
imposed and medical resources were constantly
reviewed and updated.

These reports are filed as a group because the
problem was similar to one, larger project
which made its impact ~~throughout~~ the plant
The high specific activity and missile size of
the clips made the control of the clips extremely
difficult. The total number was however
sufficient enough to prevent any clips from
leaving the RPA.

John [unclear]
Rad. Control Supervisor

HSA ID# 23

FROM B. Kimball

FILE 14-8.2/19.11.4

SUBJECT Radiological Incident 83-2

While attempting to dewater a cavity drain line filter assembly, water and radioactive crud was sprayed on the floor of the RCA and an individual near the filter.

This was caused by not shutting off the air supply to the air line being used to push the water out of the filter prior to connecting the air line to the filter. When the air line was connected, full instrumentation pressure was applied to the filter. This caused the drain from the filter to jump out of the floor drain and spray water on the RCA floor. When the individual who had connected the air line realized what had happened, he disconnected the air line from the filter. Pressure had been built up in the filter, and water and crud sprayed on him.

Surface contamination: 14 kdpm/100cm²

Personal contamination: 5600 dpm/100cm²

Personal contamination report made out and operator was sent for a body count.

Blaine Kimball
Rad. Controls Foreman

BMK/pgw

1188 2201

HSA ID# 24

24

DECOM

NOV 10 1985

ATTACHMENT B

ATLAS DOCUMENT INPUT FORM

1. TITLE		UOR 079-85 PCC Leak Underground	
2. DOCUMENT TYPE		Reports	3. DOCUMENT FORM
			M
4. DOCUMENT LOCATION		5. RETENTION PERIOD	
6. TECHNICAL FILE NUMBER		11.14.6	1.8.4.2
		1.8.4.2	
7. DOCUMENT NUMBER		UOR 85-079	
8. REVISION NUMBER	9. DATE	10-10-85	10. CLASSIFICATION TYPE
			D
11. TOPICAL INDUSTRY ISSUE			
12. KEYWORDS			
13. SUBJECT			
14. REFERENCE DOCUMENT			
15. SYSTEM CODE		16. COMPONENT CODE	
17. CYCLE NUMBER			
18. ORIGINATOR		OPS	
19. RECEIVER			
20. VENDOR CODE			
21. ACCESSION NUMBER			
ACTION: ADD/REPLACE/DELETE (CIRCLE ONE)			

079-85

OPERATIONS DEPARTMENT
UNUSUAL OCCURRENCE REPORT

MY-0-3-76
Page 1 of 2
Rev. No. 4

FILED
NOV 10 1985

DATE 10-10-85

TIME 1950

1. PLANT CONDITIONS AT TIME OF OCCURRENCE

% POWER Shutdown %

STEADY STATE _____

TAKE _____ °F

SHUTDOWN X

PZR. PRESS _____ psig

TRANSIENT _____

PZR. LEVEL _____ %

OTHER _____

PLANT TRIP YES _____ NO X

2. NOTIFICATION

DOES OCCURANCE REQUIRE NRC NOTIFICATION YES X NO _____ 50.72 (b)(2)(vi)
(if No, explain why in Discussion).

HAS PROCEDURE 2.50.0, "DECLARATION AND CATEGORIZATION OF EMERGENCY
CONDITION" BEEN CONSULTED? YES _____ NO X

NRC NOTIFIED BY R McGrath TIME/DATE 1850 / 10-10-85

WHAT METHOD RED PHONE X NET PHONE _____ OTHER _____

NSE NOTIFIED & INVOLVED R McGrath

* DUTY CALL OFFICER NOTIFIED BY _____ DATE/TIME _____

NRC RESIDENT INSPECTOR NOTIFIED (if applicable) yes

DATE/TIME _____

* DUTY CALL OFFICER WILL NOTIFY THE PLANT MANAGER & THE MANAGER OF
OPERATIONS (MOO)

NSE - NUCLEAR PLANT RELIABILITY DATA SYSTEM NPRDS - ROUTED TO
ENGINEERING SUPPORT GROUP YES _____ NO X

DISCUSSION:

Samples of water from Foundation
drains indicated cromates were leaking
from underground piping near the

OPERATIONS DEPARTMENT

UNUSUAL OCCURRENCE REPORT

NY-0-3-76
Page 2 of 2
Rev. No. 4

Containment bldg. (10-7-85)

The Maine State Department of Environmental Protection was informed on 10-8-85 and were on site investigating the leak area today. (10-10-85)

In accordance with 10CFR 50.72 R2U, the NRC was informed as this event involved notification of another Government Agency (involving a situation related to the health and safety of the public).

Excavation has revealed the approximate leak location in a Pcc line near the Spray Bldg. Currently the Pcc system is being removed SDWA service and repair efforts continuing.

DATA ATTACHED YES NO

Report Prepared By RIM AST

PSS Reviewer William Davis

Original Copy to Operations; Department Head

Copies for the following: :

J. O. Fairbridge

PSS
SOS
RO (2 copies)
FM
AM

1155545

QUESTIONNAIRE FOR MAINE YANKEE SITE CHARACTERIZATION

NAME DOU STEVENSON EMPLOYED FROM 10/70 TO 10/97

CURRENT TITLE SENIOR INSTRUCTOR DEPT TRAINING
(Leave the above blank if you choose to remain anonymous.)

PLEASE CIRCLE THE APPROPRIATE ANSWER CONCERNING ACTIVITIES AT MAINE YANKEE. ARE YOU AWARE, OR WERE YOU ASSOCIATED WITH ANY OF THE FOLLOWING ACTIVITIES:

- | | | | |
|--|-----|----------------------------------|-------------------------------------|
| 1. A spill of Radioactive Material on the plant site? | Yes | <input type="radio"/> | No <input checked="" type="radio"/> |
| 2. Inappropriate storage or control of Radioactive Material on the plant site? | Yes | <input type="radio"/> | No <input checked="" type="radio"/> |
| 3. An effort to cover over or isolate Radioactive Material on the plant site? | Yes | <input type="radio"/> | No <input checked="" type="radio"/> |
| 4. A spill of Asbestos Material on the site? | Yes | <input type="radio"/> | No <input checked="" type="radio"/> |
| 5. Inappropriate storage or control of Asbestos Material on the plant site? | Yes | <input type="radio"/> | No <input checked="" type="radio"/> |
| 6. An effort to cover over or isolate Asbestos Material on the plant site? | Yes | <input type="radio"/> | No <input checked="" type="radio"/> |
| 7. A spill of Petroleum Products on the plant site? | Yes | <input type="radio"/> | No <input checked="" type="radio"/> |
| 8. Inappropriate storage or control of Petroleum Products on the plant site? | Yes | <input type="radio"/> | No <input checked="" type="radio"/> |
| 9. An effort to cover over or isolate Petroleum Products on the plant site? | Yes | <input type="radio"/> | No <input checked="" type="radio"/> |
| 10. A Chemical spill on the plant site? | Yes | <input type="radio"/> | No <input checked="" type="radio"/> |
| 11. Inappropriate storage or control of Chemicals on the plant site? | Yes | <input checked="" type="radio"/> | No <input type="radio"/> |
| 12. An effort to cover over or isolate Chemicals on the plant site? | Yes | <input type="radio"/> | No <input checked="" type="radio"/> |
| 13. Any Raw Lead inadequately stored or contained on the plant site? | Yes | <input type="radio"/> | No <input checked="" type="radio"/> |

If you answered YES to any of the above questions, please add the appropriate details (date, time, location, etc.) related to the questions above. If you know of or have a concern about any other Hazardous Material associated with Maine Yankee, please attach that information as well. Return this completed form to Dennis Hickey of Radiation Protection.

THE ONLY HAZARDOUS MATERIAL SPILL (LEAK) THAT
COMES TO MIND IS THE PCL PIPING LEAK THAT
WAS REPAIRED. THE LEAK WAS UNDERGROUND
BETWEEN THE CONTAINMENT & SERVICE BUILDING
(THE ALLEY WAY) I BELIEVE L.J. SPEDD WAS
THE ENGINEER IN CHARGE OF REPAIR'S