

92039  
P21 ~~92039~~  
Publicly Available

NUCLEAR REGULATORY COMMISSION  
SHARED INFORMATION NETWORK  
OPERATIONS OFFICERS SUPPORT SYSTEM  
EVENT NOTIFICATION - POWER FACILITIES

EVENT NUMBER: 23289

FACILITY: FORT CALHOUN  
UNIT NO: 1  
REGION: 4  
DOCKET NO: 050-00285 -  
LICENSE TYPE: Power reactor  
STATE: NE  
EMERGENCY: N/A Not applicable  
LICENSE NO: DPR 040  
LICENSEE: OMAHA PUBLIC POWER DISTRICT  
REPORT REQUIRED BY: IND 50.72 (b)(2)(iii)(D)

EVENT DATE: 04/20/  
EVENT TIME: 15:24  
NOTIFY DATE: 04/20/  
NOTIFY TIME: 17:32  
CALLER: TERRY  
OPS OFFICER: THOMAS  
NOTIFIED: RDO T  
EO A

UNIT	SCRAM CD	RX CRITL	INIT PWR	INIT RX MODE	CURR PWR	CURR RX
1	N	N	000	Mode 5 - Cold s	000	Mode 5 -

DESCRIPTION TEXT

CRACKING OF CAM FOLLOWERS ON SBM CONTROL SWITCHES FOR 4160V SWITCHGEAR. DURING A CLOSE OUT OF AN INCIDENT REPORT (IR 920166), AN INSPECTION OF THE SWITCH FOR RAW WATER PUMP AC-10A REVEALED THAT A PLASTIC CAM FOLLOWER FOR ONE OF THE ENCLOSED CONTACTS HAD CRACKED AND RENDERED THAT SINGLE CONTACT UNABLE TO CLOSE. THE CRACKING IS BELIEVED TO BE CAUSED BY HYDROCARBON CONTAINED IN CLEANING AGENTS APPLIED TO THE SWITCH DURING MANUFACTURE AND MAINTENANCE.

FOLLOWING THE IDENTIFICATION OF THE AC-10A SWITCH FAILURE MECHANISM, A SPOT CHECK OF THE 4160V SWITCHGEAR CUBICLES ON APRIL 18 FOUND THAT ABOUT 20% OF THE FORT CALHOUN STATION SWITCHES HAD LEXAN (CLEAR PLASTIC) CAM FOLLOWERS AND 80 % OF A DELRIN (MILKY WHITE PLASTIC) MATERIAL. THE DELRIN CAM FOLLOWERS DO NOT EXHIBIT THE CRACKING PROBLEM.

AS A RESULT OF THE APRIL 18 INFORMAL INSPECTION, A SYSTEMATIC INSPECTION OF 100% OF THE CAM FOLLOWERS WAS CONDUCTED ON A TOTAL OF 191 SWITCHES. FORTY SWITCHES WITH LEXAN CAM FOLLOWERS SHOWED INDICATIONS OF CRACKING. FIFTEEN OF FORTY SWITCHES HAD MISSING PIECES OF CAM FOLLOWER MATERIAL. AN ADDITIONAL SIX OF THE 40 HAD OPEN CRACKS.

BASED UPON EVALUATION OF THE SWITCH FAILURE MECHANISM, IT HAS BEEN DETERMINED THAT A POTENTIAL COMMON MODE FAILURE MECHANISM EXISTS FOR A PIECE OF BROKEN CAM FOLLOWER TO JAM THE SBM ROTATING MECHANISM FOR AN ASSEMBLY OF THE SWITCHES WHICH FEEDS MULTIPLE COMPONENTS AND FUNCTIONS. BASED ON THE ABILITY TO MANUALLY OPERATE BREAKERS, FAILURE OF CRACKED SWITCHES WAS DETERMINED TO HAVE NO IMMEDIATE SAFETY IMPLICATIONS WITH THE PLANT IN A SHUTDOWN MODE.

REPLACEMENT OF 4160V SWITCHGEAR SBM SWITCH ASSEMBLIES WITH OPEN CRACKS OR MISSING PIECES IS IN PROGRESS IN A SEQUENCE COMPATIBLE TO SUPPORT SAFETY FUNCTIONS DURING HEATUP AND PLANT RESTART. OTHER ACTIONS TO ADDRESS SWITCH CRACKING ARE BEING DEVELOPED.

THE LICENSEE ALSO NOTED THAT THEY SUCCESSFULLY COMPLETED SAFEGUARDS TESTING

NUCLEAR REGULATORY COMMISSION  
SHARED INFORMATION NETWORK  
OPERATIONS OFFICERS SUPPORT SYSTEM  
EVENT NOTIFICATION - POWER FACILITIES

EVENT NUMBER: 23289

IN THE PAST COUPLE OF WEEKS IN WHICH THESE SWITCHES SATISFACTORILY  
PERFORMED THEIR DESIGN FUNCTION.

THE NRC RESIDENT INSPECTOR HAS BEEN NOTIFIED. NO OTHER NOTIFICATIONS ARE  
REQUIRED OR ANTICIPATED.