



**Entergy Nuclear Northeast**  
Entergy Nuclear Operations, Inc.  
Indian Point Energy Center  
295 Broadway, Suite 1  
P.O. Box 249  
Buchanan, NY 10511-0249

December 21, 2001

Re: Indian Point Unit No. 2  
Docket No. 50-247  
LER 2001-006-00  
NL-01-143

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Mail Stop O-P1-17  
Washington, DC 20555-0001

Dear Sir:

The attached Licensee Event Report 2001-006-00 is hereby submitted in accordance with the requirements of 10 CFR 50.73.

Sincerely,

A handwritten signature in black ink, appearing to read "Fred Dacimo", written over a horizontal line.

Fred Dacimo  
Vice President - Operations  
Indian Point 2

Attachment

cc: Mr. Hubert J. Miller  
Regional Administrator - Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Mr. Patrick D. Milano, Senior Project Manager  
Project Directorate I  
Division of Licensing Project Management  
U.S. Nuclear Regulatory Commission  
Mail Stop O-8-C2  
Washington, DC 20555

Senior Resident Inspector  
U.S. Nuclear Regulatory Commission  
PO Box 38  
Buchanan, NY 10511

IE 22

<b>NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION</b> (6-1998)  <b>LICENSEE EVENT REPORT (LER)</b>  (See reverse for required number of digits/characters for each block)	<b>APPROVED BY OMB NO. 3150-0104 EXPIRES 06/30/2001</b> Estimated burden per response to comply with this mandatory information collection request: 50 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Forward comments regarding burden estimate to the Records Management Branch (T-6 F33), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, and to the Paperwork Reduction Project (3150-0104), Office of Management and Budget, Washington, DC 20503. If an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.
---	--

<b>FACILITY NAME (1)</b> Indian Point, Unit 2	<b>DOCKET NUMBER (2)</b> 05000247	<b>PAGE (3)</b> 1 OF 4
--	--------------------------------------	---------------------------

**TITLE (4)** Pipe Erosion Results In Service Water System Leakage In Containmentment

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
10	29	2001	2001	-006-	00	12	21	2001	FACILITY NAME	DOCKET NUMBER
										05000
										05000

<b>OPERATING MODE (9)</b>	N	<b>THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)</b>									
<b>POWER LEVEL (10)</b>	000	20.2201(b)			20.2203(a)(2)(v)			50.73(a)(2)(i)		50.73(a)(2)(viii)	
		20.2203(a)(1)			20.2203(a)(3)(i)			50.73(a)(2)(ii)		50.73(a)(2)(x)	
		20.2203(a)(2)(i)			20.2203(a)(3)(ii)			50.73(a)(2)(iii)		73.71	
		20.2203(a)(2)(ii)			20.2203(a)(4)			50.73(a)(2)(iv)		OTHER -	
		20.2203(a)(2)(iii)			50.36(c)(1)			X		50.73(a)(2)(v)	
20.2203(a)(2)(iv)			50.36(c)(2)					50.73(a)(2)(vii)			

LICENSEE CONTACT FOR THIS LER (12)	
<b>NAME</b> Richard Louie, Licensing Engineer	<b>TELEPHONE NUMBER (Include Area Code)</b> (914) 734-5678

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
B	BI	PSX		N					

SUPPLEMENTAL REPORT EXPECTED (14)				EXPECTED SUBMISSION DATE (15)					
<b>YES</b>	(If yes, complete EXPECTED SUBMISSION DATE).			X	<b>NO</b>				

**ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)**

On October 29, 2001 during a scheduled mid-cycle maintenance outage, with the plant at cold shutdown conditions, a Service Water (EISS:BI) leak was observed inside containment located on the motor cooler outlet discharge piping from Fan Cooler (EISS:CLR) Unit No. 22. The source of the leakage was a hole (approximately 1/8 to 3/16 inch diameter) near a pipe-to-elbow weld on a two inch diameter, copper nickel Alloy 706 service water pipe, upstream of the containment penetration. No indication of leakage was detected prior to plant shutdown. At the time of discovery, this condition did not adversely impact Technical Specification requirements for containment integrity. The leak was corrected by the replacement of the elbow fitting in accordance with American Society of Mechanical Engineers (ASME) Section XI requirements prior to the plant's return to service from the outage. The root cause for this condition was excessive wear/erosion of the copper nickel material due to high, localized fluid flow rate (eddy currents) induced by the root pass weld extending into the flow path. Subsequent inspection of similarly susceptible service water piping was performed. They were found to be free of any measurable wall loss.

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENT IAL NUMBER	REVISI ON NUMBE	
Indian Point, Unit 2	05000247	2001	-006-	00	2 OF 4

**TEXT** (If more space is required, use additional copies of NRC Form 366A) (17)

PLANT AND SYSTEM IDENTIFICATION

Westinghouse 4-Loop Pressurized Water Reactor

EVENT IDENTIFICATION

Pipe Erosion Results In Service Water System Leakage In Containment

EVENT DATE

October 29, 2001

REFERENCES

Condition Reporting System Number(s): 200110417

PAST SIMILAR EVENTS

LER 95-14-00, and 91-12-00

EVENT DESCRIPTION

On October 29, 2001 during a scheduled mid-cycle maintenance outage, with the plant at cold shutdown conditions, a Service Water (EIIS:BI) leak was observed inside containment located on the motor cooler outlet discharge piping from Fan Cooler (EISS:CLR) Unit No. 22. The source of the leakage was a hole (approximately 1/8 to 3/16 inch diameter) near a pipe-to-elbow weld on a two inch diameter, copper nickel Alloy 706 service water pipe, upstream of the containment penetration. No indication of leakage was detected prior to plant shutdown. At the time of discovery, this condition did not adversely impact Technical Specification requirements for containment integrity. The leak was corrected by the replacement of the elbow fitting in accordance with American Society of Mechanical Engineers (ASME) Section XI requirements prior to the plant's return to service from the outage. The root cause for this condition was excessive wear/erosion of the copper nickel material due to high, localized fluid flow rate. Subsequent visual examination of the affected elbow fitting revealed that the root pass weld extended into the flow path. Inspections of similarly susceptible service water piping were performed. They were found to be free of any measurable wall loss.

**LICENSEE EVENT REPORT (LER)**  
**TEXT CONTINUATION**

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
Indian Point, Unit 2	05000247	YEAR	SEQUENT IAL NUMBER	REVISI ON NUMB	3 OF 4
		2001	-006	00	

**TEXT** (If more space is required, use additional copies of NRC Form 366A) (17)

EVENT ANALYSIS

The root cause for this condition has been attributed to excessive wear/erosion of the copper nickel material due to high, localized fluid flow rate. This was verified by subsequent visual examination of the affected elbow fitting. The excessive wear/erosion is attributed to localized eddy currents caused by the root pass weld extending into the flow path.

There were no structures, systems, or components that were inoperable immediately prior to the discovery of this condition that contributed to the event. All equipment functioned as designed prior to the discovery of this condition. This condition did not involve any personnel injury, radiation exposure, offsite dose release, or damage to equipment important to safety.

EVENT SAFETY SIGNIFICANCE

Because the containment fan cooler units are utilized for accident mitigation purposes, service water flow is not isolated following a design basis accident. All service water piping, to and from each of the five (5) containment fan cooler units is considered to be an extension of the containment boundary. Consequently, defects discovered within this piping may adversely affect containment integrity, and the ability to control the accidental release of radioactive materials. Based upon a 1/8 to 3/16 inch diameter hole, the estimated leakage rate would have exceeded the integrated leakage rate acceptance criteria (less than 1.0 La, where La is equal to 0.1 w/o per day of containment steam air atmosphere at 47 psig and 271F) identified in Technical Specification 4.4.A.2. However, at the time of its discovery, the plant was at cold shutdown conditions and Technical Specification requirements established for ensuring containment integrity were not necessary. An assessment of the UFSAR Chapter 14 Large Break LOCA design basis accident radiological consequences, and the additional dose from this leak was performed. Preliminary results indicate that the total effective dose equivalent (TEDE) limits of 10 CFR 50.67 would not have been exceeded. Therefore this condition has been determined to be of minimal safety significance. Should this conclusion be amended by the final assessment results, a supplement to this report will be provided. NRC notification pursuant to 10 CFR 50.72(b)(3)(v) was not required. Furthermore, the size (approximately 1/8 to 3/16 inch diameter) and physical location (fan cooler motor outlet discharge line) of the hole would not have affected the heat removal capability of Fan Cooler Unit No. 22. It has also been determined that this condition had no adverse affect on the structural integrity of the piping.

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENT IAL NUMBER	REVISI ON NUMB	
Indian Point, Unit 2	05000247	2001	-006	00	4 OF 4

**TEXT** (If more space is required, use additional copies of NRC Form 366A) (17)

CORRECTIVE ACTION

A like-in-kind replacement elbow was installed prior to the plant's return to service from the mid-cycle outage. Subsequent inspection of similarly susceptible service water piping was performed. They were found to be free of any measurable wall loss. No further corrective actions were deemed necessary.

PREVIOUS OCCURRENCES

A review of previous occurrences that involved the same underlying concern or reason as this event was performed. Two events were identified, and reported to the NRC in the following LERs:

LER 95-14-00: This LER reported that on May 18, 1995, during normal containment rounds, operations identified a leak of approximately 0.00026 gallons per minute on the weld for Fan Cooler Unit No. 22 service water discharge flow transmitter instrument line.

LER 91-012-00: This LER reported that on July 22, 1991, a pinhole leak was detected in the two inch service water system piping supplying cooling water to the motor of Fan Cooler Unit No. 23. Additionally it was reported that on August 1, 1991, a leak was observed on the return line from Fan Cooler Unit No. 24