

Beaver Valley Power Station Route 168 P.O. Box 4 Shippingport, PA 15077-0004

Lew W. Myers Senior Vice President 724-682-5234 Fax: 724-643-8069

December 21, 2001 L-01-154

Beaver Valley Power Station, Unit No. 1 Docket No. 50-334 License No. DPR-66 LER 2001-003-00

United States Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Licensee Event Report is submitted:

LER 2001-003-00, 10 CFR 50.73(a)(2)(iv), "Automatic Reactor Trip Due to Low Steam Generator Water Level."

Robert E. Donnellon FOR

Lew W. Myers

Attachment

JE24 Recido 18102 LER 2001-003-00 L-01-154 Page 2

CC: Mr. H. J. Miller, Regional Administrator
United States Nuclear Regulatory Commission
Region 1
475 Allendale Road
King of Prussia, PA 19406

Mr. L. J. Burkhart BVPS Project Manager United States Nuclear Regulatory Commission Washington, DC 20555

Mr. David M. Kern BVPS Senior Resident Inspector United States Nuclear Regulatory Commission

Mr. J. A. Hultz Ohio Edison Company 76 S. Main Street Akron, OH 44308

INPO Records Center 700 Galleria Parkway Atlanta, GA 30339-5957

Mr. L. E. Ryan
Bureau of Radiation Protection
Department of Environmental Protection
RCSOB-13th Floor
P.O. Box 8469
Harrisburg, PA 17105-8469

NRC FORM 366 (7-2001) U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)							APPROVED BY OMB NO. 3150-0104 Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to big Panc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.												
1. FACILITY NAME						2. DOC	2. DOCKET NUMBER 3. PAGE												
Beav	er Val	lley Powe	er Statio	on U	nit N	No. 1				05000334 1 of 4						4			
4. TITLI Auton		Reactor ⁻	Trip Du	e to		Steam G		ator W	ater Le	evel.									
	5. EV	ENT DATE			6.	LER NUMBER		7. F	REPORT	EPORT DATE 8. OTHER FACILITIES INVOL					NVOLVED				
МО		DAY	YEAR	YE	AR	SEQUENTIAL NUMBER	REV NO	МО	DAY	YEAR		CILITY NAME		DOCKET NUMBER					
11		06	2001	20	01	- 003 -	00	12	21	2001	FA	CILITY NAME		DOCKET NUMBER					
9. OPERATING 4					11. THIS REPO	ORT IS	SUBMIT	TED PU	RSUANT T	O TH	IE REQUIREME	ENTS OF 10	0 CFF	R§: (C	heck all tha	at apply)			
MODE		1		20.22	201(b)		20.2203	3(a)(3)(ii)			50.73(a)(2)(ii)(1	B)	5	50.73(a)(2)(ix)(A)				
10. POWER LEVEL		100 %		20.2201(d) 20			20.2203	.2203(a)(4)			50.73(a)(2)(iii)		50.73(a)(2)(x)						
		L	100 /6	Ш	20.22	0.2203(a)(1)		50.36(c	c)(1)(i)(A)		X 50.73(a)(2)(iv		(A)	7	73.71(a)(4)				
			20.22	203(a)(2)(i)		50.36(c)(1)(ii)(A)	1		50.73(a)(2)(v)(A)		73.71(a						
					20.22	203(a)(2)(ii)		50.36(c	3(c)(2)			50.73(a)(2)(v)(B) 50.73(a)(2)(v)(C)			OTHER Specify in Abstract below or in NRC Form 366A				
MA I							20.2203(a)(2)(iii)			50.46(a)(3)(ii)									
	7.7				K in the		20.22	203(a)(2)(iv)		50.73(a	a)(2)(i)(A)			50.73(a)(2)(v)(D)					
		5.727.74				203(a)(2)(v)	-)(2)(i)(B)			50.73(a)(2)(vii)							
		1000		\blacksquare		203(a)(2)(vi)		1)(2)(i)(C)			50.73(a)(2)(viii)	8		1	4			
32A V									a)(2)(ii)(A) 50.73(a)(2)(viii)(B) (CONTACT FOR THIS LER						100				
NAME							IZ. LIC	ENSEE	CONTAC	JI FUR IN		LEPHONE NUM	BER (Inclus	de Ar	rea Coc	le)			
	Cosgr	ove, Mai	nager F	legu	ılato	ry Affairs			(724) 682-5203										
		•					FOR F	ACH CO	MPONE	NT FAILUE	E D	ESCRIBED IN 1							
CAUSE SYSTEM				MANU- REP		PORTABLE O EPIX	404		SYSTEM CC		COMPONI	MANUE		MANU- CTURER	REPORTABLE TO EPIX				
×	(JB		-CV		W351		Yes	麓		T								
	14. SUPPLEMENTAL REPORT EXPECTED					****		15. EXPECTED			МС	NTH	DAY	YEAR					
YES (If yes, complete EXPECTED SUBMISSION DATE)						X N		SUBMISSION DATE						7100.00					

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

At 1416 hours on November 6, 2001, Beaver Valley Power Station Unit No. 1 reactor automatically tripped from 100% power due to low-low level in the C Steam Generator. The Feedwater Level Control Valve on the C Steam Generator unexpectedly failed closed causing the C Steam Generator water level to rapidly drop and reach the low-low water level reactor trip setpoint. Prior to the reactor trip, the Control Board Operator attempted to open the Feedwater Level Control Valve in manual control and observed no increase in the demand signal indicator or feedwater flow. After the reactor trip, Emergency Operating Procedure E-0 for Reactor Trip was performed and the plant was stabilized in Mode 3.

The automatic initiation of a reactor trip from 100% power via the Reactor Protection System on November 6, 2001, was a valid reactor trip and was not part of a pre-planned sequence during testing or reactor operation. Therefore this event is reportable pursuant to 10 CFR 50.72(b)(2)(iv)(B) and 50.73(a)(2)(iv)(A). The cause of the unexpected closure of the C Main Feedwater Regulating Valve was a random failure of a diode in the 7100 process rack module that controls the valve actuator. The safety significance of the automatic reactor trip on November 6, 2001 was small.

"NRC FORM 366A (1-2001)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)						
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER							
Beaver Valley Power Station Unit 1	05000334	2001	- 003 -	00	2	of	4				

PLANT AND SYSTEM IDENTIFICATION

Westinghouse-Pressurized Water Reactor System Feedwater/ Steam Generator Water Level Control System (JB)

CONDITIONS PRIOR TO OCCURRENCE

Unit 1: Mode 1 at 100 % power

There were no systems, structures, or components that were inoperable that contributed to the event. One system air compressor was out of service at the time.

DESCRIPTION OF EVENT

At 1416 hours on November 6, 2001, Beaver Valley Power Station Unit No. 1 reactor automatically tripped from 100% power due to low-low level in the C Steam Generator. The Feedwater Level Control Valve on the C Steam Generator unexpectedly failed closed causing the C Steam Generator water level to rapidly drop and reach the low-low water level reactor trip setpoint. Prior to the reactor trip, the Control Board Operator attempted to open the Feedwater Level Control Valve in manual control and observed no increase in the demand signal indicator or feedwater flow. After the reactor trip, Emergency Operating Procedure E-0 for Reactor Trip was performed and the plant was stabilized in Mode 3.

REPORTABILITY

The automatic initiation of a reactor trip from 100% power via the Reactor Protection System on November 6, 2001, was a valid reactor trip and was not part of a pre-planned sequence during testing or reactor operation. Therefore this event is reportable pursuant to 10 CFR 50.72(b)(2)(iv)(B) and 50.73(a)(2)(iv)(A). The NRC was notified that an automatic reactor trip occurred at BVPS Unit 1 pursuant to 10 CFR 50.72 (b)(2)(iv)(B) at 1538 hours on November 6, 2001 (ENS No. 38472).

CAUSE OF EVENT

The direct cause of the reactor trip was due to low-low level in the C Steam Generator, which was preceded by the unexpected closure of the C Main Feedwater Regulating Valve. Closure of the feedwater regulating valve resulted in a loss of feedwater flow to the C Steam Generator and the rapid decrease in steam generator water level.

The cause of the unexpected closure of the C Main Feedwater Regulating Valve was the failure of a diode in the 7100 process rack module that controls the valve actuator, causing the output of the Power Supply regulator board to rise from 35 volts to 51.55 volts. This higher voltage resulted in the output of the valve limiter to not rise above 3.8 milliamps. The control range is 4 to 20 milliamps. Since this limiter is common to both the manual and automatic control circuits and with the output

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	L	LER NUMBER (6)				PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER					
Beaver Valley Power Station Unit 1	05000334	2001	- 003 -	00	3	of	4		

limited to the 3.8 millamps value, the actuator would not respond to either Manual or Automatic control commands.

There was no evidence that voltage spikes or overheating were involved. In addition, the controller was replaced approximately one and one half years ago; therefore, age was not considered a factor. Thus, the diode failure was categorized as a random failure.

SAFETY IMPLICATIONS

Following the automatic reactor trip, the control rods fully inserted into the reactor core and the required safety systems operated as designed. Emergency Operating Procedure E-0 for Reactor Trip was performed and the plant was stabilized in Mode 3.

This event was an automatic reactor trip from full power, which is less severe than the design basis event for Loss of External Electrical Load and/or Turbine Trip from full power. The Loss of External Electrical Load and/or Turbine Trip is analyzed in BVPS Unit No. 1 UFSAR Section 14.1.7. Comparison of the UFSAR Loss of External Electrical Load and/or Turbine Trip with this event indicates that BVPS Unit 1 operated conservatively regarding the UFSAR transient in comparison to the UFSAR analysis assumptions/results. The actual plant response for this event was bounded by the UFSAR analysis for a Loss of External Electrical Load and/or Turbine Trip.

The plant risk associated with this BVPS Unit 1 automatic reactor trip on November 6, 2001 due to low steam generator water level is considered to be low. This is based on the conditional core damage probability for the event when considering the trip occurred during plant operation in Mode 1 at 100% reactor power given a partial loss of main feedwater with one system air compressor out of service.

Based on the above, the safety significance of the automatic reactor trip on November 6, 2001 was small.

CORRECTIVE ACTIONS

- 1. The deficiency in the Main Feedwater Regulating Valve FC-1FW-498 controller was corrected.
- 2. A failure analysis will be performed on the failed controller components for FC-1FW-498.
- 3. Additional enhancements are being investigated for 7100 module components, including power supplies and controllers.

Corrective action completion is being tracked through the corrective action program.

NRC FORM 366A (1-2001) U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)				PAGE (3)			
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER					
Beaver Valley Power Station Unit 1	05000334	2001	- 003 -	00	4	of	4		

PREVIOUS SIMILAR EVENTS

A review of past Beaver Valley Power Station Units 1 and 2 Licensee Event Reports found two similar events involving a reactor trip associated with steam generator water level within the last five years:

- BVPS Unit 1 LER 98-028, "Automatic Reactor Trip on 'A' Steam Generator Low Level Coincident with Steam Flow/Feed Flow Mismatch Signal from Manual Tripped Transmitter Bistables of F-MS-475."
- BVPS Unit 1 LER 97-025, "Ground in Feedwater Flow Controller Results in High Steam Generator Level and Subsequent Turbine Trip/Reactor Trip."