



Palo Verde Nuclear
Generating Station

William E. Ide
Vice President
Nuclear Production

TEL (623) 393-6116
FAX (623) 393-6077

10CFR50.73
Mail Station 7602
P.O. Box 52034
Phoenix, AZ 85072-2034

192-01103-WEI/SAB/REB
March 13, 2002

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, DC 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 3
Docket No. STN 50-530
License No. 74
Licensee Event Report 2002-001-00**

Attached please find Licensee Event Report (LER) 50-530/2002-001 -00 that has been prepared and submitted pursuant to 10CFR50.73. This LER reports a condition where Unit 3 operated with non-conservative values for the Core Operating Limit Supervisory System power operating limit margin circuit.

In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the NRC Regional Office, NRC Region IV and the Senior Resident Inspector. If you have questions regarding this submittal, please contact Daniel G. Marks, Section Leader, Regulatory Affairs, at (623) 393-6492.

Arizona Public Service Company makes no commitments in this letter.

Sincerely,

WEI/SAB/REB/kg
Attachment

cc: E. W. Merschoff (all with attachment)
J. H. Moorman
J. N. Donohew

A member of the **STARS** (Strategic Teaming and Resource Sharing) Alliance

Callaway • Comanche Peak • Diablo Canyon • Palo Verde • South Texas Project • Wolf Creek

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOF-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Palo Verde Nuclear Generating Station Unit 3	2. DOCKET NUMBER 05000530	3. PAGE 1 OF 4
---	-------------------------------------	--------------------------

4. TITLE
TS Violation Due To Incorrect Constant Entered In Core Operating Limit Supervisory System

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
01	16	2002	2002	001	00	03	13	2002	FACILITY NAME	DOCKET NUMBER

9. OPERATING MODE	1	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)							
			20.2201(b)	20.2203(a)(3)(ii)	50.73(a)(2)(ii)(B)	50.73(a)(2)(ix)(A)			
10. POWER LEVEL	99	20.2201(d)	20.2203(a)(4)	50.73(a)(2)(iii)	50.73(a)(2)(x)				
		20.2203(a)(1)	50.36(c)(1)(i)(A)	50.73(a)(2)(iv)(A)	73.71(a)(4)				
		20.2203(a)(2)(i)	50.36(c)(1)(ii)(A)	50.73(a)(2)(v)(A)	73.71(a)(5)				
		20.2203(a)(2)(ii)	50.36(c)(2)	50.73(a)(2)(v)(B)	OTHER Specify in Abstract below or in NRC Form 366A				
		20.2203(a)(2)(iii)	50.46(a)(3)(ii)	50.73(a)(2)(v)(C)					
		20.2203(a)(2)(iv)	50.73(a)(2)(i)(A)	50.73(a)(2)(v)(D)					
		20.2203(a)(2)(v)	X 50.73(a)(2)(ii)(B)	50.73(a)(2)(vii)					
		20.2203(a)(2)(vi)	50.73(a)(2)(i)(C)	50.73(a)(2)(viii)(A)					
20.2203(a)(3)(i)	50.73(a)(2)(ii)(A)	50.73(a)(2)(viii)(B)							

12. LICENSEE CONTACT FOR THIS LER

NAME Daniel G. Marks, Section Leader, Regulatory Affairs	TELEPHONE NUMBER (Include Area Code) 623-393-6492
---	--

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED				15. EXPECTED SUBMISSION DATE			
	YES (If yes, complete EXPECTED SUBMISSION DATE)	X	NO		MONTH	DAY	YEAR

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On January 16, 2002 at 1316 Mountain Standard Time, with Unit 3 operating in Mode 1, Power Operations, at approximately 99 percent power, reactor engineering personnel notified control room personnel that the core operating limit supervisory system (COLSS) had constants installed that were non-conservative. This error resulted in the COLSS power-operating limit for the departure from nucleate boiling ratio (DNBR) being non-conservative.

The error was caused by engineering personnel applying an incorrect adjustment when performing a manual calculation to support cycle 10 operation following the unit's 9th refueling outage that was completed on November 5, 2001.

Corrective action was taken to restore the COLSS constants. In addition, Units 1 and 2 were verified to have the correct constants installed.

No previous similar events have been reported in the last three years.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Palo Verde Nuclear Generating Station Unit 3	05000530	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 4
		2002	-- 001	-- 00	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

1. REPORTING REQUIREMENT(S):

This LER (50-530/2002-001-00) is being submitted pursuant to 10 CFR 50.73(a)(2)(i)(B), to report a condition that was prohibited by the plant's Technical Specifications (TS).

Specifically, Technical Specification (TS) Limiting Condition for Operation (LCO) 3.2.4, Departure From Nucleate Boiling Ratio (DNBR), requirements for operation without the core operating limit supervisory system (COLSS) (EIS:ID) inservice were not complied with.

2. DESCRIPTION OF STRUCTURE(S), SYSTEM(S) AND COMPONENT(S):

The core operating limit supervisory system is a digital computer-based on-line monitoring program used to provide information to aid the operator in complying with the technical specification operating limits on rated thermal power (total core power), linear heat rate (LHR), departure from nucleate boiling ratio (DNBR), axial shape index (ASI), and azimuthal power tilt. To do so, COLSS uses measurements of incore detector (EIS:IG) signals, control element assembly (EIS:AA) positions and plant thermal/hydraulic properties to determine the core power distribution and thermal performance. The COLSS indicates continuously to the operator, via the power operating limit (POL), how far the core is from the operating limits and provides an audible alarm when an operating limit is exceeded. Such a condition signifies a reduction in the capability of the plant to withstand an anticipated transient, but does not necessarily imply an immediate violation of fuel design limits. No trip functions are provided by this system.

The core protection calculators (CPC) (EIS:JC) also are capable of verifying that the LHR and DNBR do not exceed their limits. The CPCs perform this function by continuously calculating an actual value of DNBR and local power density for comparison with the respective trip setpoints. If power distribution or other parameters are perturbed, the high local power density or low DNBR trips in the reactor protection system (EIS:JC) initiate a reactor trip consistent with the safety analyses and UFSAR.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Palo Verde Nuclear Generating Station Unit 3	05000530	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 4
		2002	-- 001	-- 00	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

3. INITIAL PLANT CONDITIONS:

On January 16, 2002 Unit 3 was operating in Mode 1, Power Operation, at approximately 99 percent rated thermal power when a problem with the COLSS constants was identified to control room personnel. There were no structures, systems, or components that were inoperable that contributed to the condition.

4. EVENT DESCRIPTION:

On January 16, 2002, during the development of Unit 2 cycle 11 reload products, reload analysis personnel determined that there was a non-conservative error in COLSS DNBR Power Operating Limit (POL) calculation. Calculation RA-03-C10-2001-020 rev 0, Unit 3 Cycle 10 Master Setpoint Overall Uncertainty Analysis, incorrectly established the value for COLSS constants: EPOL2 = 0.03 and EPOL4 = 0.03. This error had been in place since the unit completed its 9th refueling outage on November 5, 2001.

Upon discovery of the error, reactor engineering personnel were notified who in turn notified Unit 3 control room personnel. On January 16, 2002 at 1316 MST, control room personnel declared COLSS inoperable. At 1325 MST control room personnel determined that linear heat rate (LHR) and DNBR were not within specified limits for COLSS out of service and Condition B of LCO 3.2.1 and 3.2.4 was entered. The constants were subsequently updated in COLSS and LCO 3.2.1 and 3.2.4 Condition B was exited at 1352 MST.

5. ASSESSMENT OF SAFETY CONSEQUENCES:

The error resulted in a COLSS DNBR calculated POL that was 4% higher (non-conservative) than it should have been. A review of the Unit 3 Cycle 10 core data determined that the minimum COLSS calculated POL was approximately 109 percent rated thermal power in early November of 2001. Reducing this value by 4% still yields an acceptable margin in COLSS. Therefore, no safety limits were exceeded. It should also be noted that this error did not impact the CPCs ability to generate a reactor trip signal when needed.

No automatically or manually initiated safety system actuations occurred and none were required. The condition would not have prevented the fulfillment of a safety function and the condition did not result in a safety system functional failure as defined by 10CFR50.73(a)(2)(v).

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Palo Verde Nuclear Generating Station Unit 3	05000530	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 4
		2002	-- 001	-- 00	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

6. CAUSE:

An investigation of this condition is being conducted in accordance with the corrective action program. The direct cause of the error in the EPOL2 and EPOL4 values was an error by the responsible engineer (utility, non-licensed) for the analysis in applying an incorrect correction adjustment in the hand calculation for these parameters in the U3C10 Master Setpoint Overall Uncertainty Analysis (RA-03-C10-2001-020, revision 0). This hand calculation was required because when the automated computer runs were performed the engineer used an incorrect COLSS database file. An experienced engineer applied corrections by hand rather than re-running the computer program, since the calculations to be done were simple. Our human performance error prevention tools failed to prevent an error in choosing an incorrect input constant in this case. The corrective action program has captured this error, and a thorough evaluation will be completed to identify where and why the error prevention barriers failed and to identify corrective actions needed to prevent recurrence.

7. CORRECTIVE ACTIONS:

As a transportability action, Units 1 and 2 were verified to have the correct values installed in COLSS for the EPOL 2 and EPOL4 constants.

In addition, the calculation for Unit 3 Cycle 10 Master Setpoints Overall Uncertainty Analysis (RA-03-C10-2001-020) was revised to correct the values for the EPOL2 and EPOL4 constants.

Upon completion of the investigation, other corrective action(s) will be implemented.

8. PREVIOUS SIMILAR EVENTS:

PVNGS has not reported any similar conditions in the last three years in which an incorrect value for a constant was installed in the COLSS or the CPCs that resulted in a TS violation.

9. ADDITIONAL INFORMATION:

None