

April 12, 2002

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Stop P1-137  
Washington, DC 20555-0001



ULNRC-04640

Gentlemen:

**DOCKET NUMBER 50-483  
CALLAWAY PLANT UNIT 1  
UNION ELECTRIC CO.  
FACILITY OPERATING LICENSE NPF-30  
LICENSEE EVENT REPORT 2002-005-00  
Inaccurate Steam Generator Low-Low Level setpoints due to Vendor Design  
Calculation error**

The enclosed licensee event report is submitted in accordance with 10CFR50.73(a)(2)(i)(B), 10CFR50.73(a)(2)(ii)(B), and 10CFR50.73(a)(2)(v)(A) to report inaccurate Steam Generator Low-Low Level trip setpoints due to errors in a Westinghouse design calculation.

A handwritten signature in black ink, appearing to read "John T. Patterson".

John T. Patterson  
Superintendent,  
Work Control, Mechanical

JTP/ewh

Enclosure

IE22

cc: Mr. Ellis W. Merschoff  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011-8064

Senior Resident Inspector  
Callaway Resident Office  
U.S. Nuclear Regulatory Commission  
8201 NRC Road  
Steedman, MO 65077

Mr. Jack N. Donohew (2 copies)  
Licensing Project Manager, Callaway Plant  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Mail Stop 7E1  
Washington, DC 20555-2738

Manager, Electric Department  
Missouri Public Service Commission  
PO Box 360  
Jefferson City, MO 65102

Mr. John O'Neill  
Shaw, Pittman, Potts & Trowbridge  
2300 N. Street N.W.  
Washington, DC 20037

Records Center  
Institute of Nuclear Power Operations  
700 Galleria Parkway  
Atlanta, GA 30339

Mr. Scott Bauer  
Regulatory Affairs  
Palo Verde Nuclear Generating Station  
P.O. Box 52034, Mail Station 7636  
Phoenix, AZ 85072-2034

Mr. Dennis Buschbaum  
Comanche Peak SES  
P.O. Box 1002  
Glen Rose, TX 76043

Mr. Scott Head  
Supervisor, Licensing  
South Texas Project NOC  
Mail Code N5014  
P.O. Box 289  
Wadsworth, TX 77483

Mr. Pat Nugent  
Supervisor, Licensing  
Pacific Gas & Electric  
Mail Stop 104/5/536  
P.O. Box 56  
Avila Beach, CA 93424

<b>NRC FORM 366</b> (7-2001)		<b>U.S. NUCLEAR REGULATORY COMMISSION</b>			<b>APPROVED BY OMB NO. 3150-0104</b>		<b>EXPIRES 7-31-2004</b>			
<b>LICENSEE EVENT REPORT (LER)</b>										
(See reverse for required number of digits/characters for each block)										
<b>1. FACILITY NAME</b> CALLAWAY PLANT UNIT 1					<b>2. DOCKET NUMBER</b> 05000 483			<b>3. PAGE</b> 1 OF 3		
<b>4. TITLE</b> Inaccurate Steam Generator Low-Low Level setpoints due to Westinghouse Design Calculation error.										
<b>5. EVENT DATE</b>			<b>6. LER NUMBER</b>			<b>7. REPORT DATE</b>			<b>8. OTHER FACILITIES INVOLVED</b>	
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
2	28	2002	2002	- 005 -	00	4	12	2002	FACILITY NAME	DOCKET NUMBER
<b>11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR '': (Check all that apply)</b>										
<b>9. OPERATING MODE</b>		20.2201(b)		20.2203(a)(3)(ii)		X		50.73(a)(2)(ii)(B)		50.73(a)(2)(ix)(A)
<b>10. POWER LEVEL</b>		20.2201(d)		20.2203(a)(4)				50.73(a)(2)(iii)		50.73(a)(2)(x)
		20.2203(a)(1)		50.36(c)(1)(i)(A)				50.73(a)(2)(iv)(A)		73.71(a)(4)
		20.2203(a)(2)(i)		50.36(c)(1)(ii)(A)		X		50.73(a)(2)(v)(A)		73.71(a)(5)
		20.2203(a)(2)(ii)		50.36(c)(2)				50.73(a)(2)(v)(B)		OTHER Specify in Abstract below or in NRC Form 366A
		20.2203(a)(2)(iii)		50.46(a)(3)(ii)				50.73(a)(2)(v)(C)		
		20.2203(a)(2)(iv)		50.73(a)(2)(i)(A)				50.73(a)(2)(v)(D)		
		20.2203(a)(2)(v)		X 50.73(a)(2)(i)(B)				50.73(a)(2)(vii)		
		20.2203(a)(2)(vi)		50.73(a)(2)(i)(C)				50.73(a)(2)(viii)(A)		
		20.2203(a)(3)(i)		50.73(a)(2)(ii)(A)				50.73(a)(2)(viii)(B)		
<b>12. LICENSEE CONTACT FOR THIS LER</b>										
NAME MARK A. REIDMEYER						TELEPHONE NUMBER (Include Area Code) (573) 676-4306				
<b>13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT</b>										
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	
<b>14. SUPPLEMENTAL REPORT EXPECTED</b>						<b>15. EXPECTED SUBMISSION DATE</b>		MONTH	DAY	YEAR
YES (if yes, complete EXPECTED SUBMISSION DATE)					X	NO				
<b>16. ABSTRACT</b> (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)										
<p>On 2/18/02, Callaway Plant received Westinghouse Letter SCP-02-14, which transmitted Nuclear Safety Advisory Letter (NSAL) 02-03. This NSAL addressed an error in the Westinghouse Steam Generator (S/G) water level setpoint analysis in which the pressure drop across a mid-deck plate internal to the S/G separator assembly was not accounted for in analysis calculations. This pressure drop adversely affected S/G low-low setpoint uncertainty calculations. On 2/28/02, Callaway staff engineers determined that this situation was applicable to Callaway with the S/G low-low setpoints being nonconservative and that the S/G Low-Low Trip function might not provide protection against a Main Feed Line Break (MFLB) inside Containment. A decision was made to reduce reactor power to approximately 30 percent and adjust the S/G Low-Low Trip setpoints to 21.6 percent narrow range level for normal containment environment and 27 percent narrow range level for adverse containment environment, which would satisfy the safety analysis requirements. Additional corrective actions included revision of plant procedures utilizing the S/G Low-Low Trip values.</p>										

**LICENSEE EVENT REPORT (LER)**

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Callaway Plant Unit 1	05000483	2002	- 005	- 00	2 OF 3

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

**I. DESCRIPTION OF THE REPORTABLE EVENT**

**A. REPORTABLE EVENT CLASSIFICATION**

This event is reportable under: (1) 10CFR50.73(a)(2)(i)(B), a condition prohibited by Technical Specifications, (2) 10CFR50.73(a)(2)(ii)(B), an unanalyzed condition, and (3) 10CFR50.73(a)(2)(v)(A), a condition that could have prevented fulfillment of a Safety Function to shutdown the reactor and maintain it in a safe shutdown condition.

**B. PLANT OPERATING CONDITIONS PRIOR TO THE EVENT**

On 2/28/02, Callaway Plant was in Mode 1 at 100 percent reactor power.

**C. STATUS OF STRUCTURES, SYSTEMS OR COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT**

After it was determined that the Westinghouse NSAL letter was applicable to Callaway, this rendered the portion of the Reactor Protection System responsible for a S/G Low-Low Level Trip, Inoperable.

**D. NARATIVE SUMMARY OF THE EVENT, INCLUDING DATES AND APPROXIMATE TIMES**

On 2/18/02, Callaway Plant received Westinghouse Letter SCP-02-14, which transmitted Nuclear Safety Advisory Letter (NSAL) 02-03. This NSAL addressed an error in the Westinghouse Steam Generator (S/G) water level setpoint analysis in which the pressure drop across a mid-deck plate internal to the S/G separator assembly was not accounted for in analysis calculations. This pressure drop adversely affected S/G low-low setpoint uncertainty calculations. Based upon a review of information provided by Westinghouse and Operating Event 13294 from Diablo Canyon regarding S/G Narrow Range Low-Low Level trips not responding as expected, an assessment was performed of the S/G Narrow Range (NR) Low-Low Level trip setpoints at Callaway.

On 2/28/02, this assessment determined that the Low-Low Level trip setpoint of 14.8 percent did not account for uncertainties associated with the differential pressure (dP) created by the steam flow past the mid-deck plate in the moisture separator section of the S/G. This dP phenomena would cause the S/G NR level channels to read higher than actual water level at high steam flow rates. Callaway staff engineers determined that this situation rendered the S/G low-low setpoints nonconservative. A decision was made to reduce reactor power to approximately 30 percent where engineering calculations indicated that the S/G mid-deck plate dP condition no longer resulted in non-conservative setpoints and then to adjust the S/G Low-Low Trip setpoints. The setpoints were reduced to 21.6 percent narrow range level for normal containment environment and 27 percent narrow range level for adverse containment environment, which would satisfy the safety analysis requirements. After the new S/G Narrow Range Low-Low Level Trip setpoints values were installed, reactor power was returned to 100 percent.

Additional corrective actions included revision of plant procedures utilizing the S/G Low-Low Trip values.

**E. METHOD OF DISCOVERY OF EACH COMPONENT, SYSTEM FAILURE, OR PROCEDURAL ERROR**

This problem was discovered after receiving Westinghouse NSAL 02-03.

**LICENSEE EVENT REPORT (LER)**

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Callaway Plant Unit 1	05000483	2002	- 005	- 00	3 OF 3

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

II. EVENT DRIVEN INFORMATION

A. SAFETY SYSTEMS THAT RESPONDED

Not applicable.

B. DURATION OF SAFETY SYSTEM INOPERABILITY

The RPS S/G Narrow Range Low-Low-Level Trip function was declared inoperable from 1625, 2/28/02, until 1354, 3/1/02 when all setpoints had been revised. The total inoperable time span was 21 hours, 29 minutes.

C. SAFETY CONSEQUENCES AND IMPLICATIONS OF THE EVENT.

The increase in Core Damage Frequency (delta CDF) determined for this issue, using values from the Callaway Probabilistic Risk Assessment (PRA) and conservative assumptions, is 4.4 E-7 per year.

III. CAUSE OF THE EVENT

The cause of the event was an error in design calculations as documented in Westinghouse NSAL 02-03.

IV. CORRECTIVE ACTIONS

Corrective actions consist of adjusting the S/G Narrow Range Low-Low Level Trip setpoints to new corrected values, revision of plant procedures that reference or utilize this setpoint, and revising plant specific calculations as necessary. Additionally, a revision to Callaway Plant Technical Specifications and Bases is being pursued.

V. PREVIOUS SIMILAR EVENTS

A search of Callaway Action Request System documents from 1999 until present, yielded 5 separate documents addressing NSAL issues involving S/G level accuracy concerns. They were CARs 200200503, 200201103, 200201157, 200201170, and 200201328. A similar review was conducted of LERs written at Callaway for the time frame of 1999 until present and there were no LERs involving NSAL S/G level accuracy issues.

VI. ADDITIONAL INFORMATION

The system and component codes listed below are from the IEEE Standard 805-1984 and IEEE Standard 803A-1984 respectively.

System: JG

Component: 94 RLY