CONDITION REP	NO.	1999	- 1300	P	age 1 of 17	
DESCRIPTION OF COND	DITION:					
Several filters from the CT Southwest Research Instil SRI, the analysis was con	IMT radiation monitors and tute (SRI) for analysis as p npleted on 7/29 with the fo	d a sample part of the l flowing res	rom the White Bird L RE4597AA/BA action sults:	used for CTM plan. Per tel	Fpressure reli icon with Dr. F	eases were sent ic Richard Page of
The RE 4597BA filter from There was also some most corrosion.	7/3/99 centained primaril asurable Chlorine. The Iro	ly Iron Oxid In Oxide pa	de (10-100 microns wi articles had a granular	th some smal appeance in	er particles do dicating the so	own to 1 micron). surce is from
The RE 4597BA filter from sample from the white bird to be a large quantity of Bo	n 7/9/99 also had three dan 1 filter also contained iron (oron on the filter to delect	rker spots o oxide. No i it. SRI will	on it which were analy Boron was detected, I I send a written report	zed to contair however, Dr. 1 by next Frida	n potassium ai Page indicated y.	nd chlorine. A I there would have
				· · · · · · · · · · · · · · · · · · ·		Continue
INITIATOR (print)	SIGNATURE	/	ORGANIZATION		PHONE NO. 8406	MAIL STOP
ROUGH C. FIOVERIO		Structure .				
REVIEW INCLUDING AC	TIONS TAKEN / RECOM	MENDATIC	ONS:			
1	· · · ·	a		the BE45074		
TM 99-0022 has been initia activities are recommende	ated to reduce the iron oxi d to determine the source	of the iron	ci M (atmosphere per oxide.			
TM 99-0022 has been initia activities are recommended NCAQ - RECOMMENT SUPERVISOR (print)	DED N/A	PLANT O	PERATIONS	PHONE N	D. MAIL STO	Continued DATE
TM 99-0022 has been initia activities are recommender	DED IN/A	PLANT O	PERATIONS	PHONE NO 8406	 MAIL STO 1058 	Continued DATE 7/30/99
TM 99-0022 has been initia activities are recommended NCAQ - RECOMMENT SUPERVISOR (print) Robert C. Hovland REPORTABILITY 1 HR 4 HR 24 HR	ated to reduce the iron bxi d to determine the source DED IN/A SIGNATURE D.c. Gerson R Z N/A	PLANT O ORG SYS	PERATIONS SANIZATION C OPERABLE	PHONE N 8406). MAIL STO 1058	Continued DATE 7/30/99 NON TECH SPEC.
TM 99-0022 has been initia activities are recommended DNCAQ - RECOMMENT SUPERVISOR (print) Robert C. Hovland REPORTABILITY 1 HR 4 HR 24 HI ACTIONS TAKEN / COMM	ated to reduce the iron bxi d to determine the source DED IN/A SIGNATURE B. D. C. Gerson R Z. N/A HENTS:	PLANT O ORG SYS	PERATIONS SANIZATION COPERABLE	PHONE N 8406). MAIL STO 1058 MAIL STO	Continued P DATE 7/30/99 NON TECH SPEC.
TM 99-0022 has been initia activities are recommended UNCAQ - RECOMMENT SUPERVISOR (print) Robert C. Hovland REPORTABILITY 1 HR 4 HR 24 HR ACTIONS TAKEN / COMM	DED IN/A SIGNATURE R DS N/A HENTS: thons taken at	PLANT O ORG SYS	PPERATIONS SANIZATION SC OPERABLE		D. MAIL STO 1058	Continued P DATE 7/30/99
TM 99-0022 has been initia activities are recommended UNCAQ - RECOMMENT SUPERVISOR (print) Robert C. Hovland REPORTABILITY 1 HR 4 HR 24 HI ACTIONS TAKEN / COMM	DED IN/A SIGNATURE R DENVA R DENVA	PLANT O ORG SYS	PERATIONS ANIZATION C OPERABLE). MAIL STO 1058	Continued P DATE 7/30/99 NON TECH SPEC.
TM 99-0022 has been initia activities are recommended UNCAQ - RECOMMENT SUPERVISOR (print) Robert C. Hovland REPORTABILITY 1 HR 4 HR 24 HT ACTIONS TAKEN / COMM	ated to reduce the iron oxi d to determine the source DED IN/A SIGNATURE R DE N/A IENTS: trans taken at	PLANT O ORG SYS	PERATIONS SANIZATION C OPERABLE		D. MAIL STO 1058	Continued P DATE 7/30/99 ION TECH SPEC.
TM 99-0022 has been initia activities are recommended UNCAQ - RECOMMENT SUPERVISOR (print) Robert C. Hovland REPORTABILITY 1 HR 4 HR 24 HR ACTIONS TAKEN / COMM See ac	DED IN/A SIGNATURE R DS N/A HENTS: thons taken at	PLANT O ORG SYS	DATE		D. MAIL STO 1058	Continued
TM 99-0022 has been initia activities are recommended UNCAQ - RECOMMENT SUPERVISOR (print) Robert C. Hovland REPORTABILITY 1 HR 4 HR 24 HI ACTIONS TAKEN / COMM See. ac	DED IN/A SIGNATURE R DE N/A HENTS: trans taken at	PLANT O ORG SYS	DATE	PHONE N 8408	D. MAIL STO 1058	Continued P DATE 7/30/99 NON TECH SPEC.
TM 99-0022 has been initia activities are recommended SUPERVISOR (print) Robert C. Hovland REPORTABILITY 1 HR 4 HR 24 HI ACTIONS TAKEN / COMM See. ac SIGNATURE	DED IN/A SIGNATURE R DEN Carson R DEN N/A HENTS: trans taken at	PLANT O ORG SYS	DATE		D. MAIL STO 1058 [] M [] M [] M [] M [] M [] M	Continued P DATE 7/30/99 NON TECH SPEC.
TM 99-0022 has been initia activities are recommended SUPERVISOR (prini) Robert C. Hovland REPORTABILITY 1 HR 4 HR 24 HI ACTIONS TAKEN / COMM See ac SIGNATURE CATEGORY To On that	DED IN/A SIGNATURE R DE N/A HENTS: thons taken at Manual SUCHARE SUCHARE SYSC	PLANT O ORG SYS	DATE	PHONE NO 8406	D. MAIL STO 1058 TIME 160 E DETERMINA DA G A	Continued P DATE 7/30/99 NON TECH SPEC.
TM 99-0022 has been initia activities are recommended SUPERVISOR (prini) Robert C. Hovland REPORTABILITY 1 HR 4 HR 24 HI ACTIONS TAKEN / COMM See ac SIGNATURE CATEGORY T_M_POTTAT	DED IN/A SIGNATURE R DS N/A HENTS: thons taken at Manual SYSC PERIENCE REVIEW TPR	PLANT O ORG SYS	DATE 7/30/99 DATE 000 DATE 000 DATE		D. MAIL STO 1058 TIME 160 E DETERMINA QL (C A) REVIEWS	Continued P DATE 7/30/99 NON TECH SPEC.

Â,

ź

÷

· · · · · · · · · · · · · · · · · · ·		NO. 1999-1300	
CONDEDON REPORT			
Problem Statement::			
The performance of the Cont flow conditions. The cause o primarily an Iron oxide powde	ainment Rediation (if the low sample flo ar but the source is	Monitors, RE4597AA and RE4597BA by Is due to a buildup of material on t unknown.	has degraded due to repetitive low samp he particulate filters. The particulate matte
Apparent Cause:			
A radiation monitor action pla material, and analyze the par matter that is huilding up on t be primarily an iron oxide (Se	n was completed to ticulate matter on the he filters. The mate attached report S	o check the RE4597AA/BA skid perfo he filters. The results indicate the lov arial was sent to Southwest Research SwRI Project No. 18-2321-190). Som	rmance, inspect sample lines, check filter v flow conditions are due to the particulate h institute for analysis and was determine the possible sources of the iron oxide include
1. Containment Air Cooler ac	tivities during the m	hid-cycle outage including the CAC N	o. 1 motor replacement and decon activity
2. CR 1999-0275 identified a	ondensation on Ser	vice Water piping dripping onto and i	rusting the conduit below (585' above CA
While the exact source of the (5/10/99) after the mid-cycle (required the alignment of CTI RE4597BA had a low flow also	rust is not known, i outage. The CAC r MT Purge to the Me arm on 5/13/99. Sul	the high particulate problem develop notors were started on 5/4/99 and the schanical Penetration Rooms. RE 45 bsequent filter changes were required	ed about the same time as the Plant Start e Plant entered Mode 4 on 5/7/99 which 97AA had a low flow alarm on 5/10/99 and d every 24-48 hours.
Remedial Actions:			
Temporary Modification 99-00 reduce the particulate concern	022 installed four po ntration.	ortable HEPA filtration units in contain	nment on 8/10/99 per WO 99-005029-000
The MRC assigned CATS Ite	m #1 to SYSC to de	etermine if an OE should be issued. of particulate problem. CATS Item #3	SYSC will use the Nuclear Network to ask
industry if they have experien	iceo a similar type c	parate protection of the second	•
industry if they have experien CATPR: 1. Plant Engineering will issu activities for rust removal CA & Arriver out des dernwe	iceo a similar type of the an Action Plan fo TS Item #2. Pcon	ar 12RFO which will include CTMT wa ar Engline Excision of 477 (1814) Entett and Made Lecium #	alkdowns to identify possible sources and CAPEATS FROM SMEETIN KLUD CAPEATS FROM SMEETING Killing Joyng
industry if they have experien CATPR: 1. Plant Engineering will issu activities for rust removal CAT to drawers even dernwa	iceo a similar type o ie an Action Plan fo TS Item #2. Prov For Chinacena	n 12RFO which will include CTMT wa n Engine Erinde & 4771.181.46 Entett and Mark Lecint	alkdowns to identify possible sources and ELEERS FROM STREETS PLUE ELEENS Killingthy
Industry if they have experien CATPR: 1. Plant Engineering will issu activities for rust removal CAT for for year derived	iceo a similar type o ie an Action Plan fo TS Item #2. Puen Fou Computer	SYSTEM CAPABLE OF PERFOR	Ikdowns to identify possible sources and Excess from Smearr Hund were source. Willing Specified FUNCTION?
Industry if they have experien CATPR: 1. Plant Engineering will issu activities for rust removal CAT # drovers eve dernws 10 CFR PART 21?	YES X NO	SYSTEM CAPABLE OF PERFOR	Ikdowns to identify possible sources and EARENT FROM SMEETER FLOOR CARENT FROM SMEETER FLOOR CONTRACTION? N/A
Industry if they have experien CATPR: 1. Plant Engineering will issu activities for rust removal CAT # Arvers and Arrives 10 CFR PART 217	YES NO	SYSTEM CAPABLE OF PERFOR SIGNATURE SIGNATURE	Contential Contential Contential Content of
Industry if they have experien CATPR: 1. Plant Engineering will issu activities for rust removal CA? # druess eve dernws 10 CFR PART 21? PREPARER (Print) Robert C. Hovland SUPERVISOR COSTROVAL (SUPERVISOR Electrical/Con	Print)	SYSTEM CAPABLE OF PERFOR SIGNATURE SIGNATURE	ELEVENTS to identify possible sources and ELEVENTS FROM SMEETER FLOW WING SPECIFIED FUNCTION? N/A DATE 9/23/99 DATE 9/24/99
Industry if they have experien CATPR: 1. Plant Engineering will issue activities for rust removal CAT # Arvies and Arrives 10 CFR PART 217 PREPARER (Print) Robert C. Hovland SUPERVISO COSSICOVAL (Supervisor-Electrical/Con MANAGER APPROVAL (Print) 10 CFR PART 217	Print)	SYSTEM CAPABLE OF PERFOR SYSTEM CAPABLE OF PERFOR SIGNATURE	Contections to identify possible sources and CAPEARS FROM SMEANS FLUME CAPEARS FROM SMEANS FLUME Contections Contections Contections NA DATE 9/23/99 DATE 9/24/99 DATE 9/27/99
Industry if they have experien CATPR: 1. Plant Engineering will issue activities for rust removal CAT the drawer and derrives 10 CFR PART 217 PREPARER (Print) Robert C. Hovland SUPERVISO: Electrical/Com Supervisor-Electrical/Com MANAGER APPROVAL (Print) SRB APPROVAL (Print)	Print)	SYSTEM CAPABLE OF PERFOR SYSTEM CAPABLE OF PERFOR SIGNATURE SIGNATURE SIGNATURE SIGNATURE SIGNATURE SIGNATURE SIGNATURE SIGNATURE SIGNATURE	Ikdowns to identify possible sources and EARENT FROM STREETT FLOOR WING SPECIFIED FUNCTION? NA DATE 9/23/99 DATE 9/27/114 DATE 9/27/114 DATE

~

ŧ

÷.

[4276]

ł

C ANKERS

it was the set

ANALYSIS OF FILTER DEPOSITS

Final Report \$wRI Project No. 18-2321-190

Prepared for

The Toledo Edison Company Davis-Besse Plant 5501 North State Route 2 Oak Harbor, OH 43449

Prepared by

Richard A. Page

August 1999



SOUTHWEST RESEARCH INSTITUTE

ANALYSIS OF FILTER DEPOSITS

Final Report SwRI Project No. 18-2321-190

Prepared for

The Toledo Edison Company Davis-Besse Plant 5501 North State Route 2 Oak Harbor, OH 43449

Prepared by

Richard A. Page

August 1999

APPROVED James Lankford, Jr., Director

Materials Engineering Department

An EDS spectrum from an overall area of deposit on filter 4597BA 7/9/99@2016, Figure 6, was essentially identical to those obtained from filter 4597BA 7/3/99@1400. Spectra were also obtained from two of the dark particles on the filter, Figures 7 and 8. These particles were different from the overall deposit in that the iron peaks were reduced and high potassium and chlorine peaks were present.

EDS spectra were also obtained from an overall area, Figure 9, and on an isolated particle Figure 10, on filter 7/16/99 White Bird. It is evident from these spectra that the deposits on the filter were also predominately iron oxide.

Imaging of the as-teceived filters in the SEM was limited by the low conductivity of the filter medium. To overcome this impediment, a gold palladium coating was applied to one of the filter samples, 4597BA 7/3/99@1400, following the EDS measurements. Electron micrographs obtained from the coated filter sample are shown in Figures 11 and 12. The deposits were generally less that 50µm in size and exhibited a very powdery appearance.

4.0 CONCLUSIONS

The following conclusions have been drawn from the results obtained in this investigation.

- 1. The uniform beige deposit that was present on the six 2¼ inch diameter filter samples was a powdery iron oxide. Small amounts of chlorine and copper were present in the deposit.
- 2. Large potassium chloride containing particles were present on one of the filters.
- 3. The deposits present on the 1¾ inch diameter filter were also primarily iron oxide.
- 4. Neither the shape nor the chemistry of the deposits is consistent with a Magnaflux powder origin. Titanium, a major constituent of the Magnaflux powder, was not detected on any of the filters examined, and the powdery morphology of the deposits was not at all similar to the larger angular Magnaflux powder.
- 5. The iron oxide deposits are likely corrosion products from an iron base component within the system.





[4280]

 $\{ (x_i,y_i) \in \{x_i\} \} \in \{x_i\}$



Ą 281]



2]





, .

•••

CR1999-11-06/7

Figure 6. EDS spectrum from an overall area of deposits on filter 4597BA 7/9/99@2016.

4284]

-

M. H. H. L.





EDS spectrum from a single dark particle on filter 4597BA 7/9/99@2016. Figure 7.

Þ N α ഗ്

and the state of the



õ

.... -

[4286]



and a first of the state of the

1e 1# 00

いい

JQ.

Đ

=

[428 71

·. ·. .





a and the fight

1996年である。1999年にはあ

[4 288]





97614 (a)



Figure 11. Scanning electron micrographs of an area of deposits on filter 4597BA 7/3/99@1400 following application of a gold/palladuim coating.

·自由6.还常的。"伊切林把导出中

CR1999-1300 Poge 170617





Figure 12. Scanning electron micrographs of a second area of deposits on filter 4597BA 7/3/99@1400 following application of a gold/palladium coating.

RECORD END SHEET

END OF RECORD

[4291]

The Barry and the start the second

3. BAR

.