

Exelon Generation Company, LLC
Quad Cities Nuclear Power Station
22710 206th Avenue North
Cordova, IL 61242-9740

www.exeloncorp.com

Nuclear

May 22, 2002

SVP-02-045

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Quad Cities Nuclear Power Station, Unit 2
Facility Operating License No. DPR-30
NRC Docket No. 50-265

Subject: Licensee Event Report 265/02-001, "High Pressure Coolant Injection System
Uncoupled above 150 psig due to Misapplication of Technical Specifications"

Enclosed is Licensee Event Report (LER) 265/02-001, "High Pressure Coolant Injection
System Uncoupled above 150 psig due to Misapplication of Technical Specifications," for
Quad Cities Nuclear Power Station.

This report is submitted in accordance with the requirements of the Code of Federal
Regulations, Title 10, Part 50.73(a)(2)(i)(B), which requires reporting of any operation or
condition prohibited by the plant's Technical Specifications, and Part 50.73(a)(2)(v)(D), which
requires reporting of any event or condition that alone could have prevented the fulfillment of
the safety function of structures or systems that are needed to mitigate the consequences of
an accident.

We are committing to the following actions:

Training will be implemented on Technical Specification sections 1.0 (Use and
Application) and 3.0 (LCO Applicability), including the lessons learned from this
event, to reinforce that Technical Specifications (TS) are always to be applied as
written.

The reactor startup procedure will be revised to include guidance to verify and
document operability prior to entry into non-Mode TS conditions of applicability.

Any other actions described in the submittal represent intended or planned actions by Exelon
Generation Company (EGC), LLC. They are described for the NRC's information and are
not regulatory commitments.

IE22

May 22, 2002
U.S. Nuclear Regulatory Commission
Page 2

Should you have any questions concerning this report, please contact Mr. W. J. Beck at (309) 227-2800.

Respectfully,

A handwritten signature in black ink, appearing to read 'T. Tulon', with a long horizontal flourish extending to the right.

Timothy J. Tulon
Site Vice President
Quad Cities Nuclear Power Station

cc: Regional Administrator – NRC Region III
NRC Senior Resident Inspector – Quad Cities Nuclear Power Station

NRC FORM 366 (7-2001)			U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OMB NO. 3150-0104 EXPIRES 7-31-2004 Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.						
LICENSEE EVENT REPORT (LER)												
1. FACILITY NAME Quad Cities Nuclear Power Station Unit 2					2. DOCKET NUMBER 05000265			3. PAGE 1 of 4				
4. TITLE High Pressure Coolant Injection System Uncoupled above 150 psig due to Misapplication of Technical Specifications												
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED			
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER		
03	04	02	02	- 001 - 00		05	22	02	N/A	N/A		
9. OPERATING MODE		2		11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)								
10. POWER LEVEL		005		20.2201(b)		20.2203(a)(3)(ii)		50.73(a)(2)(ii)(B)		50.73(a)(2)(ix)(A)		
				20.2201(d)		20.2203(a)(4)		50.73(a)(2)(iii)		50.73(a)(2)(x)		
				20.2203(a)(1)		50.36(c)(1)(i)(A)		50.73(a)(2)(iv)(A)		73.71(a)(4)		
				20.2203(a)(2)(i)		50.36(c)(1)(ii)(A)		50.73(a)(2)(v)(A)		73.71(a)(5)		
				20.2203(a)(2)(ii)		50.36(c)(2)		50.73(a)(2)(v)(B)		OTHER Specify in Abstract below or in NRC Form 366A		
				20.2203(a)(2)(iii)		50.46(a)(3)(ii)		50.73(a)(2)(v)(C)				
				20.2203(a)(2)(iv)		50.73(a)(2)(i)(A)		<input checked="" type="checkbox"/> 50.73(a)(2)(v)(D)				
				20.2203(a)(2)(v)		<input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)		50.73(a)(2)(vii)				
				20.2203(a)(2)(vi)		50.73(a)(2)(i)(C)		50.73(a)(2)(viii)(A)				
				20.2203(a)(3)(i)		50.73(a)(2)(ii)(A)		50.73(a)(2)(viii)(B)				
12. LICENSEE CONTACT FOR THIS LER												
NAME Wally Beck, Regulatory Assurance Manager								TELEPHONE NUMBER (Include Area Code) (309) 227-2800				
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT												
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX			
14. SUPPLEMENTAL REPORT EXPECTED								15. EXPECTED SUBMISSION DATE		MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE)								<input checked="" type="checkbox"/> NO				

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On March 4, 2002, at 1255 hours during a reactor startup, Unit 2 reactor pressure was increased above 150 psig with the High Pressure Coolant Injection turbine uncoupled from the pump. This put the unit in Technical Specification (TS) 3.5.1, condition F. This is a violation of TS 3.0.4, which does not allow entry into a specified condition of applicability while a Limiting Condition for Operation is not met. HPCI was subsequently recoupled.

The root cause of this event was that licensed personnel misapplied TS 3.5.1. As a contributing cause, the reactor startup procedural guidance was inadequate to ensure operable status of TS-required equipment when non-Mode conditions of applicability were entered.

Corrective actions include changes to the reactor startup procedure and training concerning application of TS.

The safety significance of this event was minimal. Reactor pressure did not get above approximately 160 psig until HPCI was recoupled, and the Reactor Core Isolation Cooling and Automatic Depressurization systems, as well as the low-pressure Emergency Core Cooling systems, were available throughout the event.

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	YEAR	LER NUMBER (6) SEQUENTIAL NUMBER	REVISION NUMBER	PAGE (3)
Quad Cities Nuclear Power Station Unit 2	05000265	2002	001	00	2 of 4

(If more space is required, use additional copies of NRC Form 366A)(17)

PLANT AND SYSTEM IDENTIFICATION

General Electric - Boiling Water Reactor, 2957 Megawatts Thermal Rated Core Power

Energy Industry Identification System (EIIS) codes are identified in the text as [XX].

EVENT IDENTIFICATION

High Pressure Coolant Injection System Uncoupled above 150 psig due to Misapplication of Technical Specifications

A. CONDITION PRIOR TO EVENT

Unit: 2 Event Date: March 4, 2002 Event Time: 1255 hours
Reactor Mode: 2 Mode Name: Startup Power Level: 005%

Startup (2) - Mode switch in Startup/Hot Standby position (or in Refuel position with all reactor vessel head closure bolts fully tensioned) with average reactor coolant temperature at any temperature.

B. DESCRIPTION OF EVENT

On March 4, 2002, at 0346 hours, Unit 2 entered Mode 2 for the startup from the 16th Unit 2 refueling outage (Q2R16). Overspeed testing on the High Pressure Coolant Injection (HPCI) [BJ] system was required due to work that had been conducted on the HPCI System. At 1145 hours preparations for the Unit 2 HPCI system turbine [TRB] overspeed test were started. At 1200 hours Mechanical Maintenance workers started to uncouple the turbine for testing and by 1235 the turbine uncoupling was completed. The overspeed test was performed by approximately 1245 hours, verifying that the HPCI turbine tripped in accordance with the acceptance criteria.

At that time, the Nuclear Shift Operator (NSO) initialed the reactor startup procedure to signify completion of the HPCI overspeed test. The reactor startup procedure was worded such that the reactor startup could continue and pressure could be raised above 150 psig after the HPCI overspeed test was performed, without mention of whether the HPCI turbine was coupled or not. Once the satisfactory results were received for the overspeed test, the NSO started raising pressure above 150 psig in accordance with the procedure.

At 1255, reactor pressure reached 150 psig and HPCI was declared inoperable. The NSO documented that Technical Specification (TS) 3.5.1, Condition F, which requires restoration of the HPCI system to operable status within 14 days, was entered.

TS 3.5.1 requires HPCI to be operable prior to exceeding 150 psig. The HPCI TS applicability is Modes 1, 2 & 3, with reactor steam dome pressure greater than 150 psig. The surveillance requirement for the low pressure HPCI test has a note that states that the surveillance is not required to be performed until 12 hours after reactor steam pressure and flow are adequate to perform the test.

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Quad Cities Nuclear Power Station Unit 2	05000265	2002	001	00	3 of 4

(If more space is required, use additional copies of NRC Form 366A)(17)

Raising pressure above 150 psig with HPCI uncoupled is incompatible with TS LCO 3.0.4 that states:

When an LCO is not met, entry into a MODE or other specified condition in the Applicability shall not be made except when the associated ACTIONS to be entered permit continued operation in the MODE or other specified condition in the Applicability for an unlimited period of time. This Specification shall not prevent changes in MODES or other specified conditions in the Applicability that are required to comply with ACTIONS or that are part of a shutdown of the unit.

In this case, the "other specified condition" was having reactor pressure above 150 psig. Entering this condition with HPCI not operable is not allowed by TS 3.0.4.

At 1300 hours, reactor pressure was raised to 160 psig, where it remained until after 1520 hours. At 1315 hours, preparations for recoupling the HPCI turbine were started. By 1520 hours, the HPCI turbine was recoupled and TS 3.0.4 was met.

On March 27, 2002, this event was discovered during a review of the operator logs associated with the startup process for Q2R16.

C. CAUSE OF EVENT

The root cause of this event was that licensed personnel misapplied TS 3.5.1 and did not consider TS 3.0.4 and its application.

As a contributing cause, the reactor startup procedural guidance was inadequate to ensure operable status of TS-required equipment when non-Mode conditions of applicability were entered.

D. SAFETY ANALYSIS

The safety significance of this event was minimal. Reactor pressure was held at about 160 psig until after HPCI was recoupled. Also, the low-pressure Emergency Core Cooling systems were available throughout this event, as were the Reactor Core Injection Cooling system and the Automatic Depressurization system.

E. CORRECTIVE ACTIONS

Corrective Actions to be Completed:

Training will be implemented on Technical Specification sections 1.0 (Use and Application) and 3.0 (LCO Applicability), including the lessons learned from this event, to reinforce that TS are always to be applied as written.

The reactor startup procedure will be revised to include guidance to verify and document operability prior to entry into non-Mode TS conditions of applicability.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
Quad Cities Nuclear Power Station Unit 2	05000265	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
		2002	001	00	4 of 4

(If more space is required, use additional copies of NRC Form 366A)(17)

F. PREVIOUS OCCURRENCES

No previous occurrences during the previous two years were identified involving a misapplication of TS by licensed personnel.

G. COMPONENT FAILURE DATA

There were no component failures associated with this event.