

May 23, 2002

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Stop P1-137
Washington, DC 20555-0001

ULNRC-04669

Gentlemen:



**DOCKET NUMBER 50-483
UNION ELECTRIC CO.
LICENSEE EVENT REPORT 2002-007-00
Violation of Interim Security Measures**

The enclosed Licensee Event Report is submitted in accordance with 10CFR73.71 to report a violation of security measures instituted to comply with the Order for Interim Safeguards and Security Compensatory Measures issued 2/25/02.

A handwritten signature in cursive script that reads "Warren A. Witt".

Warren A. Witt
Manager,
Callaway Plant

WAW/ewh

Enclosure

IE74

ULNRC04669

May 23, 2002

Page 2

cc: Mr. Ellis W. Merschoff
Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

Senior Resident Inspector
Callaway Resident Office
U.S. Nuclear Regulatory Commission
8201 NRC Road
Steedman, MO 65077

Mr. Jack N. Donohew (2 copies)
Licensing Project Manager, Callaway Plant
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Mail Stop 7E1
Washington, DC 20555-2738

Manager, Electric Department
Missouri Public Service Commission
PO Box 360
Jefferson City, MO 65102

Mr. John O'Neill
Shaw, Pittman, Potts & Trowbridge
2300 N. Street N.W.
Washington, DC 20037

Records Center
Institute of Nuclear Power Operations
700 Galleria Parkway
Atlanta, GA 30339

Mr. Scott Bauer
Regulatory Affairs
Palo Verde NGS
P. O. Box 52034, Mail Station 7636
Phoenix, AZ 85072-2034

Mr. Scott Head
Supervisor, Licensing
South Texas Project NOC
Mail Code N5014
P.O. Box 289
Wadsworth, TX 77483

Mr. Dennis Buschbaum
Comanche Peak SES
P.O. Box 1002
Glen Rose, TX 76043

Mr. Pat Nugent
Supervisor, Licensing
Pacific Gas & Electric
Mail Stop 104/5/536
P.O. Box 56
Avila Beach, CA 93424

LICENSEE EVENT REPORT (LER)

(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

CALLAWAY PLANT UNIT 1

2. DOCKET NUMBER

05000 483

3. PAGE

1 OF 3

4. TITLE

Violation of Site Security Plan due to Inclement Weather

5. EVENT DATE

6. LER NUMBER

7. REPORT DATE

8. OTHER FACILITIES INVOLVED

MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
4	27	2002	2002	- 007 - 00		5	23	2002	FACILITY NAME	DOCKET NUMBER
										05000
									FACILITY NAME	DOCKET NUMBER
										05000

9. OPERATING
MODE

1

10. POWER
LEVEL

100

11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 101.11 (Check all that apply)

20.2201(b)	20.2203(a)(3)(ii)	50.73(a)(2)(ii)(B)	50.73(a)(2)(ix)(A)
20.2201(d)	20.2203(a)(4)	50.73(a)(2)(iii)	50.73(a)(2)(x)
20.2203(a)(1)	50.36(c)(1)(i)(A)	50.73(a)(2)(iv)(A)	X 73.71(a)(4)
20.2203(a)(2)(i)	50.36(c)(1)(ii)(A)	50.73(a)(2)(v)(A)	73.71(a)(5)
20.2203(a)(2)(ii)	50.36(c)(2)	50.73(a)(2)(v)(B)	OTHER
20.2203(a)(2)(iii)	50.46(a)(3)(ii)	50.73(a)(2)(v)(C)	Specify in Abstract below or in
20.2203(a)(2)(iv)	50.73(a)(2)(i)(A)	50.73(a)(2)(v)(D)	NRC Form 366A
20.2203(a)(2)(v)	50.73(a)(2)(i)(B)	50.73(a)(2)(vii)	
20.2203(a)(2)(vi)	50.73(a)(2)(i)(C)	50.73(a)(2)(viii)(A)	
20.2203(a)(3)(i)	50.73(a)(2)(ii)(A)	50.73(a)(2)(viii)(B)	

12. LICENSEE CONTACT FOR THIS LER

NAME

Mark A. Reidmeyer

TELEPHONE NUMBER (Include Area Code)

(573) 676-4306

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED

15. EXPECTED
SUBMISSION
DATE

MONTH DAY YEAR

YES (If yes, complete EXPECTED SUBMISSION DATE)	X	NO			
---	---	----	--	--	--

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On 04/27/02 at 2023 hours, the Shift Security Supervisor with the approval of the Operations Shift Supervisor directed Security Force Members to seek cover due to a tornado sighting/warning in Callaway County. Outside patrols and Operations Gate officers were directed to seek cover in alternate facilities. Security vehicles were arranged to prevent site access prior to leaving posts. Protected Area posts and controls were moved into safe buildings with their contingency gear. The fall back defensive strategy was maintained. No required compensatory posts were closed as a result of this event. At 2037, the danger was no longer present and operations were returned to normal.

An Event Notification telephone call was made to the NRC Operations Center at 2105, 04/27/02 (EN# 38882).

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
Callaway Plant Unit 1	05000483	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 3
		2002	- 007	- 00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

I. DESCRIPTION OF THE REPORTABLE EVENT

A. REPORTABLE EVENT CLASSIFICATION

This Event is reportable under 10 CFR 73.71(a)(4) reporting of safeguards events.

B. PLANT OPERATING CONDITIONS PRIOR TO THE EVENT

Callaway Plant was in Mode 1 at 100 percent power.

C. STATUS OF STRUCTURES, SYSTEMS OR COMPONENTS THAT WERE INOPERABLE AT THE START OF THE EVENT AND THAT CONTRIBUTED TO THE EVENT

Not Applicable.

D. NARATIVE SUMMARY OF THE EVENT, INCLUDING DATES AND APPROXIMATE TIMES

On 04/27/02 at 2023 hours, the Shift Security Supervisor with the approval of the Operations Shift Supervisor directed Security Force Members to seek cover due to a tornado sighting/warning in Callaway County. Outside patrols and Operations Gate officers were directed to seek cover in alternate facilities. Security vehicles were arranged to prevent site access prior to leaving posts. Protected Area posts and controls were moved into safe buildings with their contingency gear. The fall back defensive strategy was maintained. No required compensatory posts were closed as a result of this event. At 2037, the danger was no longer present and operations were returned to normal.

An Event Notification telephone call was made to the NRC Operations Center at 2105, 04/27/02 (EN# 38882).

E. METHOD OF DISCOVERY OF EACH COMPONENT, SYSTEM FAILURE, OR PROCEDURAL ERROR

Not Applicable.

II. EVENT DRIVEN INFORMATION

A. SAFETY SYSTEMS THAT RESPONDED

Not Applicable.

B. DURATION OF SAFETY SYSTEM INOPERABILITY

Security measures implemented to comply with the Order for Interim Safeguards and Security Compensatory Measures, issued 2/25/02, were affected for 14 minutes.

C. SAFETY CONSEQUENCES AND IMPLICATIONS OF THE EVENT.

Selected outside patrols and posts were temporarily suspended. The actions taken due to the inclement weather reduced the effectiveness of measures implemented to comply with the Order for Interim Safeguards and Security Compensatory Measures issued 2/25/02.

III. CAUSE OF THE EVENT

The cause of the event was a Tornado sighting/warning for Callaway County.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
Callaway Plant Unit 1	05000483	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 3
		2002	- 007	- 00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

IV. CORRECTIVE ACTIONS

No corrective actions are necessary for this event.

V. PREVIOUS SIMILAR EVENTS

Callaway experienced a similar weather related event on 4/10/2001 documented in Callaway LER 2001-004-00.

VI. ADDITIONAL INFORMATION

The system and component codes listed below are from the IEEE Standard 805-1984 and IEEE Standard 803A-1984 respectively.

System: Not applicable.

Component: Not applicable.