June 28, 2002

LICENSEE: FirstEnergy Nuclear Operating Company

FACILITY: Davis-Besse Nuclear Power Station, Unit 1

SUBJECT: DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1 - MEETING SUMMARY

OF MAY 7, 2002, TO DISCUSS THE ROOT CAUSE ANALYSIS OF THE

DEGRADATION OF THE REACTOR PRESSURE VESSEL HEAD

On May 7, 2002, Nuclear Regulatory Commission management and staff conducted a public meeting in Rockville, Maryland, with representatives of FirstEnergy Nuclear Operating Company. The purpose was to discuss the root cause analysis of the degradation of the reactor pressure vessel (RPV) head at the Davis-Besse Nuclear Power Station with interested members of the public. A public notice that the meeting was to be held was issued on April 25, 2002. A telephone conference bridge was established for members of the public who were unable to attend. The meeting's participants are included as Enclosure 1 and the licensee's handouts are included as Enclosure 2.

By letter dated April 18, 2002, the licensee provided their Root Cause Analysis. In summarizing their report, the licensee stated that inadequate inspection of the RPV closure head prevented early detection of nozzle leakage resulting in prolonged boric acid corrosion and significant degradation. When describing the ultra-sonic test results on page 10 of the licensee's handouts, the licensee acknowledged that a new through-wall crack had been identified in the Nozzle 2 test results earlier that day.

The licensee described the makeup and the work of the Root Cause Investigation Team and concluded that (1) the degradation to the RPV closure head was caused by primary water stress corrosion cracking of the control rod drive (CRD) nozzle which led to leaks that were undetected allowing corrosion to occur, and (2) the existing guidance/knowledge is adequate for understanding how to prevent RPV closure head degradation from any CRD nozzle leaks.

Page 23 of the licensee's handouts provided a time-line of key events through the last three refueling outages dating back to 1995. The licensee estimated that the longest through-wall cracks were initiated around 1990 (± 3 years) and took approximately 4-6 years to propagate through the CRD nozzle wall. A significant increase in unidentified reactor coolant system leakage occurred during the 1998-1999 period. During this time period, the licensee observed that the white boron deposits initially limited to the RPV head began to change to become a significant flow of red colored boric acid emanating from the "mouse-holes" surrounding the service structure. At this same time, the licensee increased the frequency of changing the containment radiation monitor filters and the frequency of cleaning the containment air coolers.

The licensee described four stages of degradation of CRD nozzles. These include:

Stage 1 - Crack Initiation Progression

Stage 2 - Minor Weepage/Latency Period

Stage 3 - Deep Annulus Corrosive Attack

Stage 4 - General Boric Acid Corrosion

The licensee concluded that the Davis-Besse facility experienced four years of Stage 4 corrosion. This resulted in a maximum radial progression of approximately 7 inches at an average rate of 2 inches per year. The corrosion experienced was determined to be consistent with the Electric Power Research Institute Boric Acid Corrosion Guidebook.

The staff described the licensee's root cause analysis efforts as credible but also noted that uncertainties continue to exist.

Upon completion of the technical meeting with the licensee, questions were taken from members of the public who were present at the meeting followed by questions from the public on the telephone link-up. Questions focused on the licensee's proposed repair plan and the possibility of the licensee obtaining the RPV closure head from the abandoned Midland, Unit 2 facility. While the staff made clear that this decision was to be made by the licensee, the staff stated that a replacement head would represent a clearer success path.

/RA/

Douglas V. Pickett, Senior Project Manager, Section 2 Project Directorate III Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket No. 50-346

Enclosures: 1. Participants

2. Meeting Slides

cc w/encls: See next page

The licensee concluded that the Davis-Besse facility experienced four years of Stage 4 corrosion. This resulted in a maximum radial progression of approximately 7 inches at an average rate of 2 inches per year. The corrosion experienced was determined to be consistent with the Electric Power Research Institute Boric Acid Corrosion Guidebook.

The staff described the licensee's root cause analysis efforts as credible but also noted that uncertainties continue to exist.

Upon completion of the technical meeting with the licensee, questions were taken from members of the public who were present at the meeting followed by questions from the public on the telephone link-up. Questions focused on the licensee's proposed repair plan and the possibility of the licensee obtaining the RPV closure head from the abandoned Midland, Unit 2 facility. While the staff made clear that this decision was to be made by the licensee, the staff stated that a replacement head would represent a clearer success path.

/RA/

Douglas V. Pickett, Project Manager, Section 2 Project Directorate III Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket No. 50-346

Enclosures: 1. Participants

2. Meeting Slides

cc w/encls: See next page

Accession Numbers: Meeting Notice: ML021150460

Meeting Summary: ML021680521 Enclosure 2: ML021290524 Package: ML021700632

OFFICE	PM:PDIII-2	LA:PDIII-2	SC:PDIII-2
NAME	DPickett	THarris*	AMendiola
DATE	06/22/02	06/ 20 /02	06/28/02

OFFICIAL RECORD COPY

^{*}See previous concurrence

Davis-Besse Nuclear Power Station, Unit 1

CC:

Mary E. O'Reilly FirstEnergy Corporation 76 South Main St. Akron, OH 44308

Manager - Regulatory Affairs First Energy Nuclear Operating Company Davis-Besse Nuclear Power Station Oak Harbor, OH 43449-9760

Director
Ohio Department of Commerce
Division of Industrial Compliance
Bureau of Operations & Maintenance
6606 Tussing Road
P.O. Box 4009
Reynoldsburg, OH 43068-9009

Regional Administrator U.S. Nuclear Regulatory Commission 801 Warrenville Road Lisle, IL 60523-4351

Michael A. Schoppman Framatome ANP 1911 N. Ft. Myer Drive Rosslyn, VA 22209

Resident Inspector U.S. Nuclear Regulatory Commission 5503 North State Route 2 Oak Harbor, OH 43449-9760

Plant Manager, Randel J. Fast FirstEnergy Nuclear Operating Company Davis-Besse Nuclear Power Station 5501 North State - Route 2 Oak Harbor, OH 43449-9760

Dennis Clum
Radiological Assistance Section Supervisor
Bureau of Radiation Protection
Ohio Department of Health
P.O. Box 118
Columbus, OH 43266-0118

Carol O'Claire, Chief, Radiological Branch Ohio Emergency Management Agency 2855 West Dublin Granville Road Columbus, OH 43235-2206

Zack A. Clayton
DERR
Ohio Environmental Protection Agency
P.O. Box 1049
Columbus, OH 43266-0149

State of Ohio
Public Utilities Commission
180 East Broad Street
Columbus, OH 43266-0573

Attorney General
Department of Attorney
30 East Broad Street
Columbus, OH 43216

President, Board of County Commissioners of Ottawa County Port Clinton, OH 43252

President, Board of County Commissioners of Lucas County One Government Center, Suite 800 Toledo, Ohio 43604-6506

DISTRIBUTION FOR MEETING SUMMARY OF MAY 7, 2002, WITH FIRSTENERGY **NUCLEAR OPERATING COMPANY**

Hard Copy w/encls

PD III-2 Reading

PUBLIC

GGrant, RIII

Hard Copy w/Encl 1

OGC

ACRS

E-mail w/Encl 1 SCollins

BSheron

JZwolinski

TMarsh

CCasto

WBateman

KWichman

AHiser

SBajwa

SCoffin

SBloom

MMarshall

WCullen

ALee

SLong

AMendiola

SSands

DPickett

THarris

HNieh

SRosenberg

MKotzalas

JDavis

EHackett

JJacobson

LIST OF MEETING PARTICIPANTS

MAY 7, 2002

NRC

Bill Bateman Tony Mendiola Jim Davis Ed Hackett John Jacobson Bill Cullen Stephen Sands Doug Pickett

FIRSTENERGY

John Wood Dave Eshelman Mark McLaughlin Steve Loehlein

NRC CONSULTANT

Keith Wichman