



RESPONSE TO FREEDOM OF INFORMATION ACT (FOIA) / PRIVACY ACT (PA) REQUEST

2002-0292

1

RESPONSE TYPE FINAL PARTIAL

REQUESTER

Kelly L. Lecker

DATE

JUN 18 2002

PART I. -- INFORMATION RELEASED

- No additional agency records subject to the request have been located.
- Requested records are available through another public distribution program. See Comments section.
- APPENDICES **A** Agency records subject to the request that are identified in the listed appendices are already available for public inspection and copying at the NRC Public Document Room.
- APPENDICES Agency records subject to the request that are identified in the listed appendices are being made available for public inspection and copying at the NRC Public Document Room.
- Enclosed is information on how you may obtain access to and the charges for copying records located at the NRC Public Document Room, 2120 L Street, NW, Washington, DC.
- APPENDICES * Agency records subject to the request are enclosed.
- Records subject to the request that contain information originated by or of interest to another Federal agency have been referred to that agency (see comments section) for a disclosure determination and direct response to you.
- We are continuing to process your request.
- See Comments.

PART I.A -- FEES

AMOUNT *
\$

- You will be billed by NRC for the amount listed.
- None. Minimum fee threshold not met.
- You will receive a refund for the amount listed.
- Fees waived.

* See comments for details

PART I.B -- INFORMATION NOT LOCATED OR WITHHELD FROM DISCLOSURE

- No agency records subject to the request have been located.
- Certain information in the requested records is being withheld from disclosure pursuant to the exemptions described in and for the reasons stated in Part II.
- This determination may be appealed within 30 days by writing to the FOIA/PA Officer, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001. Clearly state on the envelope and in the letter that it is a "FOIA/PA Appeal."

PART I.C COMMENTS (Use attached Comments continuation page if required)

*In a telephone conversation on June 6, 2002, with Natalie Brown, you clarified the scope of your request to printouts of inspection reports and Licensee Event Reports (LERs) that are already publicly available. The printouts are enclosed. Records with an ML Accession No. are available in the NRC's Public Electronic Reading Room at <http://www.nrc.gov/reading-rm/adams.html>. All other records identified on the printouts are available in the NRC Public Document Room (PDR). We have enclosed a notice which provides procedures for obtaining records from the PDR. You may contact the PDR at (301) 415-4737, or 1-800-397-4209 if you need assistance in obtaining any of the records.

Also enclosed are 100 pages of records that you are entitled to free of charge.

SIGNATURE - FREEDOM OF INFORMATION ACT AND PRIVACY ACT OFFICER

Carol Ann Reed *(Signature)*

**APPENDIX A
RECORDS ALREADY AVAILABLE IN THE PDR**

<u>NO.</u>	<u>DATE</u>	<u>DESCRIPTION/(PAGE COUNT)</u>
1.	Undated	Print-out list of Davis-Besse Inspection reports issued from 1995-1999 (In NUDOCS) (14 pages)
2.	Undated	Print-out list of Davis-Besse LERs issued from 1995-1999 (In NUDOCS (16 pages)
3.	06/07/02	Print-out list of Davis-Besse inspection reports (In ADAMS as of 6/7/02) (5 pages)
4.	06/07/02	Print-out list of Davis-Besse LERs (In ADAMS as of 6/7/02) (2 pages)

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9910290249 (TXT)	05000346 *		NE R3	991026	A9688-288/A9688-298
	Insp rept 50-346/99-17 on 990928-1001.No violations noted. Major areas inspected:implementation of licensee protected area				
9910210096 (TXT)	05000346 *		NE R3	991008	A9637-250/A9637-264
	Insp rept 50-346/99-10 on 990802-0913.One NCV occurred. Major areas inspected:operations,maint & engineering.				
9908260185 (TXT)	05000346 *		NE R3	990820	A9046-070/A9046-086
	Insp rept 50-346/99-09 on 990623-0802.Noncited violations noted.Major areas inspected:aspects of licensee operations,				
9908130092 (TXT)	05000346 *		NE R3	990809	A8952-172/A8952-185
	Insp rept 50-346/99-15 on 990712-16.No violations noted. Major areas inspected:effectiveness of licensee program for mgt of				
9907260065 (TXT)	05000346 *		NE R3	990720	A8702-281/A8702-294
	Insp rept 50-346/99-08 on 990513-0628.Three violations noted & being treated as non-cited violations.Major areas				

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
5 <Replace>

A/1

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9906110013 (TXT)	05000346 *		NE R3	990607	A8276-004/A8276-024
	Insp rept 50-346/99-04 on 990323-0513. Two violations noted & being treated as non-cited violations. Major areas inspected :				
9906110010 (TXT)	05000346 *		NE R3	990604	A8276-222/A8276-235
	Insp rept 50-346/98-21 on 980901-1201 & 990425-0513. Violations identified with pending licensee response. Major areas				
9904300093 (TXT)	05000346 *		NE R3	990427	A7850-205/A7850-211
	Insp rept 50-346/99-05 on 990405-09. No violations noted. Major areas inspected: licensee on-line maint risk assessment program.				
9903120014 (TXT)	05000346 *		NE R3	990305	A7203-003/A7203-017
	Insp rept 50-346/99-01 on 990102-0212. No violations noted. Major areas inspected: operations, maint, engineering & plant support.				
9903090356 (TXT)	05000346 *		NE R3	990225	A7160-340/A7160-353
	Insp rept 50-346/99-02 on 990202-05. No violations noted. Major areas inspected: aspects of licensee program for controlling				

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
 5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9901280109 (TXT)	05000346 *		NE R3	990122	A6724-244/A6724-259
Insp rept 50-346/98-18 on 981110-990102.No violations noted. Major areated as non-cited violations.Major areas inspected :					
9906110010 (TXT)	05000346 *		NE R3	990604	A8276-222/A8276-235
Insp rept 50-346/98-21 on 980901-1201 & 990425-0513. Violations identified with pending licensee response.Major areas					
9904300093 (TXT)	05000346 *		NE R3	990427	A7850-205/A7850-211
Insp rept 50-346/99-05 on 990405-09.No violations noted. Major areas inspected:licensee on-line maint risk assessment program.					
9903120014 (TXT)	05000346 *		NE R3	990305	A7203-003/A7203-017
Insp rept 50-346/99-01 on 990102-0212.No violations noted. Major areas inspected:operations,maint,engineering & plant support.					
9903090356 (TXT)	05000346 *		NE R3	990225	A7160-340/A7160-353
Insp rept 50-346/99-02 on 990202-05.No violations noted. Major areas inspected:aspects of licensee program for controlling					

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9810260022 (TXT)	05000346 *		NE R2	981014	A5562-256/A5562-271
Insp rept 50-346/98-14 on 980808-0918.No violations noted. Major areas inspected:licensee operations,maint,engineering & plant					
9810070150 (TXT)	05000346 *		NE R3	980930	A5368-239/A5368-255
Insp rept 50-346/98-16 on 980831-0904.No violations noted. Major areas inspected:plant support.					
9809150030 (TXT)	05000346 *		NE R3	980909	A5107-030/A5107-031
Revised pages 15 & 18 to insp rept 50-346/98-11,correcting number given for unresolved item 50-346/95009-02.Number should					
9809090192 (TXT)	05000346 *		NE R3	980903	A5016-022/A5016-041
Insp rept 50-346/98-11 on 980803-14.No violations noted. Major areas inspected:effectiveness of corrective action program.					
9809020149 (TXT)	05000346 *		NE R3	980825	A4903-168/A4903-184
Insp rept 50-346/98-13 on 980623-0807.No violations noted. Major areas inspected:licensee operations,maint,engineering & plant					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
 5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9808250003 (TXT)	05000346 *		NE R3	980814	A4737-008/A4737-035
	Insp rept 50-346/98-12 on 980624-29.No violations noted. Major areas inspected:review of licensee response & recovery from				
9808050165 (TXT)	05000346 *		NE R3	980728	A4489-082/A4489-096
	Insp rept 50-346/98-09 on 980512-0623.Violations noted. Major areas inspected:operations,maintenance,engineering & plant				
9807070026 (TXT)	05000346 *		NE R3	980630	A4041-326/A4041-337
	Insp rept 50-346/98-08 on 980526-0617.Violations noted.Major areas inspected:licensee performance re physical security.				
9807020081 (TXT)	05000346 *		NE R3	980627	A4006-071/A4006-086
	Insp rept 50-346/98-10 on 980608-11.Violation noted. Major areas inspected:solid radwaste mgt & transportation				
9806170136 (TXT)	05000346 *		NE R3	980611	A3854-212/A3854-232
	Insp rept 50-346/98-05 on 980401-0512.Violations noted.Major areas inspected:operations,maint & engineering.				

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9806150283 (TXT)	05000346 *		NE R3	980609	A3824-006/A3824-020
	Insp rept 50-346/98-06 on 980422-0507. Violations noted. Major areas inspected: aspects of licensee code repairs of MSIV &				
9806010210 (TXT)	05000346 *		NE R3	980526	A3597-243/A3597-258
	Insp rept 50-346/98-07 on 980427-30. No violations noted. Major areas inspected: ALARA planning & controls for eleventh refueling				
9804200380 (TXT)	05000346 *		NE R3	980410	A3051-042/A3051-057
	Insp rept 50-346/98-04 on 980218-0331. No violations noted. Major areas inspected: operations, maint, engineering & plant support.				
9803170332 (TXT)	05000346 *		NE R4	980310	A2669-055/A2669-068
	Insp rept 50-346/98-02 on 980108-0218. Violations noted. Major areas inspected: licensee operations, maint, engineering & plant				
9803160006 (TXT)	05000346 *		NE R3	980310	A2604-292/A2604-305
	Insp rept 50-346/98-03 on 980223-26. No violations noted. Major areas inspected: engineering.				

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9806150283 (TXT)	05000346 *		NE R3	980609	A3824-006/A3824-020
9806010210 (TXT)	05000346 *		NE R3	980526	A3597-243/A3597-258
9804200380 (TXT)	05000346 *		NE R3	980410	A3051-042/A3051-057
9803170332 (TXT)	05000346 *		NE R4	980310	A2669-055/A2669-068
9803160006 (TXT)	05000346 *		NE R3	980310	A2604-292/A2604-305

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9802040016 (TXT)	05000346 *		NE R3	980128	A1998-006/A1998-021
	Insp rept 50-346/97-15 on 971110-980107.No violations noted. Major areas inspected:operations,maint,engineering & plant				
9712010047 (TXT)	05000346 *		NE R3	971121	A1259-164/A1259-174
	Insp rept 50-346/97-13 on 970929-1110.No violations noted. Major areas inspected:licensee operations,maint,engineering & plant				
9711180130 (TXT)	05000346 *		NE R3	971110	A1142-184/A1142-190
	Insp rept 50-346/97-14 on 971021-23.No violations noted. Major areas inspected:maint.				
9711120107 (TXT)	05000346 *		NE R3	971104	A1064-024/A1064-040
	Insp rept 50-346/97-12 on 971006-10.Violations noted. Major areas inspected:review of radiation protection & chemistry				
9711060274 (TXT)	05000346 *		NE R3	971031	A1016-251/A1016-268
	Insp rept 50-346/97-11 on 970818-0929.Violations noted. Major areas inspected:operations,maint,engineering & plant support.				

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9710200113 (TXT)	05000346 *		NE R3	971011	A0777-036/A0777-042
Insp rept 50-346/97-10 on 970806-07 & 0903-04.No violations noted.Major areas inspected:review of vehicle barrier sys.					
9710140277 (TXT)	05000346 *		NE R3	971001	A0731-277/A0731-295
Insp rept 50-346/97-09 on 970707-0818.No violations noted. Major areas inspected:licensee operations,maint,engineering & plant					
9710020005 (TXT)	05000346 *		NE R3	970923	A0597-126/A0597-142
Insp rept 50-346/97-08 on 970527-0707.Violations noted.Major areas inspected:operations,maint,engineering & plant support.					
9709180174 (TXT)	05000346 *		N*****	970904	A0421-154/A0421-189
Insp rept 50-346/97-201 on 970505-09,19-23 & 0609-20.No violations noted.Major areas inspected:HPI sys & LPI functions					
9708110073 (TXT)	05000346 *		NE R3	970804	A0012-072/A0012-082
Insp rept 50-346/97-07 on 970602-06.No violations noted. Major areas inspected:plant support re emergency plan exercise.					

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9707100086 (TXT)	05000346 *		NE R3	970626	93681-232/93681-251
Insp rept 50-346/97-06 on 970414-0527.No violations noted. Major areas inspected:plant operations,engineering,maint & plant					
9705200212 (TXT)	05000346 *		NE R3	970509	92973-333/92973-350
Insp rept 50-346/97-04 on 970303-0414.Violations noted.Major areas inspected:operations,maint,engineering & plant support.					
9705130397 (TXT)	05000346 *		NE R3	970508	92865-162/92865-173
Insp rept 50-346/97-05 on 970324-28 & 0416-21.No violations noted.Major areas inspected:inspector reviewed security force					
9704170091 (TXT)	05000346 *		NE R3	970407	92586-071/92586-092
Insp rept 50-346/97-03 on 970118-0307.Violations noted.Major areas inspected:licensee operations,maint,engineering & plant					
9703110193 (*)	05000346 *		NE R3	970306	92078-017/92078-044
Insp rept 50-346/97-02 on 970113-17.Violations noted.Major areas inspected:operations,maint,QA & engineering.					

Working...

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9703050208 (TXT)	05000346 *		NE R3	970225	91998-088/91998-113
	Insp rept 50-346/96-14 on 961126-970124 & 970213. Violations noted. Major areas inspected: operations, maintenance, engineering				
9702250472 (TXT)	05000346 *		NE R3	970206	91865-272/91865-284
	Insp rept 50-346/96-13 on 961202-970117. Violation noted. Major areas inspected: numerous effluent & area radiation monitors &				
9702100267 (ABS)	05000346 *		NE R3	970131	91691-207/91691-233
	Insp rept 50-346/96-10 on 961009-1127. No violations noted. Major areas inspected: operation, maint, engineering, plant support.				
9701130096 (*)	05000346 *		NE R3	970106	91392-099/91392-110
	Insp rept 50-346/96-11 on 961104-08 & 1218. Deviations noted. Major areas inspected: review of EP program & plant support.				
9701080154 (ABS)	05000346 *		NE R3	961227	91307-296/91307-317
	Insp rept 50-346/96-06 on 960815-1009. Violations noted. Major areas inspected: operations, maint, engineering & plant support.				

Working...

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9612190412 (*)	05000346 *		NE R3	961210	91138-003/91138-010
	Insp rept 50-346/96-12 on 961104.No violations noted.Major areas inspected:licensed operator requalification program including				
9611260053 (ABS)	05000346 *		NE R3	961119	90916-084/90916-114
	Insp rept 50-346/96-05 on 960611-0814.Violations noted. Major areas inspected:operations,maint,engineering & plant support.				
9610110193 (ABS)	05000346 *		NE R3	961004	90329-269/90329-292
	Enforcement Conference rept 50-346/96-09 on 960926.Apparent violations identified during insp discussed,along w/C/As taken				
9610090041 (ABS)	05000346 *		NE R3	961003	89979-009/89979-022
	Insp rept 50-346/96-07 on 960729-0827.No violations noted. One unresolved item identified in performance of 10CFR50.59				
9609230023 (ABS)	05000346 *		NE R3	960912	89740-071/89740-084
	Insp rept 50-346/96-08 on 960624-0711 & 0814-15.No violations noted.Major areas inspected:licensee operations,				

Working...

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9608120055 (ABS)	05000346 *		NE R3	960730	89306-255/89306-282
	Insp rept 50-346/96-03 on 960410-0611.Violations noted.Major areas inspected:operations,maint,engineering & plant support.				
9606210205 (ABS)	05000346	LANKSBURY,R.D.	NE R3	960611	88675-339/88675-355
	Enforcement conference 50-346/96-04 on 960523.Violations noted.Conference summary:two apparent violations identified				
9605280175 (ABS)	05000346	LANKSBURY,R.D.	NE R3	960503	88350-111/88350-128
	Insp rept 50-346/96-02 on 960209-0410.Violations noted. Major areas inspected:operations,maintenance,engineering, plant				
9602150257 (ABS)	05000346	LANKSBURY,R.D.	NE R3	960208	87121-321/87121-334
	Insp rept 50-346/95-09 on 951004-1215.Violation noted.Major areas inspected:operations,maint,engineering,plant support & dry				
9512110389 (*)	05000346	LANKSBURY,R.D.	NE R3	951121	86460-332/86460-346
	Insp rept 50-346/95-08 on 950823-1011.Violations noted. Major areas inspected:operations,maintenance,engineering, plant				

Working...

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
9504070026 (ABS)	05000346	LANKSBURY,R.D.	NE R3	950324	83437-344/83437-352
Insp rept 50-346/95-03 on 950122-0306.No violations noted. Major areas inspected:operations,surveillances,maint,onsite					
9503200011 (ABS)	05000346	PIRTLE,G.L.	NE R3	950303	83140-003/83140-012
Insp rept 50-346/95-02 on 950106-25.No violations noted. Major areas inspected:Physical security insp,audits, corrective					
9502220287 (ABS)	05000346	LANKSBURY,R.D.	NE R3	950213	82799-190/82799-201
Insp rept 50-346/94-17 on 950213.No violations or deviations noted.Major areas inspected:plant operations,surveillances,					
9502060020 (ABS)	05000346	YIN,I.T.	NE R3	950126	82601-050/82601-064
Insp rept 50-346/94-16 on 941128-1222.Violations noted. Major areas inspected:implementation of plant design changes.					
9501310055 (ABS)	05000346	BURGESS,S.D.	NE R3	950123	82528-131/82528-142
Insp rept 50-346/94-12 on 941128-1216.Violations noted.Major areas inspected:licensee response to GL 89-10, "Safety- Related					

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9909210097 (TXT)	05000346	MILLER,D.L.	EUTCENR	990903	A9321-351/A9321-360
LER 98-011-01:on 981014,manual reactor trip occurred.Caused by component cooling water sys leak.Breaker being installed into D1					
* 9909070142 (TXT)	05000346	COOK,R.M.	EUTCENR	990826	A9183-076/A9183-080
LER 99-003-00:on 990727,failure to perform engineering evaluation for pressurizer cooldown rate exceeding TS limit was					
* 9908180130 (TXT)	05000346	COOK,R.M.	EUTCENR	990806	A9020-094/A9020-102
LER 98-009-01:on 980909,reactor coolant sys pressurizer spray valve degraded with two of eight body to bonnet nuts					
* 9907200058 (TXT)	05000346	WOLF,G.M.	EUTCENR	990714	A8671-013/A8671-018
LER 98-001-01:on 980407,discovered that MSSV setpoints were outside of TS allowable values.Caused by valve disc sticking to					
* 9907160138 (TXT)	05000346	LOCKWOOD,D.H.	EUTCENR	990709	A8654-264/A8654-268
LER 98-012-01:on 981018,reactor trip occurred.Caused by inadequate design drawing resulting in inadequate procedure.					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
Count: *5 <Replace>

A/2

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9907010220 (TXT)	05000346	WOLF,G.M.	EUTCENR	990624	A8536-319/A8536-326
LER 98-013-01:on 981105,safety valve rupture disks may induce excessive eccentric loading of pressurizer vessel nozzles.Caused					
* 9904060318 (TXT)	05000346	WOLF,G.M.	EUTCENR	990326	A7577-056/A7577-086
LER 97-008-14:on 970318,inadequate testing of SR logic,was discovered.Caused by surveillance test review process not					
* 9903170361 (TXT)	05000346	WOLF,G.M.	EUTCENR	990305	A7310-130/A7310-134
LER 99-002-00:on 990208,both trains of emergency ventilation sys were rendered inoperable.Caused by unattended open door . Door					
* 9902250343 (TXT)	05000346	WOLF,G.M.	EUTCENR	990211	A7008-167/A7008-171
LER 98-010-01:on 980924>manual RT was noted.Caused by misdiagnosis of FW control valve solenoid valve failure.					
* 9902170250 (TXT)	05000346	COOK,R.M.	EUTCENR	990205	A6958-220/A6958-222
LER 99-001-00:on 990110,failed to comply with TS action statements due to designation of wrong breaker in tagging					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
 Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9902100298 (TXT)	05000346	WOLF,G.M.	EUTCENTR	990127	A6892-341/A6892-345
LER 98-007-01:on 980824,flanged connection for number 2 control room humidifer was found separated.Caused by less than adequate					
* 9812160178 (TXT)	05000346	WOLF,G.M.	EUTCENTR	981206	A6257-115/A6257-122
LER 98-013-00:on 981105,SV rupture disks induce excessive eccentric loading of PV nozzles.Caused by errors made in					
* 9811200276 (TXT)	05000346	LOCKWOOD,D.H.	EUTCENTR	981117	A5974-251/A5974-255
LER 98-012-00:on 981018,reactor trip occurred from approx 4% power due to ARTS signal.Caused by inadequate design drawin g					
* 9811200211 (TXT)	05000346	MILLER,D.L.	EUTCENTR	981113	A5974-239/A5974-249
LER 98-011-00:on 981014,manual RT due to CCWS leak was noted.Caused by failure of one letdown cooler rupture disk. All					
* 9811190048 (TXT)	05000346	KRAEMER,C.A.	EUTCENTR	981113	A5915-146/A5915-153
LER 98-009-00:on 980909,RCS pressurizer spray valve was not functional with two of eight body to bonnet nuts missing. Caused					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9811040224 (TXT)	05000346	WOLF,G.M.	EUTCENR	981026	A5786-344/A5786-348
LER 98-010-00:on 980924,manual reactor trip was noted.Caused by misdiagnosed failure of main FW control valve solenoid					
* 9810070213 (TXT)	05000346	MILLER,D.L.	EUTCENR	981001	A5383-178/A5383-183
LER 98-008-00:on 981001,documented proceduralized guidance for initiation of post LOCA B dilution flow path.Caused by design					
* 9809290024 (TXT)	05000346	WOLF,G.M.	EUTCENR	980922	A5287-111/A5287-116
LER 98-007-00:on 980824,CR humidifier ductwork failure caused excessive opening in positive pressure boundary. Caused by less					
* 9809090289 (TXT)	05000346	WOLF,G.M.	EUTCENR	980803	A4988-154/A4988-160
LER 96-008-02:on 961113,switchyard circuitry was declared inoperable due to switchyard breaker alignment.Caused by					
* 9808260104 (TXT)	05000346	KRAEMER,C.A.	EUTCENR	980821	A4804-261/A4804-277
LER 98-006-00:on 980624,loss of offsite power was noted. Caused by tornado damage to switchyard.Tested & repaired affected					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9807200190 (TXT)	05000346	WOLF,G.M.	EUTCENR	980713	A4300-002/A4300-006 LER 98-004-00:on 980601,ductwork for number 2 control room humidifier found disconnected from humidifier.Caused by less
* 9807200171 (TXT)	05000346	MILLER,D.L.	EUTCENR	980711	A4300-008/A4300-011 LER 98-005-00:on 980601,both low pressure injection/DHR pumps were rendered inoperable during testing.Caused by inadequate
* 9806240346 (TXT)	05000346	KRAEMER,C.A.	EUTCLEI	980618	A3944-073/A3944-078 LER 98-003-00:on 980519,Mode 3 entry without completion of surveillance requirement occurred.Caused by failure of I&C
* 9805190420 (TXT)	05000346	MILLER,D.L.	EUTCENR	980510	A3549-068/A3549-073 LER 98-002-00:on 980410,plant tripped due to high pressurizer level as result of loss of letdown capability. Makeup &
* 9805190384 (TXT)	05000346	MILLER,D.L.	EUTCENR	980510	A3680-002/A3680-007 LER 97-012-01:on 970904,decay heat cooler seismic design inadequacy occurred.Caused by inadequate design of decay heat

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9805190261 (TXT)	05000346	WOLF,G.M.	EUTCENTR	980508	A3549-052/A3549-059
LER 97-015-01:on 971210,EDG tachometer circuit was noted outside 10CFR50 App R design basis.Caused by less than adequate					
* 9805190245 (TXT)	05000346	WOLF,G.M.	EUTCENTR	980508	A3549-002/A3549-034
LER 97-008-13:on 970318,inadequate testing of safety-related logic occurred.Overall root cause will be completed by 980930 &					
* 9805140288 (TXT)	05000346	WOLF,G.M.	EUTWIEP	980506	A3470-348/A3470-352
LER 98-001-00:on 980407,main steam safety valves setpoints were outside of TS allowable values.Cause will be					
* 9803300233 (TXT)	05000346	WOLF,G.M.	EUTCENTR	980320	A2878-330/A2878-358
LER 97-008-12:on 970318,discovered inadequate testing of safety-related logic circuits.Caused by inadequate surveillance					
* 9803230504 (TXT)	05000346	WOLF,G.M.	EUTCENTR	980312	A2834-330/A2834-358
LER 97-008-11:on 970318,inadequate testing of safety related logic were noted.Caused by personnel error.Test was performed &					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9805190261 (TXT)	05000346	WOLF,G.M.	EUTCENTR	980508	A3549-052/A3549-059
LER 97-015-01:on 971210,EDG tachometer circuit was noted outside 10CFR50 App R design basis.Caused by less than adequate					
* 9805190245 (TXT)	05000346	WOLF,G.M.	EUTCENTR	980508	A3549-002/A3549-034
LER 97-008-13:on 970318,inadequate testing of safety-related logic occurred.Overall root cause will be completed by 980930 &					
* 9805140288 (TXT)	05000346	WOLF,G.M.	EUTWIEP	980506	A3470-348/A3470-352
LER 98-001-00:on 980407,main steam safety valves setpoints were outside of TS allowable values.Cause will be					
* 9803300233 (TXT)	05000346	WOLF,G.M.	EUTCENTR	980320	A2878-330/A2878-358
LER 97-008-12:on 970318,discovered inadequate testing of safety-related logic circuits.Caused by inadequate surveillance					
* 9803230504 (TXT)	05000346	WOLF,G.M.	EUTCENTR	980312	A2834-330/A2834-358
LER 97-008-11:on 970318,inadequate testing of safety related logic were noted.Caused by personnel error.Test was performed &					

Working...
Count: *5

<Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9801050270 (TXT)	05000346	WOLF,G.M.	EUTCENR	971219	A1687-036/A1687-040
LER 97-005-01:on 970212,TS surveillance requirement had not been fulfilled during last plant startup due to inadequate					
* 9801050196 (TXT)	05000346	WOLF,G.M.	EUTCENR	971226	A1686-336/A1686-358
LER 97-008-08:on 970318,inadequate testing of safety-related logic was noted.Caused by personnel error.Testing was performed					
* 9712090150 (TXT)	05000346	WOLF,G.M.	EUTCENR	971126	A1390-114/A1390-118
LER 97-014-00:on 970801,pressurizer PORV setpoint was less than allowable value.Caused by degraded wire splice.Wire containing					
* 9712010312 (TXT)	05000346	WOLF,G.M.	EUTCENR	971120	A1277-050/A1277-069
LER 97-008-07:on 970318,inadequate testing of safety related logic was noted.Caused by failure to fulfill TS of SR. Performed					
* 9711260228 (TXT)	05000346	WOLF,G.M.	EUTCENR	971106	A1269-001/A1269-017
LER 97-008-06:on 970318,inadequate testing of safety related logic was noted.Caused by failure to fulfill TS of SR.Revie w of					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9711070168 (TXT)	05000346	MILLER,D.L.	EUTTOED	971103	A1112-072/A1112-076
LER 97-013-00:on 971002,potential condition adverse to quality rept documented failure to perform surveillance test before TS					
* 9710310091 (TXT)	05000346	MILLER,D.L.	EUTTOED	971024	A0996-124/A0996-127
LER 96-009-01:on 961113,failure to apply GL 91-18 to EDG surveillance testing occurred.Caused by personnel error. Review					
* 9710290238 (TXT)	05000346	WOLF,G.M.	EUTTOED	971023	A0964-084/A0964-095
LER 97-008-05:on 970318,inadequate testing of safety-related logic occurred.Caused by personnel error.Surveillance Test was					
* 9710150239 (TXT)	05000346	MILLER,D.L.	EUTTOED	971006	A0776-057/A0776-063
LER 97-012-00:on 970904,decay heat cooler seismic design inadequacy occurred.Caused by inadequate design of DHC support					
* 9710140192 (TXT)	05000346	WOLF,G.M.	EUTTOED	971002	A0744-204/A0744-209
LER 97-011-00:on 970825,emergency ventilation sys rendered inoperable by maint on room isolation valve occurred.Caused by					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9708260278 (TXT)	05000346	MILLER,D.L.	EUTTOED	970819	A0207-205/A0207-208
LER 97-003-01:on 970130,potential condition adverse to quality rept was initiated w/regard to TS action for degraded RCS flow					
* 9708260148 (TXT)	05000346	WOLF,G.M.	EUTTOED	970819	A0207-191/A0207-196
LER 97-002-01:on 970122,identified potential overpressurization of penetrations during accident conditions.Installed mod to					
* 9708050125 (TXT)	05000346	WOLF,G.M.	EUTTOED	970731	94710-234/94710-242
LER 97-008-01:on 961113,switchboard circuit was declared inoperable due to switchyard breaker alignment.Caused by					
* 9708040038 (TXT)	05000346	MILLER,D.L.	EUTTOED	970430	94000-153/94000-157
LER 97-009-01:on 970331,SFA sys sequence logic channels surveillance testing was initiated.Caused because requirement to					
* 9707020238 (TXT)	05000346	WOLF,G.M.	EUTTOED	970620	93649-228/93649-233
LER 97-007-01:on 970305,determined that acceptance criteria of surveillance test to measure leakage into DH valve pit					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9707020228 (TXT)	05000346	WOLF,G.M.	EUTTOED	970620	93649-215/93649-227
	LER 97-008-04:on 970318,inadequate testing of safety related logic occurred.Caused by procedure inadequacy.Surveillance test				
* 9706260308 (TXT)	05000346	WOLF,G.M.	EUTCENR	970616	93592-325/93592-335
	LER 97-008-03:on 970318,inadequate testing of safety related logic was identified.Caused by personnel error.Testing was				
* 9706190102 (TXT)	05000346	WOLF,G.M.	EUTTOED	970610	93488-071/93488-080
	LER 97-008-02:on 970318,performed inadequate testing of SR logic.Caused by personnel error failing to fully understand TS				
* 9706110303 (TXT)	05000346	WOLF,G.M.	EUTTOED	970603	93347-041/93347-046
	LER 97-010-00:on 970504,Main Transformer Deluge Sys automatically actuated due to degraded temp sensor in				
* 9705140041 (TXT)	05000346	WOLF,G.M.	EUTTOED	970502	93036-266/93036-273
	LER 97-008-01:on 970318,inadequate testing of safety related logic was identified.Caused because Surveillance Test revie w				

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
 Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9705050269 (TXT)	05000346	MILLER, D.L.	EUTTOED	970430	92773-137/92773-142
LER 97-009-00: on 970331, potential condition adverse to quality rept was initiated re TS SR for Safety Features Actuation Sys					
* 9704220366 (TXT)	05000346	WOLF, G.M.	EUTTOED	970417	92616-285/92616-290
LER 97-008-00: on 970318, determined that monthly surveillance tests for SFAS failed to provide complete check of					
* 9704100188 (TXT)	05000346	WOLF, G.M.	EUTTOED	970404	92592-018/92592-023
LER 97-007-00: on 970305, determined acceptance criteria of surveillance test to measure leakage into DH valve pit					
* 9704030074 (TXT)	05000346	WOLF, G.M.	EUTTOED	970327	92497-132/92497-136
LER 97-006-00: on 970225, both containment radiation monitors were found to be missing gaskets on particulate filter & iodine					
* 9703210327 (TXT)	05000346	WOLF, G.M.	EUTTOED	970314	92246-313/92246-318
LER 97-005-00: on 970212, failed to perform surveillance requirement of vacuum leakage rate test. Caused by inadequate					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
 Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9703110053 (TXT)	05000346	WOLF,G.M.	EUTTOED	970303	92109-056/92109-062
LER 97-004-00:on 970203,RCP motor oil piping was not protected from leakage as required per 10CFR50 App R.Caused by personnel					
* 9703100259 (TXT)	05000346	MILLER,D.L.	EUTTOED	970303	92108-313/92108-317
LER 97-003-00:on 970130,non-conservative TS action for degraded reactor coolant flow,occurred because calculations performed in					
* 9702280108 (TXT)	05000346	WOLF,G.M.	EUTTOED	970221	91932-164/91932-170
LER 97-002-00:on 970122,identified potential overpressurization of penetrations during accident conditions.Plant mods &					
* 9702280091 (TXT)	05000346	KRAEMER,C.A.	EUTTOED	970221	91932-083/91932-086
LER 97-001-00:on 970122,nuclear instrumentation declared inoperable & incapable of performing safety functions.Caused by					
* 9701210524 (TXT)	05000346	KRAEMER,C.A.	EUTTOED	970113	91484-043/91484-048
LER 96-010-00:on 961212,CREV sys were not realized as inoperable when radiation monitors were inoperable.Caused by					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
 Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9612240159 (TXT)	05000346	WOLF,G.M.	EUTTOED	961213	91242-029/91242-037
	LER 96-008-00:on 961113,switchyard circuit declared inoperable due to switchyard breaker alignment.TS 3.8.1.1 entered &				
* 9612240120 (TXT)	05000346	MILLER,D.L.	EUTTOED	961213	91226-343/91226-347
	LER 96-009-00:on 961113,failure to apply generic ltr 91-18 guidance to emergency diesel generator surveillance testing				
* 9611080088 (TXT)	05000346	WOLF,G.M.	EUTTOED	961104	90671-286/90671-293
	LER 96-007-00:on 961003,CR emergency ventilation sys design bases calculation error occurred.Caused by error in Bechtel				
* 9608220247 (TXT)	05000346	WOLF,G.M.	EUTTOED	960819	89446-240/89446-245
	LER 96-005-01:on 960416,Inadequate control of heavy loads in containment building identified.Caused by lack of understanding				
* 9608060027 (TXT)	05000346	SMITH,P.	EUTTOED	960419	89286-044/89286-054
	LER 96-002-01:on 960320,noted potential for loss of remote shutdown capability.Caused by fire induced hot short which could				

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
 Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9606200388 (TXT)	05000346	ANTRASSIAN, A.	EUTTOED	960613	88694-072/88694-075
LER 96-006-00: on 960614, discovered high lip around top of Reactor Coolant Pump Motor 2-1 not in place. Caused by inadequate					
* 9605280156 (TXT)	05000346	MILLER, D.L.	EUTTOED	960523	88396-152/88396-156
LER 96-005-00: on 960416, inadequate control of heavy loads in containment bldg. RVHLT was incorrectly perceived as rigging					
* 9605240083 (TXT)	05000346	MILLER, D.L.	EUTTOED	960517	88391-225/88391-230
LER 96-004-00: on 960417, PCAQR 96-0512 document failure to initiate required compensatory actions for Thermo-Lag for					
* 9605060133 (TXT)	05000346	SMITH, P.W.	EUTTOED	960429	88165-029/88165-034
LER 96-003-00: on 960328, discovered discrepancy in SRs for testing of absorbent matl in EVS. Caused by deficiencies in					
* 9604290102 (TXT)	05000346	SMITH, P.W.	EUTTOED	960419	88045-310/88045-318
LER 96-002-00: on 960320, potential loss of remote shutdown capability discovered due to MOV fire induced damage. Evaluated					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
Count: *5 <Replace>

Accession#	Docket	Author Name	Affil	Issued	Microfiche Address
* 9604290102 (TXT)	05000346	SMITH,P.W.	EUTTOED	960419	88045-310/88045-318
LER 96-002-00:on 960320,potential loss of remote shutdown capability discovered due to MOV fire induced damage. Evaluated					
* 9604080435 (TXT)	05000346	MILLER,D.L.	EUTTOED	960403	87824-055/87824-061
LER 96-001-00:on 960304,EECS inoperable.Caused by inadequate safety review.Plant mod to install manual vent valve will b e					
* 9512220015 (TXT)	05000346	ANTRASSIAN,A.V.	EUTTOED	951218	86652-126/86652-130
LER 95-003-00:on 951117,determined that removal of fan C48 from auxiliary bldg radwaste ventilation sys on 951006 inadvertently					
* 9510130263 (TXT)	05000346	ANTRASSIAN,A.	EUTTOED	951006	85807-219/85807-223
LER 95-002-00:on 950906,discovered six post nuts missing from terminal strip in cabinet C3629.Caused by isolated wiring					
* 9503060055 (TXT)	05000346	PETERSON,N.K.	EUTTOED	950224	82997-165/82997-171
LER 95-001-00:on 950126,determined that LOCA analysis results for 2 ft core elevation potentially non-conservative due to					

Arrows-Scroll, ENTER-Select, F10-Mark For Download, CTRL-F9-Continue Download.
Count: *5 <Replace>

Davis Besse Inspection Reports (In ADAMS as of 06/07/02)

Accession Number: ML993370095
Document Date: 11/24/1999
Title: Inspection Report 50-346/99-11 conducted on September 14-October 29, 1999.

Accession Number: ML003670862
Document Date: 12/23/1999
Title: Inspection report 50-346/99-12 of inspection conducted on October 29-December 6, 1999.

Accession Number: ML003671313
Document Date: 12/29/1999
Title: Inspection report 50-346/99-06 on December 7 - 9, 1999. No violations noted. Major areas inspected: licensee performance during exercise of emergency plan.

Accession Number: ML003708803
Document Date: 04/27/2000
Title: Insp Rpt Davis Besse IR-00-005

Accession Number: ML003712068
Document Date: 05/01/2000
Title: Insp rpt - Davis Besse IR-00-001

Accession Number: ML003712133
Document Date: 02/10/2000
Title: IR-99-016, Davis-Besse, inspection on 12/07/1999 - 02/04/2000

Accession Number: ML003716000
Document Date: 05/16/2000
Title: Insp Rpt - Davis Besse IR 00-006

Accession Number: ML003724252
Document Date: 06/16/2000
Title: Insp Rpt Davis Besse IR-00-003

Accession Number: ML003734452
Document Date: 07/21/2000
Title: Davis-Besse IR-00-004

A/3

Accession Number: ML003734460
Document Date: 07/19/2000
Title: Insp Rpt - Davis-Besse - IR-00-008

Accession Number: ML003742326
Document Date: 08/17/2000
Title: Farley NRC Supplemental IR Nos. 50-348,364/00-08

Accession Number: ML003747315
Document Date: 09/05/2000
Title: Davis 50-346-00-09 (DRP)

Accession Number: ML003748472
Document Date: 09/06/2000
Title: IR 50-346/2000011(DRS); on 08/07-08/11/2000; First Energy Nuclear Operating Company, Davis-Besse Nuclear Power Station. Occupational radiation safety program and performance indicators for occupational radiation safety cornerstone and reactor coolant

Accession Number: ML003749364
Document Date: 09/11/2000
Title: IR 50-346/2000007(DRS); on 07/10 - 07/28/00; FirstEnergy Nuclear Operating Company; Davis-Besse Nuclear Power Station. Safety System Design and Performance Capability.

Accession Number: ML003759627
Document Date: 10/13/2000
Title: IR 05000346/2000-013(DRS); on 09/18-22/2000, Davis-Besse Nuclear Power Station, Unit 1, Security Specialist Report. This inspection was conducted by a regional security specialist.

Accession Number: ML003762518
Document Date: 10/23/2000
Title: Davis-Besse IR 50-346/00-10(DRP)

Accession Number: ML003766913
Document Date: 11/06/2000
Title: ER 05000346-00-301(DRS), on 10/02-06/2000, FirstEnergy Nuclear Operating Company, Davis-Besse Nuclear Power Station. Other Activities.

Accession Number: ML003769126
Document Date: 11/14/2000
Title: IR 05000346-00-12(DRS), on 10/30-11/03/2000, FirstEnergy Nuclear Operating Company, Davis-Besse Nuclear power Station. Licensed Operator Requalification Training Inspection Report.

Accession Number: ML003771486
Document Date: 11/20/2000
Title: IR 50-346-00-14 on 10/01-11/16/2000; FirstEnergy Nuclear Operating Company; Davis-Besse Nuclear Power Station; resident inspector report

Accession Number: ML003773811
Document Date: 11/06/2000
Title: ER 05000346-00-301(DRS), on 10/02-06/2000, FirstEnergy Nuclear Operating Company, Davis-Besse Nuclear Power Station. Other Activities.

Accession Number: ML010180503
Document Date: 01/18/2001
Title: IR 50-346-00-15, on 11/17-12/31/2000; FirstEnergy Nuclear Operating Company; Davis-Besse Nuclear Power Station; resident inspector report

Accession Number: ML010180582
Document Date: 01/18/2001
Title: IR 05000346-01-02(DRS), on 01/08-12/2001, FirstEnergy Nuclear Operating Company, Davis-Besse Nuclear Power Station. Evaluations of Changes, Tests, or Experiments.

Accession Number: ML010570204
Document Date: 02/26/2001
Title: IR 05000346-01-04(DRS), on 01/29-02/02/2001, FirstEnergy Nuclear Operating Company, Davis-Besse Nuclear Power Station. Radiation Safety Specialist Report.

Accession Number: ML010670088
Document Date: 03/07/2001
Title: IR 50-346-01-03, on 01/01-02/13/2001; FirstEnergy Nuclear Operating Company; Davis-Besse Nuclear Power Station. Post-maintenance testing.

Accession Number: ML010870286
Document Date: 03/27/2001
Title: IR 05000346-01-05, on 2/26-03/09/2001; FirstEnergy Nuclear Operating Company; Davis-Besse Nuclear Power Station; identification and resolution of problems

Accession Number: ML011140358
Document Date: 04/20/2001
Title: IR 50-346-01-06(DRP), on 02/14 through 03/31/2001; FirstEnergy Nuclear Operating Company; Davis-Besse Nuclear Power Station. Maintenance Risk Assessments and Emergent Work.

Accession Number: ML011580073
Document Date: 06/06/2001
Title: IR 05000346-01-09(DRP), on 04/01-05/16/2001, FirstEnergy Nuclear Operating Company, Davis-Besse Nuclear Power Station. Integrated Inspection Report.

Accession Number: ML011620112
Document Date: 06/08/2001
Title: IR 05000346-01-07(DRS), on 5/21-5/24/2001, FirstEnergy Nuclear Operating Company, Davis-Besse Nuclear Power Station. Emergency Preparedness Specialist Report.

Accession Number: ML012070092
Document Date: 07/24/2001
Title: IR 05000346/2001010(DRP), on 05/17-06/30/2001, FirstEnergy Nuclear Operating Company, Davis-Besse Nuclear Power Station. Integrated Inspection Report.

Accession Number: ML012680323
Document Date: 09/21/2001
Title: IR 05000346/2001-011, Davis-Besse Nuclear Power Station, Inspection on 07/01/2001 - 08/23/2001 of areas related to reactor safety, equipment alignments, fire protection, flood protection measures, maintenance risk assessment. No violations noted.

Accession Number: ML012980063
Document Date: 10/23/2001
Title: IR 05000346/2001-012(DRP) FirstEnergy Nuclear Operating Co. Inspection on 08/24 - 09/30/2001 related to selected procedures and records, observation of activities and interviews with personnel. No violations noted.

Accession Number: ML013460574
Document Date: 12/11/2001
Title: IR 05000346/2001-013(DRP) on 10/01-11/13/2001, FirstEnergy Nuclear Operating Company, Davis-Besse Nuclear Power Station; maintenance risk assessment and emergent work evaluation. Non-cited violation.

Accession Number: ML020160575
Document Date: 01/16/2002
Title: IR 05000345/2001-014, FirstEnergy Nuclear Operating Company, Davis-Besse Nuclear Power Station, Inspection on 12/17-20/2002 re permanent plant modification and changes, tests, and experiments. One noncited violation noted.

Accession Number: ML020220085
Document Date: 01/18/2002
Title: IR 05000346/2001-015, FirstEnergy Nuclear Operating Company, Davis-Besse Nuclear Power Station, Integrated Inspection on 11/14-12/31/2001. No violations noted.

Accession Number: ML020390163
Document Date: 01/30/2002
Title: Inspection Effort by Reactor - Fiscal Years 2000 & 2001.

Accession Number: ML020710594
Document Date: 03/08/2002
Title: IR 05000346/2001-016, Davis-Besse Nuclear Power Station.

Accession Number: ML021060078
Document Date: 04/15/2002
Title: IR 05000346/2002-002, on 02/16-03/31/2002, FirstEnergy Nuclear Operating Company, Davis-Besse Nuclear Power Station. Integrated Inspection Report. No violations identified.

Accession Number: ML021260141
Document Date: 05/03/2002
Title: IR 05000346/2002-003, Davis-Besse Nuclear Power Station. Inspection conducted on 03/12-04/05/2002, Augumented Inspection Team.

Davis Besse LERs (In ADAMS as of 06/07/02)

Accession Number: ML993070002
Document Date: 10/21/1999
Title: LER 99-004-00, Minimum Licensed Operator Shift Staffing Deficiency
Due to Inadequate Evaluation of Temporary Medical Condition

Accession Number: ML993400384
Document Date: 11/22/1999
Title: LER 99-005-00: on 10/27/1999, failure to perform technical specification
required action after opening breaker was noted. Caused by personnel
error. Surveillance test DB-SC-03023 was satisfactorily completed. With
11/22/1999 letter.

Accession Number: ML003691628
Document Date: 02/21/2000
Title: LER 2000-001, Davis-Besse Nuclear Power Station, Unit No. 1, Date of
Occurrence - September 26, 1998.

Accession Number: ML003713367
Document Date: 04/28/2000
Title: Davis-Besse Nuclear Power Station, Unit No. 1 LER 2000-002, date of
occurrence - March 29, 2000.

Accession Number: ML003716233
Document Date: 05/11/2000
Title: Davis-Besse Nuclear Power Station, Unit No. 1 LER 2000-003, on April
12, 2000.

Accession Number: ML003719442
Document Date: 05/20/2000
Title: Davis-Besse, Unit 1, Personnel Error During Bus Transfer Testing Results
in Loss of Offsite Power, Licensee Event Report

Accession Number: ML003733011
Document Date: 07/07/2000
Title: Davis-Besse Unit 1, Main Steam Drain Valve Left Open Rendering
Auxiliary Feedwater Pump Turbine Inoperable, Licensee Event Report

A/y

Accession Number: ML010090439
Document Date: 01/02/2001
Title: LER 00-S01-00, Davis-Besse Nuclear Power Station, Unit No.1,
Unescorted Access Improperly Granted to Contract Employee Due to
Misfiling of Derogatory Information.

Accession Number: ML011560015
Document Date: 05/24/2001
Title: LER-00-002-01 Davis-Besse Unit No. 1, Main Steam Safety Valve
Setpoints Greater Than Allowable Values.

Accession Number: ML021070249
Document Date: 04/11/2002
Title: LER 02-001-00, Davis-Besse, Unit 1, Main Steam Valve Setpoints Greater
Than Allowable Values.

Accession Number: ML021220082
Document Date: 04/29/2002
Title: LER 02-002-00 Davis-Besse Nuclear Power Station, Unit 1, Reactor
Coolant System Pressure Boundary Leakage Due to Primary Water Stress
Corrosion Cracking of Control Rod Drive Mechanism Nozzles and
Reactor Pressure Vessel Head Degradation.

Accession Number: ML021350137
Document Date: 05/09/2002
Title: LER 02-003-00 for Davis-Besse, Unit 1 re Fuel Movement in Spent Fuel
Pool Without Required Door Attendant.
