

10CFR50.73

**Virginia Electric and Power Company  
Surry Power Station  
5570 Hog Island Road  
Surry, Virginia 23883**

June 12, 2002

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D. C. 20555-0001

Serial No.: 02-331  
SPS: TJN R1  
Docket No.: 50-281  
License No.: DPR-37

Dear Sirs:

Pursuant to 10CFR50.73, Virginia Electric and Power Company hereby submits the following Licensee Event Report applicable to Surry Power Station Unit 2.

Report No. 50-281/2002-001-00

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to the Management Safety Review Committee for its review.

Very truly yours,



Richard H. Blount, Site Vice President  
Surry Power Station

Enclosure

Commitment contained in this letter:

1. A VT-2 inspection will be completed on the Unit 1 RHR 3/4-inch balance lines during the next cold shutdown of Unit 1.

IE22

cc: United States Nuclear Regulatory Commission  
Region II  
Sam Nunn Atlanta Federal Center  
61 Forsyth Street, SW, Suite 23 T85  
Atlanta, Georgia 30303-8931

Mr. R. A. Musser  
NRC Senior Resident Inspector  
Surry Power Station

**LICENSEE EVENT REPORT (LER)**

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

FACILITY NAME (1)

**SURRY POWER STATION , Unit 2**

DOCKET NUMBER (2)

**05000 - 281**

PAGE (3)

**1 OF 4**

TITLE (4)

**Residual Heat Removal Piping Corrosion Through-wall Leak**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCUMENT NUMBER
04	13	2002	2002	-- 001 --	00	06	12	2002	FACILITY NAME	05000-
									FACILITY NAME	05000-

OPERATING MODE (9)	NA
POWER LEVEL (10)	000 %

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply) (11)							
<input type="checkbox"/>	20.2201(b)	<input type="checkbox"/>	20.2203(a)(3)(ii)	<input type="checkbox"/>	50.73(a)(2)(ii)(B)	<input type="checkbox"/>	50.73(a)(2)(ix)(A)
<input type="checkbox"/>	20.2201(d)	<input type="checkbox"/>	20.2203(a)(4)	<input type="checkbox"/>	50.73(a)(2)(iii)	<input type="checkbox"/>	50.73(a)(2)(x)
<input type="checkbox"/>	20.2203(a)(1)	<input type="checkbox"/>	50.36(c)(1)(i)(A)	<input type="checkbox"/>	50.73(a)(2)(iv)(A)	<input type="checkbox"/>	73.71(a)(4)
<input type="checkbox"/>	20.2203(a)(2)(i)	<input type="checkbox"/>	50.36(c)(1)(ii)(A)	<input type="checkbox"/>	50.73(a)(2)(v)(A)	<input type="checkbox"/>	73.71(a)(5)
<input type="checkbox"/>	20.2203(a)(2)(ii)	<input type="checkbox"/>	50.36(c)(2)	<input type="checkbox"/>	50.73(a)(2)(v)(B)	<input type="checkbox"/>	OTHER
<input type="checkbox"/>	20.2203(a)(2)(iii)	<input type="checkbox"/>	50.46(a)(3)(ii)	<input type="checkbox"/>	50.73(a)(2)(v)(C)	<input type="checkbox"/>	Specify in Abstract below or in NRC Form 366A
<input type="checkbox"/>	20.2203(a)(2)(iv)	<input type="checkbox"/>	50.73(a)(2)(i)(A)	<input type="checkbox"/>	50.73(a)(2)(v)(D)	<input type="checkbox"/>	
<input type="checkbox"/>	20.2203(a)(2)(v)	<input checked="" type="checkbox"/>	50.73(a)(2)(i)(B)	<input checked="" type="checkbox"/>	50.73(a)(2)(vii)	<input type="checkbox"/>	
<input type="checkbox"/>	20.2203(a)(2)(vi)	<input type="checkbox"/>	50.73(a)(2)(i)(C)	<input type="checkbox"/>	50.73(a)(2)(vii)(A)	<input type="checkbox"/>	
<input type="checkbox"/>	20.2203(a)(3)(i)	<input type="checkbox"/>	50.73(a)(2)(ii)(A)	<input type="checkbox"/>	50.73(a)(2)(vii)(B)	<input type="checkbox"/>	

**LICENSEE CONTACT FOR THIS LER (12)**

NAME	Richard H. Blount, Site Vice President	TELEPHONE NUMBER (Include Area Code)	(757) 365-2000
------	--	--------------------------------------	----------------

**COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)**

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
X	BP	PSP		N					

**SUPPLEMENTAL REPORT EXPECTED (14)**

YES (If yes, complete EXPECTED SUBMISSION DATE).	X	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
--	---	----	-------------------------------	-------	-----	------

**ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)**

On April 13, 2002 at 05:05 hours during plant heatup with Unit 2 at cold shutdown, a through-wall leak was discovered on the "B" residual heat removal (RHR) pump suction 3/4-inch diameter balance line. This condition did not meet ASME XI code requirements therefore, the line was declared inoperable. Furthermore, the line was not isolable from either RHR train therefore, both trains of RHR were declared inoperable. This condition is reportable pursuant to 10CFR50.73(a)(2)(vii). The line remained structurally adequate therefore, both trains of RHR were capable of performing their intended function and the system remained in service until repairs were implemented. Because no reactor coolant system (RCS) loops were operable at that time, the Technical Specification requirement that a minimum of two non-isolated loops shall be operable was not met. As such, this condition is also reportable pursuant to 10CFR50.73(a)(2)(i)(B). Plant heatup proceeded, keeping the RHR System in service, until two RCS loops were put into operation, restoring Technical Specification compliance. The RHR System was taken out of service, the 3/4-inch line was replaced, and the RHR System declared operable. The cause of this leak was transgranular stress corrosion cracking initiated from the outer surface of the 3/4-inch line.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

FACILITY NAME (1) <b>SURRY POWER STATION</b>	DOCKET <b>05000 - 281</b>	LER NUMBER (6)			PAGE (3) <b>2 OF 4</b>
		YEAR <b>2002</b>	SEQUENTIAL NUMBER <b>001</b>	REVISION NUMBER <b>00</b>	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

**1.0 DESCRIPTION OF THE EVENT**

On April 13, 2002 at 03:16 hours, during plant heatup with Unit 2 at cold shutdown and RCS pressure approximately 300 psig, evidence of leakage discovered by Operations personnel during a plant startup walkdown was reported on the "B" residual heat removal (RHR) pump 3/4-inch balance line [EISS-BP, PSP]. At 05:05 hours, an engineering inspection determined that the 3/4-inch balance line had a through-wall leak approximately 1/2" from a sockolet which was attached to the suction piping of the "B" RHR pump.

This through-wall leak was not isolable from the suction of "A" or "B" RHR pumps because it was upstream of "B" RHR pump suction isolation. Thus, both trains of RHR were declared inoperable. However, both trains of RHR continued to operate. Additionally, both trains of RHR remained capable of performing their intended function because the structural integrity of the pipe was maintained. RHR was declared inoperable due to the ASME Code noncompliance, and not due to loss of safety function.

Technical Specification 3.1.A.1.d.1 requires a minimum of two non-isolated loops, consisting of any combination of RCS loops or RHR loops, to be operable. Because both trains of RHR were inoperable and no reactor coolant system (RCS) loops were operable at that time due to plant conditions, the Technical Specification 3.1.A.1.d.1 requirements were not met. This condition is therefore reportable pursuant to 10CFR50.73(a)(2)(i)(B).

The piping leak was not isolable from the RHR suction header, therefore the two independent trains of the RHR System were declared inoperable. This condition is therefore also reportable pursuant to 10CFR50.73(a)(2)(vii).

On April 13, 2002, ultrasonic thickness (UT) measurements were performed for a length of approximately 16-inches on the "B" RHR pump 3/4-inch balance line with the lowest reading measuring 0.109-inches, which is above the manufacturer's tolerance of 0.099-inches minimum. UT measurements were also taken on the "A" RHR pump 3/4-inch balance line and were satisfactory. Based on these UT measurements it was determined that the leak was localized, and there were no indications that the piping was degrading at other locations. Periodic monitoring of the leakage was initiated.

Plant heatup proceeded, keeping the RHR System in service, until the second RCS loop was put into operation at 23:56 hours on April 13, 2002, which restored compliance with the Technical Specifications.

On April 14, 2002, Engineering performed a visual inspection of the leak. Two circumferential, linear indications were found in the 3/4-inch diameter, schedule 40 pipe downstream from the sockolet that is welded to the 14-inch line. Some surface pitting was apparent around the leak location. The leak was very slow (approximately 2-3 drops per minute) and continued to be visually monitored periodically to verify the piping was not

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

FACILITY NAME (1) <b>SURRY POWER STATION</b>	DOCKET <b>05000 - 281</b>	LER NUMBER (6)			PAGE (3) <b>3 OF 4</b>
		YEAR <b>2002</b>	SEQUENTIAL NUMBER <b>001</b>	REVISION NUMBER <b>00</b>	

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

degrading.

On April 15, 2002, Engineering performed another visual inspection of the leak. The indications were re-measured and no changes were found in the linear lengths. Boric acid was found solidifying at the leak location. With the system in service, the linear indications were not expected to propagate. The 3/4-inch balance line on the "A" RHR pump was visually inspected with no indications of any through-wall leaks.

On April 16, 2002, with RCS loops in operation and the RCS temperature above 200 degrees F, the RHR System was taken out of service and the 3/4-inch diameter line was replaced. Post maintenance testing was completed, and the RHR System was declared operable at 16:29 hours on April 16, 2002.

**2.0 SIGNIFICANT SAFETY CONSEQUENCES AND IMPLICATIONS**

Even with this through-wall leak in the balance line associated with the "B" pump, both RHR pumps were still able to perform their intended function because the structural integrity of the pipe was maintained. RHR was declared inoperable due to ASME Code, Section XI, Class II noncompliance, and not due to loss of safety function.

**3.0 CAUSE**

Following removal of the leaking line, the failed segment was sectioned to allow detailed examination with the scanning electron microscope. The 3/4-inch section of RHR pipe failed as a result of transgranular stress corrosion cracking (TGSCC) initiated from the outside surface from an external foreign contaminant which caused surface pitting. It was from these pits that the two cracks appear to have initiated. One of these cracks propagated through the pipe until a through-wall leak developed. Based on the width of the crack and the amount of oxide on the fracture, the crack growth rate appears to have been very slow. The pitting that was present on the outer surface of the pipe adjacent to the cracks was suggestive of chloride-induced corrosion pitting. The source of the chloride contamination is unknown.

**4.0 IMMEDIATE CORRECTIVE ACTION(S)**

Plant heatup proceeded, keeping the RHR System in service, until the second RCS loop was put into operation at 23:56 hours on April 13, 2002, which restored Technical Specification compliance. On April 16, 2002, with RCS loops in operation and the RCS temperature above 200 degrees F, the RHR System was taken out of service and the 3/4-inch diameter line was replaced.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

FACILITY NAME (1) <b>SURRY POWER STATION</b>	DOCKET 05000 - 281	LER NUMBER (6)			PAGE (3) 4 OF 4
		YEAR 2002	SEQUENTIAL NUMBER 001	REVISION NUMBER 00	

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

**5.0 ADDITIONAL CORRECTIVE ACTIONS**

Post maintenance testing was completed, and the RHR System was declared operable at 16:29 hours on April 16, 2002.

**6.0 ACTIONS TO PREVENT RECURRENCE**

A VT-2 inspection will be completed on the Unit 1 RHR 3/4-inch balance lines during the next cold shutdown of Unit 1 to detect flaws such as TGSCC, or pitting which could lead to TGSCC.

**7.0 SIMILAR EVENTS**

None.

**8.0 MANUFACTURER/MODEL NUMBER**

The 3/4-inch line was schedule 40, 304 stainless steel.

**9.0 ADDITIONAL INFORMATION**

None.