


---

**TMI Tube R66-T130 SGB  
Update**


**10/26/01**

# Background

- Bobbin inspection identified 4 tubes with OD wear at secondary face of upper tube sheet, confirmed through Plus Point
- Based on pattern of wear on adjacent tubes plugged tube R66-T130 was suspected (see drwg next page)
- Tube R66-T130
  - Plugged in 1986 (1R5) due to ID/IGA near 5th TSP
  - No degradation identified at UTS based on bobbin and 8x1 probe in 1986
  - UTS I-600 plug was replaced in 1997 (1R12)



# OTSG Tube Sheet Map



# Corrosion Assisted Fatigue

- Review ID and OD corrosion experience of OTSG's
- Perform inspection of deplugged tubes in OTSG A and B outer periphery (high velocity) for unexpected corrosion
- Define a critical flaw size
- Laboratory analysis of pulled tubes to identify failure mechanism

# Corrosion

- Deplugged tube inspections
- Tube pull analysis
- Review of Degradation Assessment for industry experience and inspection capabilities
- In situ pressure testing of tubes with corrosion related degradation in vicinity of UTS

# Other Potential Failure Mechanisms

- Foreign Objects
  - Secondary side visual inspection in vicinity of R66-T130
  - Laboratory Analysis for failure mechanism
  - Loose parts monitoring
  - ECT data for presence of Foreign Object
- Mechanical Failure
  - Review operating cycle and cooldown history
  - Evaluate tube loads during shutdown
  - Evaluate impact of tube locking at TSP for cooldown loads
  - Tube pull failure mechanism
- Leaking tube plug
  - Tube pull dimensional analysis
  - Primary to secondary leak experience

# Tube Pull Plans

- R165-T130 (Largest Wear Scar)
  - Dimensional measurement of wear
  - Leak test leading to potential burst
  - Characterize leak opening
  - Pressure test with bladder over full length of wear
  - Corrosion analysis
  - SEM of fracture surface
  - Correlation to ECT results



## Results to Date

- Inspection of deplugged unstabilized tubes in OTSG A and B outer periphery (~outer 3 rows) for unexpected degradation
  - 44 deplugged tubes in OTSG A inspected with +Pt +/- 2” of secondary face of upper tube sheet
    - No unexpected indications - ID/IGA well within repair criteria
  - 20 deplugged tubes in OTSG B to be inspected with +Pt +/- 2” of secondary face of upper tube sheet - 10/29 0900

# Neighbor Tube Wear

Tube	Max Depth (%)	Avg. Depth	Length	Calculated Burst Press. (90/50) psi	In Situ Pressure (psi)	In Situ Leak Rate (gpm)
R65-T129	37	30	2"	6000	4350	0
R66-T131	62	25	~8.5"	4000	4360	3.2 @ 450 psi
R67-T130	41	24	~4.6"	5500	4350	0
R65-T130	92	35	~4.6"	1800	N/A	N/A

- Structural requirement of 3ΔP is 3950 psi corrected test pressure is 4350 p:
- R66-T131 attained the target test pressure of 4350 psi. Prior to reaching the required 2 minute hold time the tube began to leak greater the the test pump capacity
- R66-T131 will be pulled and laboratory tested to determine if a burst occurred
- R65-T130 will be leak and burst tested in the laboratory

of R66-T130

to inspection

ube severed at

be sheet

om upper tube end

identified

## Extent of Condition

- 100% inspection of in service tubes with qualified techniques
- Identification of other plugged and unstabilized tubes in the periphery
- Inspection of deplugged tubes in OTSG A and OTSG B
- Bobbin inspection of severed tube R66-T130
- Identify SG secondary side velocity profiles
- Define critical flaw size

# Industry OTSG Feedwater Chemistry Standards

- EPRI Secondary Chemistry Water Chemistry Guideline Limits for OTSG Feedwater
  - Action Level 1 Limits
    - Sodium - 1.0 ppb
    - Chloride - 3.0 ppb
    - Sulfate - 1.0 ppb
    - Iron - 5 ppb
- INPO Industry Median Values for Calculating Chemistry Performance Index (CPI)
  - Sodium - 0.3 ppb
  - Chloride - 0.5 ppb
  - Sulfate - 0.75 ppb
  - Iron - 1.8 ppb

# TMI Feedwater Chemistry Cycle 14 Results

## Statistical Analysis of All Feedwater Chemistry Results For Cycle 14

	C l, p p b	F e, p p b	S O <sub>4</sub> , p p b	N a, p p b
A v e r a g e	0 . 3 6	0 . 7 3	0 . 3 2	0 . 2 3
S t a n d a r d D e v i a t i o n	0 . 1 8	0 . 4 9	0 . 1 1	0 . 2 2
M e d i a n	0 . 3 0	0 . 6 9	0 . 3 7	0 . 2 1

Data Shows That Feedwater Chemistry Met or Exceeded Industry Standards for Contaminant Control

## Summary

- Potential failure mechanisms have been identified
- Actions are being taken to assess the potential root cause
- Impact of root cause on the operational assessment is being considered
- Significant actions being taken to obtain necessary information to support root cause investigation

Three Mile Island Nuclear Station, Unit No. 1

cc:

Site Vice President - Three Mile Island Nuclear  
Station Unit 1  
AmerGen Energy Company, LLC  
P. O. Box 480  
Middletown, PA 17057

Senior Vice President Nuclear Services  
Exelon Generation Company, LLC  
4300 Winfield Road  
Warrenville, IL 60555

Vice President - Mid-Atlantic Operations Support  
Exelon Generation Company, LLC  
200 Exelon Way, KSA 3-N  
Kennett Square, PA 19348

Senior Vice President -  
Mid Atlantic Regional Operating Group  
Exelon Generation Company, LLC  
200 Exelon Way, KSA 3-N  
Kennett Square, PA 19348

Vice President -  
Licensing and Regulatory Affairs  
Exelon Generation Company, LLC  
4300 Winfield Road  
Warrenville, IL 60555

Regional Administrator  
Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Chairman  
Board of County Commissioners  
of Dauphin County  
Dauphin County Courthouse  
Harrisburg, PA 17120

Chairman  
Board of Supervisors  
of Londonderry Township  
R.D. #1, Geyers Church Road  
Middletown, PA 17057

Senior Resident Inspector (TMI-1)  
U.S. Nuclear Regulatory Commission  
P.O. Box 219  
Middletown, PA 17057

Director - Licensing - Mid-Atlantic Regional  
Operating Group  
Exelon Generation Company, LLC  
Nuclear Group Headquarters  
Correspondence Control  
P.O. Box 160  
Kennett Square, PA 19348

David J. Allard, Director  
Bureau of Radiation Protection  
Pennsylvania Department of  
Environmental Protection  
P.O. Box 8469  
Harrisburg, PA 17105

Three Mile Island Nuclear Station Unit 1  
Plant Manager  
AmerGen Energy Company, LLC  
P. O. Box 480  
Middletown, PA 17057

Regulatory Assurance Manager - Three Mile  
Island Unit 1  
AmerGen Energy Company, LLC  
P.O. Box 480  
Middletown, PA 17057

John F. Rogge, Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Michael A. Schoppman  
Framatome ANP  
Suite 705  
1911 North Ft. Myer Drive  
Rosslyn, VA 22209

Three Mile Island Nuclear Station, Unit No. 1

cc: continued

Vice President, General Counsel and Secretary  
Exelon Generation Company, LLC  
300 Exelon Way  
Kennett Square, PA 19348

Dr. Judith Johnsrud  
National Energy Committee  
Sierra Club  
433 Orlando Avenue  
State College, PA 16803

Eric Epstein  
TMI Alert  
4100 Hillsdale Road  
Harrisburg, PA 17112

Correspondence Control Desk  
Exelon Generation Company, LLC  
200 Exelon Way, KSA 1-N-1  
Kennett Square, PA 19348

Manager Licensing - Oyster Creek and Three Mile  
Island  
Exelon Generation Company, LLC  
Nuclear Group Headquarters  
Correspondence Control  
P.O. Box 160  
Kennett Square, PA 19348