



South Texas Project Electric Generating Station P.O. Box 289 Wadsworth, Texas 77483

August 13, 2002  
NOC-AE-02001384  
File No.: G25  
10CFR50.73  
STI: 31480547

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
One White Flint North  
11555 Rockville Pike  
Rockville, MD 20852

South Texas Project  
Unit 2  
Docket No. STN 50-499  
Licensee Event Report 02-002

Unit 2 Manual Reactor Trip Due to Unexpected Closure of Feedwater Isolation Valve

Pursuant to 10CFR50.73, South Texas Project submits the attached Unit 2 Licensee Event Report 02-002 regarding the manual reactor trip of Unit 2 due to the unexpected closure of the feedwater isolation valve for the 2C Steam Generator. The unexpected closure of the feedwater isolation valve resulted from a blown fuse in the control circuit for a safety solenoid for the feedwater isolation valve. The blown fuse was the result of a shorted safety solenoid surge suppression device.

This event did not have an adverse effect on the health and safety of the public.

Corrective action number 3 is the only commitment contained in this event report.

If there are any questions on this submittal, please contact W. R. Bealefield, Jr. at (361) 972-7696 or me at (361) 972-7849.

  
E. D. Halpin  
Plant General Manager

Attachment: LER 02-002 (South Texas, Unit 2)

IE22

cc:

(paper copy)

Ellis W. Merschoff  
Regional Administrator, Region IV  
U.S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 400  
Arlington, Texas 76011-8064

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
One White Flint North  
11555 Rockville Pike  
Rockville, MD 20852

Richard A. Ratliff  
Bureau of Radiation Control  
Texas Department of Health  
1100 West 49th Street  
Austin, TX 78756-3189

Cornelius F. O'Keefe  
U. S. Nuclear Regulatory Commission  
P. O. Box 289, Mail Code: MN116  
Wadsworth, TX 77483

C. M. Canady  
City of Austin  
Electric Utility Department  
721 Barton Springs Road  
Austin, TX 78704

(electronic copy)

A. H. Gutterman, Esquire  
Morgan, Lewis & Bockius LLP

M. T. Hardt/W. C. Gunst  
City Public Service

Mohan C. Thadani  
U. S. Nuclear Regulatory Commission

R. L. Balcom/D. G. Tees  
Reliant Energy, Inc.

A. Ramirez  
City of Austin

C. A. Johnson/A. C. Bakken III  
AEP - Central Power and Light Company

Jon C. Wood  
Matthews & Branscomb

Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

### LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

<b>1. FACILITY NAME</b> South Texas Unit 2	<b>2. DOCKET NUMBER</b> 05000 499	<b>3. PAGE</b> 1 OF 5
---	--------------------------------------	--------------------------

**4. TITLE**  
Unit 2 Manual Reactor Trip Due to Unexpected Closure of Feedwater Isolation Valve

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
06	14	2002	2002	02	00	08	13	2002	FACILITY NAME	DOCKET NUMBER
										05000
										05000

<b>9. OPERATING MODE</b>	1	<b>11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR : (Check all that apply)</b>										
		20.2201(b)			20.2203(a)(3)(ii)			50.73(a)(2)(ii)(B)			50.73(a)(2)(ix)(A)	
<b>10. POWER LEVEL</b>	100	20.2201(d)			20.2203(a)(4)			50.73(a)(2)(iii)			50.73(a)(2)(x)	
		20.2203(a)(1)			50.36(c)(1)(i)(A)			x 50.73(a)(2)(iv)(A)			73.71(a)(4)	
		20.2203(a)(2)(i)			50.36(c)(1)(ii)(A)			50.73(a)(2)(v)(A)			73.71(a)(5)	
		20.2203(a)(2)(ii)			50.36(c)(2)			50.73(a)(2)(v)(B)			OTHER Specify in Abstract below or in NRC Form 366A	
		20.2203(a)(2)(iii)			50.46(a)(3)(ii)			50.73(a)(2)(v)(C)				
		20.2203(a)(2)(iv)			50.73(a)(2)(i)(A)			50.73(a)(2)(v)(D)				
		20.2203(a)(2)(v)			50.73(a)(2)(i)(B)			50.73(a)(2)(vii)				
		20.2203(a)(2)(vi)			50.73(a)(2)(i)(C)			50.73(a)(2)(viii)(A)				
20.2203(a)(3)(i)			50.73(a)(2)(ii)(A)			50.73(a)(2)(viii)(B)						

**12. LICENSEE CONTACT FOR THIS LER**

NAME William R. Bealefield, Jr.	TELEPHONE NUMBER (Include Area Code) 361-972-7696
------------------------------------	--

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX
	EF	RECT	VO30	Yes					

<b>14. SUPPLEMENTAL REPORT EXPECTED</b>				<b>15. EXPECTED SUBMISSION DATE</b>		
YES (If yes, complete EXPECTED SUBMISSION DATE)	X	NO		MONTH	DAY	YEAR

**16. ABSTRACT** (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On June 14, 2002 Unit 2 was operating in Mode 1 at 100% power. At approximately 0435 Unit 2 lost feedwater flow to steam generator 2C during the performance of Feedwater Valve Operability Test. This test performs a partial stroke of the feedwater isolation valve from 100 percent open to 90 percent open. During the test the valve failed closed. After verifying there was no indication of feedwater flow to the 2C steam generator, the Unit Supervisor directed the Reactor Operator to manually trip the reactor. The reactor was in the tripped condition approximately 15 seconds following closure of the feedwater isolation valve (FWIV). The unexpected closure of the 2C feedwater isolation valve resulted from a blown fuse in the class-1E control circuit for the B-train safety solenoid for the 2C isolation valve. The blown fuse was the result of a shorted rectifier assembly used for surge suppression on the B-train safety solenoid for the 2C FWIV.

This event resulted in no personnel injuries, offsite radiological releases or damage to important safety related equipment. Following the reactor trip, auxiliary feedwater automatically actuated as expected. There were no human performance issues or challenges to plant safety and the plant responded as expected.

**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
South Texas Unit 2	05000 499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2	OF 5
		2002	02	00		

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

DESCRIPTION OF EVENT

On June 14, 2002 while operating at 100 percent power, Unit 2 lost feedwater flow to steam generator 2C while performing Feedwater Valve Operability Test. This test performs a partial stroke of the feedwater isolation valve from 100 percent to 90 percent open. During the test, the 2C feedwater valve failed closed.

This event occurred following the successful testing of the 2A and 2B main feedwater isolation valves (FWIV). At 0435, the control room operator pushed the test button for the 2C FWIV, in accordance with the surveillance procedure, for approximately 1 second and then released it. The 2C FWIV continued to go in the closed direction, going full closed in approximately four seconds. The plant operator stationed at the FWIV notified the main control room by radio that the valve was continuing to go closed as it passed through the 50 percent open position. The plant operator and the secondary Reactor Operator in the control room reported the valve had gone full closed. The Unit Supervisor directed the secondary Reactor Operator to check feedwater flow to the 2C steam generator. The secondary reactor operator reported there was no indication of feedwater flow to the 2C steam generator. The Unit Supervisor ordered the primary Reactor Operator to manually trip the reactor. Following the reactor trip, neither the steam generator power operated relief valves or the steam generator safety valves opened, nor were they challenged. Auxiliary feedwater automatically actuated. There were no human performance issues or challenges to plant safety and the plant responded as expected.

The unexpected closure of the 2C FWIV resulted from a blown fuse in the Class-1E control circuit for the 2C FWIV B train safety solenoid. The blown fuse was the result of a shorted B train safety solenoid surge suppression device that contains four series parallel diodes. Two of the four internal diodes were shorted providing a direct short-circuit path around both redundant safety solenoid coils.

EVENT SIGNIFICANCE

This event resulted in no personnel injuries, offsite radiological releases or damage to important safety related equipment. An evaluation of this event by Probabilistic Risk Assessment determined the Conditional Core Damage Probability was  $3.1 \times 10^{-7}$  which shows the risk was minimal. This event is an important issue for the station due to the impact on plant reliability and because it caused the loss of all feedwater flow to one steam generator while at 100 percent power. Feedwater flow is necessary to maintain the steam generator's ability to remove heat from the reactor. The 2A, 2B and 2D steam generators were available during this event to remove heat from the reactor. This loss of feedwater flow challenged the automatic actuation of the auxiliary feedwater system and the operating crew's response to this abnormal situation.

**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
South Texas Unit 2	05000 499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3	OF 5
		2002	02	00		

**NARRATIVE** (If more space is required, use additional copies of NRC Form 366A) (17)

CAUSE OF EVENT

The cause of the unexpected closure of 2C FWIV was a shorted surge suppression device in the Class-1E control circuit.

The suppression device contains four series parallel diodes and is actually a diode bridge. The diode bridge is used for surge suppression across the safety related trip solenoids. This short caused the fuse to blow in the control circuit, which de-energized the B-train safety solenoid. De-energizing the B-train solenoid dumps hydraulic fluid from the valve actuator allowing the FWIV to close.

The failed diode bridge was sent off site for a laboratory failure analysis to determine the cause of the failure. The report from the laboratory listed the cause for the diode failures as electrical overstress. The location of the melt sites on the two short circuited diodes indicate that one was most likely damaged by a reverse bias voltage transient and the other by a forward current transient. The cause for the electrical overstress cannot be determined. The control circuit was analyzed and found to be satisfactory. The diodes are rated at 10 amps and 600 volts, which is adequate for the circuit in which they are installed. The diodes are normally reverse biased at 125 volts direct current and the control circuit is fused at 3 amps. The root cause for the electrical overstress is unknown and considered to be a random failure. See Additional Information section for possible failure scenarios.

CORRECTIVE ACTIONS

1. Replaced the blown fuse and the failed surge suppression device for the 2C FWIV.  
Completed June 20, 2002
  
2. Checked the condition of individual diodes in the bridge circuits for 2A, 2B and 2D FWIVs.  
Completed, June 17, 2002, no additional diode damage was found.
  
3. Test Unit 1 FWIV solenoid operated dump valves for failed diodes during a forced outage or during the refueling outage in 2003. Due date April 30,2003

ADDITIONAL INFORMATION

Following the reactor trip, the Source Range nuclear instrumentation detectors were automatically energized, at approximately 0447 the operators noted that both instrument channels were not indicating a count rate. The Extended Range nuclear instruments were operating and were monitored to determine reactor status. The Source Range detectors were found to be failed and were replaced prior to reactor startup.

**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
South Texas Unit 2	05000 499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4	OF 5
		2002	02	00		

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

ADDITIONAL INFORMATION (cont)

The risk of similar failures on this and other FWIV control circuits was evaluated based upon the potential circuit issues that could lead to surge suppressor diode failure, none were identified. Available operating experience and vendor failure history information was evaluated and indicated no known history of failure for these devices. No known circuit design issues were identified that could account for the failure. As a remedial action, all remaining Unit 2 FWIV diodes were functionally checked to ensure that no single diode failures existed. This testing was completed before the unit was restarted. A condition report was prepared to perform the same inspections and testing for the Unit 1 diodes during a forced outage or during the next refueling outage in 2003. The FWIVs are susceptible to this type of failure and other single point failures during the performance of surveillance testing and during normal operation. Each FWIV has two safety related solenoids that can trip the valve closed. Each safety solenoid consists of two solenoids, one is energized all the time and the other de-energizes 60 seconds after the FWIV is opened. Both solenoids are required to energize in order to open the FWIV, with only one required to maintain the valve open. During this plant trip, the de-energized solenoid was the one with the failed surge suppression device.

Modification documentation has been prepared to install the FWIV Energize to Actuate modifications in Units 1 and 2. These modifications will eliminate single point control circuit failures that lead to valve closure.

A Condition Report work order to test the FWIV circuits for hidden failures and degraded conditions has been developed. These tests will be performed, during a forced or planned outage, until the Energize to Actuate modifications are completed for the FWIVs.

A review of South Texas condition report events revealed no events where the apparent cause referenced a diode failure for a FWIV. Diode failures have been identified for the main generator exciter and rod control power blocking diodes. These applications are different in that those diodes are critical current carrying components that opened resulting in circuit interruption. Numerous fuse failures were found but none referenced to diode failures.

A review of industry events found numerous diode failures in Protection systems. Fifteen events found "random/Unknown" failure modes. Ten failure events were identified as "age related". Two failures resulted from "design/installation" deficiencies and no other failure mechanisms had more than one event.

**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
South Texas Unit 2	05000 499	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5	OF 5
		2002	02	00		

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

ADDITIONAL INFORMATION (cont)

The event review team for this event evaluated the FWIV Class-1E control circuit for the following potential issues that could lead to surge suppression diode failure:

1. Over-current stress

The surge suppression device is a 10-ampere, full-wave bridge rectifier. The maximum current expected through the diodes in this application is less than 0.2 amperes and lasts less than one second. No transient current sources were identified in this circuit that would be capable of stressing these diodes and the 3-ampere supply fuses that are rated well below the diode rating would most likely limit such a condition before diode damage could occur.

2. Over-voltage stress

The peak-inverse-voltage rating of the diodes is 600 volts; well above the circuit maximum of approximately 140 volts. Similar to the above, no transient voltage sources were identified in the circuit that would be capable of stressing these diodes.

3. Over-temperature stress

The rated operating temperature of these diodes is 100 degrees-C, well above the diodes located in the isolation valve cubicle temperature, and there is no internal heating of these diodes since they are for surge suppression only and do not carry any circuit current. Laboratory failure analysis confirmed there was no evidence of over temperature stress.

4. Manufacturing defects

The supplier, Valcor, was contacted for information on failure history of the device, expected life and temperature effects, device improvement history and Class-1E qualification basis information. Valcor provided data indicating that there are literally thousands of these devices in service worldwide with no reported operational failures. Our operating experience search yielded only one similar event, and it was a different manufacturer.

5. Mechanical failures

Mechanical failures such as vibration, dropping, and mishandling were evaluated briefly but it was concluded that mechanical damage would most likely result result in an open rather than a shorted diode.

The failed surge suppression device/rectifier assembly was manufactured by Valcor, manufacturer part number S1140-8-1.

Diode failures referencing vendor Valcor, the supplier of the South Texas FWIV diodes, were reviewed. Four events were found with two finding no known cause, one failure due to age and one failure due to overload when a valve motor seized. There does not appear to be a generic issue with the vendor for this component.