

conducted for "extent of condition" purposes, but did not detect recordable indications.(1)

Upon commencement of required ASME Code Section XI repair activities of the affected CRDM nozzles, Duke implemented required dye-penetrant testing (PT) of the repair weld butter and detected the presence of additional indications in two of the nine degraded penetration nozzles. While implementing the excavations and repairs of these flawed areas, Duke identified that the flaw indications (cracks) in each nozzle were significantly larger than was originally revealed by PT examinations, and had significantly sized circumferential orientations that grew into the nozzle just above the root of the J-groove weld. Further investigations and metallurgical examinations revealed that these cracks had initiated from the outside diameter (OD) of the CRDM penetration nozzles. The circumferential crack in the #56 CRDM nozzle was through-wall, and the #50 nozzle had pin hole through-wall indications. These circumferential portions of the cracks followed the weld profile contour, and were nearly 165* in length.

Primary water stress corrosion cracking (PWSCC) is a form of stress corrosion cracking (SCC), which is an age-related cracking phenomenon. SCC can only occur if the following material property and environmental conditions are present: (1) the material must be in a highly stressed environment, (2) a corrosive environment must be present, and (3) the material must be of a type that is susceptible to SCC. RPV head penetrations, including CRDM nozzles, provide the function of maintaining the reactor coolant system (RCS) pressure boundary. Cracking of CRDM nozzles and welds is a degradation of the primary RCS boundary. All CRDM nozzles are fabricated from Inconel 600 (Alloy 600), a material that is known to be susceptible to PWSCC when exposed in highly stressed, high temperature, borated coolant environments. Reports of stress corrosion cracking in Alloy 600 pressurizer nozzles and instrumentation nozzles to the reactor coolant hot legs of pressurized water reactors confirm that Alloy 600 is a material that is susceptible to SCC. If undetected and left uncorrected, PWSCC of a VHP nozzle has the potential to result in leakage of the reactor coolant from the pressure boundary and possibly to a catastrophic failure of the nozzle. The later event results in a small-break loss-of-coolant-accident (LOCA) for the facility.

The VHP nozzles are joined to the upper vessel heads using interference fits and partial penetration J-groove welds fabricated from Alloy 182, which is an Inconel filler metal material with material properties similar to Alloy 600. Previous staff reviews of the preliminary safety evaluation submittals from the Westinghouse, Combustion Engineering, and Babcock and Wilcox Owners Groups (*i.e.*, as given in Topical Reports), indicate that the methods for fabricating CRDM nozzles have been basically the same for all U.S. pressurized water reactors.

Crack initiation and growth theories model that cracks initiate and grow along planes that are perpendicular to the stress vectors acting on them. During power operations of the reactors, for regions of the nozzles adjacent to the contour of the J-groove weld, the highest tensile stresses of magnitude are represented by the nozzle hoop stresses. Therefore, in the regions of the nozzles adjacent to the contour of the J-groove welds, cracking is postulated to occur in axial-oriented planes. In contrast, in nozzle regions located at vertical positions just above the root of the J-groove welds, the axial stresses have the high tensile stress magnitudes (with the highest tensile stress magnitudes occurring at the OD of the nozzles). Thus, for the nozzle regions located just above the root of the J-groove welds, any cracking would be postulated to initiate from the outer surface of the nozzle along a circumferentially oriented plane. However, the following events would have to take place for initiation of a circumferential flaw to be possible at these locations: (1) initiation of an axial crack would need to occur, (2) the stress intensity factor for the crack tip would need to be of a magnitude high enough to grow the axial crack through-wall such that a sufficient leak path exist to allow for leakage of the coolant into the annular region of the nozzle, and (3) the environment resulting from the leakage would have to be corrosive enough to initiate the circumferential flaw from the OD surface of the nozzle. The Duke Power Company's modeling of the circumferential flaws reported in the four ONS CRDM nozzles is consistent with these stress and leakage analyses and assumptions.

B. Generic Letter 97-01, Topical Report MRP-44, Part 2, and NRC Bulletin 2001-01

Axial cracking in pressurized water reactor (PWR) CRDM nozzles has been previously identified, evaluated, and repaired. Numerous small-bore Alloy 600 nozzles and pressurizer heater sleeves have experienced leaks attributed to PWSCC. Generally, these components, including those for ONS3, are exposed to temperatures of 560°F or higher and to primary water. However, circumferential cracks above the weld from the OD to the inside diameter (ID) have not been previously identified in any of the VHP nozzles in the U.S.

In 1991, an action plan was implemented by the NRC staff to address PWSCC of Alloy 600 vessel head penetrations (VHPs) at all U.S. PWRs. This action plan included a review of the safety assessments by the PWR owners groups (Westinghouse Owners Group, Combustion Engineering Owners Group, and Babcock & Wilcox Owners Group) submitted for staff review on June 16, 1993, by the Nuclear Management and Resource Council (NUMARC, now the Nuclear Energy Institute [NEI]).

After reviewing the industry's safety assessments and examining the overseas inspection findings, the NRC staff concluded, in a safety evaluation (SE) dated November 19, 1993, that PWR CRDM nozzle and weld cracking was not an immediate safety concern. The bases for this conclusion were that if PWSCC occurred (1) the cracks would be predominately axial in orientation, (2) the axial cracks would result in detectable leakage before catastrophic failure, and (3) the leakage would be detected during visual examinations performed as part of surveillance walkdown inspections before significant damage to the RPV head would occur. However, the NRC staff noted concerns about potential circumferential cracking (which would need to be addressed on a plant-specific basis), high residual stresses from initial manufacture and from tube straightening sometimes done after welding, and the need for enhanced leakage monitoring.

By letter dated March 5, 1996, NEI submitted a white paper entitled "Alloy 600 RPV Head Penetration Primary Stress Corrosion Cracking," which reviewed the significance of PWSCC in PWR VHPs and described how the PWR licensees were managing the issue. NEI assumed that the issue was

primarily an economic issue rather than a safety issue, and described an economic decision tool to be used by PWR licensees to evaluate the probability of a VHP developing a crack or a through-wall leak during a plant's lifetime. This information would then be used by a PWR licensee to evaluate the need to conduct an inspection of the VHP nozzles at its plant.

To verify the conclusions in the industry's safety assessments, sampling inspections were performed at three PWR units in 1994. The results of these domestic inspections were consistent with the February 1993 analyses by the PWR owners groups, the staff's SE dated November 19, 1993, and the PWSCC reported in the VHP nozzles of European reactors. On the basis of the results of the first five inspections of U.S. PWRs, the PWR owners groups' analyses, and the European experience, the NRC staff determined that it was probable that CRDM nozzles at other plants contained similar axial cracks, but that such cracking did not pose an immediate- or near-term safety concern. Further, the NRC staff recognized that the scope and timing of inspections may vary for different plants, depending on their individual susceptibility to this form of degradation. However, in its SE of November 19, 1993, the staff identified that degradation of the CRDM and other VHP nozzles was an important safety consideration in the long term because of the possibility of (1) exceeding the ASME Code safety margins if the cracks are sufficiently deep and continue to propagate during subsequent operating cycles and (2) eliminating a layer of defense in depth for plant safety.

On April 1, 1997, NRC issued Generic Letter (GL) 97-01, "Degradation of Control Rod Drive Mechanism Nozzle and Other Vessel Closure Head Penetrations," which requested addressees to inform the staff of their inspection activities related to VHPs. Based on the industry's GL 97-01 response, which took credit for periodic inspections of the RPV head, the staff agreed that the conclusions in its November 19, 1993, SE remained valid.

The recent identification of significant circumferential cracking in three of the VHP nozzles at ONS3 in March 2001, and later in a single VHP nozzle at Oconee Nuclear Station, Unit 2 (ONS2) in April

2001, raises concerns about a potentially risk-significant generic condition affecting all domestic PWRs. The reports of circumferential cracking are significant in that they represent the first reported occurrences of circumferential cracking in the CRDM nozzles of U.S. PWRs. The manner in which the circumferential cracks were detected at ONS3 is also significant in that they were detected during the repair process. Although the normal inspection efforts and expanded inspection efforts to monitor for additional signs of degradation (*i.e.*, bare metal examinations) did reveal the evidence of leakage from the VHP nozzles, they were not capable of indicating the presence of the circumferential cracking that was occurring in the nozzles. The cracking reported at ONS2 and ONS3 reinforces the importance of examining the upper PWR RPV head area using NDE techniques that are capable of detecting recordable flaw indications in the VHP nozzles and their associated J-groove welds and heat-affected-zones. Presently, Paragraph IWA-5242 of Section XI, ASME Boiler and Pressure Vessel Code, does not require licensees to remove RPV head insulation materials before visually inspecting their reactor vessel heads and VHP nozzles.

After the initial finding of significant circumferential cracking at ONS3, the NRC held a public meeting with the EPRI Materials Reliability Program (MRP) on April 12, 2001, to discuss CRDM nozzle circumferential cracking issues. During the meeting, the industry representatives indicated that they were developing a generic safety assessment, recommendations for revisions of near-term inspections, and long-term inspection and flaw evaluation guidelines.

On May 18, 2001, the MRP submitted EPRI Report TP-1001491, Part 2, "PWR Materials Reliability Program Interim Alloy 600 Safety Assessments to US PWR Plants (MRP-44), Part 2: Reactor Vessel Top Head Penetrations," (henceforth MRP-44, Part 2) to provide an interim safety assessment for PWSCC of Alloy 600 VHP nozzles and Alloy 182 J-groove welds in PWR-designed plants. The approach taken in the MRP-44, Part 2, uses an assessment of the relative susceptibility of each PWR to OD-initiated or weld-initiated PWSCC based on the operating time and temperature of the penetrations. Based upon this simplified model, provided in Appendix B of the MRP-44, Part 2, each PWR plant was ranked by the MRP according to the operating time (in EFPY) required for the plant to reach an effective

time-at-temperature condition equivalent to the worst case degraded condition for ONS3. To address the experience at ONS, the MRP recommended that plants ranked within 10 EPFY of ONS3 and having fall 2001 outages should perform a visual inspection of the RPV top head capable of detecting small amounts of leakage similar to that observed at the Oconee units and Arkansas Nuclear One, Unit 1 (ANO1).

On June 7, 2001, the NRC held a public meeting at which the MRP provided initial responses to questions on the MRP-44, Part 2, report that the NRC staff had identified and transmitted to the MRP on May 25, 2001. The NRC staff provided additional questions on various aspects of the MRP-44, Part 2, report in a letter to the MRP, dated June 22, 2001. In this letter, the staff informed the MRP that the staff had two areas of contention with the industry's methodology provided in MRP-44, Part 2. With respect to the first area of contention, the staff informed the MRP that it did not agree with the MRP's conclusion that nozzle leaks would be detectable on all vessel heads. With respect to the second area of contention, the staff informed the MRP that it was concerned with the lack of consideration of an applicable crack growth rate for cracks initiated from the outer-diameter (OD) surfaces of the VHP nozzles or in their associated J-groove welds. With respect to this area of contention, the staff informed the MRP that it did not agree with the MRP conclusion in the responses of June 7, 2001, that the appropriate crack growth rate for OD-initiated cracking of VHP nozzles is adequately represented by crack growth data for Alloy 600 steam generator tubes under primary water environments.

C. NRC Bulletin 2001-01

On August 3, 2001, the Commission issued NRC Bulletin 2001-01, "Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles," to address the generic safety implications of the pressure boundary leakage at the Oconee and Arkansas Nuclear One-Unit 1 power plants on the industry's VHP nozzles, and to discuss its technical bases for the recommended graded-inspection program for U.S. VHP nozzles. In the bulletin, the staff discussed the technical aspects of plant designs that could impede the ability of visual VT-2 examination methods to detect leakage from the CRDM nozzles of commercial

U.S. PWRs.

The staff emphasized that the ability to detect reactor coolant leakage from the VHP nozzles could be limited if the visual examination methods for detecting the leakage were incapable of distinguishing between boric acid residue deposited as a result of VHP nozzle leaks and those previously deposited as a result from leakage from other sources. The staff also emphasized that it was critical for the industry to establish defensible crack growth rates for PWSCC-type flaws in both VHP nozzle base metal and filler metal materials so that a determination could be made as to whether a partial through-wall flaw would be capable of growing beyond the critical flaw size during a scheduled operating cycle for a facility.

In the bulletin, the staff stated that, as a result of its review of the susceptibility rankings given in Appendix B to MRP-44, Part 2, the population CRDM nozzles for U.S. PWRs could be categorized into the following populations. For the population of plants considered as having low susceptibility based upon a susceptibility ranking of more than 30 EFPY from the ONS3 condition, the staff stated that the likelihood of PWSCC degradation at these facilities was low, and that therefore enhanced examinations beyond those required by Section XI of the ASME Code were probably not necessary at the present time.

For the population of plants considered as having a moderate susceptibility to PWSCC based upon a susceptibility ranking of more than 5 EFPY but less than 30 EFPY from the ONS3 condition, the staff stated that an effective visual examination capable of detecting and discriminating small amounts of leakage or boric acid deposits from 100% of VHP nozzles, may be sufficient to provide reasonable confidence that PWSCC degradation would be identified prior to posing an undue risk. The staff emphasized that this effective visual examination should not be compromised by the presence of insulation, existing deposits on the RPV head, or other factors that could interfere with the detection of leakage.

For the population of plants considered as having a high susceptibility to PWSCC based upon a susceptibility ranking of less than 5 EFPY from the ONS3 condition, the staff stated that the possibility for

leaks to occur from a VHP nozzle at one of these facilities would dictate the need to use a qualified visual examination that would be capable of reliably detecting and accurately characterizing leakage from through-wall cracks in the VHP nozzles. The staff concluded that the qualified visual examination methods should be characterized by the following aspects: (1) that, as a result of a plant-specific demonstration, any VHP nozzle exhibiting through-wall cracking would be capable of providing a sufficient leakage path to the RPV head surface (based on the as-built configuration of the VHPs), and (2) that the effectiveness of the qualified visual examination should not be compromised by the presence of insulation, existing deposits on the RPV head, or other factors that could interfere with the detection of leakage. Absent the use of a qualified visual examination, the staff stated that a qualified volumetric examination of 100% of the VHP nozzles (with a demonstrated capability to reliably detect cracking on the OD of a VHP nozzle) would be appropriate to provide evidence of the structural integrity of the VHP nozzles.

For the population of plants which have already identified the existence of PWSCC in the CRDM nozzles (for example, through the detection of boric acid deposits), the staff concluded there was a sufficient likelihood that the cracking of VHP nozzles will continue to occur as the facilities continue to operate, and that, therefore, a qualified volumetric examination of 100% of the VHP nozzles (with a demonstrated capability to reliably detect cracking on the OD of the VHP nozzle) would be an appropriate method of providing evidence of the structural condition of their VHP nozzles.

In the bulletin, The staff therefore requested that licensees addressed by the bulletin submit the following information with respect to their nuclear power plants:

- the plant-specific susceptibility ranking for the plants (including all data used to determine each ranking) using the PWSCC susceptibility model described in Appendix B to the MRP-44, Part 2, report;
- a description of the VHP nozzles in the plants, including the number, type, inside and outside

diameter, materials of construction, and the minimum distance between VHP nozzles;

- a description of the RPV head insulation type and configuration;
- a description of the VHP nozzle and RPV head inspections (type, scope, qualification requirements, and acceptance criteria) that have been performed at your plant(s) over the past 4 years, and the findings, including a description of any limitations (insulation or other impediments) to accessibility of the bare metal of the RPV head for visual examinations;
- a description of the configuration of the missile shield, the CRDM housings and their support/restraint system, and all components, structures, and cabling from the top of the RPV head up to the missile shield, including the elevations of these items relative to the bottom of the missile shield.

In Bulletin 2001-01, the staff also requested that addressees discuss their plans, if any, to perform augmented examinations of their CRDM nozzles consistent with the additional augmented examination recommendations provided in the bulletin. In addition, the staff also requested, pursuant to 10 CFR 50.54(f), that addressees submit their responses to NRC Bulletin 2001-01 within 30 days of issuance of the bulletin.

III - Regulatory Basis for Issuing This Order

Section 2.202 of Part 2, Subpart B, of Title 10, *Code of Federal Regulations* and Section 50.109 to Title 10, *Code of Federal Regulations* (10 C.F.R. 2.202 and 10 C.F.R. 50.109, respectively) set forth requirements for issuing orders to holders of licenses issued under 10 C.F.R. Part 50, and for backfits the NRC wishes to impose. Under 10 C.F.R. 2.202(a)(1), the Commission has the authority to modify, suspend, or revoke an operating license when the Commission finds that there is a violation of the

Commission's requirements, or other potentially hazardous conditions or facts deemed to warrant issuance of an order. Under 10 C.F.R. 2.202(a)(5), the Commission may make orders immediately effective, without prior opportunity for hearing, in cases where the Commission determines that the public health, interest, or safety so requires, or where conduct causing the violation is willful. Pursuant to 10 C.F.R. 2.202(a)(3), any person that receives an order from the Commission is afforded an opportunity to demand a hearing on all or part of the order within 20 days of issuance of the order or such other time as may be specified in the order. Pursuant to 10 C.F.R. 2.202(e), if an order involves a modification of a 10 C.F.R. Part 50 license, and is a backfit, the order is required to meet the requirements of 10 C.F.R. 50.109, "Backfit."

The modification of Operating License Blank No. 6 (Operating License No.) stated in Blank No. 7 (Section VI or VII) of this order is based on assuring that the adequate protection of the health and safety of the public will be maintained at the Blank No. 8 (XYZ Facility). As a result, pursuant to provisions in 10 CFR 50.109(a)(4)(ii), the staff was not required to, and hence did not, perform a backfit analysis for this order to modify Operating License Blank No. 9 (Operating License No.).

Pursuant to 10 CFR 50.109(5), the Commission shall always require the backfitting of a facility if it determines that the regulatory action is necessary to ensure that the facility provides adequate protection to the health and safety of the public and is accord with the common defense and security.

IV- Adequate Protection Evaluation Required Pursuant to 10 C.F.R. 50.109(a)(4)

The current method for managing PWSCC in the VHP nozzles of U.S. PWRs is dependent on the implementation of inspection methods for detecting effect prior to a failure of a facility's VHP nozzle. Section (g)(4) to 10 CFR 50.55a requires, in part, that ASME Code Class 1, 2, and 3 component must meet the inservice inspection requirements of Section XI the ASME Boiler and Pressure Vessel Code throughout the service life of a boiling or pressurized water reactor. Pursuant to Inspection Category B-P of Table IWB-2500-1 to Section XI of the ASME Boiler and Pressure Vessel Code, licensees are required to perform VT-2 type visual examinations of their VHP nozzles and reactor vessel heads once every refueling outage for the system leak tests, and once an inspection interval for the hydrostatic pressure test. However, pursuant to Paragraph IWA-5242 of Section XI of ASME Boiler and Pressure Vessel Code, the Code does not require licensees to remove thermal insulation materials when performing ASME VT-2 examinations of their reactor vessel heads.

Based on current data supplied by the industry to date, the staff cannot be assured that VT-2 examination methods used on the upper vessel heads in accordance with Inspection Category B-P of Table IWB-2500-1 to Section XI of the ASME Boiler and Pressure Vessel Code are capable of detecting leakage from a throughwall flaw in the nozzles or their adjacent J-groove welds. Additionally, leak-rate calculations of the reactor coolant from leaking VHP nozzles at the Oconee Unit 3 station demonstrate that the leaks may occur, and in all probability do occur, at very slow rates (i.e., ≤ 1 gpy); leakage rates of this magnitude may not be high enough to allow for detectable indication of the leakage using typical instrumentation designed for the purpose of detecting reactor coolant pressure boundary leakage. The location of thermal insulating materials, and physical obstructions may also limit the capability of VT-2 examination methods to identify minute amounts of boric acid deposits on the outer surface of the vessel head. Cleanliness of reactor vessel heads during the examinations is also a critical aspect, as it is important for visual examination methods to be capable of distinguishing between boric acid residues that result from VHP nozzle leakage and those residues that result from leaks in other reactor coolant system components.

The regulations of 10 CFR Part 50, and specifically 10 CFR 50.55a, identify Section XI of the ASME Boiler and Pressure Vessel Code as the source for inspection requirements. As described above, however, compliance with these requirements is not adequate to detect and prevent potential cracking and gross failure of the VHP nozzles for PWR-designed reactors. This situation constitutes a "special circumstance" in which compliance with the Commission's regulations does not address a safety issue that may have significant risk implications. Regulatory Information Summary (RIS) 01-002, "Guidance on Risk-Informed Decisionmaking in License Amendment Reviews," provides a process for the staff to consider whether a "special circumstance" rebuts the presumption that compliance with the regulations provides adequate protection of public health and safety. Although developed for staff reviews of license amendment requests, the process in RIS 01-002 is appropriate for other regulatory decisionmaking purposes because it addresses the fundamental requirement for operation of a nuclear reactor, that there is reasonable assurance of adequate protection for the public health and safety.

Application of the RIS 01-002 process to this issue has three steps:

1. identification of a "special circumstance" involving a risk factor not addressed by regulations;
2. assessment of the factor with respect to the five safety principles of risk-informed decision-making to establish whether its effect is sufficiently large to rebut the assumption that adequate protection is achieved by compliance with existing regulations; and
3. identification of an adequate basis for establishing reasonable assurance of adequate protection when the factor is considered.

First, a special circumstance is present because 10 CFR 50.55a inservice inspection requirements for inspection of vessel heads (i.e., pursuant to Category B-P to Table IWB-2500-1 of Section XI, ASME Boiler and Pressure Vessel Code) are not adequate to assure the structural integrity of the VHP nozzles in that the specified examination method is not capable of detecting cracking in VHP nozzles. The Code

requirements are therefore inadequate to monitor for degradation in the VHP nozzles prior to leakage from the nozzles and possibly prior to a postulated occurrence of a VHP nozzle failure, and consequently a small-break LOCA scenario. This is contrary to the statement in the Preface to Section XI that states "The rules . . . [of Section XI] . . . require a mandatory program of examinations, testing and inspections to evidence adequate safety . . . [of a nuclear power plant]." Thus, a "special circumstance" exists with respect to this issue, as the regulations specify compliance with ASME Code requirements that are not adequate to degradation in the nozzles and protect against a LOCA. This satisfies step one in the RIS-01-002 process.

Second, only one of the safety principles in the integrated decision-making process described in Regulatory Guide 1.174 (RG 1.174), "An Approach for Using Probabilistic Risk Assessment in Risk-Informed Decisions on Plant-Specific Changes to the Licensing Basis," is met. First, given that the inspections being performed meet the requirements of 10 CFR 50.55a, the current regulations are met. Second, compliance with the regulations may not be adequate to prevent the failure of the reactor coolant pressure boundary, one of the three barriers to release of radioactive materials from the reactor core, and thus is contrary to the "defense-in-depth philosophy." Third, compliance with the ASME Code, Section XI, inservice inspection requirements does not ensure that the safety margins for the nozzles will be maintained since pressure boundary leakage can go undetected before gross failure occurs.

Fourth, the core damage frequency (CDF) could eventually approach the relatively high numerical value of the conditional core damage probability (CCDP) for the loss-of-coolant accident (LOCA) that would result from gross CRDM nozzle failure. CCDP values for the subject plants range from $2E-2$ per reactor-year to $1.4E-3$ per reactor-year. To fall below the RG 1.174 guidelines of a CDF increase (i.e., Δ CDF) of less than $E-5$ per reactor-year for a plant that has a baseline CDF of less than $E-4$ per reactor-year, the initiating event frequency for a VHP nozzle failure would have to be demonstrated to be below $5E-4$ to $7E-3$ per reactor-year. For the plant that has a baseline CDF of greater than $E-4$ per reactor-year, the initiating event frequency for the VHP nozzle failure would have to be demonstrated to be below $5E-5$ per reactor-year. For the age of the plants in question and the lack of a qualified examination for detecting degradation in these nozzles, there does not appear to be an adequate basis to justify the

necessarily low initiating event frequencies proposed by the industry for these type of failures.

Finally, the fifth principle is not satisfied because the basis for any licensee analysis that shows risk levels below RG 1.174 numerical guidelines must be based on assumptions that cannot be verified without performing inspections that are capable of detecting the form of degradation being modeled. In summary, this "special circumstance" does not satisfy four of the five safety principles, and therefore, the assumption that compliance with the regulations is sufficient to provide reasonable assurance for adequate protection of the public health and safety is not valid.

The third and final step for application of the RIS 01-002 process involves identification of an adequate basis for establishing reasonable assurance of protection when the "special circumstance" is considered. The Commission has compiled a number of general design criteria (GDC) for the design, fabrication, construction, testing and performance of structures, systems and components important to safety in Appendix A to 10 CFR Part 50. The GDC provide the Commission's perspectives on the factors that are sufficient to achieve "adequate protection." Three GDCs are relevant to this case.

Criterion 14 states that "The reactor coolant pressure boundary shall be designed, fabricated, erected, and tested so as to have an extremely low probability of abnormal leakage or rapidly propagating failure, and of gross rupture." Criterion 30 states that "Means shall be provided for detecting and, to the extent practical, identifying the location of the source of reactor coolant leakage." Criterion 32, in part, states that "components of the reactor coolant pressure boundary shall be designed to permit . . . periodic inspection and testing of important areas and features to assess their structural integrity and leaktight integrity."

Taken as a whole, these GDCs emphasize that the Commission considers that it is extremely important from a safety standpoint to maintain the reactor coolant pressure boundary in a leaktight and structurally sound condition, with extremely low probability of gross failure.

Failure to inspect a portion of the reactor vessel in a manner that is sufficient to detect the extent of degradation caused by a mechanism known to be degrading other plants in that portion of the vessel is

inconsistent with these GDCs. The level of degradation that has been found in other plants, if left undetected and uncorrected, would result in a gross failure of the reactor coolant pressure boundary. Therefore, given the "special circumstance," the staff does not have reasonable assurance that adequate protection is achieved by plants that do not perform inspections that are sufficient to detect this type of degradation.

I find that issuance of an order to require licensees with most highly ranked (susceptible) VHP nozzles to perform inspections that are capable of detecting VHP nozzle degradation or leakage before the safety margins for the nozzles are lost and gross rupture (*i.e.*, a full 360° through-wall failure of the nozzle) occurs is in order to provide reasonable assurance of the health and safety of the public. Furthermore, pursuant to 10 C.F.R. 50.109(a)(4)(ii), no backfit analysis is required for imposition of these inspection requirements. Pursuant to 10 C.F.R. 2.202, I have determined based on [the licensee's commitment and,] the significance of concerns regarding potentially hazardous condition that a circumferential crack may exist undetected and uncorrected in the VHP nozzles of these facilities, that the assurance of the public health and safety requires that this order be immediately effective.

By letter dated Blank No. 11 (Date-2), the Licensee submitted its responses to NRC Bulletin 2001-01 for the Blank No. 12 (XYZ Facility). The Licensee's response to NRC Bulletin 2001-01 indicates that the Blank No. 13 - (provides the plant specific input from Al Hiser that summarizes the technical information in the response to NRC Bulletin 2001-01 for the XYZ facility). Based on the inadequacy of the ASME Section XI inspection methods to detect degrading CRDM nozzle to reactor pressure vessel head welds, and the inability of the industry to establish a defensibly low initiating event frequency and core damage frequency for CRDM nozzles failures, I lack assurance that the licensee's scheduled time for performing qualified VT-2 examinations of the CRDM nozzles of the Blank No. 14 (XYZ Facility) is sufficient to provide adequate protection of the health and safety of the public. As a result, there is a significantly increased probability of a CRDM nozzle failure at this time, raising immediate concerns relative to the public health and safety.

V - Modification of the License

Accordingly, pursuant to Sections 103, 161b, 161i, 161o, 182 and 187 of the Atomic Energy Act of 1954, as amended, and the Commission's regulations in 10 CFR 2.202 and 10 CFR Part 50, IT IS HEREBY ORDERED, EFFECTIVE IMMEDIATELY, THAT LICENSE NO. Blank No. 23 (XYZ Facility Name in CAPITAL LETTERS) IS MODIFIED AS FOLLOWS:

1. Require a shutdown of the Blank No. 24 (XYZ Facility Name) to the cold shutdown Mode of Operation for the facility by Blank No. 25 (Date-6).
2. Blank 26 - (AI Hiser to provide specific details of inspection methods the staff will require under modification of the license as consistent with the recommendations in NRC Bulletin 2001-01.)
3. Blank 27 - (AI Hiser to provide specific details of what the staff will require for removal of thermal insulation materials and cleanliness of the bare surfaces of the vessel head, as consistent with the recommendations in NRC Bulletin 2001-01.)
4. Blank 28 - (AI Hiser to provide specific details of what the staff will require for performing a qualified leak path and interference fit evaluation , as consistent with the recommendations in NRC Bulletin 2001-01.)
5. Blank 29 - (AI Hiser to provide specific details of the type of information the staff will require to be submitted by the licensee and the date for submitting this information to the Commission, as consistent with the recommendations in NRC Bulletin 2001-01.)

The Regional Administrator, Region Blank No. 30 (NRC Region Number), may relax or rescind, in writing, any of the above conditions upon a showing by the Licensee of good cause.

VI - Request for Hearing

In accordance with 10 CFR 2.202, the Licensee must, and any other person adversely affected by this Order may, submit an answer to this Order, and may request a hearing on this Order, within 20 days of the date of this Order. Where good cause is shown, consideration will be given to extending the time to request a hearing. A request for extension of time must be made in writing to the Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, DC 20555, and include a statement of good cause for the extension. The answer may consent to this Order. Unless the answer consents to this Order, the answer shall, in writing and under oath or affirmation, specifically admit or deny each allegation or charge made in this order and set forth the matters of fact and law on which the Licensee or other person adversely affected relies and the reasons as to why the Order should not have been issued. Any answer or request for a hearing shall be submitted to the Secretary, U.S. Nuclear Regulatory Commission, ATTN: Rulemakings and Adjudications Staff, Washington, DC 20555. Copies also shall be sent to the Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, DC 20555, to the Assistant General Counsel for Materials Litigation and Enforcement at the same address, to the Regional Administrator, NRC Region Blank 31 - (Region No. , Blank 32 - (regional address), and to the Licensee if the answer or hearing request is by a person other than the Licensee. If a person other than the Licensee requests a hearing, that person shall set forth with particularity the manner in which his interest is adversely affected by this Order and shall address the criteria set forth in 10 CFR 2.714(d).

If a hearing is requested by the Licensee or a person whose interest is adversely affected, the Commission will issue an Order designating the time and place of any hearing. If a hearing is held, the issue to be considered at such hearing shall be whether this Order should be sustained.

Pursuant to 10 CFR 2.202(c)(2)(i), the Licensee, may, in addition to demanding a hearing, at the time the answer is filed or sooner, move the presiding officer to set aside the immediate effectiveness of the Order on the ground that the Order, including the need for immediate effectiveness, is not based on adequate evidence but on mere suspicion, unfounded allegations, or error.

In the absence of any request for hearing, or written approval of an extension of time in which to request a hearing, the provisions specified in Section IV above shall be final 20 days from the date of this Order without further order or proceedings. If an extension of time for requesting a hearing has been approved, the provisions specified in Section IV shall be final when the extension expires if a hearing request has not been received. AN ANSWER OR A REQUEST FOR HEARING SHALL NOT STAY THE IMMEDIATE EFFECTIVENESS OF THIS ORDER.

FOR THE NUCLEAR REGULATORY COMMISSION

Deputy Executive Director

for _____

Dated this ____ day of (Month) 19(XX)