

From: Lawrence Burkhardt
To: Brian Sheron; Jon Johnson; Richard Borchardt; Samuel Collins } NRR
Date: 11/27/01 7:26PM
Subject: DAILY STATUS REPORT FOR 11/27/01 (BULLETIN 2001-01 ISSUES)

THIS INFORMATION IS PRE-DECISIONAL AND NOT INTENDED FOR PUBLIC DISCLOSURE AT THIS TIME.

The updates regarding Bulletin 2001-01 issues are as follows (the DSR electronic file from 11/21/01 is attached for your information. The changes in this e-mail have not yet been incorporated in the electronic file).

1) Davis-Besse

Licensee Plans/Commitments: The licensee intends to officially submit additional information (proprietary and non-proprietary version) tomorrow morning. The staff will review this information for its relevancy to resolution of this issue. A "draft" copy of the information was forwarded to the PM and included, among other things, a commitment to shutdown on 2/16/02 (the licensee claims that this information is proprietary) to start its refueling outage and conduct the recommended inspections.

Next Regulatory Action: The Order was forwarded by the EDO to the Commissioners via memorandum on 11/21/01, and stated that the staff intends to issue the Order (which requires plant shutdown by 12/31/01 and the demonstration, by inspection, that the vessel head penetration nozzles are free of significant defects prior to subsequent operation) no sooner than 5 working days from the date of the memorandum.

Meetings & Conference Calls: The licensee has requested a working meeting on Wednesday, 11/28/01, to discuss relevant issues. The meeting is scheduled to start at 10 a.m. in room O-6B4. A phone bridge has been arranged (please dial 301-231-5539 or 1-800-638-8081 and use passcode [REDACTED])

Ex 2

(2) D.C Cook, Unit 2

Next Regulatory Action: Based on its review of information provided by the licensee and results of inspections conducted at other facilities, the staff has concluded that deferral of the inspections at D.C Cook 2 until the next outage, which begins on 1/19/01, is acceptable. Therefore, no Order is necessary.

(3) North Anna, Units 1 and 2

NRC Staff Position: Staff continues its review of the supplemental response re: qualification of visual examinations that was forwarded via letter dated 11/19/01.

Status of Inspections/Repairs: North Anna, Unit 2, has completed repairs of one vessel head penetration nozzle. Repairs to 2 other VHP nozzles are in progress.

(4) Surry, Units 1 and 2

Licensee Plans/Commitments: Surry, Unit 2, is shutdown. Visual inspections began 11/24/01.

NRC Staff Position: Staff continues its review of the supplemental response re: qualification of visual examinations that was forwarded via letter dated 11/19/01.

Status of Inspections/Repairs: Repairs to Surry, Unit 1, are essentially complete. All "under-the head" hardware has been reinstalled and the head put back on the vessel. The head has been cleaned and an "as-left" visual examination is planned. Restart is expected in the middle of next week.

A bare-head visual inspection was conducted at Surry, Unit 2, over the weekend and the head was found
Information in this record was deleted
in accordance with the Freedom of Information
Act, exemptions 2
FOIA- 2002-229

E 41

to be very clean (the head was not removed). Forced air was used to clear miscellaneous boric acid debris. There was evidence of boric acid overhead. The licensee concluded that there were no indications which would require NDE from under the head. Restart is expected to begin with a MODE change on 11/28/01.

(5) TMI-1

The staff is interested in information regarding the licensee's flaw evaluation with regard to the 2 axial (below-the-weld) flaw indications that were not repaired. Items of interest are the assumed crack growth rate and the subsequent time it takes the axial flaw to propagate into the weld. The staff will engage the licensee in the near future regarding this issue.

(6) Oconee 3 (Inspection/Repair in progress)

During a conference call on 11/26/01, the licensee presented results of the inspection and repair of the CRDM nozzles. The licensee is planning to volumetrically examine all of the VHP nozzles which have not yet been examined (a total of 43 additional nozzles) for possible circumferential cracking. These inspections are scheduled to begin on 12/2/01. A conference call has been scheduled for Friday, 11/30/01, at 10 a.m. to further discuss the status of inspections and repairs.

(7) St. Lucie (moderate susceptibility plant)

St. Lucie, Unit 2, is shutdown for its refueling outage. The effective visual examination should commence later this week. Other inspection methods (UT, etc.) may be utilized to achieve examination of all of the VHP nozzles.

CC: A. Randolph Blough; Allen Hiser; Andrea Lee; Anthony Mendiola; Art Howell; Bhagwat Jain; Bill Bateman; Brendan Moroney; Brian Holian; Bruce Mallett; Charles Casto; Chuck Paulk; Daniel Collins; David Lew; David Nelson (HQ-OE); Dennis Dambly; Douglas Pickett; Edwin Hackett; Elinor Adensam; Ellis Merschhoff; Elmo Collins; F. Mark Reinhart; Farouk Eltawila; Frank Congel; Frederick Jaxheimer; Gary Holahan; Geoffrey Grant; Giovanna Longo; Gordon Edison; Harold Christensen; Herbert Berkow; Hubert J. Miller; Jack Strosnider; Jacob Zimmerman; James Caldwell; James Wiggins; Jay Collins; Jim Dyer; Jin Chung; John Goshen; John Grobe; John Jacobson; John Stang; Kamal Manoly; Keith Wichman; Ken Brockman; Lakshminaras Raghavan; Lawrence Chandler; Lee Ellershaw; Leonard Olshian; Leonard Wert; Mark Lesser; Melvin Holmberg; Michael Marshall; Michael Mayfield; Michael Modes; Mitzi Young; Niles Chokshi; Pao-Tsin Kuo; Pat Gwynn; Richard Barrett; Richard Correia; Richard Crlenjak; Richard Laufer; Roy Caniano; Satwant Bajwa; Stephen Raul Monarque; Stephen Sands; Steven Reynolds; Stuart Richards; Suzanne Black; Tad Marsh; Timothy Colburn; Victor McCree; Wayne Lanning; William Bearden; William Reckley

~~PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE~~

DAILY STATUS REPORT

RE: UNRESOLVED RESPONSES TO THE BULLETIN 2001-01 FOR HIGH SUSCEPTIBILITY

□ Davis-Besse

Licensee Plans/Commitments: The licensee plans to shutdown and perform Bulletin recommended inspections in April 2002.

NRC Staff Position: The staff has based its safety concerns with Davis-Besse (DB) on recent inspection experience finding evidence of cracking for plants similar to DB. The staff notes that (1) DB is a high susceptibility plant per the Bulletin, and 10 out of the 11 high susceptibility plants that have performed inspections have found cracking or leakage (two plants have yet to perform inspections, including DB); (2) the other six B&W plants have performed inspections and have found cracking (DB is the only B&W plant that has not inspected), with three of the six B&W plants finding circumferential cracks; and (3) DB has the highest head temperature at operating conditions for any B&W plant (605°F) (operation at higher temperatures increases susceptibility to cracking). Based on the above, it is reasonable to conclude that DB may have cracks that could challenge the integrity of the reactor coolant pressure boundary. It is the staff's position that the licensee can provide reasonable assurance of reactor coolant pressure boundary integrity by performing inspections by December 31, 2001, as recommended in the bulletin.

The licensee has sought to justify continued operation until its scheduled refueling outage at the end of March 2002 using the results of prior inspections (from 1996 to the present) and both deterministic and probabilistic risk assessments. The staff has reviewed the risk assessment provided by DB and concluded that the methodology employed by the licensee appears to be reasonable. However, the staff has numerous questions regarding input parameters and assumptions used in the assessments, including inadequate data and high uncertainty in several cases. Regarding prior inspections, the licensee has stated that four nozzles cannot be inspected using a qualified visual examination due to an inadequate leakage path for these nozzles; one of these four nozzle locations has exhibited circumferential cracking on the nozzle outside diameter at Oconee Unit 3 in within the last week.

Next Regulatory Action: The revised Order was forwarded to the EDO via memorandum today, November 21, 2001.

Meetings & Conf. Call Summaries: A teleconference was held between EMCB and the DB licensee on Thursday, November 14. The purpose of the call was to summarize the staff's assessment of the DB bulletin response. The summary for this teleconference held on Thursday, November 14, will be issued today.

In this teleconference with the licensee, the staff provided its position, as described above, to allow the licensee to focus on items that could provide the staff with a basis to modify its position and find that DB can operate until its scheduled refueling outage in late March 2002. One possibility described by the staff was for the licensee to identify and justify features or factors that would indicate that DB should not be included in the population of high susceptibility

~~PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE~~

PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE

plants. The staff also reiterated its intent to continue discussions with the licensee, as appropriate.

The licensee has requested a working meeting to be held on Wednesday, 11/28/01, to discuss relevant issues. The time, date, and location of this meeting have not yet been confirmed.

INTERESTING NOTE: The resident Inspector for DB sat in on a licensee's morning management meeting and observed that licensee management expressed cautious optimism that the NRC would approve their (licensee's) plans to defer the inspections until April 2002. This is contrary to the message provided to DB management in the teleconference on Thursday, November 14.

□ **D. C. Cook, Unit 2**

Licensee Plans/Commitments: The licensee plans to shutdown and perform inspections on January 19, 2002. The inspection methods proposed by the licensee are not consistent with the recommended inspections described in the bulletin.

NRC Staff Position: Based on its review of information provided by the licensee and results of inspections conducted at other facilities, the staff has concluded that deferral of the inspections at D.C Cook 2 until the next outage, which begins on 1/19/02, is acceptable.

Next Regulatory Action: Based on its review of information provided by the licensee and results of inspections conducted at other facilities, the staff has concluded that deferral of the inspections at D.C Cook 2 until the next outage, which begins on 1/19/02, is acceptable. Therefore, no Order is proposed for D.C Cook 2.

Meetings & Conf. Call Summaries: A public meeting was held with the licensee today, 11/20/01, to discuss information regarding this issue.

□ **North Anna, Units 1 and 2**

Licensee Plans/Commitments: The NRC received a supplemental response on November 19, 2001, regarding information to qualify the fall inspections for North Anna and Surry Units.

NRC Staff Position: During an inspection in October 2001, the licensee identified several nozzles with cracking on the inside diameter of the nozzle and penetrant testing (PT) indications on the J-groove welds. The licensee determined that the nozzle cracking did not require repair. A staff review of the PT records concurred with the licensee's conclusions that the indications appeared to be surface indications and not relevant to a cracking mechanism. Via letter dated November 19, 2001, the licensee provided the documentation to support a "qualified visual" analysis to demonstrate acceptability of using "design" dimensions of the VHP penetrations and nozzles. The staff is reviewing this information.

PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE

~~PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE~~

North Anna, Unit 2, has a special outage for nozzle inspections in progress. Results from the visual examination indicated several nozzles that appeared to have boric acid deposits consistent with the findings at the Oconee plants and Crystal River Unit 3. Thus far the licensee has identified one of these nozzles with a through-wall crack in the J-groove weld (event report #38498). This crack was identified by the licensee due to staff insistence that the licensee destructively confirm the benign nature of PT indications on the J-groove welds dispositioned by the licensee as surface only and not relevant to a cracking mechanism. Repairs are being conducted on this nozzle and additional examinations are underway on two other suspect nozzles. Ultrasonic examination of the inside diameter of these three nozzles identified no cracking in the nozzle base metal.

With the findings at Unit 2, the staff will address with the licensee the PT findings at Unit 1.

Next Regulatory Action: None planned at this time.

Meetings & Conf. Call Summaries:

10/5/01- Conference call held to discuss the number of VHP penetrations to be inspected at North Anna, Unit 1.

10/24/01 - Conference call held to discuss the qualification of the visual exams to be conducted at North Anna, Units 1 and 2.

Drop-in visits were held by the licensee with the Commissioners and the EDO on November 19, 2001. A general status of the nozzle inspections at the North Anna and the Surry plants was provided by the licensee.

□ **Surry, Units 1 and 2**

Licensee Plans/Commitments: The NRC received a supplemental response on November 19, 2001, regarding information to qualify the fall inspections for all North Anna and Surry Units.

Licensee shutdown Unit 2 on 11/19/01 to perform the recommended inspections. Visual inspections to begin 11/24/01.

NRC Staff Position: Surry Unit 1 has an outage in progress. The licensee is nearing completion of repairs on six penetrations (this is a correction as the last DST stated that only 5 repairs were ongoing) at Surry Unit 1. As mentioned above, the licensee shutdown Surry Unit 2 on 11/19/01 to conduct the inspections.

Staff will review the licensee's supplemental response regarding qualification of visual inspections for these units.

Next Regulatory Action: None planned at this time.

Meetings & Conf. Call Summaries:

10/12/01- Surry agreed to provide a supplement to their Bulletin response addressing qualified

~~PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE~~

~~PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE~~

visual inspection (supplement sent 11/14/01). Still uncertain as to when Surry 2 would be inspected.

10/31/01 - NRC gave verbal relief for Surry Unit 1 relief requests SR-27 and SR-28 so that repair of cracks could proceed. Relief was based on NRC questions and licensee responses in previous North Anna phone calls (Surry Unit 1 relief and North Anna Unit 1 reliefs previously submitted, reviewed and withdrawn) and previous similar reliefs granted for Duane Arnold, Fitzpatrick, and Nine Mile Point.

11/6/01 - Surry agreed to docket a commitment to provide evidence of weld procedure qualification for P43 to P3 with F43 filler. Also agreed to provide analyses for weld repair and flaw evaluation prior to restart. Also agreed to address crack triplepoint, and to state there will be a PT report documenting J weld crack.

~~PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE~~

PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE

VHP NOZZLE INSPECTIONS/RESULTS
NOVEMBER 21, 2001
4:00 P.M.

□ **Crystal River, Unit 3**

Inspections completed in October 2001. The licensee identified one leaking CRDM nozzle with a 90° circumferential crack which was subsequently repaired. The staff notes that the licensee did not perform any destructive examination to further characterize the flaw. This is the highest ranked moderate susceptibility plant.

□ **North Anna, Unit 1**

Inspections completed in September 2001. The licensee identified eight shallow axial cracks below the J-groove weld and penetrant testing (PT) indications on the J-groove welds. The licensee did not perform any repairs because these cracks were not part of the reactor coolant pressure boundary. A staff review of the PT records concurred with the licensee's conclusions that the indications appeared to be surface indications and not relevant to a cracking mechanism.

□ **North Anna, Unit 2**

North Anna, Unit 2, found a through-wall leak in a CRDM nozzle (event report issued). Repairs are being conducted on this nozzle and additional examinations are underway on two other suspect nozzles. Ultrasonic examination of the inside diameter of these three nozzles identified no cracking in the nozzle base metal.

□ **Surry, Unit 1**

The licensee is nearing completion of repairs on six penetrations (this is a correction as the last DST stated that only five repairs were ongoing).

□ **Surry, Unit 2**

The licensee shutdown Unit 2 on 11/19/01 to conduct the recommended inspections. The inspections are expected to commence on 11/24/01.

□ **TMI-1**

Following shutdown for a scheduled refueling outage in October 2001, TMI-1 performed visual inspections of the reactor vessel CRDM nozzles as recommended in NRC Bulletin 2001-01. The inspections revealed axially-oriented flaw indications in eight CRDM nozzles, six nozzles were found to have cracks within the pressure boundary (five nozzles had through-wall cracks and one did not), the other two nozzles had cracks that

PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE

~~PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE~~

were outside the pressure boundary. The licensee completed Code repairs on all six of the CRDM nozzles that had flaws within the pressure boundary. Additionally, the licensee performed visual inspections of the eight thermocouple (T/C) nozzles and found evidence of leakage on all of them. Two of the leaking T/C nozzles were replaced and the remaining six were plugged in accordance with Code requirements or as allowed by an NRC-approved relief request. These corrective actions are complete.

The staff is interested in information regarding the licensee's flaw evaluation with regard to the 2 axial (below-the-weld) flaw indications that were not repaired. Items of interest are the assumed crack growth rate and the subsequent time it takes the axial flaws to propagate into the weld. The staff will engage the licensee in the near future regarding this issue.

□ **Oconee, Unit 3**

The licensee initially identified cracking in February of 2001 (nine leaking CRDMs, three circumferential cracks) during a maintenance outage. On November 12, 2001, after only seven months of operation following its previous inspection and during its regularly scheduled refueling outage Oconee, Unit 3, identified indications of leakage evidenced by boric acid buildup around four CRDM nozzles. Three additional nozzles were categorized as potential leaking nozzles and require further inspection. The licensee expects to conduct additional inspections during the weekend of November 17, 2001.

As of the morning of Monday, November 19, 2001, nine CRDM nozzles have been ultrasonically examined. These nozzles include the four nozzles that had visual indications of leakage, the three nozzles that were categorized as potential leakers based on visual examination results, and two additional nozzles. UT has verified that five nozzles have through-wall cracks. One nozzle (nozzle 2) has a circumferential indication which is not through-wall (approximately 48 degrees in length).

A telecon was held with the licensee to discuss preliminary results of its inspections of 9 control rod drive mechanism (CRDM) nozzles (4 exhibited visual indications of leakage, 3 were suspected leakers, and 2 others that were accessible due to the removal of the CRDMs).

Summary of potentially significant results (preliminary results only):

- (1) 1 nozzle indicated a circumferential crack above the J-groove weld (not through-wall) at about 48 degrees,
- (2) other nozzles had indications of ID- and OD-initiated axial cracking (mostly OD-initiated and some through-wall), and
- (3) based on the indications, the licensee is currently planning to repair 7 nozzles.

~~PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE~~

PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE

Interestingly, one of the 7 nozzles to be repaired is a nozzle that had no visual indications of leakage.

The licensee anticipates finalizing its results and its decision regarding expansion of inspections in a few days.

The conference call to discuss the status of the Oconee, Unit 3, control rod drive mechanism nozzle inspection and repair activities will be held on Monday, November 26, 1:30 pm in Room O-7B6.

PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE

~~PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE~~

MODERATE SUSCEPTIBILITY PLANT INSPECTION RESULTS
NOVEMBER 21, 2001
4:00 P.M.

The following plants have performed the recommended inspections as defined in Bulletin 2001-01 this fall and found no indications of leakage. All of these plants are ranked as moderately susceptible to primary water stress corrosion cracking. The licensee for these plants performed 100% bare metal visual inspections.

Beaver Valley, Unit 1
Farley, Unit 1
Kewaunee
Turkey Point, Unit 3

St. Lucie, Unit 2, has an outage scheduled to start on 11/26/01. Inspections should commence on or about 11/30/01.

No other moderate plants are scheduled for outages before 12/31/01.

~~PRE-DECISIONAL INFORMATION - NOT FOR PUBLIC DISCLOSURE~~